Ref: T01	Title: Earth Shrine	Category: Religious, Ritual and Funerary
Address: In front of No.23 Tai O Wing On Street		Figure Ref: Figure 10.11
Orientation: West		Grading: Nil Grade
Surrounding Environment: V	/illage houses and shops	
Historical Appraisal:		
although there is a referenc	e from 1810 that mentions th	et area probably dates back to the mid-19 th Century, ne street (Hase 1998). Commercial activities were/are the probably constructed when the settlement of the street
Associated Historical/ Cultu	ral Events or Individual: Non	e
Inscriptions: None		
Architectural Appraisal:		
The shrine is made of bricks and was construction by the	s and wood (painted brown) e wall of No. 25 Wing On Stre	with clay tile laying pitched roof (painted bright green) eet
Decorative Features: Nil Interior: N/A		
Existing Condition: Good		
Past and Present Uses: Rel	icious Pitual and Euperary	
		te coating/ no renovation or reconstruction date available.
Photographic Record:		

Ref: T02	Title: Earth Shrine	Category: Religious, Ritual and Funerary	
Address: Between No.24 &	26 Tai O Wing On Street	Figure Ref: Figure 10.11	
Orientation: South		Grading: Nil Grade	
Surrounding Environment:	Surrounding Environment: Village houses and shops		
Historical Appraisal:			
although there is a reference	e from 1810 that mentions th	et area probably dates back to the mid-19 th Century, he street (Hase 1998). Commercial activities were/are the ly constructed when the settlement of the street was	
Associated Historical/ Cultu	ral Events or Individual:		
Inscriptions:			
祠德 礼	· 一 田		
德	福		
施	蔭		
興	X		
水	X		
Architectural Appraisal:			
tiles. A statue of earth deity Decorative Features: Nil Interior: N/A	is placed inside the shrine for	Ving On Street. The shrine is made of bricks and clay or worshipping.	
Existing Condition: Good			
Past and Present Uses: Re	ligious, Ritual and Funerary		
Modifications: The current s	shrine is covered with concre	ete coating/ no renovation or reconstruction date available.	
Photographic Record:			

Ref: T03	Title: Village House	Category: Domestic
Address: No.30 Tai O Wing On Street		Figure Ref: Figure 10.11
Orientation: South		Grading: Nil Grade
Surrounding Environment:	Village houses and shops	
Historical Appraisal:		
although there is a reference dominate economy of this a established. The structure i	e from 1810 that mentions t area. The Shrine was probat s one of the remaining histo	-
Associated Historical/ Cultu	ral Events or Individual: No	ne
Inscriptions: None		
Architectural Appraisal:		
Layout: The site is a village	house with rectangular layo	but.
Construction Material:		
Roof: Timber beams and clay tile laying pitched roof Windows: Not accessible Walls: Grey or mud bricks. Façade wall upper part is wooden boards. Doors: Metal		
Decorative Features: Nil Interior: Not Accessible		
Existing Condition: Fair		
Past and Present Uses: Re	sidential (currently closed u	p)
Modifications: Metal gates a	and door on facade	
Photographic Record:		

Ref: T04	Title: Village House	Category: Domestic		
Address: No.44 & 46 Tai O Wing On Street		Figure Ref: Figure 10.11		
Orientation: South		Grading: Nil Grade		
Surrounding Environment:	Village houses and shops			
Historical Appraisal:				
although there is a reference dominate economy of this a	ce from 1810 that mentions area. The Shrine was proba s one of the remaining histo	·		
	Inal Events of Individual: No	ne		
Inscriptions: None				
Architectural Appraisal:				
Layout: Two two-level villag	ge houses with rectangular l	ayout and shared gable walls with nearby village house.		
Construction Material:				
	trade on first floor balcony	of No. 44		
Interior: Not Accessible				
Existing Condition: Good				
Past and Present Uses: Co	mmercial			
Modifications: Metal shutte been added.	r gate has been added to th	e façade entrance. Modern metal framed windows have		
Photographic Record:				

Ref: T05	Title: Yik Cheung Salt Fish Store	Category: Commercial	
Address: No.48 Tai O Wing On Street		Figure Ref: Figure 10.11	
Orientation: South		Grading: Nil Grade	
Surrounding Environment:	Village houses and shops	L	
although there is a reference dominate economy of this a	Historical Appraisal: The settlement of the Tai Ping Street and Wing On Street area probably dates back to the mid-19 th Century, although there is a reference from 1810 that mentions the street (Hase 1998). Commercial activities were/are the dominate economy of this area. The Shrine was probably constructed when the settlement of the street was established. The structure is one of the remaining historic buildings of the street.		
Associated Historical/ Cultu	ral Events or Individual: None	e	
Inscriptions: None			
Architectural Appraisal:			
Layout: Rectangular layout	structure		
Construction Material:			
Windows: Wooden shutters Walls: Probably brick with r Doors: Metal shutter across Decorative Features: Nil	Roof: Timber beams and clay tile laying pitched roof Windows: Wooden shutters across top of upper ground floor facade Walls: Probably brick with render cover Doors: Metal shutter across ground floor of facade		
Interior: Not Accessible			
Existing Condition: Good			
Past and Present Uses: Co	mmercial		
Modifications: A metal shutt	ter has been inserted on the	ground floor façade.	
Photographic Record:			

Ref: T06	Title: Shrine	Category: Religious, Ritual and Funerary
Address: In front of No.23 Tai O Wing On Street		Figure Ref: Figure 10.8
Orientation: South		Grading: Nil Grade
Surrounding Environment: F	Residential area around with	1
Historical Appraisal:		
although there is a referenc	e from 1810 that mentions t	et area probably dates back to the mid-19 th Century, he street (Hase 1998). Commercial activities were/are the probably constructed when the settlement of the street
Associated Historical/ Cultu	ral Events or Individual: Nor	ne
Inscriptions: None		
Architectural Appraisal:		
The shrine is set on a conci and an opening for incense Street.	rete platform and has a corruin is left in front of the stone.	ugated iron domed roof. The stone is set into the concrete The shrine was construction in front of No. 23 Wing On
Decorative Features: Nil		
Interior: N/A		
Existing Condition: Good		
Past and Present Uses: Re	ligious, Ritual and Funerary	
Modifications: None		
Photographic Record:		

Ref: T07	Title: Tai O Culture Shop	Category: Commercial		
Address: No. 54 Tai O Wing On Street		Figure Ref: Figure 10.11		
Orientation: South		Grading: Nil Grade		
Surrounding Environment:	Village houses and shops			
Historical Appraisal:				
although there is a reference dominate economy of this a	e from 1810 that mentions th	et area probably dates back to the mid-19 th Century, le street (Hase 1998). Commercial activities were/are the y constructed when the settlement of the street was c buildings of the street.		
Associated Historical/ Cultu	ral Events or Individual: Non	e		
Inscriptions: None				
Architectural Appraisal:				
Layout: A two-level village h	nouse with rectangular layout			
Construction Material:				
Windows: Metal framed gla Walls: Grey or mud bricks v Doors: Wooden shutters ac Decorative Features: Decor	Roof: Timber beams and clay tile laying pitched roof Windows: Metal framed glass windows Walls: Grey or mud bricks with render cover Doors: Wooden shutters across ground floor facade Decorative Features: Decorative concrete balustrade of the first floor			
Interior: Not Accessible				
Existing Condition: Good				
Past and Present Uses: Co	mmercial and first floor forme	erly residential		
Modifications: None				
Photographic Record:				

Ref: T08	Title: Village House	Category: Domestic
Address: No. 64 Tai O Wing On Street		Figure Ref: Figure 10.11
Orientation: South		Grading: Nil Grade
Surrounding Environment:	Village houses and shops	
Historical Appraisal:		
although there is a reference dominate economy of this a	e from 1810 that mentions th	et area probably dates back to the mid-19 th Century, he street (Hase 1998). Commercial activities were/are the y constructed when the settlement of the street was c buildings of the street.
Associated Historical/ Cultu	ral Events or Individual: Non	e
Inscriptions: None		
	gle storey rectangular buildin of the façade. Modern metal	g with metal shutter across the front and metal sheet corrugated roof.
Interior: Not Accessible		
Existing Condition: Fair		
Past and Present Uses: Re	sidential	
Modifications: Metal shutter inserted above the shutter of		e ground floor façade. Sheets of metal have been
<image/>		

Ref: T09	Title: Fat Kee Hardware Shop	Category: Commercial
Address: No. 72 Tai O Wing On Street		Figure Ref: Figure 10.11
Orientation: South		Grading: Nil Grade
Surrounding Environment:	Village houses and shops	1
Historical Appraisal:		
although there is a reference dominate economy of this a	ce from 1810 that mentions th	et area probably dates back to the mid-19 th Century, he street (Hase 1998). Commercial activities were/are the ly constructed when the settlement of the street was ic buildings of the street.
Associated Historical/ Cultu	ural Events or Individual: Non	e
Inscriptions: None		
Architectural Appraisal:		
Layout: A village house wit	h rectangular layout and shar	ed gable walls with nearby village houses.
Construction Material:		
Roof: Timber beams and cl Windows: Not accessible Walls: Grey or mud bricks Doors: Metal shutter across	with render cover, piers at eith	her end of the facade
Decorative Features: Nil Interior: Not Accessible		
Existing Condition: Good		
Past and Present Uses: Co		
Modifications: Metal shutte	r has been inserted across th	e ground floor façade.
Photographic Record:		

Ref: T10	Title: Village House	Category: Domestic	
Address: No. 92 Tai O Wing On Street		Figure Ref: Figure 10.11	
Orientation: South		Grading: Nil Grade	
Surrounding Environment:	/illage houses		
Historical Appraisal:			
although there is a reference dominate economy of this a	e from 1810 that mentions th	et area probably dates back to the mid-19 th Century, le street (Hase 1998). Commercial activities were/are the y constructed when the settlement of the street was c buildings of the street.	
Associated Historical/ Cultu	ral Events or Individual:		
Inscriptions: None			
Architectural Appraisal:			
Layout: A village house with	n rectangular layout.		
Construction Material:			
Roof: Timber beams and clay tile laying pitched roof Windows: Wood framed wood barred windows Walls: Grey Brick or mud brick with render covering Doors: Wooden shutters across façade with wooden slat ventilation above Decorative Features: Nil			
Interior: Not Accessible			
Existing Condition: Fair			
	sidential (Currently closed up		
Modifications: None			
Photographic Record:			

Ref: T-11	Title: Village House	Category: Domestic
Address: No. 96 Tai O Wing On Street		Figure Ref: Figure 10.11
Orientation: South		Grading: Nil Grade
Surrounding Environment:	Village houses and shops	
although there is a reference dominate economy of this a established. The structure i	e from 1810 that mentions to area. The Shrine was probab s one of the remaining histor	Ũ
	iral Events or Individual: Nor	ne
Inscriptions: None		
Architectural Appraisal:		
Layout: A village house with	h rectangular layout and sha	red gable walls with nearby village houses.
Construction Material:		
Roof: Timber beams and cl Windows: Nil Walls: Grey or mud bricks, Doors: Metal shutter across	stones and metal sheets.	
Decorative Features: Nil Interior: Not Accessible		
Existing Condition: Poor		
Past and Present Uses: Re	sidential	
Modifications: Sheet metal	over top section of façade a	nd metal shutter inserted across the lower section.
Photographic Record:		

Ref: T-12	Title: Dou Fok Tong 道福堂	Category: Commercial	
Address: No. 104 Tai O Wing On Street		Figure Ref: Figure 10.12	
Orientation: South		Grading: Nil Grade	
Surrounding Environment:	Village houses and shops		
Historical Appraisal:			
although there is a reference dominate economy of this a established. The structure i	e from 1810 that mentions area. The Shrine was proba s one of the remaining hist	-	
Associated Historical/ Cultu	ral Events or Individual: N	one	
Inscriptions: 堂福道			
Architectural Appraisal:			
Layout: A two-level village I	nouse with rectangular laye	out.	
Construction Material:			
Roof: Timber beams and cl Windows: Metal framed gla Walls: Grey bricks (render o Doors: Metal Shutters on g	ss window covered) and cut stone gro	ound floor level	
Decorative Features: The b Interior: Not Accessible	alustrade of the balcony o	f the second floor	
Existing Condition: Good			
Past and Present Uses: Co	mmercial (Coffin Store)		
Modifications: Metal shutter shutter.	inserted across the groun	nd floor façade and plastic sign has been added above the	
Photographic Record:	Photographic Record:		

Ref: T-13	Title: Village House	Category: Domestic
Address: No. 101 Tai O Wing On Street		Figure Ref: Figure 10.12
Orientation: North		Grading: Nil Grade
Surrounding Environment:	Village houses and shops	
Historical Appraisal:		
although there is a reference dominate economy of this a	e from 1810 that mentions th	et area probably dates back to the mid-19 th Century, ne street (Hase 1998). Commercial activities were/are the ly constructed when the settlement of the street was ic buildings of the street.
Associated Historical/ Cultu	ral Events or Individual: Non	e
Inscriptions: None		
Architectural Appraisal:		
Layout: A village house with	h rectangular layout and shar	ed gable walls with nearby village houses.
Construction Material:		
Roof: Timber beams and clay tile laying pitched roof Windows: Wooden framed glass windows Walls: Grey or mud bricks and stones Doors: Wooden		
Decorative Features: Nil		
Interior: Not Accessible		
Existing Condition: Fair		
Past and Present Uses: Re	sidential	
Modifications: None		
Photographic Record:		

Ref: T-14	Title: Village House	Category: Domestic
Address: No. 107 Tai O Wing On Street		Figure Ref: Figure 10.12
Orientation: Northwest		Grading: Nil Grade
Surrounding Environment: \	/illage houses and shops	
Historical Appraisal:		
although there is a reference dominate economy of this a	e from 1810 that mentions th	et area probably dates back to the mid-19 th Century, e street (Hase 1998). Commercial activities were/are the y constructed when the settlement of the street was c buildings of the street.
Associated Historical/ Cultu	ral Events or Individual: None	e e e e e e e e e e e e e e e e e e e
Inscriptions: None		
Architectural Appraisal:		
Single storey rectangular st Walls: Façade has painted t windows.	ructure with pitched roof (blac face to imitate cut stone. Woo	ck tar paper covering). oden panel across top of façade with three small round
Wooden half doors with woo	oden doors behind.	
Decorative Features: Nil		
Interior: Not Accessible		
Existing Condition: Fair		
Past and Present Uses: Res	sidential	
Modifications: None		

Ref: T-15	Title: Village House	Category: Domestic	
Address: No. 105 Tai O Wing On Street		Figure Ref: Figure 10.12	
Orientation: North		Grading: Nil Grade	
Surrounding Environment:	Village houses and shops		
Historical Appraisal:			
although there is a reference dominate economy of this a	ce from 1810 that mentions th	et area probably dates back to the mid-19 th Century, he street (Hase 1998). Commercial activities were/are the y constructed when the settlement of the street was ic buildings of the street.	
Associated Historical/ Cultu	ural Events or Individual: Non	e	
Inscriptions: None			
Architectural Appraisal:			
Layout: A two-level village	house with rectangular layout	L	
Construction Material:			
Windows: Metal framed gla Walls: Grey or mud bricks a	Roof: Timber beams and clay tile laying pitched roof Windows: Metal framed glass windows Walls: Grey or mud bricks and stones Doors: Wooden door and metal gate		
Decorative Features: Para Interior: Not Accessible	pet with fung shui feature (Di	sc with metal centre) on façade. Metal grille balustrade	
Existing Condition: Good			
Past and Present Uses: Re	esidential		
Modifications: Metal shutter	r has been inserted on the gro	ound floor façade.	
Photographic Record:	Photographic Record:		

Ref: T16	Title: Wing Chor School and Tai O Catholic Church	Category: Educational and Religious, Ritual and Funerary
Address: No. 112 Tai O Tai Ping Street		Figure Ref: Figure 10.12
Orientation: South		Grading: Nil Grade
Surrounding Environme	ent: Village houses and shops, t	he school is set in a gated compound.
Historical Appraisal:		
attached to the Catholi		named "Yuk Chi School (育 智 學 校)" and was built th and the school were destroyed by a typhoon and the enamed to Wing Chor School.
Associated Historical/ (Cultural Events or Individual: No	ne
Inscriptions: 堂主天 校學助永		
		storey structure, a new wing was added to the church in oms of the Wing Chor School.
Construction Material:		
Roof: Concrete Windows: Modern style metal framed glass windows Walls: Concrete Doors: Wooden		
Decorative Features: (Gothic style church roof	
Interior: Not Accessible	9	
Existing Condition: Goo	od	
Past and Present Uses	: Educational and Religious, Rit	ual and Funerary
Modifications: Modern windows and doors have been added to the buildings		
Photographic Record:		
a) e Wing On Streit t, 2 , - x o c		Tai Ping Street 澳太平街

Ref: T-17	Title: Village House	Category: Domestic
Address: No. 121 Tai O Tai	Ping Street	Figure Ref: Figure 10.12
Orientation: North		Grading: Nil Grade
Surrounding Environment: \	/illage houses and shops	
Historical Appraisal:		
although there is a referenc	e from 1810 that mentions the from 1810 that mentions the shrine was probable to the shrine to the shrin	eet area probably dates back to the mid-19 th Century, he street (Hase 1998). Commercial activities were/are the oly constructed when the settlement of the street was ric buildings of the street.
Associated Historical/ Cultu	ral Events or Individual: Nor	ne
Inscriptions: None		
Architectural Appraisal:		
Layout: A village house wit	h rectangular layout.	
Construction Material:		
Roof: Timber beams and cla Windows: Metal framed gla Walls: Grey or mud bricks, s Doors: Wooden, across leng	ss window stones, and wooden and me	etal sheets
Decorative Features: Nil Interior: Not Accessible		
Existing Condition: Poor		N
Past and Present Uses: Res	sidential (Currently abandon	160)
Modifications: None		
Photographic Record:		

Ref: T-18	Title: Shrine	Category: Religious, Ritual and Funerary
Address: Next to No. 120 Tai Ping Street		Figure Ref: Figure 10.12
Orientation: East		Grading: Nil Grade
Surrounding Environment: \	Village houses and shops	
Historical Appraisal:		
although there is a reference dominate economy of this a	e from 1810 that mentions th rea. The Shrine was probabl	et area probably dates back to the mid-19 th Century, he street (Hase 1998). Commercial activities were/are the y constructed when the settlement of the street was the settlement of the street was established.
Associated Historical/ Cultu	ral Events or Individual: Non	e
Inscriptions:		
富 平		
貴 安		
由是		
天福		
Architectural Appraisal:		
		of bricks. Three pieces of stones are placed on the altar been carved into a female form.
Interior: N/A		
Existing Condition: Good		
Past and Present Uses: Rel	ligious, Ritual and Funerary	
Modifications: The current s	shrine is covered with concre	te coating/ no renovation or reconstruction date available
		5
Photographic Record:		

Ref: T-19	Title: Civil Aid Association of Tai O	Category: Community function	
Address: No. 124 Tai O Tai	大澳民安促進會 Ping Street	Figure Ref: Figure 10.12	
Orientation: East		Grading: Nil Grade	
Surrounding Environment: '	Village houses and shops		
Historical Appraisal:			
The settlement of the Tai P although there is a reference dominate economy of this a	e from 1810 that mentions th	et area probably dates back to the mid-19 th Century, e street (Hase 1998). Commercial activities were/are the y constructed when the settlement of the street was c buildings of the street.	
Associated Historical/ Cultu	ral Events or Individual: None	9	
Inscriptions: None			
Architectural Appraisal:			
Layout: Single storey struct	ure with rectangular layout.		
Construction Material:			
Roof: Timber beams and clay tile laying pitched roof Windows: Wooden framed glass windows Walls: Grey or mud bricks and stones with render cover Doors: Metal Shutters across length of facade			
Decorative Features: Nil Interior: Not Accessible			
Existing Condition: Fair			
Past and Present Uses: Co	mmunity Function (currently a	appears to be closed up)	
Modifications: Metal shutter	Modifications: Metal shutters and sign on the façade have been painted green.		
Photographic Record:			

Ref: T-20	Title: Village House	Category: Domestic
Address: No. 145 Tai O Tai Ping Street		Figure Ref: Figure 10.12
Orientation: West		Grading: Nil Grade
Surrounding Environment:	Village houses and shops	
Historical Appraisal:		
although there is a reference dominate economy of this a	e from 1810 that mentions t	et area probably dates back to the mid-19 th Century, he street (Hase 1998). Commercial activities were/are the oly constructed when the settlement of the street was ric buildings of the street.
Associated Historical/ Cultu	ral Events or Individual:	
Inscriptions: None		
Architectural Appraisal:		
Layout: A village house with	n rectangular layout.	
Construction Material:		
Roof: Timber beams and clay tile laying pitched roof Windows: Not accessible Walls: The walls are covered by wooden and metal sheets Doors: Wooden half doors with metal doors behind on facade Decorative Features: Nil		
Interior: Not Accessible		
Existing Condition: Poor		
Past and Present Uses: Re	sidential (Closed up)	
Modifications: None		
Photographic Record:		

Ref: T-21	Title: Village House	Category: Domestic		
Address: No. 147 Tai O Tai Ping Street		Figure Ref: Figure 10.12		
Orientation: West		Grading: Nil Grade		
Surrounding Environment:	Village houses and shops			
Historical Appraisal:				
although there is a reference dominate economy of this a established. The structure i	ce from 1810 that mentions area. The Shrine was proba is one of the remaining hist	-		
Associated Historical/ Cultu	ural Events or Individual: No	one		
Inscriptions: None				
Architectural Appraisal:				
Layout: A village house wit	h rectangular layout.			
Construction Material:				
Windows: Not accessible	Roof: Timber beams and clay tile laying pitched roof Windows: Not accessible Walls: Grey or mud bricks and stones Doors: Wooden			
Decorative Features: Nil Interior: Not Accessible				
Existing Condition: Fair to p				
Past and Present Uses: Re	sidential			
Modifications: None				
Photographic Record:				

Title: Village House	Category: Domestic	
Ping Street	Figure Ref: Figure 10.12	
	Grading: Nil Grade	
/illage houses and shops		
e from 1810 that mentions rea. The Shrine was proba s one of the remaining histo	reet area probably dates back to the mid-19 th Century, the street (Hase 1998). Commercial activities were/are the ably constructed when the settlement of the street was oric buildings of the street.	
ral Events or Individual: No	one	
n rectangular layout.		
Roof: Timber beams and clay tile laying pitched roof. Awning supported by piers on the façade. Windows: Not accessible Walls: Grey or mud bricks and stones Doors: Wooden (across length of façade)		
d entry on side of awning o	on the façade.	
sidential (Currently closed	up)	
Photographic Record:		
	Ping Street /illage houses and shops ng Street and Wing On Str e from 1810 that mentions rea. The Shrine was proba s one of the remaining hist ral Events or Individual: No n rectangular layout. ay tile laying pitched roof. / nd stones gth of façade) d entry on side of awning of	

Ref: T-23	Title: Village House	Category: Domestic
	The Thage Thouse	Ballegery: Demoette
Address: No. 144 Tai O Tai	Pina Street	Figure Ref: Figure 10.12
	ing outdot	
Orientation: East		Grading: Nil Grade
Chomation: Edot		
Surrounding Environment: Village houses (between two modern buildings)		
Historical Appraisal:		
Historical Appraisal:		

The settlement of the Tai Ping Street and Wing On Street area probably dates back to the mid-19th Century, although there is a reference from 1810 that mentions the street (Hase 1998). Commercial activities were/are the dominate economy of this area. The Shrine was probably constructed when the settlement of the street was established. The structure is one of the remaining historic buildings of the street.

Associated Historical/ Cultural Events or Individual: None

Inscriptions: None

Architectural Appraisal:

Brick façade only section of building remaining. Grey brick sides with wooden slat over doorway across the façade, the doors have been removed.

Interior: Demolished

Existing Condition: Ruin (only façade wall remains)

Past and Present Uses: Residential

Modifications: None , most of building has been demolished.

Photographic Record:



Ref: T-24	Title: Village House	Category: Domestic
Address: No. 155 Tai O Tai Ping Street		Figure Ref: Figure 10.12
Orientation: West		Grading: Nil Grade
Surrounding Environment:	Village houses (modern bu	uildings on both sides)
although there is a reference dominate economy of this a established. The structure i	e from 1810 that mentions area. The Shrine was proba s one of the remaining hist	
Associated Historical/ Cultu	Iral Events of Individual: N	one
Inscriptions: None		
Architectural Appraisal: Layout: A two level village I Construction Material:	nouse with rectangular layo	out and shared gable walls with nearby village houses
Roof: Timber beams and clay tile laying pitched roof Windows: Modern style metal framed glass windows Walls: Grey brick Doors: Wooden		
Decorative Features: Nil Interior: Not Accessible		
Existing Condition: Fair		
Past and Present Uses: Re	sidential	
Modifications: modern wind	lows installed on upper floo	or
Photographic Record:		

Ref: T-25	Title: Village House	Category: Domestic	
Address: No. 152 Tai O Tai Ping Street		Figure Ref: Figure 10.12	
Orientation: East		Grading: Nil Grade	
Surrounding Environment:	Village houses and shops		
The settlement of the Tai P although there is a reference dominate economy of this a established. The structure i	Historical Appraisal: The settlement of the Tai Ping Street and Wing On Street area probably dates back to the mid-19 th Century, although there is a reference from 1810 that mentions the street (Hase 1998). Commercial activities were/are the dominate economy of this area. The Shrine was probably constructed when the settlement of the street was established. The structure is one of the remaining historic buildings of the street.		
	iral Events or Individual: Nor	ne	
Inscriptions: None			
Architectural Appraisal:			
Layout: A village house with	h rectangular layout and sha	ared gable walls with nearby village houses.	
Construction Material:			
Windows: Nil	Walls: Grey or mud bricks and stones covered by metal s		
Decorative Features: Nil Interior: Not Accessible			
Existing Condition: Fair			
Past and Present Uses: Re	sidential		
Modifications: Metal shutter	r and gate with awning have	been inserted on the facade	
Photographic Record:			

Ref: T-26	Title: Shop/ factory	Category: Commercial
Address: No. 156 Tai O Tai	Ping Street	Figure Ref: Figure 10.12
Orientation: East		Grading: Nil Grade
Surrounding Environment: \	/illage houses and shops	
Historical Appraisal:		
although there is a reference	e from 1810 that mentions the rea. The Shrine was probab	et area probably dates back to the mid-19 th Century, he street (Hase 1998). Commercial activities were/are the bly constructed when the settlement of the street was ric buildings of the street.
Associated Historical/ Cultu	ral Events or Individual: Nor	ne
Inscriptions: None		
Architectural Appraisal:		
Layout: A single storey strue	cture with rectangular layout	and shared gable walls with nearby village houses.
Construction Material:		
Roof: Timber beams and clay tile laying pitched roof Windows: Nil Walls: Grey or mud bricks and stones Doors: Wooden across façade with metal sheet above (probably replacing original wooden covering) Decorative Features: Nil		
Interior: Not Accessible		
Existing Condition: Poor		
Past and Present Uses: Co	mmercial	
Modifications: Metal sheet h	has been inserted across the	e upper part of the façade.
Photographic Record:		

Ref: T-27	Title: Shop House	Category: Commercial and Domestic
Address: No. 158 and No. 7	160 Tai O Tai Ping Street	Figure Ref: Figure 10.12
Orientation: East		Grading: Nil Grade
Surrounding Environment:	Village houses and shops	
Historical Appraisal:		
although there is a reference dominate economy of this a established. The structure i	e from 1810 that mentions th area. The Shrine was probabl s one of the remaining histori	-
Associated Historical/ Cultu	ral Events or Individual: None	9
Inscriptions: None		
Architectural Appraisal:		
Layout: Two two-level villag	ge houses with rectangular lay	yout and shared gable walls with each other
Construction Material:		
Roof: Timber beams and clay tile laying pitched roof Windows: Metal framed glass windows Walls: Render covered exterior, most likely brick underneath. Doors: Metal gate Decorative Features: Nil		
Interior: Not Accessible		
Existing Condition: Fair		
Past and Present Uses: Co	mmercial and residential	
Modifications: Metal shutter	rs have been inserted across	the ground floor façade.
Photographic Record:		

Ref: T28	Title: Village House	Category: Domestic
Address: No. 168 Tai O Tai Ping Street		Figure Ref: Figure 10.12
Orientation: East		Grading: Nil Grade
Surrounding Environment:	Village houses and shops	
Historical Appraisal:		
although there is a reference dominate economy of this a established. The structure i	e from 1810 that mentions area. The Shrine was probal s one of the remaining histo	
Associated Historical/ Cultu	ral Events or Individual: No	ne
Inscriptions: None		
Architectural Appraisal:		
Layout: A two-level structur	e in rectangular layout	
Construction Material:		
Roof: Timber beams, clay tile laying pitched roof and concrete Windows: Metal framed glass windows Walls: Bricks, stones and concrete Doors: Wooden across all of ground floor facade Decorative Features: Parapet across top of facade Interior: Not Accessible		
Existing Condition: Fair		
Past and Present Uses: Co	mmercial and residential	
Modifications: Façade has r	modern tile covering	
Photographic Record:		

Ref: T-29	Title: Shop/ factory Village	Category: Commercial and Domestic	
Address: No. 170 Tai O Tai	House Ping Street	Figure Ref: Figure 10.12	
Orientation: East		Grading: Nil Grade	
Surrounding Environment:	Village houses and shops		
Historical Appraisal:			
The settlement of the Tai Ping Street and Wing On Street area probably dates back to the mid-19 th Century, although there is a reference from 1810 that mentions the street (Hase 1998). Commercial activities were/are the dominate economy of this area. The Shrine was probably constructed when the settlement of the street was established. The structure is one of the remaining historic buildings of the street.			
Associated Historical/ Cultu	ral Events or Individual: None	2	
Inscriptions: None			
Architectural Appraisal:			
		out. The two halls are separated by an inner courtyard. It of the structure) are belong to the same owner.	
Construction Material:			
Roof: Timber beams and clay tile laying pitched roof Windows: Nil Walls: Grey brick with wooden door and slats on façade. Doors: Wooden			
Decorative Features: Nil			
Interior: Not Accessible			
Existing Condition: Fair			
Past and Present Uses: Co	mmercial and residential (Clo	sed up)	
Modifications: None	Modifications: None		
Photographic Record:			

Ref: T-30	Title: Tong Yi Zan 同益棧	Category: Religious, Ritual and Funerary	
Address: No. 172 Tai O Ta	Ping Street	Figure Ref: Figure 10.12	
Orientation: South		Grading: Nil Grade	
Surrounding Environment:	Village houses and shops		
Historical Appraisal:			
although there is a reference	e from 1810 that mentions area. The Shrine was proba	reet area probably dates back to the mid-19 th Century, the street (Hase 1998). Commercial activities were/are the ably constructed when the settlement of the street was toric buildings of the street.	
further inspection. However renovated.	r, according to the locals, the	estaurant or a motel before. The site was not accessible for he site was an old building before and was recently	
Associated Historical/ Cultu	Iral Events or Individual: No	one	
Inscriptions: 棧益同			
Architectural Appraisal:			
<i>Layout:</i> A three-hall-one-babe part of the Tong Yi Zan		ayout. A modernized village house (which was believed to e structure.	
Construction Material:			
Roof: Timber beams and clay tile laying pitched roof Windows: Metal framed glass windows Walls: Grey bricks and stones Doors: Wooden			
Decorative Features: The r Interior: Not Accessible	ounded stone features at t	he bottom of the side wall at the front	
Existing Condition: Very Go	ood (new materials)		
Past and Present Uses: An	cestral Hall		
Modifications: Recently ren	Modifications: Recently renovated in a traditional style		
Photographic Record:			

Ref: T-31	Title: Village House	Category: Domestic
Address: Beside No. 181 Tai O Tai Ping Street		Figure Ref: Figure 10.12
Orientation: Northwest		Grading: Nil Grade
Surrounding Environment: \	/illage houses and shops	
Historical Appraisal:		
although there is a reference dominate economy of this a	e from 1810 that mentions th	et area probably dates back to the mid-19 th Century, he street (Hase 1998). Commercial activities were/are the ly constructed when the settlement of the street was ic buildings of the street.
Associated Historical/ Cultu	ral Events or Individual: None	e
Inscriptions: None		
Architectural Appraisal:		
Grey brick and mud brick co vegetation.	ponstruction, originally two sto	reys, 1 st floor and roof collapsed and overgrown with
Interior: Not Accessible		
Existing Condition: Ruin		
Past and Present Uses: Res	sidential (Currently abandone	ed)
Modifications: None		
Photographic Record:		

Ref: T-32	Title: Village House	Category: Domestic
Address: No 181 Tai O Tai	Ping Street	Figure Ref: Figure 10.12
Orientation: Northwest		Grading: Nil Grade
Surrounding Environment:	Village houses and shops	
Historical Appraisal:		
although there is a reference dominate economy of this a	e from 1810 that mentions th	et area probably dates back to the mid-19 th Century, he street (Hase 1998). Commercial activities were/are the bly constructed when the settlement of the street was ric buildings of the street.
Associated Historical/ Cultu	ral Events or Individual: Nor	ne
Inscriptions: None		
Architectural Appraisal:		
Single storey rectangular st vent above, no windows vis		prick walls render covering. Wooden door in façade with
Interior: Not Accessible		
Existing Condition: Poor		
Past and Present Uses: Re	sidential	
Modifications: Metal shutter	gate in front of door and mo	odern corrugated fibre roof
Photographic Record:		

Ref: T-33	Title: Shop House	Category: Commercial and Domestic
Address: No. 182 Tai O Tai Ping Street		Figure Ref: Figure 10.12
Orientation: South		Grading: Nil Grade
Surrounding Environment:	Village houses and shops	1
Historical Appraisal:		
although there is a reference dominate economy of this a	e from 1810 that mentions the	et area probably dates back to the mid-19 th Century, he street (Hase 1998). Commercial activities were/are the y constructed when the settlement of the street was ic buildings of the street.
Associated Historical/ Cultu	ral Events or Individual: Non	е
Inscriptions: None		
Architectural Appraisal:		
Layout: A two-level village h	nouse with rectangular layout	and shared gable walls with nearby village house.
Construction Material:		
Roof: Timber beams and clay tile laying pitched roof Windows: Metal framed glass windows Walls: Brick and cut stone on lower sections, exterior covered in render. Doors: Wood door on upper floor façade leading to balcony. Decorative Features: Decorative wooden door opening onto first floor balcony, balcony with concrete balustrade. Interior: Not Accessible		
Existing Condition: Good		
	mmercial and Residential (C	urrently closed up)
	has been inserted across th	
Photographic Record:		

Ref: T-34	Title: Village House	Category: Domestic
Address: No. 184 Tai O Tai Ping Street		Figure Ref: Figure 10.12
Orientation: South		Grading: Nil Grade
Surrounding Environment:	/illage houses and shops	
Historical Appraisal: The settlement of the Tai Ping Street and Wing On Street area probably dates back to the mid-19 th Century, although there is a reference from 1810 that mentions the street (Hase 1998). Commercial activities were/are the dominate economy of this area. The Shrine was probably constructed when the settlement of the street was established. The structure is one of the remaining historic buildings of the street.		
Inscriptions: None	ral Events or Individual: Nor	
Architectural Appraisal: Layout: A village house with Construction Material:	n rectangular layout and sha	red gable walls with nearby village houses.
Roof: Timber beams and clay tile laying pitched roof Windows: Metal framed glass windows Walls: Grey bricks and cut stone on lower section of wall. Doors: Metal framed and metal folding shutter.		
Decorative Features: Geom frieze. Interior: Not Accessible	etric pattern in brickwork on	the top of ground floor façade wall. Plain black gable
Existing Condition: Good		
Past and Present Uses: She	•	
	and doors have been insert	ted on the ground floor façade.
Photographic Record:		

Ref: T-36	Title: Village House	Category: Domestic	
Address: Nos. 205 & 207 T	ai O Tai Ping Street	Figure Ref: Figure 10.12	
Orientation: North		Grading: Nil Grade	
Surrounding Environment:	Village houses and shops		
Historical Appraisal: The settlement of the Tai Ping Street and Wing On Street area probably dates back to the mid-19 th Century, although there is a reference from 1810 that mentions the street (Hase 1998). Commercial activities were/are the dominate economy of this area. The Shrine was probably constructed when the settlement of the street was established. The structure is one of the remaining historic buildings of the street.			
	ral Events or Individual: Nor	ne	
Inscriptions: None			
Architectural Appraisal: Layout: A row of two village temporary structure was att Construction Material:		outs. They are constructed shared gable walls. A	
Windows: Modern framed g	Roof: Timber beams and clay tile laying pitched roof Windows: Modern framed glass Walls: Grey bricks and stones		
Decorative Features: Nil Interior: Not Accessible			
Existing Condition: Good			
Past and Present Uses: Re	sidential		
Modifications: Metal door/ g	ate and windows have been	n installed on the building.	
Photographic Record:			

Ref: T-37	Title: Fuk Tak Gong 福德宮	Category: Religious, Ritual and Funerary
Address: East of No. 207 Tai O Tai Ping Street		Figure Ref: Figure 10.12
Orientation: North		Grading: Nil Grade
Surrounding Environment: \	/illage houses and shops	
Historical Appraisal:		
although there is a reference dominate economy of this a	e from 1810 that mentions th rea. The Shrine was probably	et area probably dates back to the mid-19 th Century, le street (Hase 1998). Commercial activities were/are the y constructed when the settlement of the street was s probably constructed when the settlement of the street
Associated Historical/ Cultur	ral Events or Individual: None	e
Inscriptions: 宮德福	1 1 1	
Architectural Appraisal:		
The walls of the main struct	ure are made of stone. The r	an attached square shaped structure, and an incinerator. oof of the main structure is made of clay title. The walls hed roof is constructed with timber beams and clay titles.
Decorative Features: Nil Interior: Plain rooms with alt	ar against back wall.	
Existing Condition: Good		
Past and Present Uses: Shr	ino	
the shrine.	ave been painted white. The	re was no information on renovation/ reconstruction for
Photographic Record:		

Ref: T-38	Title: Shop House	Category: Commercial and residential
Address: Nos. 2 & 4 Tai O Market Street		Figure Ref: Figure 10.11
Orientation: West		Grading: Proposed Grade 2 Historic Building
Surrounding Environment:	/illage houses and shops	
Historical Appraisal:		
Tai O Market Street was bu been for the most part retain 1930's and were probably th	ned and contain group value	 The rows of buildings on both sides of the street have Nos. 2 & 4 from their style were probably built in the site.
Associated Historical/ Cultu	ral Events or Individual: No	ne
Inscriptions: None		
Architectural Appraisal:		
The two storey end unit buil features include grille patter folding doors and fanlights,	ned balustrades, balcony c	al style with a wide balcony on the first floor. Architectural olumns, shaped veranda brackets, regularly spaced se tiles.
Interior: Not Accessible		
Existing Condition: Good		
Modifications: Exterior has h	-	and dried shrimp shop (formerly grocery store) and
<image/>		

Ref: T39	Title: Shop House	Category: Commercial and Residential		
Address: No. 1 Tai O Marke	t Street	Figure Ref: Figure 10.11		
Orientation: East		Grading: Grade 2		
Surrounding Environment:	/illage houses and shops			
Historical Appraisal:				
The lot and premises have	been in the Yun/Yuen family	and the land lease of this lot dates back to that period. for the entire period. A photograph from the 1950's ing site for fishing boat accessories such as oars and		
The rows of buildings on bo No. 1 from its style was pro site.	th sides of the street have be bably built in the 1930's or si	een for the most part retained and contain group value. milar date and was probably the original building on the		
Associated Historical/ Cultu	ral Events or Individual: None	e		
Inscriptions: None				
Architectural Appraisal:				
a balustrade and cantilevere gable end, grille work balco framed and green in colour.	The architectural style is Balcony Shophouse. The two storey end unit building is built in Neo-Classical style with a balustrade and cantilevered balcony on the first floor. Architectural features also include a pedimented style gable end, grille work balcony. The exterior walls are rendered and painted white and the windows are metal framed and green in colour.			
Interior: Not Accessible				
Existing Condition: Good				
	mmercial (currently ground fleat timber yard and also dried s	oor contains a restaurant and upper floor appears seafood shop.		
Modifications: No major mo	difications.			
<text></text>				

Ref: T-40	Title: Shop House	Category: Commercial and Domestic
Address: Nos. 7, 9, 11 &13	Tai O Market Street	Figure Ref: Figure 10.11
Orientation: East		Grading: Grade 2
Surrounding Environment: S	Shop houses of Market Stre	et
Historical Appraisal:		
	ned and contain group value). The rows of buildings on both sides of the street have e. From their style were probably built in the 1930's and
Associated Historical/ Cultu	ral Events or Individual: Nor	ne
Inscriptions: None		
Architectural Appraisal:		
	dows on the upper floor are	cony Style Shophouses with balustraded and cantilevered a mixture of older wooden framed units with some
Interior: Not Accessible		
Existing Condition: Good		
Past and Present Uses: Cor	mmercial and residential	
Modifications: None		
Photographic Record:		

Ref: T-41	Title: Shop House	Category: Commercial and Domestic
Address: No. 17 Tai O Mark	ket Street	Figure Ref: Figure 10.11
Orientation: East		Grading: Grade 2
Surrounding Environment: S	Shop houses of Market Stree	t (Modern buildings on either side)
Historical Appraisal:		
		nuk Pang of Yuen Long. It was transferred in 1924 to a nanged hands to various other owners over the years.
Associated Historical/ Cultu	ral Events or Individual: None	9
Inscriptions: None		
Architectural Appraisal:		
Balcony Shophouse style be keystone patterns supported Interior: Not Accessible		with ornamental canopy with flattened arches and
Existing Condition: Good		
-	mmercial and residential (gro	ound floor appears to be vacant, first floor seems in use
as a flat)	initicidal and residential (gro	
Modifications: Façade has r inserted across the ground		d windows on upper floor) Metal shutter has been
Photographic Record:		

Ref: T-42	Title: Shop/ factory	Category: Commercial
Address: Behind No. 20 Tai O Market Street		Figure Ref: Figure 10.11
Orientation: Northeast		Grading: Nil Grade
Surrounding Environment: I	n open area in front of Kwan	Tai and Tin Hau Temples
Historical Appraisal:		
the street has over 200 year		en established probably in the Qing Dynasty. Therefore, ivities were/are the dominate economy of this area. The street.
Associated Historical/ Cultu	ral Events or Individual: None	e
Inscriptions: None		
Architectural Appraisal:		
Rectangular single storey b covering.	uilding with pitched tile roof.	Walls of building have wooden, metal and render exterior
Interior: Not Accessible		
Existing Condition: Poor		
Past and Present Uses: Sho	op (Currently vacant, appears	s to have been closed up for some time)
Modifications: Metal shutter	and sheets of metal have be	een used to cover the exterior.
Photographic Record:		

l

Ref: T-43	Title: Shop House	Category: Commercial and Domestic
Address: No. 14 Tai O Market Street		Figure Ref: Figure 10.11
Orientation: East		Grading: Grade 2
Surrounding Environment:	Shop houses of Market Stree	bt
Historical Appraisal:		
is not known if it was a repl was first leased to promine	acement for an earlier structu	ut the style of No. 14 dates this structure to the 1930's. It ure or if it was the first building on the site. The building han Fuk Lung, but was transferred to the Cheung family over the years.
Associated Historical/ Cultu	ral Events or Individual: Non	е
Inscriptions: None		
Architectural Appraisal:		
The building is a Balcony S has casement style window		r balcony with iron grille balustrade. The upper floor also
Interior: Not Accessible		
Existing Condition: Good		
Past and Present Uses: Co	mmercial/ Residential	
Modifications: Metal shutter	across ground floor façade.	
Photographic Record:		

Ref: T-44	Title: Kwan Tai Temple	Category: Religious, Ritual and Funerary	
Address: Beside No. 32 Kat Hing Back Street		Figure Ref: Figure 10.11	
Orientation: Southeast		Grading: Grade 2 Historic Building	
Surrounding Environment: S	Shops and residences of Kat	Hing Back Street	
Historical Appraisal:			
The temple dates to the 6 th	year of the Qianlong Reign o	f the Qing Dynasty (1741).	
Associated Historical/ Cultu	ral Events or Individual: None	9	
Inscriptions: 乾隆 (inscrib	ed on a bell) and	廟 古 帝 關	
	大	威	
	義	名	
	本	震	
	春		
	秋		
Architectural Appraisal:	12		
courtyard originally open has now been covered. It is constructed of green brick walls with a pitched roof of clay tiles with wooden support structures. The main ridge is with Shiwan (石 灣) ceramics made by the Gungyuk (均 Ξ) kiln in the 25th year of the Guangxu (光 緒, 1899) reign. They include a set of Two Phoenixes Adorning the Sun (雙 鳳 朝 陽), Yeung's Military Family (楊 家 將), two <i>aoyus</i> (鰲 魚), a pearl and two unicorns. The descending ridges are with <i>ruilongs</i> (夔 龍) mouldings. The wall friezes are with landscape and figure paintings and reliefs. Its fascia boards are with flowers, plants and figures carvings.			
Interior: The middle bay of the main hall houses the statue of Kwan Tai for worship. The altar of the left bay houses Tai Sui (太 歲), God of Wealth (財 帛 星 君) and Tai San (太 神) whilst that of the right bay houses Wah Tor (華 陀). Some other deities are also worshipped at the temple including Kwan Ping (關 平), Wong Ling Kwun (Ξ 靈 官), Yue Tau Tai Wong (魚 頭 大 王) and others.			
Existing Condition: Good	Existing Condition: Good		
Past and Present Uses: Ter	mple		
Modifications: The temple v	was renovated in 1741, 1835	, 1852, 1903, 1959.1975, 1987 and 1997	
Photographic Record: (Pho	Photographic Record: (Photography inside the temple was not permitted)		

Ref: T-45	Title: Tin Hau Temple	Category: Religious, Ritual and Funerary
Address: Beside Tai O Rural Committee Building (Kat Hing Back Street)		Figure Ref: Figure 10.11
Orientation: Southeast		Grading: Grade 3 Historic Building
Surrounding Environment:	Shops and residences of Kat	Hing Back Street.
Historical Appraisal: The Tin Hau temple which the Qing Dynasty (1772). It	is connected to the Kwan Tai has a long association with th	temple was built in the 37 th year of the Qianlong Reign of the fishermen and their families in Tai O.
	iral Events or Individual: None	9
Inscriptions:	~ ~	
	合天	
母儀稱后桑榆俎豆重光	水德配天海國慈航並濟	
Architectural Appraisal:		
It is a Qing Vernacular building of two hall and one courtyard plan. The open courtyard between the entrance and main hall has been covered with a tiled roof. The building is constructed of green bricks with its walls to support its roofs of timber rafters, purlins and clay tiles. The walls have been plastered. Its doorframe and lower courses of the front wall are of granite. Interior: The altar at the end wall of the main hall houses a statue of the Tin Hau deity for worship with an offering in its front. A standing statue of Qianliyan (千里眼) and of Shunfenger (順風耳) are respectively on the left and right of the hall. An altar of the Door God (門神) and another altar of the Earth God (土地) are on the left and right of the entrance hall. The front ridge is decorated with a red <i>ruilong</i> (夔龍) mouldings at its two ends with lion mouldings in the middle. A fascia board under the front eave is of flowers, birds and bats carvings. The name of the temple is engraved above the lintel flanked by wall paintings of figures and landscape. The upper portion of the front wall is covered with white ceramic tiles.		
Existing Condition: Good		
Past and Present Uses: Temple		
Modifications: The temple has undergone renovations in 1835, 1852, 1903, 1959, 1975, 1987 and 1997. Photographic Record: Photography inside the temple was not permitted		

Ref: T-46	Title: Earth Shrine	Category: Religious, Ritual and Funerary
Address: On east exterior w Building (Kat Hing Back Stre		Figure Ref: Figure 10.11
Orientation: Southeast		Grading: Nil Grade
Surrounding Environment: T Building	Fin Hau and Kwan Tai Templ	les, the shrine is at the side of the Rural Committee
Therefore, the street has ov area. The shrine was proba years ago.	er 200 years of history. Com	en established probably in the early Qing Dynasty. Imercial activities were/are the dominate economy of this s established. Thus, it was constructed probably over 100
Inscriptions: None		-
Architectural Appraisal:		
Small concrete square box in the opening and incense		t red. Flat roof. The interior has many small idols placed
Interior: N/A		
Existing Condition: Good		
Past and Present Uses: Shi	rine	
Modifications: None		
Photographic Record:		
<image/>		

Ref: T-47	Title: Restaurant	Category: Commercial
Address: No. 42 Kat Hing Street		Figure Ref: Figure 10.11
Orientation: Northwest		Grading: Nil Grade
Surrounding Enviro	onment: Shops and residences of	FKat Hing Street. The back of the building opens onto the
Historical Appraisa	l:	
Kat Hing Street ha this period, but from	s buildings dating back to the 193 n its style it is probably over 50 ye	30's or earlier. There is no evidence that this building dates to ears old.
Associated Historie	cal/ Cultural Events or Individual:	None
Inscriptions: None		
Architectural Appra	aisal:	
Rectangular single	storey structure with tile roof. Fa	çade walls are wooden shutters and ventilation slats.
Interior: Plain conc	rete floors with plastered walls (k	itchen at rear).
Existing Condition:	Fair	
Past and Present	Jses: Restaurant	
Modifications: The	floor has been covered by concre	ete.
Photographic Reco	ord:	

Ref: T-48A and 48B	Title: Shop / Residential	Category: Commercial and Domestic	
Address: Nos. 46 & 48 Kat Hing Street		Figure Ref: Figure 10.11	
Orientation: Northwest		Grading: Grade 3 Historic Building	
Surrounding Environment:	Shops and residences of Kat	t Hing Street	
Historical Appraisal:			
purposes. Possessed by th the owner for living accomm	e Ip family, the ground floor	ound 1930) that serves both commercial-cum-residential is rented out for business, while the upper floor is held by	
Inscriptions: None			
Architectural Appraisal:			
of architecture is known as rectangular shape going ba pavement and are supporte of the verandahs are flat. T	The most significant feature of the tenement is the colonial veranda with segmental arch at the end and the style of architecture is known as a verandah style shop house. The typical style is a narrow façade with a long rectangular shape going back to the water. The first floor verandahs at the front are cantilevered over the pavement and are supported at each side by triangular shaped brackets known as "gallows" brackets. The roofs of the verandahs are flat. The construction appears to be reinforced concrete.		
Interior: Not Accessible			
Existing Condition: Fair			
Past and Present Uses: Re	sidential		
	Modifications: Metal shutters across ground floor façade of No. 46 and modern metal balustrade across the balcony on the first floor of number 48.		
Photographic Record:			

T No. 46 Kat Hing Street (T48A)

No. 48 Kat Hing Street (T48B)

XA

Ref: T-49	Title: Shop House	Category: Commercial / Residential	
Address: Nos. 60 Kat Hing	Street	Figure Ref: Figure 10.11	
Orientation: Northwest		Grading: Grade 2	
Surrounding Environment:	Shops and residences of Ka	t Hing Street	
Historical Appraisal:			
floor as a clothing shop bet	ween the 1930's and the 19 er floor was lived in by the or	y. The upper floor was used as a residence and the ground 50's. The ground floor was later leased out as a iginal builders until their deaths some years ago. The	
Associated Historical/ Cultu	ral Events or Individual: Nor	ne	
Inscriptions: None			
Architectural Appraisal:			
		e Eclectic elements. The first floor balcony is made of a rendered and painted a cream colour and the roof is	
Interior: Not Accessible			
Existing Condition: Good			
Past and Present Uses: Co floor appears closed up.	mmercial/ Residential. Grou	ind floor appears to be currently used for storage, upper	
Modifications: Metal shutter	r and awning on ground floo	r of the façade.	
Photographic Record:			
Façade and side of No. 60		We	

View of the wooden shutter door on No. 60 Kat Hing Street

Ref: T-50	Title: Shek Lun Kok	Category: Domestic		
Address: No. 33 Kat Hing Back Street (Shek Lun Kok)		Figure Ref: Figure 10.9		
Orientation: Southeast		Grading: Grade 3 Historic Building		
Surrounding Environmen	t: Village houses	I		
Historical Appraisal:				
Tai O. It was owned by T scheme and school scho Japanese's military head Board of Supervisors of t	sang Yung, who contribute larships. During the Japan quarters and later was han he Kowloon Chamber of C	w building, is the most visually prominent residential block in ed to the development of Tai O like donating to street lighting ese Occupation, the Building was once used as the ided back to Tsang Yung, who became the Chairman of the ommerce in 1940. In 1980's, the building was named as Shek owner, Wong's family. It was built in 1934.		
Associated Historical/ Cu	Itural Events or Individual:	None		
Inscriptions: None				
Architectural Appraisal:				
façades at first floor level At roof level there is a roo	It is a four-storey residential building with a mezzanine, with colonnaded verandah along the north and east façades at first floor level, giving a colonial appearance reminiscent of Portuguese or Mediterranean architecture. At roof level there is a roof terrace, water tank, and chimney stack serving the ground floor kitchen. The décor internally is in the minimalist style of the 1930s. Architectural style can be classified as Modern Eclectic.			
Layout: A four-storey rec	tangular layout structure in	cluding a mezzanine		
Construction Material: Re	einforced concrete			
Roof: Flat roof Windows: Metal framed casement windows Walls: Rendered and white painted walls Doors: Wooden				
Decorative Features: Col Interior: Not Accessible	onnaded veranda along th	e north and east façades at first floor level		
Existing Condition: Good				
Past and Present Uses: F	Past and Present Uses: Residential (was used as a recycling facility in the past)			
Modifications: None				
Photographic Record:				

Ref: T-51	Title: Village House	Category: Domestic
Address: Beside No. 39 Kat Hing Back Street		Figure Ref: Figure 10.9
Orientation: Southeast		Grading: Nil Grade
Surrounding Environment:	/illage houses	
Historical Appraisal:		
	rs of history. Commercial a	been established probably in the Qing Dynasty. Therefore, activities were/are the dominate economy of this area. The ne street.
Associated Historical/ Cultu	ral Events or Individual: No	one
Inscriptions: None		
Architectural Appraisal:		
Grey brick single storey stru	acture in ruinous condition,	roof has collapsed overgrown with vegetation.
Interior: Ruinous		
Existing Condition: Ruin		
Past and Present Uses: Re	sidential, currently abando	ned.
Modifications: None		
Photographic Record:		

Ref: T-52	Title: Village House	Category: Domestic
Address: No. 43 Kat Hing Back Street		Figure Ref: Figure 10.9
Orientation: Southeast		Grading: Nil Grade
Surrounding Environment:	Village houses	1
Historical Appraisal:		
the street has over 200 year	ling Back Street area has been rs of history. Commercial act ining historic buildings of the ining historic buildings of the	en established probably in the Qing Dynasty. Therefore, tivities were/are the dominate economy of this area. The e street.
Associated Historical/ Cultu	ral Events or Individual: Non	e
Inscriptions: None		
Architectural Appraisal:		
Single storey rectangular sl		açade wooden shutter and wooden slats above. Low ers at either end of the façade.
Interior: Not Accessible		
Existing Condition: Fair		
Past and Present Uses: Re	sidential	
Modifications: None		
Photographic Record:		

Ref: T-53	Title: Earth Shrine	Category: Religious, Ritual and Funerary		
ddress: Behind No. 56 Kat Hing Street		Figure Ref: Figure 10.9		
Orientation: East		Grading: Nil Grade		
Surrounding Environment:	Surrounding Environment: Village houses			
Historical Appraisal:				
the street has over 200 year	ars of history. Commercial I to the current location du	been established probably in the Qing Dynasty. Therefore, activities were/are the dominate economy of this area. The ring the mid-20th century or later.		
Inscriptions: None				
Architectural Appraisal:				
		h three side walls and an open front covered by a wire e is a concrete burner beside the shrine		
Interior: N/A				
Existing Condition: Fair				
Past and Present Uses: Sh	rine			
Modifications: None				
Photographic Record:				

Ref: T-54	Title: Earth Shrine	Category: Religious, Ritual and Funerary
Address: To the Northwest of No. 69 Kat Hing Back Street		Figure Ref: Figure 10.9
Orientation: East		Grading: Grade 3
Surrounding Environment: V	/illage houses	
Historical Appraisal:		
location or if the shrine was	moved here from another lo	ce before 1899. It is not known if this is the original cation. The origin of the dog and history of dog worship is ent times of the Yao and She tribes incorporating dog
a connection with Buddhism		the granite slab inscription shows there may have been
Associated Historical/ Cultu	rai Events or Individual: Non	e
Inscriptions: 南無阿彌陀佛(Namo Amitābhā)	
Architectural Appraisal:		
	ns a granite dog statue, an in	ing that been bent into a rounded shape to act as walls scribed rectangular tablet and also a triangular shaped
Decorative Features: Stone	Dog	
Interior: N/A		
Existing Condition: Fair		
Past and Present Uses: Shi	rine/ Earth God Shrine	
Modifications: None		
<image/>		

Ref: T-55	Title: Chong Long She (創龍社)	Category: Religious, Ritual and Funerary	
Address: Between Nos. 77 & 79 Kat Hing Back Street		Figure Ref: Figure 10.9	
Orientation: East		Grading: Nil Grade	
Surrounding Environment:	Village houses		
Historical Appraisal:			
the street has over 200 yea shrine was built to worship established.	rs of history. Commercial act the earth deity. It was probab	en established probably in the Qing Dynasty. Therefore, ivities were/are the dominate economy of this area. The ly constructed when the settlement of the street was	
Associated Historical/ Cultu Inscriptions:	ral Events or Individual: Non	9	
社龍創	A.I.		
	創		
	至		
	善善		
棲	地		
Architectural Appraisal:			
The shrine is an one hall and square shaped structure. The walls of the shrine are made of bricks and painted in red. The roof of the shrine is timber beam with modern green glaze clay tile pitched roof. No windows are found and the door is made of wood.			
	op of the side walls and roof r painted red, tile floor with alt		
Existing Condition: Good			
Past and Present Uses: Shi	rine		
Modifications: Recently rend Photographic Record:	ovated		

Ref: T-56	Title: Village House	Category: Domestic
Address: No. 77 Kat Hing Back Street		Figure Ref: Figure 10.9
Orientation: East		Grading: Nil Grade
Surrounding Environment:	Village houses	
Historical Appraisal:		
the street has over 200 yea	ling Back Street area has been rs of history. Commercial act ining historic buildings of the ining historic buildings of histori	en established probably in the Qing Dynasty. Therefore, ivities were/are the dominate economy of this area. The street.
Associated Historical/ Cultu	ral Events or Individual: Non	е
Inscriptions: None		
Architectural Appraisal:		
Layout: Rectangular layout	village house	
Construction Material:		
Roof: Timber beams with cl Windows: Wooden framed Walls: Grey or mud bricks [and grille window	
Decorative Features: Nil Interior: Not Accessible		
Existing Condition: Fair		
Past and Present Uses: Re	aidantial	
Modifications: Metal door at		
	l entrance.	

Ref: T-57	Title: Fuel Storage Building	Category: Commercial
Address: Between nos. 81 & 86 Kat Hing Back Street		Figure Ref: Figure 10.9
Orientation: Northeast		Grading: Nil Grade
Surrounding Environment: I	n an overgrown area between v	village houses
Historical Appraisal:		
The parapet on the front of	the building has a date of 1965	and the building probably was constructed at this time.
Associated Historical/ Cultu	ral Events or Individual: None	
Inscriptions: None		
Architectural Appraisal:		
	storey building with parapet at	t front entrance with date of 1965. It is of a similar style
to the Wing Hing petrol stat	ion building.	
Interior: Not Accessible		
Existing Condition: Fair		
Past and Present Uses: For	storage of gas canisters (curre	ently not in use and closed up)
Modifications: None		
Photographic Record:		
		and the second sec
		and the second
	TAC	
		1 ***
	1 1. 2	# 1876
	Harris T	THE T
- 1/10		
A TALE		

Ref: T-58	Title: Gate	Category: Domestic
Address: Near Nos. 86 & 87 Kat Hing Back Street		Figure Ref: Figure 10.9
Orientation: Northeast		Grading: Nil Grade
Surrounding Environment: V	Vooded hill slope behind and	d village houses sides and in front
Historical Appraisal:		
The Garden is believed to d was abandoned about 30 ye area.	ate back to the 1950's accor ears ago. An interesting relic	ding to local informants. It was a garden and orchard that of the area, no other such features were found in the
Associated Historical/ Cultur	ral Events or Individual: None	9
Inscriptions: None		
Architectural Appraisal:		
Decorative two pillar gate w	ith flat top, elaborate dragon	motifs on the pillars. Metal bar gate between the pillars.
Interior: N/A		
Existing Condition: Fair		
Past and Present Uses: Ent	rance gate to hill side garder	n in the 1950's (currently abandoned)
Modifications: None		
Photographic Record:		

Ref: T-59	Title: Wing Hing Petrol Station	Category: Commercial
Address: No. 99C Kat Hing Back Street		Figure Ref: Figure 10.6
Orientation: Southwest		Grading: Grade 3 Historic Building
Surrounding Environment: Situated along the main feetra		ath with village houses in the visinity

Surrounding Environment: Situated along the main footpath with village houses in the vicinity

Historical Appraisal:

The building was built before 1941 for the storage of kerosene and has also been referred to as Fo Shui Chong by the local population. The first owner was Chan lu and he sold the building to Lau U-ming in 1948, but the ownership was transferred back to Chan lu in the same year. After the 1960's the building was mainly used for the storage of LPG instead of kerosene. The building remains to be owned by members of Chan lu's family

Associated Historical/ Cultural Events or Individual: None

Inscriptions:

倉油火慶永

Architectural Appraisal:

It is a small one storey structure with a flat roof, there is a concrete ramp leading up to the front entrance and the compound is enclosed by a thick concrete wall. The architectural style of the building is Utilitarian.

Interior: Not Accessible

Existing Condition: Good

Past and Present Uses: Fuel and flammable goods storage.

Modifications: None

Photographic Record:



Ref: T-60	Title: Earth Shrine	Category: Religious, Ritual and Funerary
Address: Near BBQ Area on path to Yeung Hau Temple		Figure Ref: Figure 10.6
Orientation: South		Grading: Nil Grade
Surrounding Environment:	Set in an open area with som	e woodland and scattered houses.
Historical Appraisal:		
the street has over 200 year	irs of history. Commercial act	en established probably in the Qing Dynasty. Therefore, ivities were/are the dominate economy of this area. The ed. Thus, it was constructed probably over 100 years
Associated Historical/ Cultu	ral Events or Individual: Non	e
Inscriptions: None		
Architectural Appraisal:		
Small concrete box shaped the shrine. Both are painted		ont and flat roof. There is a small square burner beside
Interior: N/A		
Existing Condition: Good		
Past and Present Uses: Sh	rine	
Modifications: The current	shrine is covered with concret	te coating/ no renovation or reconstruction date available.
Photographic Record:		

Ref: T-61	Title: Village House	Category: Domestic
Address: No. 95 Kat Hing B	ack Street	Figure Ref: Figure 10.6
Orientation: North		Grading: Nil Grade
Surrounding Environment:	On village path, relatively op	en with wooded hill behind.
Historical Appraisal:		
Therefore, the street has ow		en established probably in the early Qing Dynasty. Inmercial activities were/are the dominate economy of this lings of the street.
Associated Historical/ Cultu	ral Events or Individual: Nor	le
Inscriptions: None		
Architectural Appraisal:		
with a grey render coating. floor (there is a wooden bal	The façade has a recessed	on on western side. The building is constructed of bricks central section with wooden doors on ground and first floor façade. The windows have wooden shutters and the tiled.
Interior: Not Accessible		
Existing Condition: Good		
Past and Present Uses: Re	sidential (Currently closed u	p)
Modifications: None		
Photographic Record:		

Ref: T-62	Title: Earth Shrine	Category: Religious, Ritual and Funerary
Address: To the north of No (on side of footpath)	o. 95 Kat Hing Back Street	Figure Ref: Figure 10.6
Orientation: Northeast		Grading: Nil Grade
Surrounding Environment:	Village houses, garden	
Historical Appraisal:		
the street has over 200 year	ars of history. Commercial ac	en established probably in the Qing Dynasty. Therefore, tivities were/are the dominate economy of this area. The ned. Thus, it was constructed probably over 100 years
Associated Historical/ Cultu	ural Events or Individual: Nor	ne
Inscriptions: None		
Architectural Appraisal:		
Small concrete base shrine enclosure.	e with metal sheeting over the	e top. Small incense holder and rounded stone in
Interior: N/A		
Existing Condition: Good		
Past and Present Uses: Sh	rine	
Modifications: None		
Photographic Record:		

Ref: T-63	Title: Village House	Category: Domestic	
Address: No. 98 Kat Hing E	ack Street	Figure Ref: Figure 10.9	
Orientation: West		Grading: Nil Grade	
Surrounding Environment:	/illage houses		
the street has over 200 yea structure is one of the rema	rs of history. Commercial a ining historic buildings of th	een established probably in the Qing Dynasty. Therefore, ctivities were/are the dominate economy of this area. The le street.	
Associated Historical/ Cultu	rai Events or Individual:		
Inscriptions: None			
Architectural Appraisal: Layout: A rectangular layou	t village house built with sh	ared gable walls with nearby houses	
Construction Material: Roof: Timber beams with clay title laying pitched roof Windows: Metal framed glass windows Walls: Bricks and cement Doors: Metal			
Decorative Features: Nil Interior: Not Accessible Existing Condition: Fair			
Past and Present Uses: Re	sidential		
Modifications: The exterior	walls have been covered wi	ith concrete and metal doors inserted across the façade.	
Modifications: The exterior walls have been covered with concrete and metal doors inserted across the façade.			

Ref: T-64	Title: Gate Foundation	Category: Domestic
Address: Next to the gate of Pumping Station	f Tai O No.4 Flood	Figure Ref: Figure 10.12
Orientation: N/A		Grading: Nil Grade
Surrounding Environment: p	pumping station, shrine and v	<i>i</i> llage houses
Historical Appraisal:		
The gate was used to prote Occupation in Hong Kong. (ct the street from banditry ar Only the foundation is left be	nd was demolished by the Japanese during the Japanese hind.
Associated Historical/ Cultu	ral Events or Individual: Non	e
Inscriptions: None		
Architectural Appraisal:		
Demolished.		
Interior: N/A		
Existing Condition: Demolished		
Past and Present Uses: Gat	te/ Demolished	
Modifications: Demolished		
Photographic Record:	ows pointing site of former g	ate foundation

Ref: T-65	Title: Shop/ Village House	Category: Commercial and Domestic
Address: No. 83 Kat Hing Back Street		Figure Ref: Figure 10.9
Orientation: West		Grading: Nil Grade
Surrounding Environment:	/illage houses	
Historical Appraisal:		
the street has over 200 yea		n established probably in the Qing Dynasty. Therefore, vities were/are the dominate economy of this area. The street.
Associated Historical/ Cultu	ral Events or Individual: None	9
Inscriptions: None		
Architectural Appraisal:		
Layout: A two-level rectang	ular layout village house built	with shared gable walls with nearby houses
Construction Material:		
Roof: Timber beams with cl pitched roof Windows: Metal framed gla Walls: Bricks and cement D	ss windows	
Decorative Features: Nil Interior: Not Accessible		
Existing Condition: Fair		
	ound floor shop and upper flo	
	inserted across the ground fl	loor façade.
Photographic Record:		

Ref: T-66	Title: Stilt Houses	Category: Domestic	
Address: Opposite to No.90 – 99B Kat Hing Back Street		Figure Ref: 10.9	
Orientation: Southwest		Grading: Proposed to be Graded	
Surrounding Environment: V of stilt houses.	Village houses of Kat Hing Ba	L ack Street and temporary structures	
reputation as the "Little Ven the temporary land-based s have progressively removed manner of boats, are no lon	ice of Hong Kong". It was a c ettlements of boat-based con d such settlements such that ger found elsewhere in Hong		
Associated Historical/ Cultu	ral Events or Individual: None	9	
Inscriptions: None			
Architectural Appraisal:			
The design of the stilted houses is of architectural interest. In addition to the external boat shaped structure of the houses, the interior layout of these buildings also reflects the custom and the life style of the boat people. The materials used to construct these stilted houses also presents the history of coastal relations between Tai O and the surrounding area and are of considerable historic value.Layout: Rectangular shapeConstruction Material: Roof: Metal sheet roof Windows: Metal sheet or glass Walls: Metal sheet Doors: Metal sheet			
Decorative Features: Nil Interior: Not Accessible			
	inte Deser		
Existing Condition: From Fa			
Past and Present Uses: Re	Past and Present Uses: Residential for the Fishermen and their families		
Modifications: None			
Photographic Record:			

Ref: T-67	Title: Stilt Houses	Category: Domestic		
Address: Kat Hing Back Street		Figure Ref: 10.9		
Orientation: West		Grading: Proposed to be Graded		
Surrounding Environment: of stilt houses.	Village houses of Kat Hing Ba	ack Street and temporary structures		
Historical Appraisal:				
reputation as the "Little Ver the temporary land-based s have progressively removed manner of boats, are no lor	nice of Hong Kong". It was a context ettlements of boat-based cond d such settlements such that ager found elsewhere in Hong	_		
Associated Historical/ Cultu	ral Events or Individual: None	9		
Inscriptions: None				
Architectural Appraisal:				
houses, the interior layout of materials used to construct	The design of the stilted houses is of architectural interest. In addition to the external boat shaped structure of the houses, the interior layout of these buildings also reflects the custom and the life style of the boat people. The materials used to construct these stilted houses also presents the history of coastal relations between Tai O and the surrounding area and are of considerable historic value.			
Layout: Rectangular shape				
Construction Material: Roof: Metal sheet Windows: Metal sheet Walls: Metal sheet Doors: Metal sheet				
Decorative Features: Nil				
Interior: Not Accessible				
Existing Condition: Good				
Past and Present Uses: Residential for the Fishermen and their families				
Modifications: None	Modifications: None			
Photographic Record:				

Ref: T-68	Title: Earth Shrine	Category: Religious, Ritual and Funerary
Address: To the east of No.	111 Shek Tsai Po Street	Figure Ref: Figure 10.8
Orientation: Southwest		Grading: Nil Grade
Surrounding Environment:	Foot path and stone wall.	1
Historical Appraisal:		
The shrine is modern and r	nay be a replacement for an	earlier shrine. Age is unknown.
Associated Historical/ Cultu	ral Events or Individual: Non	e
Inscriptions: None		
Architectural Appraisal:		
The shrine is a rectangular	niche set into a modern ston	e wall with a rounded stone set in the middle.
Interior: N/A		
Existing Condition: Good		
Past and Present Uses: Sh	rine	
Modifications: None		
Photographic Record:		

Ref: T-69	Title: Shop/ Residential	Category: Commercial and Domestic	
Address: Nos. 109, 110 & 111 Shek Tsai Po Street		Figure Ref: Figure 10.8	
Orientation: Southwest	t	Grading: Nil Grade	
Surrounding Environment: Open area with village houses along the waterfront side.			
Historical Appraisal:			
From the style of the b	uildings they probably date from	the mid- Twentieth Century.	
Associated Historical/	Cultural Events or Individual: No	ne	
Inscriptions: None			
Architectural Appraisal:			
Two storey shop house style buildings (3 terrace units). Concrete construction. Ground floor has metal and wooden shutter gates, all windows are metal framed. There is a balcony running across the length of the first floor façade. Flat roof.			
Interior: Not Accessible			
Existing Condition: Fair to poor			
Past and Present Uses: Commercial and residential, currently abandoned and hoarding has been placed across the front of the ground floor entrances.			
Modifications: Various modernisation features appear to have been carried out on the units over time.			
Photographic Record:			



Ref: T-70	Title: Village House	Category: Domestic		
Address: No. 97A Shek Tsa	ai Po Street	Figure Ref: Figure 10.8		
Orientation: South		Grading: Nil Grade		
Surrounding Environment:	Surrounding Environment: Set back from the foot path in a wooded and overgrown area.			
Historical Appraisal:				
The house is in very poor c would probably date it as a	condition and appears to ha pre-WWII structure.	we been abandoned for some time. The style of the building		
Associated Historical/ Cultu	ural Events or Individual: No	one		
Inscriptions: None				
Architectural Appraisal:				
		of Chinese and Western Architectural features. Mud brick ndows, First floor façade has a balcony running across with		
Interior: Not Accessible				
Existing Condition: Ruin				
Past and Present Uses: Re	sidential, currently abando	ned.		
Modifications: None				
Photographic Record:				

Ref: T-71	Title: Earth Shrine	Category: Religious, Ritual and Funerary		
Address: In front of No. 91A Shek Tsai Po Street		Figure Ref: Figure 10.8		
Orientation: South		Grading: Nil Grade		
Surrounding Environment:	/illage houses			
Historical Appraisal:				
The original shrine was prol 100 years.	pably constructed at the time	when the area was settled which may date back over		
Associated Historical/ Cultu	ral Events or Individual: Non	e		
Inscriptions:				
Parapet:	爺地土			
	爺爺地土			
地 靈 人 傑 通 四 海	地 土 靈 運 人 生 傑 金 通 財 四 興 海 旺			
	爺爺地土 on drapes inside th	ne shrine		
Architectural Appraisal:				
The shrine is rectangular ar candles.	The shrine is rectangular and covered in red tiles. The altar is elaborately decorated with hangings and electrical candles.			
Interior: N/A				
Existing Condition: Good				
Past and Present Uses: Shi	rine			
Modifications: The current s	hrine is covered with tile coa	ting/ no renovation or reconstruction date available.		
Photographic Record:				

Ref: T-72	Title: Earth Shrine	Category: Religious, Ritual and Funerary	
Address: In front of No	o. 52 Shek Tsai Po Street	Figure Ref: Figure 10.7	
Orientation: South		Grading: Nil Grade	
Surrounding Environn	aanti Villaga hayaaa		
•	ient. village nouses		
Historical Appraisal:			
The original shrine wa 100 years.	is probably constructed at the tim	ne when the area was settled which may date back over	
Associated Historical/	Cultural Events or Individual: No	one	
Inscriptions: None			
Architectural Appraisa	l:		
Small rectangular box	with small burner attached to on	e side (both painted red). Simple platform with alter inside.	
Interior: N/A			
Existing Condition: Go	Existing Condition: Good		
Past and Present Use	s: Shrine		
Modifications: The current shrine is covered with concrete coating/ no renovation or reconstruction date available.			
Photographic Record:			

(

Ref: T-73	Title: Well	Category: Domestic
Address: Behind No. 6 Shek Tsai Po		Figure Ref: Figure 10.7
Orientation: N/A		Grading: Nil Grade
Surrounding Environment: (Garden	
Historical Appraisal:		
the village is not known. Ho	wever, the Hung Shing Temp ch indicates the existence of	, Yip 葉, So 蘇, and Tsoi 蔡. The establishment date of ole in Shek Tsai Po was construction in the 11th year of settlement in the area. Therefore, the village of Shek
probably over 100 years old		in Shek Tsai Po was established. Therefore, the well is
Associated Historical/ Cultu	ral Events or Individual: None	e
Inscriptions: None		
Architectural Appraisal:		
The well is probably made of	of stone. However, the owner	of the land did not permit for further inspection.
Decorative Features: Nil Interior: N/A		
Existing Condition: Fair		
Past and Present Uses: We	ll (Currently not in use)	
Modifications: None		
Photographic Record:		

Ref: T-74	Title: Well	Category: Domestic
Address: Behind No. 19 Shek Tsai Po		Figure Ref: Figure 10.7
Orientation: N/A		Grading: Nil Grade
Surrounding Environment:	village houses in front garde	n overgrown area behind
Historical Appraisal:		
the village is not known. He	owever, the Hung Shing Tem ich indicates the existence of	3, Yip 葉, So 蘇, and Tsoi 蔡. The establishment date of ple in Shek Tsai Po was construction in the 11th year of settlement in the area. Therefore, the village of Shek
The well was constructed p probably over 100 years of		in Shek Tsai Po was established. Therefore, the well is
Associated Historical/ Culti	ural Events or Individual: Nor	ie
Inscriptions: N/A		
Architectural Appraisal:		
The shaft of the well is made	de of stone and covered with	concrete at surface.
Decorative Features: Nil Interior: N/A		
Existing Condition: Good		
Past and Present Uses: W		
Modifications: Concrete su	rface and sides on well.	
Photographic Record:		

Ref: T-75	Title: Earth Shrine	Category: Religious, Ritual and Funerary
Address: Next to No. 34 Shek Tsai Po		Figure Ref: Figure 10.10
Orientation: South		Grading: Nil Grade
Surrounding Environment:	/illage houses	
Historical Appraisal:		
the village is not known. Ho	wever, the Hung Shing Tem ch indicates the existence of	³ , Yip 葉, So 蘇, and Tsoi 蔡. The establishment date of ple in Shek Tsai Po was construction in the 11th year of f settlement in the area. Therefore, the village of Shek
is probably over 100 years	old.	ent in Shek Tsai Po was established. Therefore, the shrine
Associated Historical/ Cultu	ral Events or Individual: Nor	ne
Inscriptions: None		
Architectural Appraisal:		
	n shrine is made of stone. A f statues were placed on the	stove is found in front of the shrine. A piece of stone e altar for worshipping.
Decorative Features: Nil		
Interior: N/A		
Existing Condition: Fair		
Past and Present Uses: Sh	rine	
Modifications: None		
Photographic Record:		

Ref: T-76	Title: Village House	Category: Domestic	
Address: No. 44 Shek Tsai	Po	Figure Ref: Figure 10.10	
Orientation: Southeast		Grading: Nil Grade	
Surrounding Environment: V	/illage houses, near the coa	ast.	
Historical Appraisal:			
the village is not known. Ho the reign of Qian Long, whic Tsai Po may have over 200	wever, the Hung Shing Ten ch indicates the existence o years of history. The site is	w, Yip 葉, So 蘇, and Tsoi 蔡. The establishment date of nple in Shek Tsai Po was construction in the 11th year of f settlement in the area. Therefore, the village of Shek s one of the remaining historic buildings in the village.	
Associated Historical/ Cultu	ral Events or Individual: No	ne	
Inscriptions: None			
Architectural Appraisal:			
Layout: Rectangular layout	village house		
Construction Material:			
Roof: Timber beams with clay title laying pitched roof Windows: Wooden framed and metal barred window Walls: Grey or mud bricks and stones Doors: Wooden and metal gate			
Decorative Features: Nil			
Interior: Not Accessible			
Existing Condition: Fair			
Past and Present Uses: Rea	sidential		
Modifications: Exterior walls	have been painted white		
Photographic Record:			

Ref: T-77	Title: Earth Shrine	Category: Religious, Ritual and Funerary
Address: Next to No. 21 Shek Tsai Po		Figure Ref: Figure 10.10
Orientation: Southeast		Grading: Nil Grade
Surrounding Environment:	Village houses	
Historical Appraisal:		
the village is not known. Ho	owever, the Hung Shing Temp ch indicates the existence of	, Yip 葉, So 蘇, and Tsoi 蔡. The establishment date of ole in Shek Tsai Po was construction in the 11th year of settlement in the area. Therefore, the village of Shek
the shrine indicates the shr	I probably when the settleme ine was already in existence iral Events or Individual: Non	nt in Shek Tsai Po was established. The head stone of in 1834. e
Inscriptions:		
X 道 X 道 X 光 社 丹 歴 冬 應 月 大 修 王		
Architectural Appraisal:		
The arm-chair-shaped shrir	ne is made of bricks. A head s	stone is placed on the altar for worshipping.
Decorative Features: Nil Interior: N/A		
Existing Condition: Fair		
Past and Present Uses: Sh	ripo	
been added since the 2011		set of concrete steps and new burner (painted red) have
Photographic Record:		

Ref: T-78	Title: Well and Shrine	Category: Domestic and Religious, Ritual and Funerary
Address: Next to No. 72 Shek Tsai Po		Figure Ref: Figure 10.10
Orientation: Southwest		Grading: Nil Grade
Surrounding Environment:	Village houses	
Historical Appraisal:		
the village is not known. He	owever, the Hung Shing Tem ch indicates the existence of	, Yip 葉, So 蘇, and Tsoi 蔡. The establishment date of ple in Shek Tsai Po was construction in the 11th year of settlement in the area. Therefore, the village of Shek
associated shrine were pro	bably constructed when the s	in Shek Tsai Po was established The well and the settlement in Shek Tsai Po was established.
Associated Historical/ Cult	ural Events or Individual: Non	e
Inscriptions: None		
Architectural Appraisal:		
with the well. The arm-chai		vith wooden grille. An earth shrine is found associated e of bricks and the surface is covered by concrete. A shipping.
Decorative Features: Nil		
Interior: N/A		
Existing Condition: Fair		
Past and Present Uses: We	ell and Shrine	
Modifications: A new metal placed over the shrine.	grille cover has been placed	over the top of the well. Arched sheet of metal has been
Photographic Record:		
Well and Shrine in Novemb	With the second secon	Well and Shrine in April 2013

Ref: T-79	Title: Village House	Category: Domestic	
Address: No. 21 Shek Tsai Po		Figure Ref: Figure 10.10	
Orientation: Southeast		Grading: Nil Grade	
Surrounding Environment:	Village houses		
Historical Appraisal:			
the village is not known. Ho the reign of Qian Long, whi Tsai Po may have over 200	wever, the Hung Shing Ter ch indicates the existence of years of history. The site i	in, Yip 葉, So 蘇, and Tsoi 蔡. The establishment date of nple in Shek Tsai Po was construction in the 11th year of of settlement in the area. Therefore, the village of Shek is one of the remaining historic buildings in the village.	
Associated Historical/ Cultu	ral Events or Individual: No	ne	
Inscriptions: None			
Architectural Appraisal:			
Layout: Rectangular layout	village house built with sha	red gable wall with nearby village house	
Construction Material:			
Roof: Timber beams with clay title laying pitched roof Windows: Modern style metal framed glass windows Walls: Bricks covered with cement. Doors: Wooden			
Decorative Features: Nil Interior: Not Accessible			
Existing Condition: Good			
Past and Present Uses: Re	sidential		
Modifications: Modern meta	al door and modern window	s have been fitted.	
Modifications: Modern metal door and modern windows have been fitted. Photographic Record:			

Ref: T-80	Title: Cheng Cheung Hing's Shrimp Store 鄭祥興蝦鋪	Category: Commercial and Domestic	
Address: No. 19 Shek Tsai Po		Figure Ref: Figure 10.10	
Orientation: Southeast		Grading: Nil Grade	
Surrounding Environment: V	/illage houses		
Historical Appraisal:			
the village is not known. Ho the reign of Qian Long, whic	wever, the Hung Shing Temp ch indicates the existence of a	, Yip 葉, So 蘇, and Tsoi 蔡. The establishment date of ole in Shek Tsai Po was construction in the 11th year of settlement in the area. Therefore, the village of Shek one of the remaining historic buildings in the village.	
Associated Historical/ Cultu	ral Events or Individual: None	e	
Inscriptions: None			
Architectural Appraisal:			
Layout: Rectangular layout	village house built with share	d gable walls with nearby village houses	
Construction Material:			
Windows: Metal framed glas			
Interior: Not Accessible			
Existing Condition: Fair			
Past and Present Uses: She	op on ground floor and reside	ence on first floor	
Modifications: Metal shutter	has been fitted across the g	round floor façade.	
Photographic Record:			

Ref: T-81	Title: Village House	Category: Domestic
Address: Nos. 15, 16 & 17 Shek Tsai Po		Figure Ref: Figure 10.10
Orientation: Southeast		Grading: Nil Grade
Surrounding Environment:	/illage houses	
Historical Appraisal:		
the village is not known. Ho the reign of Qian Long, whi	wever, the Hung Shing Temp ch indicates the existence of	, Yip 葉, So 蘇, and Tsoi 蔡. The establishment date of ole in Shek Tsai Po was construction in the 11th year of settlement in the area. Therefore, the village of Shek s one of the remaining historic buildings in the village.
Associated Historical/ Cultu	ral Events or Individual: None	e
Inscriptions: None		
Architectural Appraisal:		
Layout: Rectangular layout	village house built with share	ed gable walls with nearby house
Construction Material:		
Roof: Timber beams with cl Windows: No. 16 (metal fra Walls: Grey or mud bricks a Doors: Metal framed door (med), no windows (No. 17)	d wooden door (No. 16)
Decorative Features: Nil Interior: Not Accessible		
Existing Condition: Poor		
	sidential (Nos. 15 & 16 currer	atly abandoned)
Modifications: None		

Ref: T-82	Title: Village House	Category: Domestic	
Address: Nos. 66, 67 & 68 Shek Tsai Po		Figure Ref: Figure 10.10	
Orientation: Southeast		Grading: Nil Grade	
Surrounding Environment:	Village houses		
Historical Appraisal:			
the village is not known. Ho the reign of Qian Long, whi	wever, the Hung Shing Tem ch indicates the existence of	i, Yip 葉, So 蘇, and Tsoi 蔡. The establishment date of ple in Shek Tsai Po was construction in the 11th year of settlement in the area. Therefore, the village of Shek one of the remaining historic buildings in the village.	
Associated Historical/ Cultu	ral Events or Individual: Non	e	
Inscriptions: None			
Architectural Appraisal:			
	ngular layout village stone ho	ouses built with shared gable walls with each other.	
Construction Material:		ũ	
Roof: Timber beams with clay title laying pitched roof Windows: Metal barred wooden window (no frame) Walls: Stone (granite) Doors: Wooden doors			
Decorative Features: Nil Interior: Not Accessible			
Existing Condition: Poor			
Past and Present Uses: Re	sidential (currently abandone	ed)	
Modifications: None			
Photographic Record:			

Ref: T-83	Title: Village House	Category: Domestic
Address: No. 62 Shek Tsai	Po	Figure Ref: Figure 10.10
Orientation: Southeast		Grading: Nil Grade
Surrounding Environment: V	/illage houses	
Historical Appraisal:		
the village is not known. Ho the reign of Qian Long, whic	wever, the Hung Shing Temp ch indicates the existence of s	Yip 葉, So 蘇, and Tsoi 蔡. The establishment date of ole in Shek Tsai Po was construction in the 11th year of settlement in the area. Therefore, the village of Shek one of the remaining historic buildings in the village.
Associated Historical/ Cultu	ral Events or Individual: None	9
Inscriptions: None		
Architectural Appraisal:		
Layout: Rectangular layout	village house	
Construction Material:		
Roof: Timber beams with cl Windows: Metal framed glas Walls: Grey or mud bricks Doors: Wooden		
Decorative Features: Top ri	dge of the facade oved, family shrine in rear roo	m
Existing Condition: Fair		
_	cidential (Currently being use	
	sidential (Currently being use	d to house family shifte)
Modifications: None		
<text></text>		

Ref: T-84	Title: Well	Category: Domestic
Address: South of No. 59 Shek Tsai Po		Figure Ref: Figure 10.10
Orientation: N/A		Grading: Nil Grade
Surrounding Environment: V	Village houses	
Historical Appraisal:		
the village is not known. Ho	wever, the Hung Shing Temp ch indicates the existence of	, Yip 葉, So 蘇, and Tsoi 蔡. The establishment date of ole in Shek Tsai Po was construction in the 11th year of settlement in the area. Therefore, the village of Shek
probably over 100 years old	ł	in Shek Tsai Po was established. Therefore, the well is
Associated Historical/ Cultu	ral Events or Individual: Non	e
Inscriptions: None		
Architectural Appraisal:		
The square-shaped well is r	made of stone and currently o	covered by metal sheets.
Decorative Features: Nil Interior: N/A		
Existing Condition: Fair		
Past and Present Uses: We	ell. currently abandoned.	
Modifications: None	,,,	
Photographic Record:		

Ref: T-85	Title: Earth Shrine	Category: Religious, Ritual and Funerary
Address: In front of No. 8 Shek Tsai Po		Figure Ref: Figure 10.10
Orientation: Northwest		Grading: Nil Grade
Surrounding Environment: V	/illage houses	
Historical Appraisal:		
the village is not known. How	wever, the Hung Shing Te th indicates the existence	鄭, Yip 葉, So 蘇, and Tsoi 蔡. The establishment date of emple in Shek Tsai Po was construction in the 11th year of of settlement in the area. Therefore, the village of Shek
The original shrine was const the shrine is probably over 1		ne settlement in Shek Tsai Po was established. Therefore,
Associated Historical/ Cultur		lone
Inscriptions: None		
Architectural Appraisal:		
Small, single room concrete	structure of concrete. Sir	ngle storey with flat roof. The exterior is painted red.
Interior: Single room with rea	d tiled platform altar agair	nst the rear wall.
Existing Condition: Fair		
Past and Present Uses: Shr	ine	
Modifications: The current s	hrine is covered with cond	crete coating/ no renovation or reconstruction date available.
Photographic Record:		

l

Ref: T-86	Title: Earth Shrine	Category: Religious, Ritual and Funerary
Address: Leung Uk Tsuen		Figure Ref: Figure 10.18
Orientation: North		Grading: Nil Grade
Surrounding Environment: \	/illage houses	
Historical Appraisal:		
Shenzhen (深圳). According is about 180 years ago. It is	to the locals, the Leung clai also reported that the house d that majority of the houses	ds of years ago. The Leung clan was originated from n had settled in Tai O for at least six generations, which es of Leung Uk Tsuen were already in existence 70 years of the village were constructed in the early 20th century. If Leung Uk Tsuen.
The Shrine was probably co Associated Historical/ Cultur	onstructed when Leung Uk Ta ral Events or Individual: Non	suen was established. e
Inscriptions: None		-
nisciptions. None		
Architectural Appraisal:		
		e shrine is covered by concrete; thus, the material of the ar as the earth deity for worshipping.
Decorative Features: Nil Interior: N/A		
Existing Condition: Good		
Past and Present Uses: Shr		
Modifications: The current s	hrine is covered with concre	te coating/ no renovation or reconstruction date available.
Photographic Record:		

Ref: T-87	Title: Village House	Category: Domestic	
Address: Nos. 16 17 Leung	Uk Tsuen	Figure Ref: Figure 10.18	
Orientation: North		Grading: Nil Grade	
Surrounding Environment: \	/illage houses and ruins		
Historical Appraisal:			
Shenzhen (深 圳). Accordin is about 180 years ago. It is ago. Therefore, it is believed The structure is one of the r	g to the locals, the Leung cl also reported that the hous d that majority of the houses emaining historic buildings of	-	
Associated Historical/ Cultu	ral Events or Individual: Nor	ne	
Inscriptions: None			
Architectural Appraisal:			
Layout: Village house with r	ectangular layout and share	ed gable walls with each other.	
Construction Material:			
Windows: Metal framed glas Walls: Grey or mud bricks a	Roof: Timber beams and clay tile laying pitched roof Windows: Metal framed glass windows Walls: Grey or mud bricks and stones Doors: Wooden (No.16), Metal (No.17)		
Decorative Features: Nil Interior: Not Accessible			
Existing Condition: Fair			
Past and Present Uses: Res	sidential		
Modifications: Metal doors h			
	lave been added.		
Photographic Record:			

Ref: T-88	Title: Village House	Category: Domestic	
Address: No. 15 Leung Uk Tsuen		Figure Ref: Figure 10.18	
Orientation: North		Grading: Nil Grade	
Surrounding Environment:	Village houses and ruins		
Historical Appraisal:			
Shenzhen (深 圳). Accordin is about 180 years ago. It is ago. Therefore, it is believe	ig to the locals, the Leung cla s also reported that the house	ds of years ago. The Leung clan was originated from in had settled in Tai O for at least six generations, which is of Leung Uk Tsuen were already in existence 70 years of the village were constructed in the early 20th century. f Leung Uk Tsuen.	
Associated Historical/ Cultu	ral Events or Individual: None	e	
Inscriptions: None			
Architectural Appraisal:			
Layout: A rectangular layou	t village house.		
Construction Material:			
Roof: Timber beams and clay tile laying pitched roof Windows: Metal framed glass windows Walls: Grey or mud bricks and stones Doors: Wooden			
Decorative Features: Nil Interior: Not Accessible			
Existing Condition: Fair			
Past and Present Uses: Re			
	have been added at entrance		
Photographic Record:			

Ref: T-89	Title: Village House	Category: Domestic	
Address: No. 14 Leung Uk Tsuen		Figure Ref: Figure 10.18	
Orientation: North		Grading: Nil Grade	
Surrounding Environment:	/illage houses and ruins		
Historical Appraisal:			
Shenzhen (深 圳). Accordin is about 180 years ago. It is ago. Therefore, it is believe The structure is one of the r	g to the locals, the Leung cla also reported that the house d that majority of the houses emaining historic buildings o	-	
Associated Historical/ Cultu	ral Events or Individual: Nor	ne	
Inscriptions: None			
Architectural Appraisal:			
Layout: A rectangular layou	t village house.		
Construction Material:			
Windows: Nil	Walls: Grey or mud bricks and stones		
Decorative Features: Nil Interior: Not Accessible			
Existing Condition: Fair			
Past and Present Uses: Re	sidential		
Modifications: None			
Photographic Record:			

Ref: T-90	Title: Village House	Category: Domestic
Address: No. 13 Leung Uk Tsuen		Figure Ref: Figure 10.18
Orientation: North		Grading: Nil Grade
Surrounding Environment:	/illage houses	
Historical Appraisal:		
Shenzhen (深 圳). Accordii is about 180 years ago. It is	ng to the locals, the Leung also reported that the hou d that majority of the house	reds of years ago. The Leung clan was originated from clan had settled in Tai O for at least six generations, which uses of Leung Uk Tsuen were already in existence 70 years es of the village were constructed in the early 20th century. Sof Leung Uk Tsuen.
Associated Historical/ Cultu	ral Events or Individual: No	one
Inscriptions: None		
Architectural Appraisal:		
Layout: A rectangular layou	t village house.	
Construction Material:		
Roof: Timber beams and cl Windows: Wooden Walls: Grey or mud bricks a Doors: Wooden		
Decorative Features: Nil Interior: Not Accessible		
Existing Condition: Fair		
Past and Present Uses: Re	sidential	
Modifications: None		
Photographic Record:		

Ref: T-91	Title: Village House	Category: Domestic
Address: Nos. 9 – 11 Leung Uk Tsuen		Figure Ref: Figure 10.18
Orientation: North		Grading: Nil Grade
Surrounding Environment:	Village houses	
Historical Appraisal:		
Leung Uk Tsuen was established by Leung clan hundreds of years ago. The Leung clan was originated from Shenzhen (深圳). According to the locals, the Leung clan had settled in Tai O for at least six generations, which is about 180 years ago. It is also reported that the houses of Leung Uk Tsuen were already in existence 70 years ago. Therefore, it is believed that majority of the houses of the village were constructed in the early 20th century. The structure is one of the remaining historic buildings of Leung Uk Tsuen.		
	ral Events or Individual: Non	e
Inscriptions: None		
Architectural Appraisal:		
Layout: Village houses with	rectangular layout and share	ed gable walls with each other.
Construction Material:		
Roof: Timber beams and clay tile laying pitched roof Windows: Metal framed glass windows. A modern style window was installed on No.9. Walls: Grey or mud bricks and stones Doors: Metal		
Decorative Features: Nil Interior: Not Accessible		
Existing Condition: Fair		
Past and Present Uses: Re	sidential	
Modifications: No. 11 has b	een repainted and metal doo	rs have been added at the entrances.
Photographic Record:		

Ref: T-92	Title: Village House	Category: Domestic	
Address: No. 12 Leung Uk	Tsuen	Figure Ref: Figure 10.18	
Orientation: North		Grading: Nil Grade	
Surrounding Environment:	/illage houses		
Historical Appraisal:			
Shenzhen (深圳). Accordin is about 180 years ago. It is ago. Therefore, it is believe The structure is one of the r	g to the locals, the Leung cla also reported that the house d that majority of the houses emaining historic buildings o	-	
	ral Events or Individual: Non	e	
Inscriptions: None			
Architectural Appraisal:			
Layout: A rectangular layou	t village house with an exten	sion structure attached.	
Construction Material:			
Windows: Wooden	Walls: Grey or mud bricks and stones		
Decorative Features: Nil			
Interior: Not Accessible			
Existing Condition: Poor			
Past and Present Uses: Re	sidential		
Modifications: Modern roofi	ng material has been added.		
Photographic Record:			

Ref: T-93	Title: Village House	Category: Domestic	
Address: No. 8 Leung Uk Tsuen		Figure Ref: Figure 10.18	
Orientation: North		Grading: Nil Grade	
Surrounding Environment:	Village houses		
Historical Appraisal:			
Shenzhen (深 圳). Accordir is about 180 years ago. It is ago. Therefore, it is believe The structure is one of the	g to the locals, the Leung class also reported that the house d that majority of the houses remaining historic buildings of	-	
	ral Events or Individual: Non	ie	
Inscriptions: None			
Architectural Appraisal:			
Layout: A rectangular layou	t village house with an exten	nsion structure attached.	
Construction Material:			
	Windows: modern metal framed windows Walls: Grey or mud bricks and stones (recently repaired and rendered)		
Decorative Features: Nil Interior: Not Accessible			
Existing Condition: Good (r			
Past and Present Uses: Re			
	s and doors with metal gates been fitted to the façade over	s have been installed and a new metal roof fitted. A r the doorways.	
Photographic Record:			

Ref: T-94	Title: Village House	Category: Domestic	
Address: No. 5 - 6 Leung Uk Tsuen (and units on either side)		Figure Ref: Figure 10.18	
Orientation: North		Grading: Nil Grade	
Surrounding Environment: \	/illage houses		
Historical Appraisal:			
Shenzhen (深 圳). Accordin is about 180 years ago. It is ago. Therefore, it is believed	g to the locals, the Leung cla also reported that the house	ds of years ago. The Leung clan was originated from an had settled in Tai O for at least six generations, which es of Leung Uk Tsuen were already in existence 70 years of the village were constructed in the early 20th century. f Leung Uk Tsuen.	
Associated Historical/ Cultu	ral Events or Individual: Non	e	
Inscriptions: None			
Architectural Appraisal:			
Layout: Terrace village hous	ses with rectangular layout a	nd shared gable walls with each other.	
Construction Material:			
Windows: Wooden framed a	Roof: Timber beams and clay tile laying pitched roof Windows: Wooden framed and metal barred window Walls: Grey or mud bricks and stones Doors: Wooden (No.4, 6, and the house west of No.6) and metal (No.5)		
Decorative Features: Nil			
Interior: Not Accessible			
Existing Condition: Poor			
Past and Present Uses: Res	sidential		
Modifications: None			
Photographic Record:			

Ref: T-95	Title: Leung Ancestral Hall	Category: Religious, Ritual and Funerary	
Address: Beside No. 3 Leung Uk Tsuen		Figure Ref: Figure 10.18	
Orientation: North		Grading: Nil Grade	
Surrounding Environment	: Village houses (modern villa	ge house on east side and older building on west side)	
Historical Appraisal:			
Shenzhen (深 圳). Accord is about 180 years ago. It ago. Therefore, it is believ The structure is the ances	Leung Uk Tsuen was established by Leung clan hundreds of years ago. The Leung clan was originated from Shenzhen (深 圳). According to the locals, the Leung clan had settled in Tai O for at least six generations, which is about 180 years ago. It is also reported that the houses of Leung Uk Tsuen were already in existence 70 years ago. Therefore, it is believed that majority of the houses of the village were constructed in the early 20th century. The structure is the ancestral hall of the Leung clan of Leung Uk Tsuen. Associated Historical/ Cultural Events or Individual: None		
Inscriptions: None			
Architectural Appraisal:			
Layout: Rectangular layou	ut and shared gable walls with	nearby village houses.	
Construction Material:			
Roof: Timber beams and clay tile laying pitched roof Windows: Metal framed glass windows Walls: Grey or mud bricks and stones Doors: Wooden Decorative Features: Nil			
Interior: Plain rendered wa	alls with tile floor. Simple altar	at the rear wall.	
Existing Condition: Fair			
Past and Present Uses: A	ncestral Hall		
Modifications: Modern ligh	nting		
Photographic Record:			

Ref: T-96	Title: Village House	Category: Domestic
Address: No. 2 Leung Uk T	suen	Figure Ref: Figure 10.18
Orientation: North		Grading: Nil Grade
Surrounding Environment: V	/illage houses	
Historical Appraisal:		
Shenzhen (深 圳). Accordin is about 180 years ago. It is ago. Therefore, it is believed	g to the locals, the Leung cla also reported that the house	ds of years ago. The Leung clan was originated from an had settled in Tai O for at least six generations, which es of Leung Uk Tsuen were already in existence 70 years of the village were constructed in the early 20th century. If Leung Uk Tsuen
Associated Historical/ Cultu	ral Events or Individual: Non	e
Inscriptions: None		
Architectural Appraisal:		
Layout: A village house with	n rectangular layout and shar	red gable walls with nearby village houses.
Construction Material:		
Roof: Timber beams and cla Windows: Metal framed gla Walls: Grey or mud bricks a Doors: Wooden	ss windows	
Decorative Features: Nil		
Interior: Interior has been cl	eared out , plain render walls	s, used for storage.
Existing Condition: Fair		
Past and Present Uses: Re	sidential/ currently used for s	torage.
Modifications: Interior has b	een cleared out.	
Photographic Record:		

Ref: T-97	Title: Village House	Category: Domestic		
Address: No. 1 Leung Uk Tsuen		Figure Ref: Figure 10.18		
Orientation: North		Grading: Nil Grade		
Surrounding Environment:	Surrounding Environment: Village houses (at end of row)			
Historical Appraisal:				
Shenzhen (深 圳). Accordin is about 180 years ago. It is ago. Therefore, it is believe The structure is one of the r	Leung Uk Tsuen was established by Leung clan hundreds of years ago. The Leung clan was originated from Shenzhen (深 圳). According to the locals, the Leung clan had settled in Tai O for at least six generations, which is about 180 years ago. It is also reported that the houses of Leung Uk Tsuen were already in existence 70 years ago. Therefore, it is believed that majority of the houses of the village were constructed in the early 20th century. The structure is one of the remaining historic buildings of Leung Uk Tsuen			
Associated Historical/ Cultu	ral Events or Individual: None	9		
Inscriptions: None				
Architectural Appraisal:				
Layout: A rectangular layou	t village house with an extens	sion structure attached.		
Construction Material:				
Windows: Wooden framed a structure.	Roof: Timber beams and clay tile laying pitched roof Windows: Wooden framed and metal barred window and metal framed glass window for the attached temporary structure. Walls: Grey or mud bricks and stones Doors: Wooden			
Decorative Features: Nil				
Interior: Not Accessible				
Existing Condition:				
Past and Present Uses: Re	sidential			
Modifications: Metal door ha	as been added.			
Photographic Record:				

Ref: T-98	Title: Well	Category: Domestic	
Address: East of No. 1 Leung Uk Tsuen		Figure Ref: Figure 10.18	
Orientation: N/A		Grading: Nil Grade	
Surrounding Environment:	At the eastern end of the villag	le, low vegetation and bamboo	
Historical Appraisal:			
Shenzhen (深 圳). Accordin is about 180 years ago. It is ago. Therefore, it is believe	Leung Uk Tsuen was established by Leung clan hundreds of years ago. The Leung clan was originated from Shenzhen (深 圳). According to the locals, the Leung clan had settled in Tai O for at least six generations, which is about 180 years ago. It is also reported that the houses of Leung Uk Tsuen were already in existence 70 years ago. Therefore, it is believed that majority of the houses of the village were constructed in the early 20th century.		
The well was probably cons Associated Historical/ Culture	structed when Leung Uk Tsuer Iral Events or Individual: None	n was established.	
Inscriptions: None			
Architectural Appraisal:			
The stone made well is loca	ated at the bottom of a sunken	area. The wall of the sunken area is made of stone.	
Decorative Features: Nil Interior: N/A			
Existing Condition:			
Past and Present Uses: We	-		
Modifications: None	511		
		1	
Photographic Record:			

Ref: T-99	Title: Hung Shing Temple 古廟 and	Category: Religious, Ritual and Funerary		
Address: Shek Tsai Po Street		Figure Ref: Figure 10.7		
Orientation: Southwest		Grading: Nil Grade		
Surrounding Environment: I	Located on footpath set back in	Into a wooded area with hill slope behind.		
	Historical Appraisal: The original temple was built in the 11 th year of the Qianlong reign of the Qing Dynasty (1746). Associated Historical/ Cultural Events or Individual: None			
Inscriptions:				
	聖 洪			
聖 澤 普 商 民	洪 恩 扶 水 陸			
Architectural Appraisal:				
Layout: Qing vernacular bu	ilding with two halls and one co	purtyard with three bays.		
Construction Material: Gree	en brick walls with timber rafter	s and purlins,		
Roof: pitched clay tile roof painted green with red painted roof ridge Windows: Open with ceramic grilles. Walls: green brick with plaster coating Doors: wooden				
Decorative Features: Roof ridge with ceramic aoyus decoration; painted scenes under eaves on façade and painted fascia board; green ceramic window grilles on façade side chambers.				
Interior: There is an altar at the right and Yue Tau Tai V		tatue of Hung Shing in middle with God of Wealth on		
Existing Condition: Good				
Past and Present Uses: Re	Past and Present Uses: Religious, Ritual and Funerary			
Modifications: The temple was renovated in 1802, 1841, 1875, 1930, 1969 and 1995. There is no information on the construction date/ renovation of the shrine.				
Photographic Record:				
Facade of the temple		Shrine in front of the Temple		

Ref: T-100	Title: Village House	Category: Domestic	
Address: Behind Leung Uk Playground		Figure Ref: Figure 10.18	
Orientation: North		Grading: Nil Grade	
Surrounding Environment:	In an open area near the pla	ayground	
Historical Appraisal:			
According to a grocery store owner of the village, there were no settlements in the area of Nam Chung Tusen before the 50s. Therefore, the village was probably established during the mid-20th century. The village was a mixed clan immigrant village including local people from Baoan and Hoklo people. The site is one of the remaining historic buildings of the village.			
Associated Historical/ Cult	ural Events or Individual: Nor	ne	
Inscriptions: None			
Architectural Appraisal:			
Layout: A rectangular layo	ut village house.		
Construction Material:			
Roof: Timber beams and clay tile laying pitched roof Windows: Metal framed glass windows and wooden windows Walls: Grey or mud bricks and stones Doors: Wooden			
Decorative Features: Nil			
Interior: Not Accessible			
Existing Condition: Ruin, building is heavily overgrown with vegetation.			
Past and Present Uses: Residential (Currently Abandoned)			
Modifications: None			
Photographic Record:			
		Photograph from April 2013	

Photograph from 2009 Survey

Ref: T-101	Title: Earth Shrine	Category: Religious, Ritual and Funerary	
Address: Behind No 1B Nam	Chung Tsuen	Figure Ref: Figure 10.18	
Orientation: Northwest		Grading: Nil Grade	
Surrounding Environment: Vi	Surrounding Environment: Village houses		
Historical Appraisal:			
grocery store owner of the vil Therefore, the village was pro-	The shrine was probably constructed when the village of Nam Chung Tsuen was established. According to a grocery store owner of the village, there were no settlements in the area of Nam Chung Tusen before the 50s. Therefore, the village was probably established during the mid-20th century. The shrine was probably constructed under a tree. However, only the platform is still standing and nothing was found on the platform apart from some simple incense holders.		
Associated Historical/ Cultura	al Events or Individual: None		
Inscriptions: None			
Architectural Appraisal:			
The shrine consists of a cond survey)	crete covered disc with a burnt tr	ree stump (the tree was intact during the 2009	
Interior: N/A			
Existing Condition: Fair			
Past and Present Uses: Shrin	Past and Present Uses: Shrine		
Modifications: The tree has b	ourned and only the burnt stump	remains	
Photographic Record:			
Photograph taken inApril 201	<image/>	Photograph taken during the 2009 survey	


Ref: T-102	Title: Village House	Category: Domestic		
Address: Beside No. 6 Nam Chung Tsuen		Figure Ref: Figure 10.18		
Orientation: Northwest		Grading: Nil Grade		
Surrounding Environment:	Village houses and shop/ res	taurant		
Historical Appraisal:				
before the 50s. Therefore, t	he village was probably esta e including local people from	were no settlements in the area of Nam Chung Tusen blished during the mid-20th century. The village was a Baoan and Hoklo people. The site is one of the		
Associated Historical/ Cultu	ral Events or Individual: Non	e		
Inscriptions: None				
Architectural Appraisal:				
Layout: A rectangular layou	t village house.			
Construction Material:				
Windows: Nil	Roof: Timber beams and clay tile laying pitched roof Windows: Nil Walls: Grey or mud bricks and stones Doors: Wooden			
Decorative Features: Nil				
Interior: Plain walls and floc	r			
Existing Condition: Fair				
Past and Present Uses: Re	sidential (currently used for s	storage)		
Modifications: New metal ro	oof and metal door have beer	n added.		
Photographic Record:				

Ref: T-103	Title: Earth Shrine	Category: Religious, Ritual and Funerary
Address: Next to gate of No. 8 Nam Chung Tsuen		Figure Ref: Figure 10.18
Orientation: Northeast		Grading: Nil Grade
Surrounding Environment:	/illage houses	
the gate of No.8 Nam Chun	g Tsuen	f No.8 Nam Chung Tsuen as the shrine is located next to
	ral Events or Individual: Non	le
Inscriptions: 祠德褚		
福 澤 惠 四 方	神 威 保 百 姓	
Architectural Appraisal:		
The yellow-coloured shrine	made of concrete and is loca	ated next to the gate of No.8 Nam Chung Tsuen
Decorative Features: Nil Interior: N/A		
Existing Condition: Good		
Past and Present Uses: Shi	rine	
Modifications: The current s	hrine is covered with concre	te coating/ no renovation or reconstruction date available.
Modifications: The current shrine is covered with concrete coating/ no renovation or reconstruction date available.		

Ref: T-104	Title: Well	Category: Domestic	
Address: Next to gate of No. 8 Nam Chung Tsuen		Figure Ref: Figure 10.18	
Orientation: North		Grading: Nil Grade	
Surrounding Environment: V	/illage houses		
Historical Appraisal:			
grocery store owner of the v	village, there were no settlem robably established during the	lam Chung Tsuen was established. According to a nents in the area of Nam Chung Tusen before the 50s. he mid-20th century. The well is probably construction	
Associated Historical/ Cultur	ral Events or Individual: Non	e	
Inscriptions: None			
Architectural Appraisal:			
decipherable inscription.	th concrete edging along the	e exterior opening. Concrete slab at one end, no	
Interior: N/A			
Existing Condition: Good			
Past and Present Uses: We	Il (does not appear to be cur	rently in use, though it is well maintained.	
Modifications: None			
Photographic Record:			

Ref: T-105	Title: Earth Shrine	Category: Religious, Ritual and Funerary
ddress: North of No. 10 Nam Chung Tsuen		Figure Ref: Figure 10.17
Orientation: Northwest		Grading: Nil Grade
Surrounding Environment	: Village houses	
Historical Appraisal:		
grocery store owner of the Therefore, the village was when the village was esta	e village, there were no settl probably established during blished.	e of Nam Chung Tsuen was established. According to a ements in the area of Nam Chung Tusen before the 50s. g the mid-20th century. The shrine is probably construction
Associated Historical/ Cul	tural Events or Individual: N	one
Inscriptions: None		
Architectural Appraisal:		
The pitched roof shrine is shrines are on both sides		e. A burner is found next to the shrine and two associated
Decorative Features: Nil Interior: N/A		
Existing Condition: Good	(modern structure)	
Past and Present Uses: S	hrine	
Modifications: The current	shrine is covered with conc	crete coating/ no renovation or reconstruction date available.
Photographic Record:		
ter Sig		

Ref: T-106	Title: Grave	Category: Religious, Ritual and Funerary
Address: South of No. 11 Nam Chung Tsuen		Figure Ref: Figure 10.17
Orientation: North		Grading: Nil Grade
Surrounding Environment: \	Wooded hill side	
Historical Appraisal:		
Age unknown (but probably	v over 50 years)	
Associated Historical/ Cultu	ral Events or Individual: Nor	ne
Inscriptions: None remainin	g	
Architectural Appraisal:		
The headstone of the grave However, the style of the gr	e is lost and therefore the his ave is about mid 20th centur	tory of the grave cannot be traced. y.
Interior: N/A		
Existing Condition: Poor (no	o signs of upkeep)	
Past and Present Uses: Gra	ave	
Modifications: None		
Photographic Record:		



Ref: T-108	Title: Village House	Category: Domestic		
Address: No. 8 Fan Kwai Tsuen		Figure Ref: Figure 10.19		
Orientation: North		Grading: Nil Grade		
Surrounding Environment	Row of village houses			
Historical Appraisal:				
the late Ming Dynasty. The settlement in Fan Kwai To	Fan Kwai Tong is one of the oldest settlements in Tai O. The Yip (葉) clan of the village had settled the area in the late Ming Dynasty. Therefore, the village has over 300 years of history. It is said that there was a Dutch settlement in Fan Kwai Tong during the late Ming Dynasty and this is the original of the name of Fan Kwai Tong, literally means the pond of foreigners. This structure is one of the historic buildings of the village.			
Associated Historical/ Cult	tural Events or Individual: Non	e		
Inscriptions: None				
Architectural Appraisal:				
<i>Layout:</i> Two-level village village house.	houses with rectangular layou	t and shared gable wall with each other and nearby		
Construction Material:				
Roof: Timber beams and clay tile laying pitched roof Windows: Metal framed glass windows Walls: Grey or mud bricks and stones Doors: Wooden				
Decorative Features: Nil Interior: Not Accessible				
Existing Condition: Fair				
Past and Present Uses: R	Past and Present Uses: Residential			
Modifications: None				
Photographic Record:				

Ref: T-109	Title: Village House	Category: Domestic		
Address: Nos. 6 – 7 Fan Kwai Tsuen		Figure Ref: Figure 10.19		
Orientation: North		Grading: Nil Grade		
Surrounding Environment: I	Row of village houses	-		
Historical Appraisal:				
the late Ming Dynasty. The settlement in Fan Kwai Ton literally means the pond of	Fan Kwai Tong is one of the oldest settlements in Tai O. The Yip (葉) clan of the village had settled the area in the late Ming Dynasty. Therefore, the village has over 300 years of history. It is said that there was a Dutch settlement in Fan Kwai Tong during the late Ming Dynasty and this is the original of the name of Fan Kwai Tong, literally means the pond of foreigners. This structure is one of the historic buildings of the village.			
Associated Historical/ Cultu	ral Events or Individual: No	ne		
Inscriptions: None				
Architectural Appraisal:				
<i>Layout:</i> Two-level village h village h	ouses with rectangular layo	ut and shared gable wall with each other and nearby		
Construction Material:				
Roof: Timber beams and clay tile laying pitched roof Windows: Metal framed glass windows Walls: Grey or mud bricks and stones Doors: Wooden				
Decorative Features: Nil				
Existing Condition: Fair				
Past and Present Uses: Re	sidential			
Modifications: None				
Photographic Record:				

Ref: T-110	Title: Village House	Category: Domestic	
Address: North of No. 6 Fan Kwai Tsuen		Figure Ref: Figure 10.19	
Orientation: South		Grading: Nil Grade	
Surrounding Environment: I	End of row of village houses		
Historical Appraisal:			
the late Ming Dynasty. The settlement in Fan Kwai Ton literally means the pond of t	refore, the village has over 3 g during the late Ming Dynas foreigners. This structure is	. The Yip (葉) clan of the village had settled the area in 600 years of history. It is said that there was a Dutch sty and this is the original of the name of Fan Kwai Tong, one of the historic buildings of the village.	
Associated Historical/ Cultu	ral Events or Individual: Non	e	
Inscriptions: None			
Architectural Appraisal:			
	ut village house with tempora	ary structures attached	
Construction Material: Roof: Timber beams and clay tile laying pitched roof Windows: Wooden shutters Walls: Grey or mud bricks and stones Doors: Wooden Decorative Features: Nil			
Interior: Not Accessible			
Existing Condition: Fair			
Past and Present Uses: Re	sidential		
Modifications: None			
Photographic Record:			

Ref: T-111	Title: Salt Pan	Category: Cultural Landscape	
Address: North of Wang Ha	ng Village	Figure Ref: Figure 10.13	
Orientation: N/A		Grading: Nil Grade	
Surrounding Environment:	/illage houses and open field	s and wooded hill side.	
Historical Appraisal:			
1795, according to a stone Tai O and the growth of oth	tablet in the San Tsuen Tin H	ndustrial activities recorded in Hong Kong since 1736- lau Temple at San Tsuen. However, the development of ainland China and Thailand led to a decline in the salt n.	
areas remain disused or ha and abandoned salt pan are value to the study of Hong I	Significant areas of the original salt pans have been destroyed by reclamation and development, whilst other areas remain disused or have been converted into fishponds which are subsequently abandoned. These disused and abandoned salt pan areas are the last few remaining salt pans in Hong Kong and, as such, have significant value to the study of Hong Kong's early industrial history. The earliest surviving salt pan was built in late 18th century. Others were built prior to 1898, c.1920s and in 1903-16.		
Associated Historical/ Cultu	ral Events or Individual:		
Salt producing industry of T	ai O.		
Inscriptions: None			
Architectural Appraisal: N/A	<u>.</u>		
Interior: N/A			
Existing Condition: N/A			
Past and Present Uses: Salt Pan/ pond			
Modifications: None			
Photographic Record:			

Ref: T-112	Title: Earth Shrine	Category: Religious, Ritual and Funerary
Address: East of the bridge north of Wang Hang Village		Figure Ref: Figure 10.13
Orientation: East		Grading: Nil Grade
Surrounding Environment: A	Along local footpath next to	a bridge
Historical Appraisal:		
Wang Hang is one of the ol- Village was established.	dest villages in Tai O. The S	Shrine was probably constructed when the Wang Hang
Associated Historical/ Cultu	ral Events or Individual: No	ne
Inscriptions:	福	
緣 慶 康	萬	
康	民 共	
寧	業	
Architectural Appraisal:		
The Shrine is a stone built s worshipping.	quare shaped shrine. A sta	atue of earth deity is placed inside the shrine for
Decorative Features: Nil		
Interior: N/A		
Existing Condition: Fair		
Past and Present Uses: Shi	rine	
Modifications: The current s	hrine is covered with concr	ete coating/ no renovation or reconstruction date available.
<image/>		

Ref: T-113	Title: Well and Shrine	Category: Domestic		
Address: Near No. 21B Leung Uk Tsuen		Figure Ref: Figure 10.18		
Orientation: West		Grading: Nil Grade		
Surrounding Environment: other side.	Along side of the footpath at t	he edge of the village with old agricultural fields on the		
Historical Appraisal: There know the age.	Historical Appraisal: There is no inscription or information on the age of the well and the local inhabitants did not know the age.			
Associated Historical/ Cultu	ral Events or Individual: None	9		
Inscriptions: None				
Architectural Appraisal:				
A semi-circular well with co against the natural rock fac	ncrete lining above the water e.	level. The shrine consists of simple incense holders set		
Interior: Not Applicable				
Existing Condition: Good				
Past and Present Uses: Religious, Ritual and Funerary				
Modifications: Well has concrete covering around the opening.				
Photographic Record:				

Ref: T-114	Title: Village House	Category: Domestic
Address: Nos. 2 & 4 Wang Hang Village and nearby ruins		Figure Ref: Figure 10.13
Orientation: West		Grading: Nil Grade
Surrounding Environment: \	/illage houses	
Historical Appraisal:		
Wang Hang is one of the old village.	dest villages in Tai O. The si	tructure is one of the remaining historic buildings in the
Associated Historical/ Cultur	ral Events or Individual: Nor	ne
Inscriptions: None		
Architectural Appraisal:		
Layout: Village house with r	ectangular layout and share	d gable walls with each other.
Construction Material:		
Roof: Timber beams and clay tile laying pitched roof Windows: Wood framed glass windows Walls: Grey brick and mud brick with cut stone foundation along façade and side walls Doors: Wooden		
Decorative Features: Nil Interior: Not Accessible		
Existing Condition: Poor		
Past and Present Uses: Res	sidential (currently abandone	ea)
Modifications: None		
Photographic Record:		

Ref: T-115	Title: Village House	Category: Domestic	
Address: Nos. 8 – 10 Wang Hang Village		Figure Ref: Figure 10.13	
Orientation: West		Grading: Nil Grade	
Surrounding Environment: Village houses			
Historical Appraisal:			
Wang Hang is one of the ol village.	dest villages in Tai O. The st	ructure is one of the remaining historic buildings in the	
Associated Historical/ Cultu	ral Events or Individual:		
Inscriptions: None			
Architectural Appraisal:			
Layout: Village house with	rectangular layout and shared	d gable walls with each other.	
Construction Material:			
Roof: Timber beams and clay tile laying pitched roof Windows: Metal framed glass windows Walls: Grey or mud bricks and stones Doors: Wooden or Metal			
Decorative Features: Nil Interior: Not Accessible			
Existing Condition: Good			
Past and Present Uses: Re	sidential		
Modifications: External walls are repainted.			
Photographic Record:			

Ref: T-116	Title: Wah Kwong Temple	Category: Religious, Ritual and Funerary
Address: South of Nos. 11 -	- 13 Wang Hang Village	Figure Ref: Figure 10.15
Orientation: West		Grading: Nil Grade
Surrounding Environment: V	Village houses	
		the late Qing Dynasty (about 1875-1908).
Associated Historical/ Cultu Inscriptions: 崩古		
癸 丑 年 重 修	一九七三年	
神威萬古鎮乾坤	火德千秋扶日月	
<i>Layout:</i> A one-hall Chinese building with one side hall to the left. <i>Construction Material:</i> Roof: Timber beams and modern green glazed tile laying pitched roof Windows: Modern style metal framed glass window Walls: Grey or mud bricks and stones Doors: Wooden <i>Decorative Features:</i> The paintings of the top of the façade wall and the top ridge of the roof. Interior: Plain walls and floor with elaborate altar along rear wall.		
Existing Condition: Good		
Past and Present Uses: Temple		
Modifications: Renovated in 1896, 1954, 1973, 2000, and 2005		
Photographic Record:		

Ref: T-117	Title: Village House	Category: Domestic	
Address: To the north of Nos. 19 & 20 Wang Hang Village		Figure Ref: Figure 10.15	
Orientation: West		Grading: Nil Grade	
Surrounding Environment:	Ruins		
Historical Appraisal:			
This is a temple of Wang H	ang Tsuen which was built i	n the late Qing Dynasty (about 1875-1908).	
Associated Historical/ Cultu	ral Events or Individual:		
Inscriptions: None			
Architectural Appraisal:			
Layout: A village house with	h rectangular layout.		
Construction Material:			
Roof: Timber beams and clay tile laying pitched roof Windows: Wooden framed metal bar window Walls: Grey or mud bricks and stones Doors: Wooden			
Decoration Features: Nil Interior: Plain rooms			
Existing Condition: Poor			
	Past and Present Uses: Residential		
Modifications: None			
Photographic Record:			

Ref: T-118	Title: Salt Pan	Category: Cultural Landscape	
Address: North of Nam Chung Tsuen		Figure Ref: Figure 10.17	
Orientation: N/A		Grading: Nil Grade	
Surrounding Environment: Villages and open water			
Historical Appraisal:			
Salt production in Tai O was one of the largest earliest industrial activities recorded in Hong Kong since 1736- 1795, according to a stone tablet in the San Tsuen Tin Hau Temple at San Tsuen. However, the development of Tai O and the growth of other salt production areas in mainland China and Thailand led to a decline in the salt industry and, in 1977, the last salt pan ceased production.			
Significant areas of the original salt pans have been destroyed by reclamation and development, whilst other areas remain disused or have been converted into fishponds which are subsequently abandoned. These disused and abandoned salt pan areas are the last few remaining salt pans in Hong Kong and, as such, have significant value to the study of Hong Kong's early industrial history. The earliest surviving salt pan was built in late 18th century. Others were built prior to 1898, c.1920s and in 1903-16.			
Associated Historical/ Cultu	ral Events or Individual:		
Inscriptions: N/A			
Architectural Appraisal: N/A			
Interior: N/A			
Existing Condition: Mangrove area			
Past and Present Uses: Salt Pan, abandoned and area is now filling with mangrove environment.			
Modifications: None			
Photographic Record:			