



VP2 - Existing conditions



VP2 - Photomontage at Day 1 of operation with no mitigation / enhancement


Notes: The drawing provided aesthetic impression of the indicative form, size and quality of the architectural and landscaping treatment for the landscape features. The final details of layout, material and finishes will be subject to detailed design.

Figure 8.10a

Photomontage from VP2 - View from Luk Tei Tong Bypass Channel
(Sheet 1 of 2)



VP2 - Photomontage at Day 1 of operation with mitigation / enhancement



VP2 - Photomontage at Year 10 of operation with mitigation / enhancement

Notes: The drawing provided aesthetic impression of the indicative form, size and quality of the architectural and landscaping treatment for the landscape features. The final details of layout, material and finishes will be subject to detailed design.

Figure 8.10b

Photomontage from VP2 - View from Luk Tei Tong Bypass Channel
(Sheet 2 of 2)