



VP1 - Existing conditions



VP1 - Photomontage at Day 1 of operation with no mitigation / enhancement

Notes: The drawing provided aesthetic impression of the indicative form, size and quality of the architectural and landscaping treatment for the landscape features. The final details of layout, material and finishes will be subject to detailed design.


Figure 8.9a

Photomontage from VP1 - View from Footbridge near Ngan Shu Street (Sheet 1 of 2)





VP1 - Photomontage at Day 1 of operation with mitigation / enhancement



VP1 - Photomontage at Year 10 of operation with mitigation / enhancement

Notes: The drawing provided aesthetic impression of the indicative form, size and quality of the architectural and landscaping treatment for the landscape features. The final details of layout, material and finishes will be subject to detailed design.

Figure 8.9b

Photomontage from VP1 - View from Footbridge near Ngan Shu Street (Sheet 2 of 2)