

Date of the Accident : 20 January 2006

Time : 1030

Location : Production line – Pattern Plating Line

Type of Accident : Chemical spillage near WWTP

Detailed Description of the Accident :

10 liters of dilute hydrochloric acid was spilled when the WWTP operator (Sam Liu) refilled the acid to the dosage tank of WWTP.

Responses / Corrective Actions :

Clean up the area immediately, the acid was washed down to the drainage where collected and directed to WWTP.


Possible Causes(s) of the Accident:

Lack of trainings;

The operator did not use the hand pump device for refill chemical solution

Suggested Preventive Measures:

Plant Manager will brief the WWTP operators again and ensure to apply the hand pump device for any refill of chemical solution

Submitted by:	C.M. Yuen	Position:	Production Manager
Signature:		Date:	21 January 2006

Reviewed by : Chan Fat

Date : 22 January 2006