




HY2004/09 Improvements to San Tin Interchange					
Notifications of Environmental Quality Limits Exceedance				Notification No.: 099	
Date of Notification: 7 th May 2007			Time: 11:30		
Works Inspected: Data collected from restricted hour noise monitoring on 6 th May 2007, Sunday					
Monitoring Location: CM2 – Village House near San Tin Highway					
Parameter: Noise (Leq 15 min)					
Action & Limit Levels			Measured Level:		
Time Period	Action Level	Limit Level	Time	Location	Noise Level
07:00–23:00 hrs General Holiday	-	65dB(A)	09:44–09:59 hrs	CM2*	<u>69dB(A)</u>
Possible reason for Action or Limit Level Non-compliance:					
<p>During the measurement period, no project-related works were observed to be undertaken near the monitoring location. Further to discussion with the Contractor and subsequent confirmation from the Resident Engineer, the major construction activity during the time of measurement was excavation in the N1 Division over 200m away from CM2.</p> <p>The major noise source during the noise measurement was road traffic from San Tin Highway. To this end, the noise exceedance recorded on 6th May 2007 may have been caused by high ambient road traffic noise from San Tin Highway. Thus, the exceedance was not to be attributable to project works.</p> <p>Note * A positive correction of 3dB(A) has been applied to the measured noise level at CM2 according to EPD's guideline.</p>					
Actions taken/ to be taken:					
As the noise exceedance was not project related, no immediate actions are necessary.					


Prepared by : Howard Chan Title : ET - Environmental Technician

Date : 7th May 2007

Reviewed and approved by : Susana Bezy Title : Environmental Team Leader

Date : 7th May 2007

Sent to : RE, Contractor, EPD & IEC

HY2004/09 Improvements to San Tin Interchange					
Notifications of Environmental Quality Limits Exceedance				Notification No.: 100	
Date of Notification: 14 th May 2007			Time: 12:00		
Works Inspected: Data collected from restricted hour noise monitoring on 13 th May 2007, Sunday					
Monitoring Location: CM2 – Village House near San Tin Highway					
Parameter: Noise (Leq 15 min)					
Action & Limit Levels			Measured Level:		
Time Period	Action Level	Limit Level	Time	Location	Noise Level
07:00–23:00 hrs General Holiday	-	65dB(A)	10:20–10:35 hrs	CM2*	68dB(A)
Possible reason for Action or Limit Level Non-compliance:					
<p>During the measurement period, no project-related works were observed to be undertaken near the monitoring location. Further to discussion with the Contractor and subsequent confirmation from the Resident Engineer, the major construction activity during the time of measurement was road paving in the N1 Division over 100m away from CM2.</p> <p>The major noise source during the noise measurement was road traffic from San Tin Highway. To this end, the noise exceedance recorded on 13th May 2007 may have been caused by high ambient road traffic noise from San Tin Highway. Thus, the exceedance was not to be attributable to project works.</p> <p>Note * A positive correction of 3dB(A) has been applied to the measured noise level at CM2 according to EPD's guideline.</p>					
Actions taken/ to be taken:					
As the noise exceedance was not project related, no immediate actions are necessary.					

Prepared by : K. L. Cheung Title : ET - Environmental Consultant

Date : 14th May 2007


Reviewed and approved by : Susana Bezy Title : Environmental Team Leader

Date : 14th May 2007

Sent to : RE, Contractor, EPD & IEC

HY2004/09 Improvements to San Tin Interchange					
Notifications of Environmental Quality Limits Exceedance				Notification No.: 101	
Date of Notification: 28 th May 2007			Time: 12:00		
Works Inspected: Data collected from restricted hour noise monitoring on 27 th May 2007, Sunday					
Monitoring Location: CM2 – Village House near San Tin Highway					
Parameter: Noise (Leq 15 min)					
Action & Limit Levels			Measured Level:		
Time Period	Action Level	Limit Level	Time	Location	Noise Level
07:00–23:00 hrs General Holiday	-	65dB(A)	10:28–10:43 hrs	CM2*	69dB(A)
Possible reason for Action or Limit Level Non-compliance:					
<p>During the measurement period, no project-related works were observed to be undertaken near the monitoring location. Further to discussion with the Contractor and subsequent confirmation from the Resident Engineer, the major construction activity during the time of measurement was excavation in the N1 Division over 200m away from CM2.</p> <p>The major noise source during the noise measurement was road traffic from San Tin Highway. To this end, the noise exceedance recorded on 27th May 2007 may have been caused by high ambient road traffic noise from San Tin Highway. Thus, the exceedance was not to be attributable to project works.</p> <p>Note * A positive correction of 3dB(A) has been applied to the measured noise level at CM2 according to EPD's guideline.</p>					
Actions taken/ to be taken:					
As the noise exceedance was not project related, no immediate actions are necessary.					

Prepared by : K. L. Cheung

Title : ET - Environmental Consultant



Date : 28th May 2007

Reviewed and approved by : Susana Bezy

Title : Environmental Team Leader



Date : 28th May 2007

Sent to : RE, Contractor, EPD & IEC