

**Contract No. HY 2004/09 Improvements to San Tin Interchange
Water Quality Visual Inspection Report**

Weekly Report No.: 110

	(1)	(2)	(3)
Date of Inspection:	7 th August 2007	8 th August 2007	9 th August 2007
Time:	09:45	14:30	10:00
Weather Condition:	Sunny	Fine	Rainy
Works Inspected:	Drainage laying and trench works	Drainage laying and trench works	Drainage laying and trench works
Location:	Division North 1, 2 & South	Division North 1, 2 & South	Division North 1, 2 & South

Are Works in Compliance with:

	Y	N
1. Water Pollution Control Ordinance and the Subsidiary Legislation	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Recommendations and requirements in the Project EIA Report, EM&A Manual and Environmental Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Recommendations and requirements in the Contractor's Drainage Management Plan (DMP)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Contract No. HY/2004/09, Particular Specification Section 26, Environmental Protection, items under Clause 26.04	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Recommendations and requirements in the ProPECC Note PN 1/94 "Construction Site Drainage"	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Any relevant Effluent Discharge License received by the Contractor	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Description of Environmental Non-compliance or Deficiency (if any):

Nil.

Remedial Actions – Mitigation Measures Implemented or Proposed (if any):

Nil.

Remarks:

- No specific water quality issue was recorded during the inspection conducted on 7th and 8th August 2007, respectively.
- During the inspection on 9th August 2007, the outlet from the sedimentation tank near the site office appeared to be silty. The contractor was seen to have added coagulant to the sedimentation tank immediately to improve the sedimentation process.

Prepared by : Chau Tsz Wing

Title : ET – Environmental Technician

Signature : 

Date : 9th August 2007

Reviewed and approved by : Susana Bezy

Title : Environmental Team Leader

Signature : 

Date : 15th August 2007

Sent to: IEC (ERM), ER (Maunsell), Contractor (Chun Wo)

**Contract No. HY 2004/09 Improvements to San Tin Interchange
Water Quality Visual Inspection Report**

Weekly Report No.: 111

	(1)	(2)	(3)
Date of Inspection:	13 th August 2007	15 th August 2007	17 th August 2007
Time:	14:20	14:00	09:45
Weather Condition:	Cloudy	Cloudy	Fine
Works Inspected:	Drainage laying and trench works	Drainage laying and trench works	Drainage laying and trench works
Location:	Division North 1, 2 & South	Division North 1, 2 & South	Division North 1, 2 & South

Are Works in Compliance with:

	Y	N
1. Water Pollution Control Ordinance and the Subsidiary Legislation	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Recommendations and requirements in the Project EIA Report, EM&A Manual and Environmental Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Recommendations and requirements in the Contractor's Drainage Management Plan (DMP)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Contract No. HY/2004/09, Particular Specification Section 26, Environmental Protection, items under Clause 26.04	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Recommendations and requirements in the ProPECC Note PN 1/94 "Construction Site Drainage"	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Any relevant Effluent Discharge License received by the Contractor	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Description of Environmental Non-compliance or Deficiency (if any):

Nil.

Remedial Actions – Mitigation Measures Implemented or Proposed (if any):


Nil.

Remarks:

- No specific water quality issue was observed during the inspection conducted on 13th August 2007, and 15th August 2007, respectively.
- During the inspection on 17th August 2007, the bund at the roadside near the site office was seen broken. The contractor was reminded to repair the bund or provide sand bags to proper control the site runoff.

Prepared by : Chau Tsz Wing


Title : ET – Environmental Technician

Signature : 

Date : 17th August 2007

Reviewed and approved by : Susana Bezy

Title : Environmental Team Leader

Signature : 

Date : 17th August 2007

Sent to: IEC (ERM), ER (Maunsell), Contractor (Chun Wo)

**Contract No. HY 2004/09 Improvements to San Tin Interchange
Water Quality Visual Inspection Report**

Weekly Report No.: 112

	(1)	(2)	(3)
Date of Inspection:	20 th August 2007	22 nd August 2007	24 th August 2007
Time:	14:45	14:30	14:45
Weather Condition:	Fine	Cloudy	Sunny
Works Inspected:	Drainage laying and trench works	Drainage laying and trench works	Drainage laying and trench works
Location:	Division North 1, 2 & South	Division North 1, 2 & South	Division North 1, 2 & South

Are Works in Compliance with:

	Y	N
1. Water Pollution Control Ordinance and the Subsidiary Legislation	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Recommendations and requirements in the Project EIA Report, EM&A Manual and Environmental Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Recommendations and requirements in the Contractor's Drainage Management Plan (DMP)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Contract No. HY/2004/09, Particular Specification Section 26, Environmental Protection, items under Clause 26.04	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Recommendations and requirements in the ProPECC Note PN 1/94 "Construction Site Drainage"	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Any relevant Effluent Discharge License received by the Contractor	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Description of Environmental Non-compliance or Deficiency (if any):

Nil.

Remedial Actions – Mitigation Measures Implemented or Proposed (if any):


Nil.

Remarks:

- No specific water quality issue was observed during the inspection conducted on 20th August 2007, and 24th August 2007, respectively.
- During the inspection on 22nd August 2007, the deposited sand and silts have accumulated at the U-channel in N2 Division. The contractor was reminded to remove the deposited silts from the U-channel on a regular basis as proper maintenance of the site drainage system.

Prepared by : Chau Tsz Wing


Title : ET – Environmental Technician

Signature : 

Date : 28th August 2007

Reviewed and approved by : Susana Bezy

Title : Environmental Team Leader

Signature : 

Date : 28th August 2007

Sent to: IEC (ERM), ER (Maunsell), Contractor (Chun Wo)

**Contract No. HY 2004/09 Improvements to San Tin Interchange
Water Quality Visual Inspection Report**

Weekly Report No.: 113

	(1)	(2)	(3)
Date of Inspection:	28 th August 2007	29 th August 2007	30 th August 2007
Time:	14:45	14:30	09:45
Weather Condition:	Fine	Sunny	Sunny
Works Inspected:	Drainage laying and trench works	Drainage laying and trench works	Drainage laying and trench works
Location:	Division North 1, 2 & South	Division North 1, 2 & South	Division North 1, 2 & South

Are Works in Compliance with:

	Y	N
1. Water Pollution Control Ordinance and the Subsidiary Legislation	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Recommendations and requirements in the Project EIA Report, EM&A Manual and Environmental Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Recommendations and requirements in the Contractor's Drainage Management Plan (DMP)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Contract No. HY/2004/09, Particular Specification Section 26, Environmental Protection, items under Clause 26.04	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Recommendations and requirements in the ProPECC Note PN 1/94 "Construction Site Drainage"	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Any relevant Effluent Discharge License received by the Contractor	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Description of Environmental Non-compliance or Deficiency (if any):

Nil.

Remedial Actions – Mitigation Measures Implemented or Proposed (if any):


Nil.

Remarks:

- No specific water quality issue was observed during the inspection conducted on 28th August 2007, 29th August 2007 and 30th August 2007, respectively.

Prepared by : Chau Tsz Wing


Title : ET – Environmental Technician

Signature : 

Date : 30th August 2007

Reviewed and approved by : Susana Bezy

Title : Environmental Team Leader

Signature : 

Date : 30th August 2007

Sent to: IEC (ERM), ER (Maunsell), Contractor (Chun Wo)