

Environmental Protection Department
28/F Southorn Centre
130 Hennessy Road, Wanchai
Hong Kong

Our ref: KSL09/GEN/EN101/221060

Attn: Mr. Keith Lam

21 April 2009

Dear Keith,

Kowloon Southern Link
Environmental Permit EP-215/2005/B
EP Condition 4.7
Measures to Mitigate Operational Water Quality Impact

Pursuant to EP Condition 4.7, please be confirmed that the operational water quality mitigation measures, namely freshwater cooling system and tracks contained in watertight concrete tunnel were implemented. The audit on the measures was certified by myself and verified by the IEC that a verification letter is attached.

Yours sincerely,



Richard Kwan
Manager – Environmental
(Environmental Team Leader)

Encl.


cc:

ENSR IEC (Y T Tang/Edith Ng) Fax: 2891 0305

RK/VT/TK/wc

AECOM Environment
ENSR Asia (HK) Ltd.
11/F Grand Central Plaza, Tower 2, 133 Shatin Rural Committee Road, Shatin, N.T., Hong Kong

安社亚洲(香港)有限公司
香港新界沙田乡事会路 138 号新城中心广场第 2 座 11 楼
T +852 2893 1551 F +852 2891 0305 www.aecom.com



Ref No: MEMCL/08/KGS811/enf1904201/0441
File: 60016779/c/enf1904201

By Fax (2145 4269)

MTR Corporation Limited
14th Floor South Wing
Canton Road Government Offices
393 Canton Road
Kowloon

Attn: Mr. David Sorton

20 April 2009

Dear Sir,

**Contract No. KGS811
Kowloon Southern Link
Independent Environmental Checker**

Measures to Mitigate Operational Water Quality Impact

Reference is made to the site audit conducted on 25 March 2008 for operational water quality mitigation measures.

We hereby verify the implementation of operational water quality mitigation measures is in compliance with the condition 4.7 of Environmental Permit No. EP-215/2005/B.

Should you have any queries, please feel free to contact me at 3105 8537.

Yours faithfully,
For and on behalf of
ENSR Asia (HK) Ltd.

Y T Tang
Independent Environmental Checker