

Photographs and Layout Plan for YTML Lot No. 32-33



Photo 52 YTML 32-33 : Car repair centre in operation (24 Dec 98)



Photo 53 YTML 32-33 : Car repair centre in operation (24 Dec 98)



Photo 54 YTML 32-33 : Area vacated for vehicle parking (5 Dec 98)



Photo 55 YTML 32-33 : Vacated lot area, location of former a ship repair jetty (5 Dec 98)



Photo 56 **YTML 32-33 : The only entrance for the lot (5 Dec 98)**



Photo 57 **YTML 32-33 : The rear door of the car service centre (5 Dec 98)**



Photo 58 YTML 32-33 : Area vacated for vehicle parking (5 Dec 98)





Photo 59 YTML 32-33 : Oil stain revealed inside the car repair workshop (26 Jan 99)



Photo 60 **YTML 32-33 : Oil stain revealed inside the car repair workshop (26 Jan 99)**



Photo 61 **YTML 32-33 : Outdoor repair station at the back of the car repair workshop (26 Jan 99)**



Note : Current Lot, Status - Vacanted Lot, with Car Service Workshop in Structure

Scale:	NTS
Figure:	9
Title: Layout Plan for YTML Lot No. 32-33	



EHS CONSULTANTS LIMITED