


APPENDIX 6-2

**FIELD SURVEY FINDINGS ON CONDITION OF VILLAGE HOUSE
AND ASSOCIATED SEWERAGE SYSTEM**

Location of Existing Structures found on Site





Field survey was conducted in 2011 to identify the condition and occupancy of village houses and other facilities found on site. Structures identified on site are illustrated below:











Condition of Existing Structures and Sewerage System




Table below summarized the occupancy of the structures found on site and the respective sewage treatment method from these structures. The survey results suggested that 10 houses are occupied for residential use while 8 houses (i.e. House No. 3, 5, 7, 8, 9, 10, 15 and 18) and 2 toilets i.e. No. 6 and 13 are discharged directly into the existing ponds, fields and watercourses without any treatment and while the others are treated by septic tanks

House No.	Occupied?	Use of Structure	Sewage Treatment Method	Site Photo
1	N	Unknown	Not Applicable	
2	N	Unknown	Not Applicable	
3	Y	Residential	No Treatment – Discharge to Field Directly	

4	Y	Store	Not Applicable	
5	Y	Residential	No Treatment – Discharge to Pond Directly	
6	Y	Toilet	No Treatment – Discharge to Watercourse Directly	
7	Y	Residential	No Treatment – Discharge to Field Directly	

8	Y	Residential	No Treatment – Discharge to Field Directly	
9	Y	Residential	No Treatment – Discharge to Field Directly	
10	Y	Residential	No Treatment – Discharge to Field Directly	
11	N	Unknown	NA	

12	Y	Store	NA	
13	Y	Toilet	No Treatment – Discharge to Watercourse Directly	
14	Y	Residential	Septic Tanks	
15	Y	Residential	No Treatment – Discharge to Field Directly	

16	Y	Residential	Septic Tanks	
17	Y	Store	Not Applicable	
18	Y	Residential	No Treatment – Discharge to Field Directly	
19	N	Unknown	Not Applicable	