

# Slope Stabilization



Existing conditions



Indicative photomontage of view after installation of soil nails on slope portion immediately above rock slope at toe of natural slope. Affected soil slope restored with hydroseeding and planting



Existing conditions



Indicative photomontage of view after installation of soil nails on soil slope at the toe of natural slope. Affected soil slope restored with hydroseeding and planting

Revision	Date	Description			Initial
		Designed	Checked	Drawn	
Initial					
Date					

Agreement No.  
CE 21/2012 (WS)

Contract title  
DESALINATION PLANT AT TSEUNG KWAN O - FEASIBILITY STUDY

Drawing title  
ILLUSTRATIONS OF POTENTIAL SLOPE MITIGATION WORKS

Drawing no. FIGURE 11.13c	Revision
------------------------------	----------

Scale



BLACK & VEATCH HONG KONG LIMITED  
博威工程顧問有限公司