

# Slope Stabilization



Existing conditions



Indicative photomontage of view after installation of soil nails on slope portion immediately above rock slope at toe of natural slope. Affected soil slope restored with hydroseeding and planting



Existing conditions



Indicative photomontage of view after installation of soil nails on soil slope at the toe of natural slope. Affected soil slope restored with hydroseeding and planting

Revision	Date	Description			Initial
		Designed	Checked	Drawn	
Initial					
Date					

Agreement No.	CE 21/2012 (WS)
---------------	-----------------

Contract title	DESALINATION PLANT AT TSEUNG KWAN O - FEASIBILITY STUDY
----------------	---

Drawing title	ILLUSTRATIONS OF POTENTIAL SLOPE MITIGATION WORKS
---------------	---

Drawing no.	FIGURE 3.3c	Revision	
-------------	-------------	----------	--

Scale	
-------	--

