## Hong Kong Kwong Tai Builders Limited

#### Contract No. SSW 317

#### Construction of a Secondary Boundary Fence from Mai Po to Lok Ma Chau Control Point

Environmental Monitoring and Audit Monthly Report

October 2010

(Version 1.1)

Certified By

Dr. Priscilla Choy

(Environmental Team Leader)

#### REMARKS:

The information supplied and contained within this report is, to the best of our knowledge, correct at the time of printing.

CINOTECH accepts no responsibility for changes made to this report by third parties

#### CINOTECH CONSULTANTS LTD

Room 1710, Technology Park, 18 On Lai Street, Shatin, NT, Hong Kong Tel: (852) 2151 2083 Fax: (852) 31071388

Email: info@cinotech.com.hk

#### TABLE OF CONTENTS

	Paş	ge
EX	ECUTIVE SUMMARY	. 1
1	INTRODUCTION	. 3
Ba	kground	. 3
Pro	ject Organizations	. 4
Co	nstruction Programme	. 4
Sui	nmary of EM&A Requirements	. 5
2	NOISE	6
Mo	nitoring Requirements	6
Mo	nitoring Locations	6
Mo	nitoring Equipment	6
Mo	nitoring Parameters, Frequency and Duration	6
Mo	nitoring Methodology and QA/QC Procedures	. 7
Ma	intenance and Calibration	. 7
Re	ults and Observations	. 7
3	ENVIRONMENTAL AUDIT	, 9
En	vironmental Site Audits	9
Sta	tus of Environmental Licensing and Permitting	11
Sta	tus of Waste Management	11
Im	plementation Status of Environmental Mitigation Measures	12
Im	plementation Status of Event Action Plans	12
Sui	nmary of Complaints and Prosecutions	12
4	FUTURE KEY ISSUES	13
Ke	Issues for the Coming Month	13
Co	struction Program for the Next Month	13
Mo	nitoring Schedule for the Next Month	13
5	CONCLUSIONS AND RECOMMENDATIONS	14
Co	nclusions	14
Re	commendations	14

#### LIST OF TABLES

Table I	Summary Table for Events Recorded in the Reporting Month
Table II	Summary of Key Information in the Reporting Month
Table 1.1	Key Project Contacts
Table 1.2	Monitoring Requirements
Table 2.1	Locations of Noise Monitoring Station
Table 2.2	Noise Monitoring Equipment
Table 2.3	Noise Monitoring Parameters, Frequency and Duration
Table 2.4	Baseline Noise Levels and Allowed Construction Noise Level for Monitoring
	Table
Table 2.5	Wind Speed on Monitoring Date
Table 3.1	Observations and Recommendations of Site Audits
Table 3.2	Environmental License or Permit Obtained in Reporting Month

#### LIST OF FIGURE

Figure 1.1	Site Layout Plan
Figure 1.2	ET's Organization Chart
Figure 1.3	Project Organization Chart
Figure 2.1	Locations of Construction Noise Monitoring Stations

#### LIST OF APPENDICES

Appendix A	Action and Limit Levels
Appendix B	Copies of Calibration Certificates
Appendix C	Summary of Exceedance
Appendix D	Noise Monitoring Results and Graphical Presentations
Appendix E	Site Audit Summary
Appendix F	Summary of Waste Generated
Appendix G	Environmental Mitigation Implementation Schedule (EMIS)
Appendix H	Event Action Plans for Construction Noise
Appendix I	Tentative Construction Programme
Appendix J	Environmental Monitoring Schedule

#### **EXECUTIVE SUMMARY**

#### Introduction

- 1. This is monthly Environmental Monitoring and Audit (EM&A) Report prepared by Cinotech Consultants Limited (Cinotech) for the Contract No. SS W317 "Construction of a Secondary Boundary Fence from Mai Po to Lok Ma Chau Control Point" (hereinafter called "the Project"). This document reports the findings of the environmental auditing works conducted on October 2010.
- 2. The site activities undertaken in the reporting month were:
  - Tree felling: 851M;
  - Excavation Work:- 585M;
  - blinding concrete: 335M;
  - Fixing reinforcement and formwork for footing:- 485M;
  - placing footing concrete (grade 30/20) :- 485M;
  - Fixing reinforcement and formwork for curb: 649M;
  - placing concrete for curb:- 649M; and
  - Backfill:- 331M.

#### **Environmental Monitoring and Audit Works**

- 3. Environmental monitoring and audit works for the Project was commenced on 17 March 2010.
- 4. Environmental monitoring and audit works for the Project is stipulated in the approved EM&A Manual. Site audits were conducted once per week. Environmental site audits were conducted on 6, 13, 20, and 27 October 2010. No non-compliance was observed during the site audits.
- 5. The implementation of the environmental mitigation measures, Event Action Plans and environmental complaint handling procedures were also checked.
- 6. Summary of the events and action taken in the reporting month is tabulated in **Table I**.

 Table I
 Summary Table for Events Recorded in the Reporting Month

Parameter	No. of 1	Events	No. of Events	Action Taken
1 at afficiet	<b>Action Level</b>	Limit Level	<b>Due to the Project</b>	ACTION TAKEN
Noise	0	0	0	N/A

#### **Construction Noise**

7. All construction noise monitoring was conducted as scheduled in reporting month. No Action/Limit Level exceedance was recorded.

#### **Environmental Licenses and Permits**

8. Licenses/Permits granted to the Project include Environmental Permit, Billing Account under Waste Disposal Ordinance, Notification pursuant to Section 3(1) of the Air Pollution Control Ordinance (Construction Dust) Regulation and Registration as Chemical Waste Producer.

#### **Key Information in the Reporting Month**

9. Summary of key information in the reporting month are in **Table II**.

Table II Summary of Key Information in the Reporting Month

E4	Event Details		- A -4: T-1	GL 4	D 1	
Event	Number	Nature	Action Taken	Status	Remark	
Complaint received	0		N/A	N/A		
Changes to the assumptions and key construction / operation activities recorded	0		N/A	N/A		
Status of submissions under EP	1	Monthly EM&A Report	Submitted to EPD on 15 October 2010	No Comment		
Notifications of any summons & prosecutions received	0		N/A	N/A		

• Future Key Issues:

Major site activities for the coming two months include:

- Footing construction: (Type 3 footing) CH86 to CH318
- Tree protection and maintenance: whole site
- To complete the tree felling.

The anticipated environmental impact will be potential damage on retaining trees.

#### 1 INTRODUCTION

#### **Background**

- 1.1 The Project "Construction of a Secondary Boundary Fence from Mai Po to Lok Ma Chau Control Point" with a Contract No. SS W317 is the Section 1 of the "Construction of a Secondary boundary Fence and new sections of Primary Boundary Fence and Boundary Patrol Road". Hong Kong Kwong Tai Builders Limited (hereinafter called the "Contractor") was commissioned by Architectural Services Department (ArchSD) of the Hong Kong Special Administrative Region (HKSAR) to undertake the construction.
- 1.2 The Project mainly comprises a construction purposed to erect a secondary fence along the existing boundary patrol road (approximately 4.1 km) and replace the existing checkpoint at Pak Hok Chau. **Figure 1.1** shown site layout plan.
- 1.3 An Environmental Permit No. EP-347/2009 was issued on 5 June 2009 to the Secretary for Security as the Permit Holder for "Construction of a Secondary Boundary Fence and new sections of Primary Boundary Fence and Boundary Patrol Road". Later, a Further Environmental Permit (No. FEP-01/347/2009) (hereinafter called the FEP) was issued on 19 February 2010 to Contractor as Permit Holder for the Project. On 9 June 2010, a VEP (EP-347/2009/A) for the whole project was issued to Secretary for Security as the Permit Holder with amendments on the scale and scope of section 4 in whole project.
- 1.4 An environmental impact assessment (EIA) report of the Construction of a Secondary Boundary Fence and new sections of Primary Boundary Fence and Boundary Patrol Road (Register No. AEIAR-136/2009) has been prepared in January 2009.
- 1.5 The Environmental Monitoring and Audit Manual (Project's EM&A Manual) was also included as part of the EIA report in the register and the Environmental Monitoring & Audit (EM&A) requirements are specified in Section 10.The Contractor shall follow the requirements stipulated in the EM&A requirements when implementing the Project.
- 1.6 Cinotech Consultants Ltd. (Cinotech) was commissioned by the Contractor to undertake the Environmental Monitoring and Audit (EM&A) works for the Project under Condition 2.1 of FEP.
- 1.7 Environmental monitoring and audit works for the Project was commenced at 17 March 2010.
- 1.8 This is monthly EM&A Report summarizing the EM&A works for the Project in October 2010.

#### **Project Organizations**

- 1.9 Different parties with different levels of involvement in the project organization include:
  - The Engineer for the Contract Mott MacDonald Limited (MMD).
  - Contractor Hong Kong Kwong Tai Builders Limited (HKKT).
  - Contractor Environmental Team (CET) Cinotech Consultants Limited (Cinotech).
  - Independent Environmental Checker (IEC) ENVIRON Hong Kong Limited (ENVIRON).
- 1.10 The responsibilities of respective parties are provided in Section 2.2 to 2.7 of the EM&A Manual of the Project.
- 1.11 The key contacts of the Project are shown in Table 1.1.

**Table 1.1 Key Project Contacts** 

Party	Name	Role	Phone No.	Fax No.
Engineer Mr. Peter Tsang		Engineer's Representative	26831179	
Contractor	Mr. Alex Cheung	Site Agent	64731088	27894184
Contractor	Mr. Tony Lau	Environmental Officer	61807827	2/094104
	Dr. Priscilla Choy	Contractor's Environmental Team Leader (CETL)	2151 2089	
Contractor's ET	Mr. Gary Lau	Project Coordinator & Audit Team Leader	2151 2098	3107 1388
	Mr. Henry Leung	Monitoring Team Leader	9779 7340	
IEC	Mr. David Yeung	Independent Environmental Checker (IEC)	3743 0717	3548-6988
IEC	Mr. Simon Lam	Independent Environmental Checker (IEC) Representative	3743 0708	3340-0900

1.12 The organization chart of ET and the Project are shown in **Figure 1.2** and **1.3** respectively.

#### **Construction Programme**

- 1.13 The construction activities undertaken in the reporting month were:
  - Tree felling: 851M;
  - Excavation Work: 585M;
  - blinding concrete:- 335M;
  - Fixing reinforcement and formwork for footing:- 485M;
  - placing footing concrete (grade 30/20) :- 485M;
  - Fixing reinforcement and formwork for curb: 649M;
  - placing concrete for curb:- 649M; and
  - Backfill:- 331M.

#### **Summary of EM&A Requirements**

- 1.14 The EM&A programme requires construction phase monitoring for construction noise and environmental site audit. The duties and responsibilities comprise the following:
  - > monitor various environmental parameters as specified in the EM&A Manual;
  - > analyze the environmental monitoring and audit data;
- review the EM&A programme to confirm the adequacy and effectiveness of mitigation measures implemented and the validity of the EIA predictions and to identify and adverse environmental impacts arising;
- rearry out site inspection to investigate and audit the Contractor's site practice, equipment and work methodologies with respect to pollution control and environmental mitigation, and effect proactive action to pre-empt problems;
- ➤ audit and prepare EM&A reports on the site environmental conditions;
- report the environmental audit results to the Contractor;
- > recommend appropriate mitigation measures to the Contractor in case of exceedance of Action and Limit Levels in accordance with the Event and Action Plans
- 1.15 Summary of monitoring requirements are shown in the table below:

**Table 1.2 Monitoring Requirements** 

Monitorin g Station	Parameter (Noise), dB(A)	Period	Frequency	Measurement
VH 01 and VH 03	L <sub>10</sub> (30 min.) L <sub>90</sub> (30 min.) L <sub>eq</sub> (30 min.)	07:00-19:00 hours on normal weekdays (During construction)	Once per week	Façade

- 1.16 The advice on the implementation status of environmental protection and pollution control/mitigation measures is summarized in Section 3 of this report.
- 1.17 This report presents the monitoring results, observations, locations, equipment, period, methodology and QA/QC procedures of the required monitoring parameters, namely noise levels and audit works for the Project in October 2010.

#### 2 NOISE

#### **Monitoring Requirements**

2.1 In accordance with the EM&A Manual, two noise monitoring stations (VH01and VH03) out of ten noise monitoring stations in EIA report were considered representative for Section 1 and designated for impact noise monitoring. **Appendix A** shows the established Action/Limit Levels for the environmental monitoring works.

#### **Monitoring Locations**

2.2 **Table 2.1** describes the locations of the monitoring stations and their locations are shown in **Figure 2.1**.

**Table 2.1 Locations of Noise Monitoring Stations** 

Monitoring Station	Location	
VH01	Will H W.D	
VH03	Village House at Mai Po	

#### **Monitoring Equipment**

2.3 **Table 2.2** summarizes the noise monitoring equipment models being used. Copies of calibration certificates are attached in **Appendix B**.

**Table 2.2 Noise Monitoring Equipment** 

Equipment	Model and Make	Quantity
Integrating Sound Level Meter	SVAN 955	1
Calibrator	SV30A	1

#### **Monitoring Parameters, Frequency and Duration**

2.4 **Table 2.3** summarizes the monitoring parameters, frequency and total duration of monitoring.

Table 2.3 Noise Monitoring Parameters, Frequency and Duration

Monitoring Station	Time Period	Frequency	Parameter	Method
VH01 and VH03	0700-1900 hrs on weekdays	Once per week	$L_{eq}(30\text{min.}) \text{ dB(A)}$ $L_{10}(30\text{min.}) \text{ dB(A)}, \&$ $L_{90}(30\text{min.}) \text{ dB(A)}$	Façade measurement

#### Monitoring Methodology and QA/QC Procedures

- The microphone head of the head level meter should position 1m exterior of the noise sensitive facade and lowered sufficiently so that the building's external wall acts as a reflecting surface.
- The battery condition should check to ensure the correct functioning of the meter.
- Parameters such as frequency weighting, the time weighting and the measurement time were set as follows:

frequency weighting: Atime weighting: Fast

time measurement : 30 minutes / 5 minutes

- Prior to and after each noise measurement, the meter was calibrated using a
  Calibrator for 94 dB at 1000 Hz. If the difference in the calibration level before
  and after measurement was more than 1 dB(A), the measurement was considered
  invalid and repeat of noise measurement was required after re-calibration or repair
  of the equipment.
- The wind speed was frequently checked with the portable wind meter.
- At the end of the monitoring period, the  $L_{eq}$ ,  $L_{90}$  and  $L_{10}$  were recorded. In addition, site conditions and noise sources were record on a standard record sheet.
- Noise measurement was paused during periods of high intrusive noise if possible and observation was recorded when intrusive noise was not avoided.
- Noise monitoring was cancelled in the presence of fog, rain, and wind with a steady speed exceeding 5 m/s, or wind with gusts exceeding 10 m/s.

#### **Maintenance and Calibration**

- 2.5 Maintenance and Calibration procedures were as follows:
  - The microphone head of the sound level meter and calibrator were cleaned with a soft cloth at quarterly intervals.
  - The meter and calibrator would send to laboratory to check and calibrate at yearly intervals.

#### **Results and Observations**

- 2.6 All construction noise monitoring at two designated locations were conducted as scheduled in the reporting month. The Monitoring scheduled is shown in **Appendix J.**
- 2.7 No Action/Limit Level exceedance was recorded in the reporting month. Summary of exceedance is shown in **Appendix C.**

- 2.8 The effects of weather condition on the monitoring results are insignificant and the major noise source identified for these monitoring stations was road traffic noise. Weather condition, noise monitoring results and graphical presentations are shown in **Appendix D**.
- 2.9 In accordance with Condition 5.2 of the EP, all environmental monitoring data was made available to the public via internet access at the website http://www.cinotech.com.hk/projects/SBF.
- 2.10 All the Construction Noise Levels (CNLs) reported in this report had been adjusted with the corresponding baseline levels (i.e. Measured Leq Baseline Leq = CNL), in order to facilitate the interpretation of the noise exceedance. The baseline noise level and the allowed CNL at each construction noise monitoring station are presented in **Table 2.4**.

Table 2.4 Baseline Noise Levels and Allowed Construction Noise Level (CNL) for the Monitoring Stations

Station	Baseline Noise Level, dB (A)	Allowed CNL, dB (A)
VH01 Villager House	56.4	75
VH03 Villager House	49.8	75

2.11 The wind speed records on monitoring date were shown in **Table 2.5.** 

**Table 2.5** Wind Speed on Monitoring Date

M	Wind	Wind Speed (m/s)			
Monitoring Date	Monito	ring Station			
	VH01	VH03			
6/10/2010	2.1	1.9			
15/10/2010	0.5	1.2			
19/10/2010	0.9	1.1			
28/10/2010	1.8	1.6			

#### 3 ENVIRONMENTAL AUDIT

#### **Environmental Site Audits**

- 3.1 Environmental site audits were carried out on weekly basis to monitor the timely implementation of proper environmental management practices and mitigation measures in the Project site.
- 3.2 Site audits for the Project in the reporting month were conducted on 6, 13, 20 and 27 October 2010. No non-compliance was observed during the site audits.
- 3.3 Site inspections were undertaken to ensure and check the compliance with the FEP and that the implementation and maintenance of air quality, water quality, ecology and landscape and visual mitigation measures are being properly carried out in the reporting month in accordance to section 3.2, 5.2, 6.2 and 7.3 of the EM&A Manual respectively. No non-compliance was observed during the site inspections.
- 3.4 In accordance with to Condition 3.2 of the FEP, egretry survey was jointly conducted with IEC representative on 5 August 2010.
- 3.5 No breeding Ardeids was found in the Tam Kon Chau Egretry or within the buffer area it is believed that there is currently no breeding activity in Tam Kon Chau Egretry within the 150m buffer zone.
- 3.6 Approvals from AFCD and EPD were received on 17th and 25th August 2010 respectively for commencement of construction works within the 150m buffer zone at Tam Kan Chau Egretry after 1st August 2010 and no construction works using power mechanical equipments shall be allowed between 15th November and 15th March inclusive in any consecutive year within the mentioned area.
- 3.7 Excavation works were commenced after 25th August 2010 within the 150m buffer zone from Tam Kon Chau Egretry.
- 3.8 The summaries of site audits are attached in **Appendix E**.
- 3.9 During site inspections in the reporting month, no non-conformance was identified. The observations and recommendations are summarized in **Table 3.1**.

**Table 3.1** Observations and Recommendations of Site Audits

Parameters	Date (Ref. no.)	Observations	Remediation/ Follow up
Air Quality	06-10-10 (01006-O(3))	To cover the stockpile to reduce dust emission.	The situation was observed outstanding and remarked as item 01013-O (2) on 13-10-10.
	13-10-10 (01013-O(2))	To cover the stockpile to reduce dust emission.	The situation was observed outstanding and remarked as item 01020-O (2) on 20-10-10.
	13-10-10 (01013-O(4))	To clear the mud after back filling.	The situation was observed outstanding and remarked as item 01020-O (4) on 20-10-10.

			<u> </u>	
	20-10-10 (01020-O(4))	To clear the mud after back filling.	The situation was improved / rectified on 27-10-10.	
	20-10-10 (01020-O(2))	To cover the stockpile to reduce dust emission.	The situation was observed outstanding and remarked as item 01027-O (2) on 27-10-10.	
	27-10-10 (01027-O(2))	To cover the stockpile to reduce dust emission and run-off at temporary storage area and next to fish pond.	The situation will be followed up during coming audit sessions.	
	27-10-10 (01027-O(4))	Vehicles were observed without using the wheels washing area before leaving the construction area. Contractor was reminded to notify their Sub-contractor to wash the wheels to reduce dust emission.	The situation will be followed up during coming audit sessions.	
	13-10-10 (01013-O(2))	To cover the stockpile to prevent surface run-off.	The situation was observed outstanding and remarked as item 01020-O (2) on 20-10-10.	
	13-10-10 (01013-O(3))	Muddy water was observed in Wheels washing area. Contractor was reminded to clear it more frequently.	The situation was improved / rectified on 20-10-10.	
	20-10-10 To cover the stockpile to presurface run-off.		The situation was observed outstanding and remarked as item 01027-O (2) on 27-10-10.	
	20-10-10 (01020-O(3))	Accumulation of silt and mud was observed in wheels washing bay Contractor was reminded to remove it regularly.	The situation was improved / rectified on 27-10-10.	
Water Quality	20-10-10 (01020-O(5))	Oily waster was observed in excavated area. Contractor was reminded to provide better water treatment facilities and treat the water before discharge.	The situation was improved / rectified on 27-10-10.	
	27-10-10 (01027-O(2))	To cover the stockpile to reduce dust emission and run-off at temporary storage area and next to fish pond.	The situation will be followed up during coming audit sessions.	
	27-10-10 (01027-O(3))	The green net next to fish pond was observed improperly maintained. Contractor was reminded to properly erect the net to prevent soil erosion into the fish pond.	The situation will be followed up during coming audit sessions.	
	27-10-10 (01027-O(5))	Waste water was found improperly treated. Contractor was reminded to provide proper water treatment facilities.	The situation will be followed up during coming audit sessions.	
Landscape and Visual			The situation was observed outstanding and remarked as item 01013-O (1) on 13-10-10.	
	13-10-10 (01013-O(1))	To erect protection fencing around the retaining trees at work area.(Keep progress)	The situation was observed outstanding and remarked as item 01020-O (1) on 20-10-10.	
	20-10-10 (01020-O(1))	To erect protection fencing around the retaining trees at work area.(Keep progress)	The situation was observed outstanding and remarked as item 01027-O (1) on 27-10-10.	

	27-10-10 (01027-O(1))	To erect protection fencing around the retaining trees at work area.(Around 80% completed)	The situation will be followed up during coming audit sessions.	
Waste / Chemical	06-10-10 (01006-O(2))	Oil containers were observed without labeling and drip tray. Contractor was reminded to provide label and drip tray to contain it.	The situation was improved / rectified on 13-10-10.	
Management	20-10-10 (01020-O(6))	To remove the chemical containers as chemical waste.	The situation was improved / rectified on 27-10-10.	

3.10 Proactive liaison with the contractor and close monitoring of contractor's work practices will be undertaken to ensure environmental mitigation measures are fully implemented and environmental deficiencies observed during site inspections are rectified promptly. On-site meeting would be arranged with the contractor after each site inspection in coming reporting months to discuss on the outstanding environmental deficiencies and to advise remedial measures to the contractor, so that the outstanding deficiencies could be rectified as soon as possible.

#### Status of Environmental Licensing and Permitting

3.11 Environmental license or permit obtained in the reporting month is shown in **Table 3.2.** 

 Table 3.2
 Environmental License or Permit Obtained in Reporting Month

Type of License/ Number		Valid P	eriod	- Details	Status
Permit	Number	From	То	Detans	Status
VEP	EP-347 /2009/A	15/06/2010	N/A	Location: Boundary patrol road between Mai Po and Lok Ma Chau Control	Vaild
FEP	FEP- 01/347/2009	19/02/2010	N/A	Point Po and Lok Wa Chau Control	Vaild
Registration as Chemical Waste Producer	5213-542- H3263-02	29/03/2010	N/A	i) Location of waste is produced: Border Road, Yuen Long  ii) Major chemical waste: Waste paint drum, waste paint can and waste paint.	Vaild
Billing Account under Waste Disposal Ordinance	7010229	11/02/2010	N/A	Disposal of construction and demolition waste under Waste Disposal Ordinance	Valid
Form NA	314415	23/02/2010	N/A	Notification pursuant to Section 3(1) of the Air Pollution Control Ordinance (Construction Dust) Regulation	N/A

#### **Status of Waste Management**

3.12 The amount of waste generated by the construction activities of the Project in the reporting month is shown in **Appendix F**.

#### **Implementation Status of Environmental Mitigation Measures**

3.13 According to the Environmental Permit and the EM&A Manual, the mitigation measures detailed in the documents are required to be implemented. Details of implementation Status of Environmental Mitigation Measures are provided in **Appendix G**.

#### **Implementation Status of Event Action Plans**

- 3.14 The Event Action Plans for construction noise are presented in **Appendix H**.
  - Construction Noise
- 3.15 No Action/Limit Level exceedance was reported in the reporting month.

#### **Summary of Complaints and Prosecutions**

3.16 No environmental complaint and prosecution related to the Project works was received in the reporting month.

#### 4 FUTURE KEY ISSUES

#### **Key Issues for the Coming Month**

- 4.1 Key issues to be considered in the coming month include:
  - Generation of dust from stockpiles of excavated and dusty materials;
  - Storage of chemicals/fuel and chemical waste/waste oil on-site;
  - Larviciding against mosquito breeding in stagnant water should be carried out at least on a weekly basis;
  - Silt and dust getting into the public area by the leaving site vehicles at the site exits without adequate wheel washing facilities;
  - Provide proper treatment of wastewater;
  - Site tidiness;
  - Maintenance of the protection fence for retaining trees; and
  - No using power mechanical equipments shall be allowed between 15th November and 15th March inclusive in any consecutive year.

#### **Construction Program for the Next Month**

4.2 The tentative construction program for the Project is provided in **Appendix I**.

#### **Monitoring Schedule for the Next Month**

4.3 The tentative environmental monitoring schedule for coming month for the Project is provided in **Appendix J**.

#### 5 CONCLUSIONS AND RECOMMENDATIONS

#### **Conclusions**

- 5.1 Four environmental site audits were performed in October 2010. No non-compliance was observed during the site audits.
- 5.2 All construction noise monitoring was conducted as scheduled in the reporting month. All monitoring results were checked and reviewed. No Action/Limit Level exceedance was recorded.
- 5.3 No environmental complaint and prosecution related to the project was received in the reporting month.

#### Recommendations

5.4 According to the environmental audits performed in the reporting month, the following recommendations are recommended:

#### **Dust Impact**

- To ensure water spray is applied for the dust emissive works, such as breaking, loading and unloading of soil materials;
- To implement dust suppression measures on haul road, stockpiles and dry surfaces.

#### Noise Impact

- To space out noisy equipment and position as far away as possible from sensitive receivers.
- To review the works sequence of site activities so as to reduce the number of noisy equipment in concurrent operation.
- No using power mechanical equipments shall be allowed between 15th November and 15th March inclusive in any consecutive year.

#### Water Quality Impact

- To identify any wastewater discharges from site;
- To regularly maintain the condition of u-channel, catch pits and wheel washing facilities on site;
- To regularly maintain the sediment control measures after rainstorms;
- To avoid water from accumulation on site and carry out larviciding against mosquito breeding for stagnant water when mosquito larvae are observed;
- To ensure wastewater removed by dumps from the U-chancels to prevent flooding and over flow.


#### Waste/Chemical Management

- To check for any accumulation of waste materials or rubbish on site;
- To avoid any discharge of chemical waste or oil directly from the site;
- To well maintain the equipments and drip trays to avoid oil leakage;
- To avoid improper handling or storage of oil and paint drum on site.

#### Landscape

- To maintain the protection fencing surround the retaining trees;
- To remove the felled tree to avoid damage on retaining trees;
- To remove materials and equipments placed within the tree protection area;
- To conduct tree pruning works by approved landscape contractor; and
- To replant vegetation at the earliest possible stage of the construction phase.

**FIGURE** 



# **Environmental Team Leader** Dr. Priscilla Choy (Tel: 2151 2089) **Project Coordinator** - coordination of the Project and compile reports Gary Lau (Tel: 2151 2098) **Audit Team Monitoring Team** conduct site inspection, complete the environmental checklist once - perform environmental monitoring works a week **Team Leader: Henry SM Leung Team Leader: Gary Lau** (Tel: 2151 2087) (Tel: 2151 2098) Team Members: Tang Wing Kwai, Yeung Wing Kun, Tsang Tsz **Team Members: Ivy Tam,** Keung, Tao Ching Hang, Choi Wai Yi. Sam Lam


Title


Contract No: SSW 317 Construction of a Secondary Boundary Fence from Mai Po to Lok Ma Chau Control Point

ET Organization Chart

Scale		Project	
	N.T.S	No.	MA0001
Date	Jun-10	Figure	1.2
		1	







# APPENDIX A ACTION AND LIMIT LEVELS

#### Appendix A - Action and Limit Level for Construction Noise

Time Period	Action Level	Limit Level
0700-1900 hrs on normal weekdays	When one documented complaint is received	75 dB(A)

APPENDIX B COPIES OF CALIBRATION CERTIFICATES



WELLAB LIMITED

Rms 816, 1516 & 1701, Technology Park, 18 On Lai Street, Shatin, N.T, Hong Kong. Tel: 2898 7388 Fax: 2898 7076

Website: www.wellab.com.hk

#### TEST REPORT

APPLICANT:

**Cinotech Consultants Limited** 

Room 1710, Technology Park,

18 On Lai Street,

Shatin, NT, Hong Kong

Test Report No.: C/N/100123/1
Date of Issue: 2010-01-23
Date Received: 2010-01-22

Date Tested:
Date Completed:

2010-01-23

Next Due Date:

2010-01-23 2011-01-22

ATTN:

Mr. Henry Leung

Page:

1 of 1

#### **Certificate of Calibration**

#### Item for calibration:

Description

: 'SVANTEK' Integrating Sound Level Meter

Manufacturer

: SVANTEK

Model No.

: SVAN 955

Serial No.
Microphone No.

: 14303 : 17204

Equipment No.

: N-08-05

#### Test conditions:

Room Temperatre

: 21 degree Celsius

Relative Humidity

: 56%

#### **Test Specifications:**

Performance checking at 94 and 114 dB

#### Methodology:

In-house method, according to manufacturer instruction manual

#### Results:

Reference Set Point, dB	Instrument Readings, dB
94	94.0
114	114.0

PREPARED AND CHECKED BY:

For and On Behalf of WELLAB Ltd.

PATRICK TSE
Laboratory Manager

Room 1516 & 816, Technology Park 18 On Loi Street, Shatin, N.T., Heng Keng Tel: 2898 7388 Fax: 2898 7076 Website: http://www.wellab.com.hk E-mail: wellab@wellab.com.hk

#### TEST REPORT

APPLICANT: Cinotech Consultants Limited

Room 1710, Technology Park,

18 On Lai Street,

Shatin, NT, Hong Kong

Test Report No.:	C/N/91109/1
Date of Issue:	2009-11-09
Date Received:	2009-11-07
Date Tested:	2009-11-07
Date Completed:	2009-11-09
Next Due Date:	2010-11-08

ATTN:

Mr. Henry Leung

Page:

1 of 1

Item for calibration:

Description

: Acoustical Calibrator

Manufacturer

: SVANTEK

Model No.

: SV30A

Serial No.

: 10965

Equipment No.

: N-09-02

Test conditions:

Room Temperatre

: 21 degree Celsius

**Relative Humidity** 

: 55%

#### Methodology:

The Sound Level Calibrator has been calibrated in accordance with the documented procedures and using standard(s) and instrument(s) which are recommended by the manufacturer, or equivalent.

#### Results:

Sound Pressure Level (1kHz)	Measured SPL	Tolerance
At 94 dB SPL	94.0	94.0 ± 0.1 dB
At 114 dB SPL	114.0	114.0 ± 0.1 dB

PREPARED AND CHECKED BY:

For and On Behalf of WELLAB Ltd.

PATRICK TSE

Laboratory Manager

#### APPENDIX C SUMMARY OF EXCEEDANCE

**Appendix C – Summary of Exceedance** 

**Reporting Month:** October 2010

**Exceedance Report for Construction Noise (NIL)** 

APPENDIX D NOISE MONITORING RESULTS AND GRAPHICAL PRESENTATIONS


### Appendix D - Noise Monitoring Results


Location VH01 - Village House at Mai Po							
Unit: dB (A) (30-min)							
Date	Time	Weather	Meas	Measured Noise Level Baseline Level Construction N			
			L <sub>eq</sub>	L <sub>10</sub>	L 90	L <sub>eq</sub>	L <sub>eq</sub>
6-Oct-10	09:00	Cloudy	47.8	49.5	44.0		47.8 Measured ≤ Baseline
15-Oct-10	09:00	Cloudy	48.4	49.5	44.5	56.4	48.4 Measured ≤ Baseline
19-Oct-10	09:00	Cloudy	47.3	49.0	43.5	50. <del>4</del>	47.3 Measured ≤ Baseline
28-Oct-10	14:50	Sunny	48.1	49.5	45.0		48.1 Measured ≤ Baseline

Location VH03 - Village House at Mai Po							
				Unit: dB (A) (30-min)			
Date	Time	Weather	Meas	sured Noise	Level	Baseline Level	Construction Noise Level
			L <sub>eq</sub>	L <sub>10</sub>	L 90	L <sub>eq</sub>	L <sub>eq</sub>
6-Oct-10	09:45	Cloudy	46.9	49.0	44.0		46.9 Measured ≤ Baseline
15-Oct-10	09:40	Cloudy	47.8	49.0	44.0	49.8	47.8 Measured ≤ Baseline
19-Oct-10	09:40	Cloudy	46.9	49.0	42.0	49.6	46.9 Measured ≤ Baseline
28-Oct-10	15:40	Sunny	48.8	50.0	45.0		48.8 Measured ≤ Baseline

MA0001/App D - Noise Cinotech

#### **Noise Levels**





Contract No. SSW317
Construction of a Secondary Boundary Fence
from Mai Po to Lok Ma Chau Control Point
Graphical Presentation of Construction Noise Monitoring
Results

Title



#### APPENDIX E SITE AUDIT SUMMARY

#### Contract No. SS W317

# Construction of a Secondary Boundary Fence from Mai Po to Lok Ma Chau Control Point Weekly Site Inspection Record Summary Inspection Information

Checklist Reference Number	01006
Date	6 October 2010 (Wednesday)
Time	14:00-14:30

		Related
Ref. No.	Non-Compliance	Item No.
_	None identified	•
		Related
Ref. No.	Remarks/Observations	Item No.
	B. Water Quality	
· · · · · · · · · · · · · · · · · · ·	No environmental deficiency was identified during site inspection.	
	C. Air Quality	
01006-O(3)	To cover the stockpile to reduce dust emission.	C 6
	D. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	E. Waste / Chemical Management	
01006-O(2)	Oil containers were observed without labeling and drip tray. Contractor was reminded to provide label and drip tray to contain it.	E 4
	F. Landscape	
010060-O(1)	To erect protection fencing around the retaining trees at work area.	F 4
	H. Others	
	• Environmental deficiencies were not rectified/improved by the Contractor during the site inspection: items 00930-O(1) & (4) are remarked as items 01006-O(1) & (3)	

Reminders	Related Item No.
The Contractor was reminded to implement the following preventive measures:	
B. Water Quality	
 No environmental deficiency was identified during site inspection.	
C. Air Quality	-
 No environmental deficiency was identified during site inspection.	
•	
D. Construction Noise Impact	
No environmental deficiency was identified during site inspection.	
E. Waste / Chemical Management	
 No environmental deficiency was identified during site inspection.	
F. Landscape	
 No environmental deficiency was identified during site inspection.	
G. Permits/Licences	
No environmental deficiency was identified during site inspection.	
H. Others	
N/A	

	Name	Signature	Date
Recorded by	Gary Lau	Mary L	7 October 2010
Checked by	Dr. Priscilla Choy	KI	7 October 2010

## Contract No. SS W317

# Construction of a Secondary Boundary Fence from Mai Po to Lok Ma Chau Control Point Weekly Site Inspection Record Summary Inspection Information

And Parties And Andrews			
Checklist Reference Number	01013		
Date	13 October 2010 (Wednesday)		
Time	15:00-16:00		

		Related
Ref. No.	Non-Compliance	Item No.
-	None identified	-
		Related
Ref. No.	Remarks/Observations	Item No.
	B. Water Quality	
01013-O(2)	To cover the stockpite to reduce dust emission.	B 11
01013-O(3)	Muddy water was observed in Wheels washing area. Contractor was reminded to clear it more frequently.	В 16ііі
	C. Air Quality	
01013-O(2)	To cover the stockpile to reduce dust emission.	C 6
01013-O(4)	To clear the mud after back filling.	C 2
	D. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	E. Waste / Chemical Management	
	No environmental deficiency was identified during site inspection.	
	F. Landscape	
01013-O(1)	To erect protection fencing around the retaining trees at work area.(Keep progress)	F 4
	H. Others	
	• Environmental deficiencies were not rectified/improved by the Contractor during the site inspection: items 01006-O(1) & (3) are remarked as items 01013-O(1) & (2)	

	Reminders	Related Item No.
	The Contractor was reminded to implement the following preventive measures:	110111101
	B. Water Quality	
	No environmental deficiency was identified during site inspection.	
	C. Air Quality	
	No environmental deficiency was identified during site inspection.	
	•	
	D. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	E. Waste / Chemical Management	
	No environmental deficiency was identified during site inspection.	
,	F. Landscape	
***************************************	No environmental deficiency was identified during site inspection.	
,	G. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	H. Others	
	N/A	

	Name	Signature	Date
Recorded by	Gary Lau	Ban L.	19 October 2010
Checked by	Dr. Priscilla Choy	MI	19 October 2010

#### Contract No. SS W317

## Construction of a Secondary Boundary Fence from Mai Po to Lok Ma Chau Control Point

Weekly Site Inspection Record Summary

Inspection Information

Inspection into mation	
Checklist Reference Number	01020
Date	20 October 2010 (Wednesday)
Time	14:00-16:00

		Related
Ref. No.	Non-Compliance	Item No.
-	None identified	-
		Related
Ref. No.	Remarks/Observations	Item No.
	B. Water Quality	
01020-O(2)	To cover the stockpile to reduce dust emission.	B 11
01020-O(3)	Accumulation of silt and mud was observed in wheels washing bay Contractor was reminded to remove it regularly.	B 16iii
01020-O(5)	Oily waster was observed in excavated area. Contractor was reminded to provide better water treatment facilities and treat the water before discharge.	В 8іі
	C. Air Quality	
01020-O(2)	To cover the stockpile to reduce dust emission.	C 6
01020-O(4)	To clear the mud and sand after back filling.	C 2
	D. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
The second April 201	E. Waste / Chemical Management	
01020-O(6)	To remove the chemical containers as chemical waste.	E 2ii
	F. Landscape	
01020-O(1)	To erect protection fencing around the retaining trees at work area.(Keep progress)	F 4
	H. Others	
	• Environmental deficiencies were not rectified/improved by the Contractor during the site inspection: items 01013-O(1), (2) and (4) are remarked as items 01020-O(1) (2) & (4)	

 Reminders	Related Item No.
 The Contractor was reminded to implement the following preventive measures:	
 B. Water Quality	
 No environmental deficiency was identified during site inspection.	
 C. Air Quality	
 No environmental deficiency was identified during site inspection.	
 •	
D. Construction Noise Impact	
 No environmental deficiency was identified during site inspection.	
 E. Waste / Chemical Management	
 No environmental deficiency was identified during site inspection.	
 F. Landscape	
 No environmental deficiency was identified during site inspection.	
 G. Permits/Licences	
 No environmental deficiency was identified during site inspection.	
 H, Others	
 N/A	

#### Contract No. SS W317

## Construction of a Secondary Boundary Fence from Mai Po to Lok Ma Chau Control Point

Weekly Site Inspection Record Summary

	Name	Şignature	Date
Recorded by	Gary Lau	bank-	21 October 2010
Checked by	Dr. Priscilla Choy	WI	21 October 2010

Contract ivo. 33 W31/

#### Construction of a Secondary Boundary Fence from Mai Po to Lok Ma Chau Control Point

Weekly Site Inspection Record Summary Inspection Information

2210 P T T T T T T T T T T T T T T T T T T	
Checklist Reference Number	01027
Date	27 October 2010 (Wednesday)
Time	14:00-15:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	
Ref. No.	Remarks/Observations  B. Water Quality	Related Item No.
01027-O(2)	To cover the stockpile to reduce dust emission and run-off at temporary storage area and next to fish pond.	B 11
01027-O(3)	The green net next to fish pond was observed improperly maintained. Contractor was reminded to properly erect the net to prevent soil erosion into the fish pond.	B 13
01027-O(5)	Waste water was found improperly treated. Contractor was reminded to provide proper water treatment facilities.	B 7i
	C. Air Quality	
01027-O(2)	To cover the stockpile to reduce dust emission and run-off at temporary storage area and next to fish pond.	C 6
01024-O(4)	Vehicles were observed without using the wheels washing area before leaving the construction area. Contractor was reminded to notify their Sub-contractor to wash the wheels to reduce dust emission.	C 8
	D. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	E. Waste / Chemical Management	
	No environmental deficiency was identified during site inspection.	
	F. Landscape	
01027-O(1)	To erect protection fencing around the retaining trees at work area.(Around 80% completed)	F 4
	H. Others	
	• Environmental deficiencies were not rectified/improved by the Contractor during the site inspection: items 010120-O(1) and (2) are remarked as items 01027-O(1) & (2)	

 Reminders	Related Item No.
The Contractor was reminded to implement the following preventive measures:	
B. Water Quality	
 No environmental deficiency was identified during site inspection.	
 C. Air Quality	
No environmental deficiency was identified during site inspection.	
D. Construction Noise Impact	
No environmental deficiency was identified during site inspection.	
 E. Waste / Chemical Management	
No environmental deficiency was identified during site inspection.	
F. Landscape	
 No environmental deficiency was identified during site inspection.	
G. Permits/Licences	
 No environmental deficiency was identified during site inspection.	
 H. Others	
N/A	

# <u>Construction of a Secondary Boundary Fence from Mai Po to Lok Ma Chau Control Point</u> Weekly Site Inspection Record Summary

	Name	Signature	Date
Recorded by	Gary Lau	han la	28 October 2010
Checked by	Dr. Priscilla Choy	MI	28 October 2010

2

#### APPENDIX F SUMMARY OF WASTE GENERATED

Name of Department : Architectural Services Department Contract No. : SS W317 Programme No. : 15 GB

# Monthly Summary Waste Flow Table for 2010 (year) [to be submitted not later than the 15<sup>th</sup> day of each month following reporting month] (All quantities shall be rounded off to 3 decimal places.)

	Act	ual Quantities of Ir	nert C&D Materia	als Generated Mon	thly		Actual Quantities	of C&D Waste	s Generated Montl	hly
Month	(a)=(b)+(c)+(d)+(e) Total Quantity Generated	(b) Broken Concrete (see Note 4)	(c) Reused in the Contract	(d) Reused in other Projects	(e) Disposed as Public Fill	(f) Metals	(g) Paper/ cardboard packaging	(h) Plastics (see Note 3)	(i) Chemical Waste	(j) Others, e.g. general refuse disposed at Landfill
	(in '000m <sup>3</sup> )	(in '000m <sup>3</sup> )	(in '000m <sup>3</sup> )	(in '000m <sup>3</sup> )	(in '000m <sup>3</sup> )	(in '000 kg)	(in '000kg)	(in '000kg)	(in '000kg)	(in '000m <sup>3</sup> )
Jan	0	0	0	0	0	0	0	0	0	0
Feb	0	0	0	0	0	0	0	0	0	0
Mar	0	0	0	0	0	0	0	0	0	0
Apr	0.007	0	0	0	0.007	0	0	0	0	0
May	0	0	0	0	0	0	0	0	0	0
June	0	0	0	0	0	0	0	0	0	0.072
Sub-total	0.007	0	0	0	0.007	0	0	0	0	0.072
July	0.085	0	0	0	0.085	0	0	0	0	0.215
Aug	0.904	0	0	0	0.904	0	0	0	0	0.072
Sept	0.377	0	0	0	0.377	0	0	0	0	0
Oct	0.322	0	0	0	0.322	0	0	0	0	0
Nov										
Dec										
Total	1.695	0	0	0	1.695	0	0	0	0	0.359

Notes: (1) The performance targets are given in the Particular Specification on Waste Management Plan, Sub-clause 2(5)(c).

- (2) The waste flow table shall also include C&D materials that are specified in the Contract to be imported for use at the Site.
- (3) Plastics refer to plastic bottles/containers, plastic sheets/foam from packaging material.
- (4) Broken concrete for recycling into aggregates.
- (5) If necessary, use the conversion factor: 1 full load of dumping truck being equivalent to 6.5 m<sup>3</sup> by volume.

APPENDIX G ENVIRONMENTAL MITIGATION IMPLEMENTATION SCHEDULE (EMIS)

### $\label{lem:condition} \textbf{Appendix} \ \textbf{G} \ \textbf{-} \ \textbf{Environmental Mitigation Implementation Schedule} \ (\textbf{EMIS})$

<b>Types of Impacts</b>	Mitigation Measures	Status		
	Construction Phase			
	• Excavated dusty materials or stockpile of dusty materials should be covered entirely by impervious sheeting or sprayed with water so as to maintain the entire surface wet, and recovered or backfilled or reinstated within 24 hours of the excavation or unloading.			
	The working area of excavation should be sprayed with water immediately before, during and immediately after the operations so as to maintain the entire surface wet.	٨		
Air Quality	Dusty materials carried by vehicle leaving a construction site should be covered entirely by clean impervious sheeting.	٨		
	• Vehicle washing area and the section of the road between the washing facilities and the exit point should be paved with concrete, bituminous materials or hardcores.	N/A		
	The portion of road within 30m of designated vehicle entrance or exit should be kept clear of dusty materials.	*		
	All dusty materials should be sprayed with water prior to any loading, unloading or transfer.	٨		
	Vehicle speed should be limited to 10kph except on completed access roads.	۸		
	<ul> <li>Vehicle should be washed to remove any dusty materials from its body and wheels before leaving the construction sites.</li> </ul>	#		
	Construction Phase			
	Adopt the Code of Practice on Good Management Practice to comply with the Noise Control     Ordinance (Chapter 400) (for Construction Industry) published by EPD	۸		
	Observe and comply with the statutory and non-statutory requirements and guidelines.	۸		
	Before commencing any work, the Contractor shall submit to the Engineer Representative for approval the method of working, equipment and noise mitigation measures intended to be used at the site.	٨		
Noise	The Contractor shall devise and execute working methods to minimise the noise impact on the surrounding sensitive uses, and provide experienced personnel with suitable training to ensure that those methods are implemented.	۸		
	Noisy equipment and noisy activities should be located as far away from the NSRs as is practical.	٨		
	Unused equipment should be turned off. PME should be kept to a minimum and the parallel use of noisy equipment / machinery should be avoided.	۸		
	Regular maintenance of all plant and equipment.	٨		

	Material stockpiles and other structures should be effectively utilised as noise barriers, where practicable.	^	
	Use of Quiet Plant and Movable Noise Barrier		
	Purpose-built movable noise barriers should be used to mitigate construction noise directly at sources that are not usually mobile provide that the direct line of sight to the source is blocked.	N/A	
	Construction Phase		
	The site should be confined to avoid silt runoff to the site.		
	No discharge of silty water into the storm drain and drainage channel within and the vicinity of the site.	٨	
	Any soil contaminated with chemicals/oils shall be removed from site and the void created shall be filled with suitable materials.	۸	
	Stockpiles to be covered by tarpaulin to avoid spreading of materials during rainstorms;	#	
	Suitable containers shall be used to hold the chemical wastes to avoid leakage or spillage during storage, handling and transport.	۸	
	Chemical waste containers shall be labelled with appropriate warning signs in English and Chinese to avoid accidents. There shall also be clear instructions showing what action to take in the event of an accidental.	۸	
	Storage areas shall be selected at safe locations on site and adequate space shall be allocated to the storage area.	٨	
Water Quality	<ul> <li>Any construction plant which causes pollution to the water system due to leakage of oil or fuel shall be removed off-site immediately.</li> </ul>	۸	
water Quanty	Spillage or leakage of chemical waste to be controlled by using suitable absorbent materials.	٨	
	Chemicals will always be stored on drip trays or in bunded areas where the volume is 110% of the stored volume.	٨	
	Regular clearance of domestic waste generated in the temporary sanitary facilities to avoid waste water spillage.	۸	
	Temporary sanitary facilities to be provided for on-site workers during construction	٨	
	Concreting Work		
	• Set up a temporary drainage channel to collect the runoff generated and prevent concrete-contaminated water from entering watercourses. Adjustment of pH can be achieved by adding a suitable neutralising reagent to wastewater prior to discharge.	٨	
	Soil Excavation and Stockpiling		
	Temporarily stockpiled excavated soil should be stored in a designated area and provided with a tarpaulin cover to avoid runoff into the drainage channels.	#	
	Site Depot		

	• All compounds in works areas should be located on areas of hard standing with provision of drainage channels and settlement ponds to allow interception and controlled release of settled/treated water.	N/A					
	<ul> <li>Hard standing compounds should drain via an oil interceptor, it should be regularly inspected and cleaned to avoid wash-out of oil during storm conditions. A bypass should be provided to avoid overload of the interceptor's capacity.</li> </ul>	N/A					
	Registered as a chemical waste producer for contractor generating waste oil or other chemicals. Disposal of the waste oil should be done by a licensed collector	۸					
	• Appropriate training including safety codes and relevant manuals should be given to the personnel who regularly handle the chemicals on site to keep the storage and the work space in a tidy and clean condition.	N/A					
	Construction of Checkpoint						
	Sewage system should be constructed to divert domestic sewage, which will be generated from the sanitary facilities provided in the new checkpoint at Shek Chung Au, to public sewer connected to government sewage treatment facilities.	N/A					
	Site Clearance						
	The topsoil and vegetation removed and excavated material may have to be temporarily stockpiled on-site.to prevent the generation of dust and pollution of stormwater channels, fish ponds or river channels. Stockpiling of excavated materials during the wet season should be avoided as far as practicable.						
	Construction Phase						
	<ul> <li>Good site management to minimize over-ordering and generation of waste materials such as concrete mortars and cement grouts.</li> </ul>	٨					
	The Contractor should recycle as much of the C&D materials as possible on-site.	٨					
	Trip-ticket system should be employed to monitor the disposal of C&D material and solid at public filling facilities and landfills, and to control fly-tipping.	۸					
	Chemical Waste						
Waste	To reduce generating chemical waste as much as possible.	٨					
Management	• Containers used for the storage of chemical wastes should be suitable for the substance they are holding, resistant to corrosion, maintained in a good condition, and securely closed, have a capacity of less than 450 litres with label in English and Chinese in accordance with instructions prescribed in Schedule 2 of the Regulations.	٨					
	The storage area for chemical wastes should be clearly labelled and used solely for the storage of chemical waste.	*					
	• The storage area should be enclosed on at least 3 sides, have adequate ventilation with impermeable floor, capacity to accommodate 110% of the volume of the largest container or 20% by volume of the chemical waste stored in that area.	۸					
	<ul> <li>Rainfall entering should be avoided entering to storage area and adequately separated with incompatible materials.</li> </ul>	٨					
	Disposal of chemical waste should be via a licensed waste collector to licensed facility which can supply the	*					
	necessary storage containers, or to be re-user of the waste, under approval from the EPD.						

	• Should be stored in enclosed bins or compaction units separate from C&D and chemical wastes. The Contractor should employ a reputable waste collector to remove general refuse from the site, separate from C&D and chemical wastes, on a regular basis to minimise odour, pest and litter impacts. Burning of refuse on construction sites is prohibited by law.	۸							
	Prohibition of refuse burning on construction sites	٨							
	Construction Waste Management Plan								
	Construction waste management plan (CWMP) should be prepared	٨							
	Contractor should ensure proper collection, treatment and disposal of waste on site.	٨							
	Ecological Impacts on Floral Species of Conservation Concern								
	Erection of protective fencing to protect the plant during construction period	#							
	Potential Ecological Impacts on Offsite Habitats								
	Controlling the dust and water quality by avoiding stockpiles adjacent to wetlands and covering the stockpiles	٨							
	with impervious sheeting.								
	Controlling vehicle speed and ensure no discharge of silty water to the rivers, streams.	۸							
	Disturbance to Wetland-Dependent Birds, Raptors, Terrestrial Birds and Egretry								
Ecology	<ul> <li>Restriction of excavation works within a 150m buffer zone from the egretry to ardeid non-breeding season (from August to February).</li> </ul>	۸							
	<ul> <li>Switching off unused equipment, keep minimum number of powered mechanical equipment in operation at the same period, the use of stockpiles and other structures to form noise barriers where practicable to avoid causing disturbance to feeding the wildlife.</li> </ul>	۸							
	<ul> <li>Proper cover of stockpiles with impervious sheeting to minimize construction noise, uncontrolled surface runoff and discharge of silts.</li> </ul>	۸							
	<ul> <li>Avoidance of construction works using Power Mechanical Equipments within the Wetland Conservation Area during bird migratory season (15th November – 15th March).</li> </ul>	۸							
	Preservation of Existing Vegetation throughout construction phase								
	• To retain trees that have high amenity or ecology value and contribute most to the landscape and visual amenity of the site and its immediate environs.	^							
	<ul> <li>Prohibition of the storage of materials including fuel, the movement of construction vehicles, and the refuelling and washing of equipment including concrete mixers within the precautionary area</li> </ul>	^							
Landscape and Visual	Phased segmental root pruning for trees to be retained over a suitable period (determined by species and size) prior to lifting or site formation works which affect the existing rootball of trees identified for retention. The extent of the pruning will be based on the size and the species of the tree in each case.	۸							
	Pruning of the branches of existing trees identified for retention to be based on the principle of crown thinning maintaining their form and amenity value.	^							
	The watering of existing vegetation particularly during periods of excavation when the water table beneath the existing vegetation is lowered.	۸							
	The rectification and repair of damaged vegetation following the construction phase to it's original condition prior to the commencement of the works or replacement using specimens of the same species, size and form	^							

where appropriate to the design intention of the area affected	
<ul> <li>All works affecting the trees identified for retention will be carefully monitored, including the key stages in the preparation of the trees, the implementation of protection measures and health monitoring through out the construction period</li> </ul>	,
• Detailed landscape and tree preservation proposals will be submitted to the relevant government departments for approval under the lease conditions and in accordance with ETWB TCW No. 2/2004 and WBTC No. 3/2006.	^
The tree preservation works should be implemented by approved Landscape Contractors and inspected and approved on site by a qualified Landscape Architect. A tree protection specification would be included within the contract documents.	^
Preservation of Existing Topsoil	
• Topsoil disturbed during the construction phase should be tested using a standard soil testing methodology and where it is found to be worthy of retention stored for re-use.	N/
• The soil will be stockpiled to a maximum height of 2m and will be either temporarily vegetated with hydroseeded grass during construction or covered with a waterproof covering to prevent erosion.	N/
• Regularly turned over the stockpile to avoid acidification and the degradation of the organic material, and reused after completion.	N/
Considered for re-use in other projects when above actions are not practical.	N/
Permanent and Temporary Works Areas	
• Where appropriate to the final design the landscape of these works areas should be restored following the completion of the construction phase.	N/
• Construction site controls should be enforced including the storage of materials, the location and appearance of site accommodation and the careful design of site lighting to prevent light spillage.	^
Mitigation Planting	
Replanting of disturbed vegetation should be undertaken at the earliest possible stage of the construction phase	N/
Use of native plant species predominantly in the planting design for the buffer areas.	N/.

Remarks:	٨	Compliance of mitigation measure;						
	N/A	Not Applicable;						
	*	Recommendation was made during site audit but						
	improve	ed/rectified by the contractor.						
	#	Recommendation was made during site audit and to be						
	improve	improved / rectified by the contractor.						
	Χ	Non-compliance of mitigation measure;						
	•	Non-compliance but rectified by the contractor;						

#### APPENDIX H EVENT ACTION PLANS FOR CONSTRUCTION NOISE

#### **Appendix H- Event and Action Plan for Construction Noise**

ENGEEDANGE	ACTION										
EXCEEDANCE	ET	IEC	Engineer	Contractor							
Action Level	<ol> <li>Notify IEC and the HKKT.</li> <li>Carry out investigation.</li> <li>Report the results of investigation to IEC and the HKKT.</li> <li>Discuss with the HKKT and formulate remedial measures.</li> <li>Increase monitoring frequency to check mitigation measures.</li> </ol>	Review with analyzed results submitted by ET.     Review the proposed remedial measures by the HKKT and advise ER accordingly.     Supervise the implement of remedial measures.	Confirm receipt of notification of exceedance in writing.     Notify the HKKT.     Require the HKKT to propose remedial measures for the analyzed noise problem.     Ensure remedial measures are properly implemented.	Submit noise mitigation proposals to IEC.     Implement noise mitigation proposals.							
Limit Level	<ol> <li>Identify the source.</li> <li>Notify IEC, ER, EPD and the HKKT.</li> <li>Repeat measurement to confirm findings.</li> <li>Increase monitoring frequency.</li> <li>Carry out analysis of HKKT's working procedures to determine possible mitigation to be implemented.</li> <li>Inform IEC, ER, and EPD the causes &amp; actions taken for the exceedances.</li> <li>Assess effectiveness of the HKKT's remedial actions and keep IEC, EPD and ER informed of the results.</li> <li>If exceedance stops, cease additional monitoring.</li> </ol>	1. Discuss amongst ER, ET Leader and the HKKT on the potential remedial actions. 2. Review the HKKT's remedial actions whenever necessary to assure their effectiveness and advise ER accordingly. 3. Supervise the implementation of remedial measures.	1. Confirm receipt of notification of exceedance in writing.  2. Notify the HKKT.  3. Require the HKKT to propose remedial measures for the analyzed noise problem.  4. Ensure remedial measures are properly implemented.  5. If exceedance continues, consider what activity of the work is responsible and instruct the HKKT to stop that activity of work until the exceedance is abated.	<ol> <li>Take immediate action to avoid further exceedance.</li> <li>Submit proposals for remedial actions to IEC within 3 working days of notification.</li> <li>Implement the agreed proposals.</li> <li>Resubmit proposals if problem still not under control.</li> <li>Stop the relevant activity of works as determined by the ER until the exceedance is abated.</li> </ol>							

H-1 Cinotech

#### APPENDIX I TENTATIVE CONSTRUCTION PROGRAMME

Hong Kong Kwong Tai Builders Ltd SS W317 - Construction of a Secondary Boundary Fence From Mai Po to Lok Ma Chau Control Point Date: 16 April 2010 Master Programme 開始時間 識別 WBS Task Name 工期 完成時間 2010年7月 2010年8月 2010年9月 2010年10月 2010年11月 2010年12月 2010年2月 2010年4月 2010年5月 2010年6月 2011年1月 碼  $\left| 4 \right| \left| 1 \right| \left| 7 \right| 2 \right| 4 \right| \left| 1 \right| \left| 8 \right| \left| 7 \right| 3 \right| 4 \right| \left| 1 \right| \left| 8 \right| \left| 7 \right| 3 \right| 4 \\ \left| 1 \right| \left| 8 \right| \left| 4 \right| 4 \\ \left| 1 \right| \left| 8 \right| \left| 5 \right| 2 \\ \left| 8 \right| 8 \right| 5 \\ \left| 2 \right| \left| 9 \right| \left| 5 \right| 9 \\ \left| 2 \right| \left| 9 \right| \left| 5 \right| 9 \\ \left| 6 \right| \left| 7 \right| \left| 7 \right| \left| 4 \right| 1 \\ \left| 7 \right| 1 \\ \left| 8 \right| 1 \\ \left| 7 \right| 1 \\ \left| 8 \right| 1 \\ \left| 7 \right| 1 \\ \left| 8 \right| 1 \\ \left$ Construction of a Secondary Boundary Fence from Mai Po to 2010/1/15 2011/5/8 479 days 1 Lok Ma Chau Control Point 120 days 2 1.1 2010/11/16 2011/3/15 bird migratory season 3 1.2 Application of permits and licences required under legislation 28 days 2010/1/15 2010/2/11 1.3 Conition surveying & submission of report 2010/1/21 2010/1/30 4 10 days 5 1.4 Site Office setup 45 days 2010/2/1 2010/3/17 6 1.5 Site mobilization 45 days 2010/2/1 2010/3/17 7 1.6 Material submissions 2010/1/20 131 days 2010/5/30 8 1.6.1 Submission of XPM mesh 120 days 2010/1/20 2010/5/19 9 1.6.2 Submission of concrete mix design 28 days 2010/1/25 2010/2/21 10 1.6.3 submission of spacer 28 days 2010/3/5 2010/4/1 28 days 11 1.6.4 submission of sub-base material 2010/5/3 2010/5/30 12 1.6.5 submission of bituminous material 28 days 2010/5/3 2010/5/30 13 1.7 Initital site survey 30 days 2010/3/15 2010/4/13 2010/3/25 14 **1.8** Mock up panel 63 days 2010/5/26 15 1.8.1 submission and approval of shop drawing and method 50 days 2010/3/25 2010/5/13 statement 16 1.8.2 fix mock up panel 2010/5/20 2010/5/26 7 days 2010/1/15 2010/4/24 17 **1.9** Submissions 100 days 18 1.9.1 Submission to EPD as required under the Environment 1 day 2010/1/15 2010/1/15 Permit 2010/1/15 2010/4/14 19 1.9.2 Submission of temporary traffic arrangement 90 days 20 1.9.3 submission of safety aspect schedule 30 days 2010/1/15 2010/2/13 90 days 21 1.9.4 submission of safety plan 2010/1/25 2010/4/24 22 1.9.5 Submission of Environmental Management Plan 14 days 2010/1/25 2010/2/7 2010/1/26 23 1.9.6 submission of waste management plan 30 days 2010/2/24 24 1.9.7 Submission of Smart Card System 14 days 2010/1/27 2010/2/9 25 1.10 2010/9/3 application of excavation permit (XP Permit) 169 days 2010/3/19 CH0+285 to CH 0+315(Zone 30 - Zone 31)PlanID: 2010/9/3 26 1.10.1 2010/9/3 1 day CH 3+270 to 3+300(Zone 54)PlanID: 1006328 27 1.10.2 1 day 2010/8/30 2010/8/30 28 1.10.3 CH 0+285 to CH 0+315(Zone 30 - Zone 31)PlanID: 2010/9/3 2010/9/3 1 day 1006307 CH 3+270 to CH 3+300(Zone 54)PlanID: 1006328 29 1.10.4 2010/9/3 2010/9/3 1 day 30 1.10.5 CH 0+550 to 0+600(Zone 33)PlanID: 1006317 1 day 2010/7/12 2010/7/12 31 1.10.6 CH 2+790 to CH 2+900(Zone 51)PlanID: 1006326 2010/7/12 2010/7/12 1 day 32 1.10.7 CH 2+900 to 3+030(Zone 51 - Zone 52)PlanID: 1006328 1 day 2010/7/12 2010/7/12 33 1.10.8 CH 3+030 to CH 3+270(Zone 52 - Zone54)PlanID: 1 day 2010/7/29 2010/7/29 1006328 34 1.10.9 CH 0+000 to CH 0+090(Zone 29)PlanID: 1006307 1 day 2010/7/15 2010/7/15 CH 0+090 to CH 0+285(Zone 29 - Zone 30)PlanID: 1.10.10 2010/8/9 2010/8/9 35 1 day 1006307 36 1.10.11 CH 0+550 to CH+600(Zone 33)PlanID: 1006317 1 day 2010/7/15 2010/7/15 37 1.10.12 CH 2+790 to CH 2+900(Zone 51)PlanID: 1006326 1 day 2010/7/15 2010/7/15 1.10.13 CH 2+900 to CH 3+030(Zone 51 - Zone 52)PlanID: 2010/7/15 2010/7/15 38 1 day 1006328 39 1.10.14 CH 3+030 to CH 3+270(Zone 52 - Zone 54)PlanID: 2010/8/9 2010/8/9 1 day 40 | 1.10.15 CH+000 to CH+090(Zone 29)PlanID: 1006307 1 day 2010/7/12 2010/7/12 41 1.10.16 CH+090 to CH 0+285(Zone 29 - Zone 30)PlanID: 1 day 2010/8/5 2010/8/5 1006307 42 1.10.17 CH 2+550 to CH 2+790(Zone 49 - Zone 51)PlanID: 1 dav 2010/5/12 2010/5/12 1006326 43 1.10.18 CH 0+600 to CH 0+800(Zone33 - Zone 35)PlanID: 2010/3/19 2010/3/19 1 day 1006317 44 1.10.19 CH 0+315 to CH 0+600(Zone 31 - Zone 33)PlanID: 2010/7/13 2010/7/13 1 day 1006317 1.10.20 CH 0+800 to CH 1+020(Zone 35 - Zone 37)PlanID: 2010/4/19 45 1 day 2010/4/19 46 1.10.21 CH 1+020 to CH 1+050(Zone 37)PlanID: 1006319 1 day 2010/5/17 2010/5/17 Page 1

Hong Kong Kwong Tai Builders Ltd SS W317 - Construction of a Secondary Boundary Fence From Mai Po to Lok Ma Chau Control Point Date: 16 April 2010 Master Programme 開始時間 識別 WBS Task Name 工期 完成時間 2010年7月 2010年8月 2010年2月 2010年3月 2010年4月 2010年5月 2010年6月 2010年9月 2010年10月 2010年11月 2010年12月 2011年1月 碼 1.10.22 CH 1+050 to CH 1+260(Zone 37 - Zone 39)PlanID: 2010/6/14 2010/6/14 47 1 day 48 1.10.23 CH 1+260 to CH 1+500(Zone 39 - Zone 40)PlanID: 2010/8/26 2010/8/26 1 day 1006321 1.10.24 CH 1+500 to CH 1+650(Zone 41 - Zone 42)PlanID: 2010/7/27 2010/7/27 49 1 dav 1006321 50 1.10.25 CH 1+650 to CH 1+850(Zone 42 - Zone 44)PlanID: 2010/3/19 2010/3/19 1 day 1006324 CH 1+850 to CH 2+070(Zone 44 - Zone 45)PlanID: 2010/4/19 2010/4/19 51 1.10.26 1 day 1006324 52 CH 2+070 to CH 2+150(Zone 45 - Zone 46)PlanID: 2010/5/17 2010/5/17 1.10.27 1 day 1006324 53 1.10.28 CH 2+150 to CH 2+310(Zone 46 - Zone 47)PlanID: 2010/6/14 2010/6/14 1 day 1006325 54 1.10.29 CH 2+310 to CH 2+550(Zone 47 - Zone 49)PlanID: 2010/7/13 2010/7/13 1 day 1006325 55 Anticipated issued date of excavation permit (XP Permit) 2010/4/19 2010/10/4 1.11 169 days 56 1.11.1 CH0+285 to CH 0+315(Zone 30 - Zone 31) 2010/10/4 2010/10/4 1 day 57 1.11.2 CH 3+270 to 3+300(Zone 54) 2010/9/30 2010/9/30 1 day 2010/10/4 2010/10/4 58 | 1.11.3 CH 0+285 to CH 0+315(Zone 30 - Zone 31) 1 day 59 1.11.4 CH 3+270 to CH 3+300(Zone 54) 2010/10/4 2010/10/4 1 day 60 1.11.5 CH 0+550 to 0+600(Zone 33) 2010/8/12 2010/8/12 1 day 61 1.11.6 CH 2+790 to CH 2+900(Zone 51) 1 day 2010/8/12 2010/8/12 62 1.11.7 CH 2+900 to 3+030(Zone 51 - Zone 52) 2010/8/12 2010/8/12 1 day 2010/8/29 63 1.11.8 CH 3+030 to CH 3+270(Zone 52 - Zone54) 1 day 2010/8/29 64 1.11.9 CH 0+000 to CH 0+090(Zone 29) 1 day 2010/8/15 2010/8/15 65 1.11.10 CH 0+090 to CH 0+285(Zone 29 - Zone 30) 1 day 2010/9/9 2010/9/9 2010/8/15 2010/8/15 66 1.11.11 CH 0+550 to CH+600(Zone 33) 1 day 2010/8/15 67 1.11.12 CH 2+790 to CH 2+900(Zone 51) 1 day 2010/8/15 1.11.13 CH 2+900 to CH 3+030(Zone 51 - Zone 52) 2010/8/15 2010/8/15 68 1 day 69 1.11.14 CH 3+030 to CH 3+270(Zone 52 - Zone 54) 2010/9/9 2010/9/9 1 day 70 1.11.15 CH+000 to CH+090(Zone 29) 1 day 2010/8/12 2010/8/12 2010/9/5 2010/9/5 71 | 1.11.16 CH+090 to CH 0+285(Zone 29 - Zone 30) 1 day 72 **1.11.17** CH 2+550 to CH 2+790(Zone 49 - Zone 51) 1 day 2010/6/12 2010/6/12 73 1.11.18 CH 0+600 to CH 0+800(Zone33 - Zone 35) 1 day 2010/4/19 2010/4/19 74 1.11.19 CH 0+315 to CH 0+600(Zone 31 - Zone 33) 1 day 2010/8/13 2010/8/13 75 1.11.20 CH 0+800 to CH 1+020(Zone 35 - Zone 37) 2010/5/20 2010/5/20 1 day 76 1.11.21 CH 1+020 to CH 1+050(Zone 37) 1 day 2010/6/17 2010/6/17 77 1.11.22 CH 1+050 to CH 1+260(Zone 37 - Zone 39) 1 day 2010/7/15 2010/7/15 78 1.11.23 CH 1+260 to CH 1+500(Zone 39 - Zone 40) 1 day 2010/9/26 2010/9/26 79 1.11.24 CH 1+500 to CH 1+650(Zone 41 - Zone 42) 1 day 2010/8/27 2010/8/27 2010/4/19 2010/4/19 80 1.11.25 CH 1+650 to CH 1+850(Zone 42 - Zone 44) 1 day 81 1.11.26 CH 1+850 to CH 2+070(Zone 44 - Zone 45) 1 day 2010/5/20 2010/5/20 82 1.11.27 CH 2+070 to CH 2+150(Zone 45 - Zone 46) 1 day 2010/6/17 2010/6/17 83 1.11.28 CH 2+150 to CH 2+310(Zone 46 - Zone 47) 2010/7/15 2010/7/15 1 day 84 1.11.29 CH 2+310 to CH 2+550(Zone 47 - Zone 49) 2010/8/13 2010/8/13 1 day 85 1.12 Submission 140 days 2010/2/1 2010/6/20 Submission of Computer and mobile phone 86 1.12.1 60 days 2010/2/1 2010/4/1 87 1.12.2 Submission of Subcontractor Management Plan 2010/2/8 2010/3/7 28 days 88 1.12.3 Submission of EM&A works schedule 28 days 2010/2/18 2010/3/17 89 1.12.4 Submission of Landscape Plan 30 days 2010/2/25 2010/3/26 90 1.12.5 Submission of Baseline Monitoring Report 2010/3/1 2010/3/30 30 days 1.12.6 91 submission of Site Management plan for trip ticket 30 days 2010/3/15 2010/4/13 92 1.12.7 submission of formwork & temporary work design 30 days 2010/3/15 2010/4/13 93 1.12.8 2010/4/12 2010/5/11 submission of welding procedure 30 days 94 1.12.9 submission of welder certificate 30 days 2010/4/12 2010/5/11 95 1.12.10 Submission of fencing shop drawing 28 days 2010/4/12 2010/5/9 96 1.12.11 28 days 2010/4/12 2010/5/9 Submission of gate shop drawing Page 2

Hong Kong Kwong Tai Builders Ltd SS W317 - Construction of a Secondary Boundary Fence From Mai Po to Lok Ma Chau Control Point Date: 16 April 2010 Master Programme 開始時間 識別 WBS Task Name 工期 完成時間 2010年8月 2010年2月 2010年4月 2010年5月 2010年6月 2010年7月 2010年9月 2010年10月 2010年11月 2010年12月 2011年1月 碼 1.12.12 2010/4/12 2010/5/9 97 Submission of method statement for footing at Pak Hok 28 days Chau 98 1.12.13 Submission of GBP 2010/5/24 2010/6/20 28 days 99 1.13 Checking existing underground utilities and submit report 28 days 2010/3/15 2010/4/11 100 1.14 2010/3/15 Site clearance prior to work 60 days 2010/1/15 190 days 2010/4/20 2010/10/26 101 1.15 **Footing construction** 2010/10/1 2010/10/24 102 1.15.1 工期: 20 days 24 days CH0+285 to CH 0+315(Zone 30 - Zone 31) 2010/10/5 103 1.15.1.1 20 days 2010/10/24 104 1.15.1.2 CH 3+270 to 3+300(Zone 54) 2010/10/1 2010/10/20 20 days 105 1.15.1.3 CH 0+285 to CH 0+315(Zone 30 - Zone 31) 20 days 2010/10/5 2010/10/24 106 1.15.1.4 CH 3+270 to CH 3+300(Zone 54) 20 days 2010/10/5 2010/10/24 107 **1.15.2** 2010/8/13 2010/10/4 工期: 25 days 53 days 108 1.15.2.1 CH 0+550 to 0+600(Zone 33) 25 days 2010/8/13 2010/9/6 CH 2+790 to CH 2+900(Zone 51) 2010/8/13 2010/9/6 109 1.15.2.2 25 days 110 1.15.2.3 CH 2+900 to 3+030(Zone 51 - Zone 52) 25 days 2010/8/13 2010/9/6 111 1.15.2.4 CH 3+030 to CH 3+270(Zone 52 - Zone54) 25 days 2010/8/30 2010/9/23 112 1.15.2.5 CH 0+000 to CH 0+090(Zone 29) 25 days 2010/8/16 2010/9/9 2010/10/4 113 1.15.2.6 CH 0+090 to CH 0+285(Zone 29 - Zone 30) 25 days 2010/9/10 114 1.15.2.7 CH 0+550 to CH+600(Zone 33) 25 days 2010/8/16 2010/9/9 115 1.15.2.8 CH 2+790 to CH 2+900(Zone 51) 25 days 2010/8/16 2010/9/9 116 1.15.2.9 CH 2+900 to CH 3+030(Zone 51 - Zone 52) 2010/9/9 25 days 2010/8/16 117 1.15.2.10 CH 3+030 to CH 3+270(Zone 52 - Zone 54) 25 days 2010/9/10 2010/10/4 118 **1.15.3** 2010/6/13 2010/10/4 工期: 29 days 114 days 119 1.15.3.1 CH+000 to CH+090(Zone 29) 2010/8/13 2010/9/10 29 days 120 1.15.3.2 CH+090 to CH 0+285(Zone 29 - Zone 30) 29 days 2010/9/6 2010/10/4 121 1.15.3.3 CH 2+550 to CH 2+790(Zone 49 - Zone 51) 2010/6/13 2010/7/11 29 days 工期: 30 days 2010/4/20 2010/10/26 122 **1.15.4** 190 days 123 1.15.4.1 CH 0+600 to CH 0+800(Zone33 - Zone 35) 30 days 2010/4/20 2010/5/19 124 1.15.4.2 CH 0+315 to CH 0+600(Zone 31 - Zone 33) 2010/8/14 2010/9/12 30 days CH 0+800 to CH 1+020(Zone 35 - Zone 37) 125 1.15.4.3 30 days 2010/5/21 2010/6/19 126 1.15.4.4 CH 1+020 to CH 1+050(Zone 37) 2010/6/18 2010/7/17 30 days 127 1.15.4.5 CH 1+050 to CH 1+260(Zone 37 - Zone 39) 2010/7/16 2010/8/14 30 days CH 1+260 to CH 1+500(Zone 39 - Zone 40) 2010/9/27 128 1.15.4.6 30 days 2010/10/26 129 1.15.4.7 CH 1+500 to CH 1+650(Zone 41 - Zone 42) 2010/8/28 30 days 2010/9/26 130 1.15.4.8 CH 1+650 to CH 1+850(Zone 42 - Zone 44) 2010/4/20 2010/5/19 30 days 131 | 1.15.4.9 CH 1+850 to CH 2+070(Zone 44 - Zone 45) 30 days 2010/5/21 2010/6/19 132 1.15.4.10 CH 2+070 to CH 2+150(Zone 45 - Zone 46) 2010/6/18 2010/7/17 30 days 133 1.15.4.11 CH 2+150 to CH 2+310(Zone 46 - Zone 47) 2010/7/16 2010/8/14 30 days 134 1.15.4.12 CH 2+310 to CH 2+550(Zone 47 - Zone 49) 30 days 2010/8/14 2010/9/12 135 **1.16** Structural post and Fencing construction 339 days 2010/5/27 2011/4/30 136 1.16.1 CH0+285 to CH 0+315(Zone 30 - Zone 31) 14 days 2011/3/16 2011/3/29 137 1.16.2 CH 3+270 to 3+300(Zone 54) 14 davs 2010/11/7 2010/11/20 138 1.16.3 CH 0+285 to CH 0+315(Zone 30 - Zone 31) 14 days 2011/3/16 2011/3/29 139 1.16.4 CH 3+270 to CH 3+300(Zone 54) 14 days 2011/3/16 2011/3/29 140 | 1.16.5 CH 0+550 to 0+600(Zone 33) 21 days 2010/9/19 2010/10/9 141 1.16.6 CH 3+790 to CH 3+900(Zone 51) 21 days 2010/9/19 2010/10/9 142 1.16.7 CH 3+900 to 3+030(Zone 51 - Zone 52) 2010/9/19 2010/10/9 21 days 143 1.16.8 CH 3+030 to CH 3+270(Zone 52 - Zone54) 21 days 2010/10/6 2010/10/26 144 1.16.9 CH 0+000 to CH 0+090(Zone 29) 2010/9/22 2010/10/12 21 days 145 1.16.10 CH 0+090 to CH 0+285(Zone 29 - Zone 30) 2010/10/17 21 days 2010/11/6 146 1.16.11 CH 0+550 to CH+600(Zone 33) 21 days 2010/9/22 2010/10/12 147 1.16.12 CH 3+790 to CH 3+900(Zone 51) 21 days 2010/9/22 2010/10/12 148 1.16.13 2010/10/12 CH 3+900 to CH 3+030(Zone 51 - Zone 52) 21 days 2010/9/22 149 1.16.14 CH 3+030 to CH 3+270(Zone 52 - Zone 54) 21 days 2010/10/17 2010/11/6 150 1.16.15 2010/9/19 2010/10/16 CH+000 to CH+090(Zone 29) 28 days 151 1.16.16 CH+090 to CH 0+285(Zone 29 - Zone 30) 28 days 2010/10/13 2010/11/9 Page 3

Hong Kong Kwong Tai Builders Ltd	
----------------------------------	--

## SS W317 - Construction of a Secondary Boundary Fence From Mai Po to Lok Ma Chau Control Point Master Programme

																		Da	ate:	16		Revil 20	
		2010	年9.	月		201	0年	10月		20	10年	11)	月	20	010	年12	2月		201	1年	1月		2
2/	9	/ 5/9	2/	9/	6/	/1	0/1	7/1	4/1	1/1	/1	4/1	1/1	8/1	/1	2/1	9/1	6/1	2/1	9/1	6/	3/	0/
	1							V		7													
								Ť															
	-																						
	-																						
	-																						
	-							V															
	-		Ť					•															
	-																						
	-			_																			
	-			7																			:
	-																						
	- 1																						

識別	WBS	Task Name	工期	開始時間	完成時間	2010年2月	2010年3月	2010年4月	2010年5月	2010年6月	2010年7月	2010年8月	2010年9月	2010年10月	2010年11月	2010年12月	2011年1月
碼						4/ 1/ 7/2 4/ 1/	8/ 7/3 4/ 1/	8/ 4/4 1/ 8/ 5/	2/5 9/5 6/ 3/	/ 0/ 6/6 3/ 0/	7/ 4/7 1/ 8/ 5	/ 1/8 8/8 5/ 2/	9/ 5/9 2/ 9/	6/ /1 0/1 7/1 4	/1 1/1 /1 4/1 1/1	8/1 /1 2/1 9/1 6	5/1 2/1 9/1 6/ 3/
199	1.20.4	E&M work for Pak Hok Chau check point	18 days	2010/10/19	2010/11/5												
200	1.20.4.1	E&M installation work for Pak Hok Chau Check	15 days	2010/10/19	2010/11/2												
		point															
201	1.20.4.2	T&C for Pak Hok Chau check point	3 days	2010/11/3	2010/11/5												
202	1.20.5	Electrical Installation for No.24 Metal gate	10 days	2010/10/15	2010/10/24												
203	1.21	Construction of Pak Hok Chau Check Point	34 days	2010/9/15	2010/10/18												
204	1.21.1	Excavation	5 days	2010/9/15	2010/9/19												
205	1.21.2	Footing	14 days	2010/9/20	2010/10/3												
206	1.21.3	Install GBP	15 days	2010/10/4	2010/10/18												
207	1.22	Roadworks	225 days	2010/9/22	2011/5/4									-		_	<u> </u>
208	1.22.1	reinstatement road surface	55 days	2010/9/22	2010/11/15									:			
209	1.22.2	re-surfacing	50 days	2011/3/16	2011/5/4	1											
210	1.23	Site clearance	28 days	2011/4/11	2011/5/8												
211	1.24	Handover	1 day	2011/4/11	2011/4/11	7											

APPENDIX J ENVIRONMENTAL MONITORING SCHEDULE S

#### Contract No. SS W317 Impact Noise Monitoring for Construction of a Secondary Boundary Fence from Mai Po to Lok Ma Chau Control Point Noise Monitoring Schedule for October 2010

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
					1-Oct	2-Oct
3-Oct	4-Oct	5-Oct	6-Oct	7-Oct	8-Oct	9-Oct
			Noise			
			110150			
10-Oct	11-Oct	12-Oct	13-Oct	14-Oct	15-Oct	16-Oct
					Noise	
					1,0150	
17.0	10.0	10.0	• • •		••	22.0
17-Oct	18-Oct	19-Oct	20-Oct	21-Oct	22-Oct	23-Oct
		Noise				
24.0.4	25.0.4	26.0.4	27.0	20.0.4	20.0.4	20.0.4
24-Oct	25-Oct	26-Oct	27-Oct	28-Oct	29-Oct	30-Oct
				Noise		

#### **Noise Monitoring Station**

VH01 - Village House at Mai Po VH03 - Village House at Mai Po

# Contract No. SS W317 Impact Noise Monitoring for Construction of a Secondary Boundary Fence from Mai Po to Lok Ma Chau Control Point Tentative Noise Monitoring Schedule for November 2010

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
	1-Nov	2-Nov	3-Nov	4-Nov	5-Nov	6-Nov
		Noise				
		110150				
7-Nov	8-Nov	9-Nov	10-Nov	11-Nov	12-Nov	13-Nov
7-1404	0-11UV	<i>9</i> -110 <i>V</i>	10-1107	11-1107	12-1107	13-1101
		Noise				
14-Nov	15-Nov	16-Nov	17-Nov	18-Nov	19-Nov	20-Nov
				Noise		
21-Nov	22-Nov	23-Nov	24-Nov	25-Nov	26-Nov	27-Nov
21 1(0)	22 1101	25 1107	211101	23 1101	20 1107	27 1107
			Noise			
28-Nov	29-Nov	30-Nov				

The schedule may be changed due to unforeseen circumstances (adverse weather, etc)

#### **Noise Monitoring Station**

VH01 - Village House at Mai Po

VH03 - Village House at Mai Po