



Carlyle International Limited

**Infrastructural Works for Cyberport
Development at Telegraph Bay
(EP No. EP-040/1999/C)**

**Monthly EM&A Report
(21 July 2002 - 20 August 2002)
(Rev. 0)**

August 2002

Checked By	
Approved By	
	(Project Director)

REMARKS:

The information supplied and contained within this report is, to the best of our knowledge, correct at the time of printing.

MEMCL accepts no responsibility for changes made to this report by third parties.

**MAUNSELL ENVIRONMENTAL
MANAGEMENT CONSULTANTS LTD**
Room 1213-1219, Grand Central Plaza, Tower 2
138 Shatin Rural Committee Road, Shatin, NT, Hong Kong
Tel: (852) 2893 1551 Fax: (852) 2891 0305
Email: mem@maunsell.com.hk

Maunsell



Atkins China Ltd
15th Floor Miramar Tower
132 Nathan Road
Tsim Sha Tsui
Kowloon Hong Kong

Telephone (852) 2972 1000
Fax (852) 2890 6343

acl@atkins-china.com.hk
www.atkins.com.hk
www.atkinglobal.com

To: Anna Chung, MEMCL	From: Bill Douglas
Fax: 2891 0305	Pages: 1
Phone:	Date: 08 September 2002
Re:	Email: bill@magneticfox.com

Urgent For Review Please Comment Please Reply Please Recycle

Message:

**Infrastructural Works for Cyberport Development at Telegraph Bay
Environmental Permit EP 040/1999/C
32nd Monthly EM&A Report**

There are no comments on the above captioned report.

Bill Douglas
IEC

cc. ACL - Tammy Chan (for file)
ACL - Mr C K Chan

TABLE OF CONTENTS

	Page
EXECUTIVE SUMMARY	1
1. INTRODUCTION	1
Background	1
Project Organization	1
Construction Programme	3
2. ENVIRONMENTAL MONITORING	5
AIR QUALITY	5
Monitoring Requirements	5
Monitoring Equipment	5
Data Management	5
Monitoring Frequency and Schedule	6
Monitoring Locations.....	6
Monitoring Procedures and Calibration Details.....	6
Results and Observations	9
NOISE.....	10
Monitoring Requirements	10
Monitoring Equipment.....	10
Data Management	11
Monitoring Parameters, Frequencies and Schedule	11
Monitoring During Restricted Hours	11
Monitoring Locations.....	12
Monitoring Procedures and Calibration Details.....	12
Results and Observations	13
WATER QUALITY	14
3. ENVIRONMENTAL AUDIT	15
Status of Environmental Licensing and Permitting	15
Site Environmental Audit.....	19
Review of Environmental Monitoring and Audit Procedures.....	19
Assessment of Environmental Monitoring Results.....	19
Summary of Non-compliance of the Environmental Quality Performance Limit	20
Review for the Reasons of Non-compliance (Exceedances)	20
Implementation Status of Environmental Mitigation Measures	21
Implementation Status of Event Action Plans	22
Implementation Status of Environmental Complaint Handling Procedures	22
Summary of Complaints	22
4. FUTURE KEY ISSUES	24
Construction Programme for the Coming Months.....	24
Key Issues for the Coming Month	24
Monitoring Schedule for the Coming Months	25
5. CONCLUSIONS AND RECOMMENDATIONS.....	26
Conclusions.....	26
Recommendations.....	26

LIST OF TABLES, FIGURES AND APPENDICES

TABLES:

Table 1.1	Contact Information of Key Personnel
Table 1.2	Construction Activities and Their Corresponding Environmental Mitigation Measures
Table 2.1	TSP Monitoring Equipment
Table 2.2	Frequency of TSP Monitoring
Table 2.3	Locations of the Air Quality Monitoring Stations
Table 2.4	Summary of TEOM Calibration Activities
Table 2.5	Summary of 1-hour TSP Impact Monitoring Results
Table 2.6	Summary of 24-hour TSP Impact Monitoring Results
Table 2.7	Noise Monitoring Equipment
Table 2.8	Frequency and Parameters of Noise Monitoring
Table 2.9	Locations of the Noise Monitoring Stations
Table 2.10	Summary of Corrected Impact Noise Levels During Non-Restricted Hours
Table 2.11	Summary of Corrected Impact Noise Levels During Restricted Hours
Table 3.1	Summary of environmental licensing and permit status
Table 3.2	Summary of Non-compliance (Exceedances) of the Environmental Quality Performance Limit for EP-040/1999/C
Table 3.3	Summary of Complaints for EP-040/1999/C
Table 3.4	Summary of Prosecutions/Summons

FIGURES:

1.1a	Infrastructural Works for Cyberport Development at Telegraph Bay - Construction Site Area (Contract A)
1.1b	Location of Concrete Batching Plant
1.2a	Description and Detail Locations of the Sensitive Receivers for Air Quality
1.2b	Description and Detail Locations of the Sensitive Receivers for Noise
1.2c	Description and Detail Locations of the Sensitive Receivers for Water Quality
2.1	Locations of Air Quality Monitoring Stations
2.2a	Graphical Presentation of 1-Hour TSP Monitoring for Locations A1 and A2
2.2b	Graphical Presentation of 1-Hour TSP Monitoring for Locations A3 and A4
2.3a	Graphical Presentation of 24-Hour TSP Monitoring for Locations A1 and A2
2.3b	Graphical Presentation of 24-Hour TSP Monitoring for Locations A3 and A4
2.4	Locations of Construction Noise Monitoring Stations
2.5	Graphical Presentation of Noise Monitoring Results for Location NSR1, NSR2, NSR3
2.6	Locations of Sewage Outfall Water Quality Monitoring Stations

APPENDICES:

A1	Project Organization Chart
A2	Schematic Diagram for Data Management
B1	Action and Limit Levels for Air Quality Monitoring
B2	Action and Limit Levels for Noise Monitoring
C1	Calibration Certificates for the HVS and TEOM
C2	Calibration Certificates for the Sound Level Meters
D	Monitoring Schedule for July 2002 and August 2002
E	1-hour TSP Monitoring Results
F	24-hour TSP Monitoring Results
G	Noise Monitoring Results
H	Site Audit Summary
I	Interim Notification of Environmental Quality Limit Exceedances
J	Update Summary of the EMIS
K1	Event Action Plan for Air Quality
K2	Event Action Plan for Construction Noise
L1	Summary of Previous Complaint Details
L2	Cumulative Statistics of Complaints
L3	Summary of Previous Prosecution Details
L4	Cumulative Statistics of Prosecution
M	Construction Program
N	Monitoring Schedule from September to November 2002

EXECUTIVE SUMMARY

This is the 32nd monthly Environmental Monitoring and Audit (EM&A) report prepared by Maunsell Environmental Management Consultants Limited (MEMCL), the designated Environmental Team (ET), for the "Infrastructural Works for Cyberport Development at Telegraph Bay (excluding advance works)", hereafter referred to as "the Project". This report presents the impact monitoring results and audit works for Cyberport Development at Telegraph Bay (excluding advance works) between 21 July 2002 and 20 August 2002.

Environmental monitoring was performed regularly and the results checked and reviewed. Site audit was conducted once per week. The implementation of the environmental mitigation measures, Event/Action Plan and environmental complaint handling procedures were also checked.

Environmental Monitoring Works

All monitoring at designated stations were performed according to the prescribed frequency and schedule.

Air Quality

1-hour TSP Monitoring

All measured 1-hour TSP concentrations were in compliance with the Action and Limit Levels in the reporting period.

24-hour TSP Monitoring

All measured 24-hour TSP concentrations were in compliance with the Action and Limit Levels in the reporting period.

Noise

In the reporting month, all the noise monitoring results during normal working hours and restricted hours complied with the Limit Level.

Water

The sewage outfall baseline monitoring for wet season was conducted on 6-8 June 2002 and 15-17 June 2002 respectively. The baseline report would be submitted in separate.

Environmental Licensing and Permitting

In the reporting period, no new environmental permits/licenses were issued to the Project.

Environmental Site Audit

Site inspections were carried out weekly by the Environmental Team to audit the site conditions against the conditions in the environmental permit, Environmental Impact Assessment, and environmental legislation.

In the reporting period, a total of 5 site audits were conducted. The environmental mitigation measures were generally implemented. Recommendations were made to Contractors upon any observations. The situations were mostly improved.

Environmental Complaints, Non-compliance and Prosecutions

No complaint was received in this reporting month. Up to date, a total of 15 complaints were received since the commencement of the Contract.

One prosecution related to environmental issues was received since the commencement of the Contract.

Future Key Issues

Surface runoff from construction site would be increased as the frequency of rainfall increase in the wet season. Proper operation and maintenance of wastewater treatment facilities should be enhanced. Besides, sufficient water spraying on unpaved areas and main haul roads should be maintained on dry sunny day.

Rock breaking was conducted at R3 site. As this site was close to the secondary schools and residential area in Wah Fu Estate, noise and dust impact would be a major concern. Contractor was reminded to provide noise barriers and conduct the activities in compliance with the approved PME list.

The operation of Concrete Batching Plant ceased after 24 July 2002 and was now demolished. Therefore, the condition of 3.18 of the Environmental Permit EP-040/1999/C was not applied. The real-time monitoring would be ceased on 1 September 2002. The environmental monitoring and audit programme would be in accordance with the approved "M&A Manual for Infrastructural Works for the Proposed Development at Telegraph Bay (EM&A Manual 032)". The monitoring programme would commence on 2 September 2002.