

EM&A Environmental Inspection Record

Contract No.: GE/2005/45

LANDSLIDE PREVENTIVE WORKS AT PO SHAN, MID-LEVELS

DESIGN AND CONSTRUCTION (NATURAL TERRAIN RISK MITIGATION WORKS)

AECOM

Site Inspection Summary

Inspection Information

Date:	1 September 2009
Time:	15:00
Inspection No.:	074

Non-compliance

Nil

Observations

Follow Up Observation

1. Leaves and debris inside the u-channel at Row R had been cleared. (Closed)

New Observation

Nil.

Remarks

Nil

EM&A Environmental Inspection Record

Contract No.: GE/2005/45

LANDSLIDE PREVENTIVE WORKS AT PO SHAN, MID-LEVELS

DESIGN AND CONSTRUCTION (NATURAL TERRAIN RISK MITIGATION WORKS)



Site Inspection Summary

Inspection Information

Date:	8 September 2009
Time:	15:00
Inspection No.:	075

Non-compliance

Nil

Observations

<p><u>Follow Up Observation</u></p> <p>Nil.</p> <p><u>New Observation</u></p> <p>Nil.</p>
--

Remarks

Nil

EM&A Environmental Inspection Record

Contract No.: GE/2005/45

LANDSLIDE PREVENTIVE WORKS AT PO SHAN, MID-LEVELS

DESIGN AND CONSTRUCTION (NATURAL TERRAIN RISK MITIGATION WORKS)

AECOM

Site Inspection Summary

Inspection Information

Date:	15 September 2009
Time:	15:00
Inspection No.:	076

Non-compliance

Nil

Observations

Follow Up Observation

Nil.

New Observation

Nil.

Remarks

Typhoon Signal No. 1 was hoisted. No construction work was carried out on site.

EM&A Environmental Inspection Record

Contract No.: GE/2005/45

LANDSLIDE PREVENTIVE WORKS AT PO SHAN, MID-LEVELS

DESIGN AND CONSTRUCTION (NATURAL TERRAIN RISK MITIGATION WORKS)

AECOM

Site Inspection Summary

Inspection Information

Date:	22 September 2009
Time:	15:00
Inspection No.:	077

Non-compliance

Nil

Observations

Follow Up Observation

Nil.

New Observation

Nil.

Remarks

No construction work was carried out on site.
Hydroseeding and site clearance were taking place.