China Resources Construction Company Limited MAUNSELL AECOM

Contract No. SS M333

Reprovisioning of Diamond Hill Crematorium

Monthly EM&A Report for October 2006

November 2006

	Name	Signature
Reviewed & Checked:	Kenneth Lau	Ladle
Approved: (ET Leader)	Y T Tang	Carllotin


Version:	Revision 0	Date:	14 November 200	6
The information contained in this report	is, to the best of our knowledge,	correct at the time	e of printing. The interpretati	on and

recommendations in the report are based on our experience, using reasonable professional skill and judgment, and based upon the information that was available to us. These interpretations and recommendations are not necessarily relevant to any aspect outside the restricted requirements of our brief. This report has been prepared for the sole and specific use of our client and MEMCL accepts no responsibility for its use by others.

This report is copyright and may not be reproduced in whole or in part without prior written permission.

MAUNSELL ENVIRONMENTAL MANAGEMENT CONSULTANTS LTD

11/F, Grand Central Plaza, Tower 2, 138 Shatin Rural Committee Road, Shatin, NT, Hong Kong Tel: (852) 2893 1551 Fax: (852) 2891 0305 Email: mem@maunsell.aecom.com



Consulting

安瓿工程顧問有限公司

香港灣仔 皇后大道東183號 合和中心47線

電 法, (852),2911 2293 閩文海真* (852),2805 5028

笔字系统: hyderihk@hyderconsulting.com 题 证: www.hyderconsulting.com Hyder Consulting Limited 47/F Hopewell Centre,

183 Queen's Road East, Wan Chai, Hong Kong

Tel: (852) 2911 2233 Fax: (852) 2805 5028

1148-06/E06-5787

Email: hyder.hk@hyderconsulting.com Website: www.hyderconsulting.com

Hyder Consulting Limited is incorporated in Hong Kong with limited liability. COI Number 126012

Your

Ref:

Our .

Ref:

13 November 2006

Architectural Services Department Queensway Government Offices 66 Queensway Hong Kong

For attention of: Mr Michael Mak

Dear Michael

Reprovisioning of Diamond Hill Crematorium

Monthly EM&A Report for October 2006 (Revision 0)

We refer to the email of 9 November 2006 with the enclosure of the draft monthly EM&A Report for October 2006 (Revision 0) and subsequent email of 13 November from MEMCL.

We have no further comment and hereby verified the captioned EM&A report.

Should you have any queries, please do not hesitate to contact the undersigned on 2911 2719 or Adi Lee on 2911 2729

Yours sincerely

Coleman Ng Independent Environmental Checker HYDER CONSULTING LIMITED

cc MEMCL - Mr. Y. T. Tang/Mr. Kenneth Lau CRCCL - Mr. Eric To

(Fax: 2891 0305) (Fax: 2827 2921)

CNAL



TABLE OF CONTENTS

EXE	CUTIVE SUMMARYIII
1.	INTRODUCTION1
	Background1
	Scope of Report1
	Project Organisation1
	Environmental Status in the Reporting Month1
	Summary of EM&A Requirements1
2.	AIR QUALITY2
	Monitoring Requirements2
	Monitoring Equipment2
	Monitoring Parameters, Frequency and Duration2
	Monitoring Locations2
	Monitoring Methodology
	Results and Observations4
3.	NOISE5
	Monitoring Requirements5
	Monitoring Equipment
	Monitoring Parameters, Frequency and Duration5
	Monitoring Locations5
	Monitoring Methodology5
	Results and Observations6
4.	ENVIRONMENTAL SITE INSPECTION7
	Site Inspections7
	Review of Environmental Monitoring Procedures7
	Advice on Waste Management Status7
	Status Environmental Licences and Permits7
	Implementation Status of Environmental Mitigation Measures7
	Summary of Exceedances of Environmental Quality Performance Limit
	Summary of Environmental Complaints, Notifications of Summons and Successful Prosecutions
	Prosecutions8
5.	FUTURE KEY ISSUES9
	Key Issues and Recommendations for Coming Month9 Environmental Monitoring and Audit Schedule for the Coming Months9
6.	CONCLUSIONS AND RECOMMENDATIONS10
	Conclusions10

EXECUTIVE SUMMARY

Introduction

Maunsell Environmental Management Consultants Limited (MEMCL) is the designated Environmental Team (ET) for "Reprovisioning of Diamond Hill Crematorium" (The Project). This is the twenty-second monthly Environmental Monitoring and Audit (EM&A) report prepared by MEMCL for the Project. The EM&A programme for the Project commenced on 29 October 2004. This report documents the findings of EM&A Works conducted in the month of October 2006 (1 to 31 October 2006).

As informed by the Contractor, construction activities in the reporting period were:

- Steel fixing, erect formwork and concreting for footings, internal and external walls (including fair-face concrete), columns and 1/F slabs, circular staircase and planters on 1/F level;
- Installation of M & E services at Cremator Plant Room and other plant rooms at L/G and G/F level;
- Internal Plastering and Finishing Works at L/G & G/F plant rooms and lobby area;
- Installation of external stone wall;
- Roof finishes above Cremator Plant Room area:
- Last Manhole Connection:
- Construction of EVA road;
- · Installation of cremator plant components inside cremator plant room and roof area; and
- · Testing of cremator at Cremator Plant Room.

A summary of monitoring and audit activities conducted in the reporting period is listed below:

1-hour TSP monitoring	15 sessions
24-hour TSP monitoring	5 sessions
Daytime noise monitoring	5 sessions
Environmental site inspection	5 sessions

Breaches of Action and Limit Levels

Air Quality

All 1-hour and 24-hour TSP monitoring results recorded in the month complied with the Action and Limit Levels.

Construction Noise

All noise monitoring results recorded in the month complied with the Action and Limit Levels.

Implementation Status of Environmental Mitigation Measures

In general, the Contractor satisfactorily implemented all the required mitigation measures and was reasonably responsive to the ET's recommendations on any discrepancy observed during the weekly environmental site inspection.

Environmental Complaints, Notification of Summons and Successful Prosecutions

No environmental complaint, notification of summons or successful prosecution was received or made against this Project in the month.

Reporting Changes

No reporting change was required in the month.

Reprovisioning of Diamond Hill Crematorium Monthly EM&A Report for October 2006 (Revision 0)
Future Key Issues
 Key issues to be considered in the coming month include: Generation of dust from activities on-site; Noise impact from operating equipment and machinery on-site; Generation of site surface runoffs and wastewater from activities on-site; Storage and disposal of general refuse and construction waste from activities on-site; Management of chemicals and avoidance of oil spillage.
摘要
簡介
茂盛環境管理顧問有限公司乃「重置鑽石山火葬場」[下稱(工程項目)]的指定環境小組。本冊是茂盛爲工程項目製作的第二十二份每月環境監察及審核報告。工程項目的環境監察及審核由二零零四年十月廿九日開始、本報告記錄了二零零六年十月份(二零零六年十月一日至十月三十一日)所進行的環境監察及審核工作。
根據承建商的資料,本月有以下的建築活動:
 鋼根固定,支架構成及混凝土澆灌 安裝電機結構於焚化爐機房的焚化爐上及地面機房 地面內牆噴上砂漿及修整 安裝於焚化爐機房的焚化爐上 完成焚化爐機房的天花設備 僅剩下水道的接駁 進行地底油缸的管道裝置於緊急行車輪通路 緊急行車輪通路工程 安裝焚化爐組件於焚化爐機房內和機房天花 測試焚化爐於焚化爐機房 本月有下列幾項的監察及審核活動: 小時總懸浮粒子監察 15次
廿四小時總懸浮粒子監察 5次 日間噪音監察 5次 環境巡查 5次
違反監察標準
空氣質素 本月所有一小時及二十四小時總懸浮粒子監測結果皆符合行動水平和極限水平。
建築噪音 本月所有噪音監測結果皆符合行動水平和極限水平。
環境影響緩和措施
承建商大致上完成所需的緩和措施,同時已對環境小組在每週的環境巡查中的建議作出合理的回應及跟進。
有關環境的投訴,傳票及檢控 本月沒有收到有關環境的投訴,傳票及檢控。
報告 修訂 本月並沒有修訂報告。

Reprovisioning of Diamond Hill Crematorium Monthly EM&A Report for October 2006 (Revision 0)

預計要注意的事項

下月要注意事項包括:

- 工程活動所產生的塵埃
- 操作中儀器及機器產生的噪音影響
- 工程活動所產生的污水
- 普通廢物與建築廢物的暫貯及棄置
- 化學品的管理及防止意外漏油

1. INTRODUCTION

Background

1.1 Maunsell Environmental Management Consultants Limited (MEMCL) (hereinafter called the "ET") was appointed by China Resources Construction Company Limited (CRC) (hereinafter called the "Contractor") to undertake Environmental Monitoring and Audit for "Reprovisioning of Diamond Hill Crematorium" (hereinafter called the "Project"). Under the requirements of Section 4 of Environmental Permit EP-179/2004, EM&A programme as set out in the approved EM&A Manual is required to be implemented. In accordance with the approved EM&A Manual, environmental monitoring of air quality and noise and environmental site inspections are required for the Project.

Scope of Report

1.2 The EM&A programme for the Project commenced on 29 October 2004. This report presents a summary of the environmental monitoring and audit works, list of activities, and mitigation measures for the Project in October 2006 (from 1 to 31 October 2006).

Project Organisation

1.3 The organisation of the environmental management team is shown in Figure 1.1. Key personnel contacts are presented in Appendix A.

Environmental Status in the Reporting Month

- 1.4 The construction programme of the Project is provided in Appendix B. In the month, the following activities took place for the construction of the Project:
 - Steel fixing, erect formwork and concreting for footings, internal and external walls (including fairface concrete), columns and 1/F slabs, circular staircase and planters on 1/F level;
 - Installation of M & E services at Cremator Plant Room and other plant rooms at L/G and G/F level;
 - Internal Plastering and Finishing Works at L/G & G/F plant rooms and lobby area;
 - Installation of external stone wall:
 - Roof finishes above Cremator Plant Room area:
 - Last Manhole Connection;
 - · Construction of EVA road;
 - Construction of U/F services pipeworks at EVA;
 - Installation of cremator plant components inside cremator plant room and roof area; and
 - Testing of cremator at Cremator Plant Room.
- 1.5 Layout plan of the Project work site is provided in Figure 1.2.

Summary of EM&A Requirements

- 1.6 The description and detailed locations of sensitive receivers and monitoring stations for air quality and noise are shown in Figures 2.1 and 3.1 respectively and relevant sections of this Report.
- 1.7 The EM&A programme require environmental monitoring for air quality and noise and environmental site inspections for air quality, noise, water quality, landscape and visual, and waste management. The EM&A requirements for each parameter described in the following sections include:
 - All monitoring parameters
 - Action and Limit Levels for all environmental parameters
 - Event and Action Plans
 - Environmental mitigation measures, as recommended in the project final EIA report
 - Environmental requirements in contract documents.
- 1.8 The advice on the implementation status of environmental protection and pollution control/mitigation measures is summarised in Appendix J of the Report.

2. AIR QUALITY

Monitoring Requirements

- 2.1 1-hour TSP and 24-hour TSP levels at two designated monitoring stations were monitored in the month in accordance with the EM&A Manual. Appendix C shows the established Action and Limit Levels for the environmental monitoring works.
- 2.2 The monitoring schedule for the month is shown in Appendix D. Air quality monitoring stations for 24-hour TSP and 1-hour TSP measurements are shown in Figure 2.1.

Monitoring Equipment

2.3 Portable dust meter was used to carry out 1-hour TSP monitoring. High volume sampler (HVS - Model GMWS-2310 Accu-Vol) completed with the appropriate sampling inlets was installed for 24-hour TSP sampling. The HVS meet all the requirements as specified in the approved EM&A Manual. Table 2.1 summarised the equipment that were used in the dust-monitoring programme.

Table 2.1 Air Quality Monitoring Equipment

Equipment	Model
Dust Meter (for 1-hour TSP measurement	Laser Dust Monitor - Model LD-1/LD-3
HVS (for 24-hour TSP measurement)	GMWS 2310 Accy-Vol system
Calibration Kit (for HVS)	GMW 25

Monitoring Parameters, Frequency and Duration

2.4 Table 2.2 summarised the monitoring parameters, frequency and duration of impact air quality monitoring.

Table 2.2 Air Quality Monitoring Parameters, Frequency and Duration

Parameter	Duration	Frequency
1-hour TSP	1 hour	3 times every six days
24-hour TSP	24 hours	Once every six days

Monitoring Locations

2.5 In accordance with the EM&A Manual, two air quality monitoring stations, as shown in Figure 2.1 were selected for 24-hour TSP and 1-hour TSP sampling. Table 2.3 describes the location of the air quality monitoring stations.

Table 2.3 Locations of Air Quality Monitoring Stations

Monitoring Station	Identity / Description	Level
ASR8	Po Leung Kuk Grandmont Primary School	Roof top level of 7 storey building
ASR17	Staff Quarter for Diamond Hill Crematorium	Roof top level of 1 storey building

Monitoring Methodology

1-hour TSP Monitoring

Monitoring Procedure

- 2.6 The measuring procedures of 1-hour TSP by a portable dust meter are in accordance with the Manufacturer's Instruction Manual as follows:
 - Set POWER to "ON", push BATTERY button, make sure that the meter's indicator is in the range with a red line and allow the instrument to stand for about 3 minutes (Then, the air sampling inlet has been capped).

- · Push the knob at MEASURE position.
- Push "O-ADJ" button. (Then meter's indication is 0).
- Push the knob at SENSI ADJ position and set the meter's indication to S value described on the Test Report using the trimmer for SENSI ADJ.
- Pull out the knob and return it to MEASURE position.
- Push "START" button.

Maintenance and Calibration

- The 1-hour TSP dust meters are verified at 1-year intervals throughout all stages of the impact air quality monitoring.
- Calibration details for the dust meters are provided in Appendix E.

24-hour TSP Monitoring

Installation

- 2.7 The HVSs were installed in the vicinity of the air sensitive receivers. The following criteria were considered in the installation of the HVSs:
 - A horizontal platform with appropriate support to secure the samplers against gusty wind was provided.
 - The distance between the HVS and any obstacles, such as buildings, was at least twice the height that the obstacle protrudes above the HVS.
 - A minimum of 2 meters separation from walls, parapets and penthouses was provided for rooftop sampler.
 - No furnace or incinerator flues were nearby.
 - Airflow around the sampler was unrestricted.
 - Permission was obtained to set up the sampler and to obtain access to the monitoring stations.
 - A secure supply of electricity was obtained to operate the sampler.

Preparation of Filter papers

- Glass fibre filters, G810 were labelled and sufficient filters that were clean and without pinholes were selected.
- All filters were equilibrated in the conditioning environment for 24 hours before weighing. The
 conditioning environment temperature was around 25 °C and not variable by more than ±3 °C;
 the relative humidity (RH) was < 50% and not variable by more than ±5%. A convenient working
 RH was 40%.
- ALS Technichem (HK) Pty Ltd. is a HOKLAS accredited laboratory which has comprehensive quality assurance and quality control programmes.

Monitoring Procedures

- The power supply was checked to ensure the HVSs work properly.
- The filter holder and the area surrounding the filter were cleaned.
- The filter holder was removed by loosening the four bolts and a new filter, with stamped number upward, on a supporting screen was aligned carefully.
- The filter was properly aligned on the screen so that the gasket formed an airtight seal on the outer edges of the filter.
- The swing bolts were fastened to hold the filter holder down to the frame. The pressure applied should be sufficient to avoid air leakage at the edges.
- Then the shelter lid was closed and secured with the aluminum strip.
- The HVSs were warmed-up for about 5 minutes to establish run-temperature conditions.
- A new flowrate record sheet was set into the flow recorder.
- The flow rate of the HVS was checked and adjusted at around 1.1 m³/min. The range was between 0.6-1.7 m³/min.

- The programmable timer was set for a sampling period of 24 hrs ± 1 hr, and the starting time, weather condition and the filter number were recorded.
- The initial elapsed time was recorded.
- At the end of sampling, the sampled filter was removed carefully and folded in half length so that only surfaces with collected particulate matter were in contact.
- It was then be placed in a clean plastic envelope and sealed.
- All monitoring information was recorded on a standard data sheet.
- Filters were sent to ALS Technichem (HK) Pty Ltd. for analysis.

Maintenance and Calibration

- The HVSs and their accessories were maintained in good working condition, such as replacing motor brushes routinely and checking electrical wiring to ensure a continuous power supply.
- HVSs are calibrated at bi-monthly intervals using GMW-25 Calibration Kit throughout all stages
 of the impact air quality monitoring.
- Calibration details for the HVSs are provided in Appendix E.

Results and Observations

2.8 Dust monitoring was conducted for both 1-hour TSP and 24-hour TSP at all designated monitoring stations in the month. Air quality monitoring results and graphical presentations are provided in Appendix F.

1-hour TSP Monitoring

2.9 All measured 1-hour TSP levels complied with the Action and Limit Levels in the month. A summary of 1-hour TSP monitoring results is presented in Table 2.4.

Table 2.4 Summary of Impact 1-hour TSP Monitoring Results

Monitoring	1-hour TSP (μg/m³)	Action	Limit	No	o. of
Station		Level	Level	Exce	edance
	Range	(μg/m³)	(μg/m³)	Action	Limit
ASR8	77.1 – 110.5	408.1	500.0	Nil	Nil
ASR17	80.4 118.0	408.4	500.0	Nil	Nil

24-hour TSP Monitoring

2.10 All measured 24-hour TSP levels complied with the Action and Limit Levels in the month. A summary of 24-hour TSP monitoring results is presented in Table 2.5.

Table 2.5 Summary of Impact 24-hour TSP Monitoring Results

Monitoring Station	24-hour TSP (μg/m³)	Action Level	Limit Level		o. of edance
	Range	(μg/m³)	(μg/m³)	Action	Limit
ASR8	42.0 - 109.1	195.0	260.0	Nil	Nil
ASR17	39.8 – 128.8	174.1	260.0	Nil	Nil

3. NOISE

Monitoring Requirements

- 3.1 Noise levels at three designated monitoring stations were monitored in the month in accordance with the EM&A Manual. Appendix C shows the established Action and Limit Levels for the environmental monitoring works.
- 3.2 The monitoring schedule for the month is shown in Appendix D. Noise monitoring stations are shown in Figure 3.1.

Monitoring Equipment

3.3 Integrating Sound Level Meter was employed for noise monitoring. They were Type 1 sound level meters capable of giving a continuous readout of the noise level readings including equivalent continuous sound pressure level (L_{eq}) and percentile sound pressure level (L_x). They comply with International Electrotechnical Commission Publications 651:1979 (Type 1) and 804:1985 (Type 1). Portable electronic wind speed indicator capable of measuring wind speed in m/s was employed to check the wind speed. Table 3.1 details the noise monitoring equipment used.

Table 3.1 Noise Monitoring Equipment

Equipment	Model
Integrating Sound Level Meter	Rion NL-18/31
Calibrator	Rion NC-73

Monitoring Parameters, Frequency and Duration

3.4 Table 3.2 summarised the monitoring parameters, period, frequency and duration of impact noise monitoring.

Table 3.2 Noise Monitoring Parameters, Frequency and Duration

Time Period	Parameters	Duration (min)	Frequency
Daytime (0700 to 1900 on normal weekdays)	Leq	30	Once per week

Monitoring Locations

3.5 In accordance with the EM&A Manual, three noise monitoring stations, as shown in Figure 3.1 were selected for noise monitoring. Table 3.3 describes the location of this monitoring station.

Table 3.3 Locations of Noise Monitoring Stations

Monitoring Station	Identity / Description	Level
SR3	International Christian Quality Music Secondary and Primary School	Roof top level of 7 storey building
SR4	Po Leung Kuk Grandmont Primary School	Roof top level of 7 storey building
SR6	Staff Quarter for Diamond Hill Crematorium	Roof top level of 1 storey building

Monitoring Methodology

Monitoring Procedures

- The Sound Level Meter was set on a tripod at a height of 1.2 m above the ground.
- Façade measurements were made at all three monitoring locations.
- The battery condition was checked to ensure the correct functioning of the meter.

- Parameters such as frequency weighting, the time weighting and the measurement time were set as follows:
 - frequency weighting: A
 - time weighting: Fast
 - time measurement: L_{eq}(30 minutes) during non-restricted hours i.e. between 07:00 and 19:00 on normal weekdays
- Prior to and after each noise measurement, the meter was calibrated using a Calibrator for 94 dB at 1000 Hz. If the difference in the calibration level before and after measurement was more than 1 dB(A), the measurement would be considered invalid and repeat of noise measurement would be required after re-calibration or repair of the equipment.
- The wind speed was frequently checked with a portable wind meter.
- During the monitoring period, the L_{eq}, L₁₀ and L₉₀ were recorded. In addition, site conditions and noise sources were recorded on a standard record sheet.
- Noise measurement was paused during periods of high intrusive noise (e.g. dog barking, helicopter noise) if possible. Observations were recorded when intrusive noise was unavoidable.
- Noise monitoring was cancelled in the presence of fog, rain, wind with a steady speed exceeding 5 m/s, or wind with gusts exceeding 10 m/s.

Maintenance and Calibration

- The microphone head of the sound level meter and calibrator is cleaned with soft cloth at quarterly intervals.
- The meter and calibrator are sent to the supplier or HOKLAS laboratory to check and calibrate at yearly intervals.
- Calibration details for the sound level meter and calibrator are provided in Appendix E.

Results and Observations

- 3.6 Noise monitoring was conducted at all designated monitoring stations as scheduled in the month. Noise monitoring results and graphical presentations are provided in Appendix G.
- 3.7 All measured noise levels complied with the Action and Limit Levels in the month. A summary of noise monitoring results is presented in Table 3.4.

Table 3.4 Summary of Impact Noise Monitoring Results during 07:00 – 19:00 on Normal Weekdays

Monitoring Station	Measured Noise Level, dB(A) L _{eg (30 min)}	Calculated Construction Noise Level, dB(A)	Limit Level	No. of Exceedance	
	Average and Range	Average and Range		Action*	Limit
SR3	64.7 (63.2 – 66.2)	# (# - #)	70/65##	Nil	Nil
SR4	64.6 (62.8 – 66.8)	, (# - #)	70/65##	Nil	Nil
SR6	63.6 (63.5 – 63.7)	([#] - [#])	75	Nil	Nil

^{* -} Action Level is triggered by receipt of a noise complaint

^{# -} Measured noise level is less than the baseline noise level

^{## -} reduce to 70dB(A) for schools and 65dB(A) during school examination periods

4. ENVIRONMENTAL SITE INSPECTION

Site Inspections

4.1 Site inspection was carried out on a weekly basis to monitor the timely implementation of proper environmental pollution control and mitigation measures for the Project. In the month, four site inspections were carried out in the month. The summary of weekly environmental site inspections observations and environmental site inspection checklists are attached in Appendix H.

Review of Environmental Monitoring Procedures

4.2 The monitoring works conducted by the Environmental Team were inspected regularly. Observations have been recorded for the monitoring works as follows:

Air Quality Monitoring

- The monitoring team recorded the observations around the monitoring stations within and outside of the construction site.
- The monitoring team recorded the temperature and general weather condition on the monitoring day.

Noise Monitoring

- The monitoring team recorded the observations around the monitoring stations, which might affect the results.
- Major noise sources were identified and recorded.

Advice on Waste Management Status

4.3 The actual quantities of inert C&D materials and non-inert C&D wastes generated by activities of the Project in the month are provided in Table 4.1. Trip ticket system was implemented for all offsite waste disposal.

Table 4.1 Summary of Waste Disposal in the Month

Type of Waste Material		Disposed Quantity	Destination	
Inert C&D mater	ials	106 m ³	Kai Tak Public Fill Barging Point	
Non-inert C&D	Metals	Nil	Not Applicable	
waste	Paper/cardboard packaging	Nil	Not Applicable	
	Plastics	Nil	Not Applicable	
	Chemical waste	Nil	Not Applicable	
	Others, e.g. general refuse	113 m ³	SENT Landfill	

Status Environmental Licences and Permits

4.4 The status of all permits/licences obtained/in-use in the month is summarised in Appendix I.

Implementation Status of Environmental Mitigation Measures

- 4.5 An updated summary of the Environmental Mitigation Implementation Schedule (EMIS) is presented in Appendix J.
- 4.6 During the weekly site inspection conducted by the Environmental Team in the month, the following observations and recommendations were made.

Water Quality

 The Contractor was reminded to provide and maintain the washing wheel facilities in regular basis.

- The Contractor was reminded to provide sandbags for surface runoff.
- Stagnant water in various sites working area on ground floor, first floor, the basement, outside
 the sub-contractor's office and the site exit. The Contractor was reminded to remove the
 stagnant water to prevent mosquitoes breeding and treated in the sedimentation tank before
 discharging.
- . The Contractor was reminded to clean up the mud and soil deposited within the site area.

Air Quality

- The Contractor was reminded to remove the cement bags
- Uncovered stockpile was observed on the G/F and the 1/F. The Contractor was reminded to
 provide a covers or water spraying or placed in sheltered areas for the excavator materials/
 stockpiles in order to avoid dust generation.
- The Contractor was reminded to maintain and provide water spraying for the entire road surface in order to avoid dust generation.

Noise

 No particular observations and recommendations were made during the weekly site inspections in the month.

Waste or Chemical Management

- · The Contractor was reminded to maintain or remove the construction wastes in regular basis.
- Chemical drums were observed on the G/F and 1/F. The Contractor was reminded to store in the sorting area that provided the demarcation and signposts.

Landscape and Visual

 No particular observations and recommendations were made during the weekly site inspections in the month.

Others

 No particular observations and recommendations were made during the weekly site inspections in the month.

Summary of Exceedances of Environmental Quality Performance Limit

- 4.7 The Event and Action Plans for air quality and noise are presented in Appendix K.
- 4.8 No exceedance of Action and Limit Levels for 1-hour and 24-hour TSP and noise was recorded in the month.

Summary of Environmental Complaints, Notifications of Summons and Successful Prosecutions

4.9 Figure 4.1 presents the environmental complaint flow diagram of the Project and Table 4.2 presents the statistics of complaints, notification of summons and successful prosecution since the commencement of the Project.

Table 4.2 Summary of Environmental Complaints And Prosecutions

Complaints logged		Summons served		Successful Prosecution	
October 2006	Cumulative	October 2006	Cumulative	October 2006	Cumulative
0	0	0	0	0	0

4.10 No environmental complaint, notification of summons and prosecution was received or made against the Project in the month.

5. FUTURE KEY ISSUES

Key Issues and Recommendations for Coming Month

- 5.1 Key issues to be considered in the coming month include:
 - Generation of dust from activities on-site;
 - Noise impact from operating equipment and machinery on-site;
 - Generation of site surface runoffs and wastewater from activities on-site;
 - · Storage and disposal of general refuse and construction waste from activities on-site; and
 - Management of chemicals and avoidance of oil spillage.
- 5.2 Recommendations for the coming month include:
 - Provide water spray to haul roads and unpaved areas;
 - · Provide regular maintenance to wheel wash facilities on-site;
 - · Cover the stockpiles on-site entirely;
 - Store all chemicals on site in the chemical storage area;
 - · Ensure general refuse are sorted, recycled and disposed properly; and
 - Ensure construction wastes are disposed off-site properly and regularly.

Environmental Monitoring and Audit Schedule for the Coming Months

5.3 The tentative schedules for environmental monitoring and audit for the next three months are provided in Appendix D.

6. CONCLUSIONS AND RECOMMENDATIONS


Conclusions

- 6.1 Environmental monitoring and audit was performed in October 2006. All monitoring and audit results in the month were checked and reviewed.
- 6.2 All 1-hour and 24-hour TSP monitoring results recorded in the month complied with the Action and Limit Levels.
- 6.3 All noise monitoring results recorded in the month complied with the Action and Limit Levels.
- In general, the Contractor satisfactorily implemented all the required mitigation measure and was reasonably responsive to the ET's recommendations on any discrepancy observed during the weekly environmental site inspection.
- 6.5 No environmental complaint, notification summons or successful prosecution was received or made against this Project in the month.


Recommendations

6.6 According to results of weekly environmental site inspections performed in the month and the construction programme for the coming month, recommendations for air quality, construction noise, water quality and waste and chemical management are detailed in Sections 5.1 and 5.2.

FIGURES



PROJECT ORGANIZATION FOR ENVIRONMENTAL MANAGEMENT



LEGEND:

— DIRECT COMMUNICATION


---LIAISON

MAUNSELL	AECOM
Maunseli Environme	ntal

Management Consultants Ltd

CONTRACT NO: SS M333 -	REPROVISIONING OF
DIAMOND HILL CRE	MATORIUM
PROJECT ORGANI ENVIRONMENTAL	

T	SCALE	N.T.S.	DATE	2005	
ţ	CHECK	FSYY	DRAWN	LLM	ic
ı	J08 но.		DRAW1NG	No.	REV
ſl		S07904		1.1	_




MAUNSELL AECOM


Maunsell Environmental
Management Consultants Ltd


CONTRACT NO: SS M333 - REPROVISIONING OF DIAMOND HILL CREMATORIUM

LAYOUT OF WORK SITE


SCALE	N.T.S.	DATE	2005	
CHECK	FSYY	DRAWN	LLMC	
JOB NO.		ORAW1NG	No.	REV
İ	507904		1.2	-








APPENDIX A
KEY CONTACTS OF ENVIRONMENTAL
PERSONNEL




Appendix A Key Contacts of Environmental Personnel

Party	Name	Telephone No.	Fax No.
Environmental Protection De	epartment		
SEPO	Mr. David Cox	2835 1106	2591 0558
EPO	Ms. Marlene Ho	2835 1186	2591 0558
EPO (ECD)	Mr. Charles Wu	2117 7540	2756 8588
Architect			
Architectural Services Departr	nent		
Project Architect	Mr. Michael Mak	2867 3802	2524 8194
Independent Environmental	Checker		
Hyder Consulting Limited			
IEC	Mr. Coleman Ng	2911 2233	2805 5028
Assistant to IEC	Mr. Adi Lee	2911 2233	2805 5028
Contractor			
China Resources Construction	n Company Limited		
Project Manager	Mr. Eric To	2828 1515	2827 2921
Environmental Team			
Maunsell Environmental Mana	agement Consultants L	imited	
ET Leader	Mr. Y.T. Tang	2893 1551	2891 0305
Audit Team Leader	Mr. Kenneth Lau	2893 1551	2891 0305
Monitoring Team Leader	Mr. Eddie Yang	2893 1551	2891 0305


APPENDIX B CONSTRUCTION PROGRAMME





		Site Possession (Section 1) Mobilization Initial Survey			1 days 7 days 16 days	30/10/2004 30/10/2004	- 127 - 1	Orio Elliphia	4 Parkar						
1		Initial Survey			16 days	2/11/2004	,	2011							
Part	1111	(come leaves)			40 days		-				 		-		_
Fig. 1	1111	Sic Office 311			MINATA	19/11/2004					-				
Second S	7 1 1	The Cust Manual			S damage	70027119	8/13/1004		. .		•				
1 1 1 1 1 1 1 1 1 1		Sahmis Waste Management	la l		Vely 1	\$010004	\$1117004	777						-	
17 17 17 17 17 17 17 17	7	Annual of WA4P			day	10/12/2004	10/12/2004	-			_			_	
State Stat		Hoanling Frection			173 days	2/11/2004	23/4/2005								
The column	Т	Area B (Type 3)			S3 days	2117004	_	ZIII 阿斯拉斯 Sulta		_					
	Ť	Section 1 (Type 1 & 3)			28 days	25/2/2005									
	亻	Section (Remarks Ty	() adı		36 days	21/1/2005	23/4/2005	-							
Comparison	1	CSD for U/G Utilities Diven	sion		104 days	11/11/2004	22/2/2005					 -			
The color of the	1	Revised UAC PA'D Draw	vings from ASD		48 days	16/12/2004	12/2005	(6/12 PTRESIDENT 1/2							
Check Horse State 1979 1970 1	T	Revised UAC FS PINERA	ork Drawings from ASE		92 days	19/11/2004	1807.005	19月 (20) (30) (30)							
Checker Chec	Τ	Revised street lighting l	layout from ASD		97 days	11/11/2004	15/2/2005	11/11 (国							
Concident Part 1 st 200700	Т	Incoming/Outing Cable	Ducis' Drawpit Routin	50	22 days	15/12/2004	5/1/2005	Sin igg					-		
The column Leg 1712000 171200	7	Approval of Incorping C	Cable Ducts / Draw Pit	Routing by CLP	L day	20/13/2004	2011/2004	20012 20112				·			
State Stat	Г	Submission of CSD (Pr.	climanary)		l day	7/12/2004	1/12/2004	71.2 11.2	·					-	
1 kg 200 cm 1 kg 200 cm 200 c	Т	Submission of CSD (Fit	nal)		15 days	21/1/2005	4/2/2005	2m (1)							
Electrication Colorest Colo	Т	Approval of CSD			l day	22222005	22/2/2005	220 220							_
Column	-	Road Diversion & U/C Utili.	lies Diversion		Odkys	P00Z/01/6Z	29/10/2004	0161							
Color Colo	7	Area A . Hammer Head (De	(प्राच्य)		0 days	29/10/2004	29/10/2004	0101							
Early Control Contro	23	Area C			0 days	29/10/2004	29/10/2004	00161							
Figure State 1572000 1572000 1572000 1572000 157200 1572000 1572000 1572000 1572000 1572000 1572000 157200 1572000 1572000 157200	77	Area C1 (Near Section 1)			0 days	29/10/2004	29/10/2004	0166							
Page	Г	Sile Clearance			ekup 68	15/12/2004	13/3/2005								
Process 2-004 1712/200 1717/200 17	▎	Relocate Fine Brick (FE	HO		2 days	15/12/2004	16/12/2004	21/2017							
1 And 1 An	z,	Denolish Exig Planen	' Payettent		2 dnys	1712/2004	18/12/2004	1812							
1		Temp. Road Paving			l day	18/12/2004	18/12/2004	18/18/12							
Column C		Hoading Erection			19 days	20/12/200 4	7/1/2005	11/2			<u>-</u>				
Control Cont	\Box	Speak Up Existing Paw	cment		15 days	24/12/2004	711/2005								
Column C	-	Lay Water Pipes (Dive	rsion)		10 days	11/1/2005	20/1/2005	100 (100)	 		-				
Control Cont		Lay Soil & Waste Pipe:			62 days	11/1/2005	13/3/2005	11 11 (THE PROPERTY IN STREET							
State Stat	Γ	Area C2 (Near New Tx Roo	(E)		62 days	6/12/2004	\$12/20015								
15 to 10	Г	Demolish Planters & R.	epaved		3 days	6/12/2004	8/12/2004	6412 11402							
Compared	35	Hoanling Erection			19 days	20/12/2004	\$002/11/	Total September 1997							_
Act	П	Break Up Existing Pay.	ement		15 days	24/12/2004	7/1/2005	24119-000-00							
Control Cont		Drawpits & Cuble Due.	2)		20 days	\$11/2005	24/1/2005								
16 Backfill 18 days 13 days 14 days 14 days 14 days 15 days 14 days 14 days 15 days 14 days 14 days 15 days 14 days 15 days		Backfilling & Tarmic (Area Cl & C2)		12 days	2507/2005	502/2/5	25/1 35/2				4	~~		
15 to be		Arca B			98 days	31/12/2004	7472005					•			
A	T	Break Up Exig Road P.	avlag		15 days	31/12/2004	14/1/2005		•						
Surface Denoise Surface De	_1	Demolish Extg Turaci	& Backfill	***************************************	LB days	3/1/2005	20/1/2005	744000							
A Safety Channel 15 days 1572005 15720	\neg	Construct Lamp Pole)	collise		S days	187778	SOUTH STATE	872 11 250			- -				
Service Pipework	7	Construct Cable Duct	Drawent		37 000	SOUTH	CONTAC								
Service Tipework	7	Charles New Walley	e, surrect Countries		24/1/2	13,0005	NUCLUS CONTRACTOR	CALCARIAN OF						•	
Section 13 days 27/17205 19/17205	┰	Construct & Lay 1MG	Services Pinewnet		- A claws	5006/1/5	19777005	Frank							
Manholest St days 21/12005 19/12005 19/12005 24/12005 19/12005 24/12005	Т	Draw Pils & Cabl	k Ducis		33 days	\$1/3005	62/20(15								
1	Т	Diningse Pipe & 1	Manholes		58 days	21/1/2005	19/3/20015	100-100-100-100-100-100-100-100-100-100							
1 days 221/2003 243/2005	1	Watermalas (F.S.)			30 days	1572/2005	16/3/2005	(9+-Digital 4-1)							/15-11
A child Duct	Г	Backfill & Concrete Ri	osd Slab		31 days	2007/02	24/3/2005		· · · · · · · · · · · · · · · · · · ·						
New Ta Room	Г	Handover of Draw Pri	& Cable Duct		1 day	3002/2/1	77272005	7							
New Ta Room		Cable Laying by CLP			4 days	21072005	24/2/2005	यहासि।							
12 12 12 12 12 12 12 12		Cable Termination in	New Ta Room		2 days	\$002/6/5	6772005	709 70							
Confice Section 1 day 74/2003 14/2003 14/2003 14/2004 15/2004		Diversion of PCCW C	ગુવર		25 days	1/2/2005	25/2/2005	252							
cmp 1x Room (V.O.) 92 Large 67 A Large (V.O.) 1 STATE (V.O.) 1 STA	·- F	Set Up Traffic Control	Point for Section 1		- day	74/2005	7M/2005	5/4 A-12					·	- .	
TERM TERMINENT TOTAL TO	┰	B.S. Instellation in New To	mp Tx Room (V.O.)	H 4 1 4 1 4 1	92 (12)5	P002/21/7	5002/2/3			-				 	
在		Coalinm & Issue Desi	in Delais of Lx Room	& Main Switch Koom	Åen 1	INDANICI	NA CARDA	1 (5/18) 15/12		-					
	Planned by ; ? Programme re Dated :24 June	Mr. Eric To f.: DRCA/P/S1/001 Rev.R1	在以果在存款		١.		1.00 1.00型在55	D NAMES	1		外部压力 以 被数据	Electric constant (1)		. <	Þ
			W 12120	-											




20	1	Constant of the last	007/17/1				<u> </u>	A STATE OF THE PARTY OF THE PAR	S Part
	20 days	11/8/2006	15/12/2006						- 100 COLUMN
14	_	11/5/2/106	20/10/2006					· II.A IRITIAN	Olygon o
		21/10/2006	2071 1/2006						10-20-01
	System Se	3871072000	3011/2000						
Laninet, vaning 10p & Reception Council	Γ	10/11/2006	15/12/2006						3 =
		8/11/2/006	38/11/2006	,	·-·				18/13 國 28/11
45	436 days	1/2/2005	30/11/1006		.				
		1.972005	31/5/2006		8	WINDS NO FEBRUARY AND ADDRESS OF THE PERSON NAMED IN COLUMN TWO PERSONS AND ADDRESS OF THE PERSON NAMED IN COLUMN TWO PERSON NAMED IN COLUMN TRANSPORT NAMED IN COLUMN TWO PERSON NAMED IN COLUMN TRANSPORT NAMED IN COLUMN TWO PERSON NAMED			
Submit & Approval of Fabrication Procedure		15/1/2006	30/4/2006	-		151	111 SALES ESTE 30/4		
	137 days	15/1/2006	31/5/2006				A SECTION AND A	The second second	2112
A (1)	27 days	INSTANTO	31/10/2000						1 0101
		Instanta	15/10/2006					TOP LEASE WILLIAM	
	31 days 2	21/10/2006	20/13/2005				Co. St. Canada Ready Land Co.		
Shop Drawing Submission and Approval of Roller Shutter 24		1/10/2005	31/5/2006		01/1	Harriston Statement Statement of the Sta	The William Assessment		
		15/2/2006	30/9/2006	-				I A DEFERMENT	
Steel & Metal Work (Mirorliancous) 26	269 JASE	700006	30/11/2006			272	in Street telegolisation as the	自由限制的股份	STATE SOLI
	149 days	1507,7006	10/12/2006			-			}
	L	15/10/2006	25/10/2006			4 ***			- 01/54 国本
	201	2007017	200000		<u> </u>				
		0/07/11//	53/10/2000					-	
		26/10/2006	571172006						
	}	1/11/2006	30/11/2006						1100 BE 1111
	L	1/12/2006	10/12/2006						1/13-10
	1	\$112/2/06	10/12/2006						5
		Caracaga	ADMIN TO LAND						
	, out.	TO STATE OF THE PERSON NAMED IN	20000101					C - 1 15 15 15 15 15 15 15 15 15 15 15 15 1	O THE PARTY OF THE
	١	13/1/2000	10/12/200		-			ATPLICATION STORES	HERE BANKED
		25/6/2(05	10/17/2006			1 1			
		25/8/2005	31/10/2000		 	1 1 1	1 1 1		 > -
	310 days	25/8/2005	30/6/2006		TAN INTER	1. 数据设计的160% (A) 150% (A) 150		2006	
	31 days	9002/11	31.772005					100 PM	
Window frame and such	76 days	1/8/2006	15/10/2006			e trus			2-1510
E	3) dmr	1/10/2006	31/10/2006	-					31/10
	76 1004	SWC St.	SOCKOLY					Section 1985	5
	1	NOT THE PARTY OF T	200000						
,	46 days	1/8/2006	3/9/2006					The second	·
	78 days	15/1/2006	30/9/2006		:-			5年间 指缀的数据	瓮
	91 days	1,9/2006	30/11/2006						HAVE THE SOUTH
*	17 days	15/00/00	30,000,005		-		· ·		10.00
	200	2000000	2007/70			J	1 1	Late of Late and Control	
	462 days	25/8/2005	3071 1/2006				-	-	_
proval	279 days	26/8/2005	31/5/2006		126-L	읩.			
Preparation of Mock Up Sample 12	22 days	1/3/2006	30/6/2006			<u> </u>		Egg.	_
	14 days	17/2006	14772006				#1 	画 中	
	Stab G	150020051	15/9/2006					の「西野の町」か	
7	61 days	1/10/2006	10/11/2016					1	HERA SEURIN 30/11
, p	472 days	2K/R/D/KIS	10/12/2006			-	-	ì	
Part Daniel College Co	100	36/8/005	Annopolis		→ (1) (1) (1) (1) (1) (1) (1) (1) (1) (1)	Control of the contro	THE MANAGEMENT OF SECTION	-	<u>.</u> .
	277 (18)3	202/2013	J. D. Z.C.K.D.		(C) (C)	A NOW OF THE SECOND SEC			• • • •
Preparation of Mock Up Sample	22 days	1/3/2006	30/6/2006	-			400 S (\$100 S (000)		•
	14 days	1772006	14/7/2006						
Manufacturing & Delivery	63 days	1577,2006	15/9/2006	d %			-	120	
	61 days	1002006	30/11/2006					1001	Wildling Lown
	10 40.00	3MMCR1	30000 1001						10
	r cays	01077711	C007/21/21				1		7117
	244 days	1/4/2000	30/13/2006				1		
proval	122 days	1/1/2006	31,772006				No. of the second secon	110	
ite	15 days	1/8/2006	15/8/2006		•			8/5/15/18/1	
Visual Inspection & Approval	16 days	16/8/2006	31/8/2006		 	-		2 S. L. L. S. L.	-
	61 days	9D0Z/G/1	31/10/2006	-			_	1 1/2 EEEE	TEL-1010
State Control of the		1	isshi	C C C C C C C C C C C C C C C C C C C	F-GENERAL SERVICE	24 24 24 16	:	เดเลสสา	
	+	= -1 !	MX 上期少在数	- Proceedings	9.10 10.45	海型於治 · · · · · · · · · · · · · · · · · · ·	(Commence of)		•
		'							










APPENDIX C ENVIRONMENTAL ACTION AND LIMIT LEVELS



Appendix C Environmental Action and Limit Levels

Action and Limit Levels for 24-hour TSP

Monitoring Station	Action Level (μg/m³)	Limit Level (μg/m³)
ASR8	195.0	260
ASR17	174.1	260

Action and Limit Levels for 1-hour TSP


Monitoring Station	Action Level (μg/m³)	Limit Level (μg/m³)
ASR8	408.1	500
ASR17	408.4	500

Action and Limit Levels (L_{eq}) for Construction Noise

Time Period	Action Level	Limit Le	evel	
		SR3	SR4	SR6
0700 – 1900 hours on normal weekdays	When one documented complaint is received	70/65*	70/65*	75
0700 – 2300 hours on public holidays including Sundays and	from any one of the sensitive receivers	stipulate	to requiremed in future	
1900 - 2300 hours on all days		Constru	ction Noise	Permits
2300 - 0700 on all days				

^{*}reduce to 70dB(A) for schools and 65dB(A) during school examination periods

APPENDIX D
ENVIRONMENTAL MONITORING AND
AUDIT SCHEDULES



Reprovisioning of Diamond Hill Crematorium Tentative Impact Air Quality and Noise Monitoring and Audit Schedule for October 2006

Saturday 07-Oct		14-Oct	24-hour TSP	21-Oct	1-hour TSP Noise	28-Oct				
Eriday 06-Oct		13-Oct		20-Oct	24-hour TSP	27-Oct	1-hour TSP Noise			
Thursday: 05-Oct		12-Oct		19-Oct		26-Oct	24-hour TSP			
Wednesday 04-Oct	1-hour TSP Noise	11-Oct		18-Oct		25-Oct				(adverse weather, etc)
Tuesday S.	24-hour TSP	Site Environmental Audit	1-hour TSP Noise	17-Oct		24-Oct		31-Oct	Site Environmental Audit	eable circumstances (adv
Monday 80 02-Oct		9-Oct	24-hour TSP	Site Environmental Audit	1-hour TSP Noise Site Fovironmental Audit	23-Oct	Site Environmental Audit	30-Oct		ochange due to unforese
Sunday 01-Oct		08-Oct		15-Oct		22-Oct		29-Oct		The schedule is subject to change due to unforeseeable circumstances

Tentative Impact Air Quality and Noise Monitoring and Audit Schedule for November 2006 Reprovisioning of Diamond Hill Crematorium

्र Tuesday
07-Nov
24-hour TSP
14-Nov
1-hour TSP Noise
21-Nov
······
28-Nov

The schedule is subject to change due to unforeseeable circumstances (adverse weather, etc)

Tentative Impact Air Quality and Noise Monitoring and Audit Schedule for December 2006 Reprovisioning of Diamond Hill Crematorium

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday 01-Dec	Saturday 02-Dec
					1-hour TSP Noise	
03-Dec	04-Dec	05-Dec	06-Dec	07-Dec	08-Dec	09-Dec
		24-hour TSP	1-hour TSP Noise			
Site Er	Site Environmental Audit	12 Dec	13-Dec	14-Dec	15.000	16-Dec
	24-hour TSP	1-hour TSP				24-hour TSP
Site	Site Environmental Audit	Noise				
17-Dec	18-Dec	19-Dec	20-Dec	21-Dec	22-Dec	23-Dec
	1-hour TSP Noise			24-hour TSP	1-hour TSP Noise	
24-Dec	25-Dec	26-Dec	27-Dec	28-Dec	29-Dec	30-Dec
		24-hour TSP	1-hour TSP Noise			
Site E	Site Environmental Audit					
31-Dec						


The schedule is subject to change due to unforeseeable circumstances (adverse weather, etc)

Tentative Impact Air Quality and Noise Monitoring and Audit Schedule for January 2007 Reprovisioning of Diamond Hill Crematorium

Sunday	Monday	Tuesday	Wednesda	Thursday 🕆 🧢 🕒	Friday	Saturday
	01-Jan	02-Jan	03-Jan	04-Jan	05-Jan	06-Jan
		24-hour TSP	1-hour TSP Noise			
07-Jan	08-Jan	09-Jan	10-Jan	11-Jan	12-Jan	13-Jan
· .	24-hour TSP	1-hour TSP			24-hour TSP	1-hour TSP
	Site Environmental Audit	Noise				Noise
14-Jan		16-Jan	17-Jan	18-Jan	19-Jan	20-Jan
				24-hour TSP	1-hour TSP	
	Site Environmental Audit		•		Noise	
21-Jan	1 22-Jan	23-Jan	24-Jan	25-Jan	26-Jan	27-Jan
			24-hour TSP	1-hour TSP Noise		
00	Site Environment	-1 00				
Z8-Jan	Z8-Jan	30-Jan	31-ปลา	01-Feb	29-Dec	30-Dec
		24-hour TSP	1-hour TSP			
	Site Environmental Audit					
The edition of alterday	the state of the state of the					

The schedule is subject to change due to unforeseeable circumstances (adverse weather, etc)

APPENDIX E CALIBRATION DETAILS



Station	Po Leung Kuk Gi	randmont Primar	y School (ASR8)	Operator:	Yu	en			
Cal. Date:	01-Aug-06			Next Due Date:	01-0	ct-06	_		
Equipment No.:	A-001-69T			Serial No.	07	16	•		
				Condition					
Temperatu	re, Ta (K)	302	Pressure, I	Pa (mmHg)		757.0			
			Orifice Transfer S	tandard Informatio	on				
Seria	l No:	988	Slope, mc	2.00878		epi, bc	0.0001		
Last Calibra	ation Date:	15-Nov-05		mc x Qstd + bc	= [DH x (Pa/760) x	(298/Ta)] ^{1/2}			
Next Calibra	ation Date:	15-Nov-06			Pa/760) x (298/Ta)]		<u> </u>		
	·	<u>.</u>	0-11111	4 TOD Complex	· · · · · · · · · · · · · · · · · · ·				
			Calibration o	f TSP Sampler	H/V	S Flow Recorder			
Resistance Plate) IICE						
No.	DH (orifice), in. of water	[DH x (Pa/7	60) x (298/Ta)] ^{1/2}	Qstd (m³/min) X - axis	Flow Recorder Reading (CFM)	Continuous Flow Reading IC (CF			
18	14.1		3.72	1.85	52.0	51.55	1		
13	12.5	<u> </u>	3.51	1.74	50.0	49.57	,		
10	9.0		2.97	1.48	42.0	41.64			
7	7.6 2.73 1.36 35.0 34.70 3.2 1.77 0.88 20.0 19.83								
5	3.2		1.77	0.88	20.0	19.83	,		
Slope , mw ≃ Correlation Coe	33.6461 fficient* = pefficient < 0.990,		9914 brate.	Intercept, bw =	-9.8	121			
		_ 	Cat Daint	Coloulation					
from the TSP Fig	eld Calibration Cu	rnye take Ostd =	· · · · · · · · · · · · · · · · · · ·	Calculation					
	sion Equation, the								
Tom the riegres	Sion Equation, an	, , , , , , , , , , , , , , , , , , , ,	ang to						
		mw	x Qstd + bw = IC	x [(Pa/760) x (298/	Ta)] ^{1/2}				
				10					
Therefore, Set Po	oint; IC = (mw x (Qstd + bw) x [(7	60 / Pa) x (Ta / 29)8)]" ² =	,	34.22	-		
Remarks:					·				
				15		•			
	Eddie Ja	mer	Claustine	Edit)		Date: 3/8/2	.006		
QC Reviewer:	Vivia da		Signature:	U-U		Date.			

P:\General\HVS\S07904\ASR8\2006\ASR8_60801.xls

Station	Staff Quarter Fo	r Diamond Hill C	rematorium (ASR17) Operator:	Y t	ien			
Cal. Date:	01-Aug-06		<u> </u>	Next Due Date:	01-C	oct-06			
Equipment No.:	A-001-21T			Serial No.	10	278			
• •				•		·			
			Ambient	Condition	·····				
Temperat	ure, Ta (K)	302	Pressure, F	Pa (mmHg)		757.0			
			Orifice Transfer St	andard Information	on				
Seria	al No:	988	Slope, mc	2.00878		ept, bc	0.00015		
Last Calibr	ation Date:	15-Nov-05	<u> </u>		= [DH x (Pa/760) x				
Next Calib	ration Date:	15-Nov-06		Qstd = {[DH x (Pa/760) x (298/Ta)]	^{1/2} -bc} / mc			
		•							
				f TSP Sampler			····		
			Orfice	Г	HV	S Flow Recorder			
Resistance Plate No.	DH (orifice), in. of water	[DH x (Pa/	760) x (298/Ta)] ^{1/2}	Qstd (m³/min) X - axis	Flow Recorder Reading (CFM)	Continuous Flow Reading IC (CFM			
18	13.1		3.59	1.79	48.0	47.59			
13	12.5		3.51	1.74	47.0	46.60			
10									
7	7.8								
5	3.3		1.80	0.90	25.0	24.78			
Slope , mw = Correlation Coe	ession of Y on X 25.3841 efficient* = pefficient < 0.990	0	.9929 ibrate.	Intercept, bw =	2.3	832			
						• • •			
				Calculation					
	ield Calibration Co								
From the Regres	ssion Equation, th	e "Y" value acco	rding to						
•		mv	v x Qstd + bw = IC >	c [(Pa/760) x (298/	Ta)] ^{1/2}				
				_, , , , , , , , , , , , , , , , , , ,					
Therefore, Set P	oint; IC = (mw x	Qstd + bw) x [(7	760 / Pa) x (Ta / 29	8)] ^{1/2} =		35.69			
			·		<u></u>				
Damaden									
Remarks:									
				0					
OC Boulouser	Eddie J	any	Signature:	> Wor)	Date: 3/8/2	1006		
QC Reviewer: _	()	- () -	orginature		/				
P:\Genera	al\HVS\S07904	NASR17\2006	NASR17_60801.	xls					

Station I	Po Leung Kuk G	randmont Primary	y School (ASR8)	Operator:	Yu	en	
Cal. Date:	28-Sep-06		± ± W	Next Due Date:	28-No	ov-06	•
Equipment No.:	A-001-69T			Serial No.	07	16	
	·		Ambient	Condition			
Tomporotu	ro To (K)	302	Pressure, F			760.0	
Temperatur	ie, ia (N)	302	1 1633016, 1	a (minig)		100.0	
			Orifice Transfer St	andard Informatio	n		
Serial	No:	988	Slope, mc	2.00878	Interce	<u> </u>	0.00015
Last Calibra	tion Date:	15-Nov-05		mc x Qstd + bc	= [DH x (Pa/760) x	(298/Ta)] ^{1/2}	
Next Calibra	tion Date:	15-Nov-06		Qstd = {[DH x (F	Pa/760) x (298/Ta)]	^{1/2} -bc} / mc	
		•	Calibration	f TSP Sampler		<u></u>	
		·	Orfice	, , or campion	HVS	S Flow Recorder	
Resistance Plate No.	DH (orifice), in. of water		60) x (298/Ta)] ^{1/2}	Qstd (m³/min) X - axis	Flow Recorder Reading (CFM)	Continuous Flow Reading IC (CFI	
18	14.0		3.72	1.85	51.0	50.66	
13	12.5		3.51	1.75	50.0	49.67	
10	9.2		3.01	1.50	41.0	40.73	
7	7.4		2.70	1.35	36.0	35.76	
5	3.0		1.72	0.86	22.0	21.85	
By Linear Regres Slope, mw = Correlation Coef *If Correlation Coe	29.9713 fficient* =	0.	9953 brate.	Intercept, bw = _	-4.0	231	·
			Set Point	Calculation		<u></u>	
From the TSP Fie	ald Calibration Co	invo take Octd -		Valoutation .	· <u>-, -</u>		. <u></u>
From the Regress							
		mw	x Qstd + bw = IC	x [(Pa/760) x (298/1	Га)] ^{1/2}		
Therefore, Set Po	oint; IC = (mw x	Qstd + bw) x [(7	60 / Pa) x (Ta / 29	98)] ^{1/2} =		35.17	
Damayler			<u>.</u>				
Remarks:	 	<u>-</u>			·		

P:\General\HVS\S07904\ASR8\2006\ASR8_60928.xls

	Stall Quarter For	Diamond Hill Ci	ematorium (ASR17)	Operator:	Yu	en
Cal. Date:	28-Sep-06			Next Due Date:	28-N	ov-06
Equipment No.:	A-001-21T			Serial No.	102	278
			·			 -
				Condition	<u> </u>	700.0
Temperatu	ıre, Ta (K)	302	Pressure, F	Pa (mmHg)		760.0
·		,	Orifice Transfer St	andard Informatio	on .	
Seria	al No:	988	Slope, mc	2.00878	 _	ept, bc 0.00015
Last Calibr		15-Nov-05		mc x Qstd + bc	= [DH x (Pa/760) x	(298/Ta)] ^{1/2}
Next Calibr	ration Date:	15-Nov-06			Pa/760) x (298/Ta)]	
					·	· · · · · · · · · · · · · · · · · · ·
<u> </u>				f TSP Sampler		
mastar i Diri	<u></u>	(Orfice	Т-	HV	S Flow Recorder
Resistance Plate No.	DH (orifice), in. of water	[DH x (Pa/7	'60) x (298/Ta)] ^{1/2}	Qstd (m³/min) X - axis	Flow Recorder Reading (CFM)	Continuous Flow Recorder Reading IC (CFM) Y-axis
18	13.0		3.58	1.78	49.0	48.67
13	12.5		3.51	1.75	47.0	46.69
10	9.2		3.01	1.50	41.0	40.73
	7.9		2.79	1.39	38.0	37.75
7	1.5	<u> </u>				
5	3.4		1.83	0.91	24.0	23.84
5 By Linear Regro Slope , mw = Correlation Coe	3.4 ession of Y on X 27.9024	0	1.83	0.91		23.84
5 By Linear Regro Slope , mw = Correlation Coe	3.4 ession of Y on X 27.9024 efficient* =	0	1.83 .9978 ibrate.	<u> </u>		
5 By Linear Regressions, mw = Correlation Coe *If Correlation Coe	3.4 ession of Y on X 27.9024 efficient* =	0 check and recal	1.83 .9978 ibrate. Set Point	Intercept, bw =		
5 By Linear Regression of the Correlation Coefficient of the TSP From	3.4 ession of Y on X 27.9024 efficient* = oefficient < 0.990,	0 check and recal	1.83 .9978 ibrate. Set Point 1.30m³/min	Intercept, bw =		
5 By Linear Regression of the Correlation Coefficient of the TSP From	3.4 ession of Y on X 27.9024 efficient* = oefficient < 0.990,	check and recal	1.83 .9978 ibrate. Set Point 1.30m³/min	Intercept, bw =	-1.3	
By Linear Regressions Correlation Correlat	3.4 ession of Y on X 27.9024 efficient* = cefficient < 0.990, ield Calibration Cu	check and recal urve, take Qstd = e "Y" value acco	.9978 ibrate. Set Point 1.30m³/min rding to	Intercept, bw = Calculation x [(Pa/760) x (298/	-1.3	
By Linear Regressions Correlation Correlat	3.4 ession of Y on X 27.9024 efficient* = cefficient < 0.990, ield Calibration Cu	check and recal urve, take Qstd = e "Y" value acco	1.83 .9978 ibrate. Set Point 1.30m³/min rding to y x Qstd + bw = IC	Intercept, bw = Calculation x [(Pa/760) x (298/	-1.3	8838
By Linear Regressions Correlation Correlat	3.4 ession of Y on X 27.9024 efficient* = cefficient < 0.990, ield Calibration Cu	check and recal urve, take Qstd = e "Y" value acco	1.83 .9978 ibrate. Set Point 1.30m³/min rding to y x Qstd + bw = IC	Intercept, bw = Calculation x [(Pa/760) x (298/	-1.3	8838

EQUIPMENT CALIBRATION RECORD

ı ype					<u>JUST MOZ</u>	utor		
	ufacturer/Brand:		•	SIBATA	<u> </u>			
	el No.:			LD-1				
	pment No.:			A.005.0				
Sens	itivity Adjustmen	it Scale Set	ting:	510 CF	PM			
Oper	ator:			Eddie Y	ang (EW	'NY)		
Standa	ard Equipment							
Earde	mont			-441-1				
Venu	oment:		precht & Pa erport (Pui			Na. 6 a - 11		
	el No.:		es 1400AB	Ting Sec	Unuary S	споот		
Seria		Con		0AB2198	00803			
00112		Sen		00C1436		K _o : 12500	,	
Last (Calibration Date*		une 2006				<u></u>	
*Pema	rks: Recommend	dod intonial	for bordue	calibra	tion is 1			
		ned littel val	noi naiuwa	ie calbia	uon is i	yeai		
Calibra	ation Result	· · · · · · · · · · · · · · · · · · ·						
Sensi	itivity Adjustment	Scale Sett	ing (Before	Calibratio	on):	510 CF	PM	
	tivity Adjustment						PM	
					7*		•••	
Hour	Date	Ti	me	Ami	blent	Concentration ¹	Total	Count/
j	(dd-mm-yy)	ļ			dition	(mg/m³)	Count ²	Minute ³
)			Temp	R.H.	Y-axis]	X-axis
<u> </u>				(°C)	(%)			ĺ
1	09-07-06		- 10:00	28.9	88	0.08838	2710	45.17
2	09-07-06	12:00	- 13:00	30.1	82	0.03365 0.05263	1214	20.23
3	09-07-06		- 14:00	30.4	81	1548	25,80	
4	09-07-06		- 15:00	30.3	81	0.05402	2053	34.22
Note:						shnick TEOM®	•	
	2. Total Count							
	3. Count/minut	e was caic	ulated by (I	otal Cour	1060)			
By Linea	ar Regression of	Y or X						
	(K-factor):		0.0018					
Correla	ation coefficient:	•	0.9056					
37.71 01								
validity	of Calibration R	ecord:	9 July 200	7				
Remarks	e•							
Committee	 	·						
ŀ							•	1
		•						
								1
								[
			<u> </u>					
000		.,	~ - ·	,	r de A		10/7/	200/
QC Re	viewer: Eddie	Yang	Signatu	ıre:(//	Date:	14/1/	

MAUNSELL	AECOM:

EQUIPMENT CALIBRATION RECORD

Type:			Laser D		itor		
	facturer/Brand:		SIBATA				
Mode			_LD-3				
	ment No.:		A.005.07	7a			
Sensi	tivity Adjustment	Scale Setting:	557 CP.	М			
Opera	ator:		Eddie Ya	ang (EW	NY)		
Standa	rd Equipment						
Equip	ment:	Rupprecht &	Patashnick	TEOM®			
Venue	9:	Cyberport (Pt	ui Ying Seco	ondary S	chool)		
Model	No.:	Series 1400A	В				
Serial	No:	Control:	140AB2198	99803			
		Sensor:	1200C1436	59803	K₀: 12500		
Last C	Calibration Date*:	: <u>17 June 2006</u>					
*Remar	ks: Recommend	led interval for hardv	vare calibra	tion is 1	year		
Calibra	tion Result						
		Scale Setting (Before Scale Setting (After			557 CP		
Hour	Date	Time	Ami	pient	Concentration	Total	Count/
. ,,	(dd-mm-yy)			dition	(mg/m³)	Count ²	Minute ³
j			Temp	R.H.	Y-axis		X-axis
			(°C)	(%)			
1	18-06-06	09:00 - 10:00		82	0.02370	768	12.80
2	18-06-06	10:00 - 11:00	29.1	82	0.02161	707	11.78
3⋅	18-06-06	12:00 - 13:00	29.5	82	0.02609	822	13.70
4	18-06-06	13:00 - 14:00	29.6	81	0.01991	603	10.05
Note:	2. Total Count	lata was measured t was logged by Lase e was calculated by	r Dust Moni	itor	shnick TEOM®		
3y Linea	r Regression of	YorX			•		
Slope ((K-factor):	0.0019					
	ation coefficient:	0.9281					
Validity	of Calibration R	Record: 18 June	2007				
Remarks	s:					•	
							·
•				CANA	$\overline{}$, , , , , , , , , , , , , , , , , , ,	
QC Rev	viewer: <u>Eddie</u>	Yang Sign	ature:	(W()	Date:	19 Jun	e 2006
			C	•	-		



綜合試驗有限公司 SOLS & MATERIALS ENGINEERING CO., LTD.

G/F., 9/F., 12/F., 13/F. & 20/F., Leader Centre, 37 Wong Chuk Hang Road, Aberdeen, Hong Kong. 香港黃竹坑道37號利達中心地下,9樓,12樓,13樓及20樓 F-mall: smec@clg/lsmec.com Website: www.clg/lsmec.com

Tel: (852) 2873 6860 Fax: (852) 2555 7533



CERTIFICATE OF CALIBRATION

Certificate No.: 06CA0713 01-02 Page 2 Item tested Description: Sound Level Meter (Class I) Microphone Preamp Manufacturer: Rion, Co. Ltd. Rlan, Co., Ltd. Rion, Co. Ltd. Type/Model No.: NL-31 HC-53A NH-21 Serial/Equipment No.: 00320534 102464 03581 Adaptors used: (N.007.02A Item submitted by Client: Maunsell Environmental Management Consultants Ltd. Request No.: Date of request: 12-Jul-2006 Date of test: 13-Jul-2006 Reference equipment used in the calibration Description: Model: Serial No. **Expiry Date:** Traceable to: Multi function sound calibrator B&K 4226 2288444 11-Jan-2007 CIGISMEC Measuring amplifier B&K 2610 2346941 30-Nov-2006 SCM Signal generator D\$ 360 33873 30-Nov-2006 SCM Signal generator DS 360 61227 12-Jul-2007 SCM Ambient conditions Temperature: (24 ± 1) °C Relative humidity: $(55 \pm 10) \%$ Air pressure: (1000 ± 10) hPa

Test specifications

- The Sound Level Meter has been calibrated in accordance with the requirements as specified in BS 7580: Part 1: 1997
 and the lab calibration procedure SMTP004-CA-152.
- The electrical tests were performed using an electrical signal substituted for the microphone which was removed and replaced by an equivalent capacitance within a tolerance of ±20%.
- The acoustic calibration was performed using an B&K 4226 sound calibrator and corrections was applied for the difference between the free-field and pressure responsess of the Sound Level Meter.

Test results

Details of the performed measurements are presented on page 2 of this certificate.

Actual Measurement data are documented on worksheet.

Approyed Signatory: Date: 14-Jul-2006

Comments: The results reported in this certificate refer to the condition of the instrument on the date of calibration and carry no implication regarding the long-term stability of the instrument.

© Soils & Materials Engineering Co., Ltd.

Form No.CARP152-1/Issue 1/Rev.B/01/05/2005



综合試驗有限公司
SOILS & MATERIALS ENGINEERING CO., LTD.
G/F., 9/F., 12/F., 13/F. & 20/F., Leader Centre. 37 Wong Chuk Hang Road, Aberdeen, Hong Keng.
香港黃竹道 37 號利達中心地下,9 樣 · 1 2 模 · 1 3 接及 2 0 樓
Femally and Collaborations Com. E-mail: smac@clglsmac.com Website: www.cigismec.com

Tel: (852) 2873 6860 Fax: (852) 2555 7533



CERTIFICATE OF CALIBRATION

Certificate No.:	06CA0713 01-06		Page:	1 of 2
Item tested				
Description: Manufacturer: Type/Model No.: Sertal/Equipment No.: Adaptors used:	Sound Calibrator (C Rion Co., Ltd. NC-73 10307216	Class 1) . 00 '÷. 06 }		
Item submitted by		<u> </u>		
Client: Request No.: Date of request:	Maunsell Environme - 12-Jul-2006	ental Management Co.	nsuitants Ltd.	
Date of test:	13-Jul-2006			
Reference equipment	used in the calibra	<u></u> ition		
Description: Lab standard microphone Preamplifier Measuring amplifier Signal generator Digital multi-meter Audio analyzer Universal counter Ambient conditions Temperature: Relative humidity: Air pressure: Test specifications	Model: B&K 4180 B&K 2673 B&K 2610 DS 360 34401A 8903B 53132A 24 ± 1 °C 65 ± 10 % 1000 ± 15 hPa	Serial No. 2239857 2239857 2346941 61227 US36087050 GB41300350 MY40003662	Expiry Date: 12-Apr-2007 30-Nov-2006 30-Nov-2006 12-Jul-2007 30-Nov-2006 28-Nov-2006 12-Jul-2007	Traceable to: SCL SCM SCM SCM SCM CIGISMEC SCM SCM
The Sound Calibrator and the lab calibration The calibrator was tea. The results are round	n procedure SMTP004- sted with its axis vertica led to the nearest 0.01	-CA-156. al facing downwards at dB and 0.1 Hz and hav	t the specific frequency u	d in IEC 60942 1997 Annex B sing insert voltage technique. variations from a reference t is insensitive to pressure
Test results				· · · · · · · · · · · · · · · · · · ·
This is to certify that the sound of est was performed. This does the performed mean the performed means of the performed means of the performed means. The results report the performents: The results report to implication regarding	s not imply that the sou surements are present Jian Mur	ed on page 2 of this c Date: 14-10-2	C 60942 unge any other confidence of the company Chip	
Solis & Materials Engineering Co., Ltd.			Fоли No.C/	ARP156-1/Issue 1/Rev.C/01/05/2005

Hong Kong Accreditation Service (HKAS) has accredited this laboratory under the Hong Kong Laboratory Accreditation Scheme (HOKLAS) for specific laboratory activities as listed in the HOKLAS Directory of Accredited Laboratories. The results shown in this certificate were determined by this laboratory in accordance with its terms of accreditation. Such terms of accreditation stipulate that the results shall be traceable to the International System of Units 1811 or responsible descriptional about the section of Units 1811 or responsible description of the section of Units 1811 or responsible description of Units 1811 or responsibilities of Units 1811 or responsibili



綜合試驗有限公司 SOILS & MATERIALS ENGINEERING CO., LTD.

G/F., 12/F., 13/F. & 20/F., Leader Centre, 37 Wong Chuk Hang Road, Aberdeen, Hong Kong. 香港實竹坑道37號利達中心地下,9樓,12樓,13樓及20樓 E-mall: smec@cigismec.com Website: www.cigismec.com

Tel : (852) 2873 6860 Fax: (852) 2555 7533



CERTIFICATE OF CALIBRATION

Certificate No.:

06CA0304 01-01

Page

of

ltem tested

Description: Manufacturer:

Sound Level Meter (Class I) RION CO., LTD.

Microphone RION CO. LTD. Preamp RION CO. LTD.

Type/Model No.: Serial/Equipment No.: NL-18 00570446 UC-53

NH-19

2

Adaptors used:

- . .

88764

75883

Item submitted by

Client:

Maunsell Environmental Management Consultants Ltd.

Request No.: Date of request:

04-Mar-2006

(M.108.0 - -

Date of test:

09-Mar-2006

Reference equipment used in the calibration

Description:

Multi function sound calibrator Measuring amplifier

Serial No. Model: B&K 4226 2288444 B&K 2610 2346941

Expiry Date: 11/Jan/2007 30/Nov/2006 30/Nov/2006

Traceable to: CIGISMEC SCM

Signal generator Signal generator DS 360 DS 360

33873 61227

06/Jun/2006

SCM NIM

Ambient conditions

Temperature:

Relative humidity: Air pressure:

(21 ± 1) °C (55 ± 10) % (1000 ± 15) hPa

Test specifications

The Sound Level Meter has been calibrated in accordance with the requirements as specified in BS 7580: Part 1: 1997 1, and the lab calibration procedure SMTP004-CA-152.

The electrical tests were performed using an electrical signal substituted for the microphone which was removed and 2, replaced by an equivalent capacitance within a tolerance of ±20%.

The acoustic calibration was performed using an B&K 4226 sound calibrator and corrections was applied for the difference 3. between the free-field and pressure responsess of the Sound Level Meter.

Test results

This is to certify that the Sound Level Meter conforms to BS 7580: Part 1: 1997 for the conditions under which the test was performed.

Details of the performed measurements are presented on page 2 of this certificate.

Actual Measurement data are documented on worksheet.

Approved Signatory:




Comments: The results reported in this certificate refer to the condition of the instrument on the date of calibration and carry no implication regarding the long-term stability of the instrument.

O Soils & Materials Engineering Co., Ltd.

Form No.CARP152-1/Issue 1/Rev.B/01/05/2005

Hong Kong Accreditation Service (HKAS) has accredited this laboratory under the Hong Kong Laboratory Accreditation Scheme (HOKLAS) for specific laboratory activities as listed in the HOKLAS Directory of Accredited Laboratories. The results shown in this certificate were determined by this laboratory in accordance with its terms of accreditation. Such terms of accreditation stipulate that the results shall be traceable to the international System of Units (S.I.) or recognised measurement standards. This certificate shall not be reproduced except in full.

APPENDIX F AIR QUALITY MONITORING RESULTS AND GRAPHICAL PRESENTATION



APPENDIX F: Air Quality Monitoring Results

1-hour TSP Monitoring Results at Station ASR8

<u> </u>	Ol- His		Canaantra	tion un/m2	 -
Date	Starting		Concentra	tion, µg/m3	
	Time	1st	2nd	3rd	Average
4-Oct-06	9:15	85.4	83.1	86.5	85.0
10-Oct-06	8:00	90.7	89.5	92.0	90.7
16-Oct-06	8:00	104.0	107.8	103.4	105.1
21-Oct-06	8:00	110.5	107.6	109.7	109.3
27-Oct-06	8:00	77.6	77.1	78.1	77.6
	'			Min.	77.1
				Max.	110.5
				Average	93.5

1-hour TSP Monitoring Results at Station ASR17

Tallous for Monitoring Resource at State 17 (Sec. 1987)								
Date	Starting		Concentra	tion, µg/m3				
	Time	1st	2nd	3rd	Average			
4-Oct-06	8:00	85.1	87.4	87.5	86.7			
10-Oct-06	8:00	86.8	89.6	87.5	88.0			
16-Oct-06	8:00	115.2	114.5	118.0	115.9			
21-Oct-06	8:00	99.8	103.1	100.5	101.1			
27-Oct-06	8:00	80.4	88.5	90.2	86.4			
	<u> </u>			Min.	80.4			
				Max.	118.0			
				Average	95.6			

Remark:

Bold value indicated an Action level exceedance Bold & Italic value indicated an Limit level exceedance

APPENDIX F: Air Quality Monitoring Results


24-hour TSP Monitoring Results at Station ASR8


Initial	Filter Weight (g)	Flow Rate (m³/	: (m³/min.)	Elapse	Elapse Time	Sampling	Conc.	Weather	Particulate	Av. flow	
	i Final	Initial	Final	Initial	Final	Time(hrs.)	(mg/m ₃)	Condition	weight(g)	(m³/min)	(m ₃)
3-Oct-06 3.4571	1 3.6637	1.34	1.34	3110.2	3134.2	24.0	106.9	Sunny	0.21	ľ	1932.5
9-Oct-06 3.5237	7 3.6892	1.41	1.41	3134.2	3158.2	24.0	81.8	Sunny	0.17	1.41	2023.2
H	8 3.8645	1.41	1.41	3158.2	3182.2	24.0	109.1	Fine	0.22	1,41	2023.2
╀	H	1,28	1.28	3182.2	3206.2	24.0	67.1	Sunny	0.12	1.28	1843.2
╀		1.34	1.34	3206.2	3230.2	24.0	42.0	Sunny	0.08	1.34	1932.5
						Min	42.0				
						Max	109.1				
						Average	81.4				

24-hour TSP Monitoring Results at Station ASR17


Date	Filter W	Filter Weight (g)	Flow Rate	(m³/min.)	Elapse Time	Time	Sampling	Conc.	Weather	Particulate	Av. flow	Total vol.
	Initial	Final	Initial	Final	Initial	Final	Time(hrs.)	(µg/m³)	Condition	weight(g)	(m³/min)	(m ₃)
3-Oct-06	3.4992	3.5743	1.31	1.31	17205.4	17229.4	24.0	39.8	Sunny	0.08	1.31	1889.3
9-Oct-06	3.5556	3.6440	1.39	1.39	17229.4	17253.4		44.2	Sunny	0.09	1.39	2001.6
14-Oct-06	3.6561	3.7979	1.19	1.19	17253.4	17277.4	24.0	82.5	Fine	0.14	1.19	1717.9
20-Oct-06	3.5755	3.6626	1.31	1.31	17277.4	17301.4	24.0	46.1	Sunny	60.0	1.31	1889.3
26-Oct-06	3.5276	3.8098	1.52	1.52	17301.4	17325.4	24.0	128.8	Sunny	0.28	1.52	2191.7
							Min	39.8				
							Max	128.8				
							Average	68.3				


Remark: Bold value indicated an Action level exceedance Bold & Italic value indicated an Limit level exceedance





Contract No. SS M333 Reprovisioning of Diamond Hill SCALE DATE N.T.S. 2006 MAUNSELL Crematorium **AECOM** PTPM **LLMC** CHECK DRAWN **Graphical Presentation of 1-hour TSP** APPENDIX JOB NO. Rev Monitoring Results for Location ASR8 and Maunsell Environmental S07904 Management Consultants Ltd F ASR17





MAUNSELL AECOM


Maunseil Environmental
Management Consultants Ltd

Contract No. SS M333 Reprovisioning of Diamond Hill Crematorium

Graphical Presentation of 24-hour TSP Monitoring Results for Location ASR8 and ASR17

SCALE	N.T.S.	DATE		2006	;
CHECK	PTPM	DRAWN		LLMC	7
JOB NO.	S07904	APPENDIX	F		Rev

APPENDIX G NOISE MONITORING RESULTS AND GRAPHICAL PRESENTATION



Appendix G Noise Monitoring Results

Daytime Noise Monitoring Results at Station SR3

Date	Weather	Noise	Level for	30-min, d	B(A) ⁺	Baseline Noise	Calculated Construction Noise	Limit Level,	Exceedance
Condition		Time	L90	L10	Leg	Level, dB(A)	Level, dB(A)	dB(A)	(Y/N)
4-Oct-06	Sunny	9:15	64.0	68.0	66.2	65.1 59.7		70	N
10-Oct-06	Sunny	9:30	62.0	66.2	64.9	65.1 *Note 65.1 *Note 65.1 *Note		70	N
16-Oct-06	Sunny	13:30	62.0	66.5	64.3			70	N_
27-Oct-06	Sunny	8:58	60.5	65.0	63.2			70	N
		Min	60.5	65.0	63.2				
		Max	64.0	68.0	66.2				
		Average	62.1	66.4	64.7				


Daytime Noise Monitoring Results at Station SR4

Date Weather		THOISE ECVEL IOI DO MILIT, GENTLY				Baseline Noise Level, dB(A)	Calculated Construction Noise	Limit Level,	Exceedance (Y/N)
<u></u>	Condition	Time	L90	L10	Leq	Level, GD(A)	Level. dB(A)	dB(A)	(1/(1)
4-Oct-06	Sunny	8:50	63.5	68.3	66.8	65.6	60.6	70	N
10-Oct-06	Sunny	8:50	61.5	66.0	64.8	65.6	*Note	70	N
16-Oct-06	Sunny	8:55	61.7	66.0	63.8	65.6	*Note	70	N N
27-Oct-06	Sunny	8:52	60.0	64.3	62.8	65.6	*Note	70	N
		Min	60.0	64.3	62.8				
		Max	63.5	68.3	66.8				
		Average	61.7	66.2	64.6	1			


Daytime Noise Monitoring Results at Station SR6

Date	Weather	Noise Level for 30-min, dB(A) ⁺				Baseline Noise	Calculated Construction Noise	Limit Level,	Exceedance
Daic	Condition	Time	L90	L10_	Leq	Level, dB(A)	Level. dB(A)	<u>dB(A)</u>	(Y/N)
4-Oct-06	Sunny	8:00	60.6	65.5	63.7	68.5	*Note	75	N
10-Oct-06	Sunny	8:00	60.7	65.5	63.6	68.5	*Note	75	N
16-Oct-06	Sunny	8:00	60.5	65.2	63.5	68.5	*Note	75	N
27-Oct-06	Sunny	8:00	60.2	65.0	63.5	68.5	*Note	75	N N
<u> </u>		Min	60.2	65.0	63.5				
		Max	60.7	65.5	63.7				
			60.5	65.3	63.6				

⁺ - Façade measurement Bold & Italic value indicated an Limit level exceedance Note: Measured noise level is less than the baseline noise level.



APPENDIX H
SUMMARY OF WEEKLY ENVIRONMENTAL
SITE INSPECTION OBSERVATIONS



Weekly Environmental Site Inspection Record Reprovisioning of Diamond Hill Crematorium

Inspection Information

3 October 2006	09:30 am – 12:00 am
Date	Time

Remarks/Observations

Water Quality

- The Contractor was reminded to provide the washing wheel facilities.
- Stagnant water was observed at the site exit, G/F and B/F. The Contractor was reminded to pump out or remove the water. The stagnant water should be treated in the sedimentation tank before discharging.
- The Contractor was reminded to provide sandbags for runoff. რ

Air Quality

The Contractor was reminded to remove the cement bags.

Noise

No violation was observed in this site inspection. ທ່

Waste/Chemical Management

6. The Contractor was reminded to maintain and remove the construction wastes in regular basis.

Landscape and Visual

No violation was observed in this site inspection.

Others

No violation was observed in this site inspection

Inspection Information

9 October 2006	10:05 am — 12:00 am
Date	Time

Remarks/Observations

Water Quality

- 1. The Contractor was reminded to provide the washing wheel facilities.
 - The Contractor was raminded to provide sandbags for runoff.
- Stagnant water was observed at the site exit, 1/F and outside the sub-contractor's office. The Contractor was reminded to pump out or remove the water. The stagnant water should be treated in the sedimentation tank before discharging. લું છું

Air Quality

The cement bags were not observed from the site.

No violation was observed in this site inspection. Noise

6. No violation was observed in this site inspection. Waste/Chemical Management

Landscape and Visual

7. No violation was observed in this site inspection.

8. No violation was observed in this site inspection

P:\S07904\REPORTS\Monthly\2006\0610\app\app_h.doc

MAUNSELL AECOM

PNS07904/REPORTSVMonthly/2006/0610/apphapp_h.doc

MAUNSELL | AECOM

Weekly Environmental Site Inspection Record Reprovisioning of Diamond Hill Crematorium

inspection information

16 October 2006	10:00 am - 12:00 am
Date	Time

Remarks/Observations

Water Quality

- 1. The Contractor was reminded to provide sandbags for runoff.
- The Contractor was reminded to provide and maintain the washing wheel facilities. ٥į
- Stagnant water was observed at the site exit, G/F, B/F, 1/F and outside the sub-contractor's office. The Contractor was reminded to pump out or remove the water. The stagnant water should be treated in the sedimentation tank before discharging.

Air Quality

4. Uncovered stockpiles were observed on G/F. The Contractor was reminded to provide a cover for the stockpiles in order to avoid dust generation.

Noise

No violation was observed in this site inspection. ம்

Waste/Chemical Management

- exit. The Contractor was reminded to store in the sorting area that provided the demarcation and 6. Some chemical drums and painting drums were observed on the G/F and the wall near the site
- The Contractor was reminded to maintain the waste management in regular basis.

Landscape and Visual

8. No violation was observed in this site inspection.

Others

No violation was observed in this site inspection.

Inspection Information

	23 October 2006
Time	10:00 am - 12:00 am

Remarks/Observations

Water Quality

- The Contractor was reminded to provide sandbags for runoff.
- Stagnant water was observed at the B/F and 1/F. The Contractor was reminded to pump out or remove the water. The stagnant water should be treated in the sedimentation tank before
- The Contractor was reminded to clean up the mud and soil deposited within the site area. က်

Uncovered stockpiles were observed on the 1/F. The Contractor was reminded to provide a cover The Contractor was reminded to provide and maintain the washing wheel facilities. 4,

Air Quality

- for the stockpiles in order to avoid dust generation.
- No violation was observed in this site inspection.

Noise

Waste/Chemical Management

atorium Record
elamond Hill Crematori Site Inspection Re
至三
nond Hill C Site Inspe
g of Dlan onmental
ning of Dlar vironmenta
leprovisioning /eekly Enviror
Reprovi Veekly

- Chemical drums were observed on the G/F. The Contractor was reminded to provide drip tray in order to avoid oil leakage
 - 8. The Contractor was reminded to maintain and clean up the construction wastes regularly.

Landscape and Visual

No violation was observed in this site inspection.

Others

10. No violation was observed in this site inspection.

Inspection information

Date 31 October 2006 Time 10:00 am - 12:00 am

Remarks/Observations

Water Quality

- The Contractor was reminded to provide sandbags for runoff.
- 2. Stagnant water was observed at the site exit and the B/F. The Contractor was reminded to pump out the water and should be treated in the sedimentation tank before discharging.
 - 3. The Contractor was reminded to clean up the mud and soil deposited within the site area.

Air Quality

- 4. The Contractor was reminded to maintain and repair the washing wheel facilities.
- 5. Uncovered stockpiles were observed on the B/F and 1/F. The Contractor was reminded to provide a covers or water spraying or placed in sheltered areas for the excavator materials/ stockpiles in order to avoid dust generation.
 - The Contractor was reminded to maintain and provide water spraying for the entire road surface in order to avoid dust generation. ဗ

7. No violation was observed in this site inspection.

Waste/Chemical Management

- 8. Chemical drums were observed on the 1/F. The Contractor was reminded to store at the designated are with identified labels.
 - 9. The Contractor was reminded to maintain and clean up the construction wastes regularly.

Landscape and Visual

No violation was observed in this site inspection.


Others

11. No violation was observed in this site inspection

MAUNSELL AECPM

*S07904/REPORTS/Monthly/2006/06/10/applapp_h.c

APPENDIX I STATUS OF ENVIRONMENTAL PERMITS/LICENCES




Appendix I

Status of Environmental Permits/Licenses

Permit No.	Valid	Period	٠	1	Status			
reinit No.	From	From To Section			- Jialus			
Environmental Permit & Further Environmental Permit								
EP-179/2004/B	14 Feb 2005	N/A	Reprovisioning Crematorium	of	Diamond	Hill	Valid	
Registration as a C	hemical Wa	ste Produc	er					
5213-288-C3108- 10	6 Dec 2004	N/A	Reprovisioning Crematorium	of	Diamond	Hill	Valid	
Water Discharge L	icense							
RE/C0202/288/1	9 Mar 2005	31 Mar 2010	Reprovisioning Crematorium	of	Diamond	Hill	Valid	
Construction Nois	e Permit							
GW-RE0164-06	10 Jul 2006	9 Dec 2006	Reprovisioning Crematorium	of	Diamond	Hill	Valid	

APPENDIX J
IMPLEMENTATION SCHEDULE OF
MITIGATION MEASURES



Appendix J – Environmental Mitigation Implementation Schedule

Recommended Mitigation Measures	Location and Timing	Who to Implement?	When to Implement?	What Requirements or Standards to Achieve?	Status
Air Quality Mitigation Measures			<u> </u>		
Special air pollution control systems shall be installed and operate to reduce the emissions of air pollutants to acceptable levels	New cremators in New Crematorium	Arch SD	Design, Construction, Demolition and Operation stage	BPWAPCO	4
FEHD shall apply for a Specified Process License under the APCO	New Cremators in the New Crematorium / prior to operation	FEHD	Construction, Demolition and Operation stage	APCO	N/A
The efflux velocity of chimney shall be at least 15 m/s, the design diameter of the chimneys shall be 0.22 m and 0.30 m, the design chimney height shall be 101mP.D. (28.5m above ground), for 170 kg and 250 kg cremators respectively	Chimney of New Crematorium / design and construction stages	Arch SD	Design and Construction stage	BPM/APCO	N/A
If the interior wall of existing cremators and chimney are confirmed dioxins contaminated, special precautions shall be taken avoid fugitive emissions of dioxin contaminated materials	Cremator room and chimney in Existing Crematorium / demolition	Arch SD/Contractor	Demolition stage		N/A
Sufficient water spraying should be applied during the construction work, the fugitive dust generated from general construction dust would be reduced by 90%	Project site / construction and demolition stages	Arch SD, contractor	Construction and Demolition stage	APCO	1
Carry out a confirmatory test of dioxins in the depositions on chimney wall, flue gas ducting and combustion chambers when the existing Crematorium is shut down	Chimney, flue and cremators in Existing Crematorium / decommissioning	FEHD, Arch SD	Demolition stage		N/A
If the dioxin level of surface deposition is between 1 and 10 ppb I-TEQ, it is classified as moderately contaminated with dioxins. The demolition work site should be covered up to avoid emission of fugitive dust during demolition	Chimney, flue and cremators in Existing Crematorium / decommissioning	Arch SD 3	Demolition stage		N/A

Recommended Mitigation Measures	Location and Timing	Who to Implement?	When to Implement?	What Requirements or Standards to Achieve?	Status
If the dioxin level of surface deposition exceeds 10 ppb I-TEQ, it is classified as severely dioxin-contaminated waste. If it is confirmed that the existing facilities are severely contaminated with dioxins, a special decommissioning method — Containment method — would be adopted	Chimney, flue and cremators in Existing Crematorium / decommissioning	Arch SD 3	Demolition stage		N/A
All the demolition waste would be carefully handled, sealed and treated as chemical waste. The waste collector shall be responsible for preventing fugitive dust emission when handling the demolition waste	Chimney, flue and cremators in Existing Crematorium / demolition stage	Arch SD, contractor	Demolition stage		1
Employ a registered asbestos contractor to remove asbestos containing material during the demolition of the existing crematorium building	Cremator room in Existing Crematorium / decommissioning	Arch SD, contractor	Demolition stage	APCO	N/A
Submit a formal AIR and Asbestos Abatement plan signed by a registered asbestos consultant to the Authority for approval under APCO 28 days prior to the start of any asbestos abatement work.	Cremator room in Existing Crematorium / decommissioning	Arch SD, consultant	Demolition stage	APCO	N/A
When removing asbestos containing materials, enclosure of the work area; containment and sealing for the asbestos containing waste; provision of personal decontamination facility; use of personal respiratory/protection equipment; use of vacuum cleaner equipped with higherficiency air particulate (HEPA) filter for cleaning up the work area; and carry out air quality monitoring during the asbestos abatement work	Cremator room in Existing Crematorium / decommissioning	Arch SD, consultant	Demolition stage	APCO	N/A
Appoint qualified personnel to carry out the asbestos containing material removal work, including a registered asbestos contractor to carry out the work; a registered asbestos supervisor to supervise the work; a registered asbestos laboratory to monitor the air quality, and a registered asbestos consultant to supervise and certify the asbestos sabatement work.	Cremator room in Existing Crematorium / decommissioning	Arch SD, consultant	Demolition stage	APCO	N/A

Recommended Mitigation Measures	Location and Timing	Who to Implement?	When to Implement?	What Requirements or Standards to Achieve?	Status
Erect a site barrier with the height of no less than 2.4m to enclose the construction site Apply frequent water spraying to ensure the surface of the construction site sufficiently wet to reduce fugitive dust due to wind erosion and transportation on unpaved haul road Cover up stockpiles of filt material and dusty material Install a vehicle-cleaning system at the main entrance of the construction site to clean up the vehicles before leaving the site The Air Pollution Control (Construction Dust) Regulation shall be followed for fugitive dust control	Project site / construction and demolition stages	Contractor	Construction and Demolition stage	APCO, Air Pollution Control (Construction Dust) Regulation	•
No more than 6 cremators (including both the existing and new ones) are in operation during commissioning test of new cremators. The commissioning test of each new cremator shall be recorded by a log book	Existing and new cremators in Exiting and New Crematorium / text and commissioning	Arch SD/FEHD/ Contractor	Construction stage		N/A
Special air pollution control systems shall be installed and operate to reduce the emissions of air pollutants to acceptable levels	New cremators in New Crematorium / all stages	Arch SD	Design, Construction, Demolition and Operation stage	BPM/APCO	N/A
Conduct baseline and regular 1-hour and 24-hour TSP monitoring.	A8 and A17 / baseline monitoring prior to Phase I & II works and regular monitoring throughout Phase I & II works	Contractor	Construction and Demolition stage	APCO, EM&A Guidelines for Development Projects in Hong Kong	
When the demolition material is confirmed to have ACM, monitoring for asbestos fibre would be carried out at the boundary of the construction site for reassurance purposes as per the requirement of future	Construction site boundary / demolition	Contractor	Demolition stage	Asbestos Study Report, AIR and AAP to be submitted under	N/A

Recommended Miligation Measures	Location and Timing	Who to Implement?	When to implement?	What Requirements or Standards to Achieve?	Status
license for asbestos abatement, though it is not expected that asbestos fibre would be liberated from the demolition of the Existing Crematonium building.				APCO, future licence for asbestos abatement (if any)	
Noise Mitigation Measures					
Select quiet plant, which is defined as PME with a sound power level lower than that specified in GW-TM. Examples of quiet plant can be referred to those listed in British Standard BS5228.	Project site / construction and demolition stages	Contractor	Construction and Demolition stages	GW-TM	1
Where practicable, use movable barriers of 3 to 5 m height with a small cantilevered upper portion and skid footing can be located within a few metres from a stationary plant (e.g. generator, compressor, etc.) and within about 5 m for a mobile equipment (e.g. breaker, excavator, etc.), especially in the vicinity of SR3, SR4 and SR6. The purpose-built noise barriers or screens shall be constructed of appropriate materials with a minimum superficial density of 15kg/m2.	Project site / construction and demolition stages	Contractor	Construction and Demolition stages	NCO	N/A
Only well-maintained plant should be operated on site and plant should be regularly serviced during the construction works	Project site / construction and demolition stages	Contractor	Construction and Demolition stages	NCO	1
 Plant that is used intermittently should be turned off or throttled down when not in active use 					
 Plant that is known to emit noise strongly in one direction should be oriented to face away from NSRs 					
 Silencers, mufflers and enclosures for plant should be used where possible and maintained adequately throughout the works 					
 Where possible mobile plant should be sited away from NSRs 					

Recommended Mitigation Measures	Location and Timing	Who to Implement?	When to Implement?	What Requirements or Standards to Achieve?	Status
Stockpiles of excavated materials and other structures such as site buildings should be used effectively to screen noise from the works				:	
Liaise with the school and the Examination Authority to ascertain the dates and times of examination periods during the course of the construction/ demolition works so as to avoid any noisy activities during these periods. Programme of the on-site works should hence be well programmed such that the noisier construction activities would not be coincided with the examination of the schools.	Project site / construction and demolition stages	Contractor	Demolition stage	NCO	4
Conduct regular noise monitoring.	SR 3, SR 4 and SR 6 / Phase I & II works	Contractor	Demolition stage	NCO, EM&A Guidelines for Development Projects in Hong Kong	V
Land Contamination Miligation Measures Additional site investigations in areas of the site that are currently in use and cannot be readily accessed. These investigations will be carried out once the existing facility has been decommissioned. The additional site investigations are required in the vicinity of the existing CLP secondary substation, and around the cremators and flues inside the crematorium building. Once access to these areas is available, a sampling and analysis plan will be prepared for approval by EPD, additional investigations will take place, and the need for remedial works will be determined. Any remedial works required will be in addition to those described in this current report.	CLP secondary substation and cremator room/ demolition stage (Phase I CLP secondary substation; Phase II cremator room)	Contractor	Demolition stage	ProPECC PN 3/94	4
Once the Existing Crematorium has ceased operating during Phase II, confirmatory surface	Locations S1 to S6 specified in the	Contractor	Demolition stage	ProPECC PN 3/94	N/A

Recommended Millgation Measures	Location and Timing	Who to Implement?	When to Implement?	What Requirements or Standards to Achieve?	Status
samples will be taken from the samples points S1 to S6 at a depth of 0.1m, and these samples will be analysed for the same suite of determinands (i.e. dioxins, metals and PAH) in order to confirm that no further contamination has occurred. The Remediation Action Plan will be revised on the basis of these results.	CAP/demolition				
The underground fuel storage tank and associated pipework will be removed as part of the site formation works. The base of the excavations will be inspected during and after tank removal by a suitably experienced environmental specialist in order to determine whether there is any visual or olfactory evidence of fuel contamination. If such contamination is suspected, then confirmatory soil sampling will be carried out, and the samples analysed for TPH.	Underground fuel storage tank/during and after tank removal	Contractor	Demolition stage	ProPECC PN 3/94 and Guidance Notes for Investigation and Remediation of Contaminated Sites of Petrol Filling Stations, Boatyards and Car Repair / Dismantling Workshops	N/A
Summary of remediation works at locations S3 and S5:					
1. Mark out 5m radius around S3 and S5 2. Excavate to depth of 0.5m 3. Transport to landfill site for final disposal4. Take 4 samples from edges of excavation and one sample from base of excavation, analyse for lead and tin 5. If the results exceed Dutch B Levels, extend excavation to a further 5 m radius and 0.5 m depth in the quadrant where the contaminated samples is encountered and repeat steps 3 and 4 6. If the results less than Dutch B Levels, then remediation completed.	Locations S3 and S5 specified in CAP/demolition	Contractor	Demolition stage	ProPECC PN3/94	N/A

Recommended Mitigation Measures	Location and Timing	Who to Implement?	When to Implement?	What Requirements or Standards to Achieve?	Status
During removal of the underground fuel storage tank, appropriate precautions should be taken to avoid contamination. All fuel tanks and associated pipework should be emptied prior to any demolition work being undertaken. Any remaining sludge or sediment in the tanks or pipework should be removed and disposed of as chemical waste in accordance with the appropriate regulations for disposal of such material.	Underground fuel storage tank / Phase II demolition	Agent Contractor	Demolition stage	ProPECC PN 3/94 and Guidance Notes for Investigation and Remediation of Contaminated Sites of Petrol Filling Stations, Boatyards and Car Repair / Dismantling Workshops	N/A
Should contamination be encountered beneath the fuel tank or the CLP secondary substation, further remedial work will be required. Such potential contamination would consist of either TPH (in the case of the fuel tank) or PCBs (in the case of the CLP secondary substation). As a realistic worst-case estimate, the PCB contaminated soil at CLP secondary substation may require stabilisation with cement prior to disposal to landfill. A realistic worst case estimate is that the volume of TPH contaminated soil at underground storage tank would require landfill disposal.	CLP secondary substation /Phase I demolition and underground fuel tank / Phase II demolition	Contractor	Demolition stage	ProPECC PN 3/94 and Guidance Notes for Investigation and Remediation of Contaminated Sites of Petrol Filling Stations, Boalyards and Car Repair / Dismantling Workshops	N/A
Health and Safety Precautions during Remedial Works		,			
The site workers engaged in the remedial works should be provided with adequate personal protective equipment, which should include: Protective footwear; Gloves; Dust masks; and Overalls. A clean area should be provided, equipped with washing facilities. Eating, drinking and smoking should only be permitted within designated "clean" areas after washing. Excavated material should not be stockpiled, but should immediately be treated/transported to landfill on a daily basis.	All areas requiring remedial works in Project site I demolition during Phases I and II	Contractor	Demolition stage	ProPECC PN 3/94 and Guidance Notes for Investigation and Remediation of Contaminated Sites of Petrol Filling Stations, Boalyards and Car Repair / Dismantling	N/A

Recommended Mitigation Measures	Location and Timing	Who to Implement?	When to Implement?	What Requirements or Standards to Achieve?	Status
				Workshops	
Avoidance of Impacts on Water Quality during Remedial Works In order to avoid impacts on water quality during remedial works, care will be taken to minimise the mobilisation of sediment during excavation and transport. Measures to be adopted will be based on the recommendations set out in Practice Note for Professional Persons ProPECC PN1/94 "Construction Site Drainage". The results of the site investigation suggest that there is unlikely to be any requirement for dewatering of excavations, since groundwater was not encountered in any of the exploratory holes. The contractor carrying out the remedial works will be required to submit a method statement detailing the measures to be taken to avoid water quality impacts. Typical measures would include; Carry out the works during the dry season (i.e. October to March) if possible; - Use bunds or perimeter drains to prevent run-off water entering excavations; - Sheet or otherwise cover excavations whenever rainstorms are expected to occur; - Minimise the requirements for stockpiling of material and ensure any stockpiles are covered; - Temporary on-wit stockpiling of contaminated materials should be avoided, and all excavated contaminated soils/materials should be disposed of on a daily basis; - Ensure that any discharges to storm drains pass through an appropriate silt trap.	All areas requiring remedial works in Project site / demolition during Phases I and II	Agent Contractor	Demolition stage	ProPECC PN 3/94, ProPECC PN1/94 and Guidance Notes for Investigation and Remediation of Contaminated Sites of Petrol Filling Stations, Boalyards and Car Repair / Dismantling Workshops	N/A
Waste Disposal Requirements during Remedial Works					
MORKS. An application for permission to dispose of excavated material should be made to the Facilities Management Group of EPD three months prior to disposal. A "tripticket" system should be implemented. Each load of contaminated soil despatched to landfill should be	All areas requiring remedial works in Project site / demolition during Phases I and II	Contractor	Demolition stage	ProPECC PN 3/94, Waste Disposal Ordinance (Cap. 354), WBTC No. 21/2002 and	N/A

Recommended Mitigation Measures	Location and Timing	Who to Implement?	When to Implement?	What Requirements or Standards to Achieve?	Status
accompanied by an admission ticket. Vehicles leaving the site should be adequately sheeted to prevent dispersion of contaminated material during transport. The wheels of vehicles should be cleaned prior to leaving site, to prevent contaminated material leaving site on the wheels of vehicles.				Guidance Notes for Investigation and Remediation of Contaminated Sites of Petrol Filling Stations, Boatyards and Car Repair / Dismantling Workshops	
Compliance Report for Remedial Works Following completion of remediation works, a Remediation Report should be compiled and submitted, to demonstrate that the remediation works have been carried out in accordance with the Remediation Action Plan. The Remediation Report should include details of the excavation works carried out, records of material taken to landfill, and results of confirmatory testing, and should be submitted to EPD for approval before the commencement of building works.	All areas requiring remedial works in Project site / after completion of remediation works	Agent Contractor	Demolition stage	ProPECC PN 3/94 and Guidance Notes for Investigation and Remediation of Contaminated Sites of Petrol Filling Stations, Boatyards and Car Repair / Dismantling Workshops	N/A
Land Contamination Mitigation Measures Conduct supplementary site investigation for TPH and PCB in soil samples.	CLP substation / after decommissioning but prior to demolition during Phase I work	Contractor	Demolition stage	CAR, RAP, future sampling and analysis plan	1
Conduct confirmatory testing of PAH, dioxins and metals (the "Dutch List") in soil samples.	S1 to S6 / Phase II work	Contractor	Construction and Demolition stages	CAR, RAP, future sampling and analysis plan	N/A
If fuel contamination underneath the underground fuel tank is suspected, confirmatory soil sampling will be carried out for analysis of TPH.	Underneath the underground fuel tank / Phase II	Contractor	Demolition stages	CAR, RAP, future sampling and analysis plan	N/A
Conduct confirmatory testing of tin and lead in soil	S3 and S5 / during	Contractor	Construction and	CAR, RAP, future	N/A

Recommended Mitigation Measures	Location and Timing	Who to Implement?	When to Implement?	What Requirements or Standards to Achieve?	Status
samples to confirm all contaminated soil has been excavated.	Phase II work following excavation at each location		Demolition stages	sampling and analysis plan	
Waste Management Mitigation Measures				<u> </u>	
Good Site Practice Obtain relevant waste disposal permits from the appropriate authorities, in accordance with the Waste Disposal Ordinance (Cap. 354), Waste Disposal (Chemical Waste) (General) Regulation (Cap. 354) and the Land (Miscellaneous Provision) Ordinance (Cap. 28) Prepare a Waste Management Plan approved by the Engineers / Supervising Officer of the Project in accordance with Environment, Transport and Works Bureau Technical Circular (Works) (ETWBTC(W)) 15/2003, Waste Management On Construction Sites Nominate an approved person, such as site manager, to be responsible for good site practice, arrangements for collection and effective disposal of all types of wastes generated on-site to appropriate facility Use waste haulier authorized or licensed to collect specific category of waste Establish trip ticket system as contractual requirement (with reference to Works Branch Technical Circular (WBTC) No. 21/2002) for monitoring of public fill and C&D waste at public filling facilities and landfills. Such activities should be monitored by the Environmental Team Provide training to site staff in terms of proper waste management and chemical waste handling procedures Separate chemical wastes for special handling and dispose them at licensed facility for treatment Establish routine cleaning and maintenance programme for drainage systems, sumps and oil interceptors Provide sufficient waste disposal points and regular	Project site/ design, construction and demolition stages	Contractor	Design, Construction and Demolition stages	Waste Disposal Ordinance (Cap. 354), Waste Disposal(Chemical Waste) (General) Regulation(Cap. 354) Land(Miscellaneou s Provision) Ordinance(Cap. 28) WDO, ETWBTC(W) 15/2003, WBTC No. 21/2002	

Recommended Mitigation Measures	Location and Timing	Who to Implement?	When to Implement?	What Requirements or Standards to Achieve?	Status
collection for disposal Adopt measures to minimize windblown litter and dust during transportation of waste, such as covering trucks or transporting wastes in enclosed containers Establish recording system for the amount of wastes generated, recycled and disposed of (including the disposal sites)					
Waste Management Plan The contractor should submit the Waste Management Plan to Engineer/Supervising Officer of the Project for approval. The Waste Management Plan should describe the arrangements for avoidance, reuse, recovery and recycling, storage, collection, treatment and disposal of different categories of waste to be generated from the activities of the Project and indicate the disposal location(s) of all waste. A trip ticket system shall be included in the Waste Management Plan.	Project site / design, construction and demolition stages	Contractor	Design, Construction and Demolition stages	Waste Disposal Ordinance (Cap. 354)	
Waste Reduction Measures • Minimize the damage or contamination of construction material by proper storage and site practices • Plan and stock construction materials carefully to minimize amount of waste generated and avoid unnecessary generation of waste • Prior to disposal of C&D waste, wood, steel and other metals should be separated for reuse and / or recycling to minimize the quantity of waste to be disposed of to landfil • Minimize use of wood and reuse non-limber formwork to reduce the amount of C&D waste • Recycle any unused chemicals or those with remaining functional capacity as far as practicable • As far as practicable, segregate and store different types of waste in different containers, skips or stockpiles to enhance reuse or recycling of materials and their proper disposal • Encourage collection of aluminium cans, plastic bottles and packaging material (e.g. carton boxes) and office paper by individual collectors, separate labeled	Project site / construction and demolition stages	Agent Contractor	Construction and Demolition stages	WBTC No. 32/92, 5/98 and 19/99	*

Recommended Mitigation Measures	Location and Timing	Who to Implement?	When to implement?	What Requirements or Standards to Achieve?	Status
bins should be provided to help segregate this waste from other general refuse generated by the work force					
Excavated Material Rock and soil generated from excavation should be reused for site formation as far as possible, in addition, excavated material from foundation work can be reused for landscaping as far as practicable to avoid disposal off-site.	Project site / construction and demolition stages	Contractor	Construction and Demolition stages	WBTC 12/2000	7
Construction and Demolition Material Careful design, planning and good site management can minimize over-ordering and generation of waste materials such as concrete, mortar and cement grouts. Standard formwork should be used as far as practicable, wooden formwork should be replaced by metal ones whenever possible. Alternatives such as plastic fencing and reusable site office structures can also minimize C&D waste generation. The contractor should recycle as much as possible of the C&D material on-site. Public fill and C&D waste should be segregated and stored in different containers or skips to enhance reuse or recycling of materials and their proper disposal. Materials such as concrete and masonry can be crushed and used as fill and steel reinforcing bar can be used by scrap steel mills. Different areas of sites should be designated for such segregation and storage. To maximize landfill life, government policy discourages the disposal of C&D materials with more than 20% inert material by weight) at landfill. Inert C&D material (public fill) should be directed to an approved public filling area, where it has the added benefit of offsetting the need for removal of materials from borrow areas for reclamation purposes.	Project site I construction and demolition stages	Contractor	Design, Construction and Demolition stages	WBTC 5/9B and19/99	1
Contaminated Material – Further Contamination	CLP secondary	Contractor	Demolition	ProPECC PN	N/A

Recommended Mitigation Measures		Location and Timing	Who to Implement?	When to Implement?	What Requirements or Standards to Achieve?	Status	
Location	Investigation Parameter	Investigation Period					
Cremators/ flue/chimney and surrounding areas	Asbestos (building structure)	Phase II					
CLP secondary substation	PCB, TPH (soil samples)	Phase I					
Cremators/ flue/chimney and surrounding areas	Dioxins, heavy metals, PAH (ash waste)	Phase II					
Surface soil around Existing Crematorim	Dioxins, heavy metals, PAH (soil sample)	Phase II					
Crematorim sample) Further contamination investigation shall provide information on the extent of contamination at cremators /flues / chimney as well as the quantity of contaminated materials requiring treatment and disposal.							

Recommended Mitigation Measures	Location and Timing	Who to implement?	When to implement?	What Requirements or Standards to Achieve?	Status
samples of ash/particulate matters should be collected from within the cremators (including he bottom ash), chimney walls, flues and surrounding trea of the Existing Crematorium for analysis of dioxin, heavy metals and PAHs by a HOKLAS accredited laboratory. A consultant experienced in the abatement of chemical wastes particularly the handling of DCM, should be appointed in order to assist with the evaluation of the information and orepare an abatement plan for the ash waste. Such a olan shall be submitted to EPD and the Labour Department (LD) to establish an acceptable and safe method for these potentially neazardous wastes. The abatement plan should identify the method of abatement, the herformance criteria for the protection of workers and the environment and any emergency procedures and contingency measures required. It must be ensured that the treatment of ash wastes will comply with all routine construction safety and Health Ordinance and Factories and notustrial Undertakings Ordinance. Due to the difficulties in establishing permanent and effective negligenering controls, the protection of workers is likely to be at the worker level. A safe system of work must be provided, and training and suitable personal protective equipment as well as hygienic decontamination facilities should be provided. It is recommended that the methods to be adopted by the contractor for disposal of the ash waste should be agreed with LD and EPD.	Cremator room in Existing Crematorium / before demolition and after decommission	Contractor	Demolition stage	ProPECC PN 3/94	Ν/A
Sufficient time should be allocated to abate all ash waste with DCM/HMCM/PAHCM. The contractor should ensure the implications of dust				ProPECC PN 3/94 Code of Practice	N/A

Recommended Mitigation Measures	Location and Timing	Who to Implement?	When to Implement?	What Requirements or Standards to Achieve?	Status
containing DCM/HMCM on air quality and workers health during the clean up work are mitigated. Since DCM is chemically related to Polychlorinated Biphenyl (PCB) wastes, the requirements of the Code of Practice on the Handling, Transportation and Disposal of (PCB) Wastes should be referenced when developing the abatement plan.				the Handling, Transportation and Disposat of (PCB) Wastes	
A land contamination site investigation was carried out under this EIA to determine disposal requirements for contaminated soil. Further site investigation on soil around CLP secondary substation is needed when decommissioned, which will be during Phase I of the works. In addition, confirmatory testing on DCM level in locations S1 to S6 will be required to identify the appropriate remediation and disposal requirements during Phase II of the works.	Locations S1 to S6 in CAP / prior to Phase II demolition		Demolition stage		N/A
Asbestos Containing Materials (ACM) Further asbestos assessment should be carried out when access to the cremators /flue /chimney is accessible after decommissioning and before demolition. An AMP should be prepared. The AAP should be prepared and submitted to EPD for approval prior to commencement of demolition works in accordance to the APCO. It is preferable to remove all ACM before actual demolition. A registered asbestos removal contractor should be employed to remove all ACM in accordance with the approved AAP which will be prepared in due course in accordance with the Code of Practice (COP) on Asbestos Control for Safe Handling of Low Risk ACM and Asbestos Work Using Full Containment or Mini Containment Method published by EPD. A registered asbestos consultant should also be employed to	Cremator room in Existing Crematorium / before demolition and after decommission	Contractor	Demolition stage	Code of Practice (COP) on Asbestos Control for Safe Handling of Low Risk ACM and Asbestos Work Using Full Containment or Mini Containment Method COP on Handling, Transportation and Disposal of Asbestos Waste under the Waste Disposal	N/A

5
5

Recommend	Recommended Mitigation Measures			Who to implement?	When to Implement?	What Requirements or Standards to Achieve?	Status
supervise abatement works. For the disposal of ACM, the contractor should observe the COP on Handling, Transportation and Disposal of Asbestos Waste under the Waste Disposal (Chemical Waste) (General) Regulation.						(Chemical Waste) (General) Regulation APCO	
Dioxin Conta Containing M Polyaromatic (PAHCM) fro Crematorium	ining Materials (DCM laterials (HMCM) / Hydrocarbon Contai m Demolition of the E intamination Classific MCM	l) / Heavy Metal ning Materials Existing	Cremator room in Existing Crematorium / before demolition and after decommission	Contractor	Demolition	ProPECC PN3/94 USEPA dioxin assessment criterion	N/A
Low/Non Contaminat ed by DCM / HMCM / PAHCM	< 1 ppb TEQ	< Dutch "B" List					
Moderately/ Severely Contaminat ed HMCM / PAHCM	< 1 ppb TEQ	≥ Dutch "B" List					
Moderately Contaminat ed DCM	≥ 1 and <10 ppb TEQ	Any level					

Recommended Mitigation Measures		Location and Timing	Who to Implement?	When to Implement?	What Requirements or Standards to Achieve?	Status	
Severely Contaminat ed DCM_	≥10 ppb TEQ	Any level			•		
Low/Non-Con PAHCM from Where the asl DCM/HMCM/I should avoid a demolition. Gr measures me All such ash v disposal of at Subject to the investigation, ash waste is f	PAHCM, the contrar ash waste becoming eneral dust suppres ntioned in Section 4 vaste can be directly landfil. findings of the furth building structures found but contamina	ACM / ng Crematorium whon contaminated ctor g airborne during sion should be followed. y erer asbestos where such ted with asbestos	Cremator room in Existing Crematorium / demolition	Contractor	Demolition stage	APCO	N/A
should be dealt in accordance to 7.7.16. Demolition, Handling, Treatment and Disposal of Moderately Contaminated DCM and Moderately/Severely Contaminated HMCM / PAHCM from Demolition of the Existing Crematorium Procedure on demolition, handling, treatment and disposal of Moderately Contaminated DCM and Moderately/Severely Contaminated HMCM / PAHCM is listed below Item Procedure		Cremator room in Existing Crematorium / demolition	Contractor	Demolition stage	Waste Disposal (Chemical Waste) (General) Regulation	N/A	

Recommend	Recommended Mitigation Measures		Who to Implement?	When to Implement?	What Requirements or Standards to Achieve?	Status
Site Preparation	The contractor should ensure the impacts of dust containing dioxin and/or heavy metals on air quality and workers health during the handling and transportation of the contaminated materials are mitigated. Except the cremators/flue/chimney, all removable items where moderately contaminated DCM or moderately/severely contaminated HMCM / PAHCM is identified should be removed as far as practicable to avoid obstructing the decontamination activities. Preliminary site decontamination of all debris shall be carried out using HEPA vacuum cleaner. The top portion of the chimney above the roof shall be enclosed by a chamber with three layers of polyethene sheets. At the entrance to the cremators /flues /chimney, a 3-chamber decontamination unit shall be constructed for entry and exit from the work area. The 3-chamber decontamination unit shall comprise a dirty room, a shower room and a clean room of at least 1m x 1m base each with 3 layers of fire retardant polyethene sheet where all workers shall carry out decontamination procedures before leaving the work area. Warning signs in both Chinese and English should be put up in conspicuous areas.					

Recommend	Recommended Mitigation Measures		Who to Implement?	When to Implement?	What Requirements or Standards to Achieve?	Status
	All workers shall wear full protective equipment, disposable protective coverall (such as Tyvek) (with hood and shoe covers), nitrile gloves, rubber boots (or boot covers), and full-face positive pressure respirators equipped with a combination cartridge that filters particulate and removes organic vapour. The organic vapour protection is an added protection against the unlikely exposure to any vapour. If ACM is identified in building structures where moderately contaminated DCM or moderately/severely contaminated HMCM / PAHCM is found, relevant abatement measures for building structures described in the AAP (see 7.7.16) should be implemented prior to the above site preparation.					
Decontamin ation, demolition and handling	The cremators/flue/chimney shall be removed from top down starting from the chimney. Any ash or residues attached to the cremators/flue/chimney or any other building structures shall be removed by scrubbing and HEPA vacuuming. Wastes generated from the containment or decontamination unit including the protection clothing of the workers such as the coveralt, nitrile glove, rubber boots and materials used for wet wiping shall be disposed of at landfill site.	Cremator room in Existing Crematorium / demolition	Contractor	Demolition stage	Waste Disposal (Chemical Waste) (General) Regulation	N/A

t	a
,	•

Recommend	Recommended Mitigation Measures		Who to Implement?	When to Implement?	What Requirements or Standards to Achieve?	Status
	After completion of removal, decontaminate all surfaces by HEPA vacuum.					
	If ACM is identified in building structures where moderately contaminated DCM or moderately/severely contaminated HMCM / PAHCM is found, relevant abatement measures for building structures described in the AAP (see 7.7.16) should be implemented prior to the above decontamination, demolition and handling measures.					
Treatment	The ash waste contains dioxin/heavy metals and in its untreated state would be classified as a chemical waste under the Waste Disposal (Chemical Waste) (General) Regulation. While the quantity of DCM/HMCM is not expected to be significant, the levels of dioxin and heavy metals would affect the treatment option. Immobilization of the contaminated materials by mixing with cernent followed by disposal at landfill (if landfill disposal criteria can be met) would be the most preferable option.					
	Rather than treating the already incinerated ash waste by incineration, the ash waste with moderately contaminated					

Recommended Mitigation Measures	Location and Timing	Who to Implement?	When to implement?	What Requirements or Standards to Achieve?	Status
DCM or moderately/severely contaminated HMCM / PAHCM should be collected and stabilized to meet landfill disposal criteria of the Facilities Management Group (FMG) of EPD. In this case it is envisaged that the process would involve collection and mixing of the ash waste with cement. Pilot mixing and TCLP tests should be carried out to establish the appropriate ratio of cement to ash waste to the satisfaction of EPD. It is envisaged that the pilot tests would involve the mixing of say 5%, 10% and 15% ratios of cement to ash waste and three replicate of 300 mm cube blocks for each ratio. TCLP tests should then be used to establish the correct ratio of cement to ash waste to the satisfaction of EPD.					

Recommen	ded Mitigation Measures	Location and Timing	Who to Implement?	When to implement?	What Requirements or Standards to Achieve?	Status
Disposal	After immobilization of the ash waste by mixing with cement in the correct ratio as determined by the pilot mixing and TCLP test, the waste materials should be placed inside polyethene lined steel drums for disposal at landfill. Transparent plastic sheeting of 0.15 mm thickness low-density polyethene or PVC should be employed. The drums should be 16 gauge steel or thicker and fitted with double bung fixed ends adequately sealed and well labelled in new or good condition. The drums should be clearly marked "DANGEROUS CHEMICAL WASTE" in English and Chinese. Prior agreement of the disposal criteria from the FMG of EPD and agreement to disposal from the landfill operator must be obtained. As a fall back option, if the landfill disposal criteria cannot be met after immobilization of the ash waste, disposal at the CWTC should be considered. The building structures will be disposal of at landfill.	Cremator room in Existing Crematorium / demolition	Contractor	Demolition stage	Waste Disposal (Chemical Waste) (General) Regulation	N/A

Recommende	ed Mitigation Measures	Location and Timing	Who to Implement?	When to Implement?	What Requirements or Standards to Achieve?	Status
	If ACM is identified in building structures where moderately contaminated DCM or moderately/severely contaminated HMCM / PAHCM is found, relevant disposal measures for building structures described in the AAP (see 7.7.16) should be implemented instead.					
Severely Cont Demolition of t Procedure for	andling, Treatment and Disposal of aminated DCM from the the Existing Crematorium demolition, handling, treatment and werely Contaminated DCM	Cremator room in Existing Crematorium / demolition	Contractor	Demolition stage	Waste Disposal (Chemical Waste) (General) Regulation	N/A
Item	Procedure					
Site Preparation	Except the cremators/flue/chimney, all removable items where severely contaminated DCM is identified should be removed from the cremator room as far as practicable to avoid obstructing the decontamination activities. Preliminary site decontamination of all debris shall be carried out using HEPA vacuum cleaner. The walls, floor and ceiling of the cremator room where severely contaminated DCM located shall be lined with 3 layers of fire retardant polyethene sheets. The top portion of the chimney above the roof shall be enclosed by a chamber with three layers of polyethene sheets. At the entrance to the cremators/flues/chimney, a 3-chamber					

23			
	•	3	3

Recommended Mitigation Measures	Location and Timing	Who to implement?	When to Implement?	What Requirements or Standards to Achieve?	Status
decontamination unit shall be constructed for entry and exit from the work area. The 3-chamber decontamination unit shall comprise a dirty room, a shower room and a clean room of at least 1 mx 1 m base each with 3 layers of fire retardant polyethene sheet where all workers shall carry out decontamination procedures before leaving the work area. Warning signs in both Chinese and English should be put up in conspicuous areas.					
Air movers should be installed at the cremator room, and at the bottom of the chimney to exhaust air from the work area. A stand-by air mover shall also be installed with each of the air movers. Sufficient air movement shall be maintained to give a minimum of 6 air changes per hour to the work area, and maintain a negative pressure of 0.05-0.15 inches of water within the work					
ones or water within the work area throughout the entire course of the decommissioning works. A pressure monitor with printout records and audible alarm shall be installed at an easily accessible location to demonstrate that negative pressure is maintained. New pre-filters and HEPA filters shall be used on the air movers. A copy of the maintenance records of					

Recommended Mitigation Measures	Location and Timing	Who to Implement?	When to Implement?	What Requirements or Standards to Achieve?	Status
the air movers should be kept on site for inspection upon request. The appointed contractor shall also check the differential pressure of the air mover to make sure the filter is not blocked. A differential pressure above 0.2 inches of water indicates that the filters would need to be changed.					
Smoke Test: before commencement of the decommissioning work, a smoke test with non-toxic smoke shall be carried out to ensure the air-tightness of the containment. Also check whether there are stagnant air pockets indicated by an aggregate of smoke that cannot effectively be extracted. After a successful test, switch on the air mover to exhaust smoke from the containment and to give a minimum of 6 air changes per hour, and check visually to see that the filters screen out the smoke effectively and if the pressure gauges read normal. If not, the air mover shall be sealed up and returned to the supplier workshop for necessary servicing, and replaced by a tested air mover. The normal reading pressure range for maintaining 6 air changes per hour shall be 1.5-4 mm/0.05-0.15 inches of water or equivalent	Cremator room in Existing Crematorium / demolition	Contractor	Demolition stage	Waste Disposal (Chemical Waste) (General) Regulation	N/A

_	-
7	•
4	•

Recommended Mitigation Measures	Location and Timing	Who to Implement?	When to implement?	What Requirements or Standards to Achieve?	Status
(negative pressure). The audible alarm's integrity should also be checked and the trigger shall be at <1.5 mm/0.05 inches of water (negative pressure). Otherwise securely seal up all openings before switching off the air mover. Treatment of WasteWorkers Safety Protection: the contractor shall be required to register as a Chemical Waste Producer. All workers shall wear full protective equipment, disposable protective coverall (such as Tyvek) (with hood and shoe covers), nitrile gloves, rubber boots (or boot covers), and full-face positive pressure respirators equipped with a combination cartridge that filters particulate and removes organic				Autore 1	
vapour. The organic vapour protection is an added protection against the unlikely exposure to any vapour as a necessary measure. If ACM is identified in building					
structures where severely contaminated DCM is found, relevant abatement measures for building structures described in the AAP (see 7.7.16) should be implemented prior to the above site preparation.					

Recommend	ed Mitigation Measures	Location and Timing	Who to Implement?	When to Implement?	What Requirements or Standards to Achieve?	Status
Decontamin ation, demolition and handling	The cremators/flue/chimney shall be removed from top down starting from the chimney. Any ash or residues attaching to the cremators/flue/chimney or any other building structures shall be removed by scrubbing and HEPA vacuuming. The detached sections of the building structures where severely contaminated DCM is located shall be wrapped with 2 layers of fire retardant polyethene sheets. A third layer shall then be wrapped and secured with duct tape. Decontaminate the outer layer of the wrapped flue sections by wet wiping.	Cremator room in Existing Crematorium / demolition	Contractor	Demolition stage	Waste Disposal (Chemical Waste) (General) Regulation	N/A
	Wastes generated from the containment or decontamination unit including the fire retardant polyethene sheets, protection clothing of the workers such as the coverall, nitrile glove, rubber boots and materials used for wet wiping shall be disposed of at landfill site.	Cremator room in Existing Crematorium / demolition	Contractor	Demolition stage	Waste Disposal (Chemical Waste) (General) Regulation	N/A

_	_
7	7
_	

Recommended Mitigation Measures	Location and Timing	Who to Implement?	When to Implement?	What Requirements or Standards to Achieve?	Status
The quantity of wastewater generated from the decontaminated process will be very small but the contractor should take precautionary measures as to minimize the quantity of contaminated water arising. Nevertheless, if any contaminated wastewater needs to be discharged out of the site, it has to be properly treated to WPCO requirements with prior agreement from EPD on discharge standards. After completion of removal, decontaminate the surface where severely contaminated DCM was located, including the wrapped incinerator furnace and flue sections left within the containment, by wet wiping and HEPA vacuum. Then spray the innermost layer of the fire retardant polyethene sheet covering the wall, ceiling and floor with PVA. Upon drying, peel off this innermost layer of the polyethene sheet covering the containment and dispose of at landfill site.					

Recommende	d Mitigation Measures	Location and Timing	Who to Implement?	When to Implement?	What Requirements or Standards to Achieve?	Status
	Repeat the above decontamination procedure for the second innermost layer of fire retardant polyethene sheet by wet wiping and HEPA vacuuming. After spraying with PVA, peel off this second innermost layer of the polyethene sheet covering the wall, ceiling and floor and dispose of at landfill site. Finally, the last layer of polyethene sheet shall then be taken down after spaying with PVA and be disposed as contaminated wastes.					
Treatment and disposal	If ACM is identified in building structures where severely contaminated DCM is found, relevant abatement measures for building structures described in the AAP (see 7.7.16) should be implemented prior to the above decontamination, demolition and handling measures. Waste to be disposed to CWTC: all contaminated ash waste with severely contaminated DCM removed and the used HEPA filters shall be sent to CWTC in Tsing Yi. The total volume should be confirmed by further site investigation.	Cremator room in Existing Crematorium / demolition	Contractor	Demolition stage	Waste Disposal (Chemical Waste) (General) Regulation	N/A

Recommended Mitigation Measures	Location and Timing	Who to Implement?	When to Implement?	What Requirements or Standards to Achieve?	Status
Waste to be Disposed of at Landfill: other wastes including the building structures and its associated panels as well as wastes generated from this decommissioning works are also considered as contaminated waste and shall be disposed of at a designated landfill. Wastes generated from this decommissioning works refer to the polyethene wrapping sheets for the building structures, waste generated from the dismantlement of the containment and decontamination units, and cloth used in wet wrapping, etc. as previously described in this section. They shall be placed into appropriate containers such as drums, jerricans, or heavy duty and leak-proof plastic as a prudent approach. A disposal permit has to be obtained from the Authority. The disposal trip ticket is required to be made available as record after disposal. If ACM is identified in building structures where severely contaminated DCM is found, relevant disposal measures for building structures described in the AAP (see 7.7.16) should be implemented in prior to the above					
disposal measures.	<u> </u>				<u> </u>

Recommended Mitigation Measures	Location and Timing	Who to Implement?	When to implement?	What Requirements or Standards to Achieve?	Status
Dioxin Containing Materials (DCM) / Heavy Metal Containing Materials (HMCM) //Polyaromatic Hydrocarbon Containing Materials (PAHCM) / Total Petroleum Hydrocarbon Containing Materials (TPHCM) / Polychlorinated Biphenyls Containing Materials (PCBCM) from Soil Remediation at the Project Site					
According to the CAR and RAP, less than 100 m3 of soil would require disposal at landfill. Relevant health and safety procedure, waste disposal requirements and compliance report are as detailed in Figure 6.3. Mitigation measures to avoid fugitive dust emission mentioned in S.4.7.2 should also be observed.	Locations S3 and S5 of CAP / demolition	Contractor	Demolition stage	ProPECC PN3/94 APCO	N/A
In addition, after decommissioning but before demolition of the Existing Crematorium, further investigations during Phase I of the works at the vicinity of CLP secondary substation should also be carried out to determine if additional remediation (in addition to the current RAP) is required. Confirmatory test on levels of DCM, HMCM and PAHCM in locations S1 to S6 during Phase II of the works is also required to determine any further remediation /treatment/disposal. In addition, the ash waste in cremator/chimney/flues should also be collected for the testing of DCM/HMCM/PAHCM during Phase II of the works. The sampling and analysis plan should be prepared and submitted to EPD for approval.	CLP secondary substation / after decommission and before demolition	Contractor	Demofition stage	ProPECC PN3/94	N/A
All the aforementioned ACM / DCM / HMCM / PAHCM / TPHCM / PCBCM are classified as chemical waste. In addition to the measures mentioned above, the packaging, labelling and storage practices of chemical waste as stipulated in the following paragraphs should also be applied to these contaminated materials.	Project site / demolition	Contractor	Demolition stage	Waste Disposal (Chemical Waste) (General) Regulation	N/A

Recommended Mitigation Measures	Location and Timing	Who to Implement?	When to Implement?	What Requirements or Standards to Achieve?	Status
Chemical Waste All the chemical waste should be handled according to the Code of Practice on the Packaging, Labeiling and Storage of Chemical Wastes. The Contractor should register as a chemical waste producer. The chemical waste should be stored and collected by an approved contractor for disposal at a licensed facility in accordance with the Waste Disposal (Chemical Waste) (General) Regulation. Containers used for the storage of chemical waste should;	Project site / demolition	Contractor	Demolition stage	Code of Practice on the Packaging, Labelling and Storage of Chemical Wastes. Waste Disposal (Chemical Waste) (General) Regulation.	•
Be suitable for the substance they are holding, resistant to corrosion, maintained in good condition, and securely closed;					
 Have a capacity of less than 450 L unless the specifications have been approved by the EPD; and 					
 Display a label in English and Chinese in accordance with instructions prescribed in Schedule 2 of the Waste Disposal (Chemical Waste) (General) Regulation. 					;
The storage area for chemical waste should:		1			,
 Be clearly labeled and used solely for the storage of chemical waste; 					j
 Be enclosed on at least 3 sides; 		Į.			
 Have an impermeable floor and bunding, of capacity to accommodate 110% of the volume of the largest container or 20% by volume of the chemical waste stored in that area, whichever is the greatest; 					
Have adequate ventilation;					!
 Be covered to prevent rainfall from entering (water collected within the bund must be tested and disposal as chemical waste if necessary); and 					
Be properly arranged so that incompatible					

Recommended Mitigation Measures	Location and Timing	Who to Implement?	When to Implement?	What Requirements or Standards to Achieve?	Status
materials are adequately separated. The chemical waste should be disposed of by: • A licensed waste collector; • A facility licensed to receive chemical waste, such as the CWTC at Tsing Yi, which offers chemical waste collection service and can supply the necessary storage containers; and/or • A waste recycling plant as approved by EPD.	Project site I demolition	Contractor	Demolition stage	Code of Practice on the Packaging, Labelling and Storage of Chemical Wastes. Waste Disposal (Chemical Waste) (General)	N/A
General Refuse General refuse should be stored in enclosed bins or compaction units separated from C&D and chemical wastes. A reliable waste collector should be employed by the contractor to remove general refuse from the site, separately from C&D and chemical wastes, on a daily or every second day basis to minimize odour, pest and litter impacts. The burning of refuse on construction sites is prohibited by law. Aluminum cans are often recovered from the waste stream by individual collectors if they are segregated or easily accessible. Therefore, separately labeled bins for deposit of these cans should be provided if feasible. Similarly, plastic bottles and carton package material generated on-site should be separated for recycling as far as practicable. Site office waste should be reduced through recycling of paper if volumes are large enough to warrant collection. Participation in a local collection scheme should be considered if one is available.	Project site / construction and demolition stages	Contractor	Construction and Demolition stage		
Conduct supplementary site investigation for asbestos in building structures and for dioxins, metals (the "Dutch List") and PAH in ash/particular	Around existing cremators, chimney and flues	Contractor	Demolition stage	AIR, AMP/AAP to be submitted under	N/A

2	2
J	Ç

Recommended Mitigation Measures	Location and Timing	Who to Implement?	When to Implement?	What Requirements or Standards to Achieve?	Status
matter samples.	inside cremator room / after decommissioning but prior to demolition during Phase II work			APCO, future supplementary site investigation plan	
Landscape and Visual Mitigation Measures					
The identification of the landscape and visual impacts will highlight those sources of conflict requiring design solutions or modifications to reduce the impacts and, if possible, blend the development with the surrounding landscape. The proposed landscape mitigation measures will be described and illustrated by means of site plans and photomontage and take into account factors including:	Project site / design, construction and demolition stages	Contractor/FEH D/Arch SD	Construction and Demolition stage	EIAO-TM	N/A
 Screen planting Transplanting of mature trees with good amenity 		1			
value where appropriate Conservation of topsoil for reuse					
Sensitive alignment of structures to minimise disturbance to surrounding vegetation					
 Reinstatement of areas disturbed during construction 	1				
 The design and finishes / colours of architectural and engineering structures such as terminals and pylons 					
 Existing views, views of the development with no mitigation, views with mitigation at day one of operation and after 10 years of operation 					-
Tree transplanting: The tree survey has identified the trees which will be affected by the development and which could be considered for	Project site / construction and demolition as well	Contractor/Arch SD	Construction and Demolition stage	WBTC 7/2002, WBTC 14/2002, EIAO-TM	N/A

Recommended Mitigation Measures	Location and Timing	Who to Implement?	When to Implement?	What Requirements or Standards to Achieve?	Status
transplanting prior to commencement of construction work. Felling is considered as a last resort and every effort should be made to transplant the many good trees of high amenity value to either nearby suitable sites within the cemetery or to available space in FEHD's Wo Hop Shek Crematorium pending identification of an alternative site. The feasibility of transplanting will depend on a number of factors such as size, health and species of the tree. Adequate time (a minimum of 4 months) should be allowed for preparing trees for transplanting. Weekly inspection of tree protection measures as well as monitoring of tree transplant operations during both phases should be implemented. Particular care should be taken to save the 9 nos. mature and semi-mature protected tree species and 12 nos, protected shrub and immature tree species identified. To give the protected species the best possible chance of survival it is recommended that they are relocated to sheltered and well maintained planted areas within the cemetery. The following measures for tree transplanting should be adopted: (a) Appoint a landscape contractor for the establishment and maintenance of the transplanted trees as well as any new tree planting for 12 months upon completion of the works. (b) Careful co-ordination of Phase I and II works to allow tree transplanting from Phase II site directly to Phase I site.	as operation stages				
Tree protection: Trees to be retained adjacent to works areas will be carefully protected by strong hoarding and if necessary additional protection to individual tree trunks to avoid damage by machinery. The hoarding will also prevent	Project site / construction and demolition stages	Arch SD	Construction and Demolition stage	WBTC 7/2002, WBTC 14/2002, EIAO-TM	N/A

Recommended Mitigation Measures	Location and Timing	Who to Implement?	When to Implement?	What Requirements or Standards to Achieve?	Status
contractors from compacting soil around tree roots or dumping materials. Reference should be made to the guidelines for tree protection in the Government publication "Tree Planting and Maintenance in Hong Kong".					
Topsoil conservation: Any topsoil excavated during construction will be carefully saved and stored to one side of the works area for reuse upon completion.	Project site / upon completion of construction works for each phase	Arch SD	Construction and Demolition stage	WBTC 7/2002, WBTC 14/2002, EIAO-TM	N/A
Replanting: Upon completion planting of omamental trees and shrubs will be provided to the periphery of the new cermatorium building to help screen and soften the overall appearance of the structure. In addition, a reprovisioned memorial garden with a lotus pond and omamental planting will be incorporated in the deck area of the building. Since the majority of the new planting will be on the deck structure the selection of species will be more limited with emphasis on smaller trees and ornamental shrubs to comply with loading restrictions. Notwithstanding this site constraint on tree selection, a minimum of 1.2m soil depth will be provide for tree planting on the podium / roof structure for healthy establishment of the new tree planting.	Project site / upon completion of construction works for each phase	Arch SD	Construction and Demolition stage	WBTC 7/2002, WBTC 14/2002, EIAO-TM	N/A
Weekly inspections of tree protection measures as well as monitoring of tree transplant operations.	Project site / Phase I & II works	Project Landscape Architect	Construction and Demolition stage	Landscape Master Plan, Tree Planting and Maintenance in Hong Kong	N/A
Water Quality Mitigation Measures					
Construction and Demolition Phases - General To safeguard the water quality of the WSRs potentially affected by the Project works, the	Project site / construction and demolition stages	Contractor	Construction and Demolition stage	ProPECC PN 1/94	1

Recommended Mitigation Measures	Location and Timing	Who to Implement?	When to Implement?	What Requirements or Standards to Achieve?	Status
contractor should implement appropriate mitigation measures with reference to the Practice Note for Professional Persons, Construction Site Drainage (ProPECC PN 1/94) published by EPD. Such measures are highlighted as follows.					
Construction and Demolition Phases - Construction and Demolition Run-off and Drainage Exposed soil areas should be minimized to reduce the potential for increased siltation, contamination of run-off and erosion. Any effluent discharge from the Project site is subject to the control of Water Pollution Control Ordinance (WPCO) discharge license and should be treated to meet the discharge standard set out in the relevant license. In addition, no site run-off should enter the stream on the eastern side of the Project site. Run-off impacts associated with the construction and demolition activities can be readily controlled through the use of appropriate mitigation measures, which include:	Project site / construction and demolition stages	Contractor	Construction and Demolition stage	ProPECC PN 1/94	V
Temporary ditches should be provided to facilitate run-off discharge into appropriate watercourses, via a silt retention pond					
Boundaries of earthworks should be marked and surrounded by dykes					
Open material storage stockpiles should be covered with tarpaulin or similar fabric to prevent material washing away					
Exposed soil areas should be minimized to reduce the potential for increased siltation and contamination of run-off					
Earthwork final surfaces should be well compacted and subsequent permanent work should be immediately performed					
Use of sediment traps wherever necessary		<u> </u>	<u> </u>	<u> </u>	


Recommended Mitigation Measures	Location and Timing	Who to implement?	When to Implement?	What Requirements or Standards to Achieve?	Status
Maintenance of drainage systems to prevent flooding and overflow					
All temporary drainage pipes and culverts provided to facilitate run-off discharge should be adequately designed to facilitate rapid discharge of storm flows. All sediment traps should be regularly cleaned and maintained. The temporarily diverted drainage should be reinstated to its original condition, when the construction/demolition work is completed.					4
Sand and silt in wash water from wheel washing facilities should be settled out and removed from discharge into temporary drainage pipes or culverts. A section of the haul road between the wheel washing bay and the public road should be paved with backfall to prevent wash water or other site run-off from entering public road drains.					4
Oil interceptors should be provided in the drainage system downstream of any significant oil and grease sources. They should be regularly maintained to prevent the release of oil and grease into the storm water drainage system after accidental spillage. The inceptor should have a bypass to prevent flooding during periods of heavy rain, as specified in <i>ProPECC PN</i> 1/94.	Project site / construction and demolition stages	Contractor	Construction and Demolition stage	ProPECC PN 1/94	N/A
Construction and Demolition Phases - General Construction and Demolition Activities All the solid waste and chemical waste generated on site should be collected, handled and disposed of properly to avoid affecting the water quality of the nearby WSRs. The proper waste management measures are detailed in S.7.7.5-S.7.7.6.	Project site / construction and demolition stages	Contractor	Construction and Demolition stage	ProPECC PN 1/94	1
Construction and Demolition Phases - Sewage Generated from On-site Workforce	Project site / construction and	Contractor	Construction and Demolition stage	ProPECC PN 1/94	١

Recommended Mitigation Measures	Location and Timing	Who to Implement?	When to Implement?	What Requirements or Standards to Achieve?	Status
The sewage from construction work force is expected to be handled by portable chemical toilets if the existing toilets in the Project site are not adequate. Appropriate and adequate portable toilets should be provided by licensed contractors who will be responsible for appropriate disposal and maintenance of these facilities.	demolition stages				
Construction and Demolition Phases - Soil Remediation Activities Mitigation measures will need to be implemented during the currently identified soil remediation activities. If further land contamination investigation results (at CLP secondary substation during Phase I and at locations S1 to S6 during Phase II) confirm the needs for further soil remediation prior to demolition of the Existing Crematorium, relevant water quality mitigation measures (in addition to the current RAP) will need to be identified and implemented by the contractor. In addition, the mitigation measures recommended for minimizing water quality impacts for construction and demolition run-off and drainage as well as for general construction and demolition activities should also be adopted where applicable. In order to avoid impacts on water quality during further remedial works, care will be taken to minimise the mobilisation of sediment during excavation and transport. Measures to be adopted will be based on the recommendations set out in Practice Note for Professional Persons ProPECC PN194 "Construction Site Drainage". The results of the site investigation suggest that there is unlikely to be any requirement for dewalering of	Project site / construction and demolition stages	Contractor	Construction and Demolition stage	ProPECC PN 1/94	1

Recommended Mitigation Measures	Location and Timing	Who to Implement?	When to Implement?	What Requirements or Standards to Achieve?	Status
excavations, since groundwater was not encountered in any of the exploratory holes. The contractor carrying out the remedial works will be required to submit a method statement detailing the measures to be taken to avoid water quality impacts. Typical measures would include: : Carry out the works during the dry season (i.e. October to March) if possible : Use bunds or perimeter drains to prevent run-off water entering excavations : Sheet or otherwise cover excavations whenever rainstorms are expected to occur : Minimise the requirements for stockpiling of material and ensure any stockpiles are covered : Temporary on-site stockpiling of contaminated materials should be avoided, all excavated contaminated soils/materials should be disposed of on a daily basis : Ensure that any discharges to storm drains pass through an appropriate sit trap					

Note: √ × • N/A Compliance of mitigation measure Non-compliance of mitigation measures Non-compliance but rectified by the contractor Not applicable

APPENDIX K EVENT AND ACTION PLANS



Appendix K

Event and Action Plans

Table K.1 Event and Action Plan for Air Quality

	ACTION						
EVENT ET		IEC	AR	CONTRACTOR			
ACTION LEVEL							
Exceedance for one sample	Identify source, investigate the cause of exceedance and propose remedial measures; Inform IEC and AR. Repeat measurement to confirm finding; Increase monitoring frequency to daily, if ET assessment indicates that exceedance is due to contractor's construction works.		Notily Contractor.	Rectify any unacceptable practice; Amend working methods if appropriate.			
Exceedance for two or more consecutive samples	Identify source, investigate the cause of exceedance and propose remedial measures; Inform IEC and AR; Repeat measurements to confirm findings; Increase monitoring frequency to delly, if ET assessment indicates that exceedance is due to contractor's construction works; Discuss with IEC and Contractor on remediations required; If exceedance continues, arrange meeting with IEC and AR; If exceedance stops, cease additional monitoring.	Supervise Implementation of remedial measures.	Confirm receipt of notification of exceedance in writing; Notify Contractor; Ensure remedial measures properly implemented.	Submit proposals for remedia actions to IEC within three working days of notification; Implement the agreed proposals; Amed proposal if appropriate.			
LIMIT LEVEL							
Exceedance for one sample	1. Identify source, Investigate the cause of exceedance and propose remedial measures; Inform IEC, ARI and EPD; 2. Repeat measurement to confirm finding; Increase monitoring frequency to daily, if ET assessment indicates that exceedance is due contractor's construction works; 5. Assess effectiveness of Contractor's remediactions and keep IEC, AR and EPD informed the results.	Supervise implementation of remedial measures.	Confirm receipt of notification of exceedance in writing; Notify Contractor; Ensure remedial measures properly implemented.	Take immediate action to avoid further exceedance; Submit proposals for remedial actions to IEC within three working days of notification; Implement the agreed proposals; 4. Amend proposal If appropriate.			
Exceedance for two or more consecutive samples	Notity Contractor, IEC, AR and EPD; Identity source, Investigate the cause of exceedance and propose remedial measures; Repeat measurement to confirm findings; Increase monitoring frequency to daily, if ET	Discuss amongst AR, ET, and Contractor on the potential remedial actions; Review Contractor's remedial actions whenever necessary to assure their effectiveness and advise the AR accordingly;	Confirm receipt of notification of exceedance in writing; Notify Confractor; In consultation with the IEC, agree with the Contractor on the remedial	Take immediate action to avoid further exceedance; Submit proposals for remediactions to IEC within three working days of notification;			

EVENT	ACTION					
	EŢ	IEC	AR	CONTRACTOR		
	assessment indicates that exceedance is due to contractor's construction works; 5. Carry out analysis of Contractor's working procedures to determine possible mitigation to be implemented; 6. Arrange meeting with IEC and AR to discuss the remedial actions to be taken; 7. Assess effectiveness of Contractor's remedial actions and keep IEC, AR and EPD informed of the results; 8. If exceedance stops, cease additional monitoring.	Supervise the implementation of remedial measures.	measures to be implemented; 4. Ensure remedial measures properly implemented; 5. If exceedance continues, consider what protion of the work is responsible and instruct the Contractor to stop that portion of work until the exceedance is abated.	Implement the agreed proposals; Resubmit proposals it problem still not under control; Stop the relevant portion of works as determined by the AR until the exceedance is abated.		

Table K.2 Event and Action Plan for Construction Noise

EVENT	ACTION							
	ET	IEC	AR	CONTRACTOR				
Action Level	1. Notify Contractor and IEC; 2. Carry out investigation; 3. Report the results of investigation to the IEC and Contractor; 4. Discuss with the Contractor and formulate remedial measures; 5. Increase monitoring frequency to check mitigation effectiveness, if ET assessment indicates that exceedance is due to contractor's construction work.	Review the analysed results submitted by the ET; Review the proposed remedial measures by the Contractor and advise the AR accordingly; Supervise the implementation of remedial measures.	Confirm receipt of notification of exceedance in writing; Notify Contractor; Require Contractor to propose remedial measures for the analysed noise problem; Ensure remedial measures are properly implemented.	Implement noise mitigation proposals.				
Limit Level	1. Notify Contractor, IEC, AR and EPD; 2. Identify source; 3. Repeat measurement to confirm findings; 4. Increase monitoring frequency, if ET assessment indicates that exceedance is due to contractor's construction work; 5. Carry out analysis of Contractor's working procedures to determine possible mitigation to be implemented; 6. Inform IEC, AR and EPD the causes and actions taken for the exceedances; 7. Assess effectiveness of Contractor's remedial actions and keep IEC, AR and EPD informed of the results; 8. If exceedance stops, cease additional	Discuss amongst AR, ET, and Contractor on the potential remedial actions; Review Contractors remedial actions whenever necessary to assure their effectiveness and advise the AR accordingly; Supervise the implementation of remedial measures.	Confirm receipt of notification of failure in writing; Notify Contractor; Require Contractor to propose remedial measures for the analysed noise problem; Ensure remedial measures properly implemented; If exceedance continues, consider what portion of the work is responsible and instruct the Contractor to stop that portion of work until the exceedance is abated.	to avoid further exceedance; 2. Submit proposals for remedial actions to IEC within 3 working days or notification; 3. Implement the agreed proposals; 4. Resubmit proposals if problem still not under control; 5. Stop the relevant portio of works as determined by the AR until the				