





- LEGEND:**
-  BOUNDARY OF THE SITE
  -  EXISTING FACILITIES
  -  EXISTING TREE LOCATION
  -  EXTENT OF TREE SURVEY ZONE

REV. NO.	DESCRIPTION	DATE

**DRAINAGE SERVICES DEPARTMENT,  
THE GOVERNMENT OF THE HONG KONG  
SPECIAL ADMINISTRATIVE REGION**

AGREEMENT NO. CE51/2002 (DS)  
UPGRADING OF PILLAR POINT SEWAGE TREATMENT WORKS  
- INVESTIGATION, DESIGN AND CONSTRUCTION

**APPROXIMATE  
LOCATION OF  
EXISTING TREES** (SHEET 1 OF 2)

**MAUNSELL | AECOM**  
Metcalf & Eddy Ltd.  
茂迪工程顧問有限公司

DRG. NO. **FIGURE 8.9.2**  
圖紙編號

DESIGNED BY 設計	CONTRACT NO. 合約編號	APPROVED 核准人
-------------------	----------------------	-----------------

DRAWN BY 繪圖	STATUS 階段
----------------	--------------

SCALE  
比例 1 : 500

DIMENSIONS ARE IN  
尺寸單位 METRES

© COPYRIGHT RESERVED  
版權所有

2008-11-24

TREE ASSESSMENT SCHEDULE (JANUARY 2006)

LOCATION	SPECIES	QUANTITY (NOS)	RANGE OF TRUNK DIA. (MM)	RANGE OF OVERALL HEIGHT (M)	HEALTH (G/F/P)	FORM (G/F/P)	AMENITY VALUE (H/M/L)	CHANCES OF SURVIVAL AFTER TRANSPLANTING (H/M/L)	RECOMMENDATION		
									RETAIN	TRANSPLANT	FELL
A	BAMBOO	IN CLUMPS	30-700	6-10	F TO G	F	M	M	30	0	0
	BOMBAX CEIBA	1									
	CITRUS MAXIMA	1									
	EUPHORIA LONGAN	1									
	FICUS ELASTICA	5									
	FICUS MICROCARPA	1									
	HIBISCUS TILIACEUS	20									
	DELONIX REGIA	1									
	MORUS ALBA	3									
	LEUCAENA LEUCOCEPHALA	2									
	MURRAYA PANICULATA	3									
PLUMERIA RUBRA	2										
PTEROCARPUS INDICUS	1										
B	BAMBOO	IN CLUMPS	20-500	2-13	G TO P	G TO P	H TO L	M TO L	88	34	#18
	CASTANOPSIS FISSA	1									
	CRATOXYLUM COCHINCHINENSE	3									
	HIBISCUS TILIACEUS	70									
	LEUCAENA LEUCOCEPHALA	40									
	MACARANGA TANARIUS	5									
	MAGNOLIA GRANDIFLORA	13									
	MELIA AZEDARACH	2									
	MICHELIA ALBA	1									
	PLUMERIA RUBRA	3									
	DIMOCARPUS LONGAN	1									
BOMBAX CEIBA	1										
C	CASUARINA EQUISETIFOLIA	35	100-200	5-10	F	F	M TO L	M TO L	28	7	0
D	CASSIA SIAMEA	5	95-210	2-10	G TO F	G TO P	H TO L	M TO L	49	31	0
	CASUARINA EQUISETIFOLIA	15									
	HIBISCUS TILIACEUS	60									
E	CASUARINA EQUISETIFOLIA	10	100-300	6-9	F	F	M	M	21	0	0
	HIBISCUS TILIACEUS	5									
	LEUCAENA LEUCOCEPHALA	5									
	MACARANGA TANARIUS	1									
	MORUS ALBA	1									
F	BOMBAX CEIBA	4	100-400	5-8	F TO P	P	L	M	25	0	0
	HIBISCUS TILIACEUS	20									
	LEUCAENA LEUCOCEPHALA	1									
	TOTAL NO. OF TREES:	343									
								TOTAL NO. OF TREES:	253	72	#18

REV. NO.	DESCRIPTION	DATE
<b>DRAINAGE SERVICES DEPARTMENT, THE GOVERNMENT OF THE HONG KONG SPECIAL ADMINISTRATIVE REGION</b>		
AGREEMENT NO. CE51/2002 (DS) UPGRADING OF PILLAR POINT SEWAGE TREATMENT WORKS - INVESTIGATION, DESIGN AND CONSTRUCTION		
<b>APPROXIMATE LOCATION OF EXISTING TREES</b> (SHEET 2 OF 2)		
<b>MAUNSELL   AECOM</b> Metcalf & Eddy Ltd. 茂迪工程顧問有限公司		
DRG. NO. <b>FIGURE 8.9.2</b> 圖紙編號		
DESIGNED BY 設計	CONTRACT NO. 合約編號	P. ENG. APPROVED 專業人
DRAWN BY 繪圖	SCALE 比例	DATE 日期
DIMENSIONS ARE IN METRES 尺寸單位：公尺		
© COPYRIGHT RESERVED 版權所有		