

消防處  
香港九龍尖沙咀東部康莊道1號  
消防總部大廈



FIRE SERVICES DEPARTMENT  
FIRE SERVICES HEADQUARTERS BUILDING,  
No.1 Hong Chong Road,  
Tsim Sha Tsui East, Kowloon,  
Hong Kong.

本處檔號 OUR REF. : (8) in FSD/GR AI 4/07 II  
來函檔號 YOUR REF. : 8497/0048  
電子郵件 E-mail: : hkfsdenq@hkfsd.gov.hk  
圖文傳真 FAX: : 852-2739 5879  
電 話 TEL NO. : 852-2733 7818

28 November 2008

BMT Asia Pacific Limited  
(Attn. Derek Ho, Associate Director)  
5/F, ING Tower,  
308 Des Voeux Road Central,  
Hong Kong.

*By fax (2815 3377) Only*

Dear Mr. Ho,

Re: Environmental Impact Assessment Study  
Kam Tin Road and Lam Kam Road

---

I refer to your letter dated 14 November 2008.

I have thoroughly checked my record. Please refer to Annex A for details of the incidents at the subject Petrol Filling Stations.

Should you have any questions, you may contact the undersigned on 2733 7818.

Yours faithfully,

(CHUI Man-leung)  
for Director of Fire Services

Incident records for Petrol Filling Stations at Kam Tin Road

1. Sinopec – Pat Heung Petrol Filling Station (Lot No. 2096 in DD 111, Kam Tin Road)

PFS 4
-------

No. of incident : 1  
 Incident No. : F018657  
 Date of incident : 2.4.2002  
 Time of call : 01:49 hrs  
 Nature of incident : Fire incident

2. Sinopec – Shek Kong Petrol Filling Station (Lot No. 811 in DD 110, Kam Tin Road)

PFS 2
-------

No. of incident : 1  
 Incident No. : F008778  
 Date of incident : 12.2.2001  
 Time of call : 17:49 hrs  
 Nature of incident : Gas Leakage incident

3. ESSO Petrol Filling Station (Lot No. 812 in DD 110, Kam Tin Road)

PFS 1*
--------

No. of incident : Nil

4. Caltex Petrol Filling Station (Kam Tin Road)

PFS 3
-------

No. of incident : Nil

Note:

\* As confirmed by site operator, the name of petrol filling station is Feoso Oil Limited not ESSO Petrol Filling Station

10 March 2009  
Our Ref: 8497/0082

By Post and Fax (2739 5879)

Fire Services Department,  
Fire Services Headquarters Management Group,  
9<sup>th</sup> Floor, Fire Services HQ Building,  
1 Hong Chong Road,  
Tsim Sha Tsui East, Kowloon.

Attention: Mr. Tsang Wing Hung

Dear Mr. Tsang,

**AGREEMENT NO. WD 7/2007  
UPGRADING OF REMAINING SECTIONS OF KAM TIN ROAD AND LAM KAM ROAD  
ENVIRONMENTAL IMPACT ASSESSMENT STUDY**

With reference to your letter (Ref.: (8) in FSD/GR/ AI 4/07 II) dated 28 November 2008 providing the incident records for the following existing petrol filling stations:

1. Sinopec – Pat Heung Petrol Filling Station (Lot No. 2096 in DD111, Kam Tin Road, Pat Heung, Yuen Long);
2. Sinopec - Shek Kong Petrol Filling Station (Lot No. 811 in DD110, Kam Tin Road, Shek Kong, Yuen Long);
3. Feoso Oil Limited (Lot No. 812 in DD110, Kam Tin Road, Shek Kong, Yuen Long); and
4. Caltex Petrol Filling Station (Kam Tin Road, Shek Kong, Yuen Long).

Apart from the 4 existing stations, it is also identified there is a closed petrol filling station located near the junction of Lam Kam Road and Kam Tin Road (as shown in the attached figure). We've checked against the historical aerial photographs from Lands Department and estimated the operation period of each petrol filling stations and summarized in the following table:

<b>Petrol Filling Station</b>	<b>Operation Period</b>
1. Sinopec – Pat Heung Petrol Filling Station	After 1990 to current
2. Sinopec - Shek Kong Petrol Filling Station	After 1988 to current
3. Feoso Oil Limited	After 1988 to current
4. Caltex Petrol Filling Station	After 1988 to current
5. Closed Petrol Filling Station near the junction of Lam Kam Road and Kam Tin Road	After 1949 to 2008

As requested by the EPD, it would be grateful if you could provide us the oil leakage incident records (if any) for the closed petrol filling station and confirm whether the incident records provided for all 5 petrol filling stations cover above mentioned operation period.

Should you have any queries, please do not hesitate to contact my colleague Willie Wong at 2241 9821.


Yours sincerely  
**BMT Asia Pacific Limited**



Derek Ho  
Associate Director

cc: HyD – Jacky Wu  
Mannings (Asia) Consultants Ltd. – Simon Ng

(F: 3188 3418) (fax only)  
(F: 3168 2022) (fax only)



Caltex PFS

Feoso Oil  
Limited - PFS

Sinopec - Shek  
Kong PFS




Sinopec - Pat  
Huong PFS

PAI WANG

PAI WANG

LEUNG KA  
TUNG



消防處  
香港九龍尖沙咀東部康莊道 1 號  
消防總部大廈



FIRE SERVICES DEPARTMENT  
FIRE SERVICES HEADQUARTERS BUILDING,  
No.1 Hong Chong Road,  
Tsim Sha Tsui East, Kowloon,  
Hong Kong.

本處檔號 OUR REF. : (89) in FSD/GR AI 4/07 II  
來函檔號 YOUR REF. : 8497/0082  
電訊掛號 Telex :  
圖文傳真 FAX: : 852-2739 5879  
電 話 TEL NO. : 852-2733 7741

24 March 2009

BMT Asia Pacific Ltd.  
5/F, ING Tower,  
308 Des Voeux Road Central  
Hong Kong.

Dear Sir,

**Upgrading of Remaining Sections of Kam Tin Road & Lam Kam Road**  
**Request information for Environmental Impact Assessment Study**

I refer to your letter regarding the captioned subject and reply below in response to your enquiries.

1. There is no record of oil leakage incidents for the closed petrol filling station.
2. There is no record of incidents in connection with the 5 petrol filling stations with the given conditions of your request.

Should you have any questions, please feel free to contact the undersigned on 2733 7741.

Yours faithfully,

(TSANG Wing-hung)  
for Director of Fire Services