

Figure 9.18: Side Scan Sonar Data showing construction debris associated with Kwai Chung Submarine Outfall and Tsing Yi Submarine Outfall

Mott MacDonald Hong Kong Limited

This document should not be relied on or used in circumstances other than those for which it was originally prepared and for which Mott MacDonaid Hong Kong Limite was commissioned. Mott MacDonaid Limited accepts no responsibility for this document to any other party other than the percent by whom it was commissioned. Map / Image data: reproduced with permission of the Director of Lancia, the Operational Hong Kong SAR, Agerment 10, 63 / 2001

F 2032						
2031						
2030						
2825						
8						
202	Rev Date	Drawn	Description			Chk'd App'd
	Mc	ott Ma	cDong		0/F Two Landmar 00 How Ming Stre wun Tong, Kowlo iong Kong +852 2828 5757 +852 2827 1823 / www.motimac.ci	n
K021	Client THE GOVERNMENT OF THE HONG KONG SPECIAL ADMINISTRATIVE REGION CIVIL ENGINEERING AND DEVELOPMENT DEPARTMENT					
2025	EDI	Þ	-	-	PARTMENT	
2025	KWAI	AI VIDING S TSING (-	NT WATE	R DEPTI	
2025	PROV KWAI APPR	/IDING S TSING (OACH C	UFFICIEI	NT WATE	R DEPTI N AND IT	S
2,025	PROV KWAI APPR	/IDING S TSING (OACH C	UFFICIEI CONTAIN HANNEL	NT WATE	R DEPTI N AND IT	S