



Typical Road Improvement Works at Section 8 - 8



Existing Road Condition at Section 8 - 8

Chainage 2+100 to 2+437

Figure 3.21