

NOTES :

Instantaneous Single Tank Failure - Unconfined Pool Fire (Sinopec HK Oil Terminal Chai Wan)

		<i>Ignition Prob.</i>	<i>Event Outcome</i>	<i>Outcome Probability</i>
1.00E+0	Oil Release	yes 0.004	Unconfined Pool fire / Bund pool fire	4.00E-3
		no 0.996	Unignited Release	9.96E-1
				1.00

Instantaneous Single Tank Failure - Bund Pool Fire (Sinopec HK Oil Terminal Chai Wan)

		<i>Ignition Prob.</i>	<i>Event Outcome</i>	<i>Outcome Probability</i>
1.00E+0	Oil Release	yes 0.004	Unconfined Pool fire / Bund pool fire	4.00E-3
		no 0.996	Unignited Release	9.96E-1
				1.00

Instantaneous Single Tank Failure - Sea Pool Fire (Sinopec HK Oil Terminal Chai Wan)

		<i>Ignition Prob.</i>	<i>Event Outcome</i>	<i>Outcome Probability</i>
1.00E+0	Oil Release	yes 0.008	Sea Pool Fire	8.00E-3
		no 0.992	Unignited Release	9.92E-1
				1.00

Consultant



Allied Environmental Consultants Limited
ACOUSTICIANS & ENVIRONMENTAL ENGINEERS

Project No. : 1158

File Name :

Project :
Chai Wan Government Complex and Vehicle Depot

Drawing Title :
Event Trees for Instantaneous Single Tank Failure (Sinopec HK Oil Terminal)

Drawing No : Figure 10.8 Revision : 3

Scale : NTS Date : May 2015

DO NOT SCALE OFF DRAWING. THIS DRAWING IS NOT FOR CONSTRUCTION PURPOSES UNLESS EXPRESSLY STATED. ALL RIGHTS RESERVED AND REPRODUCTION IN ANY FORM MUST BE APPROVED BY ALLIED ENVIRONMENTAL CONSULTANTS LIMITED.