APPENDIX 7B Representative Photos of Existing Site Condition

July 2021 Binnies






Photo 1 - Existing Slope for the Proposed Ancillary Building



Photo 2 – Existing Slope to the South of the Proposed Ancillary Building Currently under Landslip Prevention and Mitigation Works



Photo 3 - Lion Rock Park Transit Nursery



Photo 4 - Temporary Storage of Nursery Trees/Plants in Lion Rock Park Transit Nursery



Photo 5 - Store Room in Lion Rock Park Transit Nursery with Paved Floor



Photo 6 - Paved Open Area in Lion Rock Park Transit Nursery



Photo 7 - Vacant Land for Proposed Temporary Storage Area







Photo 9 - Chuk Yuen Road






Photo 11 - Tsz Wan Shan Road



Photo 12 - Lung Fung Street



Photo 13 - Sheung Fung Street