

Date	Inspector	Inspector Area	Responsible Person	Relevant Problem	Remarks
1/1/06	J. Ma	Production Line – Soldering	F. Li	Smell of volatile chemicals was observed in the soldering production line.	It was due to the malfunctioning of ventilation system near the soldering production line. CAR has already been issued and asked relevant departments to take corrective and preventive actions.