

Date	Inspected by	Inspection area	Responsible staff	Finding	Remark
1/1/2006	H. Wang	Production – Die-casting	Y. Fang	Smell of volatile chemicals was observed in the de-casting process	<p>It was due to the malfunctioning of ventilation system near the de-casting process.</p> <p>CAR has already been issued and asked relevant departments to take corrective and preventive actions.</p>