

Project : SCL - Tai Wai to Hung Hom Section  
 Title : Monthly Contribution (Mitigated Scenario)  
 Subtitle : Ma Chai Hang Ventilation Building

Table 1 - Noise Contribution from Sources at Jan 2012

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	0	0	0	0	0
DIH-20-1	0	0	0	0	0	0	0	0	0
DIH-21-1	0	0	0	0	0	0	0	0	0
DIH-22-1	0	0	0	0	0	0	0	0	0
DIH-23-1	0	0	0	0	0	0	0	0	0

Table 2 - Noise Contribution from Sources at Feb 2012

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	0	0	0	0	0
DIH-20-1	0	0	0	0	0	0	0	0	0
DIH-21-1	0	0	0	0	0	0	0	0	0
DIH-22-1	0	0	0	0	0	0	0	0	0
DIH-23-1	0	0	0	0	0	0	0	0	0

Table 3 - Noise Contribution from Sources at March 2012

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	0	0	0	0	0
DIH-20-1	0	0	0	0	0	0	0	0	0
DIH-21-1	0	0	0	0	0	0	0	0	0
DIH-22-1	0	0	0	0	0	0	0	0	0
DIH-23-1	0	0	0	0	0	0	0	0	0

Table 4 - Noise Contribution from Sources at Apr 2012

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	0	0	0	0	0
DIH-20-1	0	0	0	0	0	0	0	0	0
DIH-21-1	0	0	0	0	0	0	0	0	0
DIH-22-1	0	0	0	0	0	0	0	0	0
DIH-23-1	0	0	0	0	0	0	0	0	0

Table 5 - Noise Contribution from Sources at May 2012

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	0	0	0	0	0
DIH-20-1	0	0	0	0	0	0	0	0	0
DIH-21-1	0	0	0	0	0	0	0	0	0
DIH-22-1	0	0	0	0	0	0	0	0	0
DIH-23-1	0	0	0	0	0	0	0	0	0

Table 6 - Noise Contribution from Sources at Jun 2012

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	0	0	0	0	52
DIH-20-1	0	0	0	0	0	0	0	0	55
DIH-21-1	0	0	0	0	0	0	0	0	56
DIH-22-1	0	0	0	0	0	0	0	0	57
DIH-23-1	0	0	0	0	0	0	0	0	58

Project : SCL - Tai Wai to Hung Hom Section  
 Title : Monthly Contribution (Mitigated Scenario)  
 Subtitle : Ma Chai Hang Ventilation Building

Table 7 - Noise Contribution from Sources at Jul 2012

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	0	0	0	0	52
DIH-20-1	0	0	0	0	0	0	0	0	55
DIH-21-1	0	0	0	0	0	0	0	0	56
DIH-22-1	0	0	0	0	0	0	0	0	57
DIH-23-1	0	0	0	0	0	0	0	0	58

Table 8 - Noise Contribution from Sources at Aug 2012

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	0	0	0	0	52
DIH-20-1	0	0	0	0	0	0	0	0	55
DIH-21-1	0	0	0	0	0	0	0	0	56
DIH-22-1	0	0	0	0	0	0	0	0	57
DIH-23-1	0	0	0	0	0	0	0	0	58

Table 9 - Noise Contribution from Sources at Sept 2012

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	0	0	0	0	52
DIH-20-1	0	0	0	0	0	0	0	0	55
DIH-21-1	0	0	0	0	0	0	0	0	56
DIH-22-1	0	0	0	0	0	0	0	0	57
DIH-23-1	0	0	0	0	0	0	0	0	58

Table10 - Noise Contribution from Sources at Oct 2012

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	0	0	0	0	52
DIH-20-1	0	0	0	0	0	0	0	0	55
DIH-21-1	0	0	0	0	0	0	0	0	56
DIH-22-1	0	0	0	0	0	0	0	0	57
DIH-23-1	0	0	0	0	0	0	0	0	58

Table 11 - Noise Contribution from Sources at Nov 2012

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	0	0	0	0	52
DIH-20-1	0	0	0	0	0	0	0	0	55
DIH-21-1	0	0	0	0	0	0	0	0	56
DIH-22-1	0	0	0	0	0	0	0	0	57
DIH-23-1	0	0	0	0	0	0	0	0	58

Table 12 - Noise Contribution from Sources at Dec 2012

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	0	0	0	0	52
DIH-20-1	0	0	0	0	0	0	0	0	55
DIH-21-1	0	0	0	0	0	0	0	0	56
DIH-22-1	0	0	0	0	0	0	0	0	57
DIH-23-1	0	0	0	0	0	0	0	0	58

Project : SCL - Tai Wai to Hung Hom Section  
 Title : Monthly Contribution (Mitigated Scenario)  
 Subtitle : Ma Chai Hang Ventilation Building

Table 13 - Noise Contribution from Sources at Jan 2013

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	62	0	0	0	0	0	0	0	0
DIH-20-1	63	0	0	0	0	0	0	0	0
DIH-21-1	66	0	0	0	0	0	0	0	0
DIH-22-1	64	0	0	0	0	0	0	0	0
DIH-23-1	63	0	0	0	0	0	0	0	0

Table 14 - Noise Contribution from Sources at Feb 2013

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	61	0	0	0	0	0	0	0	0
DIH-20-1	62	0	0	0	0	0	0	0	0
DIH-21-1	65	0	0	0	0	0	0	0	0
DIH-22-1	63	0	0	0	0	0	0	0	0
DIH-23-1	62	0	0	0	0	0	0	0	0

Table 15 - Noise Contribution from Sources at March 2013

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	59	0	0	0	0	0	0	0
DIH-20-1	0	59	0	0	0	0	0	0	0
DIH-21-1	0	62	0	0	0	0	0	0	0
DIH-22-1	0	60	0	0	0	0	0	0	0
DIH-23-1	0	59	0	0	0	0	0	0	0

Table 16 - Noise Contribution from Sources at Apr 2013

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	57	0	0	0	0	0	0	0
DIH-20-1	0	58	0	0	0	0	0	0	0
DIH-21-1	0	61	0	0	0	0	0	0	0
DIH-22-1	0	58	0	0	0	0	0	0	0
DIH-23-1	0	57	0	0	0	0	0	0	0

Table 17 - Noise Contribution from Sources at May 2013

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	57	0	0	0	0	0	0	0
DIH-20-1	0	58	0	0	0	0	0	0	0
DIH-21-1	0	61	0	0	0	0	0	0	0
DIH-22-1	0	58	0	0	0	0	0	0	0
DIH-23-1	0	57	0	0	0	0	0	0	0

Table 18 - Noise Contribution from Sources at Jun 2013

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	57	0	0	0	0	0	0	0
DIH-20-1	0	58	0	0	0	0	0	0	0
DIH-21-1	0	61	0	0	0	0	0	0	0
DIH-22-1	0	58	0	0	0	0	0	0	0
DIH-23-1	0	57	0	0	0	0	0	0	0

Project : SCL - Tai Wai to Hung Hom Section  
 Title : Monthly Contribution (Mitigated Scenario)  
 Subtitle : Ma Chai Hang Ventilation Building

Table 19 - Noise Contribution from Sources at Jul 2013

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	56	0	0	0	0	0	0
DIH-20-1	0	0	57	0	0	0	0	0	0
DIH-21-1	0	0	60	0	0	0	0	0	0
DIH-22-1	0	0	58	0	0	0	0	0	0
DIH-23-1	0	0	57	0	0	0	0	0	0

Table 20 - Noise Contribution from Sources at Aug 2013

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	63	53	0	0	0	0
DIH-20-1	0	0	0	64	53	0	0	0	0
DIH-21-1	0	0	0	67	56	0	0	0	0
DIH-22-1	0	0	0	64	54	0	0	0	0
DIH-23-1	0	0	0	63	53	0	0	0	0

Table 21 - Noise Contribution from Sources at Sept 2013

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	63	53	0	0	0	0
DIH-20-1	0	0	0	64	53	0	0	0	0
DIH-21-1	0	0	0	67	56	0	0	0	0
DIH-22-1	0	0	0	64	54	0	0	0	0
DIH-23-1	0	0	0	63	53	0	0	0	0

Table 22 - Noise Contribution from Sources at Oct 2013

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	58	0	0	0	0
DIH-20-1	0	0	0	0	59	0	0	0	0
DIH-21-1	0	0	0	0	62	0	0	0	0
DIH-22-1	0	0	0	0	60	0	0	0	0
DIH-23-1	0	0	0	0	59	0	0	0	0

Table 23 - Noise Contribution from Sources at Nov 2013

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	58	0	0	0	0
DIH-20-1	0	0	0	0	59	0	0	0	0
DIH-21-1	0	0	0	0	62	0	0	0	0
DIH-22-1	0	0	0	0	60	0	0	0	0
DIH-23-1	0	0	0	0	59	0	0	0	0

Table 24 - Noise Contribution from Sources at Dec 2013

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	58	0	0	0	0
DIH-20-1	0	0	0	0	59	0	0	0	0
DIH-21-1	0	0	0	0	62	0	0	0	0
DIH-22-1	0	0	0	0	60	0	0	0	0
DIH-23-1	0	0	0	0	59	0	0	0	0

Project : SCL - Tai Wai to Hung Hom Section  
 Title : Monthly Contribution (Mitigated Scenario)  
 Subtitle : Ma Chai Hang Ventilation Building

Table 25 - Noise Contribution from Sources at Jan 2014

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	58	0	0	0	0
DIH-20-1	0	0	0	0	59	0	0	0	0
DIH-21-1	0	0	0	0	62	0	0	0	0
DIH-22-1	0	0	0	0	60	0	0	0	0
DIH-23-1	0	0	0	0	59	0	0	0	0

Table 26 - Noise Contribution from Sources at Feb 2014

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	58	0	0	0	0
DIH-20-1	0	0	0	0	59	0	0	0	0
DIH-21-1	0	0	0	0	62	0	0	0	0
DIH-22-1	0	0	0	0	60	0	0	0	0
DIH-23-1	0	0	0	0	59	0	0	0	0

Table 27 - Noise Contribution from Sources at Mar 2014

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	58	0	0	0	0
DIH-20-1	0	0	0	0	59	0	0	0	0
DIH-21-1	0	0	0	0	62	0	0	0	0
DIH-22-1	0	0	0	0	60	0	0	0	0
DIH-23-1	0	0	0	0	59	0	0	0	0

Table 28 - Noise Contribution from Sources at Apr 2014

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	58	0	0	0	0
DIH-20-1	0	0	0	0	59	0	0	0	0
DIH-21-1	0	0	0	0	62	0	0	0	0
DIH-22-1	0	0	0	0	60	0	0	0	0
DIH-23-1	0	0	0	0	59	0	0	0	0

Table 29 - Noise Contribution from Sources at May 2014

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	58	0	0	0	0
DIH-20-1	0	0	0	0	59	0	0	0	0
DIH-21-1	0	0	0	0	62	0	0	0	0
DIH-22-1	0	0	0	0	60	0	0	0	0
DIH-23-1	0	0	0	0	59	0	0	0	0

Table 30 - Noise Contribution from Sources at June 2014

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	58	0	0	0	0
DIH-20-1	0	0	0	0	59	0	0	0	0
DIH-21-1	0	0	0	0	62	0	0	0	0
DIH-22-1	0	0	0	0	60	0	0	0	0
DIH-23-1	0	0	0	0	59	0	0	0	0

Project : SCL - Tai Wai to Hung Hom Section  
 Title : Monthly Contribution (Mitigated Scenario)  
 Subtitle : Ma Chai Hang Ventilation Building

Table 31 - Noise Contribution from Sources at July 2014

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	58	0	0	0	0
DIH-20-1	0	0	0	0	59	0	0	0	0
DIH-21-1	0	0	0	0	62	0	0	0	0
DIH-22-1	0	0	0	0	60	0	0	0	0
DIH-23-1	0	0	0	0	59	0	0	0	0

Table 32 - Noise Contribution from Sources at Aug 2014

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	58	0	0	0	0
DIH-20-1	0	0	0	0	59	0	0	0	0
DIH-21-1	0	0	0	0	62	0	0	0	0
DIH-22-1	0	0	0	0	60	0	0	0	0
DIH-23-1	0	0	0	0	59	0	0	0	0

Table 33 - Noise Contribution from Sources at Sept 2014

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	58	0	0	0	0
DIH-20-1	0	0	0	0	59	0	0	0	0
DIH-21-1	0	0	0	0	62	0	0	0	0
DIH-22-1	0	0	0	0	60	0	0	0	0
DIH-23-1	0	0	0	0	59	0	0	0	0

Table 34 - Noise Contribution from Sources at Oct 2014

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	58	0	0	0	0
DIH-20-1	0	0	0	0	59	0	0	0	0
DIH-21-1	0	0	0	0	62	0	0	0	0
DIH-22-1	0	0	0	0	60	0	0	0	0
DIH-23-1	0	0	0	0	59	0	0	0	0

Table 35 - Noise Contribution from Sources at Nov 2014

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	58	0	0	0	0
DIH-20-1	0	0	0	0	59	0	0	0	0
DIH-21-1	0	0	0	0	62	0	0	0	0
DIH-22-1	0	0	0	0	60	0	0	0	0
DIH-23-1	0	0	0	0	59	0	0	0	0

Table 36 - Noise Contribution from Sources at Dec 2014

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	58	0	0	0	0
DIH-20-1	0	0	0	0	59	0	0	0	0
DIH-21-1	0	0	0	0	62	0	0	0	0
DIH-22-1	0	0	0	0	60	0	0	0	0
DIH-23-1	0	0	0	0	59	0	0	0	0

Project : SCL - Tai Wai to Hung Hom Section  
 Title : Monthly Contribution (Mitigated Scenario)  
 Subtitle : Ma Chai Hang Ventilation Building

Table 37 - Noise Contribution from Sources at Jan 2015

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	58	0	0	0	0
DIH-20-1	0	0	0	0	59	0	0	0	0
DIH-21-1	0	0	0	0	62	0	0	0	0
DIH-22-1	0	0	0	0	60	0	0	0	0
DIH-23-1	0	0	0	0	59	0	0	0	0

Table 38 - Noise Contribution from Sources at Feb 2015

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	58	0	0	0	0
DIH-20-1	0	0	0	0	59	0	0	0	0
DIH-21-1	0	0	0	0	62	0	0	0	0
DIH-22-1	0	0	0	0	60	0	0	0	0
DIH-23-1	0	0	0	0	59	0	0	0	0

Table 39 - Noise Contribution from Sources at Mar 2015

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	58	0	0	0	0
DIH-20-1	0	0	0	0	59	0	0	0	0
DIH-21-1	0	0	0	0	62	0	0	0	0
DIH-22-1	0	0	0	0	60	0	0	0	0
DIH-23-1	0	0	0	0	59	0	0	0	0

Table 40 - Noise Contribution from Sources at Apr 2015

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	58	0	0	0	0
DIH-20-1	0	0	0	0	59	0	0	0	0
DIH-21-1	0	0	0	0	62	0	0	0	0
DIH-22-1	0	0	0	0	60	0	0	0	0
DIH-23-1	0	0	0	0	59	0	0	0	0

Table 41 - Noise Contribution from Sources at May 2015

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	58	0	0	0	0
DIH-20-1	0	0	0	0	59	0	0	0	0
DIH-21-1	0	0	0	0	62	0	0	0	0
DIH-22-1	0	0	0	0	60	0	0	0	0
DIH-23-1	0	0	0	0	59	0	0	0	0

Table 42 - Noise Contribution from Sources at Jun 2015

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	58	0	0	0	0
DIH-20-1	0	0	0	0	59	0	0	0	0
DIH-21-1	0	0	0	0	62	0	0	0	0
DIH-22-1	0	0	0	0	60	0	0	0	0
DIH-23-1	0	0	0	0	59	0	0	0	0

Project : SCL - Tai Wai to Hung Hom Section  
 Title : Monthly Contribution (Mitigated Scenario)  
 Subtitle : Ma Chai Hang Ventilation Building

Table 43 - Noise Contribution from Sources at July 2015

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	58	0	0	0	0
DIH-20-1	0	0	0	0	59	0	0	0	0
DIH-21-1	0	0	0	0	62	0	0	0	0
DIH-22-1	0	0	0	0	60	0	0	0	0
DIH-23-1	0	0	0	0	59	0	0	0	0

Table 44 - Noise Contribution from Sources at Aug 2015

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	58	0	0	0	0
DIH-20-1	0	0	0	0	59	0	0	0	0
DIH-21-1	0	0	0	0	62	0	0	0	0
DIH-22-1	0	0	0	0	60	0	0	0	0
DIH-23-1	0	0	0	0	59	0	0	0	0

Table 45 - Noise Contribution from Sources at Sept 2015

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	58	0	0	0	0
DIH-20-1	0	0	0	0	59	0	0	0	0
DIH-21-1	0	0	0	0	62	0	0	0	0
DIH-22-1	0	0	0	0	60	0	0	0	0
DIH-23-1	0	0	0	0	59	0	0	0	0

Table 46 - Noise Contribution from Sources at Oct 2015

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	58	0	0	0	0
DIH-20-1	0	0	0	0	59	0	0	0	0
DIH-21-1	0	0	0	0	62	0	0	0	0
DIH-22-1	0	0	0	0	60	0	0	0	0
DIH-23-1	0	0	0	0	59	0	0	0	0

Table 47 - Noise Contribution from Sources at Nov 2015

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	58	0	0	0	0
DIH-20-1	0	0	0	0	59	0	0	0	0
DIH-21-1	0	0	0	0	62	0	0	0	0
DIH-22-1	0	0	0	0	60	0	0	0	0
DIH-23-1	0	0	0	0	59	0	0	0	0

Table 48 - Noise Contribution from Sources at Dec 2015

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	0	0	0	0	0
DIH-20-1	0	0	0	0	0	0	0	0	0
DIH-21-1	0	0	0	0	0	0	0	0	0
DIH-22-1	0	0	0	0	0	0	0	0	0
DIH-23-1	0	0	0	0	0	0	0	0	0



Project : SCL - Tai Wai to Hung Hom Section  
 Title : Monthly Contribution (Mitigated Scenario)  
 Subtitle : Ma Chai Hang Ventilation Building

Table 49 - Noise Contribution from Sources at Jan 2016

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	60	0	0	0	0
DIH-20-1	0	0	0	0	61	0	0	0	0
DIH-21-1	0	0	0	0	64	0	0	0	0
DIH-22-1	0	0	0	0	61	0	0	0	0
DIH-23-1	0	0	0	0	60	0	0	0	0

Table 50 - Noise Contribution from Sources at Feb 2016

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	60	0	0	0	0
DIH-20-1	0	0	0	0	61	0	0	0	0
DIH-21-1	0	0	0	0	64	0	0	0	0
DIH-22-1	0	0	0	0	61	0	0	0	0
DIH-23-1	0	0	0	0	60	0	0	0	0

Table 51 - Noise Contribution from Sources at Mar 2016

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	60	0	0	0	0
DIH-20-1	0	0	0	0	61	0	0	0	0
DIH-21-1	0	0	0	0	64	0	0	0	0
DIH-22-1	0	0	0	0	61	0	0	0	0
DIH-23-1	0	0	0	0	60	0	0	0	0

Table 52 - Noise Contribution from Sources at Apr 2016

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	52	0	0	0	0
DIH-20-1	0	0	0	0	53	0	0	0	0
DIH-21-1	0	0	0	0	56	0	0	0	0
DIH-22-1	0	0	0	0	53	0	0	0	0
DIH-23-1	0	0	0	0	52	0	0	0	0

Table 53 - Noise Contribution from Sources at May 2016

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	52	0	0	0	0
DIH-20-1	0	0	0	0	53	0	0	0	0
DIH-21-1	0	0	0	0	56	0	0	0	0
DIH-22-1	0	0	0	0	53	0	0	0	0
DIH-23-1	0	0	0	0	52	0	0	0	0

Table 54 - Noise Contribution from Sources at June 2016

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	0	59	0	0	0
DIH-20-1	0	0	0	0	0	60	0	0	0
DIH-21-1	0	0	0	0	0	62	0	0	0
DIH-22-1	0	0	0	0	0	60	0	0	0
DIH-23-1	0	0	0	0	0	59	0	0	0

Project : SCL - Tai Wai to Hung Hom Section  
 Title : Monthly Contribution (Mitigated Scenario)  
 Subtitle : Ma Chai Hang Ventilation Building

Table 55 - Noise Contribution from Sources at July 2016

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	0	59	0	0	0
DIH-20-1	0	0	0	0	0	60	0	0	0
DIH-21-1	0	0	0	0	0	62	0	0	0
DIH-22-1	0	0	0	0	0	60	0	0	0
DIH-23-1	0	0	0	0	0	59	0	0	0

Table 56 - Noise Contribution from Sources at Aug 2016

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	0	0	57	0	0
DIH-20-1	0	0	0	0	0	0	58	0	0
DIH-21-1	0	0	0	0	0	0	61	0	0
DIH-22-1	0	0	0	0	0	0	59	0	0
DIH-23-1	0	0	0	0	0	0	58	0	0

Table 57 - Noise Contribution from Sources at Sept 2016

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	0	0	0	58	0
DIH-20-1	0	0	0	0	0	0	0	59	0
DIH-21-1	0	0	0	0	0	0	0	61	0
DIH-22-1	0	0	0	0	0	0	0	59	0
DIH-23-1	0	0	0	0	0	0	0	58	0

Table 58 - Noise Contribution from Sources at Oct 2016

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	0	0	0	58	0
DIH-20-1	0	0	0	0	0	0	0	59	0
DIH-21-1	0	0	0	0	0	0	0	61	0
DIH-22-1	0	0	0	0	0	0	0	59	0
DIH-23-1	0	0	0	0	0	0	0	58	0

Table 59 - Noise Contribution from Sources at Nov 2016

NSRs	Work Site								
	S1	S2	S3	S4	S5	S6	S7	S8	S9
DIH-4-2	0	0	0	0	0	0	0	0	0
DIH-20-1	0	0	0	0	0	0	0	0	0
DIH-21-1	0	0	0	0	0	0	0	0	0
DIH-22-1	0	0	0	0	0	0	0	0	0
DIH-23-1	0	0	0	0	0	0	0	0	0