



# Societal Risk for KTD Project Kerry DG Godown - Overall



\* Risk within this region should be reduced to as low as reasonably practicable


## Societal Risk for KTD Project Kerry DG Godown - LPG



The risk is too low to be shown on the graph.


\* Risk within this region should be reduced to as low as reasonably practicable

# Societal Risk for KTD Project Kerry DG Godown - Other Flammables




\* Risk within this region should be reduced to as low as reasonably practicable

# Societal Risk for KTD Project Kerry DG Godown - Toxic Gases



\* Risk within this region should be reduced to as low as reasonably practicable

## Societal Risk for KTD Project Kerry DG Godown - Warehouse Fire



\* Risk within this region should be reduced  
to as low as reasonably practicable