Highways Department

Agreement No. HMW 5/2009 (EP) Traffic Improvements to Tuen **Mun Road Town Centre** Section

Monthly Environmental Monitoring and Audit Report - April 2012

Final

Certified by Environmental Team Leader Coleman Ng Ove Arup & Partners Hong Kong Ltd

Verified by Independent Environmental Checker David Yeung ENVIRON HK Limited

Contents

Exec	utive Sum	mary	Page 1
1		nmental Status	3
	1.1	Project Background	3
	1.2	Construction Programme	3
	1.3	Work Undertaken During the Reporting Month	3
	1.4	Project Area, Sensitive Receivers and Environmental Monitoring locations	4
	1.5	Impact Monitoring Schedule	5
	1.6	Status of Environmental Licensing and Permitting	5
	1.7	Purpose of the Report	6
2	Implen	nentation Status	8
	2.1	Implementation Status of Mitigation Measures	8
	2.2	Updated Implementation Schedule	8
3	Air Mo	nitoring	9
	3.1	Air Monitoring Requirements	9
	3.2	Air Monitoring Methodology	10
	3.3	Monitoring Results and Observations	11
4	Noise I	Monitoring	12
	4.1	Noise Monitoring Requirements	12
	4.2	Noise Monitoring Methodology	13
	4.3	Monitoring Results and Observations	14
5	Landso	cape and Visual Monitoring	17
	5.1	Landscape and Visual Monitoring Requirements	17
	5.2	Audit Results	18
	5.3	Implementation Status of Consultation Phase Landscape and Visual Mitiga Measures	ition 19
	5.4	Recommendations, Corrective Actions and Outstanding Issues	19
6	Waste	Disposal	20
7	Enviro	nmental Performance	20
	7.1	Environmental Site Inspection	20
	7.2	Complaint Record	21
	7.3	Notification of Summons and Successful Prosecution	23
	7.4	Review of Reasons of Non-Compliance	23
8	Future	Key Issues	23
	8.1	Key Issues for the Coming Month	23
	8.2	Environmental Monitoring Program for the Coming Month	23
9	Conclu	sions and Recommendations	23

	9.1	Conclusions	23
	9.2	Recommendations	24
10	Referen	ce	24
	endices		
Appen	dix A		
Constr	uction Pro	ogramme	
Appen	dix B		
Enviro	nmental M	Ionitoring Programme in the Reporting Month	
Appen	dix C		
Implen	nentation S	Schedule of Mitigation Measures	
Appen	dix D		
Calibra	ation Certif	ficates and Spreadsheets of Air Monitoring Equipments	
Appen	dix E		
Impact	Air Monite	oring Results	
Appen	dix F		
Wind E	Data		
Appen	dix G		
Calibra	ation Certif	ficates of Noise Monitoring Equipments	
Appen	dix H		
Impact	Noise Mo	onitoring Results	
Appen	dix I		
Landso	cape Sum	mary Report	
Appen	dix J		
Month	ly Summa	ry Waste Flow Table	

Appendix K

Environmental Monitoring Programme for Coming Month

Executive Summary

This is the twenty-first monthly Environmental Monitoring and Audit (EM&A) report prepared by Ove Arup & Partners Hong Kong Limited (Arup), the designated Environmental Team (ET), for the Project "Traffic Improvement to Tuen Mun Road Town Centre Section". This report presents the results of EM&A works conducted in the month of April 2012 (1 to 30 April 2012).

In the reporting month, the following activities took place for the Project:

- Site clearance
- Footbridge construction;
- Noise barrier construction;
- Tree felling and transplanting;
- · Temporary footbridge construction;
- Pilling works;
- · Ground investigation; and
- Underground utilities and drainage diversion.

Monitoring of 24-hour Total Suspended Particulates (TSP) and noise during non-restricted hours was performed and the results were checked and reviewed. Site audits were conducted on weekly basis. The implementation of the environmental mitigation measures, Event and Action Plans were checked.

Impact monitoring was carried out at 6 air quality sensitive receiver (SR) and 6 noise SRs during the reporting month.

Environmental Monitoring Works – Breaches of Action and Limit Levels

Air Quality

All measured 24-hour TSP concentrations in the reporting month were below the Action and Limit (AL) Levels.

Noise

No limit level exceedance for noise measurement during non-restricted hours was recorded in the reporting month.

No Action Level exceedance of construction noise was recorded in the reporting month.

Construction works were carried out during the restricted hours, the conditions stipulated in CNPs of related construction works were strictly followed by the Contractor. No non-compliance was recorded.

Landscape and Visual Audit

In the reporting month, landscape and visual site audit in accordance with the requirements stipulated in the EIA report was conducted on 5 and 19 April 2012.

In the reporting month, total 521 trees were felled and the pruning of the transplanted trees was carried out in accordance with the Specification for Tree Protection and Transplanting Works in Landscape Plan. The updated statuses of the felled and transplanted trees during the reporting month are described in Section 5.

The implementation and maintenance of landscape and visual mitigation measures, listed in EIA report, were checked during the site audit. No substantial change of LR, LCA and VSR was noted. No non-compliance has been triggered during the reporting month.

Waste Disposal

Inert C&D materials with actual amount of 3,612.375 m³ were generated and disposed of at public fills at Tuen Mun Area 38 in the reporting month. 82.875 m³ general refuse were generated and disposed of at WENT landfill in the reporting month.

Environmental Licensing and Permitting

Permits or licenses granted to the Project included the Environmental Permit of the Project (EP-342/2009/C), Chemical Waste Producer Registration (5213-324-G3597-01) and Construction Waste Billing Account (7010350);

5 numbers of Construction Noise Permits and 2 numbers of Wastewater Discharge License under WPCO (WT00007251-2010 and WT00008195-2011).

Environmental Auditing

A total of 4 environmental site audits were conducted on a weekly basis in the reporting month. No non-conformance to the environmental requirements was identified during the reporting month.

Complaint Log

No environmental complaint was recorded in the reporting month.

Notifications of Summons and Successful Prosecutions

No summonses or prosecution related to the environmental issues were made against the Project in the reporting month.

Reporting Changes

There were no reporting changes in the reporting month.

Future Key Issues

Construction noise is one of the key environmental issues. The implemented construction noise mitigation measures should also be maintained and improved as necessary. Especially in restricted hours, the conditions stipulated in CNPs should be strictly followed when the construction works were carried out during the restricted hours.

Construction dust is another key environmental issue. The implemented construction dust mitigation measures should also be maintained and improved as necessary. Furthermore, water quality impact is also key environmental issue. As rainy season has approached, special attention should be paid to avoid any muddy surface runoff from exposed soil surface during rainy days. The effective and efficiency mitigation measures should be strictly implemented and improved if necessary.

1 Environmental Status

1.1 Project Background

Ove Arup & Partners Hong Kong Limited (Arup) was appointed by Highways Department (HyD) as the Environmental Team (ET) for *Agreement No. CE22/2005 (HY) Supplementary Agreement 1 Traffic Improvements to Tuen Mun Road Town Centre Section* (the Project) under Agreement No. HMW 5/2009 (EP) Traffic Improvements to Tuen Mun Road Town Centre Section. Environmental parameters including air quality, noise and landscape and visual are required for baseline monitoring prior to the commencement of the Project. The Project was commenced on August 2010 and to be completed on January 2014.

The Project involves widening the following sections of TMR from dual-two carriageway to dual-three carriageway:

- Wong Chu Road Section, (from Wong Chu Road Interchange to Tuen Hing Road);
- Tuen Mun Town Plaza Section, (from Yan Oi Town Square to Tuen Hing Road).

The Project is a designated project under Schedule 2 of the Environmental Impact Assessment (EIA) Ordinance (Cap. 499). Environmental Monitoring and Audit (EM&A) work is required in accordance with the conditions stipulated in the Environmental Permit (EP) (EP-342/2009/C) and the EM&A Manual of the Project.

1.2 Construction Programme

An up-to-date rolling construction programme is attached in **Appendix A**.


1.3 Work Undertaken During the Reporting Month

The major construction activities carried out by the Contractor in the reporting month are summarized in **Table 1.1**. Location of the works area is indicated in **Figure 1.1**. The structure of the project organisation in relation to the environmental management is shown in **Figure 1.2**. Contacts of key environmental staff of the Project and are shown in **Table 1.2**.

Table 1.1 Construction activities in the reporting month

Locations	Major Works Undertaken				
All area	Site clearance, ground investigation, footbridge construction, noise barrier				
1111 41104	construction; pilling works, underground utilities and drainage diversion				

Figure 1.1 Site plan of the Project






Figure 1.2 Project Organization – Environmental Management

Table 1.2 Contacts of key environmental staff

Organization	Name	Telephone
Environmental Protection Department		
Environmental Protection Officer (Strategic Assessment)22	Thomas To	2835 1103
Project Proponent		
Highways Department: Senior Engineer	Kenneth Chan	2762 3422
Supervising Officer / Supervising Officer's Representative		
AECOM Asia Co. Ltd.: Chief Resident Engineer	Patrick Lee	2969 9200
Independent Environmental Checker		
ENVIRON Hong Kong Limited: Independent Environmental Checker	David Yeung	3743 0717
Environmental Team		
Ove Arup & Partners Hong Kong Ltd: Environmental Team Leader	Coleman Ng	2268 3097
Contractor		
China Harbour Engineering Company Limited		
Site Agent	W.S. Ng	2403 0529
Environmental Officer	Marko Chan	2403 0527

1.4 Project Area, Sensitive Receivers and Environmental Monitoring locations

The Project area is shown in **Figure 1.1**, while **Table 1.3** and **Figure 1.3** show the names and locations of the sensitive receivers and monitoring stations.

Table 1.3 Summary of air and noise monitoring stations

ID	Premise
Air	
AM1	Chung Sing Benevolent Society Mrs. Aw Boon Haw Secondary School

ID	Premise
AM2	Tung Wah Group of Hospitals Tai Tung Pui Social Service Building
AM3	Shun Tak Fraternal Association Wu Siu Kui Memorial Primary School
AM4	The Chinese Manufacturers' Association Of Hong Kong Choi Cheung Kok Secondary School
AM5	Tuen Mun Town Hall
AM6	Yan Oi Tong Jockey Club Community and Sports Centre
Noise	
N1	Kam Fai Garden
N2	Tung Wah Group of Hospitals Tai Tung Pui Social Service Building
N3	Po Leung Kuk The Hong Kong Taoist Association Yuen Yuen Primary School
N4	Shun Tak Fraternal Association Wu Siu Kui Memorial Primary School
N5	Tuen King Building
N6	The Chinese Manufacturers' Association Of Hong Kong Choi Cheung Kok Secondary School

1.5 Impact Monitoring Schedule

Environmental monitoring and audit will be carried out in accordance with the requirements stipulated in the EM&A manual. Air, noise, landscape and visual monitoring as well as weekly site audit schedule for the reporting month with respect to the construction programme is shown in **Appendix B**.

1.6 Status of Environmental Licensing and Permitting

All permits/licences inspected in the reporting month are summarised in **Table 1.4**. They are all properly kept by the contactor at their site office.


 Table 1.4
 Summary of environmental licensing status

Types of Permits / Licenses	Reference No.	Valid from	Valid to
Environmental Permit	EP-342/2009	15 May 09	Superseded
	EP-342/2009/A	27 Oct 09	Superseded
	EP-342/2009/B	14 Feb 11	Superseded
	EP-342/2009/C	29 Feb 12	N.A.
Discharge License under WPCO	WT00007251-2010	12 Aug 10	31 Aug 15
	WT00008195-2011	06 Jan 11	30 Sep 15
Notification of Construction Work under APCO	Ref.: 314528	25 Feb 2010	N/A
Construction Noise Permit	GW-RW0699-11	24 Oct 11	23 Apr 12
	GW-RW0772-11	22 Nov 11	19 May 12
	GW-RW0840-11	10 Dec 11	03 Jun 12
	GW-RW0188-12	22 Apr 12	07 May 12
	GW-RW0305-12	24 Apr 12	22 Oct 12
Chemical Waste Producer Registration	5213-424-C3597-01	26 Mar 10	N/A
Construction Waste Billing Account	7010350	25 Mar 10	N/A

1.7 Purpose of the Report

The purpose of the monthly EM&A report is to provide the information on monitoring methodology, monitoring results, environmental permit status, site audit findings, recommendations and conclusions for the scope of impact EM&A. This is the twenty-first monthly EM&A report summarising the monitoring methodology, locations, periods, frequencies, results and any observation from the air quality, noise, water quality, ecology, waste management, landscape and visual monitoring and environmental site audit from 1 to 30 April 2012.

Figure 1.3 Location of air and noise monitoring stations



2 Implementation Status

2.1 Implementation Status of Mitigation Measures

During weekly site inspections, the environmental protection, and pollution control/mitigation measures in accordance with the requirements stipulated in the EIA were observed. **Table 2.1** summarises the key observations and ET's corresponding recommendations while the Contractor's response and follow-up status are described in Section 7.1.

Table 2.1 Summary of the key observations and ET's recommendations

Location	Key Observations and Recommendations						
	Air Quality Mitigation Measures						
Pui To Road	The contractor was reminded to cover the stockpiles, which was for backfilling purpose, after daily works.						
	Water Quality Mitigation Measures						
Tuen Mun Road under TMT Plaza	The stockpile should be reallocated to avoid generating muddy water to public drainage system as far as practicable.						
Kam Fai Fa Yuen	Water flow was observed in the blocked U-channel. The contractor was reminded to verify the status of the water channel.						
Central median under Yan Oi Bridge	A small amount of muddy water was accumulated outside the water barrier in central median. The contractor should clean the muddy water and prevent the water from entering manholes directly by the use of sand bag bundings.						
All areas	The contractor was reminded to turn on all pumps in site prior to rainstorm in a view to alleviate water accumulation and overloading.						
All areas	The contractor was reminded to avoid temporary storage of excavated soil near roadside. Sand bag bundings should be provided in case no alternatives.						
	Waste Management						
Central Median under Yan Oi Bridge	The contractor should provide a drip tray for air compressor.						
Under Yan Ching Bridge	Chemical containers, such as lubricant oil container, should be stored in the designated storage area.						
	Noise						
All areas	The contractor was reminded to review the noise mitigation measures, especially for the generators near NSRs.						

2.2 Updated Implementation Schedule

According to the Environmental Permit, the mitigation measures detailed in the permits are required to be implemented. The Implementation Schedule of Mitigation Measures was inspected during the weekly site inspections in reporting month. The details of the findings/observations are described in Section 7.1. An updated summary of the Implementation Schedule of Mitigation Measures is presented in **Appendix C**.

3 Air Monitoring

3.1 Air Monitoring Requirements

Monitoring Parameters

Air quality monitoring shall be measured in terms of the TSP levels for 1-hour and 24-hour period.

Monitoring Frequency

24-hour TSP levels shall be monitored during the construction stage while 1-hour TSP levels shall be required to monitor in case of complaints received. The monitoring parameters and frequency are summarised in **Table 3.1**.

Table 3.1 TSP monitoring parameters and frequency

Parameters	Monitoring Frequency
24-hour TSP	Once every 6 days
1-hour TSP	3 times every 6 days (as required in case of complaints)

Monitoring Locations

In accordance with the EM&A Manual and the subsequent Baseline Report, six air quality monitoring locations during construction stage are required, namely:

- (i) Chung Sing Benevolent Society Mrs. Aw Boon Haw Secondary School (AM1);
- (ii) Tung Wah Group of Hospitals Tai Tung Pui Social Service Building (AM2);
- (iii) Shun Tak Fraternal Association Wu Siu Kui Memorial Primary School (AM3);
- (iv) The Chinese Manufacturers' Association Of Hong Kong Choi Cheung Kok Secondary School (AM4);
- (v) Tuen Mun Town Hall (AM5); and
- (vi) Yan Oi Tong Jockey Club Community and Sports Centre (AM6).

Wind Monitoring

Wind monitoring data including wind speed and wind directions shall be collected from Hong Kong Observatory – Tuen Mun Monitoring Station.

Environmental /Quality Performance Limits

The monitoring results will be checked against the Action and Limit levels described in the Baseline Report, of which they are excerpted and summarised in **Tables 3.2 and 3.3**.

 Table 3.2
 Action and Limit Level for air quality monitoring of 1-hour TSP level

Level		A	ir Monitori	ing Stations		
	AM1	AM2	AM3	AM4	AM5	AM6
Action Level, μg/m ³	290	291	287	292	286	290
Limit Level, μg/m ³			50	0		

Notes:

1-hr TSP monitoring would be required in case of receiving complaints.

Table 3.3 Action and Limit Level for air quality monitoring of 24-hour TSP level

Level		Air	Monitoring	Stations (No	te 1)	
	AM1	AM2	AM3	AM4	AM5	AM6
Action Level, μg/m ³	146	151	150	150	146	147
Limit Level, μg/m ³			26	0		

3.2 Air Monitoring Methodology

3.2.1 Monitoring Equipment

High Volume Sampler (HVS) was used to monitor the 24-hour TSP. **Table 3.4** shows the equipment used for the air quality monitoring.

Table 3.4 Air quality equipment list for impact air quality monitoring

Equipment	Manufacturer & Model No	Measurement Parameter	Quantity	Serial No.
High Volume Sampler	GS-2310105 / TE- 5170		6	521, 522, 505, 1278, 516 & 510
Fibreglass Filter	G810	24-hour TSP	30	-
HVS Calibration Kit	GMW-2535		1	1378

3.2.2 Maintenance and Calibration

The HVSs and their accessories were frequently checked and maintained in accordance with the manufacturer's operation and maintenance manual. The maintenance included checking of supporting screen and gasket, as well as routine replacement of motor carbon brushes for the blower motor. The power cords and power supply were checked each time before sampling to ensure proper operation.

The HVSs were calibrated at 2-month intervals using GMW-2535 calibration kit which is recalibrated by the manufacturer after one year of use. The calibration spreadsheets of the HVS and calibration certificate of the calibration kit are provided in **Appendix D**.

3.2.3 Monitoring Procedures

Specifications of the HVS are as follows:

- 0.6 1.7 m³/min (20 60SCFM);
- Equipped with a timing/control device with +/- 5 minutes accuracy for 24 hour operation;
- Installed with elapsed time meter with +/- 2 minutes accuracy for 24 hour operation;
- Capable of providing a minimum exposed area of 406 cm² (63in²);
- Flow control accuracy: +/-2.5% deviation over 24-hour sampling period;
- Equipped with a shelter to protect the filter and sampler;
- Incorporated with an electronic mass flow rate controller or other equivalent devices;
- Equipped with a flow recorder for continuous monitoring;
- Provided with a peaked roof inlet;
- Incorporated with a manometer;
- Able to hold and seal the filter paper to the sampler housing at horizontal position;
- Easy to change the filter; and
- Capable of operating continuously for 24-hour period.

The HVSs were equipped with an electronic mass flow controller and calibrated against a traceable standard at regular intervals. All equipment, calibration kit and filter papers were clearly labelled.

The relevant data including temperature, pressure, weather conditions, elapsed-time meter reading for the start and stop of the sampler, identification and weight of the filter paper, and other special phenomena observed and work progress of the concerned site were recorded.

A HOKLAS accredited laboratory (ALS Technichem (HK) Pty Ltd (HOKLAS no.: 066)), in accordance with their standard QA/QC procedures, with constant temperature and humidity

control as well as equipped with necessary measuring and conditioning instruments to handle the 24-hour TSP samples was employed for sample analysis, and equipment calibration and maintenance. Filter papers of size 8"x10" were labelled before sampling. They were inspected clean with no pin holes and conditioned in a humidity controlled chamber for over 24-hour and be pre-weighed before use for the sampling.

The 24-hour TSP levels were measured by following the standard High Volume Method for Total Suspended Particulates as set out in the *Title 40 of the United States Code of Federal Regulations, Chapter 1 (Part 50), Appendix B.* TSP was sampled by drawing air through a conditioned, pre-weighted filter paper inside the HVS at a controlled air flow rate. After 24-hour sampling, the filter papers loaded with dust were kept in a clean and tightly sealed plastic bag, and then returned to the laboratory for reconditioning in the humidity controlled chamber followed by accurate weighing by an electronic balance with a readout down to 0.1 mg. All the collected samples shall be kept in a good condition for 6 months before disposal.

3.3 Monitoring Results and Observations

3.3.1 Weather Condition

No adverse weather conditions were recorded during the monitoring dates.

3.3.2 Air Quality Monitoring Results

Monitoring of 24-hour TSP was conducted on 3, 10, 16, 20 and 26 April 2012. All monitoring data and graphical presentation of the monitoring results are provided in **Appendix E** and are summarised in **Table 3.5**. The graphical presentations of the monitoring results are provided in **Appendix E**. Wind data obtained from the Hong Kong Observatory – Tuen Mun station during the reporting period is presented in **Appendix F**.

 Table 3.5
 Summary of impact air quality monitoring results for reporting month

		Location				
	AM1	AM2	AM3	AM4	AM5	AM6
Average 24-hr TSP Concentration, µg/m³ (Range)	20 (10 – 29)	20 (9 – 38)	22 (14 – 29)	25 (11 – 50)	19 (11 – 26)	22 (9 – 30)

All 24-hour TSP measurements during the reporting month were below the Action/Limit Level. No exceedance of action and limit level was found.

3.3.1 General Observations

Major construction works including site clearance, footbridge construction, pilling works, ground investigation, underground utilities and drainage diversion were implemented during the reporting month. No abnormal condition was recorded during monitoring period.

4 Noise Monitoring

4.1 Noise Monitoring Requirements

Monitoring Parameters

Construction noise shall be measured in terms of the A-weighted equivalent continuous sound pressure level (L_{eq}). L_{10} and L_{90} shall also be recorded as supplementary reference information for data auditing.

Monitoring Frequency

Noise measurements shall be conducted on a weekly basis. The monitoring time periods, monitoring parameters and frequency are summarised in **Table 4.1**.

Table 4.1 Construction noise monitoring parameters and frequency

Time Period (when construction activity is found)	Parameters	Monitoring Frequency
Between 0700-1900 hours on normal weekdays	$L_{eq(30\;min)}$	
Between 1900-2300 hours on normal weekdays		Once nor week
Between 2300-0700 hours of next day	$L_{eq(5 min)}*$	Once per week
Between 0700-1900 hours on holidays		

^{*} The L_{eq(5 min)} will only be measured if construction activities are conducted.

Monitoring Location

In accordance with the EM&A Manual and the subsequent Baseline Report, six noise monitoring location during construction stage is required, namely:

- (i) Kam Fai Garden (N1);
- (ii) Tung Wah Group of Hospitals Tai Tung Pui Social Service Building (N2);
- (iii) Po Leung Kuk The Hong Kong Taoist Association Yuen Yuen Primary School (N3);
- (iv) Shun Tak Fraternal Association Wu Siu Kui Memorial Primary School (N4);
- (v) Tuen King Building (N5); and
- (vi) The Chinese Manufacturers' Association of Hong Kong Choi Cheung Kok Secondary School (N6).

Environmental /Quality Performance Limits

The monitoring results will be checked against the Action and Limit levels described in the Baseline Report, of which they are excerpted and summarised in **Tables 4.2**.

Table 4.2 Action and Limit Levels of construction noise

Location (Note 1)	Time Period	Action Level	Limit Level dB(A) (Note 2)
N1, N2 & N5	0700 - 1900 hours on normal weekdays	When one	75
	0700 - 2300 hours on holiday; and 1900 – 2300 hours on all other days		
	2300 – 0700 hours of next day	received	-
N3, N4 & N6	0700 - 1900 hours on normal weekdays	When one	70/65 (Note 3)
	0700 - 2300 hours on holiday; and 1900 – 2300 hours on all other days	documented complaint is received	-
	2300 – 0700 hours of next day		-

Notes:

- The detail of monitoring locations was presented in Table 2.2.
- 2. For normal day-time working hours, the noise criteria are 70 dB(A) and 65 dB(A) for normal reaching periods and examination period

respectively.

If works are to be carried out during restricted hours, the conditions stipulated in the Construction Noise Permit (CNP) issued by the Noise Control Authority have to be follows.

4.2 Noise Monitoring Methodology

4.2.1 Monitoring Equipment

Noise level was measured by a Sound Level Meter (SLM) in terms of A-weighted equivalent continuous sound pressure level. L_{eq} , L_{10} and L_{90} were recorded as supplementary information for data auditing. **Table 4.3** shows the equipment list of the noise monitoring.

Table 4.3 Noise equipment list for impact noise monitoring

Equipment	Manufacturer & Model No.	Serial No.	Precision Grade	Qty.
Integrated SLM	Brüel & Kjær 2238	2320707, 2320696 & 2654435	IEC 651 Type 1 IEC 804 Type 1	3
Sound level calibrator	Rion NC-74	34304660	IEC 942 Type 1	1

4.2.2 Maintenance and Calibration

The SLM and calibrator in compliance with the International Electrotechnical Commission (IEC) Publication 651:1979 (Type 1) and 804:1985 (Type 1) specifications according to the EM&A manual.

SLM complying with the standards of IEC 651 (Fast, Slow, Impulse rms detector tests) and IEC 804 (L_{eq} functions) and acoustical calibrator complying with IEC 942 were adopted for the noise measurement. All equipments are calibrated externally. The calibration certificates for the noise equipment are given in **Appendix G**.

4.2.3 Monitoring Procedures

- The SLM and battery were checked to ensure that they are in proper condition. The SLM was set on a tripod at 1.2m above ground and at least 1m from the exterior of the building façade;
- Before conducting the measurement, the SLM was calibrated by an acoustical calibrator;
- Measurement parameter was set to A-weighted sound pressure level. The time weighting was set in fast response and the time period of measurement at 30 minutes;
- Wind speed was checked during noise monitoring to ensure the steady wind speed does not exceed 5m/s, or wind with gusts does not exceed 10m/s;
- Any abnormal conditions that generated intrusive noise during the measurement was recorded on the field record sheet;
- After each measurement, the equivalent continuous sound pressure level (L_{eq}), L_{10} and L_{90} were recorded on the field record sheet;
- After conducting the measurement, the SLM was calibrated by an sound level calibrator;
 and
- The SLM was re-calibrated by the sound level calibrator to confirm that there is no significant drift of reading. Measurements shall be accepted as valid only if the calibration levels before and after the noise measurement agrees to within 1.0 dB.

4.3 Monitoring Results and Observations

4.3.1 Weather Condition

The weather condition was mainly sunny during the noise monitoring period in the reporting month. In 5 April and 27 April, the weather was rainy. Noise monitoring was conducted in non-rainy hours.

4.3.2 Noise Monitoring Results

Monitoring of the construction noise level was conducted during non-restricted hours on 5, 11, 21 and 27 April 2012 at monitoring locations N1, N2, N3, N4, N5 and N6. All monitoring data and graphical presentation of the monitoring results are provided in **Appendix H** and are summarised in **Table 4.4 to 4.9**. The graphical presentations of the monitoring results are provided in **Appendix H**.

Table 4.4 Summary of impact noise monitoring at location N1 in the reporting month

Date	Time	Measured Noise Level, dB(A)	Baseline Noise Level, dB(A)	Construction Noise Level(Note1), dB(A)	Limit Level
		Leq (30-min)	Leq (30-min)	Leq (30-min)	dB(A)
5 Apr 12	10:00 - 10:30	75		Measured ≤ Baseline	
11 Apr 12	09:50 - 10:20	74	76	Measured ≤ Baseline	75
21 Apr 12	09:45 - 10:15	72	76	Measured ≤ Baseline	75
27 Apr 12	09:50 - 10:20	74		Measured ≤ Baseline	

Notes:

 Table 4.5
 Summary of impact noise monitoring at location N2 in the reporting month

Date	Time	Measured Noise Level, dB(A)	Baseline Noise Level, dB(A)	Construction Noise Level(Note1), dB(A)	Limit Level
		Leq (30-min)	Leq (30-min)	Leq (30-min)	dB(A)
5 Apr 12	10:50 - 11:20	73		Measured ≦ Baseline	
11 Apr 12	10:45 - 11:15	75	78	Measured ≤ Baseline	75
21 Apr 12	10:40 - 11:10	73	76	Measured ≤ Baseline	75
27 Apr 12	10:35 - 11:05	74		Measured ≦ Baseline	

Notes:

Table 4.6 Summary of impact noise monitoring at location N3 in the reporting month

Date	Time	Measured Noise Level, dB(A)	Baseline Noise Level, dB(A)	Construction Noise Level(Note1), dB(A)	Limit Level
		Leq (30-min)	Leq (30-min)	Leq (30-min)	dB(A)
5 Apr 12	11:40 - 12:10	69		Measured ≦ Baseline	
11 Apr 12	11:40 - 12:10	68	69	Measured ≤ Baseline	70
21 Apr 12	11:30 - 12:00	67	09	Measured ≤ Baseline	70
27 Apr 12	11:30 - 12:00	68		Measured ≤ Baseline	

Notes:

^{1.} Construction Noise Level = Measured Noise Level – Baseline Noise Level.

^{1.} Construction Noise Level = Measured Noise Level - Baseline Noise Level.

^{1.} Construction Noise Level = Measured Noise Level - Baseline Noise Level.

Table 4.7 Summary of impact noise monitoring at location N4 in the reporting month

Date	Time	Measured Noise Level, dB(A)	Baseline Noise Level, dB(A)	Construction Noise Level(Note1), dB(A)	Limit Level
		Leq (30-min)	Leq (30-min)	Leq (30-min)	dB(A)
5 Apr 12	08:30 - 09:00	66		Measured ≤ Baseline	
11 Apr 12	08:30 - 09:00	65	67	Measured ≦ Baseline	70
21 Apr 12	08:30 - 09:00	66	07	Measured ≦ Baseline	70
27 Apr 12	08:30 - 09:00	66		Measured ≤ Baseline	

Notes:

Table 4.8 Summary of impact noise monitoring at location N5 in the reporting month

Date	Time	Measured Noise Level, dB(A)	Baseline Noise Level, dB(A)	Construction Noise Level(Note1), dB(A)	Limit Level
		Leq (30-min)	Leq (30-min)	Leq (30-min)	dB(A)
5 Apr 12	13:00 - 13:30	70		Measured ≤ Baseline	
11 Apr 12	13:00 - 13:30	69	70	Measured ≤ Baseline	75
21 Apr 12	13:00 - 13:30	69	70	Measured ≤ Baseline	75
27 Apr 12	13:00 - 13:30	70		Measured ≤ Baseline	

Notes:

Table 4.9 Summary of impact noise monitoring at location N6 in the reporting month

Date	Time	Measured Noise Level, dB(A)	Baseline Noise Level, dB(A)	Construction Noise Level(Note1), dB(A)	Limit Level
		Leq (30-min)	Leq (30-min)	Leq (30-min)	dB(A)
5 Apr 12	14:00 - 14:30	70		61	
11 Apr 12	13:50 - 14:20	68	69	Measured ≤ Baseline	70
21 Apr 12	13:45 - 14:15	68	09	Measured ≤ Baseline	70
27 Apr 12	14:00 - 14:30	68		Measured ≦ Baseline	

Notes:

Restricted Hours

In the reporting months, the construction works and activities such as mobilization of materials and plants etc were carried out during restricted hours. The granted Construction Noise Permits (CNPs) were issued by EPD for the related activities before the works commencement, the Contractor strictly followed the conditions stipulated in the CNPs. There was no non-compliance recorded during the reporting month.

4.3.3 Exceedance of Limit and Action Levels for Construction Noise

No limit level exceedance for noise measurements during non-restricted hours was recorded in the reporting month.

No Action Level exceedance of construction noise was recorded in the reporting month.

^{1.} Construction Noise Level = Measured Noise Level - Baseline Noise Level.

^{1.} Construction Noise Level = Measured Noise Level - Baseline Noise Level.

^{1.} Construction Noise Level = Measured Noise Level - Baseline Noise Level.

4.3.4 General Observations

The construction site had been under normal operation during the noise monitoring period and no unusual operation was observed. Traffic noise had been noticed at the monitoring locations during the noise monitoring period.

5 Landscape and Visual Monitoring

5.1 Landscape and Visual Monitoring Requirements

Monitoring Parameters

The landscape and visual conditions of the site and its vicinity shall be reviewed with regards to parameters assessed in the EIA Report, including landscape resources (LR), landscape character area (LCA) and view condition of visual sensitive receiver (VSR).

Monitoring Frequency and Location

The landscape and visual monitoring and audit shall be undertaken bi-weekly throughout the construction period. The components of each assessed parameter of LR, LCA and VSR are summarised in **Table 5.1**.

Table 5.1 Parameters of landscape resources, landscape character areas and landscape sensitive receivers assessed during baseline site survey

ID No.	landscape sensitive receivers assessed during baseline site survey Names		
Landscape	Landscape Resources		
LR1	Tsing Sin Playground		
LR2	Roadside Planting along Tuen Mun Road Adjacent to Kam Fai Garden		
LR3	Street trees along Castle Peak Road – Castle Peak Bay		
LR4	Street trees along Tuen Mun Road west of Chi Lok Fa Yuen and east of On Ting Estate		
LR5	Street trees along Tuen Mun Road west of Waldorf Garden and CMA Choi Cheung Kok Prevocational School		
LR6	Street trees along Tuen Mun Road near Tuen Mun Town Plaza		
LR7	Street trees along Tuen Mun Road east of Yan Oi Tong		
LR8	Trees at roadside planting areas near Yan Oi Tong Circuit		
LR9	Trees at planting area near Tuen Mun Town Plaza		
LR10	Trees at planting area near New Town Mansion		
LR11	Trees at planting area near On Ting Estate		
LR12	Tsing Hoi Playground		
Landscape	e Character Areas		
LZ1	Tuen Mun Residential Urban Landscape		
LZ2	Tuen Mun Mixed Modern Comprehensive Urban Development Landscape		
LZ3	Tuen Mun 'Hui' Urban Landscape		
Visual Sen	sitive Receivers		
C/R1	Tuen Mun Town Plaza, Waldorf Garden		
C/R2	Tuen Cultural Centre, Tuen Mun Town Plaza		
C/R3	Chelsea Height		
GIC1	Tuen Mun Church and Tuen Mun Tseng Choi Street Joint-user Complex		
GIC2	Sin Hing Tong Temple		
GIC3	Semple Memorial Secondary School and Chung Shing Benevolent Society Mrs. Aw Boon Haw Secondary School		
GIC4	Car park (Open)		
	Yan Oi Tong Community & Sports Centre		
GIC5	Tail Or Tong Community & Sports Centile		

ID No.	Names
GIC7	Madam Lau Wong Fat Primary School, Lui Cheung Kwong College, Leung Kau Kui College, Lui Cheung Kwong Primary School, Wu Siu Kui Primary School
GIC8	Sam Shing Temple
O1	San Hui Playground
O2	Tsing Sin Playground
O3	Siu Lun Sports Ground
O4	Hoi Sin Playground
R1	Residential Area of Tuen Mun San Hui
R2	Residential Area along Yan Oi Tong Circuit
R3	On Ting Estate and Siu On Court
R4	Residential Area along Tsing Hoi Circuit
R5	Handsome Court, Alpine Garden, Hoi Tak Garden and Harvest Garden, Kam Fai Garden
R6	Siu Lun Court
R7	Goodview Garden and Tsui Ning Garden
R8	Sam Shing Estate
R9	Hanford Garden
T1	Tuen Mun Road – Vehicular and Pedestrian

5.2 Audit Results

In the reporting month, landscape and visual site audit in accordance with the requirements stipulated in the EIA report was conducted on 5 and 19 April 2012.

In accordance with the Landscape Plan of the Project under the Clause 2.13 of the Part C of the EP and updated information by the Contractor, a total of 1031 trees would be affected. 102 trees would be retained, 399 trees would be transplanted to Siu Lang Shui Road and 521 trees would be felled during the construction phase. The implementation and maintenance of landscape and mitigation measures, listed in EIA report, were checked during the site audit. No substantial change of LR, LCA and VSR was noted. No noncompliance has been triggered during the reporting month.

Since the commencement of the Project, total 521 trees were felled and the pruning of the transplanted trees was carried out in accordance with the Specification for Tree Protection and Transplanting Works in Landscape Plan. The updated statuses of the felled and transplanted trees during the reporting month are summarized in **Tale 5.2** and the summary report is presented in **Appendix I**.

Table 5.2 Status of felled and transplanted trees during reporting month

	No. of trees to be felled	No .of trees to be transplanted				
		Crown pruning	1 st root pruning	2 nd root pruning	3 rd root pruning	
In progress	0	0	29	30	20	
Completed	521	399	370	369	379	
Total	521	399	399	399	399	
Percentage completed (%)	100	100	93	92	95	

In order to enhance the landscape and visual experience to Tuen Mun town centre neighborhood and compensate for the district tree felling, compensatory tree planting of 699 no. of trees would be carried out throughout various area in Tuen Mun after the discussion and agreement with Tuen Mun District Council (TMDC) and relevant government parties (e.g. LCSD).

5.3 Implementation Status of Consultation Phase Landscape and Visual Mitigation Measures

The design, implementation and maintenance of landscape and visual mitigation measures stipulated in the EM&A manual, were checked during the site audits. No non-compliance has been triggered.

The Implementation Schedule of Mitigation Measures was inspected during the weekly site inspections in reporting month. The details of the findings/observations are described in Section 7.1. Summary of the implementation status of construction phase Landscape and Visual mitigation measures are presented in **Appendix C**.

5.4 Recommendations, Corrective Actions and Outstanding Issues

The recommendations, corrective actions or outstanding issues in relation with the landscape and visual monitoring are as follows:

- The Contractor was reminded to strip and store the topsoil for re-use in the construction of soft landscape works, where practical;
- The Contractor was reminded to protect the retained trees carefully during construction;
- The Contractor was reminded to transplant the trees which affected by the works where possible and practical;
- The Contractor was reminded to compensate the trees for felled trees;
- The Contractor was reminded to control of night-time lighting;
- The Contractor was reminded to erect a compatible decorative screen hoarding with the surrounding setting;
- The Contractor was reminded to avoid placing the construction materials too close to the trees.

6 Waste Disposal

The actual amounts of different types of waste generated by the activities of the Project during the reporting month are shown in Table 6.1. The monthly summary flow table is provided in **Appendix J**.

Table 6.1	Amount of	waste	generated	in	reporting month
-----------	-----------	-------	-----------	----	-----------------

Waste Type	Amount	Disposal Locations
Inert C&D Materials	0 m ³ Broken concrete	
	0 m ³	Reused in the Contract
	0 m ³ Reused in other Projects	
	3,612.375 m ³	Disposal of at public fill at Tuen Mun Area 38
Chemical Waste	0 kg	N/A
Paper / cardboard packaging	0 kg	
Plastic	0 kg	Recycler
Metal	665.00 kg	
General Refuse	82.875 m ³	Disposal of at WENT landfill

7 Environmental Performance

7.1 Environmental Site Inspection

Environmental site inspections were carried out on a weekly basis to monitor environmental issues on the construction sites to ensure that all mitigation measures were implemented timely and properly. A summary of the site inspections in the reporting month is presented in **Table 7.1**.

 Table 7.1
 Key findings of weekly environmental site audit in the reporting month

Inspection Date	Location	Key Observations and Recommendations	Contractor's Response / Environmental Outcome	Closed Date / Follow up Status				
	Air Quality Mitigation Measures							
12 Apr 12	Pui To Road	The contractor was reminded to cover the stockpiles, which was for back-filling purpose, after daily works.	Agreed with the ET's advice.	The reminder has been noted. Closed on 19 Apr 12.				
	Water Quality Mitigation Measures							
5 Apr 12	Tuen Mun Road under TMT Plaza	The stockpile should be reallocated to avoid generating muddy water to public drainage system as far as practicable.	Agreed with the ET's advice.	Reallocation of stockpile has been done. Closed on 12 Apr 12.				
5 Apr 12	Kam Fai Fa Yuen	Water flow was observed in the blocked U-channel. The contractor was reminded to verify the status of the water channel.	Agreed with the ET's advice.	The reminder has been noted. Closed on 12 Apr 12.				

Inspection Date	Location	Key Observations and Recommendations	Contractor's Response / Environmental Outcome	Closed Date / Follow up Status
19 Apr 12	Central median under Yan Oi Bridge	A small amount of muddy water was accumulated outside the water barrier in central median. The contractor should clean the muddy water and prevent the water from entering manholes directly by the use of sand bag bundings.	s accumulated outside the ter barrier in central median. e contractor should clean the ddy water and prevent the ter from entering manholes ectly by the use of sand bag	
19 Apr 12	All areas	The contractor was reminded to turn on all pumps in site prior to rainstorm in a view to alleviate water accumulation and overloading.	Agreed with the ET's advice.	The reminder has been noted. Closed on 26 Apr 12.
26 Apr 12	All areas	The contractor was reminded to avoid temporary storage of excavated soil near roadside. Sand bag bundings should be provided in case no alternatives.	Agreed with the ET's advice.	The reminder has been noted. Closed on 3 May 12.
		Noise Mitigation Measures		
26 Apr 12	All areas	The contractor was reminded to review the noise mitigation measures, especially for the generators near NSRs.	Agreed with the ET's advice.	The reminder has been noted. Closed on 3 May 12.
		Waste Management		
5 Apr 12	Central Median under Yan Oi Bridge	The contractor should provide a drip tray for air compressor.	Agreed with ET's advice.	The reminder has been noted. Closed on 12 Apr 12.
12 Apr 12	Under Yan Ching Bridge	Chemical containers, such as lubricant oil container, should be stored in the designated storage area.	Agreed with ET's advice.	Chemical containers have been stored in designated storage area. Closed on 19 Apr 12.

7.2 Complaint Record

No environmental complaint was recorded in the reporting month.

The updated statistical summary of complaint is presented in **Table 7.2**.

Table 7.2 Summary of complaints for the contract

Table 7.2	Table 1.2 Summary of complaints for the contract					
Reporting Period	Complaint Statistics		Area of Concern	Validity to the Project	Status	
	Number	Cumulative				
02/08/10 -	0	0				
31/10/10	U	U	=	=	=	
01/11/10 -	1	1	Noise	Yes	Closed on	
30/11/10	1		Noise	(Ref.: C001)	30 Nov 10.	

Reporting Period	Complai	Complaint Statistics Area of Con		Validity to the Project	Status
1 01100	Number	Cumulative		Troject	
01/12/10 – 31/01/11	0	1	-	-	-
01/02/11 - 28/02/11	1	2	Noise	Yes (Ref.: C002)	Closed on 2 Mar 11.
01/03/11 – 31/03/11	0	2	-	-	-
01/04/11 – 30/04/11	2	4	Water	Yes (Ref.: C003)	Closed on 16 Apr 11.
			Noise	Yes (Ref.: C004)	Closed on 16 May 11.
01/05/11 – 31/05/11	1	5	Water	Yes (Ref.: C005)	Closed on 10 Jun 11.
01/06/11 – 30/06/11	1	6	Air	Yes (Ref.: C006)	Closed on 23 Jun 11.
	1	7	Noise	Yes (Ref.: C007)	Closed on 24 Jun 11.
	1	8	Water	Yes (Ref.: C008)	Closed on 4 Jul 11.
	1	9	Air	Yes (Ref.: C009)	Closed on 14 Jul 11.
01/07/11 – 31/07/11	1	10	Noise	Yes (Ref.: C010)	Closed on 4 Aug 11.
	1	11	Water	Yes (Ref.: C011)	Closed on 4 Aug 11.
01/08/11 - 31/08/11	0	11	-	-	-
01/09/11 – 30/09/11	1	12	Noise	Yes (Ref.: C012)	Closed on 29 Sep 11.
	1	13	Water	Yes (Ref.: C013)	Closed on 14 Oct 11.
	1	14	Water	Yes (Ref.: C014)	Closed on 14 Oct 11.
01/10/11 – 31/10/11	1	15	Water	Yes (Ref.: C015)	Closed on 28 Oct 11.
01/11/11 – 30/11/11	1	16	Noise	Yes (Ref.: C016)	Closed on 24 Nov 11.
	1	17	Noise	Yes (Ref.: C017)	Closed on 30 Nov 11.
01/12/11 – 31/12/11	0	17	-	-	-
01/01/12 - 31/01/12	1	18	Water	Yes (Ref.: C018)	Closed on 6 Feb 12.
	1	19	Water	Yes (Ref.: C019)	Closed on 6 Feb 12.
01/02/12 - 29/02/12	0	19	-	-	-
01/03/12 - 31/03/12	1	20	Water	Yes (Ref.: C020)	Closed on 22 Mar 12.
	1	21	Noise	Yes (Ref.: C021)	Closed on 28 Mar 12.
	1	22	Noise	Yes (Ref.: C022)	Closed on 5 Apr 12.

Reporting Period	Complaint Statistics		Area of Concern	Validity to the Project	Status
	Number	Cumulative			
	1	23	Water	Yes (Ref.: C023)	Closed on 5 Apr 12.
01/04/12 - 30/04/12	0	23	-	-	-

7.3 Notification of Summons and Successful Prosecution

No summons or prosecutions related to environmental issues were received or made against the Project in the reporting month.

7.4 Review of Reasons of Non-Compliance

No limit level exceedance of noise monitoring was recorded in the reporting month.

8 Future Key Issues

8.1 Key Issues for the Coming Month

Key issues to be considered in the coming month include:

- Dust generation from activities on-site, such as vehicular movements along unpaved area, excavation and demolition;
- Noise impact from operating equipment and machinery on-site;
- Muddy surface runoff overflow to public area;
- Uncontrolled water discharge into nearby water body;
- Storage and using of chemicals/fuel and chemical waste/waste oil on site;
- Disposal of construction waste; and
- Tree maintenance.

8.2 Environmental Monitoring Program for the Coming Month

Environmental monitoring and audit will be carried out in accordance with the requirements stipulated in the EM&A manual. Tentative air, noise, landscape and visual monitoring as well as weekly site audit schedule for the coming month with respect to the construction programme is shown in **Appendix K**.

The construction programme for the coming month is shown in **Table 8.1**.

Table 8.1 Tentative programme of construction works

Month	Locations	Details of Construction Works		
May 2012	Various locations	Site clearance, ground investigation, footbridge construction, noise barrier construction; pilling works, underground utilities and drainage diversion		

9 Conclusions and Recommendations

9.1 Conclusions

The construction phase of the Project was commenced on 2 August 2010. The EM&A programme has been implemented since then, including air quality, noise, landscape and visual and environmental site audits.

No Action and Limit Level exceedance was recorded for impact air quality in the reporting month.

No Limit level exceedance of noise monitoring was recorded. No Action Level exceedance of construction noise was recorded in the reporting month.

No environmental complaint was recorded in the reporting month.

No summons or prosecution related to environmental issues was received during the reporting month.

In accordance with the requirements stipulated in the EM&A manual, landscape and visual site audit was conducted on 5 and 19 April 2012. Total 521 trees were felled and the pruning of the transplanted trees was carried out during the reporting month. No substantial change of LR, LCA and VSR was noted.

Four (4) weekly environmental site audits were carried out during the reporting month. The major environmental concerns were related to air quality, noise, water quality, waste management and tree maintenance. No special observation related tree maintenance/landscape was recorded.

9.2 Recommendations

Impact monitoring will be continued to carry out in the following month and followed by the requirement stipulated in the EM&A manual. Attention will be paid to environmental issues identified in EIA report and weekly site audit. Mitigation measures recommended in EIA report and Implementation Schedule of Mitigation Measure will be fully implemented.

Construction noise is one of the key environmental issues especially in restricted hours. The conditions stipulated in CNPs should be strictly followed when the construction works were carried out during the restricted hours.

Construction dust is another key environmental issue. The implemented construction dust mitigation measures including covering of exposed slope / soil with tarpaulin sheet etc., should be maintained and improved as necessary. Adequate water spraying should be provided for the unpaved area to minimize dust disturbance.


Water quality impact is also key environmental issue. The drainage system should be well maintained. All wastewater generated within the site should be collected and treated prior to discharge. The solid and liquid waste management should be strictly followed in accordance with the requirements described in the EIA report.


10 Reference


- [1] AECOM Asia Co. Ltd. December 2008. Agreement No. CE 22/2005 (HY) Supplementary No. 1 Traffic Improvements to Tuen Mun Road Town Centre Section Environmental Monitoring & Audit Manual.
- [2] Ove Arup & Partners Hong Kong Limited. July 2010. Agreement No. HMW 5/2009 (EP) Traffic Improvements to Tuen Mun Road Town Centre Section – Baseline Monitoring Report (Revision_4).


Appendix A


Construction Programme














Appendix B

Environmental
Monitoring Programme
in the Reporting Month

Agreement No. CE 22/2005 (HY) Traffic Improvement to Tuen Mun Road Town Centre Section Tentative Impact Monitoring Schedule - April 2012 Revision 1

Date	Air Quality	Noise	Landscape &	Site Inspection
	24-hours TSP	L _{Aeq} , 30 min	Visual	
1-Apr-12 Sun				
2-Apr-12 Mon				
3-Apr-12 Tue				
4-Apr-12 Wed				
5-Apr-12 Thu				
6-Apr-12 Fri				
7-Apr-12 Sat				
8-Apr-12 Sun				
9-Apr-12 Mon				
10-Apr-12 Tue				
11-Apr-12 Wed				
12-Apr-12 Thu				
13-Apr-12 Fri				
14-Apr-12 Sat				
15-Apr-12 Sun				
16-Apr-12 Mon				
17-Apr-12 Tue				
18-Apr-12 Wed				005140
19-Apr-12 Thu				SSEMC
20-Apr-12 Fri				
21-Apr-12 Sat				
22-Apr-12 Sun 23-Apr-12 Mon				
23-Apr-12 Mon 24-Apr-12 Tue				
25-Apr-12 Wed				
26-Apr-12 Wed 26-Apr-12 Thu				
27-Apr-12 Fri				
28-Apr-12 Sat				
29-Apr-12 Sun 30-Apr-12 Mon				

Public Holiday
Monitoring Day

Monitoring Details

Monitoring	Quantity	Locations	Parameters
Air Quality	6	Mrs.Aw Boon Haw Secondary School	24-hour TSP,
		Tai Tung Pui Social Service Building	Wind speed / direction
		Wu Siu Kui Primary School	
		Choi Cheung Kok Secondary School	
		Tuen Mun Town Hall	
		Yan Oi Tong Community and Sport Centre	
Noise	6	Kam Fai Garden	L _{Aeq(30 min)} , L ₁₀ , L ₉₀
		Tai Tung Pui Social Service Building	
		Yuen Yuen Primary School	
		Wu Siu Kui Primary School	
		Tuen King Building	
		Choi Cheung Kok Secondary School	

Appendix C
Implementation
Schedule of Mitigation Measures

Summary of Implementation Schedule of Mitigation Measures

EIA Ref#	EM&A Ref#	Environmental Protection Measures / Mitigation Measures	Location / Timing	Status *
		Noise Control		
3.8.1	2.8.1	Good site practice and management can significantly reduce the noise impact of construction site activities on nearby NSRs	Works Sites / During Construction Phase	
		only well-maintained plant should be operated on-site and plant should be serviced regularly during the construction works;		✓
		machines and plant that may be in intermittent use should be shut down between work periods or should be throttled down to a minimum;		✓
		plant known to emit noise strongly in one direction should, where possible, be orientated to direct noise away from the NSRs;		✓
		mobile plant should be sited as far away from NSRs as possible; and		Rdr
		material stockpiles and other structures should be effectively utilized, where practicable, to screen noise from on-site construction activities.		✓
3.8.4	2.8.3	Use of quieter mechanical equipment	Works Sites / During Construction Phase	✓
3.8.9	2.8.4	Provision of movable noise barrier in the vicinity of the following NSRs	Works Sites from the listed NSRs / During Construction	N/O
		FEC (Far East Consortium Tuen Mun Central Building)		
		FM (Forward Mansion)	Phase	
		HTB (Hing Tai Building)		
		TMTP1 (Tuen Mun Town Plaza)		
		WG2 (Waldorf Garden)		
		CMA (CMA Choi Cheung Kok Secondary School)		
		LWF (Yan Oi Tong Madam Lau Wong Fat Primary School)		
		TMF (Tuen Mun Fa Yuen)		
		LCK (Lui Cheung Kwong Lutheran College)		
		CLFY1 (Chi Lok Fa Yuen)		

	EM&A Ref#	Environmental Protection Measures / Mitigation Measures	Location / Timing	Status *
		TFH (On Ting Estate (Ting Fuk House))		
		LCKP (Lui Cheung Kwong Lutheran Primary School)		
		TTP (Tung Wah Group of Hospitals Tai Tung Pui Social Service Building)		
		CSBS (CSBS Mrs. Aw Boon Haw Secondary School)		
		KFG3D (Kam Fai Garden)		
3.8.12	2.8.5	 Site clearance and the following activities not to be undertaken in the vicinity of the NSR LCK so as to reduce construction noise impact during normal teaching hours. truck would not operate concurrently with other PMEs during tree transplanting and noise barrier foundation work. tree transplanting would not be undertaken concurrently with bulk excavation and utilities diversion. construction of storm water drain would not be undertaken concurrently with noise barrier/enclosure foundation. construction of sub-base and road base would not be undertaken concurrently with noise barrier/enclosure installation. road surfacing, construction of road kerbs, central dividers, parapets, and installation of crash cushion and sign gantry would not be undertaken concurrently. installation of gantry and directional lighting, and street lighting would not be undertaken concurrently. 	Work site in the vicinity of Lui Cheung Kwong Lutheran College (LCK) / Stage 2 (Ch. 28050 – 28200 of TMR) during Construction Phase	•

EIA Ref#	EM&A Ref#	Environmental Protection Measures / Mitigation Measures	Location / Timing	Status *
3.8.13	2.8.6	Liaise with all the relevant schools to check out their examination periods and activities in the beginning of the work programme in order to make good planning and arrangement of works and provide sufficient mitigation plans to alleviate noise impacts.	CMA Choi Cheung Kok Secondary School (CMA), Yan Oi Tong Madam Lau Wong Fat Primary School (LWF), Lui Cheung Kwong Lutheran College (LCK), Lui Cheung Kwong Lutheran Primary School (LCKP) and CSBS Mrs. Aw Boon Haw Secondary School (CSBS) / During Construction Phase	√

[#] All recommendations and requirements resulted during the course of EIA Process, including ACE and / or accepted public comment to the proposed project.

EIA Ref#	EM&A Ref	Environmental Protection Measures / Mitigation Measures	Location / Timing	Status *
		Air Quality Control		
4.8.1	3.11.2	Implementation of dust suppression measures stipulated in Air Pollution Control (Construction Dust) Regulation.	Works Sites / During Construction Phase	
		skip hoist for material transport should be totally enclosed by impervious sheeting		✓
		every vehicle should be washed to remove any dusty materials from its body and wheels before leaving a construction site		✓
		the area where vehicle washing takes place and the section of the road between the washing facilities and the exit point should be paved with concrete, bituminous materials or hardcores		✓
		where a site boundary adjoins a road, streets or other accessible to the public, hording of not less than 2.4m high from ground level should be provided along the entire length except for a		✓

Notes (*): ✓ - Compliance; N/A - Not Applicable; N/O - Not Observed; Rdr - Reminder; Obs - Observation; N/C - Non Compliance

EIA Ref#	EM&A Ref	Environmental Protection Measures / Mitigation Measures	Location / Timing	Status *
		site entrance or exit		
		 every stack of more than 20 bags of cement should be covered entirely by impervious sheeting places in an area sheltered on the top and the 3 sides 		✓
		 all dusty materials should be sprayed with water prior to any loading, unloading or transfer operation so as to maintain the dusty materials wet 		Obs
		 the height from which excavated materials are dropped should be controlled to a minimum practical height to limit fugitive dust generation from unloading 		∀
		 the load of dusty materials carried by vehicle leaving a construction site should be covered entirely by clean impervious sheeting to ensure dust materials do not leak from the vehicle 		
		• instigation of an environmental monitoring and auditing program to monitor the construction process in order to enforce controls and modify method of work if dusty conditions arise.		V

[#] All recommendations and requirements resulted during the course of EIA Process, including ACE and / or accepted public comment to the proposed project.

EIA Ref [#]	EM&A Ref	Environmental Protection Measures / Mitigation Measures	Location / Timing	Status *
		Water Quality Control		
5.8.2	4.3.2	 Silt removal facilities such as silt traps or sedimentation facilities should be provided to remove silt particles from runoff to meet the requirements of the TM standards under the WPCO. The design of silt removal facilities should be based on the guidelines provided in ProPECC PN 1/94. All drainage facilities and erosion and sediment control structures should be inspected monthly and maintained to ensure proper and efficient operation at all times and particularly during rainstorms. 	Works Sites / During Construction Phase	✓
		 Careful programming of the works to minimise surface excavations for the road improvement works during the wet season. If excavation of soil cannot be avoided during the wet season, exposed slope surfaces should be covered by a tarpaulin or other means. Other measures that need to be implemented before, during, and after rainstorms are summarized in ProPECC PN 1/94. 		✓ ✓
		Exposed soil surfaces should be protected by paving or fill material as soon as possible to		

Notes (*): ✓ - Compliance; N/A - Not Applicable; N/O - Not Observed; Rdr - Reminder; Obs - Observation; N/C - Non Compliance

EIA Ref#	EM&A Ref	Environmental Protection Measures / Mitigation Measures	Location / Timing	Status *
		reduce the potential of soil erosion.		
		Open stockpiles of construction materials or construction wastes on-site should be covered with tarpaulin or similar fabric during rainstorms. These materials should not be placed near water courses.		Obs
5.8.3 - 5.8.4	4.3.3	General Construction Activities	Works Sites / During	
		Debris and refuse generated on-site should be collected, handled and disposed of properly to avoid entering the nearby local stormwater drainage system.	Construction Phase	✓
		Stockpiles of cement and other construction materials should be kept covered when not being used.		✓
		Oils and fuels should only be used and stored in designated areas which have pollution prevention facilities. All fuel tanks and storage areas should be provided with locks and be sited on sealed areas, within bunds of a capacity equal to 110% of the storage capacity of the largest tank. The bund should be drained of rainwater after a rain event		Obs
5.8.5	4.3.4	Sewage from Construction Workforce	Works Sites / During	
		Temporary sanitary facilities, such as portable chemical toilets, should be employed on-site. A licensed contractor would be responsible for appropriate disposal and maintenance of these facilities	Construction Phase	✓

[#] All recommendations and requirements resulted during the course of EIA Process, including ACE and / or accepted public comment to the proposed project.

EIA Ref [#]	EM&A Ref	Environmental Protection Measures / Mitigation Measures	Location / Timing	Status *
		Waste Management		
6.6.1	5.2.2	 Good Site Practices Nomination of an approved person, such as a site manager, to be responsible for good site practices, arrangements for collection and effective disposal to an appropriate facility, of all wastes generated at the site. 	Works Sites / During Construction Phase	√
		Training of site personnel in proper waste management and chemical waste handling procedures.		✓ ✓
		Provision of sufficient waste disposal points and regular collection for disposal.		
		Appropriate measures to minimize windblown litter and dust during transportation of waste by either covering trucks or by transporting wastes in enclosed containers.		✓
		Regular cleaning and maintenance programme for drainage systems, sumps and oil interceptors.		✓
		A recording system for the amount of wastes generated, recycled and disposed of (including the disposal sites).		✓
6.6.5	5.2.6	 Chemical Wastes After use, chemical wastes (for example, cleaning fluids, solvents, lubrication oil and fuel) should be handled according to the Code of Practice on the Packaging, Labelling and Storage of Chemical Wastes. 	Works Sites / During Construction Phase	Obs
		Spent chemicals should be collected by a licensed collector for disposal at the CWTC or other licensed facility, in accordance with the Waste Disposal (Chemical Waste) (General) Regulation.		✓
6.6.6	5.2.7	General Refuse	Works Sites / During	
		General refuse should be stored in enclosed bins or compaction units separate from C&D material.	Construction Phase	✓
		A reputable waste collector should be employed by the contractor to remove general refuse from the site, separately from C&D material.		✓
		An enclosed and covered area is preferred to reduce the occurrence of 'wind blown' light material.		✓

Notes (*): ✓ - Compliance; N/A - Not Applicable; N/O - Not Observed; Rdr - Reminder; Obs - Observation; N/C - Non Compliance

EIA Ref#	EM&A Ref	Environmental Protection Measures / Mitigation Measures	Location / Timing	Status *
6.6.2	5.2.3	Waste Reduction Measures	Works Sites / During	
		Good management and control can prevent the generation of a significant amount of waste. Waste reduction is best achieved at the planning and design stage, as well as by ensuring the implementation of good site practices. Recommendations to achieve waste reduction include:	Construction Phase	
		Segregation and storage of different types of waste in different containers, skips or stockpiles to enhance reuse or recycling of materials and their proper disposal.		✓
		• Encourage collection of aluminium cans, PET bottles and paper by providing separate labelled bins to enable these wastes to be segregated from other general refuse generated by the work force.		✓
		Any unused chemicals or those with remaining functional capacity shall be recycled.		✓
		Use of reusable non-timber formwork to reduce the amount of C&D material.		✓
		• Prior to disposal of C&D waste, it is recommended that wood, steel and other metals shall be separated for re-use and / or recycling to minimise the quantity of waste to be disposed of to landfill.		✓
		Proper storage and site practices to minimise the potential for damage or contamination of construction materials.		✓
		Plan and stock construction materials carefully to minimise amount of waste generated and avoid unnecessary generation of waste.		✓
6.6.4	5.2.5	Construction and Demolition (C&D) Material	Works Sites / During	
		The excavated fill material shall be re-used on-site as backfill material as far as possible.	Construction Phase	✓
		The surplus excavated material should be disposed of at the designated public fill reception facility, as agreed with the Secretary of the Public Fill Committee, for other beneficial uses.		✓
		C&D waste would require disposal to the designated landfill site.		✓
		• In order to monitor the disposal of C&D materials at the public fill reception facility and landfill and to control fly-tipping, a trip-ticket system should be included. One may make reference to ETWB TCW No. 31/2004 for details.		✓

[#] All recommendations and requirements resulted during the course of EIA Process, including ACE and / or accepted public comment to the proposed project.

EIA Ref#	EM&A Ref	Environmental Protection Measures / Mitigation Measures	Location / Timing	Status *
		Ecology		
7.9.2	6.2.2	Construction activities should be confined to developed areas of low ecological value, and there should be no direct impact on other habitats within the Study Area.	Works Sites / During Construction Phase	✓
7.9.3	6.2.3	Noise mitigation measures, including installation of noise-emitting construction plant away from egretry, careful scheduling of noisy works with high disturbance impact to avoid breeding season of ardeid species (i.e. mid March to August) to prevent impacts on nesting activities of Little Egret, operation of well-maintained machinery, careful programming of works and use of noise reduction facilities could be implemented to mitigate noise impacts arised from construction activities such as road widening and road paving. Temporary noise barrier should also be used to reduce the level of noise during construction. Noise impact would be minimised during operation phase as permanent noise barrier has been proposed to be constructed. The use of low noise road surfacing could also reduce the level of noise during operation.	Works Sites / During Construction Phase	√
7.9.4	6.2.4	In order to minimise the impact of construction dust to the vegetation and associated wildlife within and around the proposed Works Area, the following mitigation measures should be implemented: • regular watering	Works Sites / During Construction Phase	√
		complete coverage of dusty material storage piles		✓
		the use of minimum practical height for dropping excavated material		✓
7.9.6	6.2.6	To minimise the indirect impacts to the nearby Tuen Mun River Channel, the following mitigation measures should be implemented:	Works Sites / During Construction Phase	,
		Site runoff could be directed towards regularly cleaned and maintained sand traps, silt traps and where appropriate		√ N/O
		Oil/grease separators to minimise risk of sedimentation and pollution to the river channel.		IN/O
		 Debris and rubbish generated on-site should be collected, handled and disposed properly. 		✓

EIA Ref#	EM&A Ref	Environmental Protection Measures / Mitigation Measures	Location / Timing	Status *
7.9.5	6.2.5	Standard good site practice measures should be implemented and should include:	Works Sites / During	
		Placement of equipment in designated Works Areas within the existing disturbed land.	Construction Phase	✓
		Construction activities should be restricted to the proposed Works Area.		✓
		The proposed Works Area should be reinstated immediately after completion of the works.		✓
		Open burning on proposed works site is illegal, and will be strictly enforced.		./
		Waste skips should be provided to collect general refuse and construction wastes, which should be disposed regularly and properly off-site.		√
		Soil contaminated by fuel leaked from construction plants should be removed and treated.		N/O
7.9.7	6.2.7	To minimise the chance of bird collision during operation phase, falcon sticker, tinted materials, embedded opaque stripes and superimposed patterns of thin opaque stripes are methods that could be used during the design of noise barrier.	Works Sites / During Operation Phase	N/O
7.9.8	6.2.8	Compensatory planting is recommended as the current roadside plantation must be removed to give way to the works. Species of choice should be composed of similar native species and the felling and planting ratio should be no less than 1:1 in terms of quantity.	Works Sites / During Operation Phase	N/O

[#] All recommendations and requirements resulted during the course of EIA Process, including ACE and / or accepted public comment to the proposed project.

EIA Ref#	EM&A Ref	Environmental Protection Measures / Mitigation Measures	Location / Timing	Status *
		Landscape and Visual		
Table 8.8	7.3.1	CM1 Topsoil, where identified, should be stripped and stored for re-use in the construction of the soft landscape works, where practical.		✓
Table 8.8	7.3.1	CM2 Existing trees to be retained on site should be carefully protected during construction.	Maria Citas / During	✓
Table 8.8	7.3.1		Works Sites / During Construction Phase	✓
Table 8.8	7.3.1	CM4 Compensatory tree planting should be provided to compensate for felled trees.	Construction Phase	✓
Table 8.8	7.3.1	CM5 Control of night-time lighting.		✓
Table 8.8	7.3.1	CM6 Erection of decorative screen hoarding compatible with the surrounding setting.		✓

[#] All recommendations and requirements resulted during the course of EIA Process, including ACE and / or accepted public comment to the proposed project.

EIA Ref#	EM&A Ref	Environmental Protection Measures / Mitigation Measures	Location / Timing	Status *
		Land Contamination		
9.8.3	8.2.2	To minimize construction workers' potential contact with the contaminated materials	Excavation zones /	
		• The use of bulk earth-moving excavator equipment would minimise construction workers' potential contact with the contaminated materials;	During excavation	N/O
		• Exposure to any contaminated materials can be minimised by the wearing of appropriate clothing and personal protective equipment such as gloves (when interacting directly with suspected contaminated material), providing adequate hygiene and washing facilities and preventing smoking and eating during such activities;		
		• Stockpiling of contaminated soil should be avoided as far as possible. If this cannot be avoided, the stockpile of contaminated materials should be segregated from the uncontaminated ones. Moreover, the contaminated materials should be properly covered with waterproof material (e.g. tarpaulin sheet) to avoid leaching of contaminants, especially during rainy season.		
		 Vehicles containing any excavated materials should be suitably covered to limit potential dust emissions or contaminated wastewater run-off, and truck bodies and tailgates should be sealed to prevent any leakage during transport or during wet conditions; 		
		 Only licensed waste haulers should be used to collect and transport any contaminated material to an appropriate disposal site and procedures should be developed to ensure that illegal disposal of waste does not occur; 		
		 Necessary waste disposal permits should be obtained, as required, from the appropriate authorities, in accordance with the Waste Disposal Ordinance (Cap 354), Waste Disposal (Chemical Waste) (General) Regulation (Cap 35), as required; 		
		 Records of the quantities of wastes generated and disposed of should be maintained; Adequate washing facilities should be provided on site; and 		
		 In accordance with good construction practice, silt traps should be used to reduce the impact to drainage caused by suspended solids arising from disturbed ground, or any construction materials such as cement and gravel. Groundwater should be disposed of in accordance with the Water Pollution Control Ordinance (Cap 358). 		

All recommendations and requirements resulted during the course of EIA Process, including ACE and / or accepted public comment to the proposed project.

Appendix D

Calibration Certificates and Spreadsheets of Air Monitoring Equipments



TISCH ENVIROMENTAL, INC.
145 SOUTH MIAMI AVE.
VILLAGE OF CLEVES, OH 45002
513.467.9000
877.263.7610 TOLL FREE
513.467.9009 FAX
WWW.TISCH-ENV.COM

AIR POLLUTION MONITORING EQUIPMENT

ORIFICE TRANSFER STANDARD CERTIFICATION WORKSHEET TE-5025A

	eb 22, 2012 Tisch	Rootsmeter Orifice I.I		438320 1378	Ta (K) - Pa (mm) -	295 - 740.41
PLATE OR Run # 1 2 3 4 5	VOLUME START (m3) NA NA NA NA NA	VOLUME STOP (m3) NA NA NA NA NA	DIFF VOLUME (m3) 1.00 1.00 1.00 1.00	DIFF TIME (min) 1.3940 0.9740 0.8720 0.8340 0.6870	METER DIFF Hg (mm) 3.2 6.4 8.0 8.8 12.8	ORFICE DIFF H2O (in.) 2.00 4.00 5.00 5.50 8.00

DATA TABULATION

Vstd	(x axis) Qstd	(y axis)		Va	(x axis) Qa	(y axis)
0.9799 0.9756 0.9734 0.9724 0.9671	0.7029 1.0017 1.1163 1.1660 1.4077	1.4029 1.9841 2.2183 2.3265 2.8059		0.9957 0.9914 0.9891 0.9881 0.9827	0.7142 1.0178 1.1343 1.1848 1.4304	0.8927 1.2624 1.4114 1.4803 1.7853
Qstd slop intercept coefficie	t (b) = ent (r) =	1.99405 -0.00397 0.99984		Qa slope intercept coefficie	t (b) = ent (r) =	1.24864 -0.00252 0.99984
y axis =	SQRT [H20 (Pa/760)(298/	Ta)]	y axis =	SQRT [H2O ([a/Pa)]

CALCULATIONS

Vstd = Diff. Vol[(Pa-Diff. Hg)/760](298/Ta)
Qstd = Vstd/Time

Va = Diff Vol [(Pa-Diff Hg)/Pa]
Qa = Va/Time

For subsequent flow rate calculations:

Qstd = $1/m\{[SQRT(H2O(Pa/760)(298/Ta))] - b\}$ Qa = $1/m\{[SQRT H2O(Ta/Pa)] - b\}$

High Volume Air Sampler Calibration Worksheet

Calibration date

23-Mar-12

Barometric pressure

764 mm Hg

Next Calibration date

22-May-12

Tempature (°C)

17 °C

Sampler location Sampler model

AW Boon Haw Secondary School

Tempature (K)

290 K

Sampler serial number

TE-5170 521

 P_{std} T_{std} 760 mm Hg 298 K

Calibrator model

GMW-2535

Calibrator serial number


1378

2.00078

Slope of the standard curve, ms Intercept of the standard curve, bs

-0.01075

Resistance Plate No.	Manometer Reading (inch H ₂ O)	Flow Recorder Reading (CFM)	Calculated Q _{std} (m³/min)	Continuous Flow Recorder Reading IC (CFM)
5	3.40	26.00	0.94	26.43
7	5.20	34.00	1.16	34.56
10	8.20	42.00	1.46	42.69
13	11.00	53.00	1.69	53.87
18	12.80	58.00	1.82	58.95



Linear Regression

Sampler slope (m):

36.6200

Sampler intercept (b):

-8.5479 Correlation coefficient (R2): 0.9913

Correlation coefficient is greater than 0.9900 and the calibration result is accepted.

Performed by:

Date:

3/3/2012

Checked by:

Date:

High Volume Air Sampler Calibration Worksheet

Calibration date

12-Mar-12

Barometric pressure

760 mm Hg

Next Calibration date

11-May-12

Tempature (°C)

20 °C

Sampler location

Tai Tung Pui Social Service TE-5170

Tempature (K)

293 K

Sampler model Sampler serial number

522

 \mathbf{P}_{std} T_{std}

760 mm Hg 298 K

Calibrator model

GMW-2535 1378


Calibrator serial number Slope of the standard curve, ms

2.00078

Intercept of the standard curve, bs

-0.01075

Resistance Plate No.	Manometer Reading (inch H₂O)	Flow Recorder Reading (CFM)	Calculated Q _{std} (m³/min)	Continuous Flow Recorder Reading IC (CFM)
5	3.40	24.00	0.93	24.20
7	5.40	36.00	1.18	36.31
10	8.60	45.00	1.48	45.38
13	10.90	52.00	1.67	52.44
18	12.80	57.00	1.81	57.48



Linear Regression

Sampler slope (m):

36.9046

Sampler intercept (b):

-9.0434

Correlation coefficient (R²): **0.9923**

Correlation coefficient is greater than 0.9900 and the calibration result is accepted.

Performed by:

Date:

Checked by:

Date:

High Volume Air Sampler Calibration Worksheet

Calibration date

23-Mar-12

Barometric pressure

760 mm Hg

Next Calibration date Sampler location

22-May-12

Tempature (°C)

20 °C

Sampler model

Wu Siu Kui Primary School TE-5170

Tempature (K)

293 K

Sampler serial number

505

 P_{std} $T_{\rm std}$

760 mm Hg 298 K

Calibrator model Calibrator serial number GMW-2535


Slope of the standard curve, ms

1378 2.00078

Intercept of the standard curve, bs

-0.01075

Resistance Plate No.	Manometer Reading (inch H₂O)	Flow Recorder Reading (CFM)	Calculated Q _{std} (m³/min)	Continuous Flow Recorder Reading IC (CFM)
5	3.10	30.00	0.89	30.25
7	5.20	37.00	1.15	37.31
10	8.60	48.00	1.48	48.41
13	10.20	53.00	1.62	53.45
18	12.90	60.00	1.82	60.51



Linear Regression

Sampler slope (m):

33.0486

Sampler intercept (b): Correlation coefficient (R²): 0.9968

-0.0302

Correlation coefficient is greater than 0.9900 and the calibration result is accepted.

Performed by:

Date:

Checked by:


Date:

High Volume Air Sampler Calibration Worksheet

Calibration date 23-Mar-12 Barometric pressure 760 mm Hg **Next Calibration date** 22-May-12 Tempature (°C) 20 ℃ Sampler location Choi Cheung Kok Secondary Tempature (K) 293 K Sampler model Thermo Anderson 760 mm Hg P_{std} Sampler serial number 1278 298 K T_{std}

Calibrator modelGMW-2535Calibrator serial number1378Slope of the standard curve, ms2.00078Intercept of the standard curve, bs-0.01075

Resistance Plate No.	Manometer Reading (inch H₂O)	Flow Recorder Reading (CFM)	Calculated Q _{std} (m³/min)	Continuous Flow Recorder Reading IC (CFM)
5	3.50	29.00	0.95	29.25
7	5.00	34.00	1.13	34.29
10	8.20	47.00	1.45	47.40
13	10.40	52.00	1.63	52.44
18	12.80	58.00	1.81	58.49



Linear Regression

Sampler slope (m): 34.7545
Sampler intercept (b): -4.0684
Correlation coefficient (R²): 0.9959

Correlation coefficient is greater than 0.9900 and the calibration result is accepted.

Performed by:

Checked by:

Date:

Date:

High Volume Air Sampler Calibration Worksheet

Calibration date **Next Calibration date** 23-Mar-12

Barometric pressure

760 mm Hg

Sampler location

22-May-12 Tuen Mun Town Hall Tempature (°C) Tempature (K)

20 °C 293 K

Sampler model Sampler serial number TE-5170 516


 P_{std} T_{std} 760 mm Hg 298 K

Calibrator model Calibrator serial number GMW-2535 1378

Slope of the standard curve, ms Intercept of the standard curve, bs

2.00078 -0.01075

Resistance Plate No.	Manometer Reading (inch H₂O)	Flow Recorder Reading (CFM)	Calculated Q _{std} (m³/min)	Continuous Flow Recorder Reading IC (CFM)
5	3.60	26.00	0.96	26.22
7	5.40	36.00	1.18	36.31
10	8.80	45.00	1.50	45.38
13	10.80	50.00	1.66	50.42
18	13.00	56.00	1.82	56.48



Linear Regression

Sampler slope (m): Sampler intercept (b): 33.7178 -5.0770

Correlation coefficient (R2):

0.9921

Correlation coefficient is greater than 0.9900 and the calibration result is accepted.

Performed by:

Date:

Checked by:

Date:

High Volume Air Sampler Calibration Worksheet

Calibration date

23-Mar-12

Barometric pressure

760 mm Hg

Next Calibration date

22-May-12

Tempature (°C)

20 °C

Sampler location

Yan Oi Tong

Tempature (K)

293 K

Sampler model Sampler serial number TE-5170 510

 P_{std} T_{std} 760 mm Hg 298 K

Calibrator model

Calibrator serial number

GMW-2535

1378


Slope of the standard curve, ms

2.00078

Intercept of the standard curve, bs

-0.01075

Resistance Plate No.	Manometer Reading (inch H₂O)	Flow Recorder Reading (CFM)	Calculated Q _{std} (m³/min)	Continuous Flow Recorder Reading IC (CFM)
5	3.00	26.00	0.88	26.22
7	5.10	34.00	1.14	34.29
10	8.40	43.00	1.47	43.37
13	10.80	48.00	1.66	48.41
18	12.10	53.00	1.76	53.45



Linear Regression

Sampler slope (m):

29.7637

Sampler intercept (b):

0.0197

Correlation coefficient (R2):

0.9948

Correlation coefficient is greater than 0.9900 and the calibration result is accepted.

Performed by:

Date:

Checked by:

Date:

ThermoFisher SCIENTIFIC **27 FORGE PARKWAY** FRANKLIN MA 02038 TOLL FREE: 866-282-0430

TEL: 508-553-6949 FAX: 508-541-8366 www.thermofisher.com

PDR1000 CALIBRATION CERTIFICATE

This calibration is traceable to the National Institute of Standards and Technology

SERIAL NUMBER: 4715

CALIBRATION RATIO: 1.011

AVG. PDR CONCENTRATION: 1.07 mg/m3

MASTER AVG CONCENTRATION: 0.95 mg/m3

PDR BACKROUND CONCENTRATION: 0.123 mg/m3

TEMPERATURE:

74 F RH: 56 %

CALIBRATION MASTER: D319 LAST CALIBRATED: 5/15/2011

TECHNICIAN: Ramon almoste DATE: 6-24-11

Appendix E

Impact Air Quality
Monitoring Results

Ove Arup Partners HK Ltd

Agreement No. HMW 5/2009 (EP) Traffic Improvements to Tuen Mun Road Town Centre Section Impact Air Quality Monitoring Result at Mrs Aw Boon Haw Secondary School (AM1) - 24 hour TSP

			Receptor	Weather	Site	Pressure	e (mmHg)	Tempera	ture (oC)	Flow Recorder Reading (CFM)				TSP	Flow Rat	e (m³/min)	Average Flow	Elapse	e Time	Sampling	Total	(ug/m³)
Filter No.	Month	Date	No.	condition	condition	Initial	Final	Initial	Final	Initial	Final	Initial	Final	weight (g)	Initial	Final	Rate (m³/min)	Start	Finish	Time (mins.)	vol. (m³)	AM1
130658	Apr-12	3-Apr-12	AM1	Fine	Normal Operation	762.0	762.0	24.0	25.0	50.0	50.0	2.7452	2.8042	0.0590	1.6011	1.5988	1.6000	12529.30	12553.30	1440.00	2303.93	25.6
130660	Apr-12	10-Apr-12	AM1	Fine	Normal Operation	759.0	758.0	23.0	25.0	50.0	50.0	2.7443	2.7843	0.0400	1.6008	1.5953	1.5981	12553.30	12577.30	1440.00	2301.19	17.4
130670	Apr-12	16-Apr-12	AM1	Rainy	Normal Operation	756.0	756.0	26.0	21.0	50.0	50.0	2.7507	2.7725	0.0218	1.5912	1.6026	1.5969	12577.30	12601.30	1440.00	2299.54	9.5
130677	Apr-12	20-Apr-12	AM1	Rainy	Normal Operation	756.0	756.0	22.0	23.0	50.0	50.0	2.741	2.7867	0.0457	1.6003	1.5980	1.5992	12601.30	12625.30	1440.00	2302.78	19.8
130682	Apr-12	26-Apr-12	AM1	Cloudy	Normal Operation	757.0	756.0	22.0	21.0	50.0	50.0	2.747	2.8148	0.0678	1.6013	1.6026	1.6020	12625.30	12649.30	1440.00	2306.81	29.4

Average (ug/m³)	20.3
Max (ug/m³)	29.4
Min (ug/m³)	9.5

Action Level (ug/m³)	146
Limit Level (ug/m³)	260

Agreement No. HMW 5/2009 (EP) Traffic Improvements to Tuen Mun Road Town Centre Section Impact Air Quality Monitoring Result at Tai Tung Pui Social Service Building (AM2) - 24 hour TSP

										Flow Reco	der Reading											
			Receptor	Weather	Site	Pressure	(mmHg)	Tempera	ature (oC)	(C	FM)	Filter W	eight (g)	TSP	Flow Rat	e (m³/min)	Average Flow	Elapse	e Time	Sampling	Total	(ug/m³)
Filter No.	Month	Date	No.	condition	condition	Initial	Final	Initial	Final	Initial	Final	Initial	Final	weight (g)	Initial	Final	Rate (m³/min)	Start	Finish	Time	vol. (m³)	AM2
130659	Apr-12	3-Apr-12	AM2	Fine	Normal Operation	762.0	762.0	24.0	25.0	50.0	50.0	2.7484	2.7691	0.0207	1.6040	1.6017	1.6029	6683.10	6707.10	1440.00	2308.10	9.0
130665	Apr-12	10-Apr-12	AM2	Fine	Normal Operation	759.0	758.0	23.0	25.0	50.0	50.0	2.7602	2.8091	0.0489	1.6036	1.5981	1.6009	6707.10	6731.10	1440.00	2305.22	21.2
130671	Apr-12	16-Apr-12	AM2	Rainy	Normal Operation	756.0	756.0	26.0	21.0	50.0	50.0	2.7671	2.7932	0.0261	1.5941	1.6055	1.5998	6731.10	6755.10	1440.00	2303.71	11.3
130679	Apr-12	20-Apr-12	AM2	Rainy	Normal Operation	756.0	756.0	22.0	23.0	50.0	50.0	2.7327	2.7769	0.0442	1.6032	1.6009	1.6021	6755.10	6779.10	1440.00	2306.95	19.2
130683	Apr-12	26-Apr-12	AM2	Cloudy	Normal Operation	757.0	756.0	22.0	21.0	50.0	50.0	2.7538	2.8413	0.0875	1.6041	1.6055	1.6048	6779.10	6803.10	1440.00	2310.91	37.9

Average (ug/m³)	19.7
Max (ug/m³)	37.9
Min (ug/m³)	9.0

Action Level (ug/m ³)	151
Limit Level (ug/m³)	260

Agreement No. HMW 5/2009 (EP) Traffic Improvements to Tuen Mun Road Town Centre Section Impact Air Quality Monitoring Result at Wu Siu Kui Primary School (AM3) - 24 hour TSP

										Flow R	ecorder											
			Receptor	Weather	Site	Pressure	(mmHg)	Tempera	ature (oC)	Readin	g (CFM)	Filter V	/eight (g)	TSP	Flow Rate	e (m³/min)	Average Flow	Elapse	e Time	Sampling	Total	(ug/m³)
Filter No.	Month	Date	No.	condition	condition	Initial	Final	Initial	Final	Initial	Final	Initial	Final	weight (g)	Initial	Final	Rate (m³/min)	Start	Finish	Time	vol. (m³)	AM3
130661	Apr-12	3-Apr-12	AM3	Fine	Normal Operation	762.0	762.0	24.0	25.0	50.0	50.0	2.7446	2.8083	0.0637	1.5184	1.5158	1.5171	10849.39	10873.39	1440.00	2184.62	29.2
130666	Apr-12	10-Apr-12	AM3	Fine	Normal Operation	759.0	758.0	23.0	25.0	50.0	50.0	2.7641	2.7985	0.0344	1.5180	1.5119	1.5150	10873.39	10897.39	1440.00	2181.53	15.8
130672	Apr-12	16-Apr-12	AM3	Rainy	Normal Operation	756.0	756.0	26.0	21.0	50.0	50.0	2.7597	2.7902	0.0305	1.5073	1.5200	1.5137	10897.39	10921.39	1440.00	2179.66	14.0
130680	Apr-12	20-Apr-12	AM3	Rainy	Normal Operation	756.0	756.0	22.0	23.0	50.0	50.0	2.7226	2.7824	0.0598	1.5175	1.5149	1.5162	10921.39	10945.39	1440.00	2183.33	27.4
130684	Apr-12	26-Apr-12	AM3	Cloudy	Normal Operation	757.0	756.0	22.0	21.0	50.0	50.0	2.7525	2.8081	0.0556	1.5186	1.5200	1.5193	10945.39	10969.39	1440.00	2187.79	25.4

Average (ug/m³)	22.4
Max (ug/m³)	29.2
Min (ug/m³)	14.0

Action Level (ug/m	n³) 150
Limit Level (ug/m³	•

Agreement No. HMW 5/2009 (EP) Traffic Improvements to Tuen Mun Road Town Centre Section Impact Air Quality Monitoring Result at Choi Cheung Kok Secondary School (AM4) - 24 hour TSP

			Receptor	Weather	Site	Pressure	(mmHg)	Tempera	ture (oC)	Flow Recor	der Reading	Filter W	eight (g)	TSP	Flow Rate	(m³/min)	Average Flow	Elaps	e Time	Sampling	Total	(ug/m³)
Filter No.	Month	Date	No.	condition	condition	Initial	Final	Initial	Final	Initial	Final	Initial	Final	weight (g)	Initial	Final	Rate (m³/min)	Start	Finish	Time	vol. (m³)	AM4
130662	Apr-12	3-Apr-12	AM4	Fine	Normal Operation	762.0	762.0	24.0	25.0	50.0	50.0	2.746	2.7840	0.0380	1.5600	1.5576	1.5588	11731.12	11755.12	1440.00	2244.67	16.9
130667	Apr-12	10-Apr-12	AM4	Fine	Normal Operation	759.0	758.0	23.0	25.0	50.0	50.0	2.7564	2.7801	0.0237	1.5597	1.5539	1.5568	11755.12	11779.12	1440.00	2241.79	10.6
130673	Apr-12	16-Apr-12	AM4	Rainy	Normal Operation	756.0	756.0	26.0	21.0	50.0	50.0	2.7469	2.7903	0.0434	1.5495	1.5616	1.5556	11779.12	11803.12	1440.00	2239.99	19.4
130681	Apr-12	20-Apr-12	AM4	Rainy	Normal Operation	756.0	756.0	22.0	23.0	50.0	50.0	2.7379	2.8003	0.0624	1.5592	1.5568	1.5580	11803.12	11827.12	1440.00	2243.52	27.8
130687	Apr-12	26-Apr-12	AM4	Cloudy	Normal Operation	757.0	756.0	22.0	21.0	50.0	50.0	2.7378	2.8490	0.1112	1.5602	1.5616	1.5609	11827.12	11851.12	1440.00	2247.70	49.5

Average (ug/m³)	24.8
Max (ug/m³) Min (ug/m³)	49.5
Min (ug/m³)	10.6

Action Level (ug/m³)	150
Limit Level (ug/m³)	260

Agreement No. HMW 5/2009 (EP) Traffic Improvements to Tuen Mun Road Town Centre Section Impact Air Quality Monitoring Result at Tuen Mun Town Hall (AM5) - 24 hour TSP

										Flow Record	der Reading											
			Receptor	Weather	Site	Pressure	(mmHg)	Tempera	ture (oC)	(CF	·M)	Filter We	eight (g)	TSP	Flow Rate	e (m³/min)	Average Flow	Elaps	e Time	Sampling	Total	(ug/m³)
Filter No.	Month	Date	No.	condition	condition	Initial	Final	Initial	Final	Initial	Final	Initial	Final	weight (g)	Initial	Final	Rate (m³/min)	Start	Finish	Time (mins.)	vol. (m³)	AM5
130663	Apr-12	3-Apr-12	AM5	Fine	Normal Operation	762.0	762.0	24.0	25.0	50.0	50.0	2.7487	2.7754	0.0267	1.6379	1.6354	1.6367	11517.27	11541.27	1440.00	2356.78	11.3
130668	Apr-12	10-Apr-12	AM5	Fine	Normal Operation	759.0	758.0	23.0	25.0	50.0	50.0	2.7559	2.7867	0.0308	1.6375	1.6315	1.6345	11541.27	11565.27	1440.00	2353.68	13.1
130675	Apr-12	16-Apr-12	AM5	Rainy	Normal Operation	756.0	756.0	26.0	21.0	50.0	50.0	2.7527	2.8017	0.0490	1.6271	1.6396	1.6334	11565.27	11589.27	1440.00	2352.02	20.8
130685	Apr-12	20-Apr-12	AM5	Rainy	Normal Operation	756.0	756.0	22.0	23.0	50.0	50.0	2.756	2.8176	0.0616	1.6371	1.6346	1.6359	11589.27	11613.27	1440.00	2355.62	26.2
130688	Apr-12	26-Apr-12	AM5	Cloudy	Normal Operation	757.0	756.0	22.0	21.0	50.0	50.0	2.738	2.7984	0.0604	1.6381	1.6396	1.6389	11613.27	11637.27	1440.00	2359.94	25.6

Average (ug/m³)	19.4
Max (ug/m³)	26.2
Min (ug/m³)	11.3


Action Level (ug/m³)	146
Limit Level (ug/m³)	260


Agreement No. HMW 5/2009 (EP) Traffic Improvements to Tuen Mun Road Town Centre Section Impact Air Quality Monitoring Result at Yan Oi Tong Community and Sports Centre (AM6) - 24 hour TSP


			Receptor	Weather	Site	Pressure	(mmHg)	Tempera	ture (oC)	Flow Recorder	Reading (CFM)	Filter W	eight (g)	TSP	Flow Rate	e (m³/min)	Average Flow	Elapse	e Time	Sampling	Total	(ug/m³)
Filter No.	Month	Date	No.	condition	condition	Initial	Final	Initial	Final	Initial	Final	Initial	Final	weight (g)	Initial	Final	Rate (m³/min)	Start	Finish	Time	vol. (m³)	AM6
130664	Apr-12	3-Apr-12	AM6	Fine	Normal Operation	762.0	762.0	24.0	25.0	50.0	50.0	2.7414	2.7831	0.0417	1.6843	1.6814	1.6829	7850.80	7874.80	1440.00	2423.30	17.2
130669	Apr-12	10-Apr-12	AM6	Fine	Normal Operation	759.0	758.0	23.0	25.0	50.0	50.0	2.7696	2.7922	0.0226	1.6838	1.6771	1.6805	7874.80	7898.80	1440.00	2419.85	9.3
130676	Apr-12	16-Apr-12	AM6	Rainy	Normal Operation	756.0	756.0	26.0	21.0	50.0	50.0	2.7517	2.8186	0.0669	1.6720	1.6861	1.6791	7898.80	7922.80	1440.00	2417.83	27.7
130686	Apr-12	20-Apr-12	AM6	Rainy	Normal Operation	756.0	756.0	22.0	23.0	50.0	50.0	2.7293	2.8008	0.0715	1.6833	1.6805	1.6819	7922.80	7946.80	1440.00	2421.94	29.5
130689	Apr-12	26-Apr-12	AM6	Cloudy	Normal Operation	757.0	756.0	22.0	21.0	50.0	50.0	2.7554	2.8202	0.0648	1.6845	1.6861	1.6853	7946.80	7970.80	1440.00	2426.83	26.7


Average (ug/m³)	22.1
Max (ug/m³)	29.5
Min (ug/m³)	9.3


Action Level (ug/m³)	147
Limit Level (ug/m³)	260
































Appendix F

Wind Data

Wind Monitoring Data - April 2012

Date	Wind Direction (degree)	Wind Speed (km/h)			
3-Apr-12	200	6.3			
10-Apr-12	70	14.3			
16-Apr-12	220	19.9			
20-Apr-12	50	15.8			
26-Apr-12	90	23.7			

Source extracted from Hong Kong Observatory (HKO)

Appendix G

Calibration Certificates of Noise Monitoring Equipments



Certificate of Calibration

This is to certify that the equipment

Description: Integrating Sound Level Meter

Manufacturer: Bruel & Kjaer

Model No.: 2238

Serial No.: 2320696

has been calibrated for the specific items and ranges. The results are shown in the Calibration Report No. C113977.

The equipment is supplied by

Co. Name: Ove Arup & Partners Hong Kong Co., Ltd.

Address: Level 5, Festival Walk, 80 Tat Chee Avenue, Kowloon Tong, Kowloon

Date of Issue: 19 July 2011

Certified by: Chen the

The test equipment used for calibration are traceable to the National Standards as specified in this report. This report shall not be reproduced except in full and with prior written approval from this laboratory.

Tel: 2927 2606

Fax: 2744 8986

E-mail: callab@suncreation.com

Website: www.suncreation.com

Certificate of Calibration

This is to certify that the equipment

Description: Acoustical Calibrator

Manufacturer: Bruel & Kjaer

Model No.: 4231

Serial No.: 2713427

has been calibrated for the specific items and ranges. The results are shown in the Calibration Report No. C114108.

The equipment is supplied by

Co. Name: Ove Arup & Partners Hong Kong Co., Ltd.

Address: Level 5, Festival Walk, 80 Tat Chee Avenue, Kowloon Tong, Kowloon

Date of Issue: 26 July 2011

Certified by:

The test equipment used for calibration are traceable to the National Standards as specified in this report. This report shall not be reproduced except in full and with prior written approval from this laboratory.



Certificate of Calibration

This is to certify that the equipment

Description: Integrating Sound Level Meter

Manufacturer: Bruel & Kjaer

Model No.: 2238

Serial No.: 2654435

has been calibrated for the specific items and ranges. The results are shown in the Calibration Report No. C113978.

The equipment is supplied by

Co. Name: Ove Arup & Partners Hong Kong Co., Ltd.

Address: Level 5, Festival Walk, 80 Tat Chee Avenue, Kowloon Tong, Kowloon

Date of Issue: 19 July 2011

Certified by: Um Bu C HC Chan

The test equipment used for calibration are traceable to the National Standards as specified in this report. This report shall not be reproduced except in full and with prior written approval from this laboratory.

Tel: 2927 2606

Fax: 2744 8986

E-mail: callab@suncreation.com

Website: www.suncreation.com



Certificate of Calibration

This is to certify that the equipment

Description: Integrating Sound Level Meter

Manufacturer: Bruel & Kjaer

Model No.: 2238

Serial No.: 2320707

has been calibrated for the specific items and ranges. The results are shown in the Calibration Report No. C114146.

The equipment is supplied by

Co. Name: Ove Arup & Partners Hong Kong Co., Ltd.

Address: Level 5, Festival Walk, 80 Tat Chee Avenue, Kowloon Tong, Kowloon

Date of Issue: 26 July 2011


Certified by:

Tel: 2927 2606

Fax: 2744 8986

E-mail: callab@suncreation.com

Website: www.suncreation.com



Certificate of Calibration

This is to certify that the equipment

Description: Sound Calibrator

Manufacturer: Rion

Model No.: NC-74

Serial No.: 34304660

has been calibrated for the specific items and ranges. The results are shown in the Calibration Report No. C113974.

The equipment is supplied by

Co. Name: Ove Arup & Partners Hong Kong Co., Ltd.

Address: Level 5, Festival Walk, 80 Tat Chee Avenue, Kowloon Tong, Kowloon

Date of Issue: 18 July 2011

Certified by: Uhan Uhan

The test equipment used for calibration are traceable to the National Standards as specified in this report. This report shall not be reproduced except in full and with prior written approval from this laboratory.

Appendix H
Impact Noise
Monitoring Results

Agreement No. 5/2009 (EP) Traffic Improvements to Tuen Mun Road Town Centre Section - Environmental Team Day-time Noise Monitoring Results - 5 April 2012

			Mea	asured Noi	se Level, dB((A)	Baseline Noise Level, dB(A)	Construction Noise Level, dB(A)
ID	Premise	Time	L _{Aeq} ,30min	Limit	L ₁₀ ,5min	L ₉₀ ,5min	L _{Aeq} ,30min	L _{Aeq} ,30min
N1	Kam Fai Garden	10:00 - 10:30	75	75	77	72	76	Measured ≦ Baseline
N2	Tai Tung Pui Social Service Building	10:50 - 11:20	73	75	76	70	78	Measured ≤ Baseline
N3	Yuen Yuen Primary School	11:40 - 12:10	69	70	70	66	69	Measured ≦ Baseline
N4	Wu Siu Kui Primary School	08:30 - 09:00	66	70	68	64	67	Measured ≤ Baseline
N5	Tuen King Building	13:00 - 13:30	70	75	72	67	70	Measured ≤ Baseline
N6	Choi Cheung kok Secondary School	14:00 - 14:30	70	70	72	67	69	61

Note: (#): Construction Noise Level = Measured Noise Level - Baseline Noise Level

Agreement No. 5/2009 (EP) Traffic Improvements to Tuen Mun Road Town Centre Section - Environmental Team Day-time Noise Monitoring Results - 11 April 2012

			Mea	asured Noi	se Level, dB	(A)	Baseline Noise Level, dB(A)	Construction Noise Level, dB(A)
ID	Premise	Time	L _{Aeq} ,30min	Limit	L ₁₀ ,5min	L ₉₀ ,5min	L _{Aeq} ,30min	L _{Aeq} ,30min
N1	Kam Fai Garden	09:50 - 10:20	74	75	76	70	76	Measured ≦ Baseline
N2	Tai Tung Pui Social Service Building	10:45 - 11:15	75	75	77	71	78	Measured ≦ Baseline
N3	Yuen Yuen Primary School	11:40 - 12:10	68	70	70	66	69	Measured ≦ Baseline
N4	Wu Siu Kui Primary School	08:30 - 09:00	65	70	67	64	67	Measured ≦ Baseline
N5	Tuen King Building	13:00 - 13:30	69	75	72	67	70	Measured ≦ Baseline
N6	Choi Cheung kok Secondary School	13:50 - 14:20	68	70	70	67	69	Measured ≦ Baseline

Note: (#): Construction Noise Level = Measured Noise Level - Baseline Noise Level

Agreement No. 5/2009 (EP) Traffic Improvements to Tuen Mun Road Town Centre Section - Environmental Team Day-time Noise Monitoring Results - 21 April 2012


			Mea	asured Noi	se Level, dB	A)	Baseline Noise Level, dB(A)	Construction Noise Level, dB(A)
ID	Premise	Time	L _{Aeq} ,30min	Limit	L ₁₀ ,5min	L ₉₀ ,5min	L _{Aeq} ,30min	L _{Aeq} ,30min
N1	Kam Fai Garden	09:45 - 10:15	72	75	74	69	76	Measured ≦ Baseline
N2	Tai Tung Pui Social Service Building	10:40 - 11:10	73	75	75	71	78	Measured ≦ Baseline
N3	Yuen Yuen Primary School	11:30 - 12:00	67	70	68	65	69	Measured ≦ Baseline
N4	Wu Siu Kui Primary School	08:30 - 09:00	66	70	67	64	67	Measured ≤ Baseline
N5	Tuen King Building	13:00 - 13:30	69	75	71	67	70	Measured ≦ Baseline
N6	Choi Cheung kok Secondary School	13:45 - 14:15	68	70	69	66	69	Measured ≦ Baseline

Note: (#): Construction Noise Level = Measured Noise Level - Baseline Noise Level


Agreement No. 5/2009 (EP) Traffic Improvements to Tuen Mun Road Town Centre Section - Environmental Team Day-time Noise Monitoring Results - 27 April 2012

			Mea	asured Noi	se Level, dB((A)	Baseline Noise Level, dB(A)	Construction Noise Level, dB(A)
ID	Premise	Time	L _{Aeq} ,30min	Limit	L ₁₀ ,5min	L ₉₀ ,5min	L _{Aeq} ,30min	L _{Aeq} ,30min
N1	Kam Fai Garden	09:50 - 10:20	74	75	77	71	76	Measured ≦ Baseline
N2	Tai Tung Pui Social Service Building	10:35 - 11:05	74	75	76	71	78	Measured ≤ Baseline
N3	Yuen Yuen Primary School	11:30 - 12:00	68	70	69	66	69	Measured ≤ Baseline
N4	Wu Siu Kui Primary School	08:30 - 09:00	66	70	68	65	67	Measured ≤ Baseline
N5	Tuen King Building	13:00 - 13:30	70	75	72	68	70	Measured ≤ Baseline
N6	Choi Cheung kok Secondary School	14:00 - 14:30	68	70	70	67	69	Measured ≤ Baseline


Note: (#): Construction Noise Level = Measured Noise Level - Baseline Noise Level




Note: For compliance comparison, please refer to above table and report.




Note: For compliance comparison, please refer to above table and report.




Note: For compliance comparison, please refer to above table and report.




Note: For compliance comparison, please refer to above table and report.




Note: For compliance comparison, please refer to above table and report.




Note: For compliance comparison, please refer to above table and report.




Note: For compliance comparison, please refer to above table and report.




Note: For compliance comparison, please refer to above table and report.




Note: For compliance comparison, please refer to above table and report.



Note: For compliance comparison, please refer to above table and report.



Note: For compliance comparison, please refer to above table and report.



Note: For compliance comparison, please refer to above table and report.

Appendix I

Landscape Summary
Report

Design and Build of Traffic Improvements To Tuen Mun Road Town Centre Section

	No of Contract	Numbers of Contract Tree + UTRA No.1 & No.2							
	Transplant	Transplant							
	<u>362</u>	<u>399</u>							
Total Tree	Fell & Re.	Fell & Remove							
No.	<u>501</u>	<u>521</u>							
	Retain	Retain							
1031	<u>134</u>	<u>102</u>							
1031	Missing Missing								
	<u>0</u>	2							

Unnamed Dead Tree (Removed) In Progress Completed Total Completed (%)

Fell & Remove Status	Crown Pruning	1st Root Pruning	2nd Root Pruning	3rd Root Pruning & Transplant
169				
9 (On Ting E.)				
0	0	29	30	20
521	399	370	369	379
521	399	399	399	399
100%	100%	93%	92%	95%

<u>Item</u>	Drawing No.	Tree No.	Chinese Name	Location	Rec., In Contract Document	Recommendation	Fell & Remove		Crown Pruning		1st Root Pruning		2nd Root Pruning		3rd Root Pruning & Transplant		Remarks
1	6106	TW0001	石栗	Tuen Mun Road near Kam Fai Garden	Transplant	Transplant	N/A	0	08-Apr-11	0	11-Apr-11	0	12-May-11	0	09-Jul-11	0	Falling Down at KF, immediately transplanted to SLS
2	6106	TW0002	石栗	Tuen Mun Road near Kam Fai Garden	Transplant	Transplant	N/A	0	08-Apr-11	0	11-Apr-11	0	12-May-11	0	11-Jul-11	0	Transplanted
3	6106	TW0003	白千層	Tuen Mun Road near Kam Fai Garden	Transplant	Transplant	N/A	0	07-Apr-11	0	24-Dec-10	0	16-Feb-11	0	07-Apr-11	0	Transplanted
4	6106	TW0004	白千層	Tuen Mun Road near Kam Fai Garden	Transplant	Transplant	N/A	0	11-Apr-11	0	24-Dec-10	0	16-Feb-11	0	11-Apr-11	0	Transplanted
5		TW0012	台灣相思	Tuen Mun Road near Kam Fai Garden	Retain	Retain	-	0	-	0	-	0	-	0	-	0	
6		TW0013	檸檬桉	Tuen Mun Road near Kam Fai Garden	Retain	Retain	-	0	-	0	-	0	-	0	-	0	
7		TW0014	大葉桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	08-Apr-11	0	-	0	-	0	-	0	-	0	
8		TW0015	檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	11-Nov-10	0	-	0	-	0	-	0	-	0	
9		TW0016	檸檬桉	Tuen Mun Road near Kam Fai Garden	Retain	Retain	-	0	-	0	-	0	-	0	-	0	
10	-	TW0021	白千層	Tuen Mun Road near Kam Fai Garden	Retain	Retain	-	0	-	0	-	0	-	0	-	0	
11		TW0022	白千層	Tuen Mun Road near Kam Fai Garden	Transplant	Transplant	N/A	0	11-Apr-11	0	29-Dec-10	0	17-Feb-11	0	11-Apr-11	0	Transplanted
12		TW0023	大葉桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	08-Apr-11	0	-	0	-	0	-	0	-	0	
13		TW0024	大葉桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	08-Apr-11	0	-	0	-	0	-	0	-	0	
14		TW0025	大葉桉	Tuen Mun Road near Kam Fai Garden	Retain	Retain	-	0	-	0	-	0	-	0	-	0	
15		TW0026	大葉桉	Tuen Mun Road near Kam Fai Garden	Retain	Retain	-	0	-	0	-	0	-	0	-	0	
10		TW0030	台灣相思	Tuen Mun Road near Kam Fai Garden	Retain	Retain	11 N 10	0	-	0	-	0	-	0	-	0	
10		TW0033 TW0034	台灣相思 台灣相思	Tuen Mun Road near Kam Fai Garden	Fell Fell	Fell Fell	11-Nov-10	0	-	0	-	0	-	0	-	0	
18			大葉桉	Tuen Mun Road near Kam Fai Garden Tuen Mun Road near Kam Fai Garden	Fell		11-Nov-10	0	-	0	-	0	-	0	-	0	
20	-	TW0035 TW0036	檸檬桉	Tuen Mun Road near Kam Fai Garden Tuen Mun Road near Kam Fai Garden	Fell	Fell Fell	08-Apr-11 11-Nov-10	0	-	0	-	0	-	0	-	0	
21		TW0037	檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	11-Nov-10 11-Nov-10	0	-	0	-	0	-	0	-	0	
22		TW0040	1學1家1女 Missing	Tuen Mun Road near Kam Fai Garden Tuen Mun Road near Kam Fai Garden	Retain		Missing	0	-	0	-	0	<u>-</u>	0	-	0	Missing
23		TW0040	白千層	Tuen Mun Road near Kam Fai Garden	Retain	Retain	19-Nov-11	0	-	0	-	0	-	0	<u>-</u>	0	felled by sub-con
24		TW0043	白千層	Tuen Mun Road near Kam Fai Garden Tuen Mun Road near Kam Fai Garden	Transplant	Transplant	N/A	0	13-Apr-11	0	31-Dec-10	0	17-Feb-11	0	13-Apr-11	0	Transplanted
25		TW0044	白千層	Tuen Mun Road near Kam Fai Garden Tuen Mun Road near Kam Fai Garden	Transplant	Transplant	N/A	0	12-Apr-11	0	31-Dec-10	0	18-Feb-11	0	12-Apr-11	0	Transplanted
26		TW0045	白千層	Tuen Mun Road near Kam Fai Garden	Transplant	Transplant	N/A	0	12-Apr-11	0	12-Jan-11	0	18-Feb-11	0	12-Apr-11	0	Transplanted
27		TW0047	台灣相思	Tuen Mun Road near Kam Fai Garden	Retain	Retain	-	0	- 12 Hpi 11	0	-	0	-	0		0	Transplanted
28	-	TW0049	台灣相思	Tuen Mun Road near Kam Fai Garden	Fell	Fell	11-Nov-10	0	_	0	_	0	_	0	_	0	
29		TW0050	台灣相思	Tuen Mun Road near Kam Fai Garden	Fell	Fell	11-Nov-10	0	_	0	_	0	_	0		0	
30		TW0054	大葉桉	Tuen Mun Road near Kam Fai Garden	Retain	Retain	-	0	_	0	_	0	-	0	_	0	
31		TW0055	大葉桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	12-Apr-11	0	_	0	_	0	-	0	-	0	
32		TW0056	大葉桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	11-Nov-10	0	-	0	-	0	-	0	-	0	
33		TW0057	檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	11-Nov-10	0	-	0	-	0	-	0	-	0	
34	6106	TW0058	雙翼豆	Tuen Mun Road near Kam Fai Garden	Retain	Retain	-	0	-	0	-	0	-	0	-	0	
35		TW0061	台灣相思	Tuen Mun Road near Kam Fai Garden	Fell	Fell	11-Nov-10	0	-	0	-	0	-	0	-	0	
36	6106	TW0062	台灣相思	Tuen Mun Road near Kam Fai Garden	Fell	Fell	11-Nov-10	0	-	0	-	0	-	0	-	0	
37	6106	TW0066	檸檬桉	Tuen Mun Road near Kam Fai Garden	Retain	Retain	-	0	-	0	-	0	-	0	-	0	
38	6106	TW0071	大葉桉	Tuen Mun Road near Kam Fai Garden	Retain	Retain	-	0	-	0	-	0		0	-	0	
39	6106	TW0072	檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	11-Nov-10	0	-	0	-	0	-	0	-	0	
40	6106	TW0073	大葉桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	11-Nov-10	0	-	0	-	0	-	0		0	
41	6106	TW0074	白千層	Tuen Mun Road near Kam Fai Garden	Transplant	Transplant	N/A	0	13-Apr-11	0	13-Jan-11	0	18-Feb-11	0	13-Apr-11	0	Transplanted
42	6106	TW0075	白千層	Tuen Mun Road near Kam Fai Garden	Transplant	Transplant	N/A	0	13-Apr-11	0	13-Jan-11	0	18-Feb-11	0	13-Apr-11	0	Transplanted
43	6106	TW0076	白千層	Tuen Mun Road near Kam Fai Garden	Retain	Retain	-	0	-	0	-	0	-	0	-	0	

	T 1	T					T		Т	1		1 1			
44	6106	TW0079 台灣相思	Tuen Mun Road near Kam Fai Garden	Retain	Retain	- 0	-	0	-	0	-	0	-	0	
45	6106	TW0080 台灣相思	Tuen Mun Road near Kam Fai Garden	Fell	Fell	11-Nov-10 0	-	0	-	0		0	-	0	
46	6106	TW0081 台灣相思	Tuen Mun Road near Kam Fai Garden	Fell	Fell	11-Nov-10 0	-	0	-	0	-	0	-	0	
47	6106	TW0082 台灣相思	Tuen Mun Road near Kam Fai Garden	Fell	Fell	11-Nov-10 0	-	0	-	0	-	0	-	0	
48	6106	TW0083 台灣相思	Tuen Mun Road near Kam Fai Garden	Fell	Fell	11-Nov-10 0	-	0	-	0	-	0	-	0	
49	t	TW0088 檸檬桉	Tuen Mun Road near Kam Fai Garden	Retain	Retain	- 0	_	0	_	0	-	0	_	0	
50		TW0089 檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	11-Nov-10 0	_	0	_	0		0		0	
51	t	TW0090 檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	11-Nov-10 0	_	0	_	0		0		0	
52	t	TW0093 大葉桉	Tuen Mun Road near Kam Fai Garden Tuen Mun Road near Kam Fai Garden	Retain	Retain	0		0		0		0		0	
53		•				- 0	-	0	-	0	-	0	-	0	
-		TW0095 大葉桉	Tuen Mun Road near Kam Fai Garden	Retain	Retain	- 0	-		-	0	-	0	-	0	
54		TW0096 死樹	Tuen Mun Road near Kam Fai Garden	Remove	Remove	- 0	-	0	-	0	-	0	-	0	
55		TW0097 台灣相思	Tuen Mun Road near Kam Fai Garden	Fell	Fell	11-Nov-10 0	-	0	-	0	-	0	-	0	
56		TW0102 台灣相思	Tuen Mun Road near Kam Fai Garden	Retain	Retain	- 0	-	0	-	0	-	0	-	0	
57	6106	TW0104 台灣相思	Tuen Mun Road near Kam Fai Garden	Retain	Retain	- 0	-	0	-	0	-	0	-	0	
58	6106	TW0106 台灣相思	Tuen Mun Road near Kam Fai Garden	Retain	Retain	- 0	-	0	-	0	-	0	-	0	
59	6106	TW0107 台灣相思	Tuen Mun Road near Kam Fai Garden	Fell	Fell	11-Nov-10 0	-	0	-	0	-	0	-	0	
60	6106	TW0108 台灣相思	Tuen Mun Road near Kam Fai Garden	Fell	Fell	11-Nov-10 0	-	0	-	0	-	0	-	0	
61	6106	TW0112 木麻黄	Tuen Mun Road near Kam Fai Garden	Retain	Retain	- 0	_	0	_	0	-	0	-	0	
62.		TW0113 山指甲	Tuen Mun Road near Kam Fai Garden	Retain	Retain	- 0	-	0	-	()	_	0	_	()	
63	 	TW0114 台灣相思	Tuen Mun Road near Kam Fai Garden Tuen Mun Road near Kam Fai Garden	Retain	Retain	- 0	_	0	_	0	-	0		0	
64		TW0114 台灣相思	Tuen Mun Road near Kam Fai Garden Tuen Mun Road near Kam Fai Garden	Retain	Retain	- 0	_	0		0		0	<u> </u>	0	
65	 					0	-	+	-	0		0		0	
65		TW0116 台灣相思 **	Tuen Mun Road near Kam Fai Garden	Retain	Retain	- 0	-	0	-	U	-	0	-	U	
66		TW0117 木麻黄	Tuen Mun Road near Kam Fai Garden	Fell	Fell	17-Aug-11 0	-	0	-	0	-	U	-	0	
67		TW0118 台灣相思	Tuen Mun Road near Kam Fai Garden	Fell	Fell	17-Aug-11 0	-	0	-	0	-	0	-	0	
68		TW0119 木麻黄	Tuen Mun Road near Kam Fai Garden	Fell	Fell	17-Aug-11 0	-	0	-	0	-	0	-	0	
69	6106	TW0120 檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	17-Aug-11 0	-	0	-	0	-	0	-	0	
70	6106	TW0121 檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	17-Aug-11 0	-	0	-	0	-	0	-	0	
71	6106	TW0122 檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	17-Aug-11 0	-	0	-	0	-	0	-	0	
72	6106	TW0123 檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	17-Aug-11 0	-	0	-	0	-	0	-	0	
73		TW0124 檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	17-Aug-11 0	_	0	_	0	_	0	_	0	
74		TW0125 台灣相思	Tuen Mun Road near Kam Fai Garden	Fell	Fell	17-Aug-11 0	_	0	_	0	_	0	_	0	
75	 	TW0126 台灣相思	Tuen Mun Road near Kam Fai Garden Tuen Mun Road near Kam Fai Garden	Fell	Fell	17-Aug-11 0	_	0	_	0	_	0	_	0	
76		TW0127 台灣相思	Tuen Mun Road near Kam Fai Garden Tuen Mun Road near Kam Fai Garden	Fell	Fell	19-Aug-11 0	_	0	_	0		0	-	0	
70							_	0	-	0		0		0	
70		TW0128 台灣相思	Tuen Mun Road near Kam Fai Garden	Fell	Fell	19-Aug-11 0	-	0	-	0	-	0	-	0	
78	 	TW0130 台灣相思	Tuen Mun Road near Kam Fai Garden	Fell	Fell	19-Aug-11 0	-	0	-	0	-	0	-	0	
79		TW0131 台灣相思	Tuen Mun Road near Kam Fai Garden	Fell	Fell	10-Nov-10 0	-	0	-	0	-	0	-	0	
80		TW0132 台灣相思	Tuen Mun Road near Kam Fai Garden	Fell	Fell	10-Nov-10 0	-	0	-	0	-	0	-	0	
81		TW0133 檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	10-Nov-10 0	-	0	-	0	-	0	-	0	
82	6106	TW0134 檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	10-Nov-10 0	-	0	-	0	-	0	-	0	
83	6106	TW0135 檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	10-Nov-10 0	-	0	-	0	-	0	-	0	
84	6106	TW0136 檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	19-Aug-11 0		0		0	_	0	-	0	
85		TW0137 檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	10-Nov-10 0	-	0	-	0	-	0	-	0	
86		TW0138 檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	19-Aug-11 0	-	0	-	0	-	0	-	()	
87		TW0139 台灣相思	Tuen Mun Road near Kam Fai Garden	Fell	Fell	19-Aug-11 0	_	0	_	0	_	0	_	()	
88		TW0140 檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	19-Aug-11 0	_	0	_	0	_	0	_	0	
89		TW0140 檸檬桉	Tuen Mun Road near Kam Fai Garden Tuen Mun Road near Kam Fai Garden	Fell	Fell	19-Aug-11 0	_	0		0		0	-	0	
00		TW0141 一個		Fell	Fell		-	0	-	0		0		0	
01			Tuen Mun Road near Kam Fai Garden Tuen Mun Road near Kam Fai Garden			19-Aug-11 0	-		-	0	-	0	-	0	
91		TW0144 檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	19-Aug-11 0	-	0	-	U	-	0	-	U	
92		TW0144 檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	18-Aug-10 0	-	0	-	0	-	0	-	0	
93		TW0145 檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	10-Nov-10 0	-	0	-	0	-	0	-	()	
94	 	TW0146 檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	10-Nov-10 0	-	0	-	0	-	0	-	0	
95		TW0147 台灣相思	Tuen Mun Road near Kam Fai Garden	Fell	Fell	19-Aug-11 0	-	0	-	0	-	0	-	0	
96	6106	TW0148 檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	10-Nov-10 0	-	0	-	0	-	0	-	0	
97		TW0149 檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	10-Nov-10 0	-	0		0	-	0	<u> </u>	0	
98			Tuen Mun Road near Kam Fai Garden	Fell	Fell	10-Nov-10 0	-	0	-	0	-	0	-	0	
99		TW0151 檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	18-Aug-10 0	-	0	-	0	-	0	-	0	
100	1	TW0152 檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	18-Aug-10 0	_	0	_	0	-	0	_	0	
101	t	TW0153 檸檬桉	Tuen Mun Road near Kam Fai Garden Tuen Mun Road near Kam Fai Garden	Fell	Fell	18-Aug-10 0	_	0	_	0	<u>-</u>	0	-	0	
102	t		Tuen Mun Road near Kam Fai Garden Tuen Mun Road near Kam Fai Garden	Fell	Fell		-	0	-	0		0		0	
	1	i					-		-	0	-	0	-	0	
_		TW0155 檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	8	-	0	-	0	-	0	-	0	
104	6106	TW0156 檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	18-Aug-10 0	-	0	-	U	-	U	-	U	

	1		1		-		•	-	1	1					
105	6106	TW0157 檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	18-Aug-10 0	-	0	-	0	-	0	-	0	
106	6106	TW0158 檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	18-Aug-10 0	-	0	-	0	-	0	-	0	
107		TW0159 檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	14-Aug-10 0	_	0	_	0	-	0	-	0	
108		TW0160 檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	14-Aug-10 0	_	0	_	0	_	0	_	0	
109		TW0161 檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	16-Aug-10 0	_	0		0		0		0	
110		TW0162 檸檬桉	Tuen Mun Road near Kam Fai Garden Tuen Mun Road near Kam Fai Garden	Fell	Fell		 	0	-	0		0	<u> </u>	0	
110		, , , , , , , , , , , , , , , , , , , ,				16-Aug-10 0	-	_	-	0	-	0	<u>-</u>	0	
111		TW0163 台灣相思	Tuen Mun Road near Kam Fai Garden	Fell	Fell	16-Aug-10 0	-	0	-	0	-	0	-	0	
112		TW0165 檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	18-Aug-10 0	-	0	-	0	-	0	-	0	
113		TW0166 台灣相思	Tuen Mun Road near Kam Fai Garden	Fell	Fell	10-Sep-11 0	-	0	-	0	-	0	-	0	
114		TW0167 台灣相思	Tuen Mun Road near Kam Fai Garden	Fell	Fell	10-Sep-11 0	-	0	-	0	-	0	-	0	
115	6106	TW0168 檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	10-Sep-11 0	-	0	-	0	-	0	-	0	
116	6106	TW0169 檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	10-Sep-11 0	-	0	-	0	-	0	-	0	
117	6106	TW0170 檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	14-Aug-10 0	-	0	-	0	ı	0	-	0	
118	6106	TW0171 台灣相思	Tuen Mun Road near Kam Fai Garden	Fell	Fell	14-Aug-10 0	-	0	-	0	-	0	-	0	
119	6106	TW0172 檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	10-Sep-11 0	-	0	-	0	-	0	-	0	
120	6106	TW0173 檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	10-Sep-11 0	-	0	-	0	-	0	-	0	
121		TW0174 檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	13-Aug-10 0	_	0	_	0	-	0	_	0	
122		TW0175 台灣相思	Tuen Mun Road near Kam Fai Garden	Fell	Fell	13-Aug-10 0	_	0	_	0	_	0	_	0	
123		TW0176 台灣相思	Tuen Mun Road near Kam Fai Garden	Fell	Fell	12-Aug-10 0	_	0	_	0	_	0		0	
124	6106	TW0177 台灣相思	Tuen Mun Road near Kam Fai Garden	Fell	Fell	12-Aug-10 0	_	0	_	0	_	0		0	
125		TW0177	Tuen Mun Road near Kam Fai Garden Tuen Mun Road near Kam Fai Garden	Remove	Remove	13-Aug-10 0		0	_	0		0		0	
							 	0	-	0	-	0	-	0	
126		TW0179 檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	12-Aug-10 0	11		- 11	0	- 11	0	- 11	0	TD - 1 - 1
127		TW0180 垂葉榕	Tuen Mun Road near Kam Fai Garden	Transplant	Transplant	N/A 0	03-Apr-11	0	03-Apr-11	0	03-Apr-11	0	03-Apr-11	0	Transplanted
128		TW0181 檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	11-Aug-10 0	-	0	-	0	-	0	-	0	
129		TW0182 台灣相思	Tuen Mun Road near Kam Fai Garden	Fell	Fell	11-Aug-10 0	-	0	-	0	-	0	-	0	
130		TW0183 台灣相思	Tuen Mun Road near Kam Fai Garden	Fell	Fell	11-Aug-10 0	-	0	-	0	-	0	-	0	
131	6106		Tuen Mun Road near Kam Fai Garden	Fell	Fell	11-Aug-10 0	-	0	-	0	-	0	-	0	
132	6106	TW0186 檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	12-Aug-10 0	-	0	-	0	-	0	-	0	
133	6106	TW0187 台灣相思	Tuen Mun Road near Kam Fai Garden	Fell	Fell	12-Aug-10 0	-	0	-	0	1	0	-	0	
134	6106	TW0188 檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	13-Aug-10 0	-	0	-	0	•	0	-	0	
135	6106	TW0189 檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	13-Aug-10 0	-	0	-	0	-	0	-	0	
136	6106	TW0190 檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	13-Aug-10 0	-	0	-	0	-	0	-	0	
137		TW0191 檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	13-Aug-10 0	_	0	_	0	-	0	_	0	
138		TW0192 檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	14-Aug-10 0	_	0	_	0	_	0	_	0	
139		TW0193 檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	14-Aug-10 0	_	0	_	0	_	0		0	
140		TW0194 檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	14-Aug-10 0	_	0	_	0	_	0	_	0	
1/1		TW0195 檸檬桉	Tuen Mun Road near Kam Fai Garden Tuen Mun Road near Kam Fai Garden	Fell	Fell	14-Aug-10 0	 	0	_	0		0		0	
141							-	0	-	0	-	0	-	0	
142		TW0196 檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	14-Aug-10 0	-		-	0	-	0	-	0	
143		TW0197 檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	12-Aug-10 0	-	0	-	0	-	0	-	0	
144		TW0198 檸檬桉	Tuen Mun Road near Kam Fai Garden	Fell	Fell	12-Aug-10 0	-	0	-	0	-	0	-	0	
145		TW0199 台灣相思	Tuen Mun Road near Kam Fai Garden	Fell	Fell	11-Aug-10 0	-	0	-	0	-	0	-	0	
146		TW0200 台灣相思	Tuen Mun Road near Kam Fai Garden	Fell	Fell	11-Aug-10 0	-	0	-	0	-	0	-	0	
147	6105		Wong Chu Road near Ting Fuk House	Transplant	Transplant	N/A 0	07-Sep-10	0	07-Sep-10	0	30-Oct-10	0	01-Nov-10	0	Transplanted
148	6105		Wong Chu Road near Ting Fuk House	Transplant	Transplant	N/A 0	06-Sep-10	0	24-Sep-10	0	10-Sep-11	0	10-Sep-11	0	Transplanted
149	6105		Wong Chu Road near Ting Fuk House	Remove	Remove	29-May-10 0	-	0	-	0	-	0	<u>-</u>	0	Ref. letter 115
150	6105	TW0583 菩提樹	Wong Chu Road near Ting Fuk House	Transplant	Retain	N/A 0	-	0	-	0	-	0	-	0	
151	6105	TW0584 雙翼豆	Wong Chu Road near Ting Fuk House	Transplant	Retain	N/A 0		0	_	0	_	0	-	0	
152		TW0585 菩提樹	Wong Chu Road near Ting Fuk House	Transplant	Retain	N/A 0	-	0	-	0	_	0	-	0	
153	6105		Wong Chu Road near Ting Fuk House	Transplant	Transplant	N/A 0	07-Sep-10	0	08-Sep-10	0	30-Oct-10	0	01-Nov-10	0	Transplanted
154	6105		Wong Chu Road near Ting Fuk House	Transplant	Missing	20-Jan-11 0		0	-	0	-	0	-	0	Poor Health
155	6104	TW0588 雙翼豆	Wong Chu Road near Ting Fuk House	Transplant	Transplant	20-Jan-11 0		0	-	0	_	0	_	0	Poor Health
156		TW0589 雙翼豆	Wong Chu Road near Ting Fuk House	Transplant	Fell	29-May-10 0	_	0	_	0	_	0	_	0	Ref. letter 115
157		TW0590 朴樹	Wong Chu Road near Ting Fuk House Wong Chu Road near Ting Fuk House	Fell	Fell	29-May-10 0	<u> </u>	0	-	0	-	0		0	Ter. Tettel 113
						-	07 Ana 10	<u> </u>	10 Ana 10	0	24 Com 10	0	20 Oct 10	0	Trongalouted
158			Wong Chu Road near Ting Fuk House	Transplant Transplant	Transplant	N/A 0	07-Aug-10	0	10-Aug-10	U	24-Sep-10	0	30-Oct-10	0	Transplanted Transplanted
159			Wong Chu Road near Ting Fuk House	Transplant	Transplant	N/A 0		0	19-Aug-10	U	22-Sep-10	0	30-Oct-10	U	Transplanted
		TW0593 雙翼豆	Wong Chu Road near Ting Fuk House	Transplant	Fell	29-May-10 0		0	-	0	-	0	-	0	Ref. letter 115
		TW0594 木棉	Wong Chu Road near Ting Fuk House	Transplant	Transplant	N/A 0		0	19-Aug-10	0	22-Sep-10	0	11-Oct-10	0	Transplanted
162		TW0595 石栗	Wong Chu Road near Ting Fuk House	Transplant	Transplant	N/A 0	07-Aug-10	0	19-Aug-10	0	22-Sep-10	0	29-Oct-10	0	Transplanted
		TW0596 木棉	Wong Chu Road near Ting Fuk House	Transplant	Transplant	N/A 0	07-Aug-10	0	10-Aug-10	0	22-Sep-10	0	11-Oct-10	0	Transplanted
164	6104	TW0597 雙翼豆	Wong Chu Road near Ting Fuk House	Transplant	Fell	29-May-10 0	-	0	-	0	-	0	-	0	Ref. letter 115
165	6104	TW0598 -	Wong Chu Road near Ting Fuk House	Fell	-	29-May-10 0	-	0	-	0	-	0	-	0	
															

		,					•		_	1					_	
166	6104	TW0599 -		Wong Chu Road near Ting Fuk House	Fell	-	29-May-10 0	-	0	-	0	-	0	-	0	
167	6104	TW0600 木	卜棉	Wong Chu Road near Ting Fuk House	Transplant	Transplant	N/A 0	07-Aug-10	0	19-Aug-10	0	22-Sep-10	0	11-Oct-10	0	Transplanted
168	6104	TW0601 雙		Wong Chu Road near Ting Fuk House	Transplant	Transplant	20-Jan-11 0	-	0	-	0	-	0	-	0	Poor Health
169	6104	TW0603 石	三栗	Tuen Mun Road near Ting Fuk House	Transplant	Transplant	N/A 0	07-Aug-10	0	05-Mar-11	0	06-Apr-11	0	07-Jun-11	0	Transplanted
170	6104	TW0604 雙		Tuen Mun Road near Ting Fuk House	Transplant	Fell	29-May-10 0	-	0	-	0	-	0	-	0	Ref. letter 115
171	6104	TW0605 石	一栗	Tuen Mun Road near Ting Fuk House	Transplant	Transplant	N/A 0	07-Aug-10	0	05-Mar-11	0	06-Apr-11	0	12-Jul-11	0	Transplanted
172	6104	TW0606 雙		Tuen Mun Road near Ting Fuk House	Transplant	Fell	29-May-10 0	-	0	-	0	-	0	-	0	Ref. letter 115
173	6104	TW0607 雙		Tuen Mun Road near Ting Fuk House	Transplant	Fell	29-May-10 0	-	0	-	0	-	0	-	0	Ref. letter 115
174	6104	TW0608 組	Ⅲ葉榕	Tuen Mun Road near Ting Fuk House	Transplant	Transplant	N/A 0	02-Jun-11	0	03-Jun-11	0	18-Jun-11	0	18-Jul-11	0	Transplanted
175	6104	TW0609 細	Ⅲ葉榕	Tuen Mun Road near Ting Fuk House	Transplant	Transplant	N/A 0	02-Jun-11	0	02-Jun-11	0	15-Jul-11	0	15-Jul-11	0	Transplanted
176	6104	TW0610 組	葉榕	Tuen Mun Road near Ting Fuk House	Transplant	Transplant	N/A 0	31-May-11	0	02-Jun-11	0	28-Jul-11	0	28-Jul-11	0	Transplanted
177	6104	TW0611 細	⊞葉榕	Tuen Mun Road near Ting Fuk House	Transplant	Transplant	N/A 0	22-Sep-10	0	22-Sep-10	0	02-Nov-10	0	07-Jun-11	0	Transplanted
178	6104	TW0612 組	⊞葉榕	Tuen Mun Road near Ting Fuk House	Transplant	Transplant	N/A 0	31-May-11	0	02-Jun-11	0	14-Jul-11	0	14-Jul-11	0	Transplanted
179	6104	TW0613 銀	艮合歡	Tuen Mun Road near Ting Fuk House	Remove	Remove	29-Aug-10 0	-	0	-	0	-	0	-	0	
180	6104	TW0614 紅	⊞葉榕	Tuen Mun Road near Luk Cheung Kwong College	Transplant	Transplant	N/A 0	31-May-11	0	02-Jun-11	0	29-Jul-11	0	29-Jul-11	0	Transplanted
181	6104	TW0615 組	葉榕	Tuen Mun Road near Luk Cheung Kwong College	Transplant	Transplant	N/A 0	02-Jun-11	0	03-Jun-11	0	16-Aug-11	0	16-Aug-11	0	Transplanted
182	6104	TW0616 阿	可江欖仁	Tuen Mun Road near Luk Cheung Kwong College	Transplant	Transplant	N/A 0	10-Sep-10	0	28-Sep-10	0	16-Nov-10	0	18-Nov-10	0	Transplanted
183	6104	TW0617 鳳	1.	Tuen Mun Road near Luk Cheung Kwong College	Transplant	Transplant	N/A 0	10-Sep-10	0	16-Sep-10	0	02-Nov-10	0	18-Nov-10	0	Transplanted
184	6104	TW0618 周	可江欖仁	Tuen Mun Road near Luk Cheung Kwong College	Transplant	Transplant	N/A 0	10-Sep-10	0	30-Sep-10	0	16-Nov-10	0	17-Nov-10	0	Transplanted
185	6104	TW0619 阿	可江欖仁	Tuen Mun Road near Luk Cheung Kwong College	Transplant	Transplant	N/A 0	10-Sep-10	0	30-Sep-10	0	16-Nov-10	0	17-Nov-10	0	Transplanted
186	6104		責葛樹	Tuen Mun Road near Luk Cheung Kwong College	Fell	Fell	29-Aug-10 0	-	0		0		0	-	0	
187	6104	TW0621 黄	責葛樹	Tuen Mun Road near Luk Cheung Kwong College	Fell	Fell	22-Aug-10 0	-	0	-	0	-	0	-	0	
188	6104		責葛樹	Tuen Mun Road near Luk Cheung Kwong College	Fell	Fell	22-Aug-10 0	-	0		0		0	-	0	
189	6104	TW0623 黄	責葛樹	Tuen Mun Road near Luk Cheung Kwong College	Fell	Fell	29-Aug-10 0	-	0	-	0	-	0	-	0	
190	6104		責葛樹	Tuen Mun Road near Luk Cheung Kwong College	Fell	Fell	29-Aug-10 0	-	0	-	0	-	0	-	0	
191	6104		責葛樹	Tuen Mun Road near Luk Cheung Kwong College	Fell	Fell	29-Aug-10 0	-	0	-	0	-	0	-	0	
192	6104			Tuen Mun Road near Luk Cheung Kwong College	Fell	Fell	29-Aug-10 0	-	0	-	0	-	0	-	0	
193	6104		責葛樹	Tuen Mun Road near Luk Cheung Kwong College	Fell	Fell	29-Aug-10 0	-	0	-	0	-	0	-	0	
194	6104		責葛樹	Tuen Mun Road near Luk Cheung Kwong College	Fell	Fell	29-Aug-10 0	-	0	-	0	-	0	-	0	
195	6104		責葛樹	Tuen Mun Road near Luk Cheung Kwong College	Fell	Fell	22-Aug-10 0	-	0	-	0	-	0	-	0	
196	6104		責葛樹	Tuen Mun Road near Luk Cheung Kwong College	Fell	Fell	22-Aug-10 0	-	0	-	0	-	0	-	0	
197	6104			Tuen Mun Road near Luk Cheung Kwong College	Fell	Fell	22-Aug-10 0	-	0	-	0	-	0	-	0	
198	6104	TW0632 -		Tuen Mun Road near Luk Cheung Kwong College	Transplant	Missing	- 0	_	0	-	0	_	Λ	_	0	Missing
199															U	
	0104	TW0633 雙		Tuen Mun Road near Luk Cheung Kwong College	Transplant	Transplant	N/A 0	29-Sep-10	0	29-Sep-10	0	15-Nov-10	0	19-Nov-10	0	
200	6104 6104		<u> </u>	Tuen Mun Road near Luk Cheung Kwong College Tuen Mun Road near Luk Cheung Kwong College	Transplant Transplant	Transplant Transplant	N/A 0 18-Dec-10 0	29-Sep-10 28-Sep-10	0	29-Sep-10 29-Sep-10	0	15-Nov-10 15-Nov-10	0	19-Nov-10 -	0 0	Transplanted
200 201	6104	TW0634 雙		Tuen Mun Road near Luk Cheung Kwong College	Transplant	Transplant	18-Dec-10 0	29-Sep-10 28-Sep-10	0 0	29-Sep-10 29-Sep-10	0 0	15-Nov-10 15-Nov-10	0 0		0 0	
201	6104 6104	TW0634 雙 TW0635 石	雙翼豆 二栗	Tuen Mun Road near Luk Cheung Kwong College Tuen Mun Road near Luk Cheung Kwong College	Transplant Fell	Transplant Fell	18-Dec-10 0 05-Sep-10 0		0 0 0	•	0 0 0		0 0 0		0 0 0	Transplanted
201 202	6104 6104 6104	TW0634 雙 TW0635 石 TW0636 銀	雙翼豆三栗艮合歡	Tuen Mun Road near Luk Cheung Kwong College Tuen Mun Road near Luk Cheung Kwong College Tuen Mun Road near Luk Cheung Kwong College	Transplant Fell Remove	Transplant Fell Remove	18-Dec-10 0 05-Sep-10 0 05-Sep-10 0	28-Sep-10 -	0 0 0 0 0	29-Sep-10 - -	0 0 0 0	15-Nov-10 - -	0 0 0 0	- - -	0 0 0 0	Transplanted Rootball size = 0.5m
201 202 203	6104 6104 6104 6104	TW0634 雙 TW0635 石 TW0636 銀 TW0637 黃	雙翼豆 三栗 艮合歡 責花夾竹桃	Tuen Mun Road near Luk Cheung Kwong College	Transplant Fell Remove Transplant	Transplant Fell Remove Transplant	18-Dec-10 0 05-Sep-10 0 05-Sep-10 0 N/A 0	28-Sep-10	0 0 0 0 0 0	•	0 0 0 0 0		0 0 0 0 0 0		0 0 0 0 0	Transplanted
201 202 203 204	6104 6104 6104 6104 6104	TW0634雙TW0635石TW0636銀TW0637黃TW0638黃	雙翼豆 三栗 艮合歡 黃花夾竹桃 黃花夾竹桃	Tuen Mun Road near Luk Cheung Kwong College	Transplant Fell Remove Transplant Fell	Transplant Fell Remove Transplant Fell	18-Dec-10 0 05-Sep-10 0 05-Sep-10 0 N/A 0 05-Sep-10 0	28-Sep-10 -	0 0 0	29-Sep-10 - -	0 0 0 0 0	15-Nov-10 - -	0 0 0 0 0 0 0	- - -	0 0 0 0 0 0	Transplanted Rootball size = 0.5m Transplanted
201 202 203 204 205	6104 6104 6104 6104 6104 6104	TW0634 雙 TW0635 石 TW0636 銀 TW0637 黃 TW0638 黃 TW0639 台	度翼豆 一栗 長合歡 責花夾竹桃 責花夾竹桃 計灣相思	Tuen Mun Road near Luk Cheung Kwong College	Transplant Fell Remove Transplant Fell Fell	Transplant Fell Remove Transplant Fell Fell	18-Dec-10 0 05-Sep-10 0 05-Sep-10 0 N/A 0 05-Sep-10 0 29-May-10 0	28-Sep-10 -	0 0 0	29-Sep-10 - -	0 0 0 0 0	15-Nov-10 - -	0 0 0 0 0 0 0 0	- - - 09-Nov-10 -	0 0 0 0 0 0 0	Transplanted Rootball size = 0.5m
201 202 203 204	6104 6104 6104 6104 6104 6104 6104	TW0634 雙 TW0635 石 TW0636 銀 TW0637 黃 TW0638 黃 TW0639 台	度翼豆 一栗 艮合歡 責花夾竹桃 黃花夾竹桃 台灣相思 二栗	Tuen Mun Road near Luk Cheung Kwong College	Transplant Fell Remove Transplant Fell Fell Fell	Transplant Fell Remove Transplant Fell	18-Dec-10 0 05-Sep-10 0 05-Sep-10 0 N/A 0 05-Sep-10 0	28-Sep-10 -	0 0 0 0 0	29-Sep-10 - -	0 0 0 0 0 0	15-Nov-10 - -	0 0 0 0 0 0 0 0 0 0	- - - 09-Nov-10 -	0 0 0 0 0 0 0 0	Transplanted Rootball size = 0.5m Transplanted
201 202 203 204 205 206	6104 6104 6104 6104 6104 6104	TW0634 雙 TW0635 石 TW0636 銀 TW0637 黃 TW0638 黃 TW0639 台 TW0640 石 TW0641 -	度翼豆 一栗 長合歡 黃花夾竹桃 黃花夾竹桃 台灣相思 二栗	Tuen Mun Road near Luk Cheung Kwong College Tuen Mun Road Slip Road to Tuen Hing Road	Transplant Fell Remove Transplant Fell Fell Fell Retain	Transplant Fell Remove Transplant Fell Fell Fell Fell	18-Dec-10 0 05-Sep-10 0 05-Sep-10 0 N/A 0 05-Sep-10 0 29-May-10 0 05-Sep-10 0	28-Sep-10 -	0 0 0 0 0	29-Sep-10 - -	0 0 0 0 0 0 0	15-Nov-10 - - 02-Nov-10 - -	0 0 0 0 0 0 0 0	- - - 09-Nov-10 - -	0 0 0 0 0 0 0	Transplanted Rootball size = 0.5m Transplanted
201 202 203 204 205 206 207	6104 6104 6104 6104 6104 6104 6104	TW0634 雙 TW0635 石 TW0636 銀 TW0637 黄 TW0639 台 TW0640 石 TW0641 - TW0642 台	度翼豆 一栗 長合歡 黃花夾竹桃 黃花夾竹桃 台灣相思 二栗 台灣相思	Tuen Mun Road near Luk Cheung Kwong College	Transplant Fell Remove Transplant Fell Fell Fell	Transplant Fell Remove Transplant Fell Fell Fell	18-Dec-10 0 05-Sep-10 0 05-Sep-10 0 N/A 0 05-Sep-10 0 29-May-10 0 05-Sep-10 0	28-Sep-10 -	0 0 0 0 0	29-Sep-10 - -	0 0 0 0 0 0 0 0	15-Nov-10 - - 02-Nov-10 - -	0 0 0 0 0 0 0 0 0	- - - 09-Nov-10 - -	0 0 0 0 0 0 0	Transplanted Rootball size = 0.5m Transplanted
201 202 203 204 205 206 207 208	6104 6104 6104 6104 6104 6104 6104 6104	TW0634 雙 TW0635 石 TW0636 銀 TW0637 黃 TW0639 台 TW0640 石 TW0641 - TW0642 台 TW0643 宮	度翼豆 一栗 長合歡 黃花夾竹桃 黃花夾竹桃 台灣相思 二栗 台灣相思 台灣相思 台灣相思	Tuen Mun Road near Luk Cheung Kwong College Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road	Transplant Fell Remove Transplant Fell Fell Fell Retain Retain	Transplant Fell Remove Transplant Fell Fell Fell Fell - Retain	18-Dec-10 0 05-Sep-10 0 05-Sep-10 0 N/A 0 05-Sep-10 0 29-May-10 0 05-Sep-10 0 - 0	28-Sep-10 -	0 0 0 0 0 0 0	29-Sep-10 - -	0 0 0 0 0 0 0 0	15-Nov-10 - - 02-Nov-10 - -	0 0 0 0 0 0 0 0 0	- - - 09-Nov-10 - - - -	0 0 0 0 0 0 0 0	Transplanted Rootball size = 0.5m Transplanted
201 202 203 204 205 206 207 208 209	6104 6104 6104 6104 6104 6104 6104 6104	TW0634 雙 TW0635 石 TW0636 銀 TW0637 黄 TW0639 台 TW0640 石 TW0641 - TW0642 台 TW0643 宮 TW0644 台	度翼豆 一栗 長合歡 黃花夾竹桃 黃花夾竹桃 台灣相思 一票 台灣相思 台灣相思 台灣相思	Tuen Mun Road near Luk Cheung Kwong College Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road	Transplant Fell Remove Transplant Fell Fell Fell Retain Retain Retain	Transplant Fell Remove Transplant Fell Fell Fell - Retain Retain	18-Dec-10 0 05-Sep-10 0 05-Sep-10 0 N/A 0 05-Sep-10 0 29-May-10 0 05-Sep-10 0 - 0 - 0	28-Sep-10 -	0 0 0 0 0 0 0	29-Sep-10 - -	0 0 0 0 0 0 0 0 0	15-Nov-10 - - 02-Nov-10 - -	0 0 0 0 0 0 0 0 0 0 0	- - - 09-Nov-10 - - - -		Transplanted Rootball size = 0.5m Transplanted
201 202 203 204 205 206 207 208 209	6104 6104 6104 6104 6104 6104 6104 6104	TW0634 雙 TW0635 石 TW0636 銀 TW0637 黃 TW0639 台 TW0640 石 TW0641 - TW0642 台 TW0643 宮 TW0644 台 TW0645 台	雙翼豆 三栗 長合歡 黃花夾竹桃 黃花夾竹桃 台灣相思 台灣相思 台灣相思 台灣相思 台灣相思	Tuen Mun Road near Luk Cheung Kwong College Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road	Transplant Fell Remove Transplant Fell Fell Fell Retain Retain Retain Retain	Transplant Fell Remove Transplant Fell Fell Fell Fell - Retain Retain Retain	18-Dec-10 0 05-Sep-10 0 05-Sep-10 0 N/A 0 05-Sep-10 0 29-May-10 0 - 0 - 0 - 0	28-Sep-10 -	0 0 0 0 0 0 0 0	29-Sep-10 - -	0 0 0 0 0 0 0 0 0	15-Nov-10 - - 02-Nov-10 - -	0 0 0 0 0 0 0 0 0 0 0	- - - 09-Nov-10 - - - -		Transplanted Rootball size = 0.5m Transplanted
201 202 203 204 205 206 207 208 209	6104 6104 6104 6104 6104 6104 6104 6104	TW0634 雙 TW0635 石 TW0636 銀 TW0637 黃 TW0639 台 TW0640 石 TW0641 - TW0642 台 TW0643 宫 TW0644 台 TW0645 台 TW0646 宫	度翼豆 一栗 長合歡 青花夾竹桃 青花夾竹桃 青灣相思 台灣相思 台灣相思 台灣相思 台灣相思 台灣相思 台灣相思	Tuen Mun Road near Luk Cheung Kwong College Tuen Mun Road slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road	Transplant Fell Remove Transplant Fell Fell Fell Retain Retain Retain Retain Retain Retain	Transplant Fell Remove Transplant Fell Fell Fell - Retain Retain Retain Retain Retain	18-Dec-10 0 05-Sep-10 0 05-Sep-10 0 N/A 0 05-Sep-10 0 29-May-10 0 - 0 - 0 - 0 - 0	28-Sep-10 -	0 0 0 0 0 0 0 0 0	29-Sep-10 - -	0 0 0 0 0 0 0 0 0 0	15-Nov-10 - - 02-Nov-10 - -	0 0 0 0 0 0 0 0 0 0 0 0	- - - 09-Nov-10 - - - - - -		Transplanted Rootball size = 0.5m Transplanted
201 202 203 204 205 206 207 208 209	6104 6104 6104 6104 6104 6104 6104 6104	TW0634 雙 TW0635 石 TW0636 銀 TW0637 黄 TW0639 台 TW0640 石 TW0641 - TW0642 台 TW0643 宫 TW0644 台 TW0645 台 TW0646 宫 TW0647 台	度翼豆 司民合歡 黃花夾竹桃 黃花夾竹桃 黃灣相思 百灣相思 百灣相思 百灣相思 百灣相思 百灣相思 百灣相思 百灣相思 百灣相思 百灣相思 百灣相思 百灣相思 百濟相思	Tuen Mun Road near Luk Cheung Kwong College Tuen Mun Road slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road	Transplant Fell Remove Transplant Fell Fell Fell Retain Retain Retain Retain Retain Retain Retain Retain Retain	Transplant Fell Remove Transplant Fell Fell Fell - Retain Retain Retain Retain Retain Retain Retain	18-Dec-10 0 05-Sep-10 0 05-Sep-10 0 N/A 0 05-Sep-10 0 29-May-10 0 - 0 - 0 - 0 - 0 - 0	28-Sep-10 -	0 0 0 0 0 0 0 0 0	29-Sep-10 - -	0 0 0 0 0 0 0 0 0 0	15-Nov-10 - - 02-Nov-10 - -		- - - 09-Nov-10 - - - - - -		Transplanted Rootball size = 0.5m Transplanted Ref. letter 115
201 202 203 204 205 206 207 208 209	6104 6104 6104 6104 6104 6104 6104 6104	TW0634 雙 TW0635 石 TW0636 銀 TW0637 黄 TW0639 台 TW0640 石 TW0641 - TW0642 台 TW0643 宫 TW0644 台 TW0645 台 TW0646 宫 TW0647 台	雙翼豆 司果 最存數 黃花夾竹桃 黃花夾竹桃 台灣用思 台灣相思 台灣相思 台灣相思 台灣相思 台灣相思 台灣相思 台灣相思 台灣和思 台灣和思 台灣和思 台灣和思 台灣和思 台灣和思 台灣和思 台灣和思 台灣一	Tuen Mun Road near Luk Cheung Kwong College Tuen Mun Road slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road	Transplant Fell Remove Transplant Fell Fell Fell Retain	Transplant Fell Remove Transplant Fell Fell Fell - Retain Retain Retain Retain Retain Retain Retain Retain Retain	18-Dec-10 0 05-Sep-10 0 05-Sep-10 0 N/A 0 05-Sep-10 0 29-May-10 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0	28-Sep-10 -	0 0 0 0 0 0 0 0 0 0	29-Sep-10 - -	0 0 0 0 0 0 0 0 0 0 0	15-Nov-10 - - 02-Nov-10 - -		- - - 09-Nov-10 - - - - - - - -		Transplanted Rootball size = 0.5m Transplanted
201 202 203 204 205 206 207 208 209	6104 6104 6104 6104 6104 6104 6104 6104	TW0634 雙 TW0635 石 TW0637 黃 TW0637 黃 TW0639 台 TW0640 石 TW0641 - TW0642 台 TW0643 宫 TW0644 台 TW0645 台 TW0646 宫 TW0647 台	雙翼豆 司果 最存數 黃花夾竹桃 黃花夾竹桃 台灣用思 台灣相思 台灣相思 台灣相思 台灣相思 台灣相思 台灣相思 台灣相思 台灣和思 台灣和思 台灣和思 台灣和思 台灣和思 台灣和思 台灣和思 台灣和思 台灣一	Tuen Mun Road near Luk Cheung Kwong College Tuen Mun Road slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road	Transplant Fell Remove Transplant Fell Fell Fell Retain Fell Retain Fell Fell	Transplant Fell Remove Transplant Fell Fell Fell - Retain	18-Dec-10 0 05-Sep-10 0 05-Sep-10 0 N/A 0 05-Sep-10 0 29-May-10 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0	28-Sep-10 -	0 0 0 0 0 0 0 0 0 0 0	29-Sep-10 - -	0 0 0 0 0 0 0 0 0 0 0	15-Nov-10 - - 02-Nov-10 - -		- - - 09-Nov-10 - - - - - - - -		Transplanted Rootball size = 0.5m Transplanted Ref. letter 115 Night Work
201 202 203 204 205 206 207 208 209 210 211 212 213 214 215	6104 6104 6104 6104 6104 6104 6104 6104	TW0634 雙 TW0635 石 TW0636 銀 TW0637 黃 TW0639 台 TW0640 石 TW0641 - TW0642 台 TW0643 宫 TW0644 台 TW0645 台 TW0646 宫 TW0647 台 TW0677 大	雙翼豆 司果 最存數 黃花夾竹桃 黃花夾竹桃 台灣用思 台灣相思 台灣相思 台灣相思 台灣相思 台灣相思 台灣相思 台灣相思 台灣和思 台灣和思 台灣和思 台灣和思 台灣和思 台灣和思 台灣和思 台灣和思 台灣一	Tuen Mun Road near Luk Cheung Kwong College Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road	Transplant Fell Remove Transplant Fell Fell Fell Retain Retain Retain Retain Retain Retain Retain Retain Fell Missing	Transplant Fell Remove Transplant Fell Fell Fell - Retain	18-Dec-10 0 05-Sep-10 0 05-Sep-10 0 N/A 0 05-Sep-10 0 29-May-10 0 - 0 - 0 - 0 - 0 - 0 13-Mar-11 0	28-Sep-10 -	0 0 0 0 0 0 0 0 0 0 0	29-Sep-10 - -	0 0 0 0 0 0 0 0 0 0 0 0	15-Nov-10 - - 02-Nov-10 - -		- - - 09-Nov-10 - - - - - - - - - -		Transplanted Rootball size = 0.5m Transplanted Ref. letter 115 Night Work Missing
201 202 203 204 205 206 207 208 209 210 211 212 213 214 215	6104 6104 6104 6104 6104 6104 6104 6104	TW0634 雙 TW0635 石 TW0636 銀 TW0637 黃 TW0639 台 TW0640 石 TW0641 - TW0642 台 TW0643 宮 TW0644 台 TW0645 台 TW0646 宮 TW0647 台 TW0677 大 TW0678 -	雙翼豆 司果 最存數 黃花夾竹桃 黃花夾竹桃 台灣用思 台灣相思 台灣相思 台灣相思 台灣相思 台灣相思 台灣相思 台灣相思 台灣和思 台灣和思 台灣和思 台灣和思 台灣和思 台灣和思 台灣和思 台灣和思 台灣一	Tuen Mun Road near Luk Cheung Kwong College Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road	Transplant Fell Remove Transplant Fell Fell Fell Retain Retain Retain Retain Retain Retain Retain Fell Missing Missing	Transplant Fell Remove Transplant Fell Fell Fell - Retain	18-Dec-10 0 05-Sep-10 0 05-Sep-10 0 N/A 0 05-Sep-10 0 29-May-10 0 05-Sep-10 0 - 0 - 0 - 0 - 0 13-Mar-11 0 - 0	28-Sep-10 -	0 0 0 0 0 0 0 0 0 0 0 0	29-Sep-10 - -	0 0 0 0 0 0 0 0 0 0 0 0 0	15-Nov-10 - - 02-Nov-10 - -		- - - 09-Nov-10 - - - - - - - - - -		Transplanted Rootball size = 0.5m Transplanted Ref. letter 115 Night Work Missing
201 202 203 204 205 206 207 208 209 210 211 212 213 214 215 216 217	6104 6104 6104 6104 6104 6104 6104 6104	TW0634 雙 TW0635 石 TW0636 錶 TW0637 黃 TW0638 黃 TW0639 台 TW0640 石 TW0641 - TW0642 台 TW0643 宮 TW0644 台 TW0645 台 TW0646 宮 TW0647 台 TW0677 大 TW0678 - TW0679 -	雙翼豆 司果 最存數 黃花夾竹桃 黃花夾竹桃 台灣用思 台灣相思 台灣相思 台灣相思 台灣相思 台灣相思 台灣相思 台灣相思 台灣和思 台灣和思 台灣和思 台灣和思 台灣和思 台灣和思 台灣和思 台灣和思 台灣一	Tuen Mun Road near Luk Cheung Kwong College Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road	Transplant Fell Remove Transplant Fell Fell Fell Retain	Transplant Fell Remove Transplant Fell Fell Fell - Retain	18-Dec-10 0 05-Sep-10 0 05-Sep-10 0 N/A 0 05-Sep-10 0 29-May-10 0 - 0 - 0 - 0 - 0 13-Mar-11 0 - 0 - 0	28-Sep-10 -	0 0 0 0 0 0 0 0 0 0 0 0 0 0	29-Sep-10 - -	0 0 0 0 0 0 0 0 0 0 0 0 0 0	15-Nov-10 - - 02-Nov-10 - -		- - - 09-Nov-10 - - - - - - - - - - -		Transplanted Rootball size = 0.5m Transplanted Ref. letter 115 Night Work Missing Missing Missing
201 202 203 204 205 206 207 208 209 210 211 212 213 214 215 216 217 218 219	6104 6104 6104 6104 6104 6104 6104 6104	TW0634 雙 TW0635 石 TW0636 銀 TW0637 黃 TW0639 台 TW0640 石 TW0641 - TW0642 台 TW0643 宮 TW0644 台 TW0645 台 TW0647 台 TW0677 大 TW0677 大 TW0678 - TW0680 - TW0681 -	雙翼豆 司限	Tuen Mun Road near Luk Cheung Kwong College Tuen Mun Road slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road	Transplant Fell Remove Transplant Fell Fell Fell Retain	Transplant Fell Remove Transplant Fell Fell Fell - Retain - Retain Retain	18-Dec-10 0 05-Sep-10 0 05-Sep-10 0 N/A 0 05-Sep-10 0 29-May-10 0 - 0 - 0 - 0 - 0 13-Mar-11 0 - 0 - 0	28-Sep-10 17-Sep-10	0 0 0 0 0 0 0 0 0 0 0 0 0 0	29-Sep-10 - -	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	15-Nov-10 - - 02-Nov-10 - -	0 0 0 0 0 0 0 0 0 0	- - - 09-Nov-10 - - - - - - - - - - -		Transplanted Rootball size = 0.5m Transplanted Ref. letter 115 Night Work Missing Missing
201 202 203 204 205 206 207 208 209 210 211 212 213 214 215 216 217 218 219 220	6104 6104 6104 6104 6104 6104 6104 6104	TW0634 雙 TW0635 石 TW0636 銀 TW0637 黃 TW0639 台 TW0640 石 TW0641 - TW0642 台 TW0643 宮 TW0644 台 TW0645 台 TW0646 宮 TW0647 台 TW0677 大 TW0678 - TW0679 - TW0680 - TW0681 -	雙翼豆 同是花夾竹桃 黃花夾竹桃 黃花夾相思 門 一 一 一 一 一 一 一 一 一 一 一 一 一 一 一 一 一 一	Tuen Mun Road near Luk Cheung Kwong College Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road	Transplant Fell Remove Transplant Fell Fell Fell Retain Missing Missing Missing Missing Missing Missing Missing Missing Missing	Transplant Fell Remove Transplant Fell Fell Fell - Retain	18-Dec-10 0 05-Sep-10 0 N/A 0 05-Sep-10 0 29-May-10 0 05-Sep-10 0 - 0 - 0 - 0 - 0 - 0 13-Mar-11 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0	28-Sep-10 17-Sep-10	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	29-Sep-10 17-Sep-10	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	15-Nov-10 02-Nov-10	0 0 0 0 0 0 0 0 0 0	- - - 09-Nov-10 - - - - - - - - - - - - -		Transplanted Rootball size = 0.5m Transplanted Ref. letter 115 Night Work Missing Missing Missing Missing Missing Missing Missing
201 202 203 204 205 206 207 208 209 210 211 212 213 214 215 216 217 218 219 220 221	6104 6104 6104 6104 6104 6104 6104 6104	TW0634 雙 TW0635 石 TW0637 黃 TW0637 黃 TW0639 台 TW0640 石 TW0641 - TW0642 台 TW0643 宮 TW0644 台 TW0645 台 TW0647 台 TW0677 大 TW0677 大 TW0679 - TW0680 - TW0681 - TW0683 - TW0684 -	雙翼豆 同是花夾竹桃 黃花夾竹桃 黃花夾相思 門 一 一 一 一 一 一 一 一 一 一 一 一 一 一 一 一 一 一	Tuen Mun Road near Luk Cheung Kwong College Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road	Transplant Fell Remove Transplant Fell Fell Fell Retain Right and Retain Retain Retain Right and Retain Retain Right and Right and Retain Right and Ri	Transplant Fell Remove Transplant Fell Fell Fell Fell - Retain	18-Dec-10 0 05-Sep-10 0 N/A 0 05-Sep-10 0 29-May-10 0 05-Sep-10 0 - 0 - 0 - 0 - 0 - 0 13-Mar-11 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0	28-Sep-10 17-Sep-10	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	29-Sep-10 17-Sep-10	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	15-Nov-10 02-Nov-10		- - - 09-Nov-10 - - - - - - - - - - - - - -		Transplanted Rootball size = 0.5m Transplanted Ref. letter 115 Night Work Missing Missing Missing Missing Missing Missing Missing Missing Missing
201 202 203 204 205 206 207 208 209 210 211 212 213 214 215 216 217 218 219 220 221 222	6104 6104 6104 6104 6104 6104 6104 6104	TW0634 雙 TW0635 石 TW0636 錶 TW0637 黃 TW0638 黃 TW0639 台 TW0640 石 TW0641 - TW0642 台 TW0644 台 TW0645 台 TW0645 台 TW0647 台 TW0677 大 TW0678 - TW0679 - TW0680 - TW0681 - TW0683 - TW0684 - TW0685 -	雙翼豆 同是花夾竹桃 黃花夾竹桃 黃花夾相思 門 一 一 一 一 一 一 一 一 一 一 一 一 一 一 一 一 一 一	Tuen Mun Road near Luk Cheung Kwong College Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road	Transplant Fell Remove Transplant Fell Fell Fell Retain Retain Retain Retain Retain Retain Retain Retain Retain Missing	Transplant Fell Remove Transplant Fell Fell Fell Fell - Retain	18-Dec-10 0 05-Sep-10 0 N/A 0 05-Sep-10 0 29-May-10 0 05-Sep-10 0 - 0 - 0 - 0 - 0 - 0 13-Mar-11 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0	28-Sep-10 17-Sep-10	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	29-Sep-10 17-Sep-10		15-Nov-10 02-Nov-10	0 0 0 0 0 0 0 0 0 0	- - - 09-Nov-10 - - - - - - - - - - - - - -		Transplanted Rootball size = 0.5m Transplanted Ref. letter 115 Night Work Missing
201 202 203 204 205 206 207 208 209 210 211 212 213 214 215 216 217 218 219 220 221 222 223	6104 6104 6104 6104 6104 6104 6104 6104	TW0634 雙 TW0635 石 TW0637 黃 TW0637 黃 TW0639 台 TW0640 石 TW0641 - TW0642 台 TW0643 宮 TW0644 台 TW0645 台 TW0647 台 TW0677 大 TW0677 大 TW0679 - TW0680 - TW0681 - TW0681 - TW0683 - TW0684 - TW0685 - TW0685 - TW0686 -	隻翼豆 司民在花夾竹桃 青花夾竹木 青河 灣門 一灣大樓 一個 一個 一個 一個 一個 一個 一個 一個 一個 一個 一個 一個 一個	Tuen Mun Road near Luk Cheung Kwong College Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road	Transplant Fell Remove Transplant Fell Fell Fell Retain Retain Retain Retain Retain Retain Retain Retain Rissing Missing	Transplant Fell Remove Transplant Fell Fell Fell Fell - Retain	18-Dec-10 0 05-Sep-10 0 N/A 0 05-Sep-10 0 29-May-10 0 05-Sep-10 0 - 0 - 0 - 0 - 0 - 0 13-Mar-11 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0	28-Sep-10 17-Sep-10	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	29-Sep-10 17-Sep-10		15-Nov-10 02-Nov-10	0 0 0 0 0 0 0 0 0 0	- - - 09-Nov-10 - - - - - - - - - - - - - - - - - -		Transplanted Rootball size = 0.5m Transplanted Ref. letter 115 Night Work Missing
201 202 203 204 205 206 207 208 209 210 211 212 213 214 215 216 217 218 219 220 221 222 223 224	6104 6104 6104 6104 6104 6104 6104 6104	TW0634 雙 TW0635 石 TW0636 錶 TW0637 黃 TW0638 黃 TW0639 台 TW0640 石 TW0641 - TW0642 台 TW0643 宮 TW0644 台 TW0645 台 TW0647 台 TW0677 大 TW0678 - TW0679 - TW0680 - TW0681 - TW0681 - TW0682 - TW0683 - TW0684 - TW0685 - TW0686 - TW0687 台	隻翼豆 豆 長 豆 長 豆 豆 豆 豆 豆 豆 豆 一 三 三 三 三 三 三 三 三 三 三 三 三	Tuen Mun Road near Luk Cheung Kwong College Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road	Transplant Fell Remove Transplant Fell Fell Fell Retain Retain Retain Retain Retain Retain Retain Retain Missing Fell Missing Missing Fell Fell Fell Missing	Transplant Fell Remove Transplant Fell Fell Fell Fell - Retain	18-Dec-10 0 05-Sep-10 0 N/A 0 05-Sep-10 0 29-May-10 0 05-Sep-10 0 - 0 - 0 - 0 - 0 - 0 13-Mar-11 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 13-Mar-11 0	28-Sep-10 17-Sep-10	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	29-Sep-10 17-Sep-10		15-Nov-10 02-Nov-10	0 0 0 0 0 0 0 0 0 0	- - - 09-Nov-10 - - - - - - - - - - - - - - - - - -		Transplanted Rootball size = 0.5m Transplanted Ref. letter 115 Night Work Missing
201 202 203 204 205 206 207 208 209 210 211 212 213 214 215 216 217 218 219 220 221 222 223	6104 6104 6104 6104 6104 6104 6104 6104	TW0634 雙 TW0635 石 TW0637 黃 TW0637 黃 TW0639 台 TW0640 石 TW0641 - TW0642 台 TW0643 宫 TW0644 台 TW0645 台 TW0647 台 TW0677 大 TW0677 大 TW0679 - TW0680 - TW0681 - TW0682 - TW0683 - TW0684 - TW0684 - TW0685 - TW0686 - TW0687 台 TW0687 台 TW0688 台	雙翼 要 電影 表 表 表 表 表 表 表 表 表 表 表 表 表 表 表 表 表 表 表	Tuen Mun Road near Luk Cheung Kwong College Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road	Transplant Fell Remove Transplant Fell Fell Fell Retain Retain Retain Retain Retain Retain Retain Retain Rissing Missing	Transplant Fell Remove Transplant Fell Fell Fell Fell - Retain	18-Dec-10 0 05-Sep-10 0 N/A 0 05-Sep-10 0 29-May-10 0 05-Sep-10 0 - 0 - 0 - 0 - 0 - 0 13-Mar-11 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0	28-Sep-10	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	29-Sep-10 17-Sep-10		15-Nov-10 02-Nov-10	0 0 0 0 0 0 0 0 0 0	- - - 09-Nov-10 - - - - - - - - - - - - - - - - - -		Transplanted Rootball size = 0.5m Transplanted Ref. letter 115 Night Work Missing

227	5103	TW0690 ±	台灣相思	Tuen Mun Road Slip Road to Tuen Hing Road	Fell	Retain	13-Mar-11 0	-	0	-	0	-	0	-	0	Night Work
228	5103	TW0691 -		Tuen Mun Road Slip Road to Tuen Hing Road	Missing	Retain	- 0	-	0	_	0	_	0	_	0	Missing
	5103	TW0692 -		Tuen Mun Road Slip Road to Tuen Hing Road	Remove	_	- 0	-	0	_	0	-	0	_	0	<u> </u>
			台灣相思	Tuen Mun Road Slip Road to Tuen Hing Road	Fell	Retain	13-Mar-11 0	_	0	_	0	_	0	_	0	Night Work
				Tuen Mun Road Slip Road to Tuen Hing Road Tuen Mun Road Slip Road to Tuen Hing Road	Fell	Retain	13-Mar-11 0	_	0		0	_	0		0	Night Work
 							†	-	0	-	0	<u> </u>	0		0	_
				Tuen Mun Road Slip Road to Tuen Hing Road	Fell	Retain	13-Mar-11 0	-		-	0	<u>-</u>	0	-	0	Night Work
				Tuen Mun Road Slip Road to Tuen Hing Road	Fell	Retain	13-Mar-11 0	-	0	-	0	-	0	-	0	Night Work
				Tuen Mun Road Slip Road to Tuen Hing Road	Fell	Retain	13-Mar-11 0	-	0	-	0	-	0	-	0	Night Work
	5103			Tuen Hi Road near Tuen Mun Road (YL/B)	Fell	Retain	13-Mar-11 0	-	0	-	0	-	0	-	0	Night Work
236	5103	TW0699 宮	宮粉羊蹄甲	Tuen Hi Road near Tuen Mun Road (YL/B)	Retain	Retain	- 0	-	0	-	0	-	0	-	0	
237	5103	TW0700 責	黃葛樹	Tuen Fat Road near Tuen Lee Street	Fell	Fell	12-Oct-10 0	-	0	-	0	-	0	-	0	Night Work
238	5103	TW0701 石	石栗	Tuen Fat Road near Tuen Lee Street	Fell	Fell	12-Oct-10 0	-	0	-	0	-	0	-	0	Night Work
	5103	TW0702 程	石栗	Tuen Fat Road near Tuen Lee Street	Fell	Fell	12-Oct-10 0	-	0	-	0	-	0	-	0	Night Work
		 	石栗	Tuen Fat Road near Tuen Lee Street	Fell	Fell	12-Oct-10 0	_	0	_	0		0		0	Night Work
				Tuen Fat Road near Tuen Lee Street	Fell	Fell	12-Oct-10 0	_	0	_	0		0		0	Night Work
		<u> </u>	<u>日本</u> 白千層	Tuen Fat Road near Tuen Lee Street	Fell	Fell	12-Oct-10 0		0		0	<u> </u>	0	<u> </u>	0	Night Work
								-		-	0	-	0	-	0	
			黃葛樹	Tuen Fat Road near Tuen Lee Street	Fell	Fell	12-Oct-10 0	-	0	-	0	-	0	-	0	Night Work
		<u> </u>	石栗	Tuen Fat Road near Tuen Yan Street	Fell	Fell	08-Oct-10 0	-	0	-	0	-	0	-	0	Night Work
		TW0708 -	•	Tuen Fat Road near Tuen Yan Street	Fell	-	08-Oct-10 0	-	0	-	0	-	0	-	0	Night Work
		 	石栗	Tuen Fat Road near Tuen Yan Street	Fell	Fell	08-Oct-10 0	-	0	-	0	-	0	-	0	Night Work
247	5102	TW0710 責	黃葛樹	Tuen Fat Road near Tuen Yan Street	Fell	Fell	08-Oct-10 0	-	0	-	0	-	0	-	0	Night Work
248	5102	TW0711 原	鳳凰木	Tuen Fat Road near Tuen Yan Street	Fell	Fell	08-Oct-10 0	-	0	-	0	-	0	_	0	Night Work
			白千層	Tuen Fat Road near Tuen Yan Street	Fell	Fell	08-Oct-10 0	-	0	-	0	-	0	-	0	Night Work
		 	白千層	Tuen Fat Road near Tuen Yan Street	Fell	Fell	09-Oct-10 0	-	0	_	0	-	0	_	0	Night Work
	5102	 		Tuen Fat Road near Tuen Yan Street	Fell	Fell	09-Oct-10 0	_	0	_	0		0		0	Night Work
			11年 石栗	Tuen Fat Road near Tuen Yan Street	Fell	Fell	08-Oct-10 0		0	_	0		0		0	Night Work
		 					1	-	0	-	0	<u> </u>	0		0	_
				Tuen Fat Road near Tuen Yan Street	Fell	Fell	09-001-10	-	U	-	0	-	0	-	0	Night Work
		 	<u> 木棉</u>	Tuen Fat Road near Tuen Yan Street	Fell	Fell	09-Oct-10 0	-	0	-	0	-	0	-	0	Night Work
		 	石栗	Tuen Fat Road near Tuen Yan Street	Fell	Fell	09-Oct-10 0	-	0	-	0	-	0	-	0	Night Work
256	5101		白千層	Centre Median near Yan Oi Tong	Fell	Fell	31-Dec-10 0	-	0	-	0	-	0	-	0	Night Work
257	5101	TW0720 É	白千層	Centre Median near Yan Oi Tong	Fell	Fell	31-Dec-10 0	-	0	-	0	-	0	-	0	Night Work
258	5101	TW0722 ナ	大葉桉	Centre Median near Yan Oi Tong	Fell	Fell	31-Dec-10 0	-	0	-	0	-	0	-	0	Night Work
259	5102	TW0723 -	•	Centre Median near Tuen Yan Street	Fell	-	Done 0	-	0	-	0	-	0	-	0	Missing
260	5102	TW0724 É	白千層	Centre Median near Tuen Yan Street	Fell	Fell	13-Oct-10 0	-	0	-	0	-	0	-	0	Night Work
		 	白千層	Centre Median near Tuen Yan Street	Fell	Fell	13-Oct-10 0	-	0	_	0	_	0	_	0	Night Work
	5102			Centre Median near Tuen Yan Street	Fell	Fell	13-Oct-10 0	_	0	_	0	_	0		0	Night Work
				Centre Median near Tuen Yan Street	Fell	Fell	13-Oct-10 0	_	0	_	0	_	0		0	Night Work
			以 <u>資</u> ((1)					-	0	-	0		0		0	_
				Centre Median near Tuen Yan Street	Fell	Fell	13-Oct-10 0	-	0	-	0	<u>-</u>	0	-	0	Night Work
	5102		<u>白千層</u>	Centre Median near Tuen Yan Street	Fell	Fell	13-Oct-10 0	-	0	-	0	-	0	-	0	Night Work
	5102	 	白千層	Centre Median near Tuen Yan Street	Fell	Fell	13-Oct-10 0	-	0	-	0	-	0	-	0	Night Work
_		<u> </u>	白千層	Centre Median near Tuen Yan Street	Fell	Fell	13-Oct-10 0	-	0	-	0	-	0	-	0	Night Work
268	5102	TW0732 É	白千層	Centre Median near Tuen Yan Street	Fell	Fell	13-Oct-10 0	-	0	-	0	-	0	-	0	Night Work
269	5102	TW0733 É	白千層	Centre Median near Tuen Yan Street	Fell	Fell	13-Oct-10 0	-	0	-	0	-	0	-	0	Night Work
270	5102	TW0734 É	白千層	Centre Median near Tuen Yan Street	Fell	Fell	13-Oct-10 0		0	-	0		0	-	0	Night Work
271	5102	TW0735 石	石栗	Centre Median near Tuen Yan Street	Fell	Fell	15-Oct-10 0	-	0	-	0	-	0	-	0	Night Work
	5102	 		Centre Median near Tuen Yan Street	Fell	Fell	15-Oct-10 0	-	0	-	0	-	0	-	0	Night Work
_			石栗	Centre Median near Tuen Yan Street	Fell	Fell	13-Oct-10 0	_	0	_	0		0		0	Night Work
		 	11米 白千層	Centre Median near Tuen Yan Street	Fell	Fell	13-Oct-10 0		0	_	0		0	<u> </u>	0	Night Work
		<u> </u>					 	-	0	-	0	-	0		0	
	6102		白千層	Centre Median near Tuen Yan Street	Fell	Fell	13-Oct-10 0	-		-	U	-	U	-	0	Night Work
	6102	 	黄葛樹	Centre Median near Tuen Yan Street	Fell	Fell	15-Oct-10 0	-	0	-	Û		U	-	Û	Night Work
			石栗	Centre Median near Tuen Yan Street	Fell	Fell	19-Oct-10 0	-	0	-	0	-	0	-	0	Night Work
—		 	石栗	Centre Median near Tuen Yan Street	Fell	Fell	14-Oct-10 0	-	0	-	0	-	0	-	0	Night Work
279	5102	TW0743 責	黄葛樹	Centre Median near Tuen Yan Street	Fell	Fell	19-Oct-10 0	-	0	-	0	-	0	-	0	Night Work
280	5102	TW0744	石栗	Centre Median near Tuen Yan Street	Fell	Fell	19-Oct-10 0	<u>-</u>	0	-	0	_	0	<u>-</u>	0	Night Work
-		TW0745 名		Centre Median near Tuen Yan Street	Fell	Fell	14-Oct-10 0	-	0	-	0	-	0	-	0	Night Work
				Centre Median between Tuen Shing St & Tuen Hing Rd	Fell	Fell	13-Oct-10 0	-	0	-	0	-	0	-	0	Night Work
			<u> </u>	Centre Median between Tuen Shing St & Tuen Hing Rd	Fell	Fell	13-Oct-10 0	_	0	_	0	_	0		0	Night Work
		i — i —	□ 	Centre Median between Tuen Shing St & Tuen Hing Rd Centre Median between Tuen Shing St & Tuen Hing Rd	Fell	Fell	13-Oct-10 0		0	_	0	<u>-</u>	0		0	Night Work
			口米 白千層		Fell		1	-	0	-	0		0		0	
		 		Centre Median between Tuen Shing St & Tuen Hing Rd		Fell	13-Oct-10 0	-		-	0	-	0	-	0	Night Work
			鳳凰木	Centre Median between Tuen Shing St & Tuen Hing Rd	Fell	Fell	13-Oct-10 0	-	0	-	U	-	U	-	U	Night Work
287	5103	TW0751 責	黃葛樹	Centre Median between Tuen Shing St & Tuen Hing Rd	Fell	Fell	13-Oct-10 0	-	0	-	U	-	0	-	0	Night Work

	T	1	T	T	ļ	ı		1	T			_	T	1	
288 6103	TW0752	Centre Median between Tuen Shing St & Tuen Hing Rd	Fell	Fell	14-Oct-10	0	-	0	-	0	-	0	-	0	Night Work
289 6103	TW0753 黃葛樹	Centre Median between Tuen Shing St & Tuen Hing Rd	Fell	Fell	14-Oct-10	0	-	0	-	0	-	0	-	0	Night Work
290 6103	TW0754 白千層	Centre Median between Tuen Shing St & Tuen Hing Rd	Fell	Fell	07-Oct-10	0	-	0	-	0	-	0	-	0	Night Work
291 6103	TW0755 白千層	Centre Median between Tuen Shing St & Tuen Hing Rd	Fell	Fell	07-Oct-10	0	_	0	_	0	_	0	_	0	Night Work
292 6103	TW0756 石栗	Centre Median between Tuen Shing St & Tuen Hing Rd	Fell	Fell	07-Oct-10	0	_	0	_	0	_	0	_	0	Night Work
293 6103	TW0757 石栗	Centre Median between Tuen Shing St & Tuen Hing Rd	Fell	Fell	07-Oct-10	0		0		0		0		0	Night Work
							-		-		-	0	-	0	
294 6103	TW0758 白千層	Centre Median between Tuen Shing St & Tuen Hing Rd	Fell	Fell	07-Oct-10	0	-	0	-	0		0	-	0	Night Work
295 6103	TW0759 白千層	Centre Median between Tuen Shing St & Tuen Hing Rd	Fell	Fell	07-Oct-10	0	-	0	-	0	-	0	-	0	Night Work
296 6103	TW0760	Centre Median between Tuen Shing St & Tuen Hing Rd	Fell	Fell	07-Oct-10	0	-	0	-	0	-	0	-	0	Night Work
297 6103	TW0761 白千層	Centre Median between Tuen Shing St & Tuen Hing Rd	Fell	Fell	07-Oct-10	0	-	0	-	0	-	0	-	0	Night Work
298 6103	TW0762 黃葛樹	Centre Median between Tuen Shing St & Tuen Hing Rd	Fell	Fell	15-Oct-10	0	-	0	-	0	-	0	-	0	Night Work
299 6103	TW0763 石栗	Centre Median between Tuen Shing St & Tuen Hing Rd	Fell	Fell	15-Oct-10	0	-	0	-	0	-	0	-	0	Night Work
300 6103	TW0764 白千層	Centre Median between Tuen Shing St & Tuen Hing Rd	Fell	Fell	15-Oct-10	0	-	0	-	0	-	0	-	0	Night Work
301 6103	TW0765 白千層	Centre Median between Tuen Shing St & Tuen Hing Rd	Fell	Fell	15-Oct-10	0	_	0	_	0	-	0	_	0	Night Work
302 6103	TW0766	Centre Median between Tuen Shing St & Tuen Hing Rd	Fell	Fell	15-Oct-10	0	_	0	_	0	_	0	_	0	Night Work
303 6103	TW0767 白千層	Centre Median between Tuen Shing St & Tuen Hing Rd	Fell	Fell	15-Oct-10	0	_	0	_	0		0	_	0	Night Work
304 6103	TW0768 白千層	Centre Median between Tuen Shing St & Tuen Hing Rd	Fell	Fell	19-Oct-10	0		0	_	0	<u>-</u>	10		0	Night Work
					_	1	-		-		-	0	-	0	_
305 6103	TW0769 白千層	Centre Median between Tuen Shing St & Tuen Hing Rd	Fell	Fell	19-Oct-10	0	-	0	-	0	-	U	-	U	Night Work
306 6103	TW0770	Centre Median between Tuen Shing St & Tuen Hing Rd	Fell	Fell	19-Oct-10	0	-	0	-	0	-	0	-	0	Night Work
307 6103	TW0771 石栗	Centre Median between Tuen Shing St & Tuen Hing Rd	Fell	Fell	19-Oct-10	0	-	0	-	0	-	0	-	0	Night Work
308 6103	TW0772 白千層	Centre Median between Tuen Shing St & Tuen Hing Rd	Fell	Fell	19-Oct-10	0	-	0	-	0	-	0	-	0	Night Work
309 6103	TW0773 石栗	Centre Median between Tuen Shing St & Tuen Hing Rd	Fell	Fell	19-Oct-10	0	-	0	-	0		0	-	0	Night Work
310 6103	TW0774 黄葛樹	Centre Median between Tuen Shing St & Tuen Hing Rd	Fell	Fell	19-Oct-10	0	-	0	-	0	-	0	-	0	Night Work
311 6103	TW0775 石栗	Centre Median between Tuen Shing St & Tuen Hing Rd	Fell	Fell	20-Oct-10	0	-	0	-	0	-	0	-	0	Night Work
312 6103	TW0776 石栗	Centre Median between Tuen Shing St & Tuen Hing Rd	Fell	Fell	20-Oct-10	0	-	0	-	0	-	0	-	0	Night Work
313 6103	TW0777 石栗	Centre Median between Tuen Shing St & Tuen Hing Rd	Fell	Fell	20-Oct-10	0	_	0	_	0	-	0	_	0	Night Work
314 6103	TW0778 白千層	Centre Median between Tuen Shing St & Tuen Hing Rd	Fell	Fell	20-Oct-10	0	_	0	_	0	_	0	_	0	Night Work
315 6103	TW0779 黄葛樹	Centre Median between Tuen Shing St & Tuen Hing Rd	Fell	Fell	20-Oct-10	0	_	0	_	0		0	_	0	Night Work
316 6103	TW0780 白千層	Centre Median between Tuen Shing St & Tuen Hing Rd	Fell	Fell	20-Oct-10	0	_	0	_	0		10	_	0	Night Work
317 6103	TW0781 黄葛樹	Centre Median between Tuen Shing St & Tuen Hing Rd	Fell	Fell	21-Oct-10	0		0	-	0		10	_	0	Night Work
					_	0	-		-		-	0	-	0	
318 6103		Centre Median between Tuen Shing St & Tuen Hing Rd	Fell	Fell	20-Oct-10	0	-	0	-	0	-	0	-	0	Night Work
319 6103	TW0783 石栗	Centre Median between Tuen Shing St & Tuen Hing Rd	Fell	Fell	20-Oct-10	0	-	0	-	0		0	-	0	Night Work
320 6103	TW0784 石栗	Centre Median between Tuen Shing St & Tuen Hing Rd	Fell	Fell	20-Oct-10	0	-	0	-	0	-	0	-	0	Night Work
321 6103	TW0785 石栗	Centre Median between Tuen Shing St & Tuen Hing Rd	Fell	Fell	20-Oct-10	0	-	0	-	0	-	0	-	0	Night Work
322 6103	TW0786 石栗	Centre Median between Tuen Shing St & Tuen Hing Rd	Fell	Fell	20-Oct-10	0	-	0	-	0	-	0	-	0	Night Work
323 6103	TW0787 白千層	Centre Median between Tuen Shing St & Tuen Hing Rd	Fell	Fell	20-Oct-10	0	-	0	-	0	-	0	-	0	Night Work
324 6103	TW0788 黃葛樹	Centre Median between Tuen Shing St & Tuen Hing Rd	Fell	Fell	20-Oct-10	0	-	0	-	0	_	0	-	0	Night Work
325 6103	TW0789 白千層	Centre Median between Tuen Shing St & Tuen Hing Rd	Fell	Fell	19-Oct-10	0	-	0	-	0	-	0	-	0	Night Work
326 6103	TW0790 石栗	Centre Median between Tuen Shing St & Tuen Hing Rd	Fell	Fell	19-Oct-10	0	-	0	-	0	_	0	-	0	Night Work
327 6103	TW0791 石栗	Centre Median between Tuen Shing St & Tuen Hing Rd	Fell	Fell	19-Oct-10	0	_	0	_	0	_	0	_	0	Night Work
328 6103	TW0792 石栗	Centre Median between Tuen Shing St & Tuen Hing Rd	Fell	Fell	19-Oct-10	0	-	0	_	0	_	0	-	0	Night Work
329 6103	TW0793 石栗	Centre Median between Tuen Shing St & Tuen Hing Rd	Fell	Fell	19-Oct-10	0	_	0	_	0		0	_	0	Night Work
330 6103	TW0794 石栗	Centre Median between Tuen Hing Rd & Chi Lok Fa Yu		Fell	26-Oct-10	0	_	0	_	0	_	10		0	Night Work
331 6103	TW0795 石栗	Centre Median between Tuen Hing Rd & Chi Lok Fa Yu		Fell	26-Oct-10	0	<u> </u>	0	-	0	-	0	-	0	Night Work
						0	-	0	-	0	-	0	-	0	
332 6103	TW0796 石栗	Centre Median between Tuen Hing Rd & Chi Lok Fa Yu		Fell	09-Nov-10	0	-	0	-		-	0	-	0	Night Work
333 6103	TW0797 石栗	Centre Median between Tuen Hing Rd & Chi Lok Fa Yu		Fell	09-Nov-10	Û	-	Û	-	0	-	0	-	U	Night Work
334 6103	TW0798 白千層	Centre Median between Tuen Hing Rd & Chi Lok Fa Yu		Fell	09-Nov-10	()	-	0	-	0	-	0	-	0	Night Work
335 6103	TW0799	Centre Median between Tuen Hing Rd & Chi Lok Fa Yu		Fell	10-Nov-10	0	-	0	-	0	-	0	-	0	Night Work
336 6103	TW0800 石栗	Centre Median between Tuen Hing Rd & Chi Lok Fa Yu	Fell	Fell	09-Nov-10	0	-	0	-	0	-	0	-	0	Night Work
337 6103	TW0801 白千層	Centre Median between Tuen Hing Rd & Chi Lok Fa Yu	Fell	Fell	10-Nov-10	0	-	0	-	0	-	0	-	0	Night Work
338 6103	TW0802 石栗	Centre Median between Tuen Hing Rd & Chi Lok Fa Yu	Fell	Fell	10-Nov-10	0	_	0	_	0	-	0	-	0	Night Work
339 6103	TW0803 石栗	Centre Median between Tuen Hing Rd & Chi Lok Fa Yu	Fell	Fell	10-Nov-10	0		0	-	0		0	-	0	Night Work
340 6103	TW0804 白千層	Centre Median between Tuen Hing Rd & Chi Lok Fa Yu		Fell	10-Nov-10	0	-	0	-	0	-	0	-	0	Night Work
341 6103	TW0805 黃葛樹	Centre Median between Tuen Hing Rd & Chi Lok Fa Yu		Fell	10-Nov-10	0	_	0	-	0	_	0	_	0	Night Work
	TW0806 黄葛樹	Centre Median between Tuen Hing Rd & Chi Lok Fa Yu		Fell	10-Nov-10	0	_	0	_	0	_	0	_	0	Night Work
343 6104	TW0807 木麻黄	Centre Median between Tuen Hing Rd & Chi Lok Fa Yu		Fell	09-Nov-10	0		0		0		0	_	0	Night Work
344 6104	TW0808 石栗	Centre Median between Tuen Hing Rd & Chi Lok Fa Yu		Fell	09-Nov-10	0	<u>-</u>	0	-	0	-	0	-	0	Night Work
	1			1		0	-	0	-		-	0	-	0	
345 6104	TW0809 石栗	Centre Median between Tuen Hing Rd & Chi Lok Fa Yu		Fell Fell	04-Nov-10	0	-	0	-	0	-	U	-	U	Night Work
346 6104	TW0810 白千層	Centre Median between Tuen Hing Rd & Chi Lok Fa Yu		Fell	04-Nov-10	0	-	0	-	0		0	-	U	Night Work
347 6104	TW0811 白千層	Centre Median between Tuen Hing Rd & Chi Lok Fa Yu		Fell	04-Nov-10	<u>()</u>	-	0	-	0	-	0	-	0	Night Work
348 6104	TW0812	Centre Median between Tuen Hing Rd & Chi Lok Fa Yu	Fell	Fell	04-Nov-10	()	-	0	-	0	-	()	-	0	Night Work

	Г			Т	,			1							
349 6104	TW0813 白千層	Centre Median between Tuen Hing Rd & Chi Lok Fa Yue	Fell	Fell	09-Nov-10	0	-	0	-	0	-	0	-	0	Night Work
350 6104	TW0814 白千層	Centre Median between Tuen Hing Rd & Chi Lok Fa Yu	Fell	Fell	09-Nov-10	0	-	0	-	0	-	0	-	0	Night Work
351 6104	TW0815 石栗	Centre Median between Tuen Hing Rd & Chi Lok Fa Yu	Fell	Fell	09-Nov-10	0	_	0	-	0	_	0	-	0	Night Work
352 6104	TW0816 石栗	Centre Median between Tuen Hing Rd & Chi Lok Fa Yu	Fell	Fell		0	-	0		0	_	0		0	Night Work
353 6104	TW0817 白千層	Centre Median between Tuen Hing Rd & Chi Lok Fa Yu	Fell	Fell		0		0		0		0		0	
<u> </u>							-	0	-	0	-	0	-	0	Night Work
354 6104	TW0818 石栗	Centre Median between Tuen Hing Rd & Chi Lok Fa Yu	Fell	Fell		0	-	0	-	0	-	0	-	0	Night Work
355 6104	TW0819 黃葛樹	Centre Median between Tuen Hing Rd & Chi Lok Fa Yu	Fell	Fell		0	-	0		0		0	-	0	Night Work
356 6104	TW0820 白千層	Centre Median between Tuen Hing Rd & Chi Lok Fa Yu	Fell	Fell	03-Nov-10	0	-	0	-	0	_	0	-	0	
357 6104	TW0821 黃葛樹	Centre Median between Tuen Hing Rd & Chi Lok Fa Yue	Fell	Fell	03-Nov-10	0	-	0	-	0	-	0	-	0	Night Work
358 6104	TW0822 白千層	Centre Median between Tuen Hing Rd & Chi Lok Fa Yu	Fell	Fell	02-Nov-10	0	-	0	-	0	_	0	-	0	Night Work
359 6104	TW0823 白千層	Centre Median between Tuen Hing Rd & Chi Lok Fa Yu	Fell	Fell		0	_	0	_	0	_	0	_	0	Night Work
360 6104	TW0824 白千層	Centre Median between Tuen Hing Rd & Chi Lok Fa Yu	Fell	Fell		0	_	0		0		0		0	Night Work
<u> </u>	TW0825 白千層	-						0		0		0		0	
361 6104		Centre Median between Tuen Hing Rd & Chi Lok Fa Yu	Fell Fell	Fell		0	<u>-</u>	0	-	0	<u>-</u>	0	<u>-</u>	0	Night Work
362 6104	TW0826 白千層	Centre Median between Tuen Hing Rd & Chi Lok Fa Yu	Fell	Fell		0	-	0	-	0	-	0	-	0	Night Work
363 6104	TW0827 白千層	Centre Median between Tuen Hing Rd & Chi Lok Fa Yu	Fell	Fell	02-Nov-10	0	-	0	-	0	-	0	-	0	Night Work
364 6104	TW0828 白千層	Centre Median between Tuen Hing Rd & Chi Lok Fa Yue	Fell	Fell	02-Nov-10	0	-	0	-	0	-	0	-	0	Night Work
365 6104	TW0829 白千層	Centre Median between Tuen Hing Rd & Chi Lok Fa Yue	Fell	Fell	02-Nov-10	0	-	0	-	0	-	0	-	0	Night Work
366 6104	TW0830 白千層	Centre Median between Tuen Hing Rd & Chi Lok Fa Yue	Fell	Fell	02-Nov-10	0	-	0	-	0	_	0	-	0	Night Work
367 6104	TW0831 白千層	Centre Median between Tuen Hing Rd & Chi Lok Fa Yu	Fell	Fell		0	_	0	_	0	_	0	_	0	Night Work
<u> </u>								0		0		0		0	
368 6103	TW0832 大葉合歡	Tuen Hing Road Slip Road to Tuen Mun Road B bound	Fell Fell	Fell	•	0	-	0	-		-	0	-	0	Night Work
369 6103	TW0833 台灣相思	Tuen Hing Road Slip Road to Tuen Mun Road B bound	Fell	Fell	•	0	-	0	-	0	-	0	-	0	Night Work
370 6103	TW0834 台灣相思	Tuen Hing Road Slip Road to Tuen Mun Road B bound	Fell	Fell	_	0	-	0	-	0	-	0	-	0	Night Work
371 6103	TW0835 大葉合歡	Tuen Hing Road Slip Road to Tuen Mun Road B bound	Fell	Fell	16-Sep-10	0	-	0	-	0	-	0	-	0	Night Work
372 6103	TW0836 台灣相思	Tuen Hing Road Slip Road to Tuen Mun Road B bound	Fell	Fell	16-Sep-10	0	-	0	-	0	-	0	-	0	Night Work
373 6103	TW0837 -	Tuen Hing Road Slip Road to Tuen Mun Road B bound	Fell	Remove	07-Sep-10	0	-	0	_	0	_	0	_	0	by other
374 6103	TW0838 -	Tuen Hing Road Slip Road to Tuen Mun Road B bound	Fell	-	•	0	_	0		0	_	0	_	0	Missing
_	1	Tuen Hing Road Slip Road to Tuen Mun Road B bound	Fell	Fell		0		0		0		0		0	Night Work
0.00				1.611	10 500 10			0		0		0	-	0	2
	TW0840 -	Tuen Hing Road Slip Road to Tuen Mun Road B bound	Fell Fell	-		0	-	0	<u>-</u>	0	<u>-</u>	0	<u>-</u>	0	Missing
377 6103	TW0841 -	Tuen Hing Road Slip Road to Tuen Mun Road B bound	Fell	Remove	_	0	-	0	-	0	-	0	-	0	by other
378 6103	TW0842 -	Tuen Hing Road Slip Road to Tuen Mun Road B bound	Fell	Remove	07-Sep-10	0	-	0	-	0	-	0	-	0	by other
379 6103	TW0843 台灣相思	Tuen Hing Road Slip Road to Tuen Mun Road B bound	Fell	Fell	07-Sep-10	0	-	0	-	0	-	0	-	0	by other
380 6103	TW0844 -	Tuen Hing Road Slip Road to Tuen Mun Road B bound	Fell	Remove	07-Sep-10	0	-	0	-	0	-	0	-	0	by other
381 6103	TW0845 -	Tuen Hing Road Slip Road to Tuen Mun Road B bound	Fell	_		0	_	0	-	0	_	0	-	0	Missing
382 6103	TW0846 台灣相思	Tuen Hing Road Slip Road to Tuen Mun Road B bound	Fell	Fell		0	_	0	_	0	_	0	_	0	by other
383 6103	TW0847 台灣相思	Tuen Hing Road Slip Road to Tuen Mun Road B bound	Fell	Fell		0	_	0		0		0		0	- by other
		· · · · · · · · · · · · · · · · · · ·			•	_		0	-	0		0	-	0	NI: -1-4 XXI1-
384 6103	TW0848 -	Tuen Hing Road Slip Road to Tuen Mun Road B bound	Fell Fell	-		0	-	0	-	0	-	0	-	0	Night Work
385 6103	TW0849 -	Tuen Hing Road Slip Road to Tuen Mun Road B bound	Fell	-		0	-	0	-	0	-	0	-	0	Night Work
386 6103	TW0851 台灣相思	Tuen Hing Road Slip Road to Tuen Mun Road B bound	Fell	Fell	23-Nov-10	0	-	0	-	0	-	0	-	0	Night Work
387 6103	TW0852 台灣相思	Tuen Hing Road Slip Road to Tuen Mun Road B bound	Fell	Fell	16-Sep-10	0	-	0	-	0	-	0	-	0	
388 6103	TW0853 -	Tuen Hing Road Slip Road to Tuen Mun Road B bound	Fell	-	Done	0	-	0	-	0	-	0	-	0	Missing
389 6103	TW0854 桑	Tuen Hing Road Slip Road to Tuen Mun Road B bound	Fell	Fell	23-Nov-10	0	_	0	_	0	_	0	_	0	Night Work
390 6103	TW0855 木棉	Tuen Hi Road near Tuen Wui Street	Fell	Fell		0		0		0		0		0	Night Work
391 6103	TW0856 -	Tuen Hi Road near Tuen Wui Street	Fell			0		0		0		0		0	Missing
				- Eall		-	-	0	-	0	-	0	-	0	
392 6103	TW0857	Tuen Hi Road near Tuen Wui Street	Fell Fell	Fell		0		Û	-	U	-	U	-	0	Night Work
393 6103	TW0858 黄葛樹	Tuen Hi Road near Tuen Wui Street	Fell	Fell		0	-	0	-	()	-	0	-	0	Night Work
394 6103	TW0859 黃葛樹	Tuen Hi Road near Tuen Wui Street	Fell	Fell		0	-	0	-	0	-	0	-	0	Night Work
395 6103	TW0860 木棉	Tuen Hi Road near Tuen Wui Street	Fell	Fell	21-Oct-10	0	-	0	-	0	-	0	-	0	Night Work
396 6103	TW0861 黃葛樹	Tuen Hi Road near Tuen Wui Street	Fell	Fell	30-Oct-10	0	-	0	-	0	-	0	-	0	Night Work
397 6103	TW0862 黃葛樹	Tuen Hi Road near Tuen Wui Street	Fell	Fell		0	_	()	-	()	-	()	_	0	Night Work
398 6103	TW0863 黄葛樹	Tuen Hi Road near Tuen Wui Street	Fell	Fell		0	_	n	_	0		0		0	Night Work
399 6103	TW0864 黃葛樹	Tuen Hi Road near Tuen Wui Street	Fell	Fell		0		0	_	0		0		0	Night Work
						-	-	0	-	0	-	0	-	0	
400 6103	TW0865 木棉	Tuen Hi Road near Tuen Wui Street	Fell Fell	Fell		0		Û	-	U	-	U	-	0	Night Work
401 6103	TW0866 黃葛樹	Tuen Hi Road near Tuen Wui Street	Fell	Fell		0	-	Ü	-	0	-	0	-	0	Night Work
402 6103	TW0867 木棉	Tuen Hi Road near Tuen Wui Street	Fell	Fell		0	-	0	-	0	-	0	-	0	Night Work
403 6103		Tuen Hi Road near Tuen Wui Street	Fell	Fell	29-Oct-10	0	-	0	-	0	-	0	-	0	Night Work
404 6103	TW0869 黃葛樹	Tuen Hi Road near Tuen Wui Street	Fell	Fell	29-Oct-10	0	-	0	-	0	-	0	-	0	Night Work
405 6103	TW0870 木棉	Tuen Hi Road near Tuen Wui Street	Fell	Fell		0	-	0	-	0	-	0	-	0	Night Work
	TW0871 -	Tuen Hi Road near Tuen Wui Street	Fell	-		0		n		0	_	0		0	Missing
	TW0872 木棉	 						0	-	0		0	-	0	
		Tuen Hi Road near Tuen Wui Street	Fell	Fell		0	-	U	-	U	-	U	-	0	Night Work
	TW0873 黃葛樹	Tuen Hi Road near Tuen Wui Street	Fell Fell	Fell		0	-	Û	-	0	-	Ü	-	0	Night Work
409 6103	TW0874 黃葛樹	Tuen Hi Road near Tuen Wui Street	Fell	Fell	28-Oct-10	0	-	0	-	0	-	0	-	0	Night Work

	Leina		1-61						Г		Г						
410		TW0875 黃葛		Tuen Hi Road near Tuen Wui Street	Fell	Fell	28-Oct-10	0	-	0	-	0	-	0	-	0	Night Work
411	6103	TW0876 木棉		Tuen Hi Road near Tuen Wui Street	Fell	Fell	21-Oct-10	0	-	0	-	0	-	0	-	0	Night Work
412	6103	TW0877 黃葛		Tuen Hi Road near Tuen Wui Street	Fell	Fell	29-Oct-10	0	-	0	-	0	-	0	-	0	Night Work
413	6103	TW0878 黄葛	樹	Tuen Hi Road near Tuen Wui Street	Fell	Fell	29-Oct-10	0	-	0	-	0	-	0	-	0	Night Work
414	6103	TW0879 黃葛	樹	Tuen Hi Road near Tuen Wui Street	Fell	Fell	28-Oct-10	0	-	0	-	0	-	0	-	0	Night Work
415	6103	TW0880 黃葛	樹	Tuen Hi Road near Tuen Wui Street	Fell	Fell	28-Oct-10	0	-	0	-	0	1	0	-	0	Night Work
416	6102	TW0881 秋楓		Tuen Mun Road A Bound near Tuen Lung Street	Transplant	Transplant	N/A	0	31-Aug-10	0	07-Oct-10	0	17-Dec-10	0	17-Mar-11	0	Transplanted
417	6102	TW0882 秋楓		Tuen Mun Road A Bound near Tuen Lung Street	Transplant	Transplant	N/A	0	31-Aug-10	0	06-Sep-10	0	07-Oct-10	0	12-Mar-11	0	Transplanted
418	6102	TW0883 秋楓		Tuen Mun Road A Bound near Tuen Lung Street	Transplant	Transplant	N/A	0	31-Aug-10	0	04-Sep-10	0	07-Oct-10	0	12-Mar-11	0	Transplanted
419	6102	TW0884 苦棟		Tuen Mun Road A Bound near Tuen Lung Street	Transplant	Transplant	N/A	0	27-Sep-10	0	28-Sep-10	0	23-Mar-11	0	24-Mar-11	0	31/8 First Time
420	6102	TW0885 苦棟		Tuen Mun Road A Bound near Tuen Lung Street	Transplant	Transplant	N/A	0	27-Sep-10	0	28-Sep-10	0	23-Mar-11	0	24-Mar-11	0	31/8 First Time
421	6102	TW0886 秋楓		Tuen Mun Road A Bound near Tuen Lung Street	Transplant	Transplant	N/A	0	27-Sep-10	0	07-Oct-10	0	28-Mar-11	0	29-Mar-11	0	31/8 First Time
422	6102	TW0887 白千		Tuen Mun Road A Bound near Yan Ching Street	Fell	Fell	12-Nov-10	0	-	0	-	0	-	0	-	0	
423	6102	TW0888 白千		Tuen Mun Road A Bound near Yan Ching Street	Transplant	Transplant	N/A	0	25-Sep-10	0	25-Sep-10	0	09-Nov-10	0	17-Jan-11	0	Transplanted
424	6102	TW0889 白千		Tuen Mun Road A Bound near Yan Ching Street	Fell	Fell	12-Nov-10	0	-	0	-	0	-	0	-	0	, and the same of
425	6101	TW0890 白千		Tuen Mun Road A Bound near Yan Ching Street	Fell	Fell	12-Nov-10	0	-	0	_	0	_	0	_	0	
426	6101	TW0891 樹頭		Tuen Mun Road A Bound near Yan Ching Street	Transplant	Transplant	N/A	0	30-Aug-10	0	30-Aug-10	0	06-Oct-10	0	09-Nov-10	0	Transplanted
427	6101	TW0892 樹頭		Tuen Mun Road A Bound near Yan Ching Street	Transplant	Transplant	N/A	0	30-Aug-10	0	01-Sep-10	0	06-Oct-10	0	08-Nov-10	0	Transplanted
428	6101	TW0893 樹頭		Tuen Mun Road A Bound near Yan Ching Street	Transplant	Transplant	N/A	0	30-Aug-10	0	31-Aug-10	0	06-Oct-10	0	08-Nov-10	0	Transplanted
429	6101	TW0894 樹頭		Tuen Mun Road A Bound near Yan Ching Street	Transplant	Transplant	N/A	0	30-Aug-10	0	31-Aug-10	0	06-Oct-10	0	08-Nov-10	0	Transplanted
430	6101	TW0895 石栗		Tuen Mun Road A Bound near Yan Ching Street	Transplant	Transplant	N/A	0	20-Aug-10	0	02-Sep-10	0	20-Nov-10	0	20-Nov-10	0	Transplanted
431	6101	TW0896 洋紫		Tuen Mun Road A Bound near Yan Ching Street	Transplant	Transplant	N/A	0	30-Aug-10	0	02-Sep-10 04-Sep-10	0	06-Oct-10	0	04-Nov-10	0	Transplanted
432	6101	TW0897 洋紫		Tuen Mun Road A Bound near Yan Ching Street Tuen Mun Road A Bound near Yan Ching Street	•	Transplant	N/A	0	30-Aug-10 30-Aug-10	0	30-Aug-10	0	05-Oct-10	0	04-Nov-10	0	•
432	6101	TW0897		Tuen Mun Road A Bound near Yan Ching Street Tuen Mun Road A Bound near Yan Ching Street	Transplant Transplant	Transplant Transplant	N/A N/A	0	30-Aug-10 30-Aug-10	0	04-Sep-10	0	05-Oct-10	0	04-Nov-10 04-Nov-10	0	Transplanted Transplanted
	+			Tuen Mun Road A Bound near Yan Ching Street Tuen Mun Road A Bound near Yan Ching Street	Transplant			0		0	_	0		0		0	•
434	6101	TW0899 洋紫		S	Transplant	Transplant	N/A	0	20-Aug-10	0	03-Sep-10	0	05-Oct-10	0	08-Nov-10	0	Transplanted
435	6101	TW0900 石栗		Tuen Mun Road A Bound near Yan Ching Street	Transplant	Transplant	N/A	0	20-Aug-10	0	04-Sep-10	0	05-Oct-10	0	06-Dec-10	0	Transplanted
436	6101	TW0901 樹頭	•	Tuen Mun Road A Bound near Yan Ching Street	Transplant	Transplant	N/A	0	30-Aug-10	0	03-Sep-10	0	05-Oct-10	0	08-Nov-10	0	Transplanted
437	 	TW0902		Tuen Mun Road A Bound near Yan Ching Street	Transplant	Transplant	N/A	0	07-Sep-10	0	09-Oct-10	0	09-Apr-11	0	09-Apr-11	0	Undergr'd UU
438	6101	TW0903		Tuen Mun Road A Bound near Yan Ching Street	Transplant	Transplant	N/A	0	07-Sep-10	0	07-Sep-10	0	04-Oct-10	0	07-Dec-10	0	Transplanted
439	6101	TW0904		Tuen Mun Road A Bound near Yan Ching Street	Transplant	Transplant	N/A	0	07-Sep-10	0	07-Sep-10	0	04-Oct-10	0	09-Nov-10	0	Transplanted
440	6101	TW0905 石栗		Tuen Mun Road A Bound near Yan Ching Street	Transplant	Transplant	N/A	0	20-Aug-10	0	04-Sep-10	0	05-Oct-10	0	20-Nov-10	0	Transplanted
441	6101	TW0906 石栗		Tuen Mun Road A Bound near Yan Ching Street	Transplant	Transplant	N/A	0	20-Aug-10	0	03-Sep-10	0	04-Oct-10	0	06-Dec-10	0	Transplanted
442	6101	TW0907 石栗		Tuen Mun Road A Bound near Yan Ching Street	Transplant	Transplant	N/A	0	20-Aug-10	0	03-Sep-10	0	04-Oct-10	0	07-Dec-10	0	Transplanted
443	6101	TW0908 洋紫		Tuen Mun Road A Bound near Yan Ching Street	Transplant	Transplant	N/A	0	01-Sep-10	0	04-Sep-10	0	07-Oct-10	0	11-Dec-10	0	Transplanted
444	6101	TW0909 石栗		Tuen Mun Road A Bound near Yan Ching Street	Transplant	Transplant	N/A	0	01-Sep-10	0	04-Sep-10	0	09-Dec-10	0	09-Dec-10	0	Transplanted
445	6101	TW0910 石栗		Tuen Mun Road A Bound near Yan Ching Street	Transplant	Transplant	N/A	0	01-Sep-10	0	04-Sep-10	0	09-Dec-10	0	09-Dec-10	0	Transplanted
446	6101	TW0911 鳥桕		Tuen Mun Road A Bound near Yan Ching Street	Transplant	Transplant	N/A	0	01-Sep-10	0	03-Sep-10	0	08-Dec-10	0	08-Dec-10	0	Transplanted
447	6101	TW0912		Tuen Mun Road A Bound near Yan Ching Street	Transplant	Transplant	N/A	0	07-Sep-10	0	10-Dec-10	0	10-Dec-10	0	10-Dec-10	0	Transplanted
448	6101	TW0913 鳥桕		Tuen Mun Road A Bound near Yan Ching Street	Transplant	Transplant	N/A	0	01-Sep-10	0	04-Sep-10	0	13-Dec-10	0	13-Dec-10	0	Transplanted
449	6101	TW0914 假檳		Tuen Mun Road A Bound near Yan Ching Street	Transplant	Transplant	N/A	0	01-Sep-10	0	03-Sep-10	0	06-Oct-10	0	15-Dec-10	0	Transplanted
450	6101	TW0915 假檳		Tuen Mun Road A Bound near Yan Ching Street	Transplant	Transplant	N/A	0	01-Sep-10	0	02-Sep-10	0	06-Oct-10	0	15-Dec-10	0	Transplanted
451	6101	TW0916 假檳		Tuen Mun Road A Bound near Yan Ching Street	Transplant	Transplant	15-Dec-10	0	30-Aug-10	0	02-Sep-10	0	06-Oct-10	0	-	0	Poor Health
452	6101	TW0917 假檳		Tuen Mun Road A Bound near Yan Ching Street	Transplant	Transplant	N/A	0	01-Sep-10	0	02-Sep-10	0	15-Dec-10	0	18-Jan-11	0	Transplanted
453	6101	TW0918 大葉		Tuen Mun Road A Bound near Yan Ching Street	Fell	Fell	27-Oct-10	0	-	0	-	0	-	0	-	0	Night Work
454	6101	TW0919 假檳		Tuen Mun Road A Bound near Yan Ching Street	Transplant	Transplant	N/A	0	30-Aug-10	0	02-Sep-10	0	04-Oct-10	0	15-Dec-10	0	Transplanted
455	6101	TW0920 大葉		Tuen Mun Road A Bound near Yan Ching Street	Fell	Fell	27-Oct-10	0	-	0	-	0	-	0	-	0	by other
456	6101	TW0921 串錢		Tuen Mun Road A Bound near Yan Ching Street	Fell	Fell	27-Oct-10	0	-	0	-	0	-	0	-	0	Night Work
457	6101	TW0922 假檳		Tuen Mun Road A Bound near Yan Ching Street	Transplant	Transplant	N/A	0	30-Aug-10	0	03-Sep-10	0	04-Oct-10	0	15-Dec-10	0	Transplanted
458	6101	TW0923 假檳	榔	Tuen Mun Road A Bound near Yan Ching Street	Retain	Retain	-	0	-	0	-	0	-	0	-	0	
459	6101	TW0924 假檳		Tuen Mun Road A Bound near Yan Ching Street	Retain	Retain	-	0	-	0	-	0	-	0	-	0	
460	6101	TW0925 假檳	榔	Tuen Mun Road A Bound near Yan Ching Street	Retain	Retain	-	0	-	0	-	0	-	0	-	0	
461	6101	TW0926 大葉		Tuen Mun Road A Bound near Yan Ching Street	Retain	Retain	-	0	-	0	-	0	-	0	-	0	
462	6101	TW0927 串錢	柳	Tuen Mun Road A Bound near Yan Ching Street	Retain	Retain	-	0	-	0	-	0	-	0	-	0	
463	6101	TW0928 大葉		Tuen Mun Road A Bound near Yan Ching Street	Retain	Retain	-	0	-	0	-	0	-	0	-	0	
464	6101	TW0929 串錢	柳	Tuen Mun Road A Bound near Yan Ching Street	Retain	Retain	-	0	-	0	-	0	-	0	-	0	
465	6101	TW0930 大葉		Tuen Mun Road A Bound near Yan Ching Street	Fell	Fell	31-Dec-10	0	-	0	_	0	-	0	<u>-</u>	0	Night Work
466	6101	TW0931 大葉	桉	Tuen Mun Road A Bound near Yan Ching Street	Fell	Fell	31-Dec-10	0	_	0	-	0	-	0	-	0	Night Work
467	6101	TW0932 假檳		Tuen Mun Road A Bound near Yan Ching Street	Transplant	Transplant	N/A	0	30-Aug-10	0	03-Sep-10	0	04-Oct-10	0	04-Jan-11	0	Night Work
468	1	TW0933 假檳		Tuen Mun Road A Bound near Yan Ching Street	Transplant	Transplant	N/A	0	30-Aug-10	0	03-Sep-10	0	04-Oct-10	0	04-Jan-11	0	Night Work
	6101	TW0934 假檳		Tuen Mun Road A Bound near Yan Ching Street	Transplant	Transplant	N/A	0	30-Aug-10	0	03-Sep-10	0	05-Oct-10	0	04-Jan-11	0	Night Work
	1	TW0935 大葉		Tuen Mun Road A Bound near Yan Ching Street	Fell	Fell	27-Oct-10	0	-	0	-	0	-	0	-	0	Night Work
E				-						-							_

471 6101	TW0936 石栗	Tuen Mun Road A Bound near Yan Ching Street	Fell	Fell	31-Dec-10	0		0	_			0		Ιο	Night Work
	TW0937 大葉桉	Tuen Mun Road A Bound near Yan Ching Street	Fell	Fell	27-Oct-10	0	<u>-</u>	0	-	0	-	0	-	0	Night Work
473 6101	TW0937	Tuen Mun Road A Bound near Yan Ching Street	Transplant	Transplant	N/A	0	30-Aug-10	0	03-Sep-10	0	05-Oct-10	0	05-Jan-11	0	Night Work
H 1	TW0939 假檳榔	Tuen Mun Road A Bound near Yan Ching Street	Transplant	Transplant	N/A	0	30-Aug-10 30-Aug-10	0	03-Sep-10 03-Sep-10	0	05-Oct-10		05-Jan-11	0	Night Work
475 6101	TW0940 石栗	Tuen Mun Road A Bound near Yan Ching Street	Fell	Fell	Done	0	30-Aug-10	0	03-3cp-10	0	03-001-10	0	03-3411-11	0	Night Work
476 6101	TW0940	Tuen Mun Road A Bound near Yan Ching Street	Fell	Fell	31-Dec-10	0		0	-	0	-	0	-	0	Night Work
477 6101	TW0941 申銭柳 TW0942 串銭柳	Tuen Mun Road A Bound near Yan Ching Street	Fell	Fell	27-Oct-10	0	-	0	-	0	-	0	-	0	Night Work
						0	07 San 10	0	07 San 10	0	05 Oct 10	0	- 04 Ion 11	0	
	TW0943 假檳榔	Tuen Mun Road A Bound near Yan Ching Street	Transplant	Transplant	N/A	0	07-Sep-10	0	07-Sep-10	0	05-Oct-10	0	04-Jan-11	0	Night Work
+	TW0944	Tuen Mun Road A Bound near Yan Ching Street	Fell	Fell	27-Oct-10	0	- 07.0 10	0	- 07.0 10	0	05.0 + 10	0	- 05 I. 11	0	Night Work
480 6101	TW0945 假檳榔	Tuen Mun Road A Bound near Yan Ching Street	Transplant	Transplant	N/A	0	07-Sep-10	0	07-Sep-10	0	05-Oct-10	0	05-Jan-11	0	Night Work
	TW0946	Tuen Mun Road A Bound near Yan Ching Street	Fell	Fell	27-Oct-10	0	- 10	0	- 10	0	- 05.0 + 10	0	- 05 T 11	0	Night Work
	TW0947 假檳榔	Tuen Mun Road A Bound near Yan Ching Street	Transplant	Transplant	N/A	0	07-Sep-10	0	07-Sep-10	0	05-Oct-10	0	05-Jan-11	0	Night Work
483 6101	TW0948 串錢柳	Tuen Mun Road A Bound near Yan Ching Street	Fell	Fell	10-Sep-10	0	-	0	-	0	-	0	-	0	Night Work
484 6101	TW0949 串錢柳	Tuen Mun Road A Bound near Yan Ching Street	Fell	Fell	10-Sep-10	0	-	0	-	0	-	0	-	0	Night Work
	TW0950 串錢柳	Tuen Mun Road A Bound near Yan Ching Street	Fell	Fell	08-Sep-10	0	-	0	-	0	-	0	-	0	Night Work
486 6101	TW0951 串錢柳	Tuen Mun Road A Bound near Yan Ching Street	Fell	Fell	10-Sep-10	0	-	0	-	0	-	0	-	0	Night Work
487 6101	TW0952 串錢柳	Tuen Mun Road A Bound near Yan Ching Street	Fell	Fell	08-Sep-10	0	-	0	-	0	-	0		0	Night Work
	TW0953	Tuen Mun Road A Bound near Yan Ching Street	Fell	Fell	08-Sep-10	0		0	-	0	-	0	-	0	Night Work
489 6101	TW0954 串錢柳	Tuen Mun Road A Bound near Yan Ching Street	Fell	Fell	08-Sep-10	0		0	-	0	-	0	-	0	Night Work
490 6101	TW0955	Tuen Mun Road A Bound near Yan Ching Street	Fell	Fell	08-Sep-10	0	-	0	-	0	-	0	-	0	Night Work
491 6101	TW0956 -	Tuen Mun Road A Bound near Yan Ching Street	Remove	-	-	0	-	0	-	0	-	0	-	0	Missing
	TW0957 假檳榔	Tuen Mun Road A Bound near Yan Ching Street	Retain	Retain	-	0	-	0	-	0	-	0	-	0	
	TW0959 假檳榔	Tuen Mun Road A Bound near Yan Ching Street	Retain	Retain	-	0	-	0	-	0	-	0	-	0	
494 6101	TW0960 假檳榔	Tuen Mun Road A Bound near Yan Ching Street	Retain	Retain	-	0	-	0	-	0	-	0	-	0	
495 6101	TW0961 鳳凰木	Tuen Mun Road A Bound near Yan Ching Street	Retain	Retain	23-Sep-11	0	-	0	-	0	-	0	_	0	Poor health, removed by L
496 6101	TW0962 假檳榔	Tuen Mun Road A Bound near Yan Ching Street	Retain	Retain	-	0	-	0	-	0	-	0	-	0	
497 6101	TW0963 假檳榔	Tuen Mun Road A Bound near Yan Ching Street	Retain	Retain	-	0	-	0	-	0	-	0	-	0	
498 6101	TW0966 鳳凰木	Tuen Mun Road A Bound near Yan Ching Street	Retain	Retain	-	0	-	0	-	0	-	0	-	0	
499 6101	TW0969 假檳榔	Tuen Mun Road A Bound near Yan Ching Street	Retain	Retain	-	0	-	0	-	0	-	0	-	0	
500 6101	TW0973 假檳榔	Yan Oi Tong Circuit Car Park	Transplant	Transplant	N/A	0	06-Nov-10	0	06-Nov-10	0	18-Dec-10	0	18-May-11	0	Transplanted
501 6101	TW0974 假檳榔	Yan Oi Tong Circuit Car Park	Transplant	Transplant	N/A	0	06-Nov-10	0	06-Nov-10	0	18-Dec-10	0	18-May-11	0	Transplanted
502 6101	TW0975 假檳榔	Yan Oi Tong Circuit Car Park	Transplant	Transplant	N/A	0	06-Nov-10	0	06-Nov-10	0	17-Dec-10	0 :	17-May-11	0	Transplanted
503 6101	TW0976 假檳榔	Yan Oi Tong Circuit Car Park	Transplant	Transplant	N/A	0	06-Nov-10	0	06-Nov-10	0	17-Dec-10	0 :	17-May-11	0	Transplanted
504 6101	TW0977 假檳榔	Yan Oi Tong Circuit Car Park	Transplant	Transplant	N/A	0	06-Nov-10	0	06-Nov-10	0	18-Dec-10		17-May-11	0	Transplanted
505 6101	TW0978 假檳榔	Yan Oi Tong Circuit Car Park	Transplant	Transplant	N/A	0	06-Nov-10	0	06-Nov-10	0	18-Dec-10		17-May-11	0	Transplanted
	TW0979 石栗	Yan Oi Tong Circuit Planter Area	Retain	Retain	-	0	_	0	-	0	-	0	-	0	•
507 6101	TW0980 石栗	Yan Oi Tong Circuit Planter Area	Retain	Retain	-	0	-	0	-	0	-	0	_	0	
508 6101	TW0981	Yan Oi Tong Circuit Planter Area	Remove	_	_	0	_	0	-	0	_	0	_	0	Missing
	TW0982 石栗	Yan Oi Tong Circuit Planter Area	Transplant	Transplant	N/A	0	18-Nov-10	0	22-Nov-10	0	22-Nov-10	0 2	22-Nov-10	0	Transplanted
510 6101	TW0983	Yan Oi Tong Circuit Planter Area	Transplant	Transplant	N/A	0	17-Nov-10	0	24-Nov-10	0	24-Nov-10		24-Nov-10	0	Transplanted
511 6101	TW0984 石栗	Yan Oi Tong Circuit Planter Area	Transplant	Transplant	N/A	0	18-Nov-10	0	22-Nov-10	0	22-Nov-10		22-Nov-10	0	Transplanted
	TW0985 假檳榔	Yan Oi Tong Circuit Planter Area	Transplant	Transplant	N/A	0	09-Aug-10	0	10-Aug-10	0	10-Sep-10		15-Oct-10	0	Transplanted
513 6101	TW0986 假檳榔	Yan Oi Tong Circuit Planter Area	Transplant	Transplant	N/A	0	09-Aug-10	0	10-Aug-10	0	10-Sep-10		15-Oct-10	0	Transplanted
514 6101	TW0987 假檳榔	Yan Oi Tong Circuit Planter Area	Transplant	Transplant	N/A	0	09-Aug-10	0	10-Aug-10	0	10-Sep-10		15-Oct-10	0	Transplanted
515 6101	TW0988 假檳榔	Yan Oi Tong Circuit Planter Area	Transplant	Transplant	N/A	0	09-Aug-10	0	10-Aug-10	0	09-Sep-10	_	15-Oct-10	0	Transplanted
	TW0988	Yan Oi Tong Circuit Planter Area	Transplant	Transplant	N/A	0	09-Aug-10 09-Aug-10	0	10-Aug-10 10-Aug-10	0	09-Sep-10		27-Oct-10	0	Transplanted
	TW0999	Yan Oi Tong Circuit Planter Area	Transplant Transplant	Transplant	N/A	0	04-Aug-10	0	06-Aug-10	0	07-Sep-10		14-Oct-10	0	Transplanted
517 6101	TW0990	Yan Oi Tong Circuit Planter Area	Fell	Fell	14-Oct-10	n	- -	0		0		0	- -	0	Transpianicu
519 6101	TW0991 人桌 古	Yan Oi Tong Circuit Planter Area Yan Oi Tong Circuit Planter Area	Transplant	Transplant	14-Oct-10 N/A	0	- 04-Aug-10	0	- 06-Aug-10	0	- 07-Sep-10	0	14-Oct-10	0	Transplanted
	TW0992 假檳榔 TW0993 假檳榔	·	Transplant Transplant	Transplant Transplant	N/A N/A	0	04-Aug-10 04-Aug-10	0	06-Aug-10 06-Aug-10	0	07-Sep-10 07-Sep-10		14-Oct-10	0	Transplanted Transplanted
520 6101		Yan Oi Tong Circuit Planter Area Yan Oi Tong Circuit Planter Area	_	_	N/A N/A	0		0		0		_		0	
	TW0994 假檳榔 TW0995 鳳凰木		Transplant Transplant	Transplant Transplant		U A	17-Sep-10	0	17-Sep-10	0	14-Oct-10	_	14-Oct-10	0	Transplanted Transplanted
522 6101 523 6101		Yan Oi Tong Circuit Planter Area Van Oi Tong Circuit Planter Area	Transplant Transplant	Transplant Transplant	N/A	0	17-Nov-10	0	24-Nov-10	0	24-Nov-10		24-Nov-10	0	Transplanted Transplanted
	TW0996 串錢柳	Yan Oi Tong Circuit Planter Area	Transplant	Transplant	N/A	U	17-Sep-10	U	17-Sep-10	U	14-Oct-10		14-Oct-10	0	Transplanted
	TW0997	Yan Oi Tong Circuit Planter Area	Transplant	Transplant	N/A	0	17-Nov-10	U	23-Nov-10	0	23-Nov-10		23-Nov-10	0	Transplanted
		Yan Oi Tong Circuit Planter Area	Transplant	Transplant	N/A	0	17-Nov-10	0	23-Nov-10	0			23-Nov-10	0	Transplanted
	TW0999 假檳榔	Yan Oi Tong Circuit Planter Area	Transplant	Transplant	N/A	0	04-Aug-10	0	06-Aug-10	0	07-Sep-10	_	14-Oct-10	0	Transplanted
	TW1000 假檳榔	Yan Oi Tong Circuit Planter Area	Transplant	Transplant	N/A	0	04-Aug-10	0	06-Aug-10	0	07-Sep-10		14-Oct-10	0	Transplanted
	TW1001 假檳榔	Yan Oi Tong Circuit Planter Area	Transplant	Transplant	N/A	0	04-Aug-10	0	06-Aug-10	0	07-Sep-10		13-Oct-10	0	Transplanted
FOO 10101	TW1002 假檳榔	Yan Oi Tong Circuit Planter Area	Transplant	Transplant	N/A	0	04-Aug-10	0	06-Aug-10	0	07-Sep-10	0	14-Oct-10	0	Transplanted
						1									
530 6101	TW1003 假檳榔 TW1004 假檳榔	Yan Oi Tong Circuit Planter Area Yan Oi Tong Circuit Planter Area	Transplant Transplant	Transplant Transplant	N/A N/A	0	04-Aug-10	0	06-Aug-10 06-Aug-10	0	07-Sep-10 07-Sep-10		13-Oct-10 13-Oct-10	0	Transplanted

532 6	101	TW1005 假檳榔	Yan Oi Tong Circuit Planter Area	Transplant	Transplant	N/A	0	02-Aug-10	0	06-Aug-10	0	08-Sep-10	0	13-Oct-10	0	Transplanted
533 6	101	TW1006 假檳榔	Yan Oi Tong Circuit Planter Area	Transplant	Transplant	N/A	0	02-Aug-10	0	07-Aug-10	0	08-Sep-10	0	12-Oct-10	0	Transplanted
		TW1007 假檳榔	Yan Oi Tong Circuit Planter Area	Transplant	Transplant	N/A	0	04-Aug-10	0	30-Aug-10	0	12-Oct-10	0	12-Oct-10	0	Transplanted
	t to the second	TW1008 假檳榔	Yan Oi Tong Circuit Planter Area	Transplant	Transplant	N/A	0	30-Aug-10	0	30-Aug-10	0	13-Oct-10	0	13-Oct-10	0	Transplanted
		TW1009 假檳榔	Yan Oi Tong Circuit Planter Area	Transplant	Transplant	N/A	0	02-Aug-10	0	07-Aug-10	0	08-Sep-10	0	12-Oct-10	0	Transplanted
	101	TW1010	Yan Oi Tong Circuit Planter Area	Transplant	Transplant	N/A	0	18-Nov-10	0	23-Nov-10	0	23-Nov-10	0	23-Nov-10	0	Transplanted
—		TW1011 假檳榔	Yan Oi Tong Circuit Planter Area	Transplant	Transplant	N/A	0	02-Aug-10	0	13-Oct-10	0	13-Oct-10	0	13-Oct-10	0	Transplanted
	101	TW1012		-		N/A N/A	0		0		0	22-Nov-10	0		0	
1			Yan Oi Tong Circuit Planter Area	Transplant	Transplant	†	0	17-Nov-10	0	22-Nov-10	0		0	22-Nov-10	0	Transplanted
—		TW1013 假檳榔	Yan Oi Tong Circuit Planter Area	Transplant	Transplant	N/A	0	02-Aug-10	0	09-Aug-10	0	12-Oct-10	0	12-Oct-10	0	Transplanted
	+	TW1014 假檳榔	Yan Oi Tong Circuit Planter Area	Transplant	Transplant	N/A	0	02-Aug-10	0	20-Aug-10	0	12-Oct-10	0	12-Oct-10	0	Transplanted
		TW1015 假檳榔	Yan Oi Tong Circuit Planter Area	Transplant	Transplant	N/A	0	02-Aug-10	0	07-Aug-10	0	08-Sep-10	0	12-Oct-10	0	Transplanted
		TW1016 串錢柳	Yan Oi Tong Circuit Planter Area	Transplant	Transplant	N/A	0	02-Aug-10	0	06-Aug-10	0	08-Sep-10	0	27-Oct-10	0	Transplanted
544 6	101	TW1017 石栗	Yan Oi Tong Circuit Planter Area	Transplant	Transplant	N/A	0	02-Aug-10	0	07-Aug-10	0	08-Sep-10	0	08-Oct-10	0	Transplanted
		TW1018 石栗	Yan Oi Tong Circuit Planter Area	Transplant	Transplant	N/A	0	02-Aug-10	0	30-Aug-10	0	05-Oct-10	0	08-Oct-10	0	Transplanted
546 6	101	TW1019 大葉合歡	Yan Oi Tong Circuit Planter Area	Fell	Fell	03-Aug-10	0	-	0	-	0	-	0	-	0	
547 6	101	TW1020 大葉合歡	Yan Oi Tong Circuit Planter Area	Fell	Fell	02-Aug-10	0	-	0	-	0	1	0	-	0	
548 6	101	TW1021 鳥桕	Yan Oi Tong Circuit Planter Area	Transplant	Transplant	N/A	0	03-Aug-10	0	07-Aug-10	0	08-Sep-10	0	08-Oct-10	0	Transplanted
549 6	101	TW1022	Yan Oi Tong Circuit Planter Area	Transplant	Transplant	N/A	0	03-Aug-10	0	25-Nov-10	0	25-Nov-10	0	25-Nov-10	0	Transplanted
		TW1023 石栗	Yan Oi Tong Circuit Planter Area	Transplant	Transplant	N/A	0	03-Aug-10	0	07-Aug-10	0	10-Sep-10	0	08-Oct-10	0	Transplanted
		TW1024 鳥桕	Yan Oi Tong Circuit Planter Area	Transplant	Transplant	N/A	0	03-Aug-10	0	09-Aug-10	0	09-Sep-10	0	08-Oct-10	0	Transplanted
		TW1025 鳥桕	Yan Oi Tong Circuit Planter Area	Transplant	Retain	N/A	()	30-Mar-11	0	04-Apr-11	0	09-May-11	0	05-Sep-11	0	Transplanted
		TW1026 石栗	Yan Oi Tong Circuit Planter Area	Transplant	Retain	N/A	0	30-Mar-11	0	04-Apr-11	0	10-May-11	0	06-Sep-11	0	Transplanted
	-	TW1027 大葉合歡	Yan Oi Tong Circuit Planter Area	Fell	Fell	03-Aug-10	0	-	0		0	-	0		0	Tanopianoa
	101	TW1027	Yan Oi Tong Circuit Planter Area	Transplant	Transplant	N/A	0	17-Nov-10	0	25-Nov-10	0	25-Nov-10	0	25-Nov-10	0	Transplanted
	101	TW1029				N/A N/A	0	17-Nov-10 17-Nov-10	0		0		0		0	
			Yan Oi Tong Circuit Planter Area Van Oi Tong Circuit Planter Area	Transplant	Transplant		0		0	26-Nov-10	0	26-Nov-10	0	26-Nov-10	0	Transplanted Transplanted
		TW1030 假檳榔	Yan Oi Tong Circuit Planter Area	Transplant	Retain	N/A	U	30-Mar-11	0	04-Apr-11	U	09-May-11	+ +	06-Sep-11	0	Transplanted Transplanted
		TW1031 假檳榔	Yan Oi Tong Circuit Planter Area	Transplant	Retain	N/A	0	30-Mar-11	0	04-Apr-11	0	09-May-11		06-Sep-11	0	Transplanted
		TW1032 假檳榔	Yan Oi Tong Circuit Planter Area	Transplant	Retain	N/A	0	30-Mar-11	0	04-Apr-11	0	10-May-11	0	06-Sep-11	0	Transplanted
	101	TW1033 大葉合歡	Yan Oi Tong Circuit Planter Area	Retain	Retain	-	0	-	0	-	0	-	0	-	0	
		TW1034 假檳榔	Yan Oi Tong Circuit Planter Area	Transplant	Retain	N/A	0	30-Mar-11	0	04-Apr-11	0	10-May-11	0	07-Sep-11	0	Transplanted
		TW1035 假檳榔	Yan Oi Tong Circuit Planter Area	Transplant	Retain	N/A	0	30-Mar-11	0	01-Apr-11	0	10-May-11	0	07-Sep-11	0	Transplanted
		TW1036 假檳榔	Yan Oi Tong Circuit Planter Area	Transplant	Transplant	N/A	0	02-Aug-10	0	07-Aug-10	0	09-Sep-10	0	18-Oct-10	0	Transplanted
		TW1037 串錢柳	Yan Oi Tong Circuit Planter Area	Transplant	Transplant	N/A	0	03-Aug-10	0	09-Aug-10	0	09-Sep-10	0	13-Nov-10	0	Transplanted
565 6	101	TW1038 洋紫荆	Yan Oi Tong Circuit Planter Area	Transplant	Transplant	N/A	0	04-Aug-10	0	09-Aug-10	0	09-Sep-10	0	19-Oct-10	0	Transplanted
566 6	101	TW1039 串錢柳	Yan Oi Tong Circuit Planter Area	Transplant	Transplant	N/A	0	03-Aug-10	0	09-Aug-10	0	09-Sep-10	0	18-Oct-10	0	Transplanted
567 6	101	TW1040 串錢柳	Yan Oi Tong Circuit Planter Area	Transplant	Transplant	N/A	0	03-Aug-10	0	09-Aug-10	0	09-Sep-10	0	18-Oct-10	0	Transplanted
568 6	101	TW1041 串錢柳	Yan Oi Tong Circuit Planter Area	Transplant	Transplant	N/A	0	03-Aug-10	0	09-Aug-10	0	09-Sep-10	0	18-Oct-10	0	Transplanted
		TW1042 串錢柳	Yan Oi Tong Circuit Planter Area	Transplant	Transplant	N/A	0	03-Aug-10	0	09-Aug-10	0	09-Sep-10	0	18-Oct-10	0	Transplanted
		TW1043 串錢柳	Yan Oi Tong Circuit Planter Area	Transplant	Transplant	N/A	0	03-Aug-10	0	09-Aug-10	0	09-Sep-10	0	18-Oct-10	0	Transplanted
	101	TW1044	Yan Oi Tong Circuit Planter Area	Transplant	Retain	N/A	0	30-Mar-11	0	01-Apr-11	0	10-May-11	0	08-Sep-11	0	Transplanted
		TW1045	Yan Oi Tong Circuit Planter Area	Transplant	Transplant	N/A	()	04-Aug-10	0	07-Aug-10	0	09-Sep-10	0	28-Oct-10	0	Transplanted
_ 	101	TW1046 洋紫荆	Yan Oi Tong Circuit Planter Area	Transplant	Transplant	N/A	0	04-Aug-10	0	09-Sep-10	0	13-Nov-10	0	13-Nov-10	0	Transplanted
	101	TW1047	Yan Oi Tong Circuit Planter Area	Transplant	Transplant	N/A	0	17-Nov-10	0	26-Nov-10	0	26-Nov-10	0	26-Nov-10	0	Transplanted
		TW1048	Yan Oi Tong Circuit Planter Area	Fell	Retain	30-Mar-11	0	- -	0	-	0		0	-	0	Tanopianea
	101	TW1049 洋紫荆	Yan Oi Tong Circuit Planter Area	Transplant	Transplant	N/A	0	09-Sep-10	0	09-Sep-10	0	19-Oct-10	0	19-Oct-10	0	Transplanted
—		TW1050 假檳榔				N/A N/A	0		0		0	09-Sep-10	0	19-0ct-10	0	_
			Yan Oi Tong Circuit Planter Area	Transplant	Transplant	 	0	02-Aug-10	0	07-Aug-10	0		0		0	Transplanted Transplanted
—		TW1051 石栗	Yan Oi Tong Circuit Planter Area	Transplant	Retain	N/A	U	30-Mar-11	0	02-Apr-11	U	10-May-11	U	06-Sep-11	0	Transplanted
		TW1052 假檳榔	Yan Oi Tong Circuit Planter Area	Transplant	Transplant	N/A	0	02-Aug-10	0	07-Aug-10	U	09-Sep-10	U	19-Oct-10	0	Transplanted
— — — — — — — — — — — — — — — — — — —		TW1053 大葉桉	Yan Oi Tong Circuit Planter Area	Fell	Fell	05-Aug-10	0	-	0	-	0	- 1035	0	-	0	
—		TW1054 假檳榔	Yan Oi Tong Circuit Planter Area	Transplant	Retain	N/A	0	30-Mar-11	0	01-Apr-11	0	10-May-11	0	07-Sep-11	0	Transplanted
	-	TW1055 藍花楹	Yan Oi Tong Circuit Planter Area	Fell	Retain	30-Mar-11	0	-	0	-	0	-	0	-	0	
		TW1056 大葉桉	Yan Oi Tong Circuit Planter Area	Fell	Fell	05-Aug-10	0	-	0	-	0	-	0	-	0	
		TW1057 大葉桉	Yan Oi Tong Circuit Planter Area	Fell	Fell	05-Aug-10	0	-	0	-	0	-	0	-	0	
585 6	101	TW1058 大葉桉	Yan Oi Tong Circuit Planter Area	Fell	Fell	04-Aug-10	0	-	0	-	0	-	0	-	0	
586 6	101	TW1059 大葉桉	Yan Oi Tong Circuit Planter Area	Fell	Fell		0	-	0	-	0	-	0	-	0	
		TW1060 大葉合歡	Yan Oi Tong Circuit Planter Area	Retain	Retain	-	0	-	0	-	0	-	0	-	0	
		TW1061 石栗	Yan Oi Tong Circuit Planter Area	Retain	Retain	-	0	-	0	-	0	-	0	-	0	
—	-	TW1062 石栗	Yan Oi Tong Circuit Planter Area	Retain	Retain	-	()	-	0	-	()	-	0	-	0	
	101	TW1063 -	Yan Oi Tong Circuit Planter Area	Remove	-	_	0		0	_	0	_	0	-	0	
		TW1065 石栗	Yan Oi Tong Circuit Planter Area	Retain	Retain	-	0		0	_	0	-	0	-	0	
		TW1066 石栗	Yan Oi Tong Circuit Planter Area	Retain	Retain		0	<u>-</u>	0	-	0	-	0		0	
J7Z 0	101	1 W 1000 口术	Tall Of Tolig Circuit Flather Area	Kelalli	Relalli	-	U	-	U	-	U	-	U	-	U	

593	6101	TW1067 石栗	Yan Oi Tong Circuit Planter Area	Retain	Retain	_		_	0	_	0	_			0	
594	6101	TW1068 石栗	Yan Oi Tong Circuit Planter Area	Retain	Retain		0	<u> </u>	0	_	0	<u>-</u>	0	<u>-</u>	0	
595	6101	TW1069	Tuen Mun Road B Bound Slip Road to Pui To Road	Fell	Fell	15-Sep-10	0		0	_	0		0		0	Night Work
373	0101		Tuch Mun Road B Bound Ship Road to Fur To Road		T CII	13-SCP-10	0		U	_	U			-	U	Missing/removed
596	6101	TW1070 -	Tuen Mun Road B Bound Slip Road to Pui To Road	Fell	-	Done	0	-	0	-	0	-	0	-	0	during site
597	6101	TW1071 大葉合歡	Tuen Mun Road B Bound Slip Road to Pui To Road	Fell	Fell	15-Sep-10	0	_	0	_	0		0		0	Night Work
598	6101	TW1072 石栗	Tuen Mun Road B Bound Slip Road to Pui To Road Tuen Mun Road B Bound Slip Road to Pui To Road	Fell	Fell	15-Sep-10	0	-	0	-	0	-	0	-	0	Night Work
					1011						Ü					Missing/removed
599	6101	TW1073 -	Tuen Mun Road B Bound Slip Road to Pui To Road	Fell	-	Done	0	-	0	-	0	-	0	-	0	during site
600	6101	TW1074 串錢柳	Tuen Mun Road B Bound Slip Road to Pui To Road	Fell	Fell	28-Sep-10	0	-	0	-	0	-	0	-	0	Night Work
601	6101	TW1075 串錢柳	Tuen Mun Road B Bound Slip Road to Pui To Road	Fell	Fell	15-Sep-10	0	-	0	-	0	-	0	-	0	Night Work
602	6101	TW1076 串錢柳	Tuen Mun Road B Bound Slip Road to Pui To Road	Fell	Fell	15-Sep-10	0	-	0	-	0	-	0	-	0	Night Work
603	6101	TW1077 雙翼豆	Tuen Mun Road B Bound Slip Road to Pui To Road	Fell	Fell	15-Sep-10	0	-	0	-	0	-	0	-	0	Night Work
604	6101	TW1078 串錢柳	Tuen Mun Road B Bound Slip Road to Pui To Road	Fell	Fell	29-Sep-10	0	-	0	-	0	-	0	-	0	
605	6101	TW1079 串錢柳	Tuen Mun Road B Bound Slip Road to Pui To Road	Fell	Fell	28-Sep-10	0	-	0	-	0	-	0	-	0	Night Work
606	6101	TW1080 串錢柳	Tuen Mun Road B Bound Slip Road to Pui To Road	Fell	Fell	27-Sep-10	0	-	0	-	0	-	0	-	0	
607	6101	TW1081 串錢柳	Tuen Mun Road B Bound Slip Road to Pui To Road	Fell	Fell	29-Sep-10	0	-	0	-	0	-	0	-	0	
608	6101	TW1082 大葉桉	Tuen Mun Road B Bound Slip Road to Pui To Road	Fell	Fell	27-Sep-10	0	-	0	-	0	-	0	-	0	
609	6101	TW1083 串錢柳	Tuen Mun Road B Bound Slip Road to Pui To Road	Fell	Fell	27-Sep-10	0	-	0	-	0	-	0	-	0	
610	6101	TW1084 洋紫荆	Tuen Mun Road B Bound Slip Road to Pui To Road	Fell	Fell	29-Sep-10	0	-	0	-	0	-	0	-	0	
611	6101	TW1085 -	Tuen Mun Road B Bound Slip Road to Pui To Road	Fell	_	Done	0	_	0	_	0	_	0	_	0	Missing/removed
							Ŭ				Ü		Ŭ			during site
612	6101	TW1086 大葉桉	Tuen Mun Road B Bound Slip Road to Pui To Road	Fell	Fell	29-Sep-10	0	-	0	-	0	-	0	-	0	
613	6101	TW1087 洋紫荆	Tuen Mun Road B Bound Slip Road to Pui To Road	Fell	Fell	27-Sep-10	0	-	0	-	0	-	0	-	0	
614	6101	TW1088 大葉桉	Tuen Mun Road B Bound Slip Road to Pui To Road	Fell	Fell	28-Sep-10	0	-	0	-	0	-	0	-	0	
615	6101	TW1089 大葉合歡	Tuen Mun Road B Bound Slip Road to Pui To Road	Fell	Fell	27-Sep-10	0	-	0	-	0	-	0	-	0	
616	6101	TW1090 大葉合歡	Tuen Mun Road B Bound Slip Road to Pui To Road	Fell	Fell	28-Sep-10	0	-	0	-	0	-	0	-	0	Night Work
	6101	TW1091 銀合歡	Tuen Mun Road B Bound Slip Road to Pui To Road	Fell	Fell	28-Sep-10	0	-	0	-	0	-	0	-	0	Night Work
618	6101	TW1092 大葉桉	Tuen Mun Road B Bound Slip Road to Pui To Road	Fell	Fell	27-Sep-10	0	-	0	-	0	-	0	-	0	
619	6101	TW1093 大葉桉	Tuen Mun Road B Bound Slip Road to Pui To Road	Fell	Fell	28-Sep-10	0	-	0	-	0	-	0	-	0	Night Work
620	6101	TW1094 大葉桉	Tuen Mun Road B Bound Slip Road to Pui To Road	Fell	Fell	27-Sep-10	0	-	0	-	0	-	0	-	0	
621	6101	TW1095 大葉桉	Tuen Mun Road B Bound Slip Road to Pui To Road	Fell	Fell	29-Sep-10	0	-	0	-	0	-	0	-	0	
622	6101	TW1096 -	Tuen Mun Road B Bound Slip Road to Pui To Road	Fell	Missing	Done	0	-	0	-	0	-	0	-	0	Missing
623	6101	TW1097 大葉桉	Tuen Mun Road B Bound Slip Road to Pui To Road	Fell	Fell	25-Sep-10	0	-	0	-	0	-	0	-	0	Night Work
624	6101	TW1098 大葉桉	Tuen Mun Road B Bound Slip Road to Pui To Road	Fell	Fell	29-Sep-10	0	-	0	-	0	-	0	-	0	
625	6101	TW1099 大葉桉	Tuen Mun Road B Bound Slip Road to Pui To Road	Fell	Fell	29-Sep-10	0	-	0	-	0	-	0	-	0	
626	6109	TW1100 銀合歡	Castle Peak Road near Site Office	Remove	Remove	01-Jun-10	0	-	0	-	0	-	0	-	0	
627	6109	TW1101 銀合歡	Castle Peak Road near Site Office	Remove	Remove	01-Jun-10	0	-	0	-	0	-	0	-	0	
628	6109	TW1102 銀合歡	Castle Peak Road near Site Office	Remove	Remove	01-Jun-10	0	-	0	-	0	-	0	-	0	
629	6109	TW1103 銀合歡	Castle Peak Road near Site Office	Remove	Remove	01-Jun-10	0	-	0	-	0	-	0	-	0	
630	6109	TW1104 銀合歡	Castle Peak Road near Site Office	Remove	Remove	01-Jun-10	0	-	0	-	0	-	0	-	0	
631	6109	TW1105 銀合歡	Castle Peak Road near Site Office	Remove	Remove	01-Jun-10	0	-	0	-	0	-	0	-	0	
632	6109	TW1106 銀合歡	Castle Peak Road near Site Office	Remove	Remove	01-Jun-10	0	-	0	-	0	-	0	-	0	
633	6109	TW1107 銀合歡	Castle Peak Road near Site Office	Remove	Remove	01-Jun-10	0	-	0	-	0	-	0	-	0	
634	6109	TW1108 銀合歡	Castle Peak Road near Site Office	Remove	Remove	01-Jun-10	0	-	0	-	0	-	0	-	0	
635	6105	TW1143 雙翼豆	Tsing Sin Playground	Transplant	Transplant	N/A	0	25-Aug-10	0	27-Aug-10	0	04-Oct-10	0	26-Oct-10	0	Transplanted
636	6105	TW1144 -	Tsing Sin Playground	Transplant	Missing	-	0	-	0	-	0	-	0	-	0	Missing
637		TW1145 雙翼豆	Tsing Sin Playground	Transplant	Transplant	N/A	0	25-Aug-10	0	27-Aug-10	0	04-Oct-10	0	26-Oct-10	0	Transplanted
638		TW1146 雙翼豆	Tsing Sin Playground	Transplant	Transplant	N/A	0	25-Aug-10	0	27-Aug-10	0	04-Oct-10	0	26-Oct-10	0	Transplanted
639	6105	TW1147 -	Tsing Sin Playground	Transplant	Missing	- >T/A	0	- 17 4 10	0	- 17 4 10	0	- 20.0. 10	0	- 25.0 + 10	0	Missing
640	6105	TW1148 大花紫薇	Tsing Sin Playground	Transplant	Transplant	N/A	0	17-Aug-10	0	17-Aug-10	0	20-Sep-10	0	25-Oct-10	0	Transplanted
641	6105		Tsing Sin Playground	Transplant	Transplant	N/A	0	17-Aug-10	0	17-Aug-10	0	20-Sep-10	0	25-Oct-10	0	Transplanted
642	6105	TW1150 大花紫薇	Tsing Sin Playground	Transplant	Transplant	N/A	0	17-Aug-10	0	17-Aug-10	0	18-Sep-10	0	20-Oct-10	0	Transplanted
643	6105		Tsing Sin Playground	Transplant	Transplant	N/A	0	17-Aug-10	0	17-Aug-10	0	18-Sep-10	0	20-Oct-10	0	Transplanted
			Tsing Sin Playground	Transplant	Transplant	N/A	0	17-Aug-10	0	17-Aug-10	0	18-Sep-10	0	20-Oct-10	0	Transplanted
	6105		Tsing Sin Playground	Transplant	Transplant	N/A	0	17-Aug-10	0	17-Aug-10	0	18-Sep-10	0	20-Oct-10	0	Transplanted
646	6105	TW1154 細葉榕	Tsing Sin Playground	Transplant	Retain	-	0	-	0	-	0		0		0	-
647	6105	TW1155 細葉榕	Tsing Sin Playground	Transplant	Retain	-	0	-	0	-	U		0	-	0	-
648	6105	TW1156 細葉榕	Tsing Sin Playground	Transplant	Retain	-	0	-	0	-	0		0	-	0	-
649	6105	TW1157 細葉榕	Tsing Sin Playground	Transplant	Retain	-	0	- 10	0	- 02.0 10	0	-	0	- 25.0 + 10	0	- TD 1
650	6105		Tsing Hoi Circuit near RCP	Transplant	Transplant	N/A	0	31-Aug-10	0	02-Sep-10	0	04-Oct-10	0	25-Oct-10	0	Transplanted
651	6105	TW1161 血桐	Tsing Hoi Circuit near RCP	Fell	Fell	21-Aug-10	0	-	0	-	0	-	0	-	U	

_															
652	6105	TW1162 黃花夾竹桃	Tsing Hoi Circuit near RCP	Fell	Fell	21-Aug-10 0	_	0	-	0	-	0	-	0	
653	6105	TW1163 黃花夾竹桃	Tsing Hoi Circuit near RCP	Fell	Fell	21-Aug-10 0	-	0	-	0	-	0	-	0	
654	6105	TW1164 黃花夾竹桃	Tsing Hoi Circuit near RCP	Fell	Fell	21-Aug-10 0	-	0	-	0	-	0	-	0	
655		TW1165 銀合歡	Tsing Hoi Circuit near RCP	Remove	Remove	21-Aug-10 0	_	0	_	0	-	0	-	0	
656		TW1166 白千層	Castle Peak Road J/O Fu Fat Lane	Transplant	Transplant	N/A 0	15-Jun-11	0	Not Yet	1	Not Yet	1	22-Mar-12	0	
657		TW1167 白千層	Castle Peak Road J/O Fu Fat Lane	Transplant	Transplant	N/A 0	15-Jun-11	0	Not Yet	1	Not Yet	1	21-Mar-12	0	
658		TW1168 白千層	Castle Peak Road J/O Fu Fat Lane	Fell	Fell	15-Jun-11 0	-	0	-	0	-	0	-	0	
659		TW1169 白千層	Castle Peak Road J/O Fu Fat Lane	Transplant	Transplant	N/A 0	15-Jun-11	0	Not Yet	1	Not Yet	1	20-Mar-12	0	
660		TW1170 白千層	Castle Peak Road J/O Fu Fat Lane	Fell	Fell	19-Mar-12 0	13-3411-11	0	NOT TEL	0	NOT ICT	1	20-1v1a1-12	0	
			Castle Peak Road J/O Fu Fat Lane Castle Peak Road J/O Fu Fat Lane				15-Jun-11	0	Not Yet	1	Not Yet	1	19-Mar-12	0	
661		1 724771		Transplant	Transplant	N/A 0		0		1		1		0	TD 1 1
662				Transplant	Transplant	N/A 0	19-Nov-10	0	08-Jul-11	0	08-Jul-11	0	08-Jul-11	0	Transplanted
663				Transplant	Transplant	N/A 0	19-Nov-10	0	08-Jul-11	0	08-Jul-11	0	08-Jul-11	0	Transplanted
664		TW1174 木麻黄	Castle Peak Road J/O Fu Fat Lane	Fell	Fell	08-Jul-11 0	-	0	-	0	-	0	-	0	
665		TW1182 木麻黄	Castle Peak Road J/O Fu Fat Lane	Retain	Retain	- 0	-	0	-	0	-	0	-	0	
666		TW1183 南洋杉	Castle Peak Road J/O Fu Fat Lane	Retain	Retain	- 0	-	0	-	0	-	0	-	0	
667	6108	TW1185 南洋杉	Castle Peak Road J/O Fu Fat Lane	Retain	Retain	- 0	-	0	-	0	-	0	-	0	
668	6108	TW1186 南洋杉	Castle Peak Road J/O Fu Fat Lane	Retain	Retain	- 0	-	0	-	0	-	0	-	0	
669	6108	TW1187 木麻黄	Castle Peak Road J/O Fu Fat Lane	Fell	Fell	20-Feb-12 0	-	0	-	0	-	0	-	0	
670	6108	TW1190 串錢柳	Castle Peak Road J/O Fu Fat Lane	Transplant	Transplant	N/A 0	16-Nov-11	0	Not Yet	1	Not Yet	1	Not Yet	1	
671	6108	TW1191 串錢柳	Castle Peak Road J/O Fu Fat Lane	Transplant	Transplant	N/A 0	16-Nov-11	0	Not Yet	1	Not Yet	1	Not Yet	1	
672	6108	TW1192 白千層	Castle Peak Road J/O Fu Fat Lane	Transplant	Transplant	N/A 0	16-Nov-11	0	Not Yet	1	Not Yet	1	Not Yet	1	
673		TW1193 串錢柳	Castle Peak Road J/O Fu Fat Lane	Transplant	Transplant	N/A 0	16-Jun-11	0	Not Yet	1	Not Yet	1	Not Yet	1	
674		TW1194 白千層	Castle Peak Road J/O Fu Fat Lane	Transplant	Transplant	N/A 0	16-Jun-11	0	Not Yet	1	Not Yet	1	Not Yet	1	
675		TW1195 白千層	Castle Peak Road J/O Fu Fat Lane	Transplant	Transplant	N/A 0	16-Jun-11	0	Not Yet	1	Not Yet	1	Not Yet	1	
676		TW1196 白千層	Castle Peak Road J/O Fu Fat Lane	Transplant	Transplant	N/A 0	16-Jun-11	0	Not Yet	1	Not Yet	1	Not Yet	1	
677		TW1200 木棉	Tsing Hoi Circuit near Tsing Wu Square	Fell	Fell	13-Nov-10 0	-	0	-	0	-	0	-	0	Night Work
678			Tsing Hoi Circuit near Tsing Wu Square Tsing Hoi Circuit near Tsing Wu Square	Fell	Fell	05-Nov-10 0		0		0		0		0	TVIgitt WOIK
679		TW1201	Tsing Hoi Circuit near Tsing Wu Square Tsing Hoi Circuit near Tsing Wu Square	Fell	Fell	05-Nov-10 0		0	-	0	-	0	<u> </u>	0	
680		TW1202 異懂 TW1203 黃槿					-	0	-	0	-	0	-	0	
			Tsing Hoi Circuit near Tsing Wu Square	Fell	Fell	05-Nov-10 0	-	0	-	0	-	0	-	0	Mississ
681		TW1204 -	Tsing Hoi Circuit near Tsing Wu Square	Fell	- -	Done 0	-	0	-	0	-	0	-	0	Missing
682		TW1205 木棉	Tsing Hoi Circuit near Tsing Wu Square	Fell	Fell	13-Nov-10 0	-	0	-	0	-	0	-	0	Night Work
683		TW1206 黄槿	Tsing Hoi Circuit near Tsing Wu Square	Fell	Fell	13-Nov-10 0	-	0	-	0	-	0	-	0	Night Work
684		TW1207 石栗	Tsing Hoi Circuit near Tsing Wu Square	Fell	Fell	13-Nov-10 0	-	0	-	0	-	0	-	0	Night Work
685		TW1208 楓香	Tsing Hoi Circuit near Tsing Wu Square	Fell	Fell	12-Nov-10 0	-	0	-	0	-	0	-	0	Night Work
686		TW1209 黄槿	Tsing Hoi Circuit near Tsing Wu Square	Fell	Fell	13-Nov-10 0	-	0	-	0	-	0	-	0	Night Work
687		TW1210 石栗	Tsing Hoi Circuit near Tsing Wu Square	Fell	Fell	13-Nov-10 0	-	0	-	0	-	0	-	0	Night Work
688	6104	TW1211 鳳凰木	Tsing Hoi Circuit near Tsing Wu Square	Fell	Fell	13-Nov-10 0	-	0	-	0	-	0	-	0	Night Work
689	6104	TW1212 石栗	Tsing Hoi Circuit near Tsing Wu Square	Fell	Fell	13-Nov-10 0	-	0	-	0	-	0	-	0	Night Work
690	6104	TW1213 黄槿	Tsing Hoi Circuit near Tsing Wu Square	Fell	Fell	12-Nov-10 0	-	0	-	0	-	0	-	0	Night Work
691	6104	TW1214 木棉	Tsing Hoi Circuit near Tsing Wu Square	Fell	Fell	13-Nov-10 0	-	0	-	0	-	0	-	0	Night Work
692	6104	TW1215 宮粉羊蹄甲	Tsing Hoi Circuit near Tsing Wu Square	Fell	Fell	13-Nov-10 0	-	0	-	0	-	0	-	0	Night Work
693	6104	TW1216 木棉	Tsing Hoi Circuit near Tsing Wu Square	Fell	Fell	12-Nov-10 0	-	0	-	0	-	0	-	0	Night Work
694		TW1217 石栗	Tsing Hoi Circuit near Tsing Wu Square	Fell	Fell	12-Nov-10 0	-	0	-	0	-	0	-	0	Night Work
695		TW1218 木棉	Tsing Hoi Circuit near Tsing Wu Square	Fell	Fell	12-Nov-10 0	-	0	-	0	-	0	-	0	Night Work
696			Tsing Hoi Circuit near Tsing Wu Square	Fell	Fell	12-Nov-10 0	_	0	-	0	-	0	-	0	Night Work
697		TW1220 木棉	Tsing Hoi Circuit near Tsing Wu Square	Fell	Fell	11-Nov-10 0	_	0	_	0	-	0	_	0	Night Work
698		TW1221 石栗	Tsing Hoi Circuit near Tsing Wu Square Tsing Hoi Circuit near Tsing Wu Square	Fell	Fell	11-Nov-10 0	_	0	_	0	_	0	_	0	Night Work
699		TW1222 黄槿	Tsing Hoi Circuit near Tsing Wu Square Tsing Hoi Circuit near Tsing Wu Square	Fell	Fell	11-Nov-10 0	_	0	_	0		0		0	Night Work
700		TW1223 石栗	Tsing Hoi Circuit near Tsing Wu Square Tsing Hoi Circuit near Tsing Wu Square	Fell	Fell	11-Nov-10 0	_	0	_	0		0	<u>-</u>	0	Night Work
700		TW1224 木棉	Tsing Hoi Circuit hear Tsing Wu Square Tsing Hoi Circuit near Tsing Wu Square	Fell	Fell	11-Nov-10 0		0		0		0		0	Night Work
701		TW1225 石栗		Fell	Fell	11-Nov-10 0	-	0	-	0		0	<u>-</u>	0	
702			Tsing Hoi Circuit near Tsing Wu Square				-	0	-	0	-	0	-	0	Night Work
704			Tsing Hoi Circuit near Tsing Wu Square	Fell	Fell	11-Nov-10 0	-	0	-	0	-	0	-	U	Night Work
704	6104		Tsing Hoi Circuit near Tsing Wu Square	Fell	Fell	11-Nov-10 0	-	0	-	0	-	U	-	U	Night Work
705		TW1228 木棉	Tsing Hoi Circuit near Tsing Wu Square	Fell	Fell	11-Nov-10 0	-	0	-	0	-	0	-	0	Night Work
			Tsing Hoi Circuit near Tsing Wu Square	Fell	Fell	11-Nov-10 0	-	0	-	0	-	0	-	0	Night Work
			Tsing Hoi Circuit near Tsing Wu Square	Fell	Fell	11-Nov-10 0	-	0	-	0	-	0	-	0	Night Work
		TW1231 黄槿	Tsing Hoi Circuit near Tsing Wu Square	Fell	Fell	05-Nov-10 0	-	0	-	0	-	0		0	
_		TW1232 石栗	Tsing Hoi Circuit near Tsing Wu Square	Fell	Fell	11-Nov-10 0	-	0	-	0	-	0	-	0	Night Work
710	6104	TW1233 石栗	Tsing Hoi Circuit near Tsing Wu Square	Fell	Fell	11-Nov-10 0	-	0	-	0	-	0	-	0	Night Work
711		TW1234 黄槿	Tsing Hoi Circuit near Tsing Wu Square	Fell	Fell	21-Oct-10 0	-	0	-	0	-	0	-	0	
712	6104	TW1235 木棉	Tsing Hoi Circuit near Tsing Wu Square	Fell	Fell	11-Nov-10 0	-	0	-	0	-	0	-	0	Night Work

712	(104	TV11006 7 ##	Tains Hai Cinneit man Tains Was Commen	E-11	E-11	11 N 10		T	0	<u> </u>	0					NT: -1-4 XX71-
713	6104	TW1236 石栗	Tsing Hoi Circuit near Tsing Wu Square	Fell	Fell	11-Nov-10	0	- 00 4 10	0	- 15 D 10	0	- 1 / T-1- 11	0	- 20 E-1- 11	0	Night Work
714	6104 6104	TW1237 大葉合歡 TW1238 大葉合歡	Tuen Hing Road to TMR near Tsing Hoi Playground	Transplant	Transplant	N/A	0	09-Aug-10	0	15-Dec-10	0	14-Feb-11	0	22-Feb-11	0	Night Work
716	6104		Tuen Hing Road to TMR near Tsing Hoi Playground	Fell	Fell Transplant	10-Aug-10 N/A	0	00 Aug 10	0	15 Dag 10	0	- 15-Feb-11	0	<u>-</u> 26-Feb-11	0	Transplanted
716	6104	TW1239 石栗 TW1240 石栗	Tuen Hing Road to TMR near Tsing Hoi Playground	Transplant	-	N/A N/A	0	09-Aug-10	0	15-Dec-10	0	13-Feb-11 14-Feb-11	0	24-Feb-11	0	Transplanted
717	6104	TW1240 石栗	Tuen Hing Road to TMR near Tsing Hoi Playground Tuen Hing Road to TMR near Tsing Hoi Playground	Transplant Transplant	Transplant Transplant	N/A N/A	0	09-Aug-10 09-Aug-10	0	15-Dec-10 15-Dec-10	0	15-Jan-11	0	08-Mar-11	0	Transplanted Transplanted
719		TW1242 石栗	Tuen Hing Road to TMR near Tsing Hoi Playground	Transplant Transplant	Transplant	N/A N/A	0	09-Aug-10 09-Aug-10	0	15-Dec-10 15-Dec-10	0	15-Jan-11 15-Jan-11	0	08-Mar-11	0	Transplanted Transplanted
720	6104	TW1243 石栗	Tuen Hing Road to TMR near Tsing Hoi Playground	Transplant Transplant	Transplant	N/A N/A	0	09-Aug-10 09-Aug-10	0	15-Dec-10 15-Dec-10	0	13-Jan-11 14-Jan-11	0	09-Mar-11	0	Transplanted
720	6104	TW1244 石栗		Retain	Retain		0	09-Aug-10	0	13-Dec-10	0	14-Jan-11	0	09-10141-11	0	Transplanted
722	6103	TW1245 石栗	Tuen Hing Road to TMR near Tsing Hoi Playground Tuen Hing Road to TMR near Tsing Hoi Playground	Retain	Retain	-	0	-	0	-	0	-	0		0	
723	6103	TW1248 石栗	Tuen Hing Road to TMR near Tsing Hoi Playground	Retain	Retain	-	0	-	0	-	0	-	0	<u>-</u>	0	
724	6103	TW1249 石栗	Tuen Hing Road to TMR near Tsing Hoi Playground	Retain	Retain	-	0	-	0	-	0	-	0	-	0	
725	6103	TW1250 石栗	Tuen Hing Road to TMR near Tsing Hoi Playground	Retain	Retain	-	0	-	0	-	0	-	0	-	0	
726	6103	TW1250 石栗	Tuen Hing Road to TMR near Tsing Hoi Playground	Retain	Retain	-	0	-	0	-	0	-	0		0	
727	6103		Tuen Hing Road to TMR near Tsing Hoi Playground	Retain	Retain	-	0	-	0	-	0	<u>-</u>	0		0	
728	6103	TW1258 -	Tuen Hing Road to TMR near Tsing Hoi Playground	Retain			0	-	0	_	0	<u>-</u>	0	<u>-</u>	0	Missing
729	6103	TW1259 台灣相思	Tuen Hing Road to TMR near Tsing Hoi Playground	Retain		23-Dec-11	0	-	0	-	0	-	0	-	0	certified dead
730	6103	TW1260 台灣相思	Tuen Hing Road to TMR near Tsing Hoi Playground	Retain	Retain		0	-	0	_	0	<u>-</u>	0	<u>-</u>	0	certified dead
731	6103	TW1261 大葉合歡	Tuen Hing Road to TMR near Tsing Hoi Playground Tuen Hing Road to TMR near Tsing Hoi Playground	Retain Retain	Retain	-	0	_	0	-	0	-	0	<u> </u>	0	
737	6103	TW1262 大葉合歡	Tuen Hing Road to TMR near Tsing Hoi Playground Tuen Hing Road to TMR near Tsing Hoi Playground	Retain Retain	Retain		0	-	0	-	0	-	0		0	
733	6103	TW1263 大葉合歡	Tuen Hing Road to TMR near Tsing Hoi Playground	Retain	Retain	-	0		0	_	0		0		0	
734	6103	TW1264 大葉合歡	Tuen Hing Road to TMR near Tsing Hoi Playground	Retain	Retain	_	0		0	_	0		0		0	
735	6103	TW1265 大葉合歡	Tuen Hing Road to TMR near Tsing Hoi Playground	Retain	Retain	23-Dec-11	0		0	_	0		0		0	certified dead
736	6103		Tuen Hing Road to TMR near Tsing Hoi Playground	Fell	Fell	25-Aug-10	0		0	_	0		0		0	certified dead
737	6103	TW1267 -	Tuen Hing Road to TMR near Tsing Hoi Playground	Fell	-	Done	0	_	0		0		0		0	Missing
738	6103	TW1268 -	Tuen Hing Road to TMR near Tsing Hoi Playground	Fell		24-Nov-10	0		0		0		0		0	Night Work
739		TW1269 -	Tuen Hing Road to TMR near Tsing Hoi Playground	Fell		Done	0	_	0	_	0		0		0	Missing
740	6103	TW1270 大葉合歡	Tuen Hing Road to TMR near Tsing Hoi Playground	Fell	Fell	25-Aug-10	0		0		0		0		0	Wilssing
741	6103	TW1271 大葉合歡	Tuen Hing Road to TMR near Tsing Hoi Playground	Fell	Fell	23-Aug-10	0	_	0	_	0		0		0	
742	6103	TW1272 台灣相思	Tuen Hing Road to TMR near Tsing Hoi Playground	Fell	Fell	23-Aug-10	0	_	0	_	0	_	0	_	0	
743	6103	TW1273 大葉合歡	Tuen Hing Road to TMR near Tsing Hoi Playground	Fell	Fell	19-Aug-10	0	_	0	_	0	_	0		0	
744	6103	TW1274 台灣相思	Tuen Hing Road to TMR near Tsing Hoi Playground	Fell	Fell	23-Aug-10	0	_	0	_	0	_	0	_	0	
745	6103	TW1275 大葉合歡	Tuen Hing Road to TMR near Tsing Hoi Playground	Fell	Fell	25-Aug-10	0	_	0	_	0	_	0		0	
746	6103	TW1276 台灣相思	Tuen Hing Road to TMR near Tsing Hoi Playground	Fell	Fell	19-Aug-10	0	_	0	_	0	_	0	_	0	
747	6103	TW1277 台灣相思	Tuen Hing Road to TMR near Tsing Hoi Playground	Fell	Fell	19-Aug-10	0	_	0	_	0	_	0	_	0	
748	6103	TW1278 台灣相思	Tuen Hing Road to TMR near Tsing Hoi Playground	Fell	Fell	19-Aug-10	0	_	0	_	0	_	0		0	
749	6103	TW1279 台灣相思	Tuen Hing Road to TMR near Tsing Hoi Playground	Fell	Fell	12-Nov-10	0	-	0	_	0	-	0		0	Night Work
750	6103	TW1280 台灣相思	Tuen Hing Road to TMR near Tsing Hoi Playground	Fell	Fell	25-Aug-10	0	_	0	_	0	_	0		0	Tight Work
751	6103	TW1281 台灣相思	Tuen Hing Road to TMR near Tsing Hoi Playground	Fell	Fell	12-Nov-10	0	-	0	_	0	_	0	_	0	Night Work
752	6103	TW1282 -	Tuen Hing Road to TMR near Tsing Hoi Playground	Fell	-	Done	0	-	0	_	0	-	0	-	0	Missing
753	6103	TW1283 -	Tuen Hing Road to TMR near Tsing Hoi Playground	Fell	-	Done	0	-	0	_	0	-	0	_	0	Missing
754	6103	TW1284 -	Tuen Hing Road to TMR near Tsing Hoi Playground	Fell	-	Done	0	-	0	_	0	-	0	-	0	Missing
755	6103	TW1285 朴樹	Tuen Hing Road to TMR near Tsing Hoi Playground	Fell	Fell	25-Aug-10	0	-	0	-	0	-	0	-	0	
756	6103	TW1286 -	Tuen Hing Road to TMR near Tsing Hoi Playground	Remove	-	23-Aug-10	0	-	0	-	0	-	0	-	0	
757	6103	TW1287 -	Tuen Hing Road to TMR near Tsing Hoi Playground	Fell	-	Done	0	-	0	-	0	-	0	-	0	Missing
758	6103	TW1288 -	Tuen Hing Road to TMR near Tsing Hoi Playground	Fell	-	Done	0	-	0	-	0	-	0	-	0	Missing
759	6103	TW1289 -	Tuen Hing Road to TMR near Tsing Hoi Playground	Fell	-	Done	0	-	0	-	0	-	0	-	0	Missing
760	6103	TW1290 -	Tuen Hing Road to TMR near Tsing Hoi Playground	Fell	-	Done	0	-	0	-	0	-	0	-	0	Missing
761	6103	TW1291 -	Tuen Hing Road to TMR near Tsing Hoi Playground	Fell	-	Done	0	-	0	-	0	-	0	-	0	Missing
762	6103	TW1292 台灣相思	Tuen Hing Road to TMR near Tsing Hoi Playground	Fell	Fell	24-Nov-10	0	-	0	-	0	-	0	-	0	Night Work
763	6103	TW1293 台灣相思	Tuen Hing Road to TMR near Tsing Hoi Playground	Fell	Fell	24-Nov-10	0		0		0	_	0	-	0	Night Work
764	6103	TW1294 台灣相思	Tuen Hing Road to TMR near Tsing Hoi Playground	Fell	Fell	24-Nov-10	0		0		0	<u> </u>	0		0	Night Work
765	6103	TW1295 台灣相思	Tuen Hing Road to TMR near Tsing Hoi Playground	Fell	Fell	24-Nov-10	0	-	0	_	0		0	-	0	Night Work
766	6103	TW1296 台灣相思	Tuen Hing Road to TMR near Tsing Hoi Playground	Retain	Retain		0		0		0	<u> </u>	0	<u> </u>	0	
767			Tuen Hing Road to TMR near Tsing Hoi Playground	Retain	Retain	-	0	-	0	-	0	-	0	-	0	
768			Tuen Hing Road to TMR near Tsing Hoi Playground	Retain	Retain	-	0		0		0	_	0		0	
769		TW1299 台灣相思	Tuen Hing Road to TMR near Tsing Hoi Playground	Retain	Retain	-	0	-	0	-	0	-	0	-	0	
770		TW1300 台灣相思	Tuen Hing Road to TMR near Tsing Hoi Playground	Retain	Retain	-	0		0		0	<u> </u>	0	-	0	
771		1	Tuen Hing Road to TMR near Tsing Hoi Playground	Retain	Retain	-	0	-	0	-	0	-	0	-	0	
772	6103		Tuen Hing Road to TMR near Tsing Hoi Playground	Retain	Retain	-	0	-	0	-	0	-	0	-	0	
773	6104	TW1303 宮粉羊蹄甲	Tsing Wu Square Footpath	Transplant	Transplant	N/A	0	28-Aug-10	0	28-Aug-10	0	30-Sep-10	0	30-Sep-10	0	Transplanted

774	6104	TW1204	次·庇井II	Tains Wy Canage Factuath	Tuonanlant	Tuonanlant	NT/A		20 Aug 10	0	11 Care 10	0	20 San 10		20 Can 10		Tuonanlantad
		TW1304		Tsing Wu Square Footpath	Transplant	Transplant	N/A	0	28-Aug-10	0	11-Sep-10	0	30-Sep-10	0	30-Sep-10	0	Transplanted
		TW1305		Tsing Wu Square Footpath	Transplant	Transplant	N/A	0	28-Aug-10	0	28-Aug-10	0	30-Sep-10	0	30-Sep-10	0	Transplanted
	6104	TW1306		Tsing Wu Square Footpath	Transplant	Transplant	N/A	0	25-Aug-10	0	28-Aug-10	0	02-Oct-10	0	02-Oct-10	0	Transplanted
		TW1307		Tsing Wu Square Footpath	Transplant	Transplant	N/A	0	25-Aug-10	0	28-Aug-10	0	02-Oct-10	0	02-Oct-10	0	Transplanted
	6104	TW1308		Tsing Wu Square Footpath	Transplant	Transplant	N/A	0	28-Aug-10	0	28-Aug-10	0	02-Oct-10	0	02-Oct-10	0	Transplanted
	6107	TW1309	白千層	Castle Peak Road J/O Tuen Hing Road	Transplant	Transplant	N/A	0	22-Nov-10	0	28-Dec-10	0	28-Sep-11	0	28-Sep-11	0	Transplanted
	6107	TW1310		Castle Peak Road J/O Tuen Hing Road	Transplant	Transplant	N/A	0	22-Nov-10	0	23-Dec-10	0	30-Sep-11	0	30-Sep-11	0	Transplanted
	6107	TW1311	白千層	Castle Peak Road J/O Tuen Hing Road	Transplant	Transplant	N/A	0	22-Nov-10	0	28-Dec-10	0	27-Sep-11	0	27-Sep-11	0	Transplanted
		TW1312		Castle Peak Road J/O Tuen Hing Road	Transplant	Transplant	N/A	0	22-Nov-10	0	28-Dec-10	0	26-Sep-11	0	26-Sep-11	0	Transplanted
		TW1313	朴樹	Castle Peak Road J/O Tuen Hing Road	Retain	Retain	- 10	0	-	0	-	0	-	0	-	0	1
		TW1315	朴樹	Castle Peak Road J/O Tuen Hing Road	Transplant	Retain	20-Jan-12	0	-	0	-	0	-	0	-	_	removed; certified dead
	6107	TW1316	檸檬桉	Castle Peak Road J/O Tuen Hing Road	Retain	Retain	-	0	-	0	-	0	-	0	-	0	F D : 20/5
	6107	TW1340	鳳凰木	Castle Peak Road J/O Tuen Hing Road	Retain	Retain	-	0	-	0	-	0	-	0	-	0	Free Pruning on 30/5
	6107	TW1341	鳳凰木	Castle Peak Road J/O Tuen Hing Road	Retain	Retain	-	0	-	0	-	0	-	0	-	0	Free Pruning on 30/5
	6103	TW1369		Tuen Fat Road to Tuen Mun Road near Tuen Lee Street	Transplant	Transplant	N/A	0	30-Nov-10	0	30-Nov-10	0	05-Jan-11	0	26-Feb-11	0	Night Work
	6103	TW1370	白千層	Tuen Fat Road to Tuen Mun Road near Tuen Lee Street	Transplant	Transplant	N/A	0	30-Nov-10	0	30-Nov-10	0	05-Jan-11	0	26-Feb-11	0	Night Work
	6103	TW1371		Tuen Fat Road to Tuen Mun Road near Tuen Lee Street	Fell	Fell	27-Aug-10	0	-	0	-	0	-	0	-	0	
	6103	TW1372	台灣相思	Tuen Fat Road to Tuen Mun Road near Tuen Lee Street	Fell	Fell	01-Dec-10	0	-	0	-	0	-	0	-	0	
	6103	TW1373		Tuen Fat Road to Tuen Mun Road near Tuen Lee Street	Transplant	Transplant	N/A	0	01-Dec-10	0	02-Dec-10	0	05-Jan-11	0	26-Feb-11	0	Night Work
	6103	TW1374	台灣相思	Tuen Fat Road to Tuen Mun Road near Tuen Lee Street	Fell	Fell	27-Aug-10	0	-	0	-	0	-	0	-	0	
	6103	TW1381	白千層	Tuen Fat Road to Tuen Mun Road near Tuen Lee Street	Transplant	Transplant	N/A	0	30-Nov-10	0	30-Nov-10	0	31-Dec-10	0	01-Mar-11	0	Night Work
795	6103	TW1382	白千層	Tuen Fat Road to Tuen Mun Road near Tuen Lee Street	Transplant	Transplant	N/A	0	30-Nov-10	0	30-Nov-10	0	31-Dec-10	0	01-Mar-11	0	Night Work
	6103	TW1383	白千層	Tuen Fat Road to Tuen Mun Road near Tuen Lee Street	Transplant	Transplant	N/A	0	01-Dec-10	0	01-Dec-10	0	31-Dec-10	0	03-Mar-11	0	Night Work
	6103	TW1384	白千層	Tuen Fat Road to Tuen Mun Road near Tuen Lee Street	Transplant	Transplant	N/A	0	01-Dec-10	0	01-Dec-10	0	31-Dec-10	0	02-Mar-11	0	Night Work
		TW1385		Tuen Fat Road to Tuen Mun Road near Tuen Lee Street	Transplant	Transplant	N/A	0	01-Dec-10	0	01-Dec-10	0	31-Dec-10	0	02-Mar-11	0	Night Work
799	6103	TW1386	白千層	Tuen Fat Road to Tuen Mun Road near Tuen Lee Street	Transplant	Transplant	N/A	0	01-Dec-10	0	02-Dec-10	0	31-Dec-10	0	03-Mar-11	0	Night Work
800	6103	TW1387	白千層	Tuen Fat Road to Tuen Mun Road near Tuen Lee Street	Transplant	Transplant	N/A	0	01-Dec-10	0	02-Dec-10	0	29-Dec-10	0	04-Mar-11	0	Night Work
801	6102	TW1414	石栗	Tuen Mun Road B Bound Slip Road to Pui To Road	Transplant	Transplant	N/A	0	18-Sep-10	0	25-Sep-10	0	23-Dec-10	0	01-May-11	0	Night Work
802	6102	TW1415	石栗	Tuen Mun Road B Bound Slip Road to Pui To Road	Transplant	Transplant	N/A	0	18-Sep-10	0	25-Sep-10	0	12-Feb-11	0	21-May-11	0	17-Dec-10
803	6102		串錢柳	Tuen Mun Road B Bound Slip Road to Pui To Road	Transplant	Transplant	N/A	0	18-Sep-10	0	25-Sep-10	0	16-Dec-10	0	01-May-11	0	Night Work
804	6102	TW1417		Tuen Mun Road B Bound Slip Road to Pui To Road	Transplant	Transplant	N/A	0	18-Sep-10	0	25-Sep-10	0	17-Dec-10	0	01-May-11	0	Night Work
805	6102	TW1418	串錢柳	Tuen Mun Road B Bound Slip Road to Pui To Road	Transplant	Transplant	N/A	0	18-Sep-10	0	25-Sep-10	0	16-Dec-10	0	01-May-11	0	Night Work
806	6102	TW1419	石栗	Tuen Mun Road B Bound Slip Road to Pui To Road	Transplant	Transplant	N/A	0	17-Sep-10	0	27-Sep-10	0	23-Dec-10	0	19-May-11	0	
807	6102	TW1420	鳳凰木	Tuen Mun Road B Bound Slip Road to Pui To Road	Transplant	Transplant	N/A	0	13-Feb-11	0	15-Feb-11	0	09-Apr-11	0	20-May-11	0	Big tree crown
808	6102	TW1421	石栗	Tuen Mun Road B Bound Slip Road to Pui To Road	Fell	Fell	25-Sep-10	0	-	0	-	0	-	0	-	0	Night Work
809	6102	TW1422	串錢柳	Tuen Mun Road B Bound Slip Road to Pui To Road	Transplant	Transplant	N/A	0	18-Sep-10	0	28-Sep-10	0	04-Dec-10	0	04-Dec-10	0	Transplanted
810	6102	TW1423	串錢柳	Tuen Mun Road B Bound Slip Road to Pui To Road	Fell	Fell	18-Sep-10	0	-	0	-	0	-	0	-	0	
811	6101	TW1425	石栗	Tuen Mun Road B Bound Slip Road to Pui To Road	Transplant	Transplant	N/A	0	14-Dec-10	0	17-Dec-10	0	19-Jan-11	0	21-May-11	0	
812	6101	TW1426	石栗	Tuen Mun Road B Bound Slip Road to Pui To Road	Transplant	Transplant	N/A	0	18-Sep-10	0	17-Dec-10	0	19-Jan-11	0	14-Feb-11	0	27/9 First Root
813	6101	TW1427	石栗	Tuen Mun Road B Bound Slip Road to Pui To Road	Transplant	Transplant	N/A	0	14-Dec-10	0	17-Dec-10	0	19-Jan-11	0	14-Feb-11	0	Transplanted
814	6101	TW1428	鳳凰木	Tuen Mun Road B Bound Slip Road to Pui To Road	Transplant	Transplant	N/A	0	14-Dec-10	0	16-Dec-10	0	19-Jan-11	0	12-Feb-11	0	Transplanted
815	6101	TW1429		Tuen Mun Road B Bound Slip Road to Pui To Road	Transplant	Transplant	N/A	0	18-Sep-10	0	27-Sep-10	0	04-Dec-10	0	04-Dec-10	0	Transplanted
		TW1430	串錢柳	Tuen Mun Road B Bound Slip Road to Pui To Road	Transplant	Transplant	N/A	0	18-Sep-10	0	27-Sep-10	0	03-Dec-10	0	03-Dec-10	0	Transplanted
	6101	TW1431	串錢柳	Tuen Mun Road B Bound Slip Road to Pui To Road	Transplant	Transplant	N/A	0	18-Sep-10	0	27-Sep-10	0	03-Dec-10	0	03-Dec-10	0	Transplanted
	6101	TW1432		Tuen Mun Road B Bound Slip Road to Pui To Road	Fell	Fell	25-Sep-10	0	-	0	-	0	-	0	-	0	Night Work
	6101	TW1433	大葉合歡	Tuen Mun Road B Bound Slip Road to Pui To Road	Fell	Fell	25-Sep-10	0	-	0	-	0	-	0	-	0	Night Work
	6101	TW1434	石栗	Tuen Mun Road B Bound Slip Road to Pui To Road	Transplant	Transplant	N/A	0	18-Sep-10	0	28-Sep-10	0	17-Dec-10	0	11-Feb-11	0	Transplanted
		TW1435	大葉桉	Tuen Mun Road B Bound Slip Road to Pui To Road	Fell	Fell	25-Sep-10	0	-	0	-	0	-	0	<u> </u>	0	Night Work
	6101	TW1436	大葉桉	Tuen Mun Road B Bound Slip Road to Pui To Road	Fell	Fell	28-Sep-10	0	-	0	-	0	-	0	-	0	Night Work
		TW1437	大葉桉	Tuen Mun Road B Bound Slip Road to Pui To Road	Fell	Fell	28-Sep-10	0	_	0	_	0	-	0	-	0	Night Work
824	6101	TW1438	大葉桉	Tuen Mun Road B Bound Slip Road to Pui To Road	Fell	Fell	28-Sep-10	0	_	0	_	0	-	0	-	0	Night Work
825	6101	TW1439	-	Tuen Mun Road B Bound Slip Road to Pui To Road Tuen Mun Road B Bound Slip Road to Pui To Road	Remove	-	_0 50p 10	0	_	0	_	0	-	0	-	0	2.2011 11 0111
	6101		血桐	Tuen Mun Road B Bound Slip Road to Pui To Road Tuen Mun Road B Bound Slip Road to Pui To Road	Transplant	Transplant	N/A	0	17-Sep-10	0	27-Sep-10	0	23-Dec-10	0	14-Feb-11	0	Transplanted
	6101	TW1441	大葉合歡	Tuen Mun Road B Bound Slip Road to Pui To Road Tuen Mun Road B Bound Slip Road to Pui To Road	Transplant	Transplant	N/A	0	17-Sep-10	0	27-Sep-10	0	16-Dec-10	0	18-Jan-11	0	Transplanted
		TW1441 TW1442		Tuen Mun Road B Bound Slip Road to Pui To Road Tuen Mun Road B Bound Slip Road to Pui To Road	Transplant	Transplant	N/A	n	14-Dec-10	0	16-Dec-10	0		0	12-Feb-11	0	Transplanted Transplanted
			蒲葵	Tuen Mun Road B Bound Slip Road to Pui To Road Tuen Mun Road B Bound Slip Road to Pui To Road	Retain	Retain	- 17/17	n	-	0	-	0		n	-	0	Transpianica
				Tuen Mun Road B Bound Slip Road to Pui To Road Tuen Mun Road B Bound Slip Road to Pui To Road	Retain	Retain		n		0	<u> </u>	0		0	<u>-</u>	0	
			日本 假檳榔	Tuen Mun Road B Bound Slip Road to Pui To Road Tuen Mun Road B Bound Slip Road to Pui To Road	Transplant	Transplant	N/A	0	17-Sep-10	0	25-Sep-10	0	16-Dec-10	n	19-Feb-11	0	Transplanted
				Tuen Mun Road B Bound Slip Road to Pui To Road Tuen Mun Road B Bound Slip Road to Pui To Road	Transplant Transplant	Transplant Transplant	N/A N/A	0	17-Sep-10 17-Sep-10	0	25-Sep-10 25-Sep-10	0	16-Dec-10 16-Dec-10	0	19-Feb-11	0	Transplanted
			假檳榔	Tuen Mun Road B Bound Slip Road to Pui To Road Tuen Mun Road B Bound Slip Road to Pui To Road	Transplant Transplant	Transplant Transplant	N/A N/A	0	17-Sep-10 17-Sep-10	0	23-Sep-10 24-Sep-10	0	16-Dec-10 16-Dec-10	0	19-Feb-11	0	Transplanted
				Tuen Mun Road B Bound Slip Road to Pui To Road Tuen Mun Road B Bound Slip Road to Pui To Road	Transplant Transplant	Transplant Transplant	19-Feb-11	Λ		0		0	16-Dec-10 16-Dec-10	0	17-1'50-11	0	Poor Health
0.24	0101	1 111440	IIX/I具/IVI	Tuch with road d double ship road to ful 10 road	Transplant	Transplant	17-17-01-11	U	17-Sep-10	U	25-Sep-10	U	10-10-10	U	-	U	1 001 11541111

835	6101	TW1449 大葉桉	Tuen Mun Road B Bound Slip Road to Pui To Road	Fell	Fell	25-Sep-10	0	_	0	_	0	_	0 1	-	0	Night Work
836	6101	TW1450 假檳榔	Tuen Mun Road B Bound Slip Road to Pui To Road Tuen Mun Road B Bound Slip Road to Pui To Road	Transplant	Transplant	N/A	0	17-Sep-10	0	25-Sep-10	0	16-Dec-10	0	21-Feb-11	0	Transplanted
837	6101	TW1450 大葉桉	Tuen Mun Road B Bound Slip Road to Pui To Road Tuen Mun Road B Bound Slip Road to Pui To Road	Fell	Fell	25-Sep-10	0		0	25-3cp-10	0	- -	0	21-1-0-11	0	Night Work
838	6101	TW1451 大栗板	Tuen Mun Road B Bound Slip Road to Pui To Road Tuen Mun Road B Bound Slip Road to Pui To Road	Transplant	Transplant	N/A	0	17-Sep-10	0	25-Sep-10	0	16-Dec-10	0	21-Feb-11	0	Transplanted
839	6101	TW1453 假檳榔	Tuen Mun Road B Bound Slip Road to Pui To Road Tuen Mun Road B Bound Slip Road to Pui To Road	Transplant	Transplant	06-Oct-10	0	- -	0	23-3cp-10	0	- -	0	-	0	Poor Health
840	6101	TW1456 -	Tuen Mun Road B Bound Slip Road to Pui To Road Tuen Mun Road B Bound Slip Road to Pui To Road	Remove	-	-	0		0		0		0		0	1 001 Health
8/11		TW1450 - 大葉桉	Yan Oi Tong Circuit Car Park	Fell	Fell	16-Nov-10	0		0	_	0		0	<u> </u>	0	
842	6101	TW1457 大葉桉	Yan Oi Tong Circuit Car Park	Fell	Fell	16-Nov-10	0		0	-	0	-	0	-	0	
843	6101	TW1458		Fell		16-Nov-10	0		0	-	0	-	0		0	
844	6101	TW1459 - TW1460 石栗	Yan Oi Tong Circuit Car Park Yan Oi Tong Circuit Car Park	Fell	Fell	16-Nov-10	0	-	0	-	0	-	0	-	0	
845	6101	TW1460		Fell	Fell		0	-	0	-	0	-	0	-	0	
846	6101	TW1461 石栗 TW1462 石栗	Yan Oi Tong Circuit Car Park	Fell	Fell	16-Nov-10 16-Nov-10	0	-	0	-	0	-	0	-	0	lary at lang
			Yan Oi Tong Circuit Car Park Contro Median pean Sen Teina Street				0	-	0	-	0	-	0	-	0	by other
847		TW1466 白千層	Centre Median near San Tsing Street	Fell	Fell	05-Oct-10	0	-	+	-	0	-	0	-	0	
848	6101	TW1467 白千層	Centre Median near San Tsing Street	Fell	Fell	05-Oct-10	0	-	0	-	0	-	0	-	0	
849	6101	TW1468 白千層	Centre Median near San Tsing Street	Fell	Fell	05-Oct-10	0	-	0	-	0	-	0	-	0	
850	6101	TW1469 白千層	Centre Median near San Tsing Street	Fell	Fell	05-Oct-10	0	-	0	-	0	-	0	-	0	
851	6101	TW1470 白千層	Centre Median near San Tsing Street	Fell	Fell	05-Oct-10	0	-	0	-	0	-	0	-	0	
852	6101	TW1471 白千層	Centre Median near San Tsing Street	Fell	Fell	05-Oct-10	0	-	0	-	0	-	0		0	
853	6101	TW1472 白千層	Centre Median near San Tsing Street	Fell	Fell	05-Oct-10	0	-	0	-	0	-	0		0	
854		TW1473 白千層	Centre Median near San Tsing Street	Retain	Retain	-	0	-	0	-	0	-	0		0	
855	6101	TW1474 白千層	San Tsing Street Car Park	Retain	Retain	-	0	-	0	-	0	-	0		0	
856	6101	TW1475 白千層	San Tsing Street Car Park	Retain	Retain	-	0	-	0	-	0	-	0	-	0	
857	6101	TW1476 白千層	San Tsing Street Car Park	Retain	Retain	-	0	-	0	-	0	-	0	-	0	
858	6101	TW1477 白千層	San Tsing Street Car Park	Retain	Retain	-	0	-	0	-	0	-	0	-	0	
859	6101	TW1478 白千層	San Tsing Street Car Park	Retain	Retain	-	0	-	0	-	0	-	0	-	0	
860	6101	TW1479 白千層	San Tsing Street Car Park	Retain	Retain	-	0	-	0	-	0	-	0	-	0	
861			桃 San Tsing Street Car Park	Retain	Retain	-	0	-	0	-	0	-	0	-	0	
862	6101		桃 San Tsing Street Car Park	Retain	Retain	-	0	-	0	-	0	-	0	-	0	
863	6101		桃 San Tsing Street Car Park	Retain	Retain	-	0	-	0	-	0	-	0	-	0	
864	6108	TW1526 檸檬桉	Castle Peak Road J/O Fu Fat Lane	Fell	Fell	21-Nov-11	0		0	-	0	-	0	-	0	
865	6108	TW1527 檸檬桉	Castle Peak Road J/O Fu Fat Lane	Fell	Fell	21-Nov-11	0	-	0	-	0	-	0	-	0	
866	6108	TW1528 檸檬桉	Castle Peak Road J/O Fu Fat Lane	Fell	Fell	22-Nov-11	0	-	0	-	0	-	0	-	0	
867	6108	TW1529 白千層	Castle Peak Road J/O Fu Fat Lane	Transplant	Transplant	N/A	0	14-Jun-11	0	Not Yet	1	Not Yet	1	19-Mar-12	0	
868	6108	TW1530 白千層	Castle Peak Road J/O Fu Fat Lane	Transplant	Transplant	N/A	0	14-Jun-11	0	19-Aug-11	0	Not Yet	1	23-Mar-12	0	
869	6108	TW1531 白千層	Castle Peak Road J/O Fu Fat Lane	Transplant	Transplant	N/A	0	14-Jun-11	0	Not Yet	1	Not Yet	1	26-Mar-12	0	
870	6108	TW1532 白千層	Castle Peak Road J/O Fu Fat Lane	Transplant	Transplant	N/A	0	14-Jun-11	0	Not Yet	1	Not Yet	1	27-Mar-12	0	
871	6108	TW1533 白千層	Castle Peak Road J/O Fu Fat Lane	Transplant	Transplant	N/A	0	14-Jun-11	0	Not Yet	1	Not Yet	1	28-Mar-12	0	
872	6108	TW1534 檸檬桉	Castle Peak Road J/O Fu Fat Lane	Fell	Fell	22-Nov-11	0	-	0	-	0	-	0	-	0	
873	6108	TW1535 石栗	Castle Peak Road J/O Fu Fat Lane	Transplant	Transplant	N/A	0	13-Jun-11	0	Not Yet	1	Not Yet	1	25-Apr-12	0	
874	6108	TW1536 白千層	Castle Peak Road J/O Fu Fat Lane	Transplant	Transplant	N/A	0	13-Jun-11	0	Not Yet	1	Not Yet	1	Not Yet	1	
875	6108	TW1537 木棉	Castle Peak Road J/O Fu Fat Lane	Transplant	Transplant	N/A	0	13-Jun-11	0	Not Yet	1	Not Yet	1	Not Yet	1	
876	6108	TW1538 洋紫荆	Castle Peak Road near Fu Fat Lane Footpath	Transplant	Transplant	N/A	0	19-Nov-10	0	08-Jul-11	0	08-Jul-11	0	08-Jul-11	0	Transplanted
877	6108	TW1539 宮粉羊蹄	甲 Castle Peak Road near Fu Fat Lane Footpath	Transplant	Transplant	N/A	0	19-Nov-10	0	08-Jul-11	0	08-Jul-11	0	08-Jul-11	0	Transplanted
878	6108	TW1540 宮粉羊蹄	甲 Castle Peak Road near Fu Fat Lane Footpath	Transplant	Transplant	N/A	0	19-Nov-10	0	07-Jul-11	0	07-Jul-11	0	07-Jul-11	0	Transplanted
879	6108	TW1541 洋紫荆	Castle Peak Road near Fu Fat Lane Footpath	Transplant	Transplant	N/A	0	19-Nov-10	0	02-Apr-11	0	12-May-11	0	06-Jul-11	0	Transplanted
880	6108	TW1542 洋紫荆	Castle Peak Road near Fu Fat Lane Footpath	Transplant	Transplant	N/A	0	19-Nov-10	0	02-Apr-11	0	12-May-11	0	07-Jul-11	0	Transplanted
881	6108	TW1543 宮粉羊蹄	甲 Castle Peak Road near Fu Fat Lane Footpath	Transplant	Transplant	N/A	0	19-Nov-10	0	01-Apr-11	0	12-May-11	0	05-Jul-11	0	Transplanted
882	6108	TW1544 宮粉羊蹄	甲 Castle Peak Road near Fu Fat Lane Footpath	Transplant	Transplant	N/A	0	19-Nov-10	0	01-Apr-11	0	12-May-11	0	05-Jul-11	0	Transplanted
883	6108	TW1545 洋紫荆	Castle Peak Road near Fu Fat Lane Footpath	Transplant	Transplant	N/A	0	19-Nov-10	0	02-Apr-11	0	12-May-11	0	05-Jul-11	0	Transplanted
884	6108	TW1546 宮粉羊蹄	甲 Castle Peak Road near Fu Fat Lane Footpath	Transplant	Transplant	N/A	0	19-Nov-10	0	01-Apr-11	0	12-May-11	0	05-Jul-11	0	Transplanted
885	6108	TW1547 宮粉羊蹄	甲 Castle Peak Road near Fu Fat Lane Footpath	Transplant	Transplant	N/A	0	19-Nov-10	0	01-Apr-11	0	12-May-11	0	04-Jul-11	0	Transplanted
886	6108	TW1548 白千層	Castle Peak Road near Fu Fat Lane Footpath	Fell	Fell	29-Jul-11	0	_	0	_	0	-	0	-	0	
887	6108	TW1549 木麻黄	Castle Peak Road near Fu Fat Lane Footpath	Fell	Fell	29-Jul-11	0	-	0	-	0	-	0	-	0	
888	6108	TW1550 木麻黄	Castle Peak Road near Fu Fat Lane Footpath	Fell	Fell	29-Jul-11	0		0	-	0		0	-	0	
		TW1551 木麻黄	Castle Peak Road near Fu Fat Lane Footpath	Fell	Fell	29-Jul-11	0	-	0	-	0	-	0	-	0	
890		TW1552 木麻黄	Castle Peak Road near Fu Fat Lane Footpath	Fell	Fell	29-Jul-11	0	-	0	-	0	-	0	-	0	
		TW1553 串錢柳	Tsing Sin Playground	Transplant	Transplant	N/A	0	17-Aug-10	0	17-Aug-10	0	21-Sep-10	0	21-Sep-10	0	Transplanted
892		TW1554 串錢柳	Tsing Sin Playground	Transplant	Transplant	N/A	0	17-Aug-10	0	17-Aug-10	0	21-Sep-10	0	21-Sep-10	()	Transplanted
893		TW1555 串錢柳	Tsing Sin Playground	Transplant	Transplant	N/A	0	18-Aug-10	0	18-Aug-10	()	21-Sep-10	0	21-Sep-10	0	Transplanted
894		TW1556 串錢柳	Tsing Sin Playground	Transplant	Transplant	N/A	()	18-Aug-10	0	18-Aug-10	0	20-Sep-10	0	20-Sep-10	()	Transplanted
		TW1557 串錢柳	Tsing Sin Playground	Transplant	Transplant	N/A	0	18-Aug-10	0	18-Aug-10	0	20-Sep-10	0	20-Sep-10	0	Transplanted
		1 22 171		- I amopimit	- Impimit	A 1/ A A	J	-0 -100 10	J	10 11005 10	V	_	Ŭ	_	J	_11111111111111111111111111111111111111

							1 1		1	1					1 1	1
-		TW1558 串錢柳	Tsing Sin Playground	Transplant	Transplant	N/A	0	18-Aug-10	0	18-Aug-10	0	20-Sep-10	0	20-Sep-10	0	Transplanted
		TW1559 串錢柳	Tsing Sin Playground	Transplant	Transplant	N/A	0	18-Aug-10	0	18-Aug-10	0	20-Sep-10	0	20-Sep-10	0	Transplanted
<u> </u>		TW1560 串錢柳	Tsing Sin Playground	Transplant	Transplant	N/A	0	18-Aug-10	0	18-Aug-10	0	20-Sep-10	0	20-Sep-10	0	Transplanted
899 6	105	TW1561 串錢柳	Tsing Sin Playground	Transplant	Transplant	N/A	0	18-Aug-10	0	18-Aug-10	0	20-Sep-10	0	20-Sep-10	0	Transplanted
900 6	105	TW1562 散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	04-Aug-10	0	04-Aug-10	0	04-Aug-10	0	25-Aug-10	0	Transplanted
901 6	105	TW1563 散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	04-Aug-10	0	04-Aug-10	0	04-Aug-10	0	25-Aug-10	0	Transplanted
902 6	105	TW1564 散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	04-Aug-10	0	04-Aug-10	0	04-Aug-10	0	25-Aug-10	0	Transplanted
903 6	105	TW1565 散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	04-Aug-10	0	04-Aug-10	0	04-Aug-10	0	25-Aug-10	0	Transplanted
904 6	105	TW1566 散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	04-Aug-10	0	04-Aug-10	0	04-Aug-10	0	24-Aug-10	0	Transplanted
905 6	105	TW1567 散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	04-Aug-10	0	04-Aug-10	0	04-Aug-10	0	24-Aug-10	0	Transplanted
906 6	105	TW1568 散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	04-Aug-10	0	04-Aug-10	0	04-Aug-10	0	24-Aug-10	0	Transplanted
907 6	105	TW1569 散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	04-Aug-10	0	04-Aug-10	0	04-Aug-10	0	24-Aug-10	0	Transplanted
908 6	105	TW1570 散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	04-Aug-10	0	04-Aug-10	0	04-Aug-10	0	25-Aug-10	0	Transplanted
909 6	105	TW1571 散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	04-Aug-10	0	04-Aug-10	0	04-Aug-10	0	25-Aug-10	0	Transplanted
910 6	105	TW1572 散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	04-Aug-10	0	04-Aug-10	0	04-Aug-10	0	25-Aug-10	0	Transplanted
		TW1573 散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	04-Aug-10	0	04-Aug-10	0	04-Aug-10	0	25-Aug-10	0	Transplanted
		TW1574 散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	04-Aug-10	0	04-Aug-10	0	04-Aug-10	0	26-Aug-10	0	Transplanted
		TW1575 散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	04-Aug-10	0	04-Aug-10	0	04-Aug-10	0	26-Aug-10	0	Transplanted
		TW1576 散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	04-Aug-10	0	04-Aug-10	0	04-Aug-10	0	26-Aug-10	0	Transplanted
		TW1577 散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	04-Aug-10	0	04-Aug-10	0	04-Aug-10	0	26-Aug-10	0	Transplanted
		TW1578 散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	04-Aug-10	0	04-Aug-10	0	04-Aug-10	0	26-Aug-10	0	Transplanted
— — — — — — — — — — — — — — — — — — —		TW1579 散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	04-Aug-10	0	04-Aug-10	0	04-Aug-10	0	26-Aug-10	0	Transplanted
		TW1580 散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	()	04-Aug-10	0	04-Aug-10	()	04-Aug-10	()	26-Aug-10	0	Transplanted
		TW1581 散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	05-Aug-10	0	05-Aug-10	0	05-Aug-10	0	26-Aug-10	0	Transplanted
		TW1582 散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	05-Aug-10	0	05-Aug-10	0	05-Aug-10	0	26-Aug-10	0	Transplanted
		TW1583 散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	05-Aug-10	0	05-Aug-10	0	05-Aug-10	0	26-Aug-10	0	Transplanted
		TW1584 散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	05-Aug-10	0	05-Aug-10	0	05-Aug-10	0	26-Aug-10	0	Transplanted
		TW1585 散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	05-Aug-10	0	05-Aug-10	0	05-Aug-10	0	26-Aug-10	0	Transplanted
		TW1586 散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	05-Aug-10	0	05-Aug-10	0	05-Aug-10	0	26-Aug-10	0	Transplanted
		TW1587 散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	05-Aug-10	0	05-Aug-10	0	05-Aug-10	0	26-Aug-10	0	Transplanted
— — — — — — — — — — — — — — — — — — —		TW1588 散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	05-Aug-10	0	05-Aug-10	0	05-Aug-10	0	26-Aug-10	0	Transplanted
		TW1589 散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	05-Aug-10	0	05-Aug-10	0	05-Aug-10	0	26-Aug-10	0	Transplanted
		TW1590 散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	05-Aug-10	0	05-Aug-10	0	05-Aug-10	0	26-Aug-10	0	Transplanted
		TW1590 散尾葵 TW1591 散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	05-Aug-10	0	05-Aug-10	0	05-Aug-10	0	26-Aug-10	0	Transplanted
		TW1592 散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	05-Aug-10	0	05-Aug-10	0	05-Aug-10	0	26-Aug-10	0	Transplanted
		TW1593 散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	05-Aug-10	0	05-Aug-10	0	05-Aug-10	0	26-Aug-10	0	Transplanted
		TW1594 散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	05-Aug-10	0	05-Aug-10	0	05-Aug-10	0	27-Aug-10	0	Transplanted
		TW1595 散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	05-Aug-10	0	05-Aug-10	0	05-Aug-10	0	27-Aug-10	0	Transplanted
		TW1596 散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	05-Aug-10 05-Aug-10	0	05-Aug-10	0	05-Aug-10 05-Aug-10	0	27-Aug-10	0	Transplanted
— — — — — — — — — — — — — — — — — — —		TW1597 散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	05-Aug-10 05-Aug-10	0	05-Aug-10	0	05-Aug-10 05-Aug-10	0	27-Aug-10	0	Transplanted
— — — — — —		TW1598 散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	05-Aug-10	0	05-Aug-10	0	05-Aug-10	0	27-Aug-10	0	Transplanted
		TW1599 散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	05-Aug-10	0	05-Aug-10	0	05-Aug-10	0	27-Aug-10 27-Aug-10	0	Transplanted
		TW1600 散尾葵	Tsing Sin Playground	Transplant Transplant	Transplant	N/A	0	05-Aug-10 05-Aug-10	0	05-Aug-10	0	05-Aug-10 05-Aug-10	0	27-Aug-10 27-Aug-10	0	Transplanted
		TW1601 散尾葵 TW1601 散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	03-Aug-10 02-Aug-10	0	03-Aug-10 02-Aug-10	0	03-Aug-10 02-Aug-10	0	15-Sep-10	0	Transplanted
		TW1602 散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	02-Aug-10 02-Aug-10	0	02-Aug-10 02-Aug-10	0	02-Aug-10 02-Aug-10	0	15-Sep-10 15-Sep-10	0	Transplanted
		TW1603 散尾葵	Tsing Sin Playground Tsing Sin Playground	Transplant Transplant	Transplant Transplant	N/A N/A	0	02-Aug-10 02-Aug-10	0	02-Aug-10 02-Aug-10	0	02-Aug-10 02-Aug-10	0	15-Sep-10 15-Sep-10	0	Transplanted Transplanted
— — — — — — — — — — — — — — — — — — —		TW1604 散尾葵	Tsing Sin Playground	Transplant	Transplant Transplant	N/A	0	02-Aug-10 02-Aug-10	0	02-Aug-10 02-Aug-10	0	02-Aug-10 02-Aug-10	0	15-Sep-10 15-Sep-10	0	Transplanted
		TW1605 散尾葵	Tsing Sin Playground Tsing Sin Playground	Transplant Transplant	Transplant Transplant	N/A N/A	0	02-Aug-10 02-Aug-10	0	02-Aug-10 02-Aug-10	0	02-Aug-10 02-Aug-10	0	15-Sep-10 15-Sep-10	0	Transplanted Transplanted
		TW1606 散尾葵	Tsing Sin Playground Tsing Sin Playground		Transplant Transplant	N/A N/A	0		0	02-Aug-10 02-Aug-10	0		0	15-Sep-10 15-Sep-10	0	Transplanted Transplanted
		TW1607 散尾葵 TW1607 散尾葵		Transplant Transplant		N/A N/A	0	02-Aug-10	0		0	02-Aug-10	0		0	
_ 			Tsing Sin Playground	Transplant Transplant	Transplant Transplant		0	02-Aug-10	0	02-Aug-10	0	02-Aug-10	0	15-Sep-10	0	Transplanted Transplanted
		TW1608 散尾葵	Tsing Sin Playground	Transplant Transplant	Transplant Transplant	N/A	0	02-Aug-10	0	02-Aug-10	0	02-Aug-10	0	15-Sep-10	0	Transplanted Transplanted
		TW1609 散尾葵	Tsing Sin Playground	Transplant Transplant	Transplant Transplant	N/A	0	02-Aug-10	0	02-Aug-10	U	02-Aug-10	0	15-Sep-10	U	Transplanted Transplanted
		TW1610 散尾葵	Tsing Sin Playground	Transplant Transplant	Transplant Transplant	N/A	0	02-Aug-10	0	02-Aug-10	0	02-Aug-10	0	15-Sep-10	0	Transplanted Transplanted
		TW1611 散尾葵	Tsing Sin Playground	Transplant Transplant	Transplant Transplant	N/A	0	02-Aug-10	0	02-Aug-10	0	02-Aug-10	0	15-Sep-10	0	Transplanted Transplanted
		TW1612 散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	U	02-Aug-10	0	02-Aug-10	U	02-Aug-10	0	15-Sep-10	U	Transplanted
		TW1613 散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	U	02-Aug-10	0	02-Aug-10	U	02-Aug-10	U	15-Sep-10	U	Transplanted Transplanted
		TW1614 散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	02-Aug-10	0	02-Aug-10	U	02-Aug-10	0	15-Sep-10	U	Transplanted Transplanted
		TW1615 散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	02-Aug-10	0	02-Aug-10	U	02-Aug-10	0	15-Sep-10	U	Transplanted
		TW1616 散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	02-Aug-10	0	02-Aug-10	U	02-Aug-10	U	15-Sep-10	U	Transplanted
		TW1617 散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	02-Aug-10	0	02-Aug-10	U	02-Aug-10	U	15-Sep-10	U	Transplanted
956 6	105	TW1618 散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	02-Aug-10	U	02-Aug-10	U	02-Aug-10	0	15-Sep-10	U	Transplanted

	•				,		T		T		1					
957 6105	TW1619	散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	02-Aug-10	0	02-Aug-10	0	02-Aug-10	0	15-Sep-10	0	Transplanted
958 6105	TW1620	散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	02-Aug-10	0	02-Aug-10	0	02-Aug-10	0	15-Sep-10	0	Transplanted
959 6105	TW1621	散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	02-Aug-10	0	02-Aug-10	0	02-Aug-10	0	15-Sep-10	0	Transplanted
960 6105	TW1622	散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	02-Aug-10	0	02-Aug-10	0	02-Aug-10	0	15-Sep-10	0	Transplanted
961 6105	TW1623	散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	02-Aug-10	0	02-Aug-10	0	02-Aug-10	0	15-Sep-10	0	Transplanted
962 6105	TW1624	散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	02-Aug-10	0	02-Aug-10	0	02-Aug-10	0	15-Sep-10	0	Transplanted
963 6105	TW1625	散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	02-Aug-10	0	02-Aug-10	0	02-Aug-10	0	15-Sep-10	0	Transplanted
964 6105	TW1626	散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	02-Aug-10	0	02-Aug-10	0	02-Aug-10	0	15-Sep-10	0	Transplanted
965 6105	TW1627	散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	02-Aug-10	0	02-Aug-10	0	02-Aug-10	0	15-Sep-10	0	Transplanted
966 6105	TW1628	散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	02-Aug-10	0	02-Aug-10	0	02-Aug-10	0	14-Sep-10	0	Transplanted
967 6105	TW1629	散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	02-Aug-10	0	02-Aug-10	0	02-Aug-10	0	14-Sep-10	0	Transplanted
968 6105	TW1630	散尾葵		Transplant Transplant	Transplant	N/A	0		0	02-Aug-10 02-Aug-10	0	02-Aug-10 02-Aug-10	0		0	
	•		Tsing Sin Playground				0	02-Aug-10	0		0		0	14-Sep-10	0	Transplanted Transplanted
969 6105	TW1631	散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	02-Aug-10	0	02-Aug-10	0	02-Aug-10	0	14-Sep-10	0	Transplanted
970 6105	TW1632	散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	02-Aug-10	0	02-Aug-10	0	02-Aug-10	0	14-Sep-10	0	Transplanted
971 6105	TW1633	散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	03-Aug-10	0	03-Aug-10	0	03-Aug-10	0	14-Sep-10	0	Transplanted
972 6105	TW1634	散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	03-Aug-10	0	03-Aug-10	0	03-Aug-10	0	14-Sep-10	0	Transplanted
973 6105	TW1635	散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	03-Aug-10	0	03-Aug-10	0	03-Aug-10	0	14-Sep-10	0	Transplanted
974 6105	TW1636	散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	03-Aug-10	0	03-Aug-10	0	03-Aug-10	0	14-Sep-10	0	Transplanted
975 6105	TW1637	散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	03-Aug-10	0	03-Aug-10	0	03-Aug-10	0	14-Sep-10	0	Transplanted
976 6105	TW1638	散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	03-Aug-10	0	03-Aug-10	0	03-Aug-10	0	14-Sep-10	0	Transplanted
977 6105	TW1639	散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	03-Aug-10	0	03-Aug-10	0	03-Aug-10	0	14-Sep-10	0	Transplanted
978 6105	TW1640	散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	03-Aug-10	0	03-Aug-10	0	03-Aug-10	0	14-Sep-10	0	Transplanted
979 6105	TW1641	散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	03-Aug-10	0	03-Aug-10	0	03-Aug-10	0	14-Sep-10	0	Transplanted
980 6105	TW1642	散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	03-Aug-10	0	03-Aug-10	0	03-Aug-10	0	14-Sep-10	0	Transplanted
981 6105	TW1643	散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	03-Aug-10	0	03-Aug-10	0	03-Aug-10	0	14-Sep-10	0	Transplanted
982 6105	TW1644	散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	03-Aug-10	0	03-Aug-10	0	03-Aug-10	0	14-Sep-10	0	Transplanted
983 6105	†	散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	03-Aug-10	0	03-Aug-10	0	03-Aug-10	0	14-Sep-10	0	Transplanted
984 6105	TW1646	散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	03-Aug-10	0	03-Aug-10	0	03-Aug-10	0	14-Sep-10	0	Transplanted
985 6105	TW1647	散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	03-Aug-10	0	03-Aug-10	0	03-Aug-10	0	14-Sep-10	0	Transplanted
986 6105	TW1648	散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	03-Aug-10	0	03-Aug-10	0	03-Aug-10	0	14-Sep-10	0	Transplanted
987 6105	TW1649	散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	10	03-Aug-10	0	03-Aug-10	0	03-Aug-10	0	14-Sep-10	0	Transplanted
988 6105	TW1650	散尾葵	Tsing Sin Playground Tsing Sin Playground	Transplant	Transplant	N/A	0	03-Aug-10	0	03-Aug-10	0	03-Aug-10	0	14-Sep-10	0	Transplanted
989 6105	TW1651	散尾葵				N/A	0		0		0		0		0	
			Tsing Sin Playground	Transplant	Transplant		0	03-Aug-10	0	03-Aug-10	0	03-Aug-10	0	14-Sep-10	0	Transplanted
990 6105	TW1652	散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	03-Aug-10	0	03-Aug-10	0	03-Aug-10	0	14-Sep-10	0	Transplanted
991 6105	TW1653	散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	03-Aug-10	0	03-Aug-10	0	03-Aug-10	0	14-Sep-10	0	Transplanted
992 6105	TW1654	散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	03-Aug-10	0	03-Aug-10	0	03-Aug-10	0	13-Sep-10	0	Transplanted
993 6105	TW1655	散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	03-Aug-10	0	03-Aug-10	0	03-Aug-10	0	13-Sep-10	0	Transplanted
994 6105	TW1656	散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	03-Aug-10	0	03-Aug-10	0	03-Aug-10	0	13-Sep-10	0	Transplanted
995 6105	TW1657	散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	03-Aug-10	0	03-Aug-10	0	03-Aug-10	0	13-Sep-10	0	Transplanted
996 6105	TW1658	散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	03-Aug-10	0	03-Aug-10	0	03-Aug-10	0	13-Sep-10	0	Transplanted
997 6105	TW1659	散尾葵	Tsing Sin Playground	Transplant	Transplant	N/A	0	03-Aug-10	0	03-Aug-10	0	03-Aug-10	0	13-Sep-10	0	Transplanted
998 6108	TWA1	白千層	Castle Peak Road J/O Fu Fat Lane	Transplant	-	N/A	0	16-Nov-11	0	Not Yet	1	Not Yet	1	Not Yet	1	
999 6108	TWA2	白千層	Castle Peak Road J/O Fu Fat Lane	Transplant	-	N/A	0	16-Nov-11	0	Not Yet	1	Not Yet	1	Not Yet	1	
1000 6108	TWA3	石栗	Castle Peak Road J/O Fu Fat Lane	Transplant	-	N/A	0	16-Nov-11	0	Not Yet	1	Not Yet	1	Not Yet	1	
1001 6108	TWA4	白千層	Castle Peak Road J/O Fu Fat Lane	Transplant	-	N/A	0	16-Nov-11	0	Not Yet	1	Not Yet	1	Not Yet	1	
1002 6108	TWA5	白千層	Castle Peak Road J/O Fu Fat Lane	Transplant	-	N/A	0	16-Nov-11	0	Not Yet	1	Not Yet	1	Not Yet	1	
1003 6108	TWA6	白千層	Castle Peak Road J/O Fu Fat Lane	Transplant	-	N/A	0	16-Nov-11	0	Not Yet	1	Not Yet	1	Not Yet	1	
1004 6108	TWA7	白千層	Castle Peak Road J/O Fu Fat Lane	Fell	-	16-Nov-11	0	-	0	-	0	-	0	-	0	
1005 6108	TWA8	白千層	Castle Peak Road J/O Fu Fat Lane	Transplant	-	N/A	0	16-Nov-11	0	Not Yet	1	Not Yet	1	Not Yet	1	
1006 6108	TWA9	白千層	Castle Peak Road J/O Fu Fat Lane	Transplant	-	N/A	0	13-Jun-11	0	Not Yet	1	Not Yet	1	Not Yet	1	
1007 6108	TWA10	石栗	Castle Peak Road J/O Fu Fat Lane	Transplant	-	N/A	0	13-Jun-11	0	Not Yet	1	Not Yet	1	Not Yet	1	
1008 6108	TWA11	白千層	Castle Peak Road J/O Fu Fat Lane	Transplant	-	N/A	0	13-Jun-11	0	Not Yet	1	Not Yet	1	Not Yet	1	
1009 6108	TWA12	白千層	Castle Peak Road J/O Fu Fat Lane	Transplant	-	N/A	0	13-Jun-11	0	Not Yet	1	Not Yet	1	Not Yet	1	
1010 6109	TWA30	火焰木	Castle Peak Road - Castle Peak Bay Outside Site Office	Transplant	-	N/A	0	07-May-11	0	07-May-11	0	09-Jun-11	0	09-Jun-11	0	Transplanted
1011 6109	TWA31	火焰木	Castle Peak Road - Castle Peak Bay Outside Site Office	Transplant	-	N/A	0	07-May-11	0	07-May-11	0	09-Jun-11	0	09-Jun-11	0	Transplanted
1012 6109		木棉	Castle Peak Road - Castle Peak Bay Outside Site Office	Transplant	-	N/A	0	09-May-11	0	16-May-11	0	18-Jun-11	0	23-Jul-11	0	Transplanted
1013 6101	TWA33	鳳凰木	Yan Oi Tong Circuit Car Park	Fell	-	14-Mar-11	0	-	0	-	0	-	0	-	0	
1014 6101	TWA34	洋蹄甲	Yan Oi Tong Circuit Car Park	Fell	-	14-Mar-11	0	-	0	-	0	-	0	-	0	
1015 6101	TWA35	蒲葵	Yan Oi Tong Circuit Car Park	Transplant	-	N/A	0	14-Mar-11	0	15-Apr-11	0	18-May-11	0	18-May-11	0	Transplanted
1016 6101	TWA36	蒲葵	Yan Oi Tong Circuit Car Park	Transplant	-	N/A	0	14-Mar-11	0	15-Apr-11	0	18-May-11	0	18-May-11	0	Transplanted
1017 6104	TWA37	洋蹄甲	Tsing Wui Street Car Park	Fell	-	14-Mar-11	0	-	0	-	0	-	0	-	0	
1018 6104	TWA38	火焰木	Tsing Wui Street Car Park	Transplant	-	N/A	0	14-Mar-11	0	31-Mar-11	0	13-May-11	0	13-May-11	0	Transplanted

1019	5103	TWA39	宮粉羊蹄甲	Tuen Mun Road Slip Road to Tuen Hing Road	Fell	-	13-Mar-11	0	-	0	-	0	-	0	-	0	Night Work
1020	5103	TWA40	宮粉羊蹄甲	Tuen Mun Road Slip Road to Tuen Hing Road	Fell	-	13-Mar-11	0	-	0	-	0	-	0	-	0	Night Work
1021	5103	TWA41	宮粉羊蹄甲	Tuen Mun Road Slip Road to Tuen Hing Road	Fell	-	13-Mar-11	0	-	0	-	0	-	0	-	0	Night Work
1022	SK/880	TWB1	洋紫荆	Castle Peak Road under Sam Shing Hui Bridge	Transplant	Transplant	N/A	0	27-Aug-11	0	27-Aug-11	0	20-Sep-11	0	20-Sep-11	0	
1023	SK/880	TWB2	黃槐	Castle Peak Road under Sam Shing Hui Bridge	Transplant	Transplant	N/A	0	27-Aug-11	0	27-Aug-11	0	19-Sep-11	0	19-Sep-11	0	
1024	SK/880	TWB3	白千層	Castle Peak Road under Sam Shing Hui Bridge	Transplant	Transplant	N/A	0	27-Aug-11	0	27-Aug-11	0	20-Sep-11	0	20-Sep-11	0	
1025	SK/880	TWB4	洋紫荆	Castle Peak Road under Sam Shing Hui Bridge	Transplant	Transplant	N/A	0	27-Aug-11	0	27-Aug-11	0	19-Sep-11	0	19-Sep-11	0	
1026	SK/880	TWB5	黃槐	Castle Peak Road under Sam Shing Hui Bridge	Transplant	Transplant	N/A	0	27-Aug-11	0	27-Aug-11	0	19-Sep-11	0	19-Sep-11	0	
1027	SK/880	TWB6	白千層	Castle Peak Road under Sam Shing Hui Bridge	Transplant	Transplant	N/A	0	27-Aug-11	0	27-Aug-11	0	22-Sep-11	0	22-Sep-11	0	
1028	SK/880	TWB7	洋紫荆	Castle Peak Road under Sam Shing Hui Bridge	Transplant	Transplant	N/A	0	27-Aug-11	0	29-Aug-11	0	19-Sep-11	0	19-Sep-11	0	
1029	SK/880	TWB8	白千層	Castle Peak Road under Sam Shing Hui Bridge	Transplant	Transplant	N/A	0	27-Aug-11	0	29-Aug-11	0	22-Sep-11	0	22-Sep-11	0	
1030	SK/880	TWB9	洋紫荆	Castle Peak Road under Sam Shing Hui Bridge	Transplant	Transplant	N/A	0	27-Aug-11	0	29-Aug-11	0	21-Sep-11	0	21-Sep-11	0	
1031	SK/880	TWB10	洋紫荆	Castle Peak Road under Sam Shing Hui Bridge	Transplant	Transplant	N/A	0	27-Aug-11	0	29-Aug-11	0	20-Sep-11	0	20-Sep-11	0	

24 nos. of New trees under UPTRA No.1 & Revised the proposed treatment

26 nos. of big crown trees

29 nos. of trees in poor health (Application No.2)

Appendix J

Monthly Summary
Waste Flow Table



Monthly Summary of Waste Flow Table for 2012 (year)

Name of Person completing the Record: Marko Chan

Month	Actual Quantities of Inert C&D Materials Generated Monthly				Actual Quantities of Non-inert C&D Wastes Generated Monthly					
	Total Quantity	Broken Concrete	Reused in the Contract	Reused in other	Disposed as Public Fill	Metals	Paper/ cardboard	Plastics	Chemical Waste	Others, e.g. general
	Generated	(see Note 1)		Projects			packaging	(see Note 2)		refuse
	(in '000m ³)	(in '000m ³)	(in '000m ³)	(in '000m ³)	(in '000m ³)	(in '000 Kg)	(in '000 Kg)	(in '000 Kg)	(in '000 Kg)	(in '000m ³)
Jan	3.461250	Nil	Nil	Nil	3.461250	Nil	Nil	Nil	Nil	0.087750
Feb	4.314375	Nil	Nil	Nil	4.314375	5.86600	0.23500	Nil	Nil	0.107250
Mar	5.060250	Nil	0.209625	0.141375	4.709250	0.07015	Nil	Nil	Nil	0.136500
Apr	3.612375	Nil	Nil	Nil	3.612375	0.66500	Nil	Nil	Nil	0.082875
May										
Jun										
Jul										
Aug										
Sept										
Oct										
Nov										
Dec										
Total	16.448250	Nil	0.209625	0.141375	16.097250	6.60115	0.23500	Nil	Nil	0.414375

Notes: (1) Broken concrete for recycling into aggregates.

(2) Plastics refer to plastic bottles/containers, plastic sheets/foam from packaging material.

(3) Use the conversion factor: 1 full load of dumping truck being equivalent to 6.5m3 by volume.

Appendix K
Environmental Monitoring Programme for Coming Month

Agreement No. CE 22/2005 (HY) Traffic Improvement to Tuen Mun Road Town Centre Section Tentative Impact Monitoring Schedule - May 2012 Revision 1

Date	Air Quality	Noise	Landscape &	Site Inspection
	24-hours TSP	L _{Aeq} , 30 min	Visual	
1-May-12 Tue				
2-May-12 Wed				
3-May-12 Thu				
4-May-12 Fri				
5-May-12 Sat				
6-May-12 Sun				
7-May-12 Mon				
8-May-12 Tue				
9-May-12 Wed				
10-May-12 Thu				
11-May-12 Fri				
12-May-12 Sat				
13-May-12 Sun				
14-May-12 Mon				
15-May-12 Tue				
16-May-12 Wed				
17-May-12 Thu				SSEMC
18-May-12 Fri				
19-May-12 Sat				
20-May-12 Sun				
21-May-12 Mon				
22-May-12 Tue				
23-May-12 Wed				
24-May-12 Thu				
25-May-12 Fri				
26-May-12 Sat 27-May-12 Sun				
27-May-12 Sun 28-May-12 Mon				
29-May-12 World				
30-May-12 Wed				
31-May-12 Wed				
31-Way-12 Inu				

Public Holiday
Monitoring Day

Monitoring Details

Monitoring	Quantity	Locations	Parameters
Air Quality	6	Mrs.Aw Boon Haw Secondary School	24-hour TSP,
		Tai Tung Pui Social Service Building	Wind speed / direction
		Wu Siu Kui Primary School	
		Choi Cheung Kok Secondary School	
		Tuen Mun Town Hall	
		Yan Oi Tong Community and Sport Centre	
Noise	6	Kam Fai Garden	L _{Aeq(30 min)} , L ₁₀ , L ₉₀
		Tai Tung Pui Social Service Building	
		Yuen Yuen Primary School	
		Wu Siu Kui Primary School	
		Tuen King Building	
		Choi Cheung Kok Secondary School	