



Sheung Shui to Lok Ma Chau Spur Line (上水至落馬洲支線)  
 Figure 5 - The vertical profile of the tunnel across Long Valley as described Condition 3.9  
 圖五 - 條例3.9所指貫穿壟原之隧道垂直剖面圖  
 (Reproduced from Figure 1 of Appendix A 31 of the EIA Report (Register No.: AEIAR-052/2002)  
 摘自環境評估報告附件A3.1圖 - (登記冊編號: AEIAR - 052/2002)

Environmental  
 Permit  
 No.: FEP-03/29/2002  
 環境許可證編號:  
 FEP-03/129/2002

