

3a. NOISE IMPACT (TTAL SITE)

- 3a.1.1.1 No noise sensitive receiver (NSR) was identified within 300m from the boundary of the IWMF at the TTAL site. Construction and operation noise monitoring is therefore not considered necessary.