

Existing Condition



After Completion
(Indicative)



Copyright in this document and all proprietary rights in the information it contains belong to the AA. It is a condition of the supply of this document, in whatever form, that the recipient shall hold it in confidence and shall not duplicate or otherwise reproduce it in whole or in part, nor disclose its contents without the written consent of the AA.

Rev.	Date	Description	Checked	<div><div><div><div>HONG KONG INTERNATIONAL AIRPORT</div><div>香港國際機場</div></div><div><div>Airport Authority HQA Tower, 1 Sky Plaza Road, Hong Kong Tel: (852) 2388 7711</div><div><div>International Airport, Lantau, Hong Kong Tel: (852) 2551 0717</div></div></div></div><div><div><div><div>Mott MacDonald</div><div>In association with</div></div><div><div>ARUP Atkins China Limited Clymene Enterprises</div><div><div>Deltares Ecosystems Limited SDA Marine Limited</div><div><div>Urbis Limited URS Scott Wilson Limited</div></div></div></div><div>Comparison of the Existing Condition with After Completion of Proposed Diversion Works at Sheung Sha Chau Island</div><div><div>Consultant's Signatures for Approval</div><div><div>Design</div><div>Checkers</div><div>Design Supervisor</div><div>Authorised Representative</div></div><div><div>JT</div><div>GC</div><div>EC</div><div>AFK</div></div><div><div>Date</div><div>13JAN14</div><div>13JAN14</div><div>21MAR14</div><div>21MAR14</div></div></div><div><div>EXPANSION OF HONG KONG INTERNATIONAL AIRPORT INTO A THREE-RUNWAY SYSTEM</div><div><div>Drawing No.</div><div>MCL/P132/EIA/12-035a</div></div><div><div>Scale at A3</div><div>Rev. B</div></div></div></div></div></div>
------	------	-------------	---------	--