



來函檔號 Your Ref: () EP2/N6/F/151 Pt. 2

本署檔號 Our Ref: (00CC1D) in SP 8/4412DS/CE0315/17

電 話 Tel: (852) 2594 7502 圖文傳真 Fax: (852) 2827 8700 渠務署 污水工程部 香港灣仔告士打道 5 號 稅務大樓 44 樓

Environmental Protection Department 28/F, Southorn Centre, 130 Hennessy Road, Wan Chai, Hong Kong

15 April 2019

By Fax (2591 0558)

(Attn: Mr. K. H. TO)

Dear Mr. TO,

Environmental Impact Assessment (EIA) Ordinance, Cap. 499 Application for Approval of EIA Report

Project Title: Yuen Long Effluent Polishing Plant (Application No. EIA-259/2018)

I refer to your above referenced letter dated 12 April 2019 regarding the request for information on the captioned EIA application.

In response to the following request:

"Is there any maintenance dredging at the outfalls during the operation? If affirmative, are there any mitigation measures to avoid adverse water quality and ecological impact?"

Please be informed that there is no maintenance dredging at the outfalls for YLEPP during the operation.

Should you have any queries on the above, please contact the undersigned.

Yours faithfully,

(LEUNG Wing-yuen, Walter) Chief Engineer/Sewerage Projects Drainage Services Department

WKE/TMY