

Shuen Wan Golf Course, Tai Po	SCALE	As Shown	DATE	MAR 201	9
Silderi Wall Goll Course, Tai Po	CHECKED	ELK	DRAWN	TEAM	
Visual Impacts (Scenario 1)	FIGURE NO.	Figur	e 12.10.1		F
		i igui	0 12.10.1		




LEGEND



Project Site Boundary

Visual Envelope



Photomontage Viewpoints


Visually Sensitive Receivers

, , , , , , , , , , , , , , , , , , , ,	
VSR 1.1	Students and Staff of The Education University of Hong Kong
VSR 1.2	Residents of low-rises along Lo Fai Road
PVSR 1.3	Residents of Planned low-rises along Lo Fai Road
VSR 1.4	Pedestrians / Cyclists / Vehicular travellers along Ting Kok Road
VSR 2.1	Residents of Fortune Garden
VSR 2.2	Residents of The Beverly Hills
VSR 2.3	Villagers at Sam Mun Tsai
	0
VSR 3.1	Visitors to Ma On Shan Promenade and Ma On Shan Park
VSR 3.2	Residents of high-rises along Ma On Shan Promenade
VSR 3.3	Workers of Hong Kong Science Park
VSR 3.4	Residents of Pak Shek Kok Promenade
VSR 3.5	Pedestrians / Cyclists along Tolo Harbour
VSR 3.6	Residents of low-rises along Yau King Lane
VSR 3.7	Residents of low-rises along Yat Yiu Avenue, Hung Lam Drive and Tai Po Kau
VSR 4.1	Visitors of Yuen Chau Tsai Park
VSR 4.2	Residents of high-rises at Kwong Fuk Estate and Wang Fuk Court
VSR 4.3	Residents of high-rises at Fu Shin Estate, Ming Nga Court and Riviera Lodge
VSR 4.4	Visitors of Tai Po Waterfront Park
VSR 4.5	Workers of Tai Po Industrial Estate
VSR 4.6	Residents at Ha Hang Village and Casa Brava
VSR 4.7	Workers of Tai Po Sewage Treatment Works
VSR 4.8	Visitors of Tai Po Waterfront Pier

Landscape Impact

	VSR		
	Construction	Operation	
Unmitigated	Substantial Adverse	Moderate Adverse	
Mitigated	Slight Adverse	Insubstantial (Year 10)	





Shuen Wan Golf Course, Tai Po	SCALE	As Shown	DATE	1
Shuen wan Gon Course, Tai Fo	CHECKED	ELK	DRAWN	
Visual Impacts (Scenario 2)	FIGURE NO.	Figur	e 12.10.2	

LEGEND



Project Site Boundary

Visual Envelope

 VSR1
 Major Visually Sensitive Receiver (VSR) and angle of main views

Photomontage Viewpoints

Visually Sensitive Receivers

,	
VSR 1.1	Students and Staff of The Education University of Hong Kong
VSR 1.2	Residents of low-rises along Lo Fai Road
PVSR 1.3	Residents of Planned low-rises along Lo Fai Road
VSR 1.4	Pedestrians / Cyclists / Vehicular travellers along Ting Kok Road
VSR 2.1	Residents of Fortune Garden
VSR 2.2	Residents of The Beverly Hills
VSR 2.3	Villagers at Sam Mun Tsai
VSR 3.1	Visitors to Ma On Shan Promenade and Ma On Shan Park
VSR 3.2	Residents of high-rises along Ma On Shan Promenade
VSR 3.3	Workers of Hong Kong Science Park
VSR 3.4	Residents of Pak Shek Kok Promenade
VSR 3.5	Pedestrians / Cyclists along Tolo Harbour
VSR 3.6	Residents of low-rises along Yau King Lane
VSR 3.7	Residents of low-rises along Yat Yiu Avenue, Hung Lam Drive and Tai Po Kau
PVSR 3.8	Staff at planned quarters / guests at planned overnight accommodation
VSR 4.1	Visitors of Yuen Chau Tsai Park
VSR 4.2	Residents of high-rises at Kwong Fuk Estate and Wang Fuk Court
VSR 4.3	Residents of high-rises at Fu Shin Estate, Ming Nga Court and Riviera Lodge
VSR 4.4	Visitors of Tai Po Waterfront Park
VSR 4.5	Workers of Tai Po Industrial Estate
VSR 4.6	Residents at Ha Hang Village and Casa Brava
VSR 4.7	Workers of Tai Po Sewage Treatment Works
VSR 4.8	Visitors of Tai Po Waterfront Pier
Landscape	Impact
	VSR

	VSR	
	Construction	Operation
Unmitigated	Substantial Adverse	Moderate Adverse
Mitigated	Slight Adverse	Insubstantial (Year 10)

