



PAUL Y. ITC – CCECC JOINT VENTURE

Contract No. CV/2002/08
Fill Bank at Tseung Kwan O Area 137

Quarterly EM&A Summary Report No. 2
(for January to March 2003)

April 2003

| | |
|-------------|---|
| Checked By |  |
| Approved By |  (Project Director) |

REMARKS:

The information supplied and contained within this report is, to the best of our knowledge, correct at the time of printing.

MEMCL accepts no responsibility for changes made to this report by third parties.

**MAUNSELL ENVIRONMENTAL
MANAGEMENT CONSULTANTS LTD**

Room 1213-1219, Grand Central Plaza, Tower 2
138 Shatin Rural Committee Road, Shatin, NT, Hong Kong
Tel: (852) 2893 1551 Fax: (852) 2891 0305

Email: mem@maunsell.com.hk

Maunsell

CONTENTS

EXECUTIVE SUMMARY

- 1 INTRODUCTION
- 2 ENVIRONMENTAL MONITORING AND AUDIT REQUIREMENTS
 - MONITORING PARAMETERS
 - MONITORING METHODOLOGY AND CALIBRATION DETAILS
 - ENVIRONMENTAL QUALITY PERFORMANCE LIMITS (ACTION/LIMIT LEVELS)
 - ENVIRONMENTAL MITIGATION MEASURES
- 3 MONITORING RESULTS
 - AIR QUALITY
 - NOISE
 - WATER QUALITY
- 4 INSPECTION RESULTS
 - IMPLEMENTATION STATUS OF ENVIRONMENTAL MITIGATION MEASURES
 - STATUS OF ENVIRONMENTAL LICENSING AND PERMITTING
 - ADVICE ON SOLID AND LIQUID WASTE MANAGEMENT STATUS
- 5 NON-COMPLIANCE (EXCEEDANCES) OF THE ENVIRONMENTAL QUALITY PERFORMANCE LIMITS (ACTION AND LIMIT LEVELS)
 - SUMMARY OF EXCEEDANCES
 - REVIEW OF THE REASONS FOR AND THE IMPLICATIONS OF NON-COMPLIANCE
 - SUMMARY OF ACTIONS TAKEN
- 6 ENVIRONMENTAL COMPLAINTS
 - COMPLAINT LOG
- 7 NOTIFICATION OF SUMMONS AND SUCCESSFUL PROSECUTIONS
- 8 COMMENTS, CONCLUSIONS AND RECOMMENDATIONS

LIST OF TABLES, FIGURES, AND APPENDICES

TABLES

| | |
|-----------|--|
| TABLE 1.1 | CONTACT INFORMATION OF KEY PERSONNEL |
| TABLE 1.2 | SUMMARY OF WORKS UNDERTAKEN IN THE REPORTING QUARTER |
| TABLE 3.1 | SUMMARY OF NUMBER OF EXCEEDANCES FOR 1-HR & 24-HR TSP CONCENTRATION |
| TABLE 3.2 | COMPARISON OF BASELINE AND VARIOUS PERIOD OF AVERAGED 1-HR & 24-HR TSP IMPACT MONITORING RESULTS |
| TABLE 3.3 | SUMMARY OF IMPACT MONITORING RESULTS OF NOISE (DAY-TIME) MONITORING |
| TABLE 3.4 | TOTAL NUMBER OF WATER QUALITY EXCEEDANCES AND PERCENTAGE DIFFERENCES OF NUMBER OF WATER QUALITY EXCEEDANCES IN THE QUARTER |
| TABLE 3.5 | SUMMARY OF STATISTICALLY SIGNIFICANT RESULTS OF SS |
| TABLE 4.1 | IMPORTED DUMP TRUCK LOADS IN THE REPORTING QUARTER |
| TABLE 4.2 | ESTIMATED OFFSITE WASTE DISPOSAL IN THE REPORTING QUARTER |

FIGURES

| | |
|------------|---|
| Figure 1.1 | Project Site Location |
| Figure 1.2 | Air Quality Environmental Monitoring Stations |
| Figure 1.3 | Noise Environmental Monitoring Station |
| Figure 1.4 | Water Quality Monitoring Stations |

APPENDICES

| | |
|------------|--|
| Appendix A | Project Organisation Chart |
| Appendix B | Construction Programme |
| Appendix C | Details of Monitoring Requirements |
| Appendix D | Copy of Equipment Calibration Certificates |
| Appendix E | Environmental Quality Performance (Action/Limit Levels) |
| Appendix F | Implementation Status of Environmental Mitigation Measures (EMIS) |
| Appendix G | Graphical Presentation of Air Quality Monitoring Results |
| Appendix H | Graphical Presentation of Noise Monitoring Results |
| Appendix I | Graphical Presentation of Water Quality Monitoring Results |
| Appendix J | Statistical Analysis of the Trend of Suspended Solids in the Quarter |
| Appendix K | Permits and Licence Details |
| Appendix L | Event Action Plan |