

**Contract No. HY 2004/09 Improvements to San Tin Interchange
Water Quality Visual Inspection Report**

Weekly Report No.: 070

	(1)	(2)	(3)
Date of Inspection:	31 st October 2006	2 nd November 2006	4 th November 2006
Time:	15:00	15:00	10:00
Weather Condition:	Sunny	Sunny	Sunny
Works Inspected:	Drainage laying and formwork erection	Drainage laying and formwork erection	Drainage laying and formwork erection
Location:	Division North 1, 2 & South	Division North 1, 2 & South	Division North 1, 2 & South

Are Works in Compliance with:

	Y	N
1. Water Pollution Control Ordinance and the Subsidiary Legislation	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Recommendations and requirements in the Project EIA Report, EM&A Manual and Environmental Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Recommendations and requirements in the Contractor's Drainage Management Plan (DMP)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Contract No. HY/2004/09, Particular Specification Section 26, Environmental Protection, items under Clause 26.04	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Recommendations and requirements in the ProPECC Note PN 1/94 "Construction Site Drainage"	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Any relevant Effluent Discharge License received by the Contractor	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Description of Environmental Non-compliance or Deficiency (if any):

Nil.

Remedial Actions – Mitigation Measures Implemented or Proposed (if any):


Nil.

Remarks:

No specific water quality issues were observed during the inspections conducted on 31st October 2006, 2nd November 2006 and on 4th November 2006.

Prepared by : K. L. Cheung

Title : ET – Environmental Consultant

Signature : 

Date : 6th November 2006

Reviewed and approved by : Susana Bezy

Title : Environmental Team Leader

Signature : 

Date : 6/11/06

Sent to: IEC (ERM), ER (Maunsell), Contractor (Chun Wo)

**Contract No. HY 2004/09 Improvements to San Tin Interchange
Water Quality Visual Inspection Report**

Weekly Report No.: 071

	(1)	(2)	(3)
Date of Inspection:	7 th November 2006	9 th November 2006	11 th November 2006
Time:	14:30	14:30	10:00
Weather Condition:	Sunny	Sunny	Sunny
Works Inspected:	Drainage laying and formwork erection	Drainage laying and formwork erection	Drainage laying and formwork erection
Location:	Division North 1, 2 & South	Division North 1, 2 & South	Division North 1, 2 & South

Are Works in Compliance with:

	Y	N
1. Water Pollution Control Ordinance and the Subsidiary Legislation	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Recommendations and requirements in the Project EIA Report, EM&A Manual and Environmental Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Recommendations and requirements in the Contractor's Drainage Management Plan (DMP)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Contract No. HY/2004/09, Particular Specification Section 26, Environmental Protection, items under Clause 26.04	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Recommendations and requirements in the ProPECC Note PN 1/94 "Construction Site Drainage"	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Any relevant Effluent Discharge License received by the Contractor	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Description of Environmental Non-compliance or Deficiency (if any):

Nil.

Remedial Actions – Mitigation Measures Implemented or Proposed (if any):

Nil.

Remarks:

No specific water quality issues were observed during the inspections conducted on 7th, 9th and 11th November 2006.

Prepared by : Howard Chan Title : ET – Environmental Team

Signature :  Date : 13th November 2006

Reviewed and approved by : Susana Bezy Title : Environmental Team Leader

Signature :  Date : 14/11/2006

Sent to: IEC (ERM), ER (Maunsell), Contractor (Chun Wo)

**Contract No. HY 2004/09 Improvements to San Tin Interchange
Water Quality Visual Inspection Report**

Weekly Report No.: 072

	(1)	(2)	(3)
Date of Inspection:	13 th November 2006	16 th November 2006	18 th November 2006
Time:	14:30	14:30	14:00
Weather Condition:	Cloudy	Cloudy	Cloudy
Works Inspected:	Drainage laying and formwork erection	Drainage laying and formwork erection	Drainage laying and formwork erection
Location:	Division North 1, 2 & South	Division North 1, 2 & South	Division North 1, 2 & South

Are Works in Compliance with:

	Y	N
1. Water Pollution Control Ordinance and the Subsidiary Legislation	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Recommendations and requirements in the Project EIA Report, EM&A Manual and Environmental Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Recommendations and requirements in the Contractor's Drainage Management Plan (DMP)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Contract No. HY/2004/09, Particular Specification Section 26, Environmental Protection, items under Clause 26.04	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Recommendations and requirements in the ProPECC Note PN 1/94 "Construction Site Drainage"	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Any relevant Effluent Discharge License received by the Contractor	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Description of Environmental Non-compliance or Deficiency (if any):

Nil.

Remedial Actions – Mitigation Measures Implemented or Proposed (if any):

Nil.

Remarks:

No specific water quality issues were observed during the inspections conducted on 13th November 2006, 16th November 2006 and 18th November 2006, respectively.

Prepared by : K. L. Cheung

Title : ET – Environmental Consultant

Signature : 

Date : 20th November 2006

Reviewed and approved by : Susana Bezy

Title : Environmental Team Leader

Signature : 

Date : 20/11/06

Sent to: IEC (ERM), ER (Maunsell), Contractor (Chun Wo)

Contract No. HY 2004/09 Improvements to San Tin Interchange Water Quality Visual Inspection Report	Weekly Report No.: 073
---	-------------------------------



	(1)	(2)	(3)
Date of Inspection:	20 th November 2006	23 rd November 2006	25 th November 2006
Time:	15:00	14:30	10:00
Weather Condition:	Cloudy	Cloudy	Cloudy
Works Inspected:	Drainage laying and formwork erection	Drainage laying and formwork erection	Drainage laying and formwork erection
Location:	Division North 1, 2 & South	Division North 1, 2 & South	Division North 1, 2 & South

Are Works in Compliance with:	Y	N
1. Water Pollution Control Ordinance and the Subsidiary Legislation	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Recommendations and requirements in the Project EIA Report, EM&A Manual and Environmental Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Recommendations and requirements in the Contractor's Drainage Management Plan (DMP)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Contract No. HY/2004/09, Particular Specification Section 26, Environmental Protection, items under Clause 26.04	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Recommendations and requirements in the ProPECC Note PN 1/94 "Construction Site Drainage"	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Any relevant Effluent Discharge License received by the Contractor	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Description of Environmental Non-compliance or Deficiency (if any):
Nil.

Remedial Actions – Mitigation Measures Implemented or Proposed (if any):
Nil.

Remarks:
No specific water quality issues were observed during the inspections conducted on 20 th November 2006, 23 rd November 2006 and 25 th November 2006, respectively.

Prepared by : <u>Howard Chan</u> Signature : <u></u>	Title : <u>Environmental Team</u> Date : <u>27th November 2006</u>
Reviewed and approved by : <u>Susana Bezy</u> Signature : <u></u>	Title : <u>Environmental Team Leader</u> Date : <u>27/11/06</u>
Sent to: <u>IEC (ERM), ER (Maunsell), Contractor (Chun Wo)</u>	

**Contract No. HY 2004/09 Improvements to San Tin Interchange
Water Quality Visual Inspection Report**

Weekly Report No.: 074

	(1)	(2)	(3)
Date of Inspection:	28 th November 2006	30 th November 2006	2 nd December 2006
Time:	15:00	14:30	9:30
Weather Condition:	Cloudy	Sunny	Sunny
Works Inspected:	Drainage laying and formwork erection	Drainage laying and formwork erection	Drainage laying and formwork erection
Location:	Division North 1, 2 & South	Division North 1, 2 & South	Division North 1, 2 & South

Are Works in Compliance with:

	Y	N
1. Water Pollution Control Ordinance and the Subsidiary Legislation	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Recommendations and requirements in the Project EIA Report, EM&A Manual and Environmental Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Recommendations and requirements in the Contractor's Drainage Management Plan (DMP)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Contract No. HY/2004/09, Particular Specification Section 26, Environmental Protection, items under Clause 26.04	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Recommendations and requirements in the ProPECC Note PN 1/94 "Construction Site Drainage"	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Any relevant Effluent Discharge License received by the Contractor	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Description of Environmental Non-compliance or Deficiency (if any):

Nil.


Remedial Actions – Mitigation Measures Implemented or Proposed (if any):

Nil.


Remarks:

- During the inspection on 30th November 2006, tarpaulin sheet covering the slope surface at the South Abutment works area in N1 Division was found damaged. The slope surface was observed to have been covered with repaired tarpaulin sheet during the subsequent inspection on 2nd December 2006.
- No specific water quality issues were observed during the inspections conducted on 28th November 2006 and 2nd December 2006, respectively.

Prepared by : K. L. Cheung Title : ET – Environmental Consultant

Signature :  Date : 4th December 2006

Reviewed and approved by : Susana Bezy Title : Environmental Team Leader

Signature :  Date : 5/12/06

Sent to: IEC (ERM), ER (Maunsell), Contractor (Chun Wo)