

**Contract No. HY 2004/09 Improvements to San Tin Interchange  
Water Quality Visual Inspection Report**

**Weekly Report No.: 118**

	(1)	(2)	(3)
<b>Date of Inspection:</b>	3 <sup>rd</sup> October 2007	4 <sup>th</sup> October 2007	5 <sup>th</sup> October 2007
<b>Time:</b>	14:30	10:00	09:30
<b>Weather Condition:</b>	Cloudy	Fine	Fine
<b>Works Inspected:</b>	Drainage laying and trench works	Drainage laying and trench works	Drainage laying and trench works
<b>Location:</b>	Division North 1, 2 & South	Division North 1, 2 & South	Division North 1, 2 & South

<b>Are Works in Compliance with:</b>	<b>Y</b>	<b>N</b>
1. Water Pollution Control Ordinance and the Subsidiary Legislation	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Recommendations and requirements in the Project EIA Report, EM&A Manual and Environmental Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Recommendations and requirements in the Contractor's Drainage Management Plan (DMP)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Contract No. HY/2004/09, Particular Specification Section 26, Environmental Protection, items under Clause 26.04	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Recommendations and requirements in the ProPECC Note PN 1/94 "Construction Site Drainage"	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Any relevant Effluent Discharge License received by the Contractor	<input checked="" type="checkbox"/>	<input type="checkbox"/>

**Description of Environmental Non-compliance or Deficiency (if any):**  
Nil.

**Remedial Actions – Mitigation Measures Implemented or Proposed (if any):**  
Nil.

**Remarks:**

- Litters were observed to have been accumulated in the U-channel adjacent to M3 (South Division) and near Slip Road E during the inspection conducted on 3<sup>rd</sup> and 4<sup>th</sup> October 2007. The Contractor was reminded to clear the litters and silts in U-channel as regular maintenance of the drainage system.
- Litters and silt accumulated in the U-channel were seen to have been cleared during the inspection conducted on 5<sup>th</sup> October 2007.

Prepared by : Chau Tsz Wing Title : ET – Environmental Technician

Signature :  Date : 5<sup>th</sup> October 2007

Reviewed and approved by : Susana Bezy Title : Environmental Team Leader

Signature :  Date : 5<sup>th</sup> October 2007

Sent to: IEC (ERM), ER (Maunsell), Contractor (Chun Wo)

**Contract No. HY 2004/09 Improvements to San Tin Interchange  
Water Quality Visual Inspection Report**

**Weekly Report No.: 119**

	(1)	(2)	(3)
<b>Date of Inspection:</b>	9 <sup>th</sup> October 2007	10 <sup>th</sup> October 2007	11 <sup>th</sup> October 2007
<b>Time:</b>	14:30	14:30	15:45
<b>Weather Condition:</b>	Fine	Fine	Cloudy
<b>Works Inspected:</b>	Drainage laying and trench works	Drainage laying and trench works	Drainage laying and trench works
<b>Location:</b>	Division North 1, 2 & South	Division North 1, 2 & South	Division North 1, 2 & South

<b>Are Works in Compliance with:</b>	<b>Y</b>	<b>N</b>
1. Water Pollution Control Ordinance and the Subsidiary Legislation	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Recommendations and requirements in the Project EIA Report, EM&A Manual and Environmental Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Recommendations and requirements in the Contractor's Drainage Management Plan (DMP)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Contract No. HY/2004/09, Particular Specification Section 26, Environmental Protection, items under Clause 26.04	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Recommendations and requirements in the ProPECC Note PN 1/94 "Construction Site Drainage"	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Any relevant Effluent Discharge License received by the Contractor	<input checked="" type="checkbox"/>	<input type="checkbox"/>

**Description of Environmental Non-compliance or Deficiency (if any):**

Nil.

**Remedial Actions – Mitigation Measures Implemented or Proposed (if any):**

Nil.

**Remarks:**

No specific water quality issue was observed during the inspections conducted on 9<sup>th</sup>, 10<sup>th</sup> and 11<sup>th</sup> October 2007, respectively.

Prepared by : Chau Tsz Wing Title : ET – Environmental Technician

Signature :  Date : 15<sup>th</sup> October 2007

Reviewed and approved by : Susana Bezy Title : Environmental Team Leader

Signature :  Date : 15<sup>th</sup> October 2007

Sent to: IEC (ERM), ER (Maunsell), Contractor (Chun Wo)

**Contract No. HY 2004/09 Improvements to San Tin Interchange  
Water Quality Visual Inspection Report**

Weekly Report No.: 120

	(1)	(2)	(3)
<b>Date of Inspection:</b>	15 <sup>th</sup> October 2007	16 <sup>th</sup> October 2007	17 <sup>th</sup> October 2007
<b>Time:</b>	14:00	13:45	15:45
<b>Weather Condition:</b>	Fine	Fine	Fine
<b>Works Inspected:</b>	Drainage laying and trench works	Drainage laying and trench works	Drainage laying and trench works
<b>Location:</b>	Division North 1, 2 & South	Division North 1, 2 & South	Division North 1, 2 & South

**Are Works in Compliance with:**

	Y	N
1. Water Pollution Control Ordinance and the Subsidiary Legislation	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Recommendations and requirements in the Project EIA Report, EM&A Manual and Environmental Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Recommendations and requirements in the Contractor's Drainage Management Plan (DMP)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Contract No. HY/2004/09, Particular Specification Section 26, Environmental Protection, items under Clause 26.04	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Recommendations and requirements in the ProPECC Note PN 1/94 "Construction Site Drainage"	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Any relevant Effluent Discharge License received by the Contractor	<input checked="" type="checkbox"/>	<input type="checkbox"/>

**Description of Environmental Non-compliance or Deficiency (if any):**

Nil.

**Remedial Actions – Mitigation Measures Implemented or Proposed (if any):**

Nil.

**Remarks:**

No specific water quality issue was observed during the inspections conducted on 15<sup>th</sup>, 16<sup>th</sup> and 17<sup>th</sup> October 2007, respectively.

Prepared by : Chau Tsz Wing


Title : ET – Environmental Technician

Signature : 

Date : 22<sup>nd</sup> October 2007

Reviewed and approved by : Susana Bezy

Title : Environmental Team Leader

Signature : 

Date : 22<sup>nd</sup> October 2007

Sent to: IEC (ERM), ER (Maunsell), Contractor (Chun Wo)

**Contract No. HY 2004/09 Improvements to San Tin Interchange  
Water Quality Visual Inspection Report**

Weekly Report No.: 121

	(1)	(2)	(3)
<b>Date of Inspection:</b>	22 <sup>nd</sup> October 2007	24 <sup>th</sup> October 2007	26 <sup>th</sup> October 2007
<b>Time:</b>	14:00	14:30	15:05
<b>Weather Condition:</b>	Fine	Fine	Fine
<b>Works Inspected:</b>	Drainage laying and trench works	Drainage laying and trench works	Drainage laying and trench works
<b>Location:</b>	Division North 1, 2 & South	Division North 1, 2 & South	Division North 1, 2 & South

**Are Works in Compliance with:**

	Y	N
1. Water Pollution Control Ordinance and the Subsidiary Legislation	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Recommendations and requirements in the Project EIA Report, EM&A Manual and Environmental Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Recommendations and requirements in the Contractor's Drainage Management Plan (DMP)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Contract No. HY/2004/09, Particular Specification Section 26, Environmental Protection, items under Clause 26.04	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Recommendations and requirements in the ProPECC Note PN 1/94 "Construction Site Drainage"	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Any relevant Effluent Discharge License received by the Contractor	<input checked="" type="checkbox"/>	<input type="checkbox"/>

**Description of Environmental Non-compliance or Deficiency (if any):**

Nil.


**Remedial Actions – Mitigation Measures Implemented or Proposed (if any):**

Nil.

**Remarks:**

- No specific water quality issue was observed during the inspections conducted on 22<sup>nd</sup> and 26<sup>th</sup> October 2007, respectively.
- Rubbish was seen to have been discarded in the U-channel near Pier B8 on 24<sup>th</sup> October 2007. The rubbish in the U-channel had been removed as seen on 26<sup>th</sup> October 2007.

Prepared by : Chau Tsz Wing Title : ET – Environmental Technician

Signature :  Date : 29<sup>th</sup> October 2007

Reviewed and approved by : Susana Bezy Title : Environmental Team Leader

Signature :  Date : 29<sup>th</sup> October 2007

Sent to: IEC (ERM), ER (Maunsell), Contractor (Chun Wo)

**Contract No. HY 2004/09 Improvements to San Tin Interchange  
Water Quality Visual Inspection Report**

Weekly Report No.: 122

	(1)	(2)	(3)
<b>Date of Inspection:</b>	30 <sup>th</sup> October 2007	31 <sup>st</sup> October 2007	1 <sup>st</sup> November 2007
<b>Time:</b>	14:00	14:30	09:45
<b>Weather Condition:</b>	Fine	Cloudy	Mist
<b>Works Inspected:</b>	Drainage laying and trench works	Drainage laying and trench works	Drainage laying and trench works
<b>Location:</b>	Division North 1, 2 & South	Division North 1, 2 & South	Division North 1, 2 & South

**Are Works in Compliance with:**

	Y	N
1. Water Pollution Control Ordinance and the Subsidiary Legislation	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Recommendations and requirements in the Project EIA Report, EM&A Manual and Environmental Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Recommendations and requirements in the Contractor's Drainage Management Plan (DMP)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Contract No. HY/2004/09, Particular Specification Section 26, Environmental Protection, items under Clause 26.04	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Recommendations and requirements in the ProPECC Note PN 1/94 "Construction Site Drainage"	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Any relevant Effluent Discharge License received by the Contractor	<input checked="" type="checkbox"/>	<input type="checkbox"/>

**Description of Environmental Non-compliance or Deficiency (if any):**

Nil.

**Remedial Actions – Mitigation Measures Implemented or Proposed (if any):**

Nil.

**Remarks:**

- No specific water quality issue was observed during the inspection conducted on 30<sup>th</sup> October 2007, respectively.
- Rubbish and silts were seen to have accumulated in the U-channel in M2 works area and near the West Abutment during the inspection conducted on 31<sup>st</sup> October 2007 and 1<sup>st</sup> November 2007. The Contractor is reminded to keep the U-channel free of debris as proper maintenance of the drainage system.

Prepared by : Chau Tsz Wing

Title : ET – Environmental Technician

Signature : 

Date : 1<sup>st</sup> November 2007

Reviewed and approved by : Susana Bezy

Title : Environmental Team Leader

Signature : 

Date : 1<sup>st</sup> November 2007

Sent to: IEC (ERM), ER (Maunsell), Contractor (Chun Wo)