

**Contract No. HY 2004/09 Improvements to San Tin Interchange
Water Quality Visual Inspection Report**

Weekly Report No.: 127

| | |
|---------------------|---|
| Date of Inspection: | 5 th December 2007 |
| Time: | 14:30 |
| Weather Condition: | Fine |
| Works Inspected: | Trees Transplantation and landscaping works |
| Location: | Division North 1, 2 & South |

| Are Works in Compliance with: | Y | N |
|---|-------------------------------------|--------------------------|
| 1. Water Pollution Control Ordinance and the Subsidiary Legislation | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2. Recommendations and requirements in the Project EIA Report, EM&A Manual and Environmental Permit | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. Recommendations and requirements in the Contractor's Drainage Management Plan (DMP) | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 4. Contract No. HY/2004/09, Particular Specification Section 26, Environmental Protection, items under Clause 26.04 | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 5. Recommendations and requirements in the ProPECC Note PN 1/94 "Construction Site Drainage" | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 6. Any relevant Effluent Discharge License received by the Contractor | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Description of Environmental Non-compliance or Deficiency (if any):
Nil.

Remedial Actions – Mitigation Measures Implemented or Proposed (if any):
Nil.

Remarks:
• No specific water quality issue was observed during the inspection conducted on 5th December 2007.

Prepared by : Chau Tsz Wing Title : ET – Environmental Technician

Signature :  Date : 7th December 2007

Reviewed and approved by : Susana Bezy Title : Environmental Team Leader

Signature :  Date : 7th December 2007

Sent to: IEC (ERM), ER (Maunsell), Contractor (Chun Wo)

**Contract No. HY 2004/09 Improvements to San Tin Interchange
Water Quality Visual Inspection Report**

Weekly Report No.: 128



| | |
|---------------------|---|
| Date of Inspection: | 11 th December 2007 |
| Time: | 14:30 |
| Weather Condition: | Fine |
| Works Inspected: | Trees Transplantation and landscaping works |
| Location: | Division North 1, 2 & South |

| Are Works in Compliance with: | Y | N |
|---|-------------------------------------|--------------------------|
| 1. Water Pollution Control Ordinance and the Subsidiary Legislation | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2. Recommendations and requirements in the Project EIA Report, EM&A Manual and Environmental Permit | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. Recommendations and requirements in the Contractor's Drainage Management Plan (DMP) | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 4. Contract No. HY/2004/09, Particular Specification Section 26, Environmental Protection, items under Clause 26.04 | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 5. Recommendations and requirements in the ProPECC Note PN 1/94 "Construction Site Drainage" | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 6. Any relevant Effluent Discharge License received by the Contractor | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

| |
|--|
| Description of Environmental Non-compliance or Deficiency (if any): |
| Nil. |

| |
|---|
| Remedial Actions – Mitigation Measures Implemented or Proposed (if any): |
| Nil. |

| |
|---|
| Remarks: |
| <ul style="list-style-type: none">Debris and sediment were found at the existing outfall near M6. The contractor was reminded to remove the debris as proper maintenance. |

Prepared by : Chau Tsz Wing Title : ET – Environmental Technician
Signature :  Date : 12th December 2007
Reviewed and approved by : Susana Bezy Title : Environmental Team Leader
Signature :  Date : 12th December 2007

Sent to: IEC (ERM), ER (Munsell), Contractor (Chun Wo)

**Contract No. HY 2004/09 Improvements to San Tin Interchange
Water Quality Visual Inspection Report**

Weekly Report No.: 129

| | |
|----------------------------|---|
| Date of Inspection: | 19 th December 2007 |
| Time: | 14:30 |
| Weather Condition: | Fine |
| Works Inspected: | Trees Transplantation and landscaping works |
| Location: | Division North 1, 2 & South |

| Are Works in Compliance with: | Y | N |
|---|-------------------------------------|--------------------------|
| 1. Water Pollution Control Ordinance and the Subsidiary Legislation | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2. Recommendations and requirements in the Project EIA Report, EM&A Manual and Environmental Permit | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. Recommendations and requirements in the Contractor's Drainage Management Plan (DMP) | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 4. Contract No. HY/2004/09, Particular Specification Section 26, Environmental Protection, items under Clause 26.04 | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 5. Recommendations and requirements in the ProPECC Note PN 1/94 "Construction Site Drainage" | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 6. Any relevant Effluent Discharge License received by the Contractor | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Description of Environmental Non-compliance or Deficiency (if any):
Nil.

Remedial Actions – Mitigation Measures Implemented or Proposed (if any):
Nil.

Remarks:

- Soil sediment and leaves were found at the existing outfall near M6. The contractor was reminded to clean regularly to maintain free water flow.

Prepared by : Chau Tsz Wing Title : ET – Environmental Technician

Signature :  Date : 21st December 2007

Reviewed and approved by : Susana Bezy Title : Environmental Team Leader

Signature :  Date : 21st December 2007

Sent to: IEC (ERM), ER (Maunsell), Contractor (Chun Wo)

**Contract No. HY 2004/09 Improvements to San Tin Interchange
Water Quality Visual Inspection Report**

Weekly Report No.: 130

| | |
|---------------------|---|
| Date of Inspection: | 28 th December 2007 |
| Time: | 14:30 |
| Weather Condition: | Sunny |
| Works Inspected: | Trees Transplantation and landscaping works |
| Location: | Division North 1, 2 & South |

| Are Works in Compliance with: | Y | N |
|---|-------------------------------------|--------------------------|
| 1. Water Pollution Control Ordinance and the Subsidiary Legislation | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2. Recommendations and requirements in the Project EIA Report, EM&A Manual and Environmental Permit | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. Recommendations and requirements in the Contractor's Drainage Management Plan (DMP) | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 4. Contract No. HY/2004/09, Particular Specification Section 26, Environmental Protection, items under Clause 26.04 | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 5. Recommendations and requirements in the ProPECC Note PN 1/94 "Construction Site Drainage" | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 6. Any relevant Effluent Discharge License received by the Contractor | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

| |
|--|
| Description of Environmental Non-compliance or Deficiency (if any): |
| Nil. |

| |
|---|
| Remedial Actions – Mitigation Measures Implemented or Proposed (if any): |
| Nil. |

| |
|---|
| Remarks: |
| • No specific water quality issues observed on 28 th December 2007 |

Prepared by : Chau Tsz Wing Title : ET – Environmental Technician

Signature :  Date : 3rd January 2008

Reviewed and approved by : Susana Bezy Title : Environmental Team Leader

Signature :  Date : 3rd January 2008

Sent to: IEC (ERM), ER (Maunsell), Contractor (Chun Wo)