

**Contract No. HY 2004/09 Improvements to San Tin Interchange
Water Quality Visual Inspection Report**

Weekly Report No.: 131

Date of Inspection:	9 th January 2008
Time:	14:30
Weather Condition:	Cloudy
Works Inspected:	Trench works, trees transplantation and landscaping works
Location:	Division North 1, 2 & South

Are Works in Compliance with:	Y	N
1. Water Pollution Control Ordinance and the Subsidiary Legislation	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Recommendations and requirements in the Project EIA Report, EM&A Manual and Environmental Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Recommendations and requirements in the Contractor's Drainage Management Plan (DMP)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Contract No. HY/2004/09, Particular Specification Section 26, Environmental Protection, items under Clause 26.04	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Recommendations and requirements in the ProPECC Note PN 1/94 "Construction Site Drainage"	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Any relevant Effluent Discharge License received by the Contractor	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Description of Environmental Non-compliance or Deficiency (if any):
Nil.


Remedial Actions – Mitigation Measures Implemented or Proposed (if any):
Nil.

Remarks:

- Rubbish and silts have been accumulated in the U-channel in the B12 works areas near San Tin Highway. The contractor was reminded to remove the rubbish regularly and keep the drainage system free of deposited debris.

Prepared by : Chau Tsz Wing


Title : ET – Environmental Technician

Signature : 

Date : 10th January 2008

Reviewed and approved by : Susana Bezy

Title : Environmental Team Leader

Signature : 

Date : 10th January 2008

Sent to: IEC (ERM), ER (Maunsell), Contractor (Chun Wo)

**Contract No. HY 2004/09 Improvements to San Tin Interchange
Water Quality Visual Inspection Report**

Weekly Report No.: 132

Date of Inspection:	16 th January 2008
Time:	15:00
Weather Condition:	Cloudy
Works Inspected:	Trench works, trees transplantation and landscaping works
Location:	Division North 1, 2 & South

Are Works in Compliance with:	Y	N
7. Water Pollution Control Ordinance and the Subsidiary Legislation	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Recommendations and requirements in the Project EIA Report, EM&A Manual and Environmental Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Recommendations and requirements in the Contractor's Drainage Management Plan (DMP)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
10. Contract No. HY/2004/09, Particular Specification Section 26, Environmental Protection, items under Clause 26.04	<input checked="" type="checkbox"/>	<input type="checkbox"/>
11. Recommendations and requirements in the ProPECC Note PN 1/94 "Construction Site Drainage"	<input checked="" type="checkbox"/>	<input type="checkbox"/>
12. Any relevant Effluent Discharge License received by the Contractor	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Description of Environmental Non-compliance or Deficiency (if any):
Nil.

Remedial Actions – Mitigation Measures Implemented or Proposed (if any):
Nil.

Remarks:
<ul style="list-style-type: none">No specific water quality issues observed on 16th January 2008.

Prepared by : Chau Tsz Wing Title : ET – Environmental Technician

Signature :  Date : 21st January 2008

Reviewed and approved by : Susana Bezy Title : Environmental Team Leader

Signature :  Date : 21st January 2008

Sent to: IEC (ERM), ER (Maunsell), Contractor (Chun Wo)

**Contract No. HY 2004/09 Improvements to San Tin Interchange
Water Quality Visual Inspection Report**

Weekly Report No.: 133

Date of Inspection:	23 rd January 2008
Time:	14:30
Weather Condition:	Fine
Works Inspected:	Trench works, trees transplantation and landscaping works
Location:	Division North 1, 2 & South

Are Works in Compliance with:	Y	N
13. Water Pollution Control Ordinance and the Subsidiary Legislation	<input checked="" type="checkbox"/>	<input type="checkbox"/>
14. Recommendations and requirements in the Project EIA Report, EM&A Manual and Environmental Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>
15. Recommendations and requirements in the Contractor's Drainage Management Plan (DMP)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
16. Contract No. HY/2004/09, Particular Specification Section 26, Environmental Protection, items under Clause 26.04	<input checked="" type="checkbox"/>	<input type="checkbox"/>
17. Recommendations and requirements in the ProPECC Note PN 1/94 "Construction Site Drainage"	<input checked="" type="checkbox"/>	<input type="checkbox"/>
18. Any relevant Effluent Discharge License received by the Contractor	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Description of Environmental Non-compliance or Deficiency (if any):
Nil.


Remedial Actions – Mitigation Measures Implemented or Proposed (if any):
Nil.

Remarks:
Rubbish and silts were accumulated in the U-channel near the pedestrian subway in the South Division. The Contractor was reminded to collect the rubbish regularly and keep the site drainage system free of deposited debris.

Prepared by : Chau Tsz Wing Title : ET – Environmental Technician

Signature :  Date : 25th January 2008

Reviewed and approved by : Susana Bezy Title : Environmental Team Leader

Signature :  Date : 25th January 2008

Sent to: IEC (ERM), ER (Maunsell), Contractor (Chun Wo)

**Contract No. HY 2004/09 Improvements to San Tin Interchange
Water Quality Visual Inspection Report**

Weekly Report No.: 134

Date of Inspection:	28 th January 2008
Time:	13:00
Weather Condition:	Cloudy
Works Inspected:	Trench works, trees transplantation and landscaping works
Location:	Division North 1, 2 & South

Are Works in Compliance with:	Y	N
19. Water Pollution Control Ordinance and the Subsidiary Legislation	<input checked="" type="checkbox"/>	<input type="checkbox"/>
20. Recommendations and requirements in the Project EIA Report, EM&A Manual and Environmental Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>
21. Recommendations and requirements in the Contractor's Drainage Management Plan (DMP)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Contract No. HY/2004/09, Particular Specification Section 26, Environmental Protection, items under Clause 26.04	<input checked="" type="checkbox"/>	<input type="checkbox"/>
23. Recommendations and requirements in the ProPECC Note PN 1/94 "Construction Site Drainage"	<input checked="" type="checkbox"/>	<input type="checkbox"/>
24. Any relevant Effluent Discharge License received by the Contractor	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Description of Environmental Non-compliance or Deficiency (if any):
Nil.


Remedial Actions – Mitigation Measures Implemented or Proposed (if any):
Nil.

Remarks:
• No specific water quality issues observed on 28th January 2008.

Prepared by : Chau Tsz Wing Title : ET – Environmental Technician

Signature :  Date : 31st January 2008

Reviewed and approved by : Susana Bezy Title : Environmental Team Leader

Signature :  Date : 31st January 2008

Sent to: IEC (ERM), ER (Maunsell), Contractor (Chun Wo)