

**Contract No. HY 2004/09 Improvements to San Tin Interchange
Water Quality Visual Inspection Report**

Weekly Report No.: 143

Date of Inspection: 10th April 2008

Time: 09:30

Weather Condition: Fine

Works Inspected: Trench works, trees transplanted and landscaping works

Location: Division North 1, 2 & South

Are Works in Compliance with:

| | Y | N |
|---|-------------------------------------|--------------------------|
| 1. Water Pollution Control Ordinance and the Subsidiary Legislation | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2. Recommendations and requirements in the Project EIA Report, EM&A Manual and Environmental Permit | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. Recommendations and requirements in the Contractor's Drainage Management Plan (DMP) | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 4. Contract No. HY/2004/09, Particular Specification Section 26, Environmental Protection, items under Clause 26.04 | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 5. Recommendations and requirements in the ProPECC Note PN 1/94 "Construction Site Drainage" | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 6. Any relevant Effluent Discharge License received by the Contractor | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Description of Environmental Non-compliance or Deficiency (if any):

Nil.

Remedial Actions – Mitigation Measures Implemented or Proposed (if any):

Nil.

Remarks:

- The stagnant water was found near the U-channel at N1 division (near the site office). The contractor was reminded to clear the stagnant water immediately to prevent the mosquito breeding.

Prepared by : Chau Tsz Wing

Title : ET – Environmental Technician

Signature : 

Date : 11th April 2008

Reviewed and approved by : Susana Bezy

Title : Environmental Team Leader

Signature : 

Date : 11th April 2008

Sent to: IEC (ERM), ER (Maunsell), Contractor (Chun Wo)

**Contract No. HY 2004/09 Improvements to San Tin Interchange
Water Quality Visual Inspection Report**

Weekly Report No.: 144

Date of Inspection: 15th April 2008

Time: 14:30

Weather Condition: Cloudy

Works Inspected: Trench works, trees transplanted and landscaping works

Location: Division North 1, 2 & South

Are Works in Compliance with:

| | Y | N |
|---|-------------------------------------|--------------------------|
| 1. Water Pollution Control Ordinance and the Subsidiary Legislation | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2. Recommendations and requirements in the Project EIA Report, EM&A Manual and Environmental Permit | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. Recommendations and requirements in the Contractor's Drainage Management Plan (DMP) | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 4. Contract No. HY/2004/09, Particular Specification Section 26, Environmental Protection, items under Clause 26.04 | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 5. Recommendations and requirements in the ProPECC Note PN 1/94 "Construction Site Drainage" | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 6. Any relevant Effluent Discharge License received by the Contractor | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Description of Environmental Non-compliance or Deficiency (if any):

Nil.

Remedial Actions – Mitigation Measures Implemented or Proposed (if any):

Nil.

Remarks:

- Stagnant water was observed to be accumulated at work areas near the hoarding of site office at N1 division. The contractor was reminded to clear the stagnant water immediately to prevent the mosquito breeding.

Prepared by : Chau Tsz Wing

Title : ET – Environmental Technician

Signature : 

Date : 16th April 2008

Reviewed and approved by : Susana Bezy

Title : Environmental Team Leader

Signature : 

Date : 16th April 2008

Sent to: IEC (ERM), ER (Maunsell), Contractor (Chun Wo)

**Contract No. HY 2004/09 Improvements to San Tin Interchange
Water Quality Visual Inspection Report**

Weekly Report No.: 145

Date of Inspection: 23rd April 2008

Time: 14:30

Weather Condition: Overcast

Works Inspected: Trench works and landscaping works

Location: Division North 1, 2 & South

Are Works in Compliance with:

| | Y | N |
|---|-------------------------------------|--------------------------|
| 1. Water Pollution Control Ordinance and the Subsidiary Legislation | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2. Recommendations and requirements in the Project EIA Report, EM&A Manual and Environmental Permit | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. Recommendations and requirements in the Contractor's Drainage Management Plan (DMP) | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 4. Contract No. HY/2004/09, Particular Specification Section 26, Environmental Protection, Items under Clause 26.04 | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 5. Recommendations and requirements in the ProPECC Note PN 1/94 "Construction Site Drainage" | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 6. Any relevant Effluent Discharge License received by the Contractor | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Description of Environmental Non-compliance or Deficiency (If any):

Nil.

Remedial Actions – Mitigation Measures Implemented or Proposed (If any):

Nil.

Remarks:

- Silts and rubbishes were accumulated in the U-channel in the San Tin Highway works area. The contractor was reminded to collect rubbish regularly and keep drainage system free of debris
- Stagnant water pool was seen in Slip Road A work areas, Castle Peak Road works area and at the sand trap in San Tin Highway works area. The contractor was reminded to clear the water pools promptly after rainstorm events to prevent mosquito breeding.

Prepared by : Chau Tsz Wing

Title : ET – Environmental Technician

Signature : 

Date : 24th April 2008

Reviewed and approved by : Susana Bezy

Title : Environmental Team Leader

Signature : 

Date : 24th April 2008

Sent to: IEC (ERM), ER (Maunsell), Contractor (Chun Wo)

**Contract No. HY 2004/09 Improvements to San Tin Interchange
Water Quality Visual Inspection Report**

Weekly Report No.: 146

Date of Inspection: 28th April 2008

Time: 14:30

Weather Condition: Cloudy

Works Inspected: Trench works and landscaping works

Location: Division North 1, 2 & South

Are Works in Compliance with:

| | Y | N |
|---|-------------------------------------|--------------------------|
| 1. Water Pollution Control Ordinance and the Subsidiary Legislation | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2. Recommendations and requirements in the Project EIA Report, EM&A Manual and Environmental Permit | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. Recommendations and requirements in the Contractor's Drainage Management Plan (DMP) | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 4. Contract No. HY/2004/09, Particular Specification Section 26, Environmental Protection, Items under Clause 26.04 | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 5. Recommendations and requirements in the ProPECC Note PN 1/94 "Construction Site Drainage" | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 6. Any relevant Effluent Discharge License received by the Contractor | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Description of Environmental Non-compliance or Deficiency (If any):

Nil.

Remedial Actions – Mitigation Measures Implemented or Proposed (If any):

Nil.

Remarks:

- No specific water quality issues observed on 28th April 2008.

Prepared by : Chau Tsz Wing

Title : ET – Environmental Technician

Signature : 

Date : 30th April 2008

Reviewed and approved by : Susana Bezy

Title : Environmental Team Leader

Signature : 

Date : 30th April 2008

Sent to: IEC (ERM), ER (Maunsell), Contractor (Chun Wo)