

Gammon Skanska Limited

Contract No. CV/2002/04

Penny's Bay Reclamation Stage 2

Monthly EM&A Report for February 2004

March 2004

(Revision 1)

Approved By



(Environmental Team Leader)

REMARKS:

The information contained in this report is, to the best of our knowledge, correct at the time of printing. The interpretation and recommendations in the report are based on our experience, using reasonable professional skill and judgment, and based upon the information that was available to us. These interpretations and recommendations are not necessarily relevant to any aspect outside the restricted requirements of our brief. This report has been prepared for the sole and specific use of our client and MEMCL accepts no responsibility for its use by others.

This report is copyright and may not be reproduced in whole or in part without prior written permission.

**MAUNSELL ENVIRONMENTAL
MANAGEMENT CONSULTANTS LTD**
Room 1213-1219, Grand Central Plaza, Tower 2
138 Shatin Rural Committee Road, Shatin, NT, Hong Kong
Tel: (852) 2893 1551 Fax: (852) 2891 0305
Email: mem@maunsell.com.hk

Maunsell

TABLE OF CONTENTS

EXECUTIVE SUMMARY

1. INTRODUCTION

Background
Project Organisation
Construction Works undertaken during the Reporting Month
Compliance with EP conditions
Summary of EM&A Requirements

2. AIR QUALITY MONITORING

Monitoring Requirements
Monitoring Equipment
Monitoring Parameters, Frequency and Duration
Monitoring Locations
Monitoring Methodology
Results and Observations

3. NOISE MONITORING

Monitoring Requirements
Monitoring Equipment
Monitoring Parameters, Frequency and Duration
Monitoring Locations
Monitoring Methodology
Results and Observations

4. WATER QUALITY MONITORING

Discrete Marine Water Quality Monitoring
Monitoring of TBT/PAHs/PCBs
Continuous Marine Water Quality Monitoring

5. TERRESTRIAL ECOLOGY

Monitoring Requirements
Monitoring Equipment
Monitoring Parameters, Frequency and Duration
Monitoring Locations
Monitoring Methodology
Results and Observations

6. MARINE MAMMAL MONITORING

Monitoring Requirements
Monitoring Equipment
Monitoring Parameter, Frequencies and Duration
Monitoring Location
Monitoring Procedures
Results and Observations

7. SUBTIDAL MONITORING
 - Monitoring Requirement
 - Monitoring Parameters, Frequency, Schedule
 - Monitoring Locations
 - Monitoring Procedures
 - Results and Observations
8. ENVIRONMENTAL AUDIT
 - Site Environmental Audit
 - Review of Environmental Monitoring Procedures
 - Status of Environmental Licensing and Permitting
 - Implementation Status of Environmental Mitigation Measures
 - Implementation Status of Event/Action Plans
 - Implementation Status of Environmental Complaint Handling Procedures
9. FUTURE KEY ISSUES
 - Key Issues for the Coming Month
 - Monitoring Schedules for the Next Month
 - Construction Program for the Next 3 Months
10. CONCLUSIONS AND RECOMMENDATIONS
 - Conclusions
 - Recommendations

List of Tables

Table 1.1	Estimated Amounts of Waste Generated in February 2004
Table 1.2	Environmental Permit Submission
Table 2.1	TSP Monitoring Equipment
Table 2.2	Air Quality Monitoring Parameters and Frequency
Table 2.3	Location of Air Quality Monitoring Stations
Table 3.1	Noise Monitoring Equipment
Table 3.2	Noise Monitoring Parameters, Period and Frequency
Table 3.3	Noise Monitoring Locations
Table 4.1	Discrete Marine Water Quality Monitoring Equipment
Table 4.2	Discrete Marine Water Quality Monitoring Parameters, Period and Frequency
Table 4.3	Discrete Marine Water Quality Monitoring Locations
Table 4.4	Water Quality Exceedance Summary
Table 4.5	TBT Monitoring Equipment
Table 4.6	TBT Monitoring Parameters, Period and Frequency
Table 4.7	TBT Monitoring Locations
Table 4.8	Standard Methods for Laboratory Analysis of Water Samples
Table 4.9	Continuous Marine Water Quality Monitoring Equipment
Table 4.10	Continuous Marine Water Quality Monitoring Parameters, Period and Frequency
Table 4.11	Continuous Marine Water Quality Monitoring Locations
Table 5.1a	Time Allocation (%) for White-bellied Sea Eagle (female and male) activity at Pa Tau Kwu on 7 February
Table 5.1b	Time Allocation (%) for White-bellied Sea Eagle (female and male) activity at Pa Tau Kwu on 20 February
Table 6.1	Marine Mammal Monitoring Equipment
Table 7.1	Subtidal monitoring results from Sze Pak Wan
Table 7.2	Subtidal monitoring results from Kau Yi Chau
Table 8.1	Summary of Environmental Licensing and Permit Status

List of Figures

Figure 1.1	Project Organisation
Figure 1.2	Layout of Work Site
Figure 2.1	Locations of Air Quality Monitoring Stations
Figure 3.1	Locations of Noise Monitoring Stations
Figure 4.1	Locations of Discrete Water Quality Monitoring Stations
Figure 4.2	Locations of TBT/PAHs/PCBs Monitoring Stations
Figure 4.3	Locations of Continuous Water Quality Monitoring Stations
Figure 5.1	Locations of White-bellied Sea Eagles Monitoring
Figure 5.2	Photographic Records of the White-bellied Sea Eagle
Figure 6.1	Locations of Marine Mammal Monitoring
Figure 7.1	Locations of Subtidal Monitoring
Figure 7.2	Photographic Records of Corals at Sze Pak Wan
Figure 7.3	Photographic Records of Corals at Kau Yi Chau

List of Appendices

Appendix A	Amount of Marine Sediment Dredged, Dumped and Filled
Appendix B	Action and Limit Levels
Appendix C	Environmental Monitoring Schedules
Appendix D	Air Quality Monitoring Results
Appendix E	Noise Monitoring Results
Appendix F1	Discrete Water Quality Monitoring Results
Appendix F2	Graphical Presentation of Discrete Water Quality Monitoring Results
Appendix G1	Continuous Water Quality Monitoring Results
Appendix G2	Graphical Presentation of Continuous Water Quality Monitoring Results
Appendix H	TBT, PAHs and PCBs Monitoring Results
Appendix I	The QA/QC Procedures and Results
Appendix J	Calibration Details
Appendix K	Site Inspection Records
Appendix L	Summary of Environmental Mitigation Implementation Schedule
Appendix M	Event and Action Plans
Appendix N	Complaint Flow Diagram and Complaint Log
Appendix O	Construction Programme
Appendix P	Contacts of Key Environmental Personnel
Appendix Q	Subtidal Survey Results