



Gammon Skanska Limited

Maunsell

Contract No. CV/2002/04  
Penny's Bay Reclamation Stage 2  
Monthly EM&A Report for April 2004  
[May 2004]

  
Reviewed by (PM):

  
Checked by:

  
Approved by:  
(Environmental Team Leader)

Report Version: Revision 1 Date of Submission: 12 May 2004

The information contained in this report is, to the best of our knowledge, correct at the time of printing. The interpretation and recommendations in the report are based on our experience, using reasonable professional skill and judgment, and based upon the information that was available to us. These interpretations and recommendations are not necessarily relevant to any aspect outside the restricted requirements of our brief. This report has been prepared for the sole and specific use of our client and MEMCL, accepts no responsibility for its use by others.

This report is copyright and may not be reproduced in whole or in part without prior written permission.

**MAUNSELL ENVIRONMENTAL MANAGEMENT CONSULTANTS LTD**  
Room 1213-1219, Grand Central Plaza, Tower 2, 138 Shatin Rural Committee Road, Shatin, NT, Hong Kong  
Tel: (852) 2893 1551 Fax: (852) 2891 0305 Email: [mem@maunsell.com.hk](mailto:mem@maunsell.com.hk)

## TABLE OF CONTENTS

### EXECUTIVE SUMMARY

#### 1. INTRODUCTION

Background  
Project Organisation  
Construction Works undertaken during the Reporting Month  
Compliance with EP conditions  
Summary of EM&A Requirements

#### 2. AIR QUALITY MONITORING

Monitoring Requirements  
Monitoring Equipment  
Monitoring Parameters, Frequency and Duration  
Monitoring Locations  
Monitoring Methodology  
Results and Observations

#### 3. NOISE MONITORING

Monitoring Requirements  
Monitoring Equipment  
Monitoring Parameters, Frequency and Duration  
Monitoring Locations  
Monitoring Methodology  
Results and Observations

#### 4. WATER QUALITY MONITORING

Discrete Marine Water Quality Monitoring  
Monitoring of TBT/PAHs/PCBs  
Continuous Marine Water Quality Monitoring

#### 5. TERRESTRIAL ECOLOGY

Monitoring Requirements  
Monitoring Equipment  
Monitoring Parameters, Frequency and Duration  
Monitoring Locations  
Monitoring Methodology  
Results and Observations

#### 6. MARINE MAMMAL MONITORING

Monitoring Requirements  
Monitoring Equipment  
Monitoring Parameter, Frequencies and Duration  
Monitoring Location  
Monitoring Procedures

Results and Observations

7. SUBTIDAL MONITORING

Monitoring Requirement

8. ENVIRONMENTAL AUDIT

Site Environmental Audit

Review of Environmental Monitoring Procedures

Status of Environmental Licensing and Permitting

Implementation Status of Environmental Mitigation Measures

Implementation Status of Event/Action Plans

Implementation Status of Environmental Complaint Handling Procedures

9. FUTURE KEY ISSUES

Key Issues for the Coming Month

Monitoring Schedules for the Next Month

Construction Program for the Next 3 Months

10. CONCLUSIONS AND RECOMMENDATIONS

Conclusions

Recommendations

## List of Tables

Table 1.1	Estimated Amounts of Waste Generated in April 2004
Table 1.2	Environmental Permit Submission
Table 2.1	TSP Monitoring Equipment
Table 2.2	Air Quality Monitoring Parameters and Frequency
Table 2.3	Location of Air Quality Monitoring Stations
Table 3.1	Noise Monitoring Equipment
Table 3.2	Noise Monitoring Parameters, Period and Frequency
Table 3.3	Noise Monitoring Locations
Table 4.1	Discrete Marine Water Quality Monitoring Equipment
Table 4.2	Discrete Marine Water Quality Monitoring Parameters, Period and Frequency
Table 4.3	Discrete Marine Water Quality Monitoring Locations
Table 4.4	Water Quality Exceedance Summary
Table 4.5	TBT Monitoring Equipment
Table 4.6	TBT Monitoring Parameters, Period and Frequency
Table 4.7	TBT Monitoring Locations
Table 4.8	Standard Methods for Laboratory Analysis of Water Samples
Table 4.9	Continuous Marine Water Quality Monitoring Equipment
Table 4.10	Continuous Marine Water Quality Monitoring Parameters, Period and Frequency
Table 4.11	Continuous Marine Water Quality Monitoring Locations
Table 5.1a	Time Allocation (%) for White-bellied Sea Eagle (female and male) activity at Pa Tau Kwu on 17 April
Table 5.1b	Time Allocation (%) for White-bellied Sea Eagle (female and male) activity at Pa Tau Kwu on 24 April
Table 6.1	Marine Mammal Monitoring Equipment
Table 8.1	Summary of Environmental Licensing and Permit Status

## **List of Figures**

Figure 1.1	Project Organisation
Figure 1.2	Layout of Work Site
Figure 2.1	Locations of Air Quality Monitoring Stations
Figure 3.1	Locations of Noise Monitoring Stations
Figure 4.1	Locations of Discrete Water Quality Monitoring Stations
Figure 4.2	Locations of TBT/PAHs/PCBs Monitoring Stations
Figure 4.3	Locations of Continuous Water Quality Monitoring Stations
Figure 5.1	Locations of White-bellied Sea Eagles Monitoring
Figure 5.2	Photographic Records of the White-bellied Sea Eagle
Figure 6.1	Locations of Marine Mammal Monitoring
Figure 7.1	Locations of Subtidal Monitoring

## **List of Appendices**

Appendix A	Amount of Marine Sediment Dredged, Dumped and Filled
Appendix B	Action and Limit Levels
Appendix C	Environmental Monitoring Schedules
Appendix D	Air Quality Monitoring Results
Appendix E	Noise Monitoring Results
Appendix F1	Discrete Water Quality Monitoring Results
Appendix F2	Graphical Presentation of Discrete Water Quality Monitoring Results
Appendix G1	Continuous Water Quality Monitoring Results
Appendix G2	Graphical Presentation of Continuous Water Quality Monitoring Results
Appendix H	TBT Monitoring Results
Appendix I	The QA/QC Procedures and Results
Appendix J	Calibration Details
Appendix K	Site Inspection Records
Appendix L	Summary of Environmental Mitigation Implementation Schedule
Appendix M	Event and Action Plans
Appendix N	Complaint Flow Diagram and Complaint Log
Appendix O	Construction Programme
Appendix P	Contacts of Key Environmental Personnel