PAUL Y. ITC - CCECC JOINT VENTURE

Contract No. CV/2002/08 Fill Bank at Tseung Kwan O Area 137

Quarterly EM&A Summary Report No. 3 (for April to June 2003)

July 2003

Checked By	Edip
Approved By	- Carollitain
	(Project Director)

REMARKS:

The information supplied and contained within this report is, to the best of our knowledge, correct at the time of printing.

MEMCL accepts no responsibility for changes made to this report by third parties.

MAUNSELL ENVIRONMENTAL MANAGEMENT CONSULTANTS LTD Room 1213-1219, Grand Central Plaza, Tower 2

138 Shatin Rural Committee Road, Shatin, NT, Hong Kong Tel: (852) 2893 1551 Fax: (852) 2891 0305

Email: mem@maunsell.com.hk

Maunsell

CONTENTS

EXECUTIVE SUMMARY

1 INTRODUCTION

BACKGROUND SCOPE OF REPORT PROJECT ORGANIZATION SUMMARY OF CONSTRUCTION WORKS SUMMARY OF EM&A REQUIREMENTS

2 ENVIRONMENTAL MONITORING AND AUDIT REQUIREMENTS

MONITORING PARAMETERS MONITORING METHODOLOGY AND CALIBRATION DETAILS ENVIRONMENTAL QUALITY PERFORMANCE LIMITS (ACTION/LIMIT LEVELS) ENVIRONMENTAL MITIGATION MEASURES

3 MONITORING RESULTS

AIR QUALITY NOISE WATER QUALITY

4 INSPECTION RESULTS

IMPLEMENTATION STATUS OF ENVIRONMENTAL MITIGATION MEASURES STATUS OF ENVIRONMENTAL LICENSING AND PERMITTING ADVICE ON SOLID AND LIQUID WASTE MANAGEMENT STATUS

5 NON-COMPLIANCE (EXCEEDANCES) OF THE ENVIRONMENTAL QUALITY PERFORMANCE LIMITS (ACTION AND LIMIT LEVELS)

SUMMARY OF EXCEEDANCES REVIEW OF THE REASONS FOR AND THE IMPLICATIONS OF NON-COMPLIANCE SUMMARY OF ACTIONS TAKEN

6 ENVIRONMENTAL COMPLAINTS

COMPLAINT LOG

- 7 NOTIFICATION OF SUMMONS AND SUCCESSFUL PROSECUTIONS
- 8 COMMENTS, CONCLUSIONS AND RECOMMENDATIONS

LIST OF TABLES, FIGURES, AND APPENDICES

TABLES

TABLE 1.1	CONTACT INFORMATION OF KEY PERSONNEL
TABLE 1.2	SUMMARY OF WORKS UNDERTAKEN IN THE REPORTING
	QUARTER
TABLE 3.1	SUMMARY OF NUMBER OF EXCEEDANCES FOR 1-HR & 24-HR TSP
	CONCENTRATION
TABLE 3.2	COMPARISON OF BASELINE AND VARIOUS PERIOD OF
	AVERAGED 1-HR & 24-HR TSP IMPACT MONITORING RESULTS
TABLE 3.3	SUMMARY OF IMPACT MONITORING RESULTS OF NOISE (DAY-
	TIME) MONITORING
TABLE 3.4	TOTAL NUMBER OF WATER QUALITY EXCEEDANCES AND
	PERCENTAGE DIFFERENCES OF NUMBER OF WATER QUALITY
	EXCEEDANCES IN THE QUARTER
TABLE 3.5	SUMMARY OF STATISTICALLY SIGNIFICANT RESULTS OF SS
TABLE 4.1	IMPORTED DUMP TRUCK LOADS IN THE REPORTING QUARTER
TABLE 4.2	ESTIMATED OFFSITE WASTE DISPOSAL IN THE REPORTING
	QUARTER

FIGURES

Figure 1.1	Project Site Location
Figure 1.2	Air Quality Environmental Monitoring Stations
Figure 1.3	Noise Environmental Monitoring Station
Figure 1.4	Water Quality Monitoring Stations

APPENDICES

	Appendix	ĸА	Projec	t Orga	nisation	Chart
--	----------	----	--------	--------	----------	-------

- Appendix B Construction Programme
- Appendix C Details of Monitoring Requirements
- Appendix D Copy of Equipment Calibration Certificates
- Appendix E Environmental Quality Performance (Action/Limit Levels)
- Appendix F Implementation Status of Environmental Mitigation Measures (EMIS)
- Appendix G Graphical Presentation of Air Quality Monitoring Results
- Appendix H Graphical Presentation of Noise Monitoring Results
- Appendix I Graphical Presentation of Water Quality Monitoring Results
- Appendix J Statistical Analysis of the Trend of Suspended Solids in the Quarter
- Appendix K Permits and Licence Details
- Appendix L Event Action Plan