PAUL Y. ITC - CCECC JOINT VENTURE

Contract No. CV/2002/08 Fill Bank at Tseung Kwan O Area 137 Monthly EM&A Report No.9

(for the month June 2003) (Rev. 0)

July 2003

Approved By

(Project Director)

REMARKS:

The information supplied and contained within this report is, to the best of our knowledge, correct at the time of printing.

MEMCL accepts no responsibility for changes made to this report by third parties.

MAUNSELL ENVIRONMENTAL MANAGEMENT CONSULTANTS LTD

Room 1213-1219, Grand Central Plaza, Tower 2 138 Shatin Rural Committee Road, Shatin, NT, Hong Kong Tel: (852) 2893 1551 Fax: (852) 2891 0305

Email: mem@maunsell.com.hk

Maunsell

TABLE OF CONTENTS

EXECUTIVE SUMMARY

1. INTRODUCTION

BACKGROUND SCOPE OF REPORT PROJECT ORGANIZATION SUMMARY OF CONSTRUCTION WORKS SUMMARY OF EM&A REQUIREMENTS

2. AIR QUALITY

MONITORING REQUIREMENTS
MONITORING EQUIPMENT
MONITORING PARAMETER, FREQUENCY AND SCHEDULE
MONITORING LOCATIONS
MONITORING METHODOLOGY
CALIBRATION DETAILS
RESULTS AND OBSERVATIONS

3. NOISE MONITORING

MONITORING REQUIREMENTS
MONITORING EQUIPMENT
MONITORING PARAMETER, FREQUENCY AND SCHEDULE
MONITORING LOCATION
MONITORING PROCEDURES
RESULTS AND OBSERVATIONS

4. WATER QUALITY

MONITORING EQUIPMENT MONITORING PARAMETERS, FREQUENCY AND DURATION MONITORING METHODOLOGY AND CALIBRATION DETAILS RESULTS AND OBSERVATIONS ASSESSMENT OF ENVIRONMENTAL MONITORING RESULTS

5. ENVIRONMENTAL SITE INSPECTION

SITE INSPECTIONS
REVIEW OF ENVIRONMENTAL MONITORING PROCEDURES
ASSESSMENT OF ENVIRONMENTAL MONITORING RESULTS
ADVICE ON THE SOLID AND LIQUID WASTE MANAGEMENT STATUS
ENVIRONMENTAL LICENCES AND PERMITS
IMPLEMENTATION STATUS OF ENVIRONMENTAL MITIGATION MEASURES
SUMMARY OF EXCEEDANCES OF THE ENVIRONMENTAL QUALITY
PERFORMANCE LIMIT
SUMMARY OF COMPLAINTS, NOTIFICATIONS OF SUMMONS AND
SUCCESSFUL PROSECUTIONS

6. FUTURE KEY ISSUES

CONSTRUCTION PROGRAMME FOR THE COMING MONTHS KEY ISSUES FOR COMING MONTH MONITORING SCHEDULE FOR THE COMING MONTHS

7. CONCLUSIONS AND RECOMMENDATIONS

CONCLUSIONS RECOMMENDATIONS

LIST OF TABLES

TABLE 1.1	CONTACT INFORMATION OF KEY PERSONNEL
TABLE 2.1	AIR QUALITY MONITORING EQUIPMENT
TABLE 2.2	FREQUENCY OF AIR QUALITY MONITORING
TABLE 2.3	AIR QUALITY MONITORING STATIONS
TABLE 2.4	SUMMARY OF 1-HR TSP MONITORING RESULTS
TABLE 2.5	SUMMARY OF 24-HR TSP MONITORING RESULTS
TABLE 3.1	NOISE MONITORING EQUIPMENT
TABLE 3.2	FREQUENCY AND PARAMETERS OF NOISE MONITORING
TABLE 3.3	LOCATION OF THE NOISE MONITORING STATION
TABLE 3.4	SUMMARY OF IMPACT NOISE LEVEL
TABLE 4.1	WATER QUALITY MONITORING EQUIPMENT
TABLE 4.2	WATER QUALITY MONITORING EQUIPMENT
TABLE 4.3	LOCATION OF WATER QUALITY MONITORING STATIONS
TABLE 4.4	SUMMARY OF TOTAL NUMBER OF EXCEEDANCES IN THE
	REPORTING MONTH
TABLE 4.5	TOTAL NUMBER OF WATER QUALITY EXCEEDANCES IN THE
	REPORTING MONTH AND PREVIOUS MONTH
TABLE 5.1	DATES OF IC(E) SITE AUDITS IN JUNE 2003
TABLE 5.2	KEY FINDINGS OF IC(E) SITE AUDITS IN JUNE 2003
TABLE 5.3	SUMMARY OF ENVIRONMENTAL LICENSING AND PERMIT
	STATUS
TABLE 5.4	SUMMARY OF ENVIRONMENTAL COMPLAINTS AND
	PROSECUTIONS

LIST OF FIGURES

Figure 1.1	General Layout
Figure 2.1	Air Quality Environmental Monitoring Stations
Figure 3.1	Noise Environmental Monitoring Station
Figure 4.1	Water Quality Monitoring Stations

APPENDIX

Appendix B Appendix C Appendix D Appendix E Appendix F Appendix G Appendix G Appendix G Appendix G Appendix G Appendix H Appendix I
Appendix D Appendix E Appendix E Appendix F Appendix G Appendix G Appendix H Appendix H Appendix I Calibration Certificates Air Quality Monitoring Results and Graphical Presentation Water Monitoring Results and Graphical Presentation Appendix H Appendix I CE's Site Inspection Record Appendix I ET's Site Inspection Summary
Appendix E Appendix F Appendix F Appendix G Appendix H Appendix H Appendix I Appendix I Appendix I Air Quality Monitoring Results and Graphical Presentation Water Monitoring Results and Graphical Presentation IC(E)'s Site Inspection Record Appendix I ET's Site Inspection Summary
Appendix F Appendix G Appendix H Appendix H Appendix I ET's Site Inspection Summary Noise Monitoring Results and Graphical Presentation Graphical Presentation IC(E)'s Site Inspection Record ET's Site Inspection Summary
Appendix G Water Monitoring Results and Graphical Presentation Appendix H IC(E)'s Site Inspection Record Appendix I ET's Site Inspection Summary
Appendix H IC(E)'s Site Inspection Record Appendix I ET's Site Inspection Summary
Appendix I ET's Site Inspection Summary
11 ,
Appendix I Implementation Schodule of Mitigation Massures
Appendix J Implementation Schedule of Mitigation Measures
Appendix K Interim Notification of Environmental Quality Limits Exceedance
Appendix L Event Action Plan
Appendix M Construction Programme
Appendix N Tentative Schedules for July to September 2003
Appendix O Wind Data
Appendix P Truck Loads Record