

PAUL Y. ITC – CCECC JOINT VENTURE

Contract No. CV/2002/08
Fill Bank at Tseung Kwan O Area 137

Quarterly EM&A Summary Report No. 4
(for July to September 2003)

October 2003

Approved By



(Project Director)

REMARKS:

The information supplied and contained within this report is, to the best of our knowledge, correct at the time of printing.

MEMCL accepts no responsibility for changes made to this report by third parties.

**MAUNSELL ENVIRONMENTAL
MANAGEMENT CONSULTANTS LTD**
Room 1213-1219, Grand Central Plaza, Tower 2
138 Shatin Rural Committee Road, Shatin, NT, Hong Kong
Tel: (852) 2893 1551 Fax: (852) 2891 0305
Email: mem@maunsell.com.hk

Maunsell

CONTENTS

Page

	EXECUTIVE SUMMARY	
1	INTRODUCTION	
	BACKGROUND	
	SCOPE OF REPORT	
	PROJECT ORGANIZATION	
	SUMMARY OF CONSTRUCTION WORKS	
	SUMMARY OF EM&A REQUIREMENTS	
2	ENVIRONMENTAL MONITORING AND AUDIT REQUIREMENTS	
	MONITORING PARAMETERS	
	MONITORING METHODOLOGY AND CALIBRATION DETAILS	
	ENVIRONMENTAL QUALITY PERFORMANCE LIMITS (ACTION/LIMIT LEVELS)	
	ENVIRONMENTAL MITIGATION MEASURES	
3	MONITORING RESULTS	
	AIR QUALITY	
	NOISE	
	WATER QUALITY	
4	INSPECTION RESULTS	
	IMPLEMENTATION STATUS OF ENVIRONMENTAL MITIGATION MEASURES	
	STATUS OF ENVIRONMENTAL LICENSING AND PERMITTING	
	ADVICE ON SOLID AND LIQUID WASTE MANAGEMENT STATUS	
5	NON-COMPLIANCE (EXCEEDANCES) OF THE ENVIRONMENTAL QUALITY PERFORMANCE LIMITS (ACTION AND LIMIT LEVELS)	
	SUMMARY OF EXCEEDANCES	
	REVIEW OF THE REASONS FOR AND THE IMPLICATIONS OF NON-COMPLIANCE	
	SUMMARY OF ACTIONS TAKEN	
6	ENVIRONMENTAL COMPLAINTS	
	COMPLAINT LOG	
7	NOTIFICATION OF SUMMONS AND SUCCESSFUL PROSECUTIONS	
8	COMMENTS, CONCLUSIONS AND RECOMMENDATIONS	

LIST OF TABLES, FIGURES, AND APPENDICES

TABLES

TABLE 1.1	CONTACT INFORMATION OF KEY PERSONNEL
TABLE 1.2	SUMMARY OF WORKS UNDERTAKEN IN THE REPORTING QUARTER
TABLE 3.1	SUMMARY OF NUMBER OF EXCEEDANCES FOR 1-HR & 24-HR TSP CONCENTRATION
TABLE 3.2	COMPARISON OF BASELINE AND VARIOUS PERIOD OF AVERAGED 1-HR & 24-HR TSP IMPACT MONITORING RESULTS
TABLE 3.3	SUMMARY OF IMPACT MONITORING RESULTS OF NOISE (DAY-TIME) MONITORING
TABLE 3.4	TOTAL NUMBER OF WATER QUALITY EXCEEDANCES AND PERCENTAGE DIFFERENCES OF NUMBER OF WATER QUALITY EXCEEDANCES IN THE QUARTER
TABLE 3.5	SUMMARY OF STATISTICALLY SIGNIFICANT RESULTS OF SS
TABLE 4.1	IMPORTED DUMP TRUCK LOADS IN THE REPORTING QUARTER
TABLE 4.2	ESTIMATED OFFSITE WASTE DISPOSAL IN THE REPORTING QUARTER

FIGURES

Figure 1.1	Project Site Location
Figure 1.2	Air Quality Environmental Monitoring Stations
Figure 1.3	Noise Environmental Monitoring Station
Figure 1.4	Water Quality Monitoring Stations

APPENDICES

Appendix A	Project Organisation Chart
Appendix B	Construction Programme
Appendix C	Details of Monitoring Requirements
Appendix D	Copy of Equipment Calibration Certificates
Appendix E	Environmental Quality Performance (Action/Limit Levels)
Appendix F	Implementation Status of Environmental Mitigation Measures (EMIS)
Appendix G	Graphical Presentation of Air Quality Monitoring Results
Appendix H	Graphical Presentation of Noise Monitoring Results
Appendix I	Graphical Presentation of Water Quality Monitoring Results
Appendix J	Statistical Analysis of the Trend of Suspended Solids in the Quarter
Appendix K	Permits and Licence Details
Appendix L	Event Action Plan