



Contract No. CV/2004/13**Temporary Construction Waste Sorting
Facilities at Tseung Kwan O Area 137
and Tuen Mun Area 38****Quarterly EM&A Summary Report No.1
(for the months Nov 05 to Jan 06
at Tseung Kwan O Area 137)**

[03/2006]

	Name	Signature
Reviewed & Checked:	Fiona Li	
Approved:	Y T Tang	

Version:

0

Date: 1 March 2006

The information contained in this report is, to the best of our knowledge, correct at the time of printing. The interpretation and recommendations in the report are based on our experience, using reasonable professional skill and judgment, and based upon the information that was available to us. These interpretations and recommendations are not necessarily relevant to any aspect outside the restricted requirements of our brief. This report has been prepared for the sole and specific use of our client and MEMCL accepts no responsibility for its use by others.

This report is copyright and may not be reproduced in whole or in part without prior written permission.

MAUNSELL ENVIRONMENTAL MANAGEMENT CONSULTANTS LTD

11/F, Grand Central Plaza, Tower 2, 138 Shatin Rural Committee Road, Shatin, NT, Hong Kong

Tel: (852) 2893 1551 Fax: (852) 2891 0305 Email: mem@maunsell.aecom.com

TABLE OF CONTENTS

EXECUTIVE SUMMARY	II
1. INTRODUCTION	1
SCOPE OF REPORT	1
CONSTRUCTION PROGRAMME.....	1
2. ENVIRONMENTAL MONITORING AND AUDIT REQUIREMENTS.....	2
MONITORING PARAMETERS	2
ENVIRONMENTAL QUALITY PERFORMANCE LIMITS (ACTION/LIMIT LEVELS)	2
ENVIRONMENTAL MITIGATION MEASURES	2
3. MONITORING RESULTS.....	3
AIR QUALITY.....	3
ENVIRONMENTAL SITE INSPECTION	3
ADVICE ON SOLID AND LIQUID WASTE MANAGEMENT STATUS	4
4. SUMMARY OF NON-COMPLIANCE (EXCEEDANCES) OF ENVIRONMENTAL QUALITY	5
SUMMARY OF EXCEEDANCES AND REVIEW OF THE REASONS FOR NON-COMPLIANCE.....	5
5. ENVIRONMENTAL COMPLAINTS, NOTIFICATION OF SUMMONS AND SUCCESSFUL PROSECUTION.....	5
6. COMMENTS, RECOMMENDATIONS AND CONCLUSIONS.....	6
COMMENTS ON MITIGATION MEASURES	6
RECOMMENDATIONS ON EM&A PROGRAMME	6
CONCLUSION	6

List of Tables

Table 1.1	Contact Information of Key Personnel	1
Table 3.1	Summary of Number of Exceedances for 1-hr & 24-hr TSP Concentration	3
Table 5.1	Summary of Environmental Complaints and Prosecutions	5

List of Figures

Figure 1.1	General Site Layout for TKO Area 137
Figure 2.1	Air Quality Environmental Monitoring Stations for TKO Area 137

Appendices

Appendix A	Project Organization Chart
Appendix B	Construction Programme
Appendix C	Action and Limit Levels for Air Quality
Appendix D	Implementation Schedule of Mitigation Measures (EMIS)
Appendix E	Graphical Presentation of Air Quality Monitoring Results