


LEGEND:
 C1 • CONTROL STATIONS
 M4 • MONITORING STATIONS

Contract No. CV/2005/12
 Operation of Public Fill Reception Facilities at Tseung Kwan O Area 137, Quarry Bay and Mui Wo

Figure 1
 Locations of Water Quality Monitoring Stations –
 Fill Bank at Tseung Kwan O Area 137





LEGEND:

- N → NOISE MONIORING STATION
- WD ▲ WIND STATION

Contract No. CV/2005/12


Operation of Public Fill Reception Facilities at Tseung Kwan O Area 137, Quarry Bay and Mui Wo

Figure 2

Locations of Noise Monitoring Station –
Fill Bank at Tseung Kwan O Area 137



東業德勤測試顧問有限公司
ETS-TESTCONSULT LIMITED



Legend:

AA ● Air Monitoring Stations

WD ■ Wind Station

Contract No. CV/2005/12

Operation of Public Fill Reception Facilities at Tseung Kwan O Area 137, Quarry Bay and Mui Wo

Figure 3

Locations of Air Quality Monitoring Stations –
Fill Bank at Tseung Kwan O Area 137



東業德動測試顧問有限公司
ETS-TESTCONSULT LIMITED