

Contract No. CV/2007/05
Demolition of Kennedy Town Incineration Plant and Abattoir
Cracks Repaired Record Photos of the Site
Photos Taken on 26 January 2008



Crack No.:
1

Repaired cracked / damaged concrete ground slab between Refrigeration
Block and Weighbridge Office in Kennedy Town Abattoir



Crack No.:
2

Repaired cracked / damaged concrete ground slab between Refrigeration
Block and Weighbridge Office in Kennedy Town Abattoir

Contract No. CV/2007/05
Demolition of Kennedy Town Incineration Plant and Abattoir
Cracks Repaired Record Photos of the Site
Photos Taken on 26 January 2008



Crack No.:
3

Repaired cracked / damaged concrete ground slab outside
Refrigeration Block in Kennedy Town Abattoir



Crack No.:
4

Repaired cracked / damaged concrete road kerb between Refrigeration
Block and Slaughterhouse Block in Kennedy Town Abattoir

Contract No. CV/2007/05
Demolition of Kennedy Town Incineration Plant and Abattoir
Cracks Repaired Record Photos of the Site
Photos Taken on 26 January 2008



Crack No.:
5

Repaired cracked / damaged concrete road slab between Refrigeration
Block and Slaughterhouse Block in Kennedy Town Abattoir



Crack No.:
6

Repaired cracked / damaged concrete road kerb and slab between
Refrigeration Block and Slaughterhouse Block in Kennedy Town Abattoir

Contract No. CV/2007/05
Demolition of Kennedy Town Incineration Plant and Abattoir
Cracks Repaired Record Photos of the Site
Photos Taken on 26 January 2008



Crack No.:
7

Repaired cracked / damaged concrete road kerb between Refrigeration
Block and Slaughterhouse Block in Kennedy Town Abattoir



Crack No.:
8

Repaired cracked / damaged concrete ground slab between
E&M Services Dept. and Chimney C in Kennedy Town Abattoir

Contract No. CV/2007/05

Demolition of Kennedy Town Incineration Plant and Abattoir

Cracks Repaired Record Photos of the Site

Photos Taken on 26 January 2008



Crack No.:
9

Repaired cracked / damaged concrete ground slab between E&M Services
Dept. and Slaughterhouse Block in Kennedy Town Abattoir



Crack No.:
10

Repaired cracked / damaged concrete ground slab between E&M Services
Dept. and Slaughterhouse Block in Kennedy Town Abattoir

Contract No. CV/2007/05

Demolition of Kennedy Town Incineration Plant and Abattoir

Cracks Repaired Record Photos of the Site

Photos Taken on 26 January 2008



Crack No.:
11

Repaired cracked / damaged concrete ground slab between Lairage Block
and Slaughterhouse Block in Kennedy Town Abattoir



Crack No.:
12

Repaired cracked / damaged concrete ground slab between E&M Services
Dept. and Slaughterhouse Block in Kennedy Town Abattoir

Contract No. CV/2007/05
Demolition of Kennedy Town Incineration Plant and Abattoir
Cracks Repaired Record Photos of the Site
Photos Taken on 26 January 2008



Crack No.:
13

Repaired cracked / damaged concrete ground slab under the steel shed
of Lairage Block in Kennedy Town Abattoir



Crack No.:
14

Repaired cracked / damaged concrete ground slab / kerb under the
steel shed of Lairage Block in Kennedy Town Abattoir

Contract No. CV/2007/05

Demolition of Kennedy Town Incineration Plant and Abattoir

Cracks Repaired Record Photos of the Site

Photos Taken on 26 January 2008



Crack No.:
15

Repaired cracked / damaged concrete ground slab under the steel shed
of Lairage Block in Kennedy Town Abattoir



Crack No.:
16

Repaired cracked / damaged concrete ground slab under the steel shed
of Lairage Block in Kennedy Town Abattoir

Contract No. CV/2007/05
Demolition of Kennedy Town Incineration Plant and Abattoir
Cracks Repaired Record Photos of the Site
Photos Taken on 26 January 2008



Crack No.:
17

Repaired cracked / damaged concrete ground slab under the steel shed
of Lairage Block in Kennedy Town Abattoir



Crack No.:
18

Repaired cracked / damaged concrete ground slab under the steel shed
of Lairage Block in Kennedy Town Abattoir

Contract No. CV/2007/05
Demolition of Kennedy Town Incineration Plant and Abattoir
Cracks Repaired Record Photos of the Site
Photos Taken on 26 January 2008



Crack No.:
19

Repaired cracked / damaged concrete ground slab under the steel shed
of Lairage Block in Kennedy Town Abattoir



Crack No.:
20

Repaired cracked / damaged concrete ground slab under the steel shed
of Lairage Block in Kennedy Town Abattoir

Contract No. CV/2007/05
Demolition of Kennedy Town Incineration Plant and Abattoir
Cracks Repaired Record Photos of the Site
Photos Taken on 26 January 2008



Crack No.:
21

Repaired cracked / damaged concrete ground slab outside Lairage
Block and the steel shed in Kennedy Town Abattoir



Crack No.:
22

Repaired cracked / damaged concrete ground slab and kerb outside
Lairage Block in Kennedy Town Abattoir

Contract No. CV/2007/05
Demolition of Kennedy Town Incineration Plant and Abattoir
Cracks Repaired Record Photos of the Site
Photos Taken on 26 January 2008



Photo No.:
23

Repaired cracked / damaged concrete ground slab and kerb outside
Lairage Block and the ramp in Kennedy Town Abattoir



Photo No.:
24

Repaired cracked / damaged road slab between Chimney B and the ramp
in Kennedy Town Incineration Plant

Contract No. CV/2007/05
Demolition of Kennedy Town Incineration Plant and Abattoir
Cracks Repaired Record Photos of the Site
Photos Taken on 26 January 2008



Crack No.:
25

Repaired cracked / damaged road slab between Chimney B and the ramp
in Kennedy Town Incineration Plant



Crack No.:
26

Repaired cracked / damaged road slab between Chimney A and
Chimney B in Kennedy Town Incineration Plant

Contract No. CV/2007/05

Demolition of Kennedy Town Incineration Plant and Abattoir

Cracks Repaired Record Photos of the Site

Photos Taken on 20 December 2007 and 26 January 2008



Crack No.:
27

Repaired cracked / damaged concrete U-channel and slab between
the external wall and Chlorine Store in Kennedy Town Incineration Plant



Crack No.:
28

Repaired cracked / damaged concrete ground slab outside Chlorine
Store in Kennedy Town Incineration Plant

Contract No. CV/2007/05

Demolition of Kennedy Town Incineration Plant and Abattoir

Cracks Repaired Record Photos of the Site

Photos Taken on 18 December 2007 and 19 December 2007



Crack No.:
29

Repaired cracked / damaged concrete ground slab outside Pump

House in Kennedy Town Incineration Plant



Crack No.:
30

Repaired cracked / damaged concrete U-channel and slab between
the external wall and Kennedy Town Incineration Plant

Contract No. CV/2007/05

Demolition of Kennedy Town Incineration Plant and Abattoir

Cracks Repaired Record Photos of the Site

Photos Taken on 20 December 2007 and 23 January 2008



Crack No.:
31

Repaired cracked / damaged concrete U-channel between the external wall
and Kennedy Town Incineration Plant



Crack No.:
32

Repaired cracked / broken concrete ground slab between the external wall
and Kennedy Town Incineration Plant

Contract No. CV/2007/05
Demolition of Kennedy Town Incineration Plant and Abattoir
Cracks Repaired Record Photos of the Site
Photos Taken on 26 January 2008



Crack No.:
33

Repaired cracked / damaged concrete ground slab inside the Kennedy
Town Incineration Plant



Crack No.:
34

Repaired cracked / damaged concrete ground slab inside the Kennedy
Town Incineration Plant

Contract No. CV/2007/05
Demolition of Kennedy Town Incineration Plant and Abattoir
Cracks Repaired Record Photos of the Site
Photos Taken on 26 January 2008



Crack No.:
35

Repaired cracked / broken concrete ground slab inside the Kennedy
Town Incineration Plant



Crack No.:
36

Repaired cracked / broken concrete ground slab inside the Kennedy
Town Incineration Plant

Contract No. CV/2007/05
Demolition of Kennedy Town Incineration Plant and Abattoir
Cracks Repaired Record Photos of the Site
Photos Taken on 26 January 2008



Crack No.:
37

Repaired cracked / damaged road slab between the external wall and
Lairage Block in Kennedy Town Abattoir



Crack No.:
38

Repaired cracked / damaged road slab between the external wall and
Lairage Block in Kennedy Town Abattoir

Contract No. CV/2007/05

Demolition of Kennedy Town Incineration Plant and Abattoir

Cracks Repaired Record Photos of the Site

Photos Taken on 26 January 2008



Crack No.:
39

Repaired cracked / damaged concrete ground slab and kerb between
the external wall and Lairage Block in Kennedy Town Abattoir



Crack No.:
40

Repaired cracked / damaged concrete ground slab and kerb between
the Lairage Block and Substation in Kennedy Town Abattoir

Contract No. CV/2007/05

Demolition of Kennedy Town Incineration Plant and Abattoir

Cracks Repaired Record Photos of the Site

Photos Taken on 26 January 2008 and 22 December 2007



Crack No.:
41

Repaired cracked / damaged concrete ground slab and kerb between the
external wall and Slaughterhouse Block in Kennedy Town Abattoir



Crack No.:
42

Repaired cracked / damaged concrete ground slab and kerb between the
external wall and Slaughterhouse Block in Kennedy Town Abattoir