Civil Engineering and Development Department

Agreement No. CE 67/2015 (HY)
Cycle Tracks from Tuen Mun
to Sheung Shui – Remaining Works
Design and Construction

Monthly EM&A Report (Version 1.0)

November 2016

Approved By

(Dr. Priscilla Choy,

Environmental Team Leader)

REMARKS:

The information supplied and contained within this report is, to the best of our knowledge, correct at the time of printing.

CINOTECH accepts no responsibility for changes made to this report by third parties.

CINOTECH CONSULTANTS LTD

Room 1710, Technology Park, 18 On Lai Street, Shatin, NT, Hong Kong Tel: (852) 2151 2083 Fax: (852) 3107 1388 Email: info@cinotech.com.hk

TABLE OF CONTENTS

	EXECUTIVE SUMMARY	1
	Introduction	
	Environmental Monitoring Works	
	Key Information in the Reporting Month	
	Environmental License and Permits	
	Future Key Issues	
1	INTRODUCTION	3
	Background	3
	Project Organizations	3
	Construction Activities undertaken during the Reporting Month	4
	Summary of EM&A Requirements	5
2	AIR QUALITY	6
	Monitoring Requirements	6
3	WATER QUALITY	
J		
	Monitoring Requirements	
4	NOISE	7
	Monitoring Requirements	7
	Monitoring Locations	
	Monitoring Equipment	
	Monitoring Parameters and Frequency	
	Monitoring Methodology and QA/QC Procedures	
	Maintenance and Calibration	
5	COMPARISON OF EM&A RESULTS WITH EIA PREDICTIONS	
3	COMPARISON OF EMAA RESULTS WITH EIA PREDICTIONS	11
6	ECOLOGY AND FISHERIES	12
7	LANDSCAPE AND VISUAL IMPACT	12
_		
8	ENVIRONMENTAL AUDIT	13
	Site Audits	
	Review of Environmental Monitoring Procedures	
	Statues of Environmental Licensing and Permitting	
	Status of Waste Management Implementation Status of Environmental Mitigation Measures	
	Implementation Status of Environmental Whitgation Weasures Implementation Status of Event and Action Plans	
	Summary of Complaint, Warning, Notification of any Summons and Successful	,,,,,,т
	Prosecution	15
9	FUTURE KEY ISSUES	16
	Key Issues for the Coming Month	
	Monitoring Schedule for the Next Month	
10	CONCLUSIONS AND RECOMMENDATIONS	
10		
	Conclusions	18

Recommendations	18

LIST OF TABLES

Table I	Non-compliance Record for the Project in the Reporting Month
Table II	Summary Table for Key Information in the Reporting Month
Table 1.1	Key Project Contacts
Table 1.2	Construction Programme Showing the Inter-Relationship with Environmental
	Protection/Mitigation Measures
Table 4.1	Noise Monitoring Stations
Table 4.2	Noise Monitoring Equipment
Table 4.3	Frequency and Parameters of Noise Monitoring
Table 4.4	Baseline Noise Level and Noise Limit Level for Monitoring Stations
Table 4.5	Summary Table of Noise Monitoring Results during the Reporting Month
Table 5.1	Comparison of Noise Monitoring Data with predictions in EIA Report and ERR
Table 8.1	Summary of Environmental Licensing and Permit Status
Table 8.2	Observations and Recommendations of Site Audit

LIST OF FIGURES

Figure 1a-1h	Layout Plan of the Project Site
Figure 2	Locations of Construction Noise Monitoring Stations
Figure 3	Organization Chart

LIST OF APPENDICES

A	Work Programme
В	Action and Limit Levels for Noise
C	Copies of Calibration Certificates
D	Environmental Monitoring Schedules
E	Noise Monitoring Results and Graphical Presentations
F	Summary of Exceedance
G	Site Audit Summary
Н	Event and Action Plans
I	Environmental Mitigation Implementation Schedule (EMIS)
J	Summaries of Environmental Complaint, Warning, Summon and Notification of
	Successful Prosecution
K	Summary of Waste Generation and Disposal Records

Remaining Works – Design and Construction Monthly EM&A Report – November 2016

EXECUTIVE SUMMARY

Introduction

- 1. This is the 1st Environmental Monitoring and Audit (EM&A) Report prepared by Cinotech Consultants Limited for the "Agreement No. CE 67/2015 (HY) Cycle Tracks from Tuen Mun to Sheung Shui Remaining Works Design and Construction" (hereinafter called "the Project"). This report documents the findings of EM&A Works conducted in 23th 30th November 2016.
- 2. During the reporting month, the major site activities undertaken in the reporting month included:
 - Site clearance at Portion K;
 - Ground investigation works at Portions E and F;
 - Construction of wheel washing facilities at Portions A and K;
 - Construction of trial pit at Portions E and F;
 - Construction of borehole at Portions E and F:
 - Utilities diversion works at Portions D, E, F, G, H, N and K;
 - Excavation works for site formation at Portion L; and
 - Tree felling at Portion K.

Environmental Monitoring Works

- 3. Environmental monitoring for the Project shall be performed in accordance with the EM&A Manual and the monitoring results were checked and reviewed. Site Inspections/Audits were conducted once per week. The implementation of the environmental mitigation measures, Event Action Plans and environmental complaint handling procedures were also checked.
- 4. Summary of the non-compliance in the reporting month for the Project is tabulated in **Table I**.

Table I Non-compliance Record for the Project in the Reporting Month

Parameter	No. of Exc	eedance	Action
	Action Level	Limit Level	Taken
Noise	0	0	N/A

Construction Noise

5. All construction noise monitoring was conducted as scheduled in the reporting month. No Action/Limit Level exceedance was recorded.

Key Information in the Reporting Month

6. Summary of key information in the reporting month is tabulated in **Table II**.

Table II Summary Table for Key Information in the Reporting Month

Event	Event Details		Action Taken	Status	Remark
	Number	Nature			

Event	Event Event Details		Action Taken	Status	Remark
	Number	Nature			
Complaint received	0		N/A	N/A	
Reporting Changes	0		N/A	N/A	
Notifications of any summons & prosecutions received	0		N/A	N/A	

Environmental License and Permits

- 7. Licenses/Permits granted to the Project include:
 - Environmental Permits (EP) for the Project,
 - EP-450/2013 issued on 30 May 2013 and EP-450/2013/A issued on 25 August 2015; and
 - EP-501/2015 issued on 2 September 2015
 - Billing Account for Waste Disposal (Acc No.: 7025411)

Future Key Issues

- 8. The future key environmental issues in the coming two months include:
 - Dust generation from stockpiles of dusty materials, exposed site area, excavation works and other dust-generating activities;
 - Water spraying for dust generating activity and on haul road;
 - Proper storage of construction materials on-site;
 - Storage of chemicals/fuel and chemical waste/waste oil on-site;
 - Accumulation of general refuse and construction waste on-site;
 - Noise from operation of the equipment, especially for excavation works and machinery onsite:
 - Wastewater and runoff generation on-site;
 - Regular removal of silt, mud and sand along u-channels and inside sedimentation tanks;
 - Protection measures for retained trees on-site; and
 - Review and implementation of temporary drainage system for the surface runoff.

Monthly EM&A Report – November 2016

1 INTRODUCTION

Background

- 1.1 "Construction of Cycle Tracks and the Associated Supporting Facilities from Sha Po Tsuen to Shek Sheung River" (the EIA Report) is a Schedule 2 Designated Project (DP) under Environmental Impact Assessment Ordinance (EIAO). The Environmental Impact Assessment (EIA) Report (Registered No.: AEIAR-133/2009) and the associated Environmental Monitoring and Audit (EM&A) Manual was approved on 12 March 2009.
- 1.2 Civil Engineering and Development Department (CEDD) implemented the DP in two stages, i.e. Stage 1 and Stage 2. An Environmental Permit (EP) No. EP-450/2013 has been granted for Stage 1 works on 30 May 2013. Pursuant to Section 13 of the EIAO, the Director of Environmental Protection amends the Environmental Permit (No. EP-450/2013) based on the Application No. VEP-478/2015 and the EP (Permit No. EP-450/2013/A) was issued on 25 August 2015 to CEDD as the Permit Holder.
- 1.3 An Environmental Review (ER) Report of the "Construction of Cycle Tracks and the Associated Supporting Facilities from Sha Po Tsuen to Shek Sheung River Stage 2" had been prepared in July 2015 and the Environmental Monitoring and Audit Manual (EM&A Manual) was also included as part of the ER report in the application (Application No.: AEP-501-2015). An Environmental Permit No. EP-501/2015 was issued on 2 September 2015 for Stage 2 works to CEDD as the Permit Holder.
- 1.4 "Agreement No. CE 67/2015 (HY) Cycle Tracks from Tuen Mun to Sheung Shui Remaining Works Design and Construction" (hereinafter called the "Project") covers the Stage 1 (Part) and Stage 2 works of the DP. This Project was commissioned to Sang Hing Kuly Joint Venture (hereinafter called the "Contractor") for "Contract No.: YL/2015/01 Cycle Tracks from Tuen Mun to Sheung Shui Remaining Works". The site location and work programme are shown in **Figure 1a-1h** and **Appendix A** respectively.
- 1.5 Cinotech Consultants Ltd. was designated as the Environmental Team (ET) to undertake the Environmental Monitoring and Audit (EM&A) works for the Project. The construction commencement of the Project was on 23th November 2016. This is the 1st Monthly EM&A Report summarizing the EM&A works for the Project from 23th 30th November 2016.

Project Organizations

- 1.6 Different parties with different levels of involvement in the project organization include:
 - Project Proponent Civil Engineering and Development Department (CEDD)
 - Supervisor Representative Mannings (Asia) Consultants Limited (Mannings)
 - Environmental Team (ET) Cinotech Consultants Limited (Cinotech)
 - Independent Environmental Checker (IEC) ANewR Consulting Limited (ANewR)
 - Contractor Sang Hing Kuly Joint Venture (SKJV)
- 1.7 The Organizational Structure for Environmental Management is shown in **Figure 3**.




Figure 3 Organization Structure (Environmental Aspects)

1.8 The key contacts of the Project are shown in **Table 1.1**.

Table 1.1 Key Project Contacts

Tuble 111 Tkey 110 geet Contacts					
Party	Role	Contact Person	Phone No.	Fax No.	
CEDD Project Proponent		Mr. Chu Wai Lun, Thomas	2417 6370	2412 0358	
Mannings Supervisor Representative		Mr. Simon Ng	3168 2028	3168 2022	
Environmental	Dr. Priscilla Choy	2151 2089	3107 1388		
Cinotech	Cinotech Team	Ms. Ivy Tam	2151 2090	3107 1366	
ANewR	Independent Environmental Checker	Mr. Adi Lee	2618 2836	3007 8648	
SKJV Contractor		Mr. Michael Wan	9222 3089	N/A	

Construction Activities undertaken during the Reporting Month

- 1.9 The major site activities undertaken in the reporting month included:
 - Site clearance at Portion K;
 - Ground investigation works at Portions E and F:
 - Construction of wheel washing facilities at Portions A and K;
 - Construction of trial pit at Portions E and F;
 - Construction of borehole at Portions E and F;
 - Utilities diversion works at Portions D, E, F, G, H, N and K;

- Excavation works for site formation at Portion L; and
- Tree felling at Portion K.
- 1.10 The construction programme showing the inter-relationship with environmental protection/mitigation measures are presented in **Table 1.2**.

Table 1.2 Construction Programme Showing the Inter-Relationship with Environmental Protection/Mitigation Measures

Construction Works	Major Environmental Impact	Control Measures
As mentioned in Section 1.8	Noise, dust impact, water quality and waste generation	 Sufficient watering of the works site with active dust emitting activities Properly cover the stockpiles On-site waste sorting and implementation of trip ticket system Appropriate desilting/sedimentation devices provided on site for treatment with valid Discharge License before discharge Well maintain the drainage system to prevent the spillage of wastewater during heavy rainfall Use of quiet plant and well-maintained construction plant Provide movable noise barrier Proper wheel washing for construction vehicles before leaving the site Provide sufficient mitigation measures as recommended in Approved EM&A Manual/Lease requirement

Summary of EM&A Requirements

- 1.11 The EM&A programme requires construction noise monitoring, air quality monitoring, landscape and visual monitoring and environmental site audit. The EM&A requirements for each parameter are described in the following sections, including:
 - All monitoring parameters;
 - Action and Limit levels for all environmental parameters;
 - Event and Action Plans;
 - Environmental mitigation measures, as recommended in the EIA Reports, Environmental Review Reports and EM&A Manuals
- 1.12 The advice on the implementation status of environmental protection and pollution control/mitigation measures is summarized in Section 8 of this report.
- 1.13 This report presents the monitoring results, observations, locations, equipment, period, methodology and QA/QC procedures of the required noise monitoring and audit works for the Project in 23 30 November 2016.

2 AIR QUALITY

Monitoring Requirements

- 2.1 According to the approved EM&A Manuals for Stage 1 works and Stage 2 works in Year 2015, no air quality monitoring is required for the Project.
- 2.2 Site audits were carried out on a weekly basis to monitor and audit the timely implementation of air quality mitigation measures within the site boundaries of this Project. The summaries of site audits are attached in **Appendix G**.

3 WATER QUALITY

Monitoring Requirements

- 3.1 According to the approved EM&A Manuals for Stage 1 works and Stage 2 works in Year 2015, no water quality monitoring is required for the Project.
- 3.2 Site audits were carried out on a weekly basis to monitor and audit the timely implementation of water quality mitigation measures within the site boundaries of this Project. The summaries of site audits are attached in **Appendix G**.

4 NOISE

Monitoring Requirements

- 4.1 In accordance with approved EM&A Manuals for Stage 1 works in Year 2015, no noise impact monitoring is required for Stage 1 works of the Project.
- 4.2 According to approved EM&A Manual for Stage 2 works (Year 2015), construction noise monitoring was conducted to monitor the construction noise arising from the construction activities under the Stage 2 works of the Project. The regular monitoring frequency for each monitoring station shall be on a weekly basis and conduct one set of measurements between 0700 and 1900 hours on normal weekdays. **Appendix B** shows the established Action and Limit Levels for the environmental monitoring works.

Monitoring Locations

4.3 Noise monitoring was conducted at 6 designated monitoring stations (N1, N2, N3, N5, N6 and N7) in the reporting month. **Figures 2a – 2c** shows the locations of these stations.

Table 4.1 Noise Monitoring Stations

Monitoring Stations	Locations	Location of Measurement
N1	HKMLC Wong Chan Sook Ying Memorial School	Rooftop (about 5/F) area
N2	Bethel High School	Rooftop (about 4/F) area
N3	No. 159 Mai Po San Tsuen	G/F area
N5	Block 2, Dills Corner Garden	G/F area
N6	Home of Loving Faithfulness	Rooftop (about 3/F) area
N7	Village House in Shek Wu Wai	G/F area

Monitoring Equipment

- 4.4 Integrating Sound Level Meter was used for impact noise monitoring. The meters are Type 1 sound level meter capable of giving a continuous readout of the noise level readings including equivalent continuous sound pressure level (L_{eq}) and percentile sound pressure level (L_x) that also complied with International Electrotechnical Commission Publications 651:1979 (Type 1) and 804:1985 (Type 1) specifications.
- 4.5 Acoustic Calibrator was used to check the accuracy of the sound level meter. The calibrators generate a continuous and highly stable sound pressure level at known frequency of 1 kHz that also complied with IEC 942: 1988 Class 1 specifications. **Table 4.2** summarizes the noise monitoring equipment in reporting period. Copies of calibration certificates are provided in **Appendix C**.

Table 4.2 Noise Monitoring Equipment

Equipment	Model and Make	Qty.
Integrating Sound Level Meter	SVAN 955, 957	1
Acoustic Calibrator	SVAN SV30A, B&K4231	1

Monitoring Parameters and Frequency

4.6 **Table 4.3** summarizes the monitoring parameters, frequency and total duration of monitoring. The noise monitoring schedule is shown in **Appendix D**.

Table 4.3 Frequency and Parameters of Noise Monitoring

Monitoring Stations	Parameter	Period	Frequency	Measurement
N1				Façade
N2	L _{eq} (30 min.) dB(A) L ₁₀ (30 min.) dB(A) L ₉₀ (30 min.) dB(A)	0700 1000 has		Façade
N3		on normal		Free Field
N5		weekdays	Once per week	Free Field
N6		weekuays		Façade
N7				Free Field

Monitoring Methodology and QA/QC Procedures

- 4.7 The monitoring procedures are as follows:
 - The monitoring station were normally be at a point 1m from the exterior of the sensitive receivers building façade and be at a position 1.2m above the ground.
 - For free field measurement, the meter was positioned away from any nearby reflective surfaces. All records for free field noise levels were adjusted with a correction of +3 dB(A).
 - The battery condition was checked to ensure the correct functioning of the meter.
 - Parameters such as frequency weighting, the time weighting and the measurement time were set as follows:

frequency weighting: Atime weighting : Fast

- measurement time : 30 minutes

- Prior to and after each noise measurement, the meter was calibrated using a Calibrator for 94.0 dB at 1000 Hz. If the difference in the calibration level before and after measurement is more than 1.0 dB, the measurement was considered invalid and repeat of noise measurement was required after re-calibration or repair of the equipment.
- At the end of the monitoring period, the L_{eq} , L_{90} and L_{10} were recorded. In addition, noise sources were recorded on a standard record sheet.
- Noise measurement would be paused temporarily during periods of high intrusive noise if possible and observation would be recorded when intrusive noise was not avoided.
- Noise monitoring would be cancelled in the presence of fog, rain, and wind with a steady speed exceeding 5 m/s, or wind with gusts exceeding 10 m/s. supplementary monitoring would be provided to ensure sufficient data would be obtained.

Maintenance and Calibration

- 4.8 The microphone head of the sound level meter and calibrator were cleaned with a soft cloth at quarterly intervals.
- 4.9 The sound level meter and calibrator were checked and calibrated at yearly intervals.

4.10 Immediately prior to and following each noise measurement, the accuracy of the sound level meter was checked using an acoustic calibrator generating a known sound pressure level at a known frequency. Measurements may be accepted as valid only if the calibration levels from before and after the noise measurement agree to within 1.0 dB.

Results and Observations

- 4.11 All construction noise monitoring was conducted as scheduled in the reporting month. No Action/Limit Level exceedance was recorded. The summary of exceedance record in the reporting month is shown in **Appendix F**.
- 4.12 The baseline noise level and the Noise Limit Level at each designated noise monitoring stations are presented in **Table 4.4**.
- 4.13 Noise monitoring results and graphical presentations are shown in **Appendix E**.
- 4.14 The other noise sources identified which might affect the noise monitoring results at the designated noise monitoring stations are as follows:

Monitoring Stations	Locations	Other Noise Source(s)
N1	HKMLC Wong Chan Sook Ying Memorial School	Road traffic noise Noise from daily school activities
N2	Bethel High School	Road traffic noise Noise from daily school activities
N3	No. 159 Mai Po San Tsuen	Road traffic noise
N5	Block 2, Dills Corner Garden	Road traffic noise
N6	Home of Loving Faithfulness	Road traffic noise Noise from activities at the premise and workshops near the premise
N7	Village House in Shek Wu Wai	Road traffic noise Noise from activities at workshops near the village house

Table 4.4 Baseline Noise Level and Noise Limit Level for Monitoring Stations

Station	Baseline Noise Level, dB (A)	Noise Limit Level, dB (A)
N1	62.2 (at 0700 – 1900 hrs on normal weekdays)	70* (at 0700 – 1900 hrs on
N2	55.2 (at 0700 – 1900 hrs on normal weekdays)	
N3	68.8 (at 0700 – 1900 hrs on normal weekdays)	75 (at 0700 – 1900 hrs on normal weekdays)

N5	70.7 (at 0700 – 1900 hrs on normal weekdays)	75 (at 0700 – 1900 hrs on normal weekdays)
N6	72.0 (at 0700 – 1900 hrs on normal weekdays)	75 (at 0700 – 1900 hrs on normal weekdays)
M7	70.7 (at 0700 – 1900 hrs on normal weekdays)	75 (at 0700 – 1900 hrs on normal weekdays)

^(*) Noise Limit Level is 65 dB(A) during school examination periods.

Table 4.5 Summary Table of Noise Monitoring Results during the Reporting Month

Date	Measured Noise Level, Leq(30min) dB (A)	Baseline Level dB (A)	Construction Noise Level (1): Leq(30min) dB (A)			
N1 - HKMLC	Wong Chan Sook Ying	Memorial School				
23-Nov-16	62.4	62.2	48.9			
N2 – Bethel Hi	gh School					
23-Nov-16	55.4	55.2	41.9			
N3 – No. 159 N	N3 – No. 159 Mai Po San Tsuen					
23-Nov-16	69.7	68.8	62.4			
N5 – Block 2, Dills Corner Garden						
23-Nov-16	73.9	70.7	71.1			
N6 – Home of Loving Faithfulness						
23-Nov-16	73.0	72.0	66.1			
N7 – Village House in Shek Wu Wai						
23-Nov-16	71.5	70.7	63.8			

Note (1) The noise level due to the construction work (CNL) was calculated by the following formula:

 $CNL = 10 \log (10^{MNL/10} - 10^{BNL/10})$

Remarks: MNL = Measured Noise Level BNL = Baseline Noise Level

5 COMPARISON OF EM&A RESULTS WITH EIA PREDICTIONS

5.1 The EM&A data was compared with the predictions in EIA Report (Year 2009) and Environmental Review Report (ERR) for Stage 2 Works (Year 2015) as summarized in **Table 5.1**.

Table 5.1 Comparison of Noise Monitoring Data with Predictions in EIA Report and ERR

Stations	Predicted Mitigated Construction Noise Levels in EIA (2009), dB(A)	Predicted Mitigated Worst Case Construction Noise Levels in ERR for Stage 2 (2015), dB(A)	Reporting Month (Nov 16), Leq (30min) dB(A)
N1 - HKMLC Wong Chan Sook Ying Memorial School	55-62	62 ⁽¹⁾	48.9
N2 – Bethel High School	57-64	64 ⁽¹⁾	41.9
N3 – No. 159 Mai Po San Tsuen	70-73	74 ⁽²⁾	62.4
N5 – Block 2, Dills Corner Garden	73-75	75 ⁽²⁾	71.1
N6 – Home of Loving Faithfulness	64-73	74 ⁽¹⁾	66.1
N7 – Village House in Shek Wu Wai	N/A ⁽³⁾	70 ⁽²⁾	63.8

Remark:

- (1) With adoptions of quiet PMEs, temporary noise barrier and enclosure
- (2) With sub-grouping of construction activities
- (3) No construction noise level was predicted in EIA Report (2009)
- 5.2 The noise monitoring results in the reporting month at monitoring stations (N1, N2, N3 and N5) were lower than the predicted mitigated construction noise levels in the EIA Report. The noise monitoring results at N6 in the reporting month was within the range of predictions in the EIA Report.
- 5.3 The noise monitoring results in the reporting month at 6 monitoring stations were lower than the predicted mitigated worst case construction noise levels in the ERR for Stage 2 Works.

Monthly EM&A Report – November 2016

6 ECOLOGY AND FISHERIES

- 6.1 In accordance with the EM&A Manuals for Stage 1 and Stage 2 works in Year 2015, no specific ecological or fisheries monitoring is required during the construction phase of the Project.
- 6.2 Site audits were carried out on a weekly basis to monitor and audit the timely implementation of ecology and fisheries mitigation measure. The summaries of site audits are attached in **Appendix G**.

7 LANDSCAPE AND VISUAL IMPACT

- 7.1 In accordance with the EM&A Manuals for Stage 1 and Stage 2 works in Year 2015, regular audits should be carried out to ensure all the recommended landscape and visual mitigation measures in EIA Report, Environmental Review Reports and EM&A Manuals were effectively implemented.
- 7.2 ET Site audits were carried out on a weekly basis to monitor and audit the timely implementation of landscape and visual mitigation measure. The summaries of site audits are attached in **Appendix G**.

8 ENVIRONMENTAL AUDIT

Site Audits

- 8.1 Site audit was carried out on a weekly basis to monitor the timely implementation of proper environmental management practices and mitigation measures in the Project site. The summaries of site audits are attached in **Appendix G**.
- 8.2 Site audit was conducted on 23 November 2016 in the reporting month. No non-compliance was observed during the site audit.

Review of Environmental Monitoring Procedures

8.3 The monitoring works conducted by the monitoring were inspected regularly. The following observations have been recorded for the monitoring works:

Noise Monitoring

- The monitoring team recorded all observations around the monitoring stations, which might affect the monitoring result.
- Major noise sources were identified and recorded. Other intrusive noise attributing to the result was trimmed off by pausing the monitoring temporarily.

Statues of Environmental Licensing and Permitting

8.4 All permits/licenses obtained for the Project are summarized in **Table 10.1**.

Table 10.1 Summary of Environmental Licensing and Permit Status

Permit No.	Valid	Period	Details	Status	
Permit No.	From	To	Details	Status	
Environmental Peri	mit (EP)				
			Construction of Cycle Tracks and the		
EP-450/2013/A	25/08/15	N/A	Associated Supporting Facilities from Sha	Valid	
			Po Tsuen to Shek Sheung River – Stage 1		
			Construction of Cycle Tracks and the		
EP-501/2015	02/09/15	N/A	Associated Supporting Facilities from Sha	Valid	
			Po Tsuen to Shek Sheung River – Stage 2		
Billing Account for C	onstruction	Waste Dispo	osal		
			Billing Account for construction waste		
A/C No.: 7025411	N/A	N/A	disposal under Waste Disposal (Charges	Valid	
A/C No 7023411	IV/A	IV/A	for Disposal of Construction Waste)	v anu	
			Regulation		
Effluent Discharge Li	Effluent Discharge License				
Under Application					
Registration of Chemical Waste Producer					
Under Application					
Construction Noise Permit (CNP)					
N/A					

Status of Waste Management

- 8.5 The amount of wastes generated by the major site activities of this Project during the reporting month is shown in **Appendix K**.
- 8.6 In respect of the dump truck cover, the Contractor is advised to take record photos and inspection to ensure that all dump trucks have fully covered the skip before leaving the site.

Implementation Status of Environmental Mitigation Measures

- 8.7 According to the Environmental Review Reports, Environmental Permits and the EM&A Manuals of the Project, the mitigation measures detailed in the documents are recommended to be implemented during the construction phase. An updated summary of the Environmental Mitigation Implementation Schedule (EMIS) is provided in **Appendix I**.
- 8.8 During site inspections in the reporting month, no non-conformance was identified. The ET weekly site inspections were carried out during the reporting month and the observations and recommendations are summarized in **Table 10.2**.

Table 10.2 Observations and Recommendations of Site Audit

Parameters	Date	Observations and Recommendations	Follow-up
Water Quality	23 Nov 2016	Reminder: Mud accumulated near the sediment tank near Mai Po Lung Road should be cleared to prevent muddy runoff generation.	Follow up actions will be reported in the next month.
Air Quality	N/A	There was no observation in the reporting period.	N/A
Noise	N/A	There was no observation in the reporting period.	N/A
Waste / Chemical Management	23 Nov 2016	Reminder General refuse at Portions A & C should be properly disposed of to prevent accumulation.	Follow up actions will be reported in the next month.
Ecology and Fisheries	N/A	There was no observation in the reporting period.	N/A
Landscape and Visual	N/A	There was no observation in the reporting period.	N/A
Permits/ Licenses	23 Nov 2016	Reminder: Environmental Permit should be properly displayed at Portion A	Follow up actions will be reported in the next month.

Implementation Status of Event and Action Plans

8.9 The Event and Action Plan for noise is presented in **Appendix H**.

Construction Noise

8.10 No Action/Limit Level exceedance was recorded in the reporting month.

Cycle Tracks from Tuen Mun to Sheung Shui – Remaining Works – Design and Construction Monthly EM&A Report – November 2016

Summary of Complaint, Warning, Notification of any Summons and Successful Prosecution

8.11 The summaries of environmental complaint, warning, summon and notification of successful prosecution for the Project is presented in **Appendix J**.

9 FUTURE KEY ISSUES

- 9.1 Major site activities undertaken for the coming two months include:
 - Site clearance at Portions B, D, F, G, H, I and M;
 - Construction of trial pit at Portions C, D and E;
 - Construction of ball hole at Portions D, E, H and M;
 - Construction of RC Structure at Portion L;
 - Tree felling at Portion K and M; and
 - Construction of retaining wall at Portions A, C, E and K.

Key Issues for the Coming Month

- 9.2 Key environmental issues in the coming months include:
 - Wastewater and runoff generation on-site;
 - Regular removal of silt, mud and sand along u-channels and inside sedimentation tanks;
 - Review and implementation of temporary drainage system for the surface runoff;
 - Noise from operation of the equipment, especially for excavation works and machinery on-site;
 - Dust generation from stockpiles of dusty materials, exposed site area, excavation works and other dust-generating activities;
 - Water spraying for dust generating activities and on haul road;
 - Proper storage of construction materials on-site;
 - Storage of chemicals/fuel and chemical waste/ waste oil on-site;
 - Accumulation of general refuse and construction waste on-site;
 - Protection measures for retained trees on-site.
- 9.3 The tentative program of major site activities and the impact prediction and control measures for the coming month, i.e. December 2016 to January 2017, are summarized as follows:

Construction Works	Major Impact Prediction	Control Measures
A	Air quality impact (dust) Water quality impact (surface run-off)	 (a) Frequent watering of haul road and unpaved/exposed areas; (b) Frequent watering or covering stockpiles with tarpaulin or similar means; and (c) Watering of any earth moving activities. (d) Diversion of the collected effluent to de-silting facilities for treatment in compliance with valid Discharge License prior to discharge to public
As mentioned in Section 9.1	Tun-On)	storm water drains; (e) Provision of adequate de-silting facilities for treating surface run-off and other collected effluents prior to discharge; (f) Provision of perimeter protection such as sealing of hoarding footings to avoid run-off from entering the existing storm water drainage system via public road; and (g) Provision of measures to prevent discharge into

	the stream.
Noise impact	(h) Scheduling of noisy construction activities if
	necessary to avoid persistent noisy operation;
	(i) Controlling the number of plants use on site;
	(j) Regular maintenance of machines
	(k) Use of quiet PMEs on-site; and
	(1) Use of acoustic barriers and noise enclosure if
	necessary.
Landscape and	(m) Proper setup of precautionary area for retained
Visual	trees.

Monitoring Schedule for the Next Month

9.4 The tentative environmental monitoring schedules for the next month are shown in **Appendix D**.

10 CONCLUSIONS AND RECOMMENDATIONS

Conclusions

10.1 Environmental monitoring works were performed in the reporting month and all monitoring results were checked and reviewed.

Construction Noise Monitoring

10.2 All construction noise monitoring was conducted as scheduled in the reporting month. No Action/Limit Level exceedance was record.

Site Audit

10.3 1 times of ET joint weekly environmental site inspection was conducted in the reporting month.

Complaint and Prosecution

- 10.4 No environmental complaints and environmental prosecution were received in the reporting month.
- 10.5 No environmental prosecution was received in the reporting month.

Recommendations

10.6 According to the environmental audit performed in the reporting month, the following recommendations were made:

Water Quality

• All mud / soil should be avoided to locate near the rivers to prevent silty surface run-off entering the surrounding water environment.


Waste/Chemical Management


• General refuse should be removed regularly to prevent accumulation on-site. Proper enclosed bin should be provided for collection of general refuse from workforce.


Permits/Licenses


• Environmental Permits of the Project should be properly displayed at the site entrance(s) of work area(s). All environmental related permits and licenses shall be available for inspection.

FIGURES











Agreement No. CE 67/2015(HY)
Cycle Tracks from Tuen Mun to Sheung Shui - Remaining Works
Design and Construction
Site Layout Plan

CINOTECH







Agreement No. CE 67/2015(HY)
Cycle Tracks from Tuen Mun to Sheung Shui - Remaining Works
Design and Construction
Site Layout Plan

N.T.S No. MA16036

Date Dec-16 Figure 1f


CINOTECH







Agreement No. CE 67/2015(HY)
Cycle Tracks from Tuen Mun to Sheung Shui - Remaining Works
Design and Construction
Site Layout Plan


CINOTECH











APPENDIX A WORK PROGRAMME

















APPENDIX B ACTION AND LIMIT LEVELS FOR NOISE

Appendix B - Action and Limit Levels

 Table B-1
 Action and Limit Levels for Construction Noise

Time Period	Action Level	Limit Level
0700-1900 hrs on normal weekdays	When one documented complaint is received	75 dB(A) 70dB(A)/65dB(A)*

Remarks: If works are to be carried out during restricted hours, the conditions stipulated in the Construction Noise Permit (CNP) issued by the Noise Control Authority have to be followed. *70dB(A) and 65dB(A) for schools during normal teaching periods and school examination periods, respectively.

APPENDIX C COPIES OF CALIBRATION CERTIFICATES





Rms 1516, 1701 & 1716, Technology Park, 18 On Lai Street, Shatin, N.T., Hong Kong. Tel: 2898 7388 Fax: 2898 7076

Website: www.wellab.com.hk



APPLICANT: Cinotech Consultants Limited

Room 1710, Technology Park,

18 On Lai Street,

Shatin, NT, Hong Kong

Test Report No.: C/N/160819B
Date of Issue: 2016-08-22
Date Received: 2016-08-19
Date Tested: 2016-08-19
Date Completed: 2016-08-22
Next Due Date: 2017-08-21

ATTN:

Mr. W.K. Tang

Page:

1 of 1

Certificate of Calibration

Item for calibration:

Description

: 'SVANTEK' Integrating Sound Level Meter

Manufacturer

: SVANTEK

Model No.

: SVAN 957 : 21459

Serial No.
Microphone No.

: 43676

Equipment No.

: N-08-08

Test conditions:

Room Temperatre

: 24 degree Celsius

Relative Humidity

: 58%

Test Specifications:

Performance checking at 94 and 114 dB

Methodology:

In-house method, according to manufacturer instruction manual

Results:

Reference Set Point, dB	Instrument Readings, dB
94	94.0
114	114.0

PREPARED AND CHECKED BY:

For and On Behalf of WELLAB Ltd.

PATRICK TSE

Laboratory Manager



Rms 1516, 1701 & 1716, Technology Park, 18 On Lai Street, Shatin, N.T., Hong Kong. Tel: 2898 7388 Fax: 2898 7076 Website: www.wellab.com.hk

TEST REPORT

APPLICANT: Cinotech Consultants Limited

Room 1710, Technology Park,

18 On Lai Street,

Shatin, NT, Hong Kong

Test Report No.:	C/N/160819D
Date of Issue:	2016-08-22
Date Received:	2016-08-19
Date Tested:	2016-08-19
Date Completed:	2016-08-22
Next Due Date:	2017-08-21

ATTN:

Mr. W.K. Tang

Page:

1 of 1

Certificate of Calibration

Item for calibration:

Description

: Acoustical Calibrator

Manufacturer

: Brüel & Kjær

Model No.

: 4231

Serial No.

: 2412367

Equipment No.

: N-02-03

Test conditions:

Room Temperatre

: 24 degree Celsius

Relative Humidity

: 58%

Methodology:

The Sound Level Calibrator has been calibrated in accordance with the documented procedures and using standard(s) and instrument(s) which are recommended by the manufacturer, or equivalent.

Results:

Sound Pressure Level (1kHz)	Measured SPL	Tolerance
At 94 dB SPL	94.0	$94.0 \pm 0.1 \text{ dB}$
At 114 dB SPL	114.0	114.0 ± 0.1 dB

PREPARED AND CHECKED BY:

For and On Behalf of WELLAB Ltd.

PATRICK TSE

Laboratory Manager

APPENDIX D ENVIRONMENTAL MONITORING SCHEDULES

Agreement No. CE 67/2015 (HY)

Cycle Tracks from Tuen Mun to Sheung Shui - Remaining Works Impact Noise Monitoring Schedule (November 2016)

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
		1-Nov	2-Nov	3-Nov	4-Nov	5-Nov
6-Nov	7-Nov	8-Nov	9-Nov	10-Nov	11-Nov	12-Nov
0-1107	7 1107	0 1107) 110V	10 1107	11 1107	12 1101
13-Nov	14-Nov	15-Nov	16-Nov	17-Nov	18-Nov	19-Nov
20-Nov	21-Nov	22-Nov	23-Nov	24-Nov	25-Nov	26-Nov
20-1107	21-1101	22-110V	23-110V	24-1101	23-110V	20-1101
					Noise	
					- 1.4-0-2	
27-Nov	28-Nov	29-Nov	30-Nov			

Noise Monitoring Station

- N1 HKMLC Wong Chan Sook Ying Memorial School
- N2 Bethel High School
- N3 No. 159 Mai Po San Tsuen
- N5 Dills Corner Garden Block 2
- N6 Home of Loving Faithfulness
- N7 Village House in Shek Wu Wai

Agreement No. CE 67/2015 (HY)

Cycle Tracks from Tuen Mun to Sheung Shui - Remaining Works - Design and Construction Tentative Impact Noise Monitoring Schedule (December 2016)

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
	10.4			1-Dec	2-Dec	3-Dec
				Noise		
4-Dec	5-Dec	6-Dec	7-Dec	8-Dec	9-Dec	10-Dec
			Noise			
11-Dec	12-Dec	13-Dec	14-Dec	15-Dec	16-Dec	17-Dec
				Noise		
18-Dec	19-Dec	20-Dec	21-Dec	22-Dec	23-Dec	24-Dec
			Noise			
25-Dec	26-Dec	27-Dec	28-Dec	29-Dec	30-Dec	31-Dec
					Noise	

The schedule may be changed due to unforeseen circumstances (adverse weather, etc)

Noise Monitoring Station

- N1 HKMLC Wong Chan Sook Ying Memorial School
- N2 Bethel High School
- N3 No. 159 Mai Po San Tsuen
- N5 Dills Corner Garden Block 2
- N6 Home of Loving Faithfulness
- N7 Village House in Shek Wu Wai

APPENDIX E NOISE MONITORING RESULTS AND GRAPHICAL PRESENTATIONS

Appendix E - Noise Monitoring Results

(0700-1900 hrs on Normal Weekdays)

Location N1 - HKMLC Wong Chan Sook Ying Memorial School											
Unit: dB (A) (30-min)											
Date	Time Weather	Meas	sured Noise L	_evel	Baseline Level	Construction Noise Level					
			L eq L10 L 90 L eq L eq								
25-Nov-16	10:00	Cloudy	62.4								

Location N2 - E	Location N2 - Bethel High School												
Unit: dB (A) (30-min)													
Date	Time	Time Weather	Meas	sured Noise L	_evel	Baseline Level	Construction Noise Level						
			L eq L 10 L 90 L eq L eq										
25-Nov-16	10:45	Cloudy	55.4	56.3	52.1	55.2	41.9						

Location N3 - N	Location N3 - No.159 Mai Po San Tsuen												
			Unit: dB (A) (30-min)										
Date	Time	Weather	Meas	Measured Noise Level			Construction Noise Level						
			L _{eq}	L ₁₀	L 90	L _{eq}	L _{eq}						
25-Nov-16	11:30	Cloudy	69.7	71.6	67.5	68.8	62.4						


Location N5 - Block 2, Dills Corner Garden											
Unit: dB (A) (30-min)											
Date	Time	Weather	Meas	Measured Noise Level			Construction Noise Level				
			L eq L 10 L 90 L eq L eq								
25-Nov-16	8:30	Cloudy	73.9	77.2	71.1	70.7	71.1				


Location N6 - H	Location N6 - Home of Loving Faithfulness												
Unit: dB (A) (30-min)													
Date	Time	Weather	Meas	sured Noise L	_evel	Baseline Level	Construction Noise Level						
			L eq L 10 L 90 L eq L eq										
25-Nov-16	9:15	Cloudy	73.0	74.6	70.8	72.0	66.1						

Location N7 - V	Location N7 - Village House in Shek Wui Wai												
Unit: dB (A) (30-min)													
Date	Time	Weather	Meas	Measured Noise Level			Construction Noise Level						
			L eq L ₁₀ L ₉₀ L _{eq} L _{eq}										
25-Nov-16	13:25	Cloudy	71.5	70.3	64.7	70.7	63.8						

MA16036/App E - Noise Cinotech

Noise Levels - N1 N1 - HKMLC Wong Chan Sook Ying Memorial School Limit Level, 70.0 dB(A), Examination Periods, 65.0 dB(A) dB(A) 80 75 **Construction Noise Level** 70 65 60 55 50 45 1404, 404, 40 40 04.404.46 1424 HOUNG 100 HOY 100 TO 12 HON 16 1, 21, 40⁴, 60 120 MOV 10 Date Baseline NL, 68.1 dB(A) N2 - Bethel High School · Limit Level. 70.0 dB(A) Examination Periods, 65.0 dB(A) 80 75 70





Title Agreement No. CE 67/2015 (HY)


Cycle Tracks from Tuen Mun to Sheung Shui - Remaining Works
Design and Construction


Graphical Presentation of


Construction Noise Monitoring Results



Noise Levels







Title Agreement No. CE 67/2015 (HY)

Cycle Tracks from Tuen Mun to Sheung Shui - Remaining Works
Design and Construction

Graphical Presentation of Construction Noise Monitoring Results

Scale Project
N.T.S No. MA16036

Date Appendix

Nov 16

Ε



APPENDIX F SUMMARY OF EXCEEDANCE

Agreement No. CE 67/2015 (HY)

Cycle Tracks from Tuen Mun to Sheung Shui – Remaining Works – Design and Construction

Appendix F – Summary of Exceedance

Exceedance Report for Contract No. YL/2015/01 – Cycle Tracks from Tuen Mun to Sheung Shui – Remaining Works

(A) Exceedance Report for Construction Noise (NIL in the reporting month)

APPENDIX G SITE AUDIT SUMMARY

Agreement No. CE 67/2015 (HY)

Cycle Tracks from Tuen Mun to Sheung Shui – Remaining Works – Design and Construction

Contract No. YL/2015/01

Cycle Tracks from Tuen Mun to Sheung Shui – Remaining Works

Weekly Site Inspection Record Summary

Inspection Information

Checklist Reference Number	161123
Date	23 November 2016 (Wednesday)
Time	10:00-12:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
161123-R03	Water Quality Mud accumulated near the sediment tank near Mai Po Lung Road should be cleared to prevent muddy runoff generation.	В 4
	C. Air Quality No environmental deficiency was identified during site inspection.	
	 D. Construction Noise Impact No environmental deficiency was identified during site inspection. 	A de la visita del visita de la visita dela visita de la visita della
	E. Waste / Chemical Management	
161123-R02	• General refuse at PortionsA&C should be properly disposed of to prevent accumulation.	Eli& Eliii
	F. Ecology and Fisheries • No environmental deficiency was identified during site inspection.	
	G. Landscape & Visual • No environmental deficiency was identified during site inspection.	
	H. Permits/Licences	1
161123-R01	Environmental Permit should be properly displayed at Portion A.	H 5
	I. Others • N/A	

	Name	Signature	Date
Recorded by	KC Chung	Oly	23 November 2016
Checked by	Dr. Priscilla Choy	NI	23 November 2016

APPENDIX H EVENT AND ACTION PLANS

Appendix H - Event and Action Plans

Event and Action Plan for Construction Noise

EVENT	ACTION					
	ET LEADER	IEC	ER	CONTRACTOR		
Action Level	1. Notify IC(E) and Contractor;	1. Review the analysed results	1. Confirm receipt of	1. Submit noise mitigation		
being	2. Carry out investigation;	submitted by the ET;	notification of failure in	proposals to IC(E);		
exceeded	3. Report the results of investigation to	2. Review the proposed remedial	writing;	2. Implement noise mitigation		
	the IC(E) and Contractor;	measures by the Contractor and	2. Notify Contractor;	proposals.		
	4. Discuss with the Contractor and	advise the ER accordingly;	3. Require Contractor to			
	formulate remedial measures;	3. Supervise the implementation	propose remedial measures			
	5. Increase monitoring frequency to	of remedial measures.	for the analysed noise			
	check mitigation effectiveness.		problem;			
			4. Ensure remedial measures			
			are properly implemented.			
Limit Level	1. Notify IC(E), ER, EPD and	1. Discuss amongst ER, ET, and	1. Confirm receipt of	1. Take immediate action to		
being	Contractor;	Contractor on the potential	notification of failure in	avoid further exceedance;		
exceeded	2. Identify source;	remedial actions;	writing;	2. Submit proposals for remedial		
	3. Repeat measurement to confirm	2. Review Contractor's remedial	2. Notify Contractor;	actions to IC(E) within 3 working		
	findings	actions whenever necessary to	3. Require Contractor to	days of notification;		
	4. Increase monitoring frequency;	assure their effectiveness and	propose remedial measures	3. Implement the agreed		
	5. Carry out analysis of Contractor's	advise the ER accordingly.	for the analysed noise	proposals;		
	working procedures to determine	3. Supervise the implementation	problem;	4. Resubmit proposal if problem		
	possible mitigation to be implemented;	of remedial measures	4. Ensure remedial measures	still not under control;		
	6. Inform IC(E), ER and EPD the		are properly implemented;	5. Stop the relevant portion of		
	causes & actions taken for the		5. If exceedance continues,	works as determined by the ER		
	exceedances;		consider what portion of the	until the exceedance is abated.		

Appendix H - Event and Action Plans

7. Assess effectiveness of	work is responsible and	
Contractor's remedial actions and	instruct the Contractor to stop	
keep IC(E), EPD and ER informed of	that portion of the work until	
the results;	the exceedance is abated.	
8. If exceedance stops, cease		
additional monitoring		

APPENDIX I ENVIRONMENTAL MITIGATION IMPLEMENTATION SCHEDULE (EMIS)

Appendix I - Summary of Implementation Schedule of Mitigation Measures for Construction Phase

EIA Ref.	EM&A Ref.	Mitigation Measures	Status
Construction	Air Quality		
S.3.6.2	S.3.2.3	All the dust control measures as recommended in the Air Pollution Control (Construction Dust) Regulation, where applicable, should be implemented. Typical dust control measures include:	٨
S.3.6.2	S.3.2.3	• The works area for site clearance shall be sprayed with water before, during and after the operation so as to maintain the entire surface wet	٨
S.3.6.2	S.3.2.3	• Restricting heights from which materials are to be dropped, as far as practicable to minimize the fugitive dust arising from unloading/ loading	٨
S.3.6.2	S.3.2.3	• Immediately before leaving a construction site, all vehicles shall be washed to remove any dusty materials from the bodies and wheels. However, all spraying of materials and surfaces should avoid excessive water usage	۸
S.3.6.2	S.3.2.3	• Where a vehicle leaving a construction site is carrying a load of dusty materials, the load shall be covered entirely by clean impervious sheeting to ensure that the dusty materials will not leak from the vehicle	۸
S.3.6.2	S.3.2.3	• Travelling speeds should be controlled to reduce traffic induced dust dispersion and re-suspension within the site from the operating haul trucks	٨
S.3.6.2	S.3.2.3	• Erection of hoarding of not less than 2.4 m high from ground level along the site boundary, where appropriate	٨
S.3.6.2	S.3.2.3	• Any stockpile of dusty materials shall be covered entirely by impervious sheeting; and/or placed in an area sheltered on the top and 4 sides	٨

EIA Ref.	EM&A Ref.	Mitigation Measures	Status
S.3.6.2	S.3.2.3	 All dusty materials shall be sprayed with water or a dust suppression chemical immediately prior to any loading, unloading or transfer operation so as to maintain the dusty materials wet 	۸
Construction	Noise Impact		
S5.5.11	S4.2.17 (Stage 1 only)	In order to prevent potential cumulative construction noise impacts to NSRs at Mai Po San Tsuen and Palm Springs, the works at the cycle track section (near CH-MP5+100m) are recommended to be scheduled to avoid works at the areas near Castle Peak Road of the Proposed Comprehensive Development at Wo Shang Wai (CDWSW) project if the works site of the CDWSW project is less than 300 m away from Castle Peak Road.	N/A
S.5.5.14	S.4.2.2 (Stage 1 only)	The contractor shall liaise with the Yuen Long and Kam Tin Sewerage and Sewage Disposal Stage 2 (YLKTSSD2) and North West New Territories Salt Water Supply (NWNTSWS) works contractors so as to avoid undertaking works concurrently with the works when they are in the close proximity as far as practicable. As a conservative approach, works for the cycle track shall be carried out when the works from the other projects are over 300 m away. The requirements shall be included in the works contracts.	N/A
N/A	N/A (Stage 2 only)	The contractor shall liaise with Yuen Long and Kam Tin Sewerage and Sewage Disposal (YLKSSD), Construction of Cycle Tracks and the associated Supporting Facilities at Nam Sang Wai, Yuen Long (NSWCT), Drainage Improvement at Northern NT - Package A – Drainage Improvement Works in San Tin (Remaining Works) - Investigation, North East New Territories New Development Areas Planning and Engineering Study (Investigation) (NENTNDA) and the Proposed Residential cum Passive Recreational Development within "Recreation" ("REC") zone and "Residential (Group C)" Zone at Various Lots in DD 104, Yuen Long, N.T. (RCPRD) contractors so as to avoid undertaking works concurrently with their works (refer to S. 4.2.2 of the EM&A Manual for Stage 2 Works).	٨

EIA Ref.	EM&A Ref.	Mitigation Measures	Status
Table 5-7	S.4.2.19	Use of quiet plant (PME):	^
		- mini excavator	
		- mobile crane	
		- dump truck	
		- hand-held electric circular saw	
		- concrete lorry mixer	
		- lorry	
		- vibratory poker	
		- asphalt paver	
		- crane mounted auger	
		- road roller	
		- road ripper, excavator mounted	
S.5.6.2	S.4.2.19	Noise barrier in the form of site hoarding shall be used for the following PMEs	^
Table 5-8		where practicable:	
		- mini excavator	
		- mobile crane	
		- dump truck	
		- hand-held electric circular saw	
		- bar bender	
		- vibrating hammer	
		- generator	
		- concrete lorry mixer	
		- lorry	
		- vibratory poker	
		- asphalt paver	
		- compactor	
		- road roller	
		- crane mounted auger	

EIA Ref.	EM&A Ref.	Mitigation Measures	Status
		- grout mixer	
		- grout pump	
		- drill	
		- road ripper, excavator mounted	
S.5.6.2	S.4.2.19	Noise enclosure shall be used for the following PMEs where practicable:	N/A(1)
		- air compressor	
		- hand-held breaker	
S.5.6.2	S.4.2.19	The barrier / enclosure material's surface mass shall be in excess of 7 kg/m ² .	٨
S.5.6.6	S.4.2.19	Use of alternative quieter plant such as road ripper, excavator mounted instead of	٨
		handheld breaker during levelling/excavation works.	
S.5.6.8	S.4.2.19	The Contractor shall adopt the Code of Practice on Good Management Practice to	٨
		Prevent Violation of the Noise Control Ordinance (Chapter 400) (for Construction	
		Industry) published by EPD	
S.5.6.8	S.4.2.19	The Contractor shall observe and comply with the statutory and non-statutory	٨
		requirements and guidelines	
S.5.6.8	S.4.2.19	Before commencing any work, the Contractor shall submit to the project Engineer	٨
		for approval the method of working, equipment and noise mitigation measures	
		intended to be used at the site	
S.5.6.8	S.4.2.19	The Contractor shall devise and execute working methods to minimize the noise	٨
		impact on the surrounding sensitive uses, and provide experienced personnel with	
		suitable training to ensure that those methods are implemented	
S.5.6.8	S.4.2.19	Noisy equipment and noisy activities should be located as far away from the NSRs as	٨
		is practical	
S.5.6.8	S.4.2.19	Unused equipment should be turned off. PME should be kept to a minimum and the	٨
		parallel use of noisy equipment / machinery should be avoided	
S.5.6.8	S.4.2.19	Regular maintenance of all plant and equipment	٨
S.5.6.8	S.4.2.19	Material stockpiles and other structures should be effectively utilised as noise	N/A
		barriers, where practicable	

EIA Ref.	EM&A Ref.	Mitigation Measures	Status
S.5.6.8	S.4.2.19	The Contractor shall liaise with the schools that are located near the works sites regarding their examination period and schedule the noisy works to avoid the examination period as far as possible	^
Construction	Water Quality		
S.6.6.1	S.5.2.4	Mitigation measures should be implemented to prevent the uncontrolled discharge of wastewater from the construction site in accordance with Practice Note for Professional Persons ProPECC PN1/94 - Construction Site Drainage	^
S.6.6.1	S.5.2.4	Surface run-off from the construction sites will be directed into storm drains via adequately designed wastewater treatment facilities such as sand traps, silt traps and sediment settling basins. This is important for works immediately along the Kam Tin River, Ngau Tam Mei Main Drainage Channel, River Beas and Shek Sheung River	٨
S.6.6.1	S.5.2.4	Channels, earth bunds or sand bag barriers will be provided on-site to properly direct stormwater to the above-mentioned facilities	۸
S.6.6.1	S.5.2.4	Existing silt removal facilities, channels and manholes along roads and pedestrian walkways will be maintained and the deposited silt and grit will be removed regularly, at the onset of and after each rainstorm to ensure that these facilities are functioning properly at all times	٨
S.6.6.1	S.5.2.4	Other manholes (including any newly constructed ones) will be adequately covered and temporarily sealed so as to prevent silt, construction materials or debris from getting into the drainage system	^
S.6.6.1	S.5.2.4	Open stockpiles of materials on site will be avoided or where unavoidable covered with tarpaulin or similar fabric during rainstorms. Measures will be taken to prevent the washing away of construction materials, soil, silt or debris into any drainage system	٨
S.6.6.1	S.5.2.4	Where possible, works entailing soil excavation will be minimized during the rainy season (i.e. April to September);	٨
S.6.6.1	S.5.2.4	Where applicable, final earthworks surfaces/ slopes will be well compacted and	N/A

EIA Ref.	EM&A Ref.	Mitigation Measures	Status
		hydro-seeded following completion to prevent erosion	
S.6.6.1	S.5.2.4	During construction works, chemical toilets will be provided for the use of site staff.	٨
		These will be provided by a licensed contractor, who will be responsible for	
		appropriate disposal and maintenance of the effluent	
S.6.6.1	S.5.2.4	Works adjacent to the fishponds near Mai Po San Tsuen should be avoided as far as	٨
		possible during the wet season to avoid runoff into the fishponds	
S.6.6.1	S.5.2.4	Wastewater from site facilities (such as toilets) should be discharged to foul sewer,	٨
		where available. Chemical toilets will be considered where there is no foul sewer	
		connection. There is not expected to be a temporary canteen.	
S.6.6.1	S.5.2.4	All site discharges within Water Control Zones must comply with the terms and	^
		conditions of a valid discharge licence issued by EPD	
S.6.6.1	S.5.2.4	Vehicle wheel washing facilities should be provided, where applicable, at the site	^
		exit such that mud, debris, etc. deposited onto the vehicle wheels or body can be	
		washed off before the vehicles are leaving the site area	
S.6.6.1	S.5.2.4	Section of the road between the wheel washing bay and the public road should be	^
		paved with backfill to reduce vehicle tracking of soil and to prevent site run-off from	
		entering public road drains	
S.6.6.1	S.5.2.4	The project may occasionally involve the handling of fuel and generates chemical	^
		wastes. It must be ensured that all fuel tanks and chemical storage are sited on sealed	
		areas and provided with locks	
S.6.6.1	S.5.2.4	The storage areas will be surrounded by bunds with a capacity equal to 110% of the	*
		storage capacity of the largest tank to prevent accidentally spilled oil, fuel or	
		chemicals from reaching the receiving waters	
S.6.6.1	S.5.2.4	Oil and grease removal facilities will be provided where appropriate, for example, in	N/A
		area near plant workshop/ maintenance areas	
S.6.6.1	S.5.2.4	Chemical waste arising from the site should be properly stored, handled, treated and	٨
		disposed of in compliance with the requirements stipulated under the Waste Disposal	
		(Chemical Waste) (General) Regulation	

EIA Ref.	EM&A Ref.	Mitigation Measures	Status
-	S.5.2.7 (Stage 1 only)	The construction work of cycle bridge at Shek Sheung River is not recommended to be carried out during wet seasons (April to October), and the dry weather flow will be diverted to avoid entering the works area. In order to further protect the river water quality from disturbance, the construction work especially excavation works, will be surrounded by cofferdams to ensure the works will be carried out in a dry condition to prevent water pollution to the river.	^
N/A	S.5.2.4 (Stage 2 only)	Stream decking is recommended to be carried out during dry weather condition. To prevent disturbance to the river water quality, measures will be taken to ensure the works to be carry out in a dry condition to prevent water pollution to the river, such as sandbag barriers.	^
N/A	S.5.2.6 (Stage 2 only)	Based on the current available information, the tentative programmes of some construction works for the Agreement No. CE 57/2011 (DS) Drainage Improvement at Northern NT - Package A Drainage Improvement Works in San Tin (Remaining Works) - Investigation (DIST) and the Construction of Cycle Tracks and the associated Supporting Facilities at Nam Sang Wai, Yuen Long (NSWCT) projects may overlap with Stage 2 cycle track construction works. It is recommended that the Contractor should liaise with the project contractor(s) of the DIST and the NSWCT projects to schedule the construction works and allow programme phrasing to avoid major concurrent activities to be undertaken simultaneously in the vicinity.	٨
Construction	Waste Managem	ent	
S.7.4.1	S.6.2.1 – S.6.2.4	An on-site environmental co-ordinator employed by the Contractor should be identified at the outset of the works. Prior to commencement of Project works, the co-ordinator shall prepare a WMP in accordance with the requirements set out in the ETWB TCW No. 19/2005, Waste Management on Construction Sites, for the ER's approval. The WMP shall include monthly and yearly Waste Flow Tables ("WFT") that indicate the amounts of waste generated, recycled and disposed of (including final disposal site), and which should be regularly updated;	^
S.7.4.1	S.6.2.6	Given the potential for secondary environmental impacts (dust, noise, water quality	٨

EIA Ref.	EM&A Ref.	Mitigation Measures	Status
		and visual impacts), mitigation measures are required to ensure proper handling, storage, transportation and disposal of materials at the outset and throughout the construction phase of the project	
S.7.4.1	S.6.2.6	The reuse/ recycling of all materials on site shall be investigated and exhausted prior to treatment/ disposal off-site	^
S.7.4.1	S.6.2.6	 Good site practices shall be adopted from the commencement of works to avoid the generation of waste, reduce cross contamination of waste and to promote waste minimisation 	٨
S.7.4.1	S.6.2.6	• All waste materials shall be sorted on-site into inert and non-inert C&D materials, and where the materials can be recycled or reused, they shall be further segregated. Inert material, or public fill will comprise stone, rock, masonry, brick, concrete and soil which is suitable for land reclamation and site formation whilst non-inert materials include all other wastes generated from the construction process such as plastic packaging and vegetation (from site clearance)	٨
S.7.4.1	S.6.2.6	• The Contractor shall be responsible for identifying what materials can be recycled/ reused, whether on-site or off-site. In the event of the latter, the Contractor shall make arrangements for the collection of the recyclable materials. Any remaining non-inert waste shall be collected and disposed of to the Public Filling Areas whilst any inert C&D materials shall be re-used on site as far as possible. Alternatively, if no use of the inert material can be found onsite, the materials can be delivered to a Public Fill Area or Public Fill Bank after obtaining the appropriate licence	٨
S.7.4.1	S.6.2.6	• In order to monitor the disposal of C&D material and solid wastes at public filling facilities and landfills, and control fly-tipping, a trip-ticket system shall be implemented by the Contractor, in accordance with the contract and the requirements of DEVB Technical Circular (Works) No. 6/2010 "Trip Ticket System for Disposal of Construction and Demolition Material".	٨

EIA Ref.	EM&A Ref.	Mitigation Measures	Status
S.7.4.1	S.6.2.6	• Under the Waste Disposal (Chemical Waste) (General) Regulation, the Contractor shall register as a Chemical Waste Producer if chemical wastes such as spent lubricants and paints are generated on site. Only licensed chemical waste collectors shall be employed to collect any chemical waste generated at site. The handling, storage, transportation and disposal of chemical wastes shall be conducted in accordance with the Code of Practice on the Packaging, Labelling and Storage of Chemical Wastes and A Guide to the Chemical Waste Control Scheme both published by EPD;	^
S.7.4.1	S.6.2.6	• A sufficient number of covered bins shall be provided on site for the containment of general refuse to prevent visual impacts and nuisance to the sensitive surroundings. These bins shall be cleared daily and the collected waste disposed of to the refuse transfer station. Further to the issue of ETWB Technical Circular (Works) No. 8/2010, Enhanced Specification for Site Cleanliness and Tidiness, the Contractor is required to maintain a clean and hygienic site throughout the project works;	*
S.7.4.1	S.6.2.6	• All chemical toilets, if any, shall be regularly cleaned and the night-soil collected and transported by a licensed contractor to a Government Sewage Treatment Works facility for disposal; and	۸
S.7.4.1	S.6.2.6	Toolbox talks should be provided to workers about the concepts of site cleanliness and appropriate waste management procedures, including waste reduction, reuse and recycling.	۸
S.7.4.1	S.6.2.6	• The Contractor shall comply with all relevant statutory requirements and guidelines and their updated versions that may be issued during the course of project construction.	٨
Land Contam	nination		
S.8.7.2 – S.8.7.3	S.7.2.2	Preparation of Contamination Assessment Plan (CAP), which should be submitted to EPD for endorsement, prior to investigation.	۸

EIA Ref.	EM&A Ref.	Mitigation Measures	Status
		Site investigation and sampling works in accordance with the approved CAP. If	
		contamination is identified, Contamination Assessment Report (CAR) and	
		Remediation Action Plan (RAP) shall be prepared and submitted for EPD's approval.	
S.8.7.5	S.7.3.1	The following control measures should be implemented when handling identified contaminated materials:	N/A
		■ General site safety shall be enforced to include basic practices such as the use of	
		safety boots, hard hats, coveralls, gloves and eye protection;	
		Avoid skin contact, ingestion and inhalation of excavated contaminated soils. Basic	
		personal protective equipment should be used;	
		• Site staff and workers shall be given adequate training and instructions specific to	
		the potential hazards, their health and safety responsibilities and safe working	
		practice including basic personal hygiene;	
		 Measures shall be implemented to prevent non-workers from approaching the 	
		identified works areas in order to avoid exposure to contaminants.	
S.8.7.5	S.7.3.1	Management of Contaminated Soils	N/A
		 Where appropriate, the use of bulk handling equipment should be maximised to 	
		reduce the potential contacts between excavated contaminated materials and	
		associated workers;	
		■ The plants for excavation and transportation of the material shall be cleaned prior to leaving the Site;	
		 All temporary stockpiles of the materials shall be completely covered with plastic/ 	
		tarpaulin sheets, particularly during heavy rainstorms. The stockpiling areas should	
		be concrete-paved or lined with its perimeter constructed of a concrete	
		bund where appropriate in order to avoid any leachate from migrating out of the area;	
		Any vehicles transporting the material shall be suitably covered to limit potential	
		dust emissions;	
		■ Surface waters shall be diverted around any contaminated areas or stockpiles to	
		minimize potential runoff into excavations, as runoff might increase the volume of	

EIA Ref.	EM&A Ref.	Mitigation Measures	Status
		contaminated water requiring disposal and suspended solids in the wastewater stream	
Ecological & 1	Fisheries Impact		
S.9.11.4	S.8.2.2	Prior to tree felling, survey inspections should be made for their suitability for roosting bats. Once these trees have been highlighted, then appropriate checks of each tree for bats should be made prior to removal as a precautionary measure.	٨
S.9.11.7	S.8.2.3 (Stage 1 only)	In situ compensation planting at the Information Kiosk and R9 should occur to provide continuing function of the bamboo and plantation (see Figure 8-1 of EM&A Manual for Stage 1 Works (Year 2015)). It is recommended that the Information Kiosk and Resting Station R9 should be designed sympathetically to the natural surroundings. Compensation planting along the Sheung Yue River and Shek Sheung River including at R9 and Information Kiosk could be implemented as appropriate.	N/A
S.9.11.17 – S.9.11.19	S.8.2.4 (Stage 1) S.8.2.3 (Stage 2)	or the Kam Tin section and the Long Valley section of the Project, construction orks shall not be carried out during the wet season (April to October) which is onsidered to have no significant impact to wildlife and to avoid the breeding season of Greater Painted-snipes at Long Valley. This is also to prevent any site run-off to diacent water channels and fishponds including those fishponds along San Tin suen Road.	
S.9.11.23	S.8.2.4 (Stage 2 only)	Construction of the section in the vicinity of Mai Po Village SSSI shall be undertaken beyond the recognised breeding seasons for ardeids in Hong Kong to prevent any potential disturbance to the nesting birds, i.e., from September to February.	٨
-	S.8.2.5 (Stage 1 only)	In order to avoid any adverse impact to the healthiness of the bamboo groove from dust-coating on leave next to the R9 and hence affect the breeding habitat of the very rare Dark Brown Ace, a dust barrier should be installed between the bamboo and the construct site.	N/A
-	S.8.2.6 (Stage 1 only)	For the lower Shek Sheung River, construction works should be scheduled in dry season to minimize the disturbance to the foraging ardeids and the Quiet PME shall	۸

EIA Ref.	EM&A Ref.	Mitigation Measures	Status	
		be implemented practicable to minimize the noise disturbance to the foraging ardeids.		
S.10.5.4	S.8.2.7	To prevent any negative impact to water quality as a result of site run-off, good site	٨	
	(Stage 1)	practice must be employed at all times, particularly in the areas close to fishponds.		
	S.8.2.5	Practice Note for Professional Persons ProPECC PN1/94 – Construction Site		
	(Stage 2)	Drainage shall be implemented.		
S.10.5.4	S.8.2.8	Along Pok Wai South Road, once the final construction sequencing is known, liaison	N/A	
	(Stage 1)	with local residents and aquaculturists should be implemented in order to minimise		
	S.8.2.6	temporary road blockages and to identify the best timing for works along this area.		
	(Stage 2)			
S.10.5.3	S.8.2.9	During wet seasons, surface run-off from the construction sites will need to be	٨	
	(Stage 1)	directed into storm drains via adequately designed wastewater treatment facilities		
	S.8.2.7	such as sand traps, silt traps, oil interceptors and sediment settling basins. Works		
	(Stage 2)	adjacent to the fishponds near NTMDC inside the Wetland Conservation Area		
		(WCA) and Mai Po San Tsuen should be avoided, as far as practicable, during the		
		wet season to avoid runoff into the fishponds.		
-	S.8.2.10	The use of signage at the Resting Stations to indicate that wildlife may be present	N/A	
	(Stage 1 only)	and that noise levels and activities should be kept to a minimum could be		
		implemented. This may help to reduce any potential disturbance to wildlife from		
		human activity. At Long Valley, to mitigate against potential indirect human		
		disturbance to Greater Painted-snipe, planting could be undertaken as appropriate		
		along the proposed cycle track at meander 8 to act as screening.		
S.9.11.27	S.8.2.11	The following good work practices are recommended:	^	
	(Stage 1)	 Avoid soil storage against trees; 		
	S.8.2.9	■ Fence off any potentially ecologically sensitive areas;		
	(Stage 2)	 Delineation of works area to prevent encroachment onto adjacent habitats; 		
		■ Reinstatement of habitat after works;		
		■ No on-site burning of waste;		

EIA Ref.	EM&A Ref.	Mitigation Measures	Status
		 Waste and refuse in appropriate receptacles; Staff training/toolbox talks for site work near Long Valley and WCA – important areas for birds therefore staff should reduce amount of noise whilst working and during breaks where possible; Regular ecological checks; and Silt/ Sediment/ Oil traps for drainage to prevent site run-off 	
Cultural Heri	tage Impact	The state of the s	
S.11.5.1	S.9.2.1	Care should be taken during the construction stage to report any signs of possible discovery of artefacts.	N/A
Landscape an	d Visual		
Detailed Desig	gn Phase		
Table 12-11	CP1	A detailed tree survey to be carried out by the IDC Consultant during the detailed design stage. The recommendations of the preliminary tree survey shall be reviewed and confirmed during the detailed survey. Should tree felling be required, tree felling application is required in accordance with DEVB Technical Circular (Works) No. 10/2013 Tree Preservation	^
S.12.9.3	CP6	It has been agreed that the proposed landscape areas under DSD's 4215DS project which falls within the cycle track works area will be implemented by Project proponent of this Project in form of roadside amenity areas after completion of the cycle track. During the detailed design, the works programme of this Project shall be coordinated with the above-mentioned DSD project in order to avoid abortive planting works and impact on landscape resources between the interface of different public works. The proposed landscape areas under 4215DS falled within the cycle track works area shall be incorporated in the final landscape design of this Project.	٨
S.12.10.1	OP1	The Design Concept Drawings and Conceptual Landscape Master Plan of cycle track and associated facilities demonstrate landscape and visual mitigation strategies and design measures including integrated design approach, amenity and compensatory	٨

EIA Ref.	EM&A Ref.	Mitigation Measures	Status
		planting proposals and treatment of retaining structure and slopes have been recommended in the EIA. More detailed landscape and compensatory planting	
		proposals shall be developed by IDC consultants at later stage during detailed design and construction phase of this project following the completion of the detailed Tree	
Construction I	Ola aga	Survey Report and approval from relevant departments at that stage	
Table 12-11	CP1.1	To retain trees, which have high amenity or ecology value and contribute most to the landscape and visual amenity of the site and its immediate environs.	٨
	CP1.2	Creation of precautionary area around trees to be retained equal to half of the trees canopy diameter. Precautionary area to be fenced.	٨
	CP1.3	Prohibition of the storage of materials including fuel, the movement of construction vehicles, and the refuelling and washing of equipment including concrete mixers within the precautionary area.	^
	CP1.4	Phased segmental root pruning for trees to be retained and transplanted over a suitable period (determined by species and size) prior to lifting or site formation works which affect the existing rootball of trees identified for retention. The extent of the pruning will be based on the size and the species of the tree in each case.	٨
	CP1.5	Pruning of the branches of existing trees identified for transplantation and retention to be based on the principle of crown thinning maintaining their form and amenity value.	^
	CP1.6	The watering of existing vegetation particularly during periods of excavation when the water table beneath the existing vegetation is lowered.	۸
	CP1.7	The rectification and repair of damaged vegetation following the construction phase to it's original condition prior to the commencement of the works or replacement using specimens of the same species, size and form where appropriate to the design intention of the area affected	N/A
	CP1.8	All works affecting the trees identified for retention and transplantation will be carefully monitored. This includes the key stages in the preparation of the trees, the	٨

EIA Ref.	EM&A Ref.	Mitigation Measures	Status
		implementation of protection measures and health monitoring through out the	
		construction period	
	CP1.9	Detailed landscape and tree preservation proposals will be submitted to the relevant	N/A
		government departments for approval under the lease conditions and in accordance	
		with ETWB TCW No. 2/2004 and WB Technical Circular No. 14/2002.	
	CP2.0	The tree preservation works should be implemented by approved Landscape	^
		Contractors and inspected and approved on site by a qualified Landscape Architect.	
		A tree protection specification would be included within the contract documents.	
	CP2.1	Topsoil disturbed during the construction phase should be tested using a standard soil	٨
		testing methodology and where it is found to be worthy of retention stored for re-use.	
	CP2.2	The soil will be stockpiled to a maximum height of 2m and will be either temporarily	٨
		vegetated with hydroseeded grass during construction or covered with a waterproof	
		covering to prevent erosion.	
	CP2.3	The stockpile should be turned over on a regular basis to avoid acidification and the	٨
		degradation of the organic material, and reused after completion. Alternatively, if	
		this is not practicable, it should be considered for use elsewhere, including other	
		projects.	
	CP3.1	Where appropriate to the final design the landscape of these works areas should be	N/A
		restored following the completion of the construction phase.	
	CP3.2	Construction site controls should be enforced including the storage of materials, the	٨
		location and appearance of site accommodation and the careful design of site lighting	
		to prevent light spillage.	
	CP3.3	Screen the works area during the construction phase through the use of decorative	٨
		hoarding along the site boundary facing adjacent VSRs	
	CP4.1	Replanting of disturbed vegetation should be undertaken at the earliest possible stage	٨
		of the construction phase	
	CP4.2	Use of native plant species predominantly in the planting design for the buffer areas.	٨
	CP4.3	The tree planting works should be implemented by approved Landscape Contractors	^

EIA Ref.	EM&A Ref.	Mitigation Measures	Status
		and inspected and approved on site by a qualified Landscape Architect. A tree planting specification would be included within the contract documents	
	CP5.1	The tree transplanting works should be implemented by approved Landscape Contractors and inspected and approved on site by a qualified Landscape Architect. A tree protection / transplanting specification would be included within the contract documents.	۸
	CP5.2	The implementation program should reserve enough time for advance tree transplanting preparation.	۸

Remarks:	EM&A Manual for Stage 1 Works under EP-450/2013/A (App No.: VEP-478/2015) EM&A Manual for Stage 2 Works under EP-501/2015 (App No.: AEP-501/2015)				
	^ Compliance of mitigation measure; X Non-compliance of mitigation measure;				
	N/A Not Applicable at this stage; • Non-compliance but rectified by the contractor;				
	* Recommendation was made during site audit but improved/rectified by the contractor.				

APPENDIX J SUMMARIES OF ENVIRONMENTAL COMPLAINT, WARNING, SUMMON AND NOTIFIATION OF SUCCESSFUL PROSECUTION Agreement No. CE 67/2015 (HY)

Cycle Tracks from Tuen Mun to Sheung Shui – Remaining Works – Design and Construction

 $\label{eq:linear_summary} \textbf{Appendix} \ \textbf{J} - \textbf{Summary} \ \textbf{of} \ \textbf{environmental} \ \textbf{complaint}, \ \textbf{warning}, \ \textbf{summon} \ \textbf{and} \ \textbf{notification} \ \textbf{of} \ \textbf{successful} \ \textbf{prosecution}$

Reporting Month: November 2016

Contract No. YL/2015/01

Cycle Tracks from Tuen Mun to Sheung Shui – Remaining Works

Log Ref.	Location	Received Date	Details of Complaint/warning/summon and prosecution	Investigation/Mitigation Action	Status
N/A	N/A	N/A	N/A	N/A	N/A

Remarks: No environmental complaint/warning/summon and prosecution were received in the reporting period.

APPENDIX K SUMMARY OF WASTE GENERATION AND DISPOSAL RECORDS Sang Hing – Kuly Joint Venture Environmental Management Plan for Contract No. YL/2015/01 Cycle Tracks from Tuen Mun to Sheung Shui – Remaining Works

Name of Department: CEDD

Contract No.:

YL/2015/01

Monthly Summary Waste Flow Table for <u>2016</u> (Year)

			TATAL	y Dummara,	y Traible R	XO YY X SEDI	<u> </u>	to (I cai)			
Month	Actual Quantities of Inert C&D Materials Generated Monthly						Actual Quantities of C&D Wastes Generated Monthly				
	Total Quantity Generated	Hard Rock and Large Broken Concrete	Reused in the Contract	Reused in other Projects	Disposed as Public Fill	Imported Fill*	Metals	Paper/ cardboard packaging	Plastics (see Note 3)	Chemical Waste	Others, e.g. general refuse
	$(in '000m^3)$	(in '000m³)	(in '000m ³)	(in '000m ³)	(in '000m ³)	(in '000m ³)	(in '000 kg)	(in '000kg)	(in '000kg)	(in '000kg)	(in '000m ³)
Jan	-	-	<u></u>	_	-	-	-		_	-	_
Feb	-		.	_	-	-	_	ш	-	-	
Mar	-	-	-	_	_	14	1		_	-	-
Apr	-	-	-	-	-	-		-	_	_	_
May	<u></u>		-	-	-	-	-	_	-	-	_
June	_	-	_	_	-	-		-	-	_	-
Sub-total	_	-	-	_	-	-	-	-	_	-	_
July	-	-	-	_		-	0.01	0.01	0.01	-	0.01
Aug	-	_	-	-	-	-	0.01	0.01	0.01	-	0.01
Sept	0.005	-	_		0.005	I	0.01	0.01	0.01	-	0.06
Oct	_	-	-	-	-	-	0.05	0.05	0.05	-	0.04
Nov	0.35	1	-	-	0.35	-	0.05	0.05	0.05	-	0.05
Dec	-	-	-	-	-	-	-	_	-	_	
Total	0.355	-	-	.	0.005	-	0.13	0.13	0.13	-	0.17

^{*}Remark: Imported Fill not taken into account of Total Quantity Generated

#Revised Figure

Sang Hing – Kuly Joint Venture Environmental Management Plan for Contract No. YL/2015/01 Cycle Tracks from Tuen Mun to Sheung Shui – Remaining Works

	Forecast of Total Quantities of C&D Materials to be Generated from the Contract*											
Total Quantity Generated	Hard Rock and Large Broken Concrete	Reused in the Contract	Reused in other Projects	Disposed as Public Fill	Imported Fill	Metals	Paper/ cardboard packaging	Plastics (see Note 3)	Chemical Waste	Others, e.g. general refuse		
(in '000m ³)	(in '000m ³)	(in '000m ³)	(in '000m ³)	(in '000m ³)	(in '000m ³)	(in '000 kg)		(in '000kg)	(in '000kg)	(in '000m ³)		
5	2	1	1	1	10	3	3	1	1	3		

*Remark: Figure to be revised if necessary

Notes:

- (1) The performance targets are given in ETWB Technical Circular PS Clause 6(14).
- (2) The waste flow table shall also include C&D materials that are specified in the Contract to be imported for use at the Site.
- (3) Plastics refer to plastic bottles/containers, plastic sheets/foam from packaging material
- The Contractor shall also submit the latest forecast of the total amount of C&D materials expected to be generated from the Works, together with a breakdown of the nature where the total amount of C&D materials expected to be generated from the Works is equal to or exceeding 50,000 m3. (ETWB Technical Circular PS Clause 5(4)(b) refers). [Delete Note (4) and the table above on the forecast, where inapplicable].