

**JOB NO.: TCS00694/13** 

AGREEMENT NO. CE 45/2008 (CE) Liantang/Heung Yuen Wai Boundary Control Point and Associated Works

30<sup>th</sup> QUARTERLY ENVIRONMENTAL MONITORING & AUDIT SUMMARY REPORT – (November 2020 to January 2021)

**PREPARED FOR** 

CIVIL ENGINEERING AND DEVELOPMENT DEPARTMENT (CEDD)

# **Quality Index**

Vers

2

| Date         | Reference No.           | Prepared By                              | Certified By                            |
|--------------|-------------------------|--|---|
| 8 March 2021 | TCS00694/13/600/R2611v2 | Anh                                      | Jam                                     |
|              |                         | Nicola Hon<br>(Environmental Consultant) | T.W. Tam<br>(Environmental Team Leader) |

| sion | Date         | Description                  |
|------|--------------|------------------------------|
| 1    | 1 March 2021 | First Submission             |
| 2    | 8 March 2021 | Amended As Per IEC's comment |
|      |              |                              |

This report has been prepared by Action-United Environmental Services & Consulting with all reasonable skill, care and diligence within the terms of the Agreement with the client, incorporating our General Terms and Conditions of Business and taking account of the resources devoted to it by agreement with the client. We disclaim any responsibility to the client and others in respect of any matters outside the scope of the above. This report is confidential to the client and we accept no responsibility of whatsoever nature to third parties to whom this report, or any part thereof, is made known. Any such party relies upon the report at their own risk.



Our ref: 7076192/L27134/AW/MCC/rw

9 March 2021

AECOM 8/F, Grand Central Plaza, Tower 2 138 Shatin Rural Committee Road Shatin, N.T.

#### Attention: Mr Owen NG

By Email & Post

Dear Sir

Agreement No. CE 45/2008 (CE) Liantang/Heung Yuen Wai Boundary Control Point and Associated Works Independent Environmental Checker – Investigation Quarterly EM&A Summary Report (No. 30) – November 2020 to January 2021

With reference to the Quarterly EM&A Report No. 30 for November 2020 to January 2021 (Version 2) certified by the ET Leader and received by us on 8 March 2021, please note that we have no adverse comments on the captioned submission. We herewith verify the captioned submission in accordance with Section 13.4 of the EM&A Manual.

Thank you for your attention and please do not hesitate to contact the undersigned on tel. 3995 8120 or by email to antony.wong@smec.com; or our Mr Arthur CHIU on tel. 3995 8144 or by email to arthur.chiu@smec.com.

Yours faithfully

Antony WONG

Independent Environmental Checker

cc CEDD/BCP ArchSD AECOM Ronald Lu AUES

- Mr LU Pei Yu / Mr Derek LAU
- Ms Becky WAN

Mr Pat LAM / Mr Julian LING

Mr Peter YAM / Mr Justin CHEUNG Mr TW TAM by fax: 3547 1659 by fax: 2804 6805 by email by email by email

SMEC ASIA LIMITED 27/F Ford Glory Plaza, 37-39 Wing Hong Street Cheung Sha Wan, Kowloon, Hong Kong

T +852 3995 8100
F +852 3995 8101

E hongkong@smec.com

W www.smec.com

W WWW.SINCC.CON



# **EXECUTIVE SUMMARY**

- ES.01. This is the **30<sup>th</sup>** Quarterly EM&A Summary Report for the "*Liantang/Heung Yuen Wai Boundary Control Point and Associated Works*" under Environmental Permit No. EP-404/2011/D (hereinafter "the EP"), covering the period from **1 November 2020 to 31 January 2021** (hereinafter "Reporting Period").
- ES.02. In the Reporting Period, the construction works under Liantang/Heung Yuen Wai Boundary Control Point and Associated Works of the Project included Contract 3 and Contract 6. Environmental monitoring activities under the EM&A programme in the Reporting Period are summarized in the following table.

| Environmental                       | Monitoring Poromotors /  | Reportin                            | g Period               |  |
|-------------------------------------|--|-------------------------------------|------------------------|--|
| Aspect                              | Monitoring Parameters /<br>Inspection  | Monitoring Locations /<br>Contracts | <b>Total Occasions</b> |  |
|                                     | 1-hour TSP   | 7(@)                                | 336                    |  |
| Air Quality                         | 24-hour TSP  | 7 (@)                               | 112                    |  |
| Construction<br>Noise               | L <sub>eq(30min)</sub> Daytime   | 8 (~)                               | 104                    |  |
|                                     |  | WM1 & WM1-C,                        | 38 scheduled           |  |
|                                     |  | WM2A & WM2A-Cx                      | 38 scheduled           |  |
| Water Quality                       | Water in-situ measurement  | WM2B & WM2B-C                       | (*) 38 Scheduled       |  |
| water Quanty                        | and/or sampling  | WM3x &WM3-C                         | (*) 38 scheduled       |  |
|                                     |  | WM4, WM4-CA<br>&WM4-CB              | 38 scheduled           |  |
| Ecology                             | <ul> <li>Woodland compensation</li> <li>i) General Health condition of planted species</li> <li>ii) Survival of planted species</li> </ul> | 9 Quadrats and transect             | 1                      |  |
|                                     | Wetland compensation<br>i) Site inspection   | Contract 6                          | 13                     |  |
|                                     |  | Contract 3                          | 13                     |  |
| Joint Site<br>Inspection /<br>Audit | IEC, ET, the Contractor and<br>RE joint site Environmental<br>Inspection and Auditing  | Contract 6                          | 13                     |  |

Note: Extra monitoring day was due to measurement results exceedance

- (\*) During the whole reporting period, water sampling was unable to carry out at WM2B, WM2B-C due to shallow water. Besides, WM3-C was also unable to carry out due to shallow water. (Water depth under 150mm)
- (@) Number of air monitoring location changed to 7 since the partial termination proposal approved by EPD on 9 July 2020.
- (~) Number of noise monitoring location changed to 8 since the partial termination proposal approved by EPD on 9 July 2020.

# **BREACHES OF ACTION/LIMIT LEVELS**

ES.03. In the Reporting Period, no exceedance was recorded for construction noise, air quality and water quality monitoring. The summary of exceedance for the Reporting Period is shown below.

| Engineen an tal         | Manitaning               | Manifaning Astion |   | Event & Action |               | on                    |
|-------------------------|--------------------------|-------------------|---|----------------|---------------|-----------------------|
| Environmental<br>Aspect | Monitoring<br>Parameters | Action<br>Level   |   |                | Investigation | Corrective<br>Actions |
| Ain Quality             | 1-hour TSP               | 0                 | 0 | 0              |               |                       |
| Air Quality             | 24-hour TSP              | 0                 | 0 | 0              |               |                       |

| Environmontal                      | Monitoring                        | g Action | Limit | Event & Action |               |                       |
|------------------------------------|-----------------------------------|----------|-------|----------------|---------------|-----------------------|
| Environmental<br>Aspect Parameters |                                   | Level    |       | NOE<br>Issued  | Investigation | Corrective<br>Actions |
| Construction<br>Noise              | L <sub>eq(30min)</sub><br>Daytime | 0        | 0     | 0              |               |                       |
| Water Quality                      | DO                                | 0        | 0     | 0              |               |                       |
|                                    | Turbidity                         | 0        | 0     | 0              |               |                       |
|                                    | SS                                | 0        | 0     | 0              |               |                       |

ES.04. As the major construction work under Contract 3 and Contract 6 were substantially completed. In view of insignificant environmental impacts of the remaining outstanding construction works of Contracts 3 and 6, "proposal for termination of the Construction Phase Environmental Monitoring & Audit (EM&A) Programme for the remaining Contract 3 and Contract 6 of the Project" which certified by ETL and verified by IEC, was submitted to Environmental Protection Department (EPD) on 18 November 2020. EPD issued comments on 6 January 2021 and the revised proposal has been subsequently prepared and certified by ETL and verified by IEC. The revised proposal was re-submitted by AECOM to EPD with written agreement/confirmation obtained from CEDD on 5 February 2021.

#### **ENVIRONMENTAL COMPLAINT**

ES.05. No environmental complaint was recorded in the Reporting Period.

#### NOTIFICATION OF SUMMONS AND SUCCESSFUL PROSECUTIONS

ES.06. No environmental summons or successful prosecutions were recorded in the Reporting Period.

#### **REPORTING CHANGES**

ES.07. No reporting change was recorded in the Reporting period.

#### **FUTURE KEY ISSUES**

- ES.08. During dry season and in consideration of construction site under the Project are located adjacent to villages, the Contractors should fully implement air quality mitigation measures to reduce construction dust emission.
- ES.09. In addition, all effluent discharge shall be ensure to fulfill Technical Memorandum of Effluent Discharged into Drainage and Sewerage Systems, inland and Coastal Waters criteria or discharge permits stipulation.
- ES.10. Construction noise would be a key environmental issue during construction work of the Project. Noise mitigation measures such as using quiet plants should be implemented in accordance with the EM&A requirement.



# TABLE OF CONTENTS

| 1  | INTRODUCTION   | 1               |
|----|--|-----------------|
|    | 1.1 PROJECT BACKGROUND   | 1               |
|    | 1.2 REPORT STRUCTURE   | 1               |
| 2  | PROJECT ORGANIZATION AND CONSTRUCTION PROGRESS   | 2               |
|    | 2.1 CONSTRUCTION CONTRACT PACKAGING  | 2               |
|    | 2.2 PROJECT ORGANIZATION   | 4               |
|    | 2.3 CONCURRENT PROJECTS  | 6               |
|    | 2.4 CONSTRUCTION PROGRESS  | 6               |
|    | 2.5 SUMMARY OF ENVIRONMENTAL SUBMISSIONS   | 7               |
| 3  | PROJECT ORGANIZATION AND CONSTRUCTION PROGRESS   | 8               |
|    | 3.1 GENERAL  | 8               |
|    | 3.2 MONITORING PARAMETERS  | 8               |
|    | 3.3 MONITORING LOCATIONS   | 8               |
|    | 3.4 MONITORING FREQUENCY AND PERIOD  | 11              |
|    | 3.5 MONITORING EQUIPMENT   | 11              |
|    | 3.6 MONITORING METHODOLOGY   | 13              |
|    | 3.7 EQUIPMENT CALIBRATION  | 15              |
|    | 3.8 DERIVATION OF ACTION/LIMIT (A/L) LEVELS  | 16              |
|    | 3.9 DATA MANAGEMENT AND DATA QA/QC CONTROL   | 16              |
| 4  | AIR QUALITY MONITORING   | 18              |
|    | 4.1 GENERAL  | 18              |
|    | 4.2 SUMMARY OF MONITORING RESULTS  | 18              |
| 5  | CONSTRUCTION NOISE MONITORING  | 20              |
| -  | 5.1 GENERAL  | 20              |
|    | 5.2 SUMMARY OF MONITORING RESULTS  | 20              |
| 6  | WATER QUALITY MONITORING   | 22              |
| U  | 6.1 GENERAL  | 22              |
|    | 6.2 SUMMARY OF MONITORING RESULTS  | $\frac{22}{22}$ |
| 7  | ECOLOGY MONITORING   | 24              |
| ,  | 7.1 MONITORING ON WOODLAND COMPENSATION  | 24              |
|    | 7.2 MONITORING ON WETLAND COMPENSATION   | 24              |
| 0  |  |                 |
| 8  | WASTE MANAGEMENT   | 25<br>25        |
|    | <ul><li>8.1 GENERAL WASTE MANAGEMENT</li><li>8.2 RECORDS OF WASTE QUANTITIES</li></ul> | 25<br>25        |
|    |  |                 |
| 9  | SITE INSPECTIONS   | <b>26</b>       |
|    | 9.1 REQUIREMENTS   | 26              |
| 10 | NON-COMPLIANCE, COMPLAINTS, NOTIFICATIONS OF SUMMONS AND                               |                 |
|    | PROSECUTIONS   | 27              |
|    | 10.1 STATUS OF NON-COMPLIANCE ENVIRONMENTAL COMPLAINT, SUMMON                          |                 |
|    | PROSECUTION  | 27              |
| 11 | IMPLEMENTATION STATUS OF MITIGATION MEASURES   | 29              |
|    | 11.1 GENERAL REQUIREMENTS  | 29              |
| 12 | CONCLUSIONS AND RECOMMENDATIONS  | 31              |
|    | 12.1 CONCLUSIONS   | 31              |
|    | 12.2 RECOMMENDATIONS   | 31              |

# LIST OF TABLES

 TABLE 2-1
 STATUS OF ENVIRONMENTAL LICENSES AND PERMITS OF THE CONTRACTS

 $AII \vdash S$ 

- TABLE 3-1SUMMARY OF EM&A REQUIREMENTS
- TABLE 3-2
   IMPACT MONITORING STATIONS AIR QUALITY
- TABLE 3-3
   IMPACT MONITORING STATIONS CONSTRUCTION NOISE
- TABLE 3-4
   IMPACT MONITORING STATIONS WATER QUALITY
- TABLE 3-5
   AIR QUALITY MONITORING EQUIPMENT
- TABLE 3-6
   CONSTRUCTION NOISE MONITORING EQUIPMENT
- TABLE 3-7
   WATER QUALITY MONITORING EQUIPMENT
- TABLE 3-8
   ACTION AND LIMIT LEVELS FOR AIR QUALITY MONITORING
- TABLE 3-9
   ACTION AND LIMIT LEVELS FOR CONSTRUCTION NOISE
- TABLE 3-10
   ACTION AND LIMIT LEVELS FOR WATER QUALITY
- TABLE 4-1
   SUMMARY OF AIR QUALITY MONITORING RESULTS
- TABLE 4-2SUMMARIES OF BREACHES OF AIR QUALITY A/L LEVELS
- TABLE 5-1
   SUMMARY OF CONSTRUCTION NOISE MONITORING RESULTS
- TABLE 5-2
   SUMMARIES OF BREACHES OF CONSTRUCTION NOISE A/L LEVELS
- TABLE 6-1
   SUMMARY OF THE WATER QUALITY MONITORING RESULTS CONTRACTS 6
- TABLE 6-2
   SUMMARY OF THE WATER QUALITY MONITORING RESULTS CONTRACTS 3
- TABLE 6-3
   SUMMARY OF THE WATER QUALITY MONITORING RESULTS CONTRACT 6
- TABLE 6-4
   SUMMARY OF THE WATER QUALITY MONITORING RESULTS CONTRACTS 6
- TABLE 6-5
   SUMMARIES OF BREACHES OF THE EXISTING WATER QUALITY A/L LEVELS
- TABLE 6-6
   SUMMARY OF WATER QUALITY EXCEEDANCE IN THE REPORTING PERIOD
- TABLE 8-1SUMMARY OF QUANTITIES OF INERT C&D MATERIALS
- TABLE 8-2SUMMARY OF QUANTITIES OF C&D WASTES
- TABLE 9-1
   SUMMARY OF REMINDERS/OBSERVATIONS OF SITE INSPECTION CONTRACT 3
- TABLE 9-2
   SUMMARY OF REMINDERS/OBSERVATIONS OF SITE INSPECTION CONTRACT 6
- TABLE 10-1
   STATISTICAL SUMMARY OF ENVIRONMENTAL COMPLAINTS
- TABLE 10-2
   STATISTICAL SUMMARY OF ENVIRONMENTAL SUMMONS
- TABLE 10-3
   STATISTICAL SUMMARY OF ENVIRONMENTAL PROSECUTION
- TABLE 11-1
   ENVIRONMENTAL MITIGATION MEASURES

# LIST OF ANNEXES

- APPENDIX A LAYOUT PLAN OF THE PROJECT
- APPENDIX B ENVIRONMENTAL MANAGEMENT ORGANIZATION CHART
- APPENDIX C DESIGNATED MONITORING LOCATIONS AS RECOMMENDED IN THE APPROVED EM&A MANUAL
- APPENDIX D MONITORING LOCATIONS FOR IMPACT MONITORING
- APPENDIX E EVENT AND ACTION PLAN
- APPENDIX F GRAPHICAL PLOTS FOR MONITORING RESULT
- APPENDIX G WEATHER INFORMATION
- APPENDIX H WASTE FLOW TABLE
- APPENDIX I IMPLEMENTATION SCHEDULE FOR ENVIRONMENTAL MITIGATION MEASURES
- APPENDIX J IMPLEMENTATION STATUS OF MITIGATION MEASURES FOR OPERATION PHASE

# **1 INTRODUCTION**

# **1.1 PROJECT BACKGROUND**

- 1.1.1. Civil Engineering and Development Department is the Project Proponent and the Permit Holder of *Agreement No. CE 45/2008 (CE) Liantang / Heung Yuen Wai Boundary Control Point and Associated Works*, which is a Designated Project to be implemented under Environmental Permit number EP-404/2011/C granted on 12 March 2015 and the latest Environmental Permit number EP-404/2011/D granted on 20 January 2017.
- 1.1.2. The Project consists of two main components: Construction of a Boundary Control Point (hereinafter referred as "BCP"); and Construction of a connecting road alignment. Layout plan of the Project is shown in *Appendix A*.
- 1.1.3. The proposed BCP is located at the boundary with Shenzhen near the existing Chuk Yuen Village, comprising a main passenger building with passenger and cargo processing facilities and the associated customs, transport and ancillary facilities. The connecting road alignment consists of six main sections:
  - 1) Lin Ma Hang to Frontier Closed Area (FCA) Boundary this section comprises at-grade and viaducts and includes the improvement works at Lin Ma Hang Road;
  - Ping Yeung to Wo Keng Shan this section stretches from the Frontier Closed Area Boundary to the tunnel portal at Cheung Shan and comprises at-grade and viaducts including an interchange at Ping Yeung;
  - 3) North Tunnel this section comprises the tunnel segment at Cheung Shan and includes a ventilation building at the portals on either end of the tunnel;
  - 4) Sha Tau Kok Road this section stretches from the tunnel portal at Wo Keng Shan to the tunnel portal south of Loi Tung and comprises at-grade and viaducts including an interchange at Sha Tau Kok and an administration building;
  - 5) South Tunnel this section comprises a tunnel segment that stretches from Loi Tung to Fanling and includes a ventilation building at the portals on either end of the tunnel as well as a ventilation building in the middle of the tunnel near Lau Shui Heung;
  - 6) Fanling this section comprises the at-grade, viaducts and interchange connection to the existing Fanling Highway.
- 1.1.4. Action-United Environmental Services & Consulting has been commissioned as an Independent ET to implement the relevant EM&A programme in accordance with the approved EM&A Manual, as well as the associated duties.
- 1.1.5. This is the **30<sup>th</sup>** Quarterly EM&A Summary Report presenting the monitoring results and inspection findings for the Reporting Period from **1 November 2020 to 31 January 2021**.

#### **1.2 REPORT STRUCTURE**

- 1.2.1 The Quarterly EM&A Summary Report is structured into the following sections:-
  - *Section 1* Introduction
  - Section 2 Project Organization and Construction progress
  - Section 3 Summary of Impact monitoring Requirements
  - *Section 4* Air Quality Monitoring
  - Section 5 Construction Noise Monitoring
  - Section 6 Water Quality Monitoring
  - Section 7 Ecology Monitoring
  - Section 8 Waste Management
  - *Section 9* Site Inspection
  - Section 10 Non-compliance, Complaints, Notifications of Summons and Prosecutions
  - Section 11 Implementation Status of Mitigation Measures
  - Section 12 Conclusions and Recommendations

# 2 PROJECT ORGANIZATION AND CONSTRUCTION PROGRESS

# 2.1 CONSTRUCTION CONTRACT PACKAGING

- 2.1.1 To facilitate the project management and implementation, the Project would be divided by the following contracts:
  - Contract 2 (CV/2012/08)
  - Contract 3 (CV/2012/09)
  - Contract 4 (NE/2014/02)
  - Contract 5 (CV/2013/03)
  - Contract 6 (CV/2013/08)
  - Contract 7 (NE/2014/03)
  - ArchSD Contract No. SS C505
- 2.1.2 The details of each contracts is summarized below and the delineation of each contracts is shown in *Appendix A*.

# Contract 2 (CV/2012/08)

- 2.1.3 Contract 2 has awarded in December 2013 and construction work was commenced on 19 May 2014. Major Scope of Work of the Contract 2 is listed below:
  - construction of an approximately 5.2km long dual two-lane connecting road (with about 0.4km of at-grade road and 4.8km of tunnel) connecting the Fanling Interchange with the proposed Sha Tau Kok Interchange;
  - construction of a ventilation adit tunnel and the mid-ventilation building;
  - construction of the north and south portal buildings of the Lung Shan Tunnel and their associated slope works;
  - provision and installation of ventilation system, E&M works and building services works for Lung Shan tunnel and Cheung Shan tunnel and their portal buildings;
  - construction of Tunnel Administration Building adjacent to Wo Keng Shan Road and the associated E&M and building services works; and
  - construction of associated footpath, slopes, retaining structures, drainage, sewerage, waterworks, landscaping works and other ancillary works.

#### Contract 3 (CV/2012/09)

- 2.1.4 Contract 3 was awarded in July 2013 and construction work was commenced on 5 November 2013. Major Scope of Work of the Contract 3 is listed below:
  - construction of four link roads connecting the existing Fanling Highway and the south portal of the Lung Shan Tunnel;
  - realignment of the existing Tai Wo Service Road West and Tai Wo Service Road East;
  - widening of the existing Fanling Highway (HyD's entrustment works);
  - demolishing existing Kiu Tau vehicular bridge and Kiu Tau footbridge and reconstruction of the existing Kiu Tau Footbridge (HyD's entrustment works); and
  - construction of associated footpath, slopes, retaining structures, drainage, sewerage, waterworks, landscaping works and other ancillary works.

#### *Contract 4 (NE/2014/02)*

- 2.1.5 Contract 4 was awarded in mid-April 2016 and construction work will be commenced on 2 May 2017. The scope of work of the Contract 4 includes:
  - design, supply, delivery, installation, testing and commissioning of a traffic control and surveillance system for the connecting road linking up the Liantang / Heung Yuen Wai Boundary Control Point and the existing Fanling Highway.

Contract 5 (CV/2013/03)

- 2.1.6 Contract 5 has awarded in April 2013 and construction work was commenced in August 2013. Major Scope of Work of the Contract 5 is listed below:
  - site formation of about 23 hectares of land for the development of the BCP;
  - construction of an approximately 1.6 km long perimeter road at the BCP including a 175m long depressed road;
  - associated diversion/modification works at existing local roads and junctions including Lin Ma Hang Road;
  - construction of pedestrian subway linking the BCP to Lin Ma Hang Road;
  - provision of resite area with supporting infrastructure for reprovisioning of the affected village houses; and
  - construction of associated footpath, slopes, retaining structures, drainage, sewerage, waterworks, landscaping works and other ancillary works.

# Contract 6 (CV/2013/08)

- 2.1.7 Contract 6 was awarded in June 2015 and construction work was commenced on 23 October 2015. Major Scope of Work of the Contract 6 would be included below:
  - construction of an approximately 4.6km long dual two-lane connecting road (with about 0.6km of at-grade road, 3.3km of viaduct and 0.7km of tunnel) connecting the BCP with the proposed Sha Tau Kok Road Interchange and the associated ventilation buildings;
  - associated diversion/modification works at access roads to the resite of Chuk Yuen Village;
  - provision of sewage collection, treatment and disposal facilities for the BCP and the resite of Chuk Yuen Village;
  - construction of a pedestrian subway linking the BCP to Lin Ma Hang Road;
  - provisioning of the affected facilities including Wo Keng Shan Road garden; and
  - construction of associated footpath, slopes, retaining structures, drainage, sewerage, waterworks, landscaping works and other ancillary works.

#### Contract 7 (NE/2014/03)

- 2.1.8 Contract 7 was awarded in December 2015 and the construction work was commenced 15 February 2016. Major Scope of Work of the Contract 7 would be included below:
  - construction of the Hong Kong Special Administrative Region (HKSAR) portion of four vehicular bridge
  - construction of one pedestrian bridge crossing Shenzhen (SZ) River (cross boundary bridges)

# ArchSD Contract No. SS C505

- 2.1.9 SS C505 has been awarded in July 2015 and construction work was commenced on 1 September 2015. Major Scope of Work of the SS C505 would be included below:
  - passenger-related facilities including processing kiosks and examination facilities for private cars and coaches, passenger clearance building and halls, the interior fitting works for the pedestrian bridge crossing Shenzhen River, etc.;
  - cargo processing facilities including kiosks for clearance of goods vehicles, customs inspection platforms, X-ray building, etc.;
  - accommodation for the facilities inside of the Government departments providing services in connection with the BCP;
  - transport-related facilities inside the BCP including road networks, public transport interchange, transport drop-off and pick-up areas, vehicle holding areas and associated road furniture etc;
  - a public carpark; and
  - other ancillary facilities such as sewerage and drainage, building services provisions and electronic systems, associated environmental mitigation measure and landscape works.

#### **2.2 PROJECT ORGANIZATION**

2.2.1 The project organization is shown in *Appendix B*. The responsibilities of respective parties are:

#### *Civil Engineering and Development Department (CEDD)*

2.2.2 CEDD is the Project Proponent and the Permit Holder of the EP of the development of the Project and will assume overall responsibility for the project. An Independent Environmental Checker (IEC) shall be employed by CEDD to audit the results of the EM&A works carried out by the ET.

#### Architectural Services Department (ArchSD)

2.2.3 ArchSD acts as the works agent for Development Bureau (DEVB), for Contract SS C505 Liantang/ Heung Yuen Wai Boundary Control Point (BCP) – BCP Buildings and Associated Facilities.

#### Environmental Protection Department (EPD)

2.2.4 EPD is the statutory enforcement body for environmental protection matters in Hong Kong.

#### Ronald Lu & Partners (Hong Kong) Ltd (The Architect)

- 2.2.5 Ronald Lu & Partners (Hong Kong) Ltd is appointed by ArchSD as an Architect for Contract SS C505 Liantang/ Heung Yuen Wai Boundary Control Point (BCP) BCP Buildings and Associated Facilities. It responsible for overseeing the construction works of Contract SS C505 and for ensuring that the works are undertaken by the Contractor in accordance with the specification and contract requirements. The duties and responsibilities of the Architect with respect to EM&A are:
  - Monitor the Contractors' compliance with contract specifications, including the implementation and operation of the environmental mitigation measures and their effectiveness
  - Monitor Contractors' and ET's compliance with the requirements in the Environmental Permit (EP) and EM&A Manual
  - Facilitate ET's implementation of the EM&A programme
  - Participate in joint site inspection by the ET and IEC
  - Oversee the implementation of the agreed Event / Action Plan in the event of any exceedance
  - Adhere to the procedures for carrying out complaint investigation
  - Liaison with DSD, Engineer/Engineer's Representative, ET, IEC and the Contractor of the "Construction of the DSD's Regulation of Shenzhen River Stage 4 (RSR 4)" Project discussing regarding the cumulative impact issues.

#### Engineer or Engineers Representative (ER)

- 2.2.6 The ER is responsible for overseeing the construction works and for ensuring that the works are undertaken by the Contractor in accordance with the specification and contract requirements. The duties and responsibilities of the ER with respect to EM&A are:
  - Monitor the Contractors' compliance with contract specifications, including the implementation and operation of the environmental mitigation measures and their effectiveness
  - Monitor Contractors's, ET's and IEC's compliance with the requirements in the Environmental Permit (EP) and EM&A Manual
  - Facilitate ET's implementation of the EM&A programme
  - Participate in joint site inspection by the ET and IEC
  - Oversee the implementation of the agreed Event / Action Plan in the event of any exceedance
  - Adhere to the procedures for carrying out complaint investigation

• Liaison with DSD, Engineer/Engineer's Representative, ET, IEC and the Contractor of the "Construction of the DSD's Regulation of Shenzhen River Stage 4 (RSR 4)" Project discussing regarding the cumulative impact issues.

# The Contractor(s)

- 2.2.7 There will be one contractor for each individual works contract. The Contractor(s) should report to the ER. The duties and responsibilities of the Contractor are:
  - Comply with the relevant contract conditions and specifications on environmental protection
  - Employ an Environmental Team (ET) to undertake monitoring, laboratory analysis and reporting of EM &A Facilitate ET's monitoring and site inspection activities
  - Participate in the site inspections by the ET and IEC, and undertake any corrective actions
  - Provide information / advice to the ET regarding works programme and activities which may contribute to the generation of adverse environmental impacts
  - Submit proposals on mitigation measures in case of exceedances of Action and Limit levels in accordance with the Event / Action Plans
  - Implement measures to reduce impact where Action and Limit levels are exceeded
  - Adhere to the procedures for carrying out complaint investigation

# Environmental Team (ET)

- 2.2.8 One ET will be employed for this Project. The ET shall not be in any way an associated body of the Contractor(s), and shall be employed by the Project Proponent/Contractor to conduct the EM&A programme. The ET should be managed by the ET Leader. The ET Leader shall be a person who has at least 7 years' experience in EM&A and has relevant professional qualifications. Suitably qualified staff should be included in the ET, and resources for the implementation of the EM&A programme should be allocated in time under the Contract(s), to enable fulfillment of the Project's EM&A requirements as specified in the EM&A Manual during construction of the Project. The ET shall report to the Project Proponent and the duties shall include:
  - Monitor and audit various environmental parameters as required in this EM&A Manual
  - Analyse the environmental monitoring and audit data, review the success of EM&A programme and the adequacy of mitigation measures implemented, confirm the validity of the EIA predictions and identify any adverse environmental impacts arising
  - Carry out regular site inspection to investigate and audit the Contractors' site practice, equipment/plant and work methodologies with respect to pollution control and environmental mitigation, and effect proactive action to pre-empt problems
  - Monitor compliance with conditions in the EP, environmental protection, pollution prevention and control regulations and contract specifications
  - Audit environmental conditions on site
  - Report on the environmental monitoring and audit results to EPD, the ER, the IEC and Contractor(s) or their delegated representatives
  - Recommend suitable mitigation measures to the Contractor in the case of exceedance of Action and Limit levels in accordance with the Event and Action Plans
  - Liaise with the IEC on all environmental performance matters and timely submit all relevant EM&A proforma for approval by IEC
  - Advise the Contractor(s) on environmental improvement, awareness, enhancement measures etc., on site
  - Adhere to the procedures for carrying out complaint investigation
  - Liaison with the client departments, Engineer/Engineer's Representative, ET, IEC and the Contractor(s) of the concurrent projects as listed under Section 2.3 below regarding the cumulative impact issues.

Independent Environmental Checker (IEC)

- 2.2.9 One IEC will be employed for this Project. The Independent Environmental Checker (IEC) should not be in any way an associated body of the Contractor(s) or the ET for the Project. The IEC should be employed by the Permit Holder (i.e., CEDD) prior to the commencement of the construction of the Project. The IEC should have at least 10 years' experience in EM&A and have relevant professional qualifications. The duty of IEC should be:
  - Provide proactive advice to the ER and the Project Proponent on EM&A matters related to the project, independent from the management of construction works, but empowered to audit the environmental performance of construction
  - Review and audit all aspects of the EM&A programme implemented by the ET
  - Review and verify the monitoring data and all submissions in connection with the EP and EM&A Manual submitted by the ET
  - Arrange and conduct regular, at least monthly site inspections of the works during construction phase, and ad hoc inspections if significant environmental problems are identified
  - Check compliance with the agreed Event / Action Plan in the event of any exceedance
  - Check compliance with the procedures for carrying out complaint investigation
  - Check the effectiveness of corrective measures
  - Feedback audit results to ET by signing off relevant EM&A proforma
  - Check that the mitigation measures are effectively implemented
  - Report the works conducted, the findings, recommendation and improvement of the site inspections, after reviewing ET's and Contractor's works, and advices to the ER and Project Proponent on a monthly basis
  - Liaison with the client departments, Engineer/Engineer's Representative, ET, IEC and the Contractor(s) of the concurrent projects as listed under Section 2.3 below regarding the cumulative impact issues.

#### **2.3 CONCURRENT PROJECTS**

- 2.3.1 The concurrent construction works that may be carried out include, but not limited to, the following:
  - (a) Regulation of Shenzhen River Stage IV;
  - (b) Widening of Fanling Highway Tai Hang to Wo Hop Shek Interchange Contract No. HY/2012/06;
  - (c) Construction of BCP facilities in Shenzhen.

#### **2.4 CONSTRUCTION PROGRESS**

2.4.1 In the Reporting Period, the major construction activity conducted under the Project is located in Contracts 3 and 6 and they are summarized in below.

# Contract 3 (CV/2012/09)

- 2.4.2 Contract commenced in November 2013, the following activities were conducted in the Reporting Period.
  - Laying of rising mains

#### Contract 6 (CV/2013/08)

- 2.4.3 Contract 6 has awarded in June 2015 and construction work was commenced on 23 October 2015. In this Reporting Period, construction activities conducted are listed below:
  - Water Pipe Connection Work
  - Road Construction
  - Landscaping
  - Implementation of Wetland



#### 2.5 SUMMARY OF ENVIRONMENTAL SUBMISSIONS

- 2.5.1 In according to the EP, the required documents have submitted to EPD which listed in below:
  - Project Layout Plans of Contracts 2, 3, 4, 5, 6, 7 and SS C505
  - Landscape Plan
  - Topsoil Management Plan
  - Environmental Monitoring and Audit Programme
  - Baseline Monitoring Report (TCS00690/13/600/R0030v3) for the Project
  - Waste Management Plan of the Contracts 2, 3, 4, 5, 6, 7 and SS C505
  - Contamination Assessment Plan (CAP) and Contamination Assessment Report (CAR) for Po Kat Tsai, Loi Tung and the workshops in Fanling
  - Vegetation Survey Report
  - Woodland Compensation Plan
  - Habitat Creation Management Plan
  - Wetland Compensation Plan
- 2.5.2 Summary of the relevant permits, licenses, and/or notifications on environmental protection for the Project of each contracts are presented in *Table 2-1*.

# Table 2-1 Status of Environmental Licenses and Permits of the Contracts

| Item | Description   | License/   |                |                             |  |  |  |  |
|------|---|--|----------------|-----------------------------|--|--|--|--|
| Item | Description   | Ref. no.   | Effective Date | Expiry Date                 |  |  |  |  |
|      | Contract 3  |  |                |                             |  |  |  |  |
| 1    | Air pollution Control<br>(Construction Dust)<br>Regulation                              | Ref. No: 362101                                  | 17 Jul 2013    | Till Contract<br>ends       |  |  |  |  |
| 2    | Chemical Waste Producer<br>Registration   | Waste Producers Number:<br>No.:5113-634-C3817-01 | 7 Oct 2013     | Till Contract<br>ends       |  |  |  |  |
| 3    | Water Pollution Control<br>Ordinance - Discharge<br>License                             | No.:WT00032188 – 2018                            | 20 Sep 2018    | 31 Aug 2023                 |  |  |  |  |
| 4    | Waste Disposal<br>Regulation - Billing<br>Account for Disposal of<br>Construction Waste | Account No. 7017914                              | 2 Aug 13       | Till Contract<br>ends       |  |  |  |  |
|      |   | Contract 6                                       |                |                             |  |  |  |  |
| 1    | Air pollution Control<br>(Construction Dust)<br>Regulation                              | Ref. No: 390614                                  | 29 Jun 2015    | Till the end of<br>Contract |  |  |  |  |
| 2    | Chemical Waste Producer<br>Registration   | Waste Producers Number No.: 5213-652-C3969-01    | 31 Aug 2015    | Till the end of<br>Contract |  |  |  |  |
| 3    | Waste Disposal<br>Regulation - Billing<br>Account for Disposal of<br>Construction Waste | Account No. 7022707                              | 9 Jul 2015     | Till the end of<br>Contract |  |  |  |  |
| 4    | Water Pollution Control   | No.:WT00024574-2016                              | 31 May 2016    | 31 May 2021                 |  |  |  |  |
|      | Ordinance - Discharge<br>License  | No.:WT00024576-2016                              | 31 May 2016    | 31 May 2021                 |  |  |  |  |
|      |   | No.:WT00024742-2016                              | 14 June 2016   | 30 June 2021                |  |  |  |  |
|      |   | No.:WT00024746-2016                              | 14 June 2016   | 30 June 2021                |  |  |  |  |

# **3 PROJECT ORGANIZATION AND CONSTRUCTION PROGRESS**

# **3.1 GENERAL**

- 3.1.1 The Environmental Monitoring and Audit requirements are set out in the Approved EM&A manual. Environmental issues such as air quality, construction noise and water quality were identified as the key issues during the construction phase of the Project.
- 3.1.2 A summary of construction phase EM&A requirements are presented in the sub-sections below.

# **3.2 MONITORING PARAMETERS**

- 3.2.1 The EM&A program of construction phase monitoring shall cover the following environmental issues:
  - Air quality;
  - Construction noise; and
  - Water quality
- 3.2.2 A summary of the monitoring parameters is presented in *Table 3-1*.

Table 3-1Summary of EM&A Requirements

| <b>Environmental Issue</b> | Parameters   |
|----------------------------|--|
| Air Quality                | 1-hour TSP by Real-Time Portable Dust Meter; and                         |
|                            | • 24-hour TSP by High Volume Air Sampler.                                |
|                            | • L <sub>eq(30min)</sub> in normal working days (Monday to Saturday)     |
|                            | 07:00-19:00 except public holiday; and                                   |
| Noise                      | • 3 sets of consecutive $L_{eq(5min)}$ on restricted hours i.e. 19:00 to |
| 110150                     | 07:00 next day, and whole day of public holiday or Sunday                |
|                            | • Supplementary information for data auditing, statistical results       |
|                            | such as $L_{10}$ and $L_{90}$ shall also be obtained for reference.      |
|                            | In-situ Measurements   |
|                            | • Dissolved Oxygen Concentration (mg/L);                                 |
|                            | • Dissolved Oxygen Saturation (%);                                       |
|                            | • Turbidity (NTU);   |
| Water Quality              | • pH unit;   |
|                            | • Water depth (m); and   |
|                            | • Temperature (°C).  |
|                            | Laboratory Analysis  |
|                            | • Suspended Solids (mg/L)  |

#### **3.3 MONITORING LOCATIONS**

- 3.3.1 The designated monitoring locations as recommended in the *EM&A Manual* are shown in *Appendix C*. As the access to some of the designated monitoring locations was questionable due to safety reason or denied by the landlords, alternative locations therefore have had proposed. The latest alternative monitoring locations has been updated in the revised EM&A Programme (Rev.7) which approved by EPD on 7 April 2017. Besides, in view of Location AM1b was demolished and returned to the landlord on 27 April 2018, alterative location AM1c was proposed by ET and approved by EPD on 26 November 2018. *Table 3-2, Table 3-3* and *Table 3-4* are respectively listed the air quality, construction noise and water quality monitoring locations for the Project and a map showing these monitoring stations is presented in *Appendix D*.
- 3.3.2 Following the proposal for partial termination of the construction phase EM&A programme for Contract 2, 4, 7 and SSC505 approved by EPD on 9 July 2020. The corresponding air quality monitoring stations including AM1c and AM8 were ceased after last monitoring carried out on 7 July 2020 and 10 July 2020 respectively. Besides, the corresponding noise monitoring stations including NM1 and NM7 were ceased after last monitoring carried out on 7 July 2020 and 10

Contract 6

Contract 2 Contract 2

Contract 3

Contract 3

July 2020 respectively.

| Station ID        | Description                            | Works Area      | Related to the<br>Work Contract |
|-------------------|--|-----------------|---------------------------------|
| AM1c(*)           | Open area of Tsung Yuen Ha Village No. | BCP             | SS C505                         |
| (\$)              | 63                                     |                 | Contract 7                      |
| AM2               | Village House near Lin Ma Hang Road    | LMH to Frontier | Contract 6                      |
|                   |  | Closed Area     |                                 |
| AM3               | Ta Kwu Ling Fire Service Station of Ta | LMH to Frontier | Contract 6                      |
|                   | Kwu Ling Village.                      | Closed Area     |                                 |
| AM4b^             | House no. 10B1 Nga Yiu Ha Village      | LMH to Frontier | Contract 6                      |
|                   |  | Closed Area     |                                 |
| AM5a^             | Ping Yeung Village House               | Ping Yeung to   | Contract 6                      |
|                   |  | Wo Keng Shan    |                                 |
| AM6               | Wo Keng Shan Village House             | Ping Yeung to   | Contract 6                      |
|                   |  | Wo Keng Shan    |                                 |
| AM7b <sup>@</sup> | Loi Tung Village House                 | Sha Tau Kok     | Contract 2                      |
|                   |  | Road            | Contract 6                      |
| AM8(\$)           | Po Kat Tsai Village No. 4              | Po Kat Tsai     | Contract 2                      |
| AM9b#             | Nam Wa Po Village House No. 80         | Fanling         | Contract 3                      |

Table 3\_2 **Impact Monitoring Stations - Air Quality** 

# Proposal for the change of air quality monitoring location from AM9a to AM9b was submitted to EPD on 4 Nov 2013 after verified by the IEC and it was approved by EPD (EPD's ref.: (15) in EP 2/N7/A/52 Pt.10 dated 8 Nov 2013).

(a) Proposal for the change of air quality monitoring location from AM7a to AM7b was submitted to EPD on 4 June 2014 after verified by the IEC. It was approved by EPD (EPD's ref.: (7) in EP 2/N7/A/52 Pt.12 dated 9 Jun 2014).

^ Proposal for change of air quality monitoring locations was enclosed in the updated EM&A Programme which approval by EPD on 29 Mar 2016. Besides, Location AM1b was temporary suspended (24-hour TSP monitoring) since 27 April 2018 as the rented land was demolished and returned to the landlord.

\* Revised proposal for alterative location AMIc was submitted to EPD on 31 October 2018 after verified by the IEC and it was approved by EPD (EPD's ref.: () in Ax(1) to EP 2/N7/A/52 Pt.26 dated 26 November 2018)

\$ Am1c and AM8 were ceased after last monitoring carried out on 7 July 2020 and 10 July 2020 respectively according to Partial Termination Proposal approved by EPD on 9 July 2020.

| Station<br>ID | Description  | Works Area                             | Related to the<br>Work Contract |
|---------------|--|--|---------------------------------|
| NM1(\$)       | Tsung Yuen Ha Village House No. 63                 | ВСР                                    | SS C505<br>Contract 7           |
| NM2a#         | Village House near Lin Ma Hang<br>Road             | Lin Ma Hang to<br>Frontier Closed Area | Contract 6                      |
| NM3           | Ping Yeung Village House (facade facing northeast) | Ping Yeung to Wo<br>Keng Shan          | Contract 6                      |
| NM4           | Wo Keng Shan Village House                         | Ping Yeung to Wo<br>Keng Shan          | Contract 6                      |
| NM5           | Village House, Loi Tung                            | Sha Tau Kok Road                       | Contract 2,<br>Contract 6       |
| NM6           | Tai Tong Wu Village House 2                        | Sha Tau Kok Road                       | Contract 2,                     |

Sha Tau Kok Road

Po Kat Tsai

Fanling

Fanling

Table 3-3 **Impact Monitoring Stations - Construction Noise** 

Z:\Jobs\2013\TCS00694\600\EM&A Report\Quarterly EM&A Report\30th Quarter\R2611v2.docx Action-United Environmental Services and Consulting

Po Kat Tsai Village

NM6

NM7(\$)

NM8

NM9

Tai Tong Wu Village House 2

Village House, Tong Hang

Village House, Kiu Tau Village

# Proposal for the change of construction noise monitoring location from NM2 to NM2a was verified by the IEC on 6 May 2016 and was effective on 9 May 2016.

*\$ NM1 and NM7 were ceased after last monitoring carried out on 7 July 2020 and 10 July 2020 respectively according to Partial Termination Proposal approved by EPD on 9 July 2020.* 

| Table 3-4 | Impact Monitoring Stations - Water Quality |
|-----------|--|
|-----------|--|

| Station ID     | Description                          | Coordinates of<br>Designated /<br>Alternative Location |         | Nature of the location   | Related to<br>the Work<br>Contract |
|----------------|--------------------------------------|--|---------|--|------------------------------------|
| WM1            | Downstream of<br>Kong Yiu<br>Channel | 833 679  | 845 421 | Alternative location located at<br>upstream 51m of the<br>designated location    | Contract 6                         |
| WM1- Control   | Upstream of<br>Kong Yiu<br>Channel   | 834 185  | 845 917 | NA   | Contract 6                         |
| WM2A           | Downstream of<br>River Ganges        | 834 204  | 844 471 | Alternative location located at<br>downstream 81m of the<br>designated location  | Contract 6                         |
| WM2A(a)*       | Downstream of<br>River Ganges        | 834 191  | 844 474 | Alternative location located at<br>upstream 70m of the<br>designated location    | Contract 6                         |
| WM2A- Control# | Upstream of<br>River Ganges          | 835 377  | 844 188 | Alternative location located at<br>upstream 160m of the<br>designated location   | Contract 6                         |
| WM2B           | Downstream of<br>River Ganges        | 835 433  | 843 397 | NA   | Contract 6                         |
| WM2B- Control  | Upstream of<br>River Ganges          | 835 835  | 843 351 | Alternative location located at<br>downstream 31m of the<br>designated location  | Contract 6                         |
| WM3x#          | Downstream of<br>River Indus         | 836 206  | 842 270 | Alternative location located at<br>downstream 180m of the<br>designated location | Contract 6                         |
| WM3- Control   | Upstream of<br>River Indus           | 836 763  | 842 400 | Alternative location located at<br>downstream 26m of the<br>designated location  | Contract 6                         |
| WM4            | Downstream of<br>Ma Wat Channel      | 833 850  | 838 338 | Alternative location located at<br>upstream 11m of the<br>designated location    | Contract 3                         |
| WM4– Control A | Kau Lung Hang<br>Stream              | 834 028  | 837 695 | Alternative location located at<br>downstream 28m of the<br>designated location  | Contract 3                         |
| WM4– Control B | Upstream of Ma<br>Wat Channel        | 833760   | 837395  | Alternative location located at<br>upstream 15m of the<br>designated location    | Contract 3                         |

Note: EPD has approved the revised EM&A Programme (Rev.7) which proposed that (1) if the measured water depth of the monitoring station is lower than 150 mm, alternative location based on the criteria were selected to perform water monitoring; and (2) If no suitable alternative location could be found within 15m far from the original location, the sampling at that location will be cancelled since sampling at too far from the designated location could not make a representative sample in accordance with the updated EM&A Programme (Rev. 07) (Section 4.1.4) (EPD ref.: () in EP2/N7/A/52 Ax(1) Pt.20 dated 7 April 2017)

(\*) Proposal for the change of water monitoring location from WM2A to WM2A(a) was verified by the IEC and it was approved by EPD. (EPD's ref. (10) in EP 2/N7/A/52 Pt.19)

(#) Proposal for the change of water quality monitoring location (WM3x and WM2A-C was included in the EM&A Programme Rev .05 which approved by EPD on 29 March 2016 (EPD ref.: (3) in EP2/N7/A/52 Ax(1) Pt.19)

# 3.4 MONITORING FREQUENCY AND PERIOD

3.4.1 The requirements of impact monitoring are stipulated in *Sections 2.1.6, 3.1.5* and *4.1.6* of the approved *EM&A Manual* and presented as follows.

# <u>Air Quality Monitoring</u>

- 3.4.2 Frequency of impact air quality monitoring is as follows:
  - 1-hour TSP 3 times every six days during course of works
  - 24-hour TSP Once every 6 days during course of works.

#### Noise Monitoring

3.4.3 One set of  $L_{eq(30min)}$  as 6 consecutive  $L_{eq(5min)}$  between 0700-1900 hours on normal weekdays and once every week during course of works. If construction work necessary to carry out at other time periods, i.e. restricted time period (19:00 to 07:00 the next morning and whole day on public holidays) (hereinafter referred as "the restricted hours"), 3 consecutive  $L_{eq(5min)}$  measurement will depended CNP requirements to undertake. Supplementary information for data auditing, statistical results such as  $L_{10}$  and  $L_{90}$  shall also be obtained for reference.

# Water Quality Monitoring

3.4.4 The water quality monitoring frequency shall be 3 days per week during course of works. The interval between two sets of monitoring shall not be less than 36 hours.

# 3.5 MONITORING EQUIPMENT

# Air Quality Monitoring

- 3.5.1 The 24-hour and 1-hour TSP levels shall be measured by following the standard high volume sampling method as set out in the Title 40 of the Code of Federal Regulations, Chapter 1 *(Part 50), Appendix B.* If the ET proposes to use a direct reading dust meter to measure 1-hour TSP levels, it shall submit sufficient information to the IEC to approve.
- 3.5.2 The filter paper of 24-hour TSP measurement shall be determined by HOKLAS accredited laboratory.
- 3.5.3 All equipment to be used for air quality monitoring is listed in *Table 3-5*.

| Equipment               | Model  |  |  |
|-------------------------|--|--|--|
| 24-Hour TSP             |  |  |  |
| High Volume Air Sampler | TISCH High Volume Air Sampler, HVS Model TE-5170                 |  |  |
| Calibration Kit         | TISCH Model TE-5025A   |  |  |
| 1-Hour TSP              |  |  |  |
| Portable Dust Meter     | Sibata LD-3B Laser Dust monitor Particle Mass Profiler & Counter |  |  |

Table 3-5Air Quality Monitoring Equipment

# Wind Data Monitoring Equipment

- 3.5.4 According to the approved EM&A Manual, wind data monitoring equipment shall also be provided and set up for logging wind speed and wind direction near the dust monitoring locations. The equipment installation location shall be proposed by the ET and agreed with the IEC. For installation and operation of wind data monitoring equipment, the following points shall be observed:
  - 1) The wind sensors should be installed 10 m above ground so that they are clear of obstructions or turbulence caused by buildings.
  - 2) The wind data should be captured by a data logger. The data shall be downloaded for analysis at least once a month.
  - 3) The wind data monitoring equipment should be re-calibrated at least once every six months.
  - 4) Wind direction should be divided into 16 sectors of 22.5 degrees each.

- 3.5.5 ET has liaised with the landlords of the successful granted HVS installation premises. However, the owners rejected to provide premises for wind data monitoring equipment installation.
- 3.5.6 Under this situation, the ET proposed alternative methods to obtain representative wind data. Meteorological information as extracted from "the Hong Kong Observatory Ta Kwu Ling Station" is alternative method to obtain representative wind data. For Ta Kwu Ling Station, it is located nearby the Project site. Moreover, this station is located at 15m above mean sea level while its anemometer is located at 13m above the existing ground which in compliance with the general setting up requirement. Furthermore, this station also can be to provide the humidity, rainfall, and air pressure and temperature etc. meteorological information. In Hong Kong of a lot development projects, weather information extracted from Hong Kong Observatory is common alternative method if weather station installation not allowed.

# Noise Monitoring

- Sound level meter in compliance with the International Electrotechnical Commission 3.5.7 Publications 651: 1979 (Type 1) and 804: 1985 (Type 1) specifications shall be used for carrying out the noise monitoring. The sound level meter shall be checked using an acoustic calibrator. The wind speed shall be checked with a portable wind speed meter capable of measuring the wind speed in m s-1.
- 3.5.8 Noise monitoring equipment to be used for monitoring is listed in *Table 3-6*.

| Table | 3-6 |  |
|-------|-----|--|
| Lanc  |     |  |

#### **Construction Noise Monitoring Equipment**

| Equipment                     | Model              |
|-------------------------------|--------------------|
| Integrating Sound Level Meter | Rion NL-52         |
| Calibrator                    | Rion NC-73 & NC-75 |
| Portable Wind Speed Indicator | Testo Anemometer   |

3.5.9 Sound level meters listed above comply with the International Electrotechnical Commission Publications 651: 1979 (Type 1) and 804: 1985 (Type 1) specifications, as recommended in TM issued under the NCO. The acoustic calibrator and sound level meter to be used in the impact monitoring will be calibrated yearly.

# Water Quality Monitoring

- 3.5.10 DO and water temperature should be measured in-situ by a DO/temperature meter. The instrument should be portable and weatherproof using a DC power source. It should have a membrane electrode with automatic temperature compensation complete with a cable. The equipment should be capable of measuring:
  - DO level in the range of 0-20 mg/l and 0-200% saturation; and
  - temperature of between 0 and 45 degree Celsius.
- 3.5.11 A portable pH meter capable of measuring a range between 0.0 and 14.0 should be provided to measure pH under the specified conditions accordingly to the APHA Standard Methods.
- 3.5.12 The instrument should be portable and weatherproof using a DC power source. It should have a photoelectric sensor capable of measuring turbidity between 0-1000 NTU.
- 3.5.13 A portable, battery-operated echo sounder or tape measure will be used for the determination of water depth at each designated monitoring station as appropriate.
- 3.5.14 A water sampler e.g. Kahlsico Water Sampler, which is a transparent PVC cylinder with capacity not less than 2 litres, will be used for water sampling if water depth over than 0.5m. For sampling from very shallow water depths e.g. <0.5 m, water sample collection will be directly from water surface below 100mm use sampling plastic bottle to avoid inclusion of bottom sediment or humus. Moreover, Teflon/stainless steel bailer or self-made sampling buckets

maybe used for water sampling. The equipment used for sampling will be depended the sampling location and depth situations.

- 3.5.15 Water samples for laboratory measurement of SS will be collected in high density polythene bottles, packed in ice (cooled to 4 °C without being frozen), and delivered to the laboratory in the same day as the samples were collected.
- 3.5.16 Analysis of suspended solids should be carried out in a HOKLAS or other accredited laboratory. Water samples of about 1L should be collected at the monitoring stations for carrying out the laboratory suspended solids determination. The SS determination work should start within 24 hours after collection of the water samples. The SS analyses should follow the *APHA Standard Methods 2540D* with Limit of Reporting of 2 mg/L.
- 3.5.17 Water quality monitoring equipment used in the impact monitoring is listed in *Table 3-7*. Suspended solids (SS) analysis is carried out by a local HOKLAS-accredited laboratory, namely *ALS Technichem (HK) Pty Ltd*.

| Equipment            | Model  |
|----------------------|--|
| Water Depth Detector | Eagle Sonar or tape measures                                       |
| Water Sampler        | A 2-litre transparent PVC cylinder with latex cups at both ends or |
|                      | teflon/stainless steel bailer or self-made sampling bucket         |
| Thermometer & DO     | YSI Professional Plus /YSI PRO20 Handheld Dissolved Oxygen         |
| meter                | Instrument/ YSI 550A Multifunctional Meter/ YSI Professional       |
|                      | DSS  |
| pH meter             | YSI Professional Plus / AZ8685 pH pen-style meter/ YSI 6820/       |
|                      | 650MDS/ YSI Professional DSS                                       |
| Turbidimeter         | Hach 2100Q/ YSI 6820/ 650MDS/ YSI Professional DSS                 |
| Sample Container     | High density polythene bottles (provided by laboratory)            |
| Storage Container    | 'Willow' 33-liter plastic cool box with Ice pad                    |

Table 3-7Water Quality Monitoring Equipment

# **3.6** MONITORING METHODOLOGY

# <u>1-hour TSP Monitoring</u>

- 3.6.1 The 1-hour TSP monitor was a brand named "Sibata LD-3B Laser Dust monitor Particle Mass Profiler & Counter" which is a portable, battery-operated laser photometer. The 1-hour TSP meter provides a real time 1-hour TSP measurement based on 90° light scattering. The 1-hour TSP monitor consists of the following:
  - (a.) A pump to draw sample aerosol through the optic chamber where TSP is measured;
  - (b.) A sheath air system to isolate the aerosol in the chamber to keep the optics clean for maximum reliability; and
  - (c.) A built-in data logger compatible with Windows based program to facilitate data collection, analysis and reporting.
- 3.6.2 The 1-hour TSP meter is used within the valid period as follow manufacturer's Operation and Service Manual.

# 24-hour TSP Monitoring

- 3.6.3 The equipment used for 24-hour TSP measurement is Tisch Environmental, Inc. Model TE-5170 TSP high volume air sampling system, which complied with *EPA Code of Federal Regulation*, *Appendix B to Part 50*. The High Volume Air Sampler (HVS) consists of the following:
  - (a.) An anodized aluminum shelter;
  - (b.) A 8"x10" stainless steel filter holder;
  - (c.) A blower motor assembly;
  - (d.) A continuous flow/pressure recorder;

- (e.) A motor speed-voltage control/elapsed time indicator;
- (f.) A 7-day mechanical timer, and
- (g.) A power supply of 220v/50 Hz
- 3.6.4 The HVS is operated and calibrated on a regular basis in accordance with the manufacturer's instruction using Tisch Calibration Kit Model TE-5025A. Calibration would carry out in two month interval.
- 3.6.5 24-hour TSP is collected by the ET on filters of HVS and quantified by a local HOKLAS accredited laboratory, ALS Technichem (HK) Pty Ltd (ALS), upon receipt of the samples. The ET keep all the sampled 24-hour TSP filters in normal air conditioned room conditions, i.e. 70% RH (Relative Humidity) and 25°C, for six months prior to disposal.

# Noise Monitoring

- 3.6.6 Noise measurements were taken in terms of the A-weighted equivalent sound pressure level ( $L_{eq}$ ) measured in decibels dB(A). Supplementary statistical results ( $L_{10}$  and  $L_{90}$ ) were also obtained for reference.
- 3.6.7 During the monitoring, all noise measurements were performed with the meter set to FAST response and on the A-weighted equivalent continuous sound pressure level ( $L_{eq}$ ). Leq<sub>(30min)</sub> in six consecutive Leq<sub>(5min)</sub> measurements were used as the monitoring parameter for the time period between 0700-1900 hours on weekdays; and also Leq<sub>(15min)</sub> in three consecutive Leq<sub>(5min)</sub> measurements is used as monitoring parameter for other time periods (e.g. during restricted hours), if necessary.
- 3.6.8 Prior of noise measurement, the accuracy of the sound level meter is checked using an acoustic calibrator generating a known sound pressure level at a known frequency. The checking was performed before and after the noise measurement.

# Water Quality

3.6.9 Water quality monitoring is conducted at the designated locations. The sampling produce with the in-situ monitoring are presented as below:

#### Sampling Procedure

- 3.6.10 A Digital Global Positioning System (GPS) is used to identify the designated monitoring stations prior to water sampling. A portable, battery-operated echo sounder is used for the determination of water depth at each station. At each station, water sample would be collected from 0.1m below water surface or the water surface to prevent the river bed sediment for stirring.
- 3.6.11 If the water level of a monitoring station is too shallow when sampling, sediment would be disturbed which affecting the accuracy of water quality monitoring. In order to avoid disturbing sediment, depth limits should be set up for the water sampling for the ease of reference. When the measured water depth of the monitoring station (both control and impact stations) is lower than 150mm, water monitoring would not be to perform at that monitoring location. Instead, the monitoring location will be moved to a temporary alternative location monitoring location based on the criteria below:-
  - (a) the alternative location should be either upstream or downstream of the original location and at the same the river/drain channel
  - (b) the alternative location should be within 15m far from the original location
  - (c) if no suitable alternative location could be found within 15m far from the original location, the sampling at that location will be cancelled since sampling at too far from the designated location could not make a representative sample.
- 3.6.12 The sample container will be rinsed with a portion of the water sample. The water sample then

will be transferred to the high-density polythene bottles as provided by the laboratory, labeled with a unique sample number and sealed with a screw cap.

- 3.6.13 Before sampling, general information such as the date and time of sampling, weather condition as well as the personnel responsible for the monitoring would be recorded on the field data sheet.
- 3.6.14 A 'Willow' 33-liter plastic cool box packed with ice will be used to preserve the water samples prior to arrival at the laboratory for chemical determination. The water temperature of the cool box is maintained at a temperature as close to 4<sup>o</sup>C as possible without being frozen. Samples collected are delivered to the laboratory upon collection.

# <u>In-situ Measurement</u>

- 3.6.15 Instrument including YSI PRO20 Handheld Dissolved Oxygen Instrument and YSI 550A Multifunctional Meter are used for water in-situ measures, which automates the measurements and data logging of temperature, dissolved oxygen and dissolved oxygen saturation. Before each round of monitoring, the dissolved oxygen probe would be calibrated by the wet bulb method.
- 3.6.16 A portable AZ8685 pH pen-style meter or YSI Professional Plus is used for in-situ pH measurement. The pH meter is capable of measuring pH in the range of 0 14 and readable to 0.1.
- 3.6.17 A portable Hach 2100Q Turbidimeter is used for in-situ turbidity measurement. The turbidity meter is capable of measuring turbidity in the range of 0 1000 NTU. StablCal<sup>®</sup> Standards of known NTU are used for calibration of the instrument before and after measurement.
- 3.6.18 All in-situ measurement equipment are calibrated by HOKLAS accredited laboratory of three month interval.

#### Laboratory Analysis

3.6.19 All water samples are analyzed with Suspended Solids (SS) as specified in the *EM&A Manual* by a local HOKLAS-accredited testing laboratory (ALS Technichem (HK) Pty Ltd HOKLAS registration no. 66). SS analysis is determined by the laboratory upon receipt of the water samples using *APHA Standard Methods 2540D* (namely ALS Method EA-025 as accredited HOKLAS Scheme) started within 48 hours of water sample receipt.

# **3.7** EQUIPMENT CALIBRATION

- 3.7.1 Calibration of the HVS is performed upon installation and thereafter at bimonthly intervals in accordance with the manufacturer's instruction using the certified standard calibrator (TISCH Model TE-5025A). Moreover, the Calibration Kit would be calibrated annually. The calibration data are properly documented and the records are maintained by ET for future reference.
- 3.7.2 The 1-hour TSP meter was calibrated by the supplier prior to purchase. Zero response of the equipment would be checked before and after each monitoring event. Annually calibration with the High Volume Sampler (HVS) in same condition would be undertaken by the Laboratory.
- 3.7.3 The sound level meter and calibrator are calibrated and certified by a laboratory accredited under HOKLAS or any other international accreditation scheme at yearly basis.
- 3.7.4 All water quality monitoring equipment is calibrated by HOKLAS accredited laboratory of three month intervals.
- 3.7.5 The calibration certificates of all monitoring equipment used for the impact monitoring program in the Reporting Period and the HOKLAS accredited certificate of laboratory are presented in the relevant monthly EM&A reports.

#### DERIVATION OF ACTION/LIMIT (A/L) LEVELS 3.8

3.8.1 The baseline results form the basis for determining the environmental acceptance criteria for the impact monitoring. According to the approved Environmental Monitoring and Audit Manual, the air quality, construction noise and water quality criteria were set up, namely Action and Limit levels are listed in Tables 3-8, 3-9 and 3-10.

| Monitoring Station | Action ]   | Level (µg /m³) | Limit Level (µg/m <sup>3</sup> ) |             |
|--------------------|------------|----------------|----------------------------------|-------------|
| Monitoring Station | 1-hour TSP | 24-hour TSP    | 1-hour TSP                       | 24-hour TSP |
| AM1b               | 265        | 143            |                                  |             |
| AM2                | 268        | 149            |                                  |             |
| AM3                | 269        | 145            |                                  |             |
| AM4b               | 267        | 148            |                                  |             |
| AM5a               | 268        | 143            | 500                              | 260         |
| AM6                | 269        | 148            |                                  |             |
| AM7b               | 275        | 156            | ]                                |             |
| AM8                | 269        | 144            |                                  |             |
| AM9b               | 271        | 151            |                                  |             |

Table 3-8 Action and Limit Levels for Air Quality Monitoring

| Table 3-9Action and Limit Levels for Co | onstruction Noise |
|---|-------------------|
|---|-------------------|

| Monitoring Location                                      | Action Level  | Limit Level in dB(A)                    |  |  |
|--|---|---|--|--|
| Wollitoring Location                                     | Time Period: 0700-1900 hours on normal weekdays     |   |  |  |
| NM1, NM2a, NM3, NM4,<br>NM5, NM6, NM7, NM8,<br>NM9, NM10 | When one or more documented complaints are received | 75 dB(A) <sup>Note 1 &amp; Note 2</sup> |  |  |

Note 1: Acceptable Noise Levels for school should be reduced to 70 dB(A) and 65 dB(A) during examination period.

Note 2: If works are to be carried out during restricted hours, the conditions stipulated in the construction noise permit issued by the NCA have to be followed.

| Table 3-10                                      | Action and Limit Levels for Water Quality                          |                     |  |                     |                |                     |
|---|--|---------------------|--|---------------------|----------------|---------------------|
| <b>D</b>  | Performance  | Monitoring Location |  |                     |                |                     |
| Parameter                                       | criteria   | WM1                 | WM2A(a)  | WM2B                | WM3x           | WM4                 |
| $\mathbf{DO}(\mathbf{m} \mathbf{a}/\mathbf{I})$ | Action Level   | <sup>(*)</sup> 4.23 | <sup>(**)</sup> 4.00                                 | <sup>(*)</sup> 4.74 | (**)4.00       | <sup>(*)</sup> 4.14 |
| DO (mg/L)                                       | Limit Level  | <sup>(#)</sup> 4.19 | <sup>(**)</sup> 4.00                                 | <sup>(#)</sup> 4.60 | (**)4.00       | (#)4.08             |
|   | Action Laval   | 51.3                | 24.9   | 11.4                | 13.4           | 35.2                |
| Turbidity                                       | idity Action Level AND 120% of upstream control station of the sam |                     |  |                     | same day       |                     |
| (NTU)   | Limit Level  | 67.6                | 33.8   | 12.3                | 14.0           | 38.4                |
|   | Lillin Level   | AND                 | 130% of upstream control station of the same day     |                     |                |                     |
|   | A ation I areal  | 54.5                | 14.6   | 11.8                | 12.6           | 39.4                |
|   | Action Level   | AND                 | 120% of upst   | ream control s      | station of the | same day            |
| SS (mg/L)                                       | Limit Land   | 64.9                | 17.3   | 12.4                | 12.9           | 45.5                |
|   | Limit Level  | AND                 | AND 130% of upstream control station of the same day |                     |                |                     |

#### **Remarks:**

(\*) The Proposed Action Level of Dissolved Oxygen is adopted to be used 5%-ile of baseline data (\*\*) The Proposed Action & Limit Level of Dissolved Oxygen is used 4mg/L

(#) The Proposed Limit Level of Dissolved Oxygen is adopted to be used 1%-ile of baseline data

3.8.2 Should non-compliance of the environmental quality criteria occurs, remedial actions will be triggered according to the Event and Action Plan which presented in *Appendix E*.

#### 3.9 DATA MANAGEMENT AND DATA QA/QC CONTROL

3.9.1 All monitoring data will be handled by the ET's in-house data recording and management system. The monitoring data recorded in the equipment will be downloaded directly from the equipment at the end of each monitoring day. The downloaded monitoring data will input into a computerized database properly maintained by the ET. The laboratory results will be input directly into the computerized database and checked by personnel other than those who input the data.

3.9.2 For monitoring parameters that require laboratory analysis, the local laboratory shall follow the QA/QC requirements as set out under the HOKLAS scheme for the relevant laboratory tests.

# 4 AIR QUALITY MONITORING

# 4.1 GENERAL

4.1.1 Proposal for partial termination of the construction phase EM&A programme for Contract 2, Contract 4, Contract 7 and Contract SS C505 was approved by EPD on 9 July 2020 (EPD's ref.: () in Ax (3) to EP 2/N7/A/52 Pt.17). The corresponding air quality monitoring stations AM1c and AM8 ceased accordingly, while monitoring at other monitoring stations continued in the Reporting Period.

#### 4.2 SUMMARY OF MONITORING RESULTS

4.2.1 Summary of air quality monitoring results during the Reporting Period are tabulated in *Table 4-1*. The relevant graphical plots throughout the Reporting Period are presented in *Appendix F*.

| Table 4 1   | Summary of the Quarty Montoring Results |           |           |           |              |                  |
|-------------|---|-----------|-----------|-----------|--------------|------------------|
| Monitoring  | 1-hour TSP (μg/m³)                      |           |           | 24-ho     | ur TSP (µg/m | 1 <sup>3</sup> ) |
| Location    | Max                                     | Min       | Mean      | Max       | Min          | Mean             |
| AM2         | 126                                     | 67        | 94        | 139       | 38           | 97               |
| Record Date | 28-Jan-21                               | 4-Nov-20  | 48 events | 19-Dec-20 | 26-Nov-20    | 16 events        |
| AM3         | 114                                     | 60        | 85        | 136       | 55           | 102              |
| Record Date | 22-Jan-21                               | 15-Dec-20 | 48 events | 2-Dec-20  | 26-Nov-20    | 16 events        |
| AM4b        | 107                                     | 45        | 84        | 135       | 65           | 103              |
| Record Date | 11-Nov-20                               | 16-Dec-20 | 48 events | 21-Dec-20 | 22-Jan-21    | 16 events        |
| AM5a        | 111                                     | 62        | 85        | 139       | 40           | 96               |
| Record Date | 30-Jan-21                               | 16-Dec-20 | 48 events | 21-Dec-20 | 21-Nov-20    | 16 events        |
| AM6         | 110                                     | 58        | 86        | 130       | 14           | 78               |
| Record Date | 30-Jan-21                               | 16-Dec-20 | 48 events | 11-Jan-21 | 22-Jan-21    | 16 events        |
| AM7b        | 104                                     | 60        | 84        | 105       | 30           | 72               |
| Record Date | 11-Nov-20                               | 5-Nov-20  | 48 events | 4-Nov-20  | 21-Nov-20    | 16 events        |
| AM9b        | 123                                     | 60        | 84        | 134       | 35           | 88               |
| Record Date | 9-Dec-20                                | 10-Nov-20 | 48 events | 8-Dec-20  | 20-Nov-20    | 16 events        |

 Table 4-1
 Summary of Air Quality Monitoring Results

4.2.2 Breaches of air quality A/L levels and statistical analysis of compliance for the air quality monitoring results are summarized in *Table 4-2*.

Table 4-2Summaries of Breaches of Air Quality A/L Levels

| Location | Exceedance   | 1-hour TSP | 24- hour TSP | Total |
|----------|--------------|------------|--------------|-------|
| 4 1 4 2  | Action Level | 0          | 0            | 0     |
| AM2      | Limit Level  | 0          | 0            | 0     |
| AM3      | Action Level | 0          | 0            | 0     |
| ANIS     | Limit Level  | 0          | 0            | 0     |
| AM4a     | Action Level | 0          | 0            | 0     |
| Alvi4a   | Limit Level  | 0          | 0            | 0     |
| AM5a     | Action Level | 0          | 0            | 0     |
| AMJa     | Limit Level  | 0          | 0            | 0     |
| AM6      | Action Level | 0          | 0            | 0     |
| ANIO     | Limit Level  | 0          | 0            | 0     |
| AM7b     | Action Level | 0          | 0            | 0     |
| Alvi / D | Limit Level  | 0          | 0            | 0     |
| AM9b     | Action Level | 0          | 0            | 0     |
| AM90     | Limit Level  | 0          | 0            | 0     |

4.2.3 In the Reporting Period, all the 1-hour TSP and 24-hour TSP monitoring results were below the Action/Limit Levels.

AUES

4.2.4 The summary of weather conditions during the Reporting Period is presented in *Appendix G*.

# **5** CONSTRUCTION NOISE MONITORING

# 5.1 GENERAL

5.1.1 Proposal for partial termination of the construction phase EM&A programme for Contract 2, Contract 4, Contract 7 and Contract SS C505 was approved by EPD on 9 July 2020 (EPD's ref.: () in Ax (3) to EP 2/N7/A/52 Pt.17). The corresponding noise quality monitoring stations NM1 and NM7 ceased accordingly, while monitoring at other monitoring stations in the Reporting Period.

# 5.2 SUMMARY OF MONITORING RESULTS

- 5.2.1 The sound level meter was set in 1m from the exterior of the building façade including noise monitoring locations NM3, NM4, NM5, NM6, NM8 and NM9. No façade correction (+3 dB(A) is added according to acoustical principles and EPD guidelines. However, free-field status is performed at NM2a and NM10 and façade correction (+3 dB(A) has added according to the requirement.
- 5.2.2 Summary of noise monitoring results during the Reporting Period are tabulated in *Table 5-1*. The relevant graphical plots throughout the Reporting Period are presented in *Appendix F*.

| Fable 5-1           | itoring Results                                       |  |  |  |  |
|---------------------|---|--|--|--|--|
| Monitoring          | Leq, 30min (dB((A))                                   |  |  |  |  |
| Location            | Max   | Min  |  |  |  |
| NM2a <sup>(*)</sup> | 69  | 59   |  |  |  |
| Record Date         | 9-Dec-20, 28-Jan-21                                   | 10-Nov-20                                    |  |  |  |
| NM3                 | 62  | 55   |  |  |  |
| Record Date         | 5-Nov-20  | 23-Nov-20, 16-Dec-20<br>22-Dec-20, 13-Jan-21 |  |  |  |
| NM4                 | 66  | 60   |  |  |  |
| Record Date         | 28-Dec-20   | 10-Dec-20                                    |  |  |  |
| NM5                 | 56  | 51   |  |  |  |
| Record Date         | 17-Nov-20   | 19-Jan-21, 25-Jan-21                         |  |  |  |
| NM6                 | 60  | 55   |  |  |  |
| Record Date         | 17-Nov-20, 19-Jan-21                                  | 10-Dec-20                                    |  |  |  |
| NM8                 | 62  | 55   |  |  |  |
| Record Date         | 27-Nov-20, 3-Dec-20, 9-Dec-20<br>21-Dec-20, 28-Jan-21 | 22-Jan-21                                    |  |  |  |
| NM9                 | 63  | 59   |  |  |  |
| Record Date         | 3-Dec-20  | 22-Jan-21                                    |  |  |  |
| NM10 <sup>(*)</sup> | 66  | 54   |  |  |  |
| Record Date         | 30-Dec-20   | 10-Nov-20                                    |  |  |  |

 Table 5-1
 Summary of Construction Noise Monitoring Results

(\*) façade correction (+3 dB(A)) is added according to acoustical principles and EPD guidelines

5.2.3 Breaches of construction noise A/L levels and statistical analysis of compliance for construction noise monitoring results are summarized in *Table 5-2*.

 Table 5-2
 Summaries of Breaches of Construction Noise A/L Levels

| Station | Limit Level | Action Level | Received Date |
|---------|-------------|--------------|---------------|
| NM2a    | 0           |              |               |
| NM3     | 0           | 0            | N/A           |
| NM4     | 0           | 0            | N/A           |
| NM5     | 0           |              |               |

Z:\Jobs\2013\TCS00694\600\EM&A Report\Quarterly EM&A Report\30th Quarter\R2611v2.docx Action-United Environmental Services and Consulting



| Station | Limit Level | Action Level | <b>Received Date</b> |
|---------|-------------|--------------|----------------------|
| NM6     | 0           |              |                      |
| NM8     | 0           |              |                      |
| NM9     | 0           |              |                      |
| NM10    | 0           |              |                      |

5.2.4 In this Reporting Period, the noise level measured at all designated monitoring locations were below 75dB(A). No Action level and Limit Level exceedance was triggered and no corrective action was required.

# 6 WATER QUALITY MONITORING

# 6.1 GENERAL

6.1.1 Proposal for partial termination of the construction phase EM&A programme for Contract 2, Contract 4, Contract 7 and Contract SS C505 was approved by EPD on 9 July 2020 (EPD's ref.: () in Ax (3) to EP 2/N7/A/52 Pt.17). In the Reporting Period, construction works under the project has been undertaken in Contracts 3 and 6 and water quality monitoring was performed at all designated locations.

# 6.2 SUMMARY OF MONITORING RESULTS

- 6.2.1 Summary of monitoring results during the Reporting Period are tabulated in *Tables 6-1 and 6-4*. The relevant graphical plots throughout the Reporting Period are presented in *Appendix F*.
- 6.2.2 In accordance with "*Event and Action Plan*", the water quality monitoring frequency shall be increased to daily when exceedance recorded at the exceeded monitoring location. In the Reporting Period, no exceedance was recorded at all monitoring locations.

|            | DO (I          | mg/L) | Turbidit | y (NTU)         | SS (mg/L) |                 |  |
|------------|----------------|-------|----------|-----------------|-----------|-----------------|--|
| Statistics | WM1 WM<br>Cont |       | WM1      | WM1-<br>Control | WM1       | WM1-<br>Control |  |
| Min        | 6.8            | 6.2   | 2.8      | 2.1             | 2         | <2              |  |
| Max        | 12.1           | 10.7  | 25.7     | 105             | 52.5      | 108.5           |  |
| Average    | 9.2            | 8.1   | 8.0      | 7.3             | 11.1      | 7.8             |  |

 Table 6-1
 Summary of the Water Quality Monitoring Results – Contract 6

| Table 6-2 | Summary of the Water Quality Monitoring Results – Contract 3 |
|-----------|--|
|-----------|--|

|            | Ι   | DO (mg/L    | .)          | Tur  | bidity (N   | TU)         | SS (mg/L) |             |             |
|------------|-----|-------------|-------------|------|-------------|-------------|-----------|-------------|-------------|
| Statistics | WM4 | WM4 -<br>CA | WM4 -<br>CB | WM4  | WM4 -<br>CA | WM4 -<br>CB | WM4       | WM4 -<br>CA | WM4 -<br>CB |
| Min        | 4.5 | 4.9         | 5.8         | 1.5  | 0.4         | 1.5         | <2        | <2          | <2          |
| Max        | 9.1 | 8.7         | 11.3        | 14.2 | 7.5         | 8.2         | 23        | 20          | 13          |
| Average    | 7.1 | 6.8         | 8.7         | 4.3  | 2.2         | 4.5         | 5.2       | 5.5         | 5.9         |

| Table 0-5 Summary of the Water Quality Monitoring Results – Contract of | Table 6-3 | Summary of the Water ( | Quality Monitoring Results – Contract 6 |
|---|-----------|------------------------|---|
|---|-----------|------------------------|---|

|            | DO (mg/L) |        |      |        |             | Turbidity (NTU) |      |        |             | SS (mg/L)  |      |        |  |
|------------|-----------|--------|------|--------|-------------|-----------------|------|--------|-------------|------------|------|--------|--|
| Statistics | WM2A(a)   | WM2A-C | WM2B | WM2B-C | WM2A<br>(a) | WM2A-<br>C      | WM2B | WM2B-C | WM2A<br>(a) | WM2A-<br>C | WM2B | WM2B-C |  |
| Min        | 4         | 6.2    | *    | *      | 2.2         | 4.8             | *    | *      | <2          | <2         | *    | *      |  |
| Max        | 8.9       | 9.7    | *    | *      | 24.5        | 287             | *    | *      | 12.5        | 349.5      | *    | *      |  |
| Average    | 6.2       | 7.8    | *    | *      | 5.7         | 20.6            | *    | *      | 4.4         | 16.4       | *    | *      |  |

*Remark: (\*) Since 10 Apr 2017, water sampling was unable to carry out at WM2B and WM2B-C due to shallow water (water depth under 150mm)* 

| Table 6-4 | Summary of the Water Quality Monitoring Results - Con | itract 6  |
|-----------|---|-----------|
|           | Summary of the Water Quanty Montoning Results Con     | iti act o |

|            | DO (mg/L) |                         | Turbidit | y (NTU)         | SS (mg/L) |                 |  |
|------------|-----------|-------------------------|----------|-----------------|-----------|-----------------|--|
| Statistics | WM3x      | WM3x WM3-<br>Control WM |          | WM3-<br>Control | WM3x      | WM3-<br>Control |  |
| Min        | 6.1       | *                       | 1.7      | *               | <2.0      | *               |  |
| Max        | 9.3       | *                       | 13.1     | *               | 12        | *               |  |
| Average    | 8.0       | *                       | 5.4      | *               | 5.9       | *               |  |

*Remark: (\*) Water sampling was unable to carry out at WM3-C due to shallow water (water depth under 150mm)* 

6.2.3 Breaches of water quality A/L levels and statistical analysis of compliance for the water quality monitoring results are summarized in *Tables 6-5*.

 Table 6-5
 Summaries of Breaches of the Existing Water Quality A/L Levels

| Reporting | No. of<br>sampling | Location | DO (r  | ng/L) | Turb<br>(N7 | oidity<br>רU) | SS (mg/L) |       |
|-----------|--------------------|----------|--------|-------|-------------|---------------|-----------|-------|
| Period    | day                |          | Action | Limit | Action      | Limit         | Action    | Limit |
|           | 13                 | WM1      | 0      | 0     | 0           | 0             | 0         | 0     |
|           | 13                 | WM2A(a)  | 0      | 0     | 0           | 0             | 0         | 0     |
| Nov-20    | 0                  | WM2B     | 0      | 0     | 0           | 0             | 0         | 0     |
|           | 13                 | WM3x     | 0      | 0     | 0           | 0             | 0         | 0     |
|           | 13                 | WM4      | 0      | 0     | 0           | 0             | 0         | 0     |
|           | 12                 | WM1      | 0      | 0     | 0           | 0             | 0         | 0     |
|           | 12                 | WM2A(a)  | 0      | 0     | 0           | 0             | 0         | 0     |
| Dec-20    | 0                  | WM2B     | 0      | 0     | 0           | 0             | 0         | 0     |
|           | 12                 | WM3x     | 0      | 0     | 0           | 0             | 0         | 0     |
|           | 12                 | WM4      | 0      | 0     | 0           | 0             | 0         | 0     |
|           | 13                 | WM1      | 0      | 0     | 0           | 0             | 0         | 0     |
|           | 13                 | WM2A(a)  | 0      | 0     | 0           | 0             | 0         | 0     |
| Jan-21    | 0                  | WM2B     | 0      | 0     | 0           | 0             | 0         | 0     |
|           | 13                 | WM3x     | 0      | 0     | 0           | 0             | 0         | 0     |
|           | 13                 | WM4      | 0      | 0     | 0           | 0             | 0         | 0     |
|           | 38                 | WM1      | 0      | 0     | 0           | 0             | 0         | 0     |
|           | 38                 | WM2A(a)  | 0      | 0     | 0           | 0             | 0         | 0     |
| Total     | 0                  | WM2B     | 0      | 0     | 0           | 0             | 0         | 0     |
|           | 38                 | WM3x     | 0      | 0     | 0           | 0             | 0         | 0     |
|           | 38                 | WM4      | 0      | 0     | 0           | 0             | 0         | 0     |
|           | Sum                |          | 0      | 0     | 0           | 0             | 0         | 0     |

6.2.4 No exceedance was recorded in the Reporting Period. The detailed investigation reports are summarized in *Table 6-6* and presented in the relevant monthly EM&A reports.

#### Table 6-6 Summary of Water Quality Exceedance in the Reporting Period

| Date of<br>Exceedance | Location | Exceeded<br>Parameter | Cause of Water Quality Exceedance In Brief |
|-----------------------|----------|-----------------------|--|
|                       |          |                       |  |

# 7 ECOLOGY MONITORING

# 7.1 MONITORING ON WOODLAND COMPENSATION

- 7.1.1 According to the approved Woodland Compensation Plan (WCP), ecological monitoring for woodland compensation shall be conducted at bi-monthly interval for the first year and the monitoring frequency would be reduced to quarterly from the second year.
- 7.1.2 As Stage 2 of the enhancement planting work was undertaken in August 2019 has covered all of the 9 monitoring quadrats, the monitoring frequency should have increased from quarterly to bi-monthly interval for the first year of enhancement planting.
- 7.1.3 The quarterly ecological monitoring for period of September 2020 to November 2020 had carried out on 24<sup>th</sup> and 25<sup>th</sup> November 2020 by transects inspection and quadrat monitoring. The quarterly Ecological Monitoring Report was verified by IEC on 22 December 2020 and it has been submitted as a stand-alone copy to supplement the EM&A Report on 22 December 2020.

#### 7.2 MONITORING ON WETLAND COMPENSATION

- 7.2.1 According to the approved Habitat Creation and Management Plan (HCMP), the proposed Wetland Compensation Area (WCA) near the Ping Yeung Interchange adjacent to the section of Ping Yuen River was adopted. Ecological monitoring at implementation and establishment periods of WCA will be conducted to cover the ecological attributes. Implementation of the wetland will commence within the construction phase after completion of the construction works at Ping Yeung Section. Monitoring on the WCA will be conducted in implementation and establishment stages.
- 7.2.2 As advised by the Contractor, construction of WCA was commenced on *11 November 2019*. According to the approved HCMP and further clarified by the RE and Contractor, site inspection is required during construction of wetland and other monitoring parameters shall be commenced after the wetland is established.
- 7.2.3 Site inspection for the construction of WCA was conducted by ET as part of the weekly inspection of Contract 6. It was observed that landscaping was carried out in the WCA. No non-compliance observed during the site inspection. The details of findings / deficiencies could refer to the corresponding monthly EM&A Report.
- 7.2.4 As discussed among CEDD, AECOM and Contractor of Contract 6 in the SSEMC in October 2020, establishment stage for the wetland was commenced on 1 October 2020 for one year after completion of construction of the wetland.
- 7.2.5 In the Reporting Period, wetland monitoring was conducted on **23 and 26 November 2020**, **18 and 22 December 2020** and **27 January 2021**. The monthly monitoring report for the WCA will be submitted as a stand-alone copy to supplement the EM&A Report after verified by IEC.

# 8 WASTE MANAGEMENT

#### 8.1 GENERAL WASTE MANAGEMENT

8.1.1 Waste management was carried out by an on-site Environmental Officer or an Environmental Supervisor from time to time.

# 8.2 **RECORDS OF WASTE QUANTITIES**

- 8.2.1 All types of waste arising from the construction work are classified into the following:
  - Construction & Demolition (C&D) Material;
  - Chemical Waste;
  - General Refuse
  - Excavated Soil.
- 8.2.2 Whenever possible, materials were reused on-site as far as practicable. The quantities of waste for disposal in the Reporting Period are summarized in *Tables 8-1* and *8-2* and the Waste Flow Table is presented in *Appendix H*.

 Table 8-1
 Summary of Quantities of Inert C&D Materials

| Tune of Weste                    | Contract |          | Qua      | ntity    |        | Disposal    |
|----------------------------------|----------|----------|----------|----------|--------|-------------|
| Type of Waste                    | No       | Nov 2020 | Dec 2020 | Jan 2021 | Total  | Location    |
| C&D Materials (Inert)            | 3        | 0.004    | 0        | 0.006    | 1 72 4 | -           |
| (in '000m <sup>3</sup> )         | 6        | 0.379    | 1.322    | 0.023    | 1.734  | -           |
| Reused in this Project (Inert)   | 3        | 0        | 0        | 0        | 0      | -           |
| (in '000m <sup>3</sup> )         | 6        | 0        | 0        | 0        | 0      | -           |
| Reused in other Projects (Inert) | 3        | 0        | 0        | 0        | 0      | -           |
| (in '000m <sup>3</sup> )         | 6        | 0        | 0        | 0        | 0      | -           |
| Disposal as Public Fill (Inert)  | 3        | 0.004    | 0        | 0.006    | 1.734  | Tuen Mun 38 |
| (in '000m <sup>3</sup> )         | 6        | 0.379    | 1.322    | 0.023    | 1./34  | TKO 137     |

| Toma of Wests                         | Contract | Quantity |          |          |       | Disposal |
|---------------------------------------|----------|----------|----------|----------|-------|----------|
| Type of Waste                         | No       | Nov 2020 | Dec 2020 | Jan 2021 | Total | Location |
| Described Matel (2000)as) #           | 3        | 0        | 0        | 0        | 0     | -        |
| Recycled Metal ('000kg) #             | 6        | 0        | 0        | 0        | 0     |          |
| Recycled Paper / Cardboard            | 3        | 0        | 0        | 0        | 0     |          |
| Packing ('000kg) #                    | 6        | 0        | 0        | 0        | 0     | -        |
| Recycled Plastic ('000kg) #           | 3        | 0        | 0        | 0        | 0     |          |
|                                       | 6        | 0        | 0        | 0        | 0     | -        |
| Chamical Wastes ('000kg) *            | 3        | 0        | 0        | 0        | 0     |          |
| Chemical Wastes ('000kg) *            | 6        | 0        | 0        | 0        | 0     | -        |
| General Refuses ('000m <sup>3</sup> ) | 3        | 0        | 0.005    | 0.010    | 0.236 | NENT     |
|                                       | 6        | 0.085    | 0.077    | 0.059    | 0.230 | INLINI   |

Remark:

(#) Unit of recycled metal, recycled paper/ cardboard packing and recycled plastic for Contractor 3 was in ( $(000m^3)$ ).

(\*) Unit of chemical waste for Contractor 3 was in m3.

8.2.3 To control the site performance on waste management, the Contractor shall ensure that all solid and liquid waste management works are fully in compliance with the relevant license/permit requirements, such as the effluent discharge license and the chemical waste producer registration. The Contractor is also reminded to implement the recommended environmental mitigation measures according to the Environmental Monitoring and Audit Manual.

# **9 SITE INSPECTIONS**

# 9.1 **REQUIREMENTS**

- 9.1.1 According to the approved EM&A Manual, the environmental site inspection shall be formulation by ET Leader. Weekly environmental site inspections should carry out to confirm the environmental performance.
- 9.1.2 Proposal for partial termination of the construction phase EM&A programme for Contract 2, Contract 4, Contract 7 and Contract SS C505 was approved by EPD on 9 July 2020 (EPD's ref.: () in Ax (3) to EP 2/N7/A/52 Pt.17). The ET's site inspection and audit for corresponding Contract 2, 4, 7 and SS C505 were ceased after last site inspection undertaken on 10 July 2020.

#### Contract 3

9.1.3 During the Reporting Period, 13 events of the joint site inspections were undertaken at Contract 3 to evaluate the site environmental performance. The summaries of the findings during site inspection are presented in *Table 9-2* and the details of site inspection can be found in relevant EM&A monthly report.

| Reporting<br>Period | Date of site inspection           | Nos. of findings /<br>reminders | Follow-Up<br>Status |
|---------------------|-----------------------------------|---------------------------------|---------------------|
| November 2020       | 4, 11, 19 and 25 November 2020    | 0                               | NA                  |
| December 2020       | 4, 9, 17, 23 and 30 December 2020 | 0                               | NA                  |
| January 2021        | 6, 15, 20 and 27 January 2021     | 0                               | NA                  |

 Table 9-1
 Summary of Reminders/Observations of Site Inspection – Contract 3

9.1.4 In the Reporting Period, no non-compliance and no observations/ reminders was recorded during the site inspections. The environmental performance of the Project was therefore considered satisfactory.

#### Contract 6

9.1.5 During the Reporting Period, 13 events of the joint site inspections were undertaken at Contract 6 to evaluate the site environmental performance. The summaries of the findings during site inspection are presented in *Table 9-4* and the details of site inspection can be found in relevant EM&A monthly report.

| Reporting<br>Period | Date of site inspection           | Nos. of findings /<br>reminders | Follow-Up<br>Status |
|---------------------|-----------------------------------|---------------------------------|---------------------|
| November 2020       | 4, 11, 19 and 26 November 2020    | 0                               | NA                  |
| December 2020       | 4, 9, 17, 22 and 30 December 2020 | 0                               | NA                  |
| January 2021        | 6, 15, 20 and 28 January 2021     | 0                               | NA                  |

 Table 9-2
 Summary of Reminders/Observations of Site Inspection – Contract 6

9.1.6 In the Reporting Period, no non-compliance and no observations/ reminders was recorded during the site inspections. The environmental performance of the Project was therefore considered satisfactory.

# **Other Contracts**

9.1.7 Since the construction work of Contract 2, 4, 5, 7 and Contract SS C505 has substantially completed. Proposal for partial termination of the construction phase EM&A programme for Contract 2, Contract 4, Contract 7 and Contract SS C505 was approved by EPD on 7 July 2020, no site inspection was performed.

# 10 NON-COMPLIANCE, COMPLAINTS, NOTIFICATIONS OF SUMMONS AND PROSECUTIONS

- 10.1 STATUS OF NON-COMPLIANCE ENVIRONMENTAL COMPLAINT, SUMMONS AND PROSECUTION
- 10.1.1 In the Reporting Period, no environmental complaint was recorded.
- 10.1.2 No summons and prosecution under the EM&A Programme was lodged for all Contracts.
- 10.1.3 The statistical summary table of environmental complaint, summons and prosecution are presented in Tables 10-1, 10-2 and 10-3.

|                |                     | Environmental Complaint Statistics |  |  |   |  |
|----------------|---------------------|------------------------------------|--|--|---|--|
| Contract<br>No | Reporting<br>Period | Frequency                          | Cumulative since<br>commencement of<br>project | Complaint Nature   | Project related<br>complaint  |  |
|                | Nov 2020            | 0                                  |  | • (3) Dust   |   |  |
|                | Dec 2020            | 0                                  | • (3) Water quality                            |  | (1) site cleanliness  |  |
| 3              | Jan 2021            | 0                                  | 10   | <ul> <li>(2) Noise</li> <li>(2) site cleanliness<br/>(dust &amp; water<br/>quality)</li> </ul>   | (dust & water<br>quality)   |  |
|                | Nov 2020            | 0                                  |  | • (24) Water Quality   |   |  |
|                | Dec 2020            | 0                                  |  | • (12) Dust  | (8) water quality   |  |
| 6              | Jan 2021            | 0                                  | 46   | <ul> <li>(3) Noise</li> <li>(1) Nuisance</li> <li>(2) Noise and dust</li> <li>(3) Water quality<br/>and dust</li> <li>(1) Water quality<br/>and noise</li> </ul> | <ul> <li>(3) dust</li> <li>(1) nuisance</li> <li>(1) water quality<br/>and dust</li> <li>(1) water quality<br/>and noise</li> </ul> |  |

Table 10-1Statistical Summary of Environmental Complaints

#### **Table 10-2**

# Statistical Summary of Environmental Summons

|             |                     | Environmental Summons Statistics |  |                  |  |
|-------------|---------------------|----------------------------------|--|------------------|--|
| Contract No | Reporting<br>Period | Frequency                        | Cumulative since<br>commencement of<br>project | Complaint Nature |  |
|             | Nov 2020            | 0                                |  |                  |  |
| 3           | Dec 2020            | 0                                | 0  | NA               |  |
|             | Jan 2021            | 0                                |  |                  |  |
|             | Nov 2020            | 0                                |  |                  |  |
| 6           | Dec 2020            | 0                                | 0  | NA               |  |
|             | Jan 2021            | 0                                |  |                  |  |

Table 10-3

Statistical Summary of Environmental Prosecution

|             |                     | Environmental Prosecution Statistics |  |                         |  |
|-------------|---------------------|--------------------------------------|--|-------------------------|--|
| Contract No | Reporting<br>Period | Frequency                            | Cumulative since<br>commencement of<br>project | <b>Complaint Nature</b> |  |
|             | Nov 2020            | 0                                    |  |                         |  |
| 3           | Dec 2020            | 0                                    | 0  | NA                      |  |
|             | Jan 2021            | 0                                    |  |                         |  |
|             | Nov 2020            | 0                                    |  |                         |  |
| 6           | Dec 2020            | 0                                    | 0  | NA                      |  |
|             | Jan 2021            | 0                                    |  |                         |  |

10.1.4 Since the construction works at the Contract 2, 4, 5, 7 and Contract SS C505 was substantially completed, no environmental complaint, summons and prosecution under the EM&A Programme are registered.

# 11 IMPLEMENTATION STATUS OF MITIGATION MEASURES

# **11.1 GENERAL REQUIREMENTS**

11.1.1 The environmental mitigation measures that recommended in the Implementation Schedule for Environmental Mitigation Measures (ISEMM) in the approved EM&A Manual covered the issues of dust, noise, water and waste and they are summarized presented in *Appendix I*.

# **Implementation of Mitigation Measures during Construction Phase**

11.1.2 All contracts under the Project shall be implementing the required environmental mitigation measures according to the approved EM&A Manual as subject to the site condition. Environmental mitigation measures generally implemented by Contracts 2, 3, 5, 6 and SS C505 in this Reporting Period are summarized in *Table 11-1*.

| Issues                              | Environmental Mitigation Measures  |
|-------------------------------------|--|
| Water Quality                       | • Wastewater to be treated by the filtration systems i.e. sedimentation tank or AquaSed before to discharge.   |
| Air Quality                         | <ul> <li>Maintain damp / wet surface on access road</li> <li>Low vehicular speed within the works areas.</li> <li>All vehicles must use wheel washing facility before off site</li> <li>Sprayed water during breaking works</li> <li>A cleaning truck was regularly performed on the public road to prevent fugitive dust emission</li> </ul>                          |
| Noise                               | <ul> <li>Restrain operation time of plants from 07:00 to 19:00 on any working day except for Public Holiday and Sunday.</li> <li>Keep good maintenance of plants</li> <li>Place noisy plants away from residence or school</li> <li>Provide noise barriers or hoarding to enclose the noisy plants or works</li> <li>Shut down the plants when not in used.</li> </ul> |
| Waste and<br>Chemical<br>Management | <ul> <li>On-site sorting prior to disposal</li> <li>Follow requirements and procedures of the "Trip-ticket System"</li> <li>Predict required quantity of concrete accurately</li> <li>Collect the unused fresh concrete at designated locations in the sites for subsequent disposal</li> </ul>  |
| General                             | The site was generally kept tidy and clean.  |

#### Table 11-1Environmental Mitigation Measures

#### **Implementation of Mitigation Measures during Operation Phase**

- 11.1.3 The Heung Yuen Wai (HYW) Highway and connecting roads under the Project was opened on 26 May 2019. Since partial commencement of operation is the same as the commencement of operation for the entire project from EIAO perspective. All relevant requirements as stipulated in the EP and the approved EIA report (including the EM&A Manual) for the commencement of operation of the Project shall be strictly complied with.
- 11.1.4 In general, the recommended mitigation measures for operation stage of HYW Highway and connecting roads under the Project have been implemented. The implementation status of mitigation measures for operation phase in the Reporting Period are summarized in *Appendix J*.
- 11.1.5 For more details about the implementation status of mitigation measures for operation phase with photo illustration, an Environmental Monitoring and Audit report on the implementation of the mitigation measures for operation stage of the Project will be disposed to EPD not later than three months after the commencement of operation of the Project under EP-404/2011/D condition 5.5. The abovementioned report was submitted to EPD on 23 August 2019.

Z:\Jobs\2013\TCS00694\600\EM&A Report\Quarterly EM&A Report\30th Quarter\R2611v2.docx Action-United Environmental Services and Consulting

- 11.1.6 Pursuant to EM&A Manual Section 10.2, the implementation of landscape mitigation measures during establishment period shall be audited by a qualified landscape architect of the ET, to ensure compliance with the aims of proposed measures. Site inspection should be undertaken at least once per month. The checklist for the implementation status is shown in *Appendix J*.
- 11.1.7 As BCP was partially opened on 26 August 2020, a supplement operation phase EM&A report covering the operation of the BCP will be submitted to EPD in accordance with the EP-404/2011/D condition 5.5 separately.
- 11.1.8 Pursuant to EM&A Manual Section 10.2, the implementation of landscape mitigation measures during establishment period shall be audited by a qualified landscape architect. Site inspection for establishment period was commenced in August 2019 and competed in July 2020 respectively. The relevant checklists were included in the corresponding EM&A Reports.

### **12 CONCLUSIONS AND RECOMMENDATIONS**

#### 12.1 CONCLUSIONS

- 12.1.1 This is the **30<sup>th</sup>** Quarterly EM&A Summary Report presenting the monitoring results and inspection findings for the Reporting Period from **1 November 2020 to 31 January 2021**.
- 12.1.2 For air quality monitoring, no 1-hour TSP and 24-hour TSP monitoring results triggered the Action /Limit Level.
- 12.1.3 In the Reporting Period, no construction noise exceedances was recorded and no complaints (which triggered the Action Level exceedance) were received.
- 12.1.4 For water quality monitoring, no exceedance was recorded in the Reporting Period.
- 12.1.5 The bi-monthly ecological monitoring for period of September to November 2020 had carried out on 24<sup>th</sup> and 25<sup>th</sup> November 2020 by transects inspection and quadrat monitoring. The bi-monthly Ecological Monitoring Report was verified by IEC on 22 December 2020 and it has been submitted as a stand-alone copy to supplement the EM&A Report on 22 December 2020.
- 12.1.6 As the major construction work under Contract 3 and Contract 6 were substantially completed. In view of insignificant environmental impacts of the remaining outstanding construction works of Contracts 3 and 6, "proposal for termination of the Construction Phase Environmental Monitoring & Audit (EM&A) Programme for the remaining Contract 3 and Contract 6 of the Project" which certified by ETL and verified by IEC, was submitted to Environmental Protection Department (EPD) on 18 November 2020. EPD issued comments on 6 January 2021 and the revised proposal has been subsequently prepared and certified by ETL and verified by IEC. The revised proposal was re-submitted by AECOM to EPD with written agreement/confirmation obtained from CEDD on 5 February 2021.
- 12.1.7 No environmental compliant, summons or successful prosecutions were recorded in the Reporting Period.
- 12.1.8 During the Reporting Period, weekly joint site inspection by the RE, IEC, ET with the relevant Main-contractor were carried out for Contracts 3 and 6 in accordance with the EM&A Manual stipulation. No non-compliance observed during the site inspection.


### **12.2 RECOMMENDATIONS**

- 12.2.1 During dry season and in consideration of construction site under the Project are located adjacent to villages, the Contractors should fully implement air quality mitigation measures to reduce construction dust emission.
- 12.2.2 In addition, all effluent discharge shall be ensure to fulfill Technical Memorandum of Effluent Discharged into Drainage and Sewerage Systems, inland and Coastal Waters criteria or discharge permits stipulation.
- 12.2.3 Construction noise would be a key environmental issue during construction work of the Project. Noise mitigation measures such as using quiet plants should be implemented in accordance with the EM&A requirement.
- 12.2.4 Furthermore, daily cleaning and weekly tidiness shall be properly performed and maintained. In addition, mosquito control should be kept to prevent mosquito breeding on site.



# Appendix A

# Layout plan of the Project






# **Appendix B**

# **Environmental Management Organization Chart**





| Organization | Project Role Name of Key Staff       |               | Tel No    | Fax No.   |
|--------------|--------------------------------------|---------------|-----------|-----------|
| AECOM        | Engineer's Representative            | Alan Lee      | 2171 3303 | 2171 3498 |
| SMEC         | Independent Environmental<br>Checker | Antony Wong   | 3995 8120 | 3995 8101 |
| Chun Wo      | Project Director                     | Ken Ko        | 3758 8735 | 2638 7077 |
| Chun Wo      | Project Manager                      | William Leung | 2638 6136 | 2638 7077 |
| Chun Wo      | Site Agent                           | Ken Lun       | 2638 6144 | 2638 7077 |
| Chun Wo      | Environmental Officer                | Yip Yun Lam   | 2638 6151 | 2638 7077 |
| Chun Wo      | Environmental Supervisor             | YEUNG Sze yin | 2638 6125 | 2638 7077 |
| AUES         | Environmental Team Leader            | T. W. Tam     | 2959 6059 | 2959 6079 |
| AUES         | Environmental Consultant             | Nicola Hon    | 2959 6059 | 2959 6079 |
| AUES         | Environmental Consultant             | Ben Tam       | 2959 6059 | 2959 6079 |

### Contact Details of Key Personnel for Contract 3 - CV/2012/09

AUES

*Remark: (#) Site Agent Mr Daniel Ho was replaced by Mr Ken Lun in July 2019.* 

Legend:


CEDD (Employer) – Civil Engineering and Development Department

AECOM (Engineer) – AECOM Asia Co. Ltd.

Chun Wo (Main Contractor) – Chun Wo Construction Ltd.

SMEC (IEC) – SMEC Asia Limited

AUES (ET) – Action-United Environmental Services & Consulting



Environmental Management Organization – CV/2013/08

| Organization | Project Role                             | Name of Key Staff   | Tel No.   | Fax No.   |
|--------------|--|---------------------|-----------|-----------|
| AECOM        | Engineer's Representative                | Owen Ng             | 2251 0688 | 2251 0698 |
| SMEC         | Independent Environmental<br>Checker     | Antony Wong         | 3995 8120 | 3995 8101 |
| CCK JV       | Project Director                         | Wang Yanhua         | 6190 4212 |           |
| CCK JV       | Project Manager                          | Raymond Mau Sai-Wai | 9011 5340 |           |
| CCK JV       | Site Agent                               | Vincent Chan        | 9655 9404 |           |
| CCK JV       | Senior Safety &<br>Environmental Manager | H.Y. Yue            | 9185 8186 |           |
| CCK JV       | Environmental Manager                    | K M Lui             | 5113 8223 |           |
| AUES         | Environmental Team Leader                | TW Tam              | 2959 6059 | 2959 6079 |
| AUES         | Environmental Consultant                 | Ben Tam             | 2959 6059 | 2959 6079 |
| AUES         | Environmental Consultant                 | Nicola Hon          | 2959 6059 | 2959 6079 |

### Contact Details of Key Personnel for Contract 6 - CV/2013/08

AUES

Legend:

CEDD (Employer) – Civil Engineering and Development Department AECOM (Engineer) – AECOM Asia Co. Ltd.

CCK JV (Main Contractor) – CRBE-CEC-Kaden Joint Venture


SMEC (IEC) – SMEC Asia Limited


AUES (ET) – Action-United Environmental Services & Consulting




Appendix C

Designated Monitoring Locations as Recommended in the Approved EM&A Manual












# **Appendix D**

# **Monitoring Locations for Impact Monitoring**









Appendix E

## **Event and Action Plan**



## Event and Action Plan for Air Quality

| Event   | ar   | IE  | C   | R Contracto  |
|---|--|---|---|--|
| Action Level                                    |  |   |   |  |
| 1. Exceedance<br>for one sample                 | I. Identify source,<br>investigate the causes of<br>exceedance and propose<br>remedial measures;     I. Inform IEC and ER;     S. Repeat measurement to<br>confirm finding;     I. Increase monitoring<br>frequency to daily.  | <ol> <li>Check monitoring data<br/>submitted by ET;</li> <li>Check Contractor's<br/>working method.</li> </ol>  |   | unacceptable<br>practice;<br>2. Amend working<br>methods if<br>appropriate.  |
| 2. Exceedance<br>for two or more<br>consecutive | 1. Identify source;<br>2. Inform IEC and ER;<br>3. Advise the ER on the  | <ol> <li>Check monitoring data<br/>submitted by ET;</li> <li>Check Contractor's</li> </ol>  | <ol> <li>Confirm receipt on<br/>notification of failur<br/>in writing;</li> </ol>   |  |
| samples   | effectiveness of the<br>proposed remedial<br>measures;<br>4. Repeat measurements to<br>confirm findings;<br>5. Increase monitoring<br>frequency to daily;<br>6. Discuss with IEC and<br>Contractor on remedial<br>actions required;<br>7. If exceedance continues,<br>arrange meeting with<br>IEC and ER;<br>8. If exceedance stops,<br>cease additional monitoring. | <ol> <li>working method;</li> <li>Discuss with ET and<br/>Contractor on possible<br/>remedial measures;</li> <li>Advise the ET on the<br/>effectiveness of the<br/>proposed remedial<br/>measures;</li> <li>Monitor the<br/>implementation of remed<br/>measures.</li> </ol>                                  | <ol> <li>Notify Contractor</li> <li>Ensure remedial<br/>measures properly<br/>implemented.</li> </ol>   | r; days of notification;<br>2. Implement the   |
| time 1 street                                   | cease additional monitoring.   |   |   |  |
| Limit Level<br>1. Exceedance                    | 1. Identify source,  | 1. Check monitoring data  | 1. Confirm receipt  | of 1. Take immediate   |
| for one sample                                  | investigate the causes of<br>exceedance and propose<br>remedial measures;<br>2. Inform ER, Contractor and<br>EPD;<br>3. Repeat measurement to<br>confirm finding;<br>4. Increase monitoring<br>frequency to daily;<br>5. Assess effectiveness of<br>Contractor's remedial<br>actions and keep IEC, EPD<br>and ER informed of<br>the results.                         | submitted by ET;<br>2. Check Contractor's<br>working method;<br>3. Discuss with ET and<br>Contractor on possible<br>remedial measures;<br>4. Advise the ER on the<br>effectiveness of the<br>proposed remedial<br>measures;<br>5. Monitor<br>theimplementation of<br>remedial measures.                       | notification of failur<br>in writing;<br>2. Notify Contracto<br>3. Ensure remedial<br>measures properly<br>implemented.   | e action to avoid<br>further<br>r; exceedance;<br>2. Submit proposals  |
| 2. Exceedance                                   | 1. Notify IEC, ER, Contractor  | <ol> <li>Check monitoring data<br/>submitted by ET;</li> </ol>  |   |  |
| for two or more<br>consecutive<br>samples       | and EPD;<br>2. Identify source;<br>3. Repeat measurement to<br>confirm findings;<br>4. Increase monitoring<br>frequency to daily;<br>5. Carry out analysis of<br>Contractor's working<br>procedures to determine<br>possible mitigation to be<br>implemented;<br>6. Arrange meeting with IEC   | <ol> <li>Submitted by E1;</li> <li>Check Contractor's<br/>working method;</li> <li>Discuss amongst ER,<br/>ET, and Contractor on<br/>the potential remedial<br/>actions;</li> <li>Review Contractor's<br/>remedial actions<br/>whenever necessary to<br/>assure their<br/>effectiveness and advise</li> </ol> | notification of failur<br>in writing;<br>2. Notify Contracto<br>3. In consolidation<br>with the IEC, agree<br>with the Contractor<br>on the remedial<br>measures to be<br>implemented;<br>4. Ensure remedial<br>measures properly<br>implemented; | further exceedance;<br>r; 2. Submit proposals<br>for remedial actions<br>to IEC within 3<br>working days of<br>notification;<br>3. Implement the<br>agreed proposals;<br>4. Resubmit |
|   |  |   |   |  |
| ren<br>7. /<br>Cor<br>acti<br>and<br>the        | nedial actions to be taken; 5. 1<br>Assess effectiveness of imp  | ER accordingly;<br>Monitor the<br>olementation of remedial<br>asures.   | 5. If exceedance<br>continues, consider<br>what portion of the<br>work is responsible<br>and instruct the<br>Contractor to stop<br>that portion of work   | under control;<br>5. Stop the relevant<br>portion of works as<br>determined by the<br>ER until the<br>exceedance is<br>abated.   |

until the exceedance

is abated.

8. If exceedance stops,

cease additional monitoring.



### **Event and Action Plan for Construction Noise**

| Event           | ET   | IEC  | ER  | Action<br>Contractor  |
|-----------------|--|--|---|---|
| Action<br>Level | <ol> <li>Notify ER, IEC and<br/>Contractor;</li> <li>Carry out investigation;</li> <li>Report the results of<br/>investigation to the IEC, ER<br/>and Contractor;</li> <li>Discuss with the IEC and<br/>Contractor on remedial<br/>measures required;</li> <li>Increase monitoring<br/>frequency to check<br/>mitigation effectiveness.</li> </ol>   | <ol> <li>Review the<br/>investigation results<br/>submitted by the ET;</li> <li>Review the proposed<br/>remedial measures by<br/>the Contractor and<br/>advise the ER<br/>accordingly;</li> <li>Advise the ER on the<br/>effectiveness of the<br/>proposed remedial<br/>measures.</li> </ol> | Confirm receipt of<br>notification of failure in<br>writing;     Z. Notify Contractor;     J. In consolidation with the<br>IEC, agree with the<br>Contractor on the remedial<br>measures to be<br>implemented;     Supervise the<br>implementation of remedial<br>measures.   | <ol> <li>Submit noise<br/>mitigation proposals to<br/>IEC and ER;</li> <li>Implement noise<br/>mitigation proposals.</li> </ol>   |
| Limit<br>Level  | 1. Inform IEC, ER,<br>Contractor and EPD;<br>2. Repeat measurements to<br>confirm findings;<br>3. Increase monitoring<br>frequency;<br>4. Identify source and<br>investigate the cause of<br>exceedance;<br>5. Carry out analysis of<br>Contractor's working<br>procedures;<br>6. Discuss with the IEC,<br>Contractor and ER on<br>remedial measures<br>required;<br>7. Assess effectiveness of<br>Contractor's remedial<br>actions and keep IEC, EPD<br>and ER informed of the<br>results;<br>8. If exceedance stops,<br>cease additional monitoring. | 1. Discuss amongst ER,<br>ET, and Contractor on<br>the ootential remedial<br>actions;<br>2. Review Contractor's<br>remedial actions<br>whenever necessary to<br>assure their effectiveness<br>and advise the ER<br>accordingly.  | Confirm receipt of<br>notification of failure in<br>writino:     Notify Contractor;     In consolidation with the<br>IEC, agree with the<br>Contractor on the remedial<br>measures to be<br>implemented;     Supervise the<br>implementation of remedial<br>measures;     If exceedance continues,<br>consider stopping the<br>Contractor to continue<br>working on that portion of<br>work which causes the<br>exceedance until the<br>exceedance is abated. | <ol> <li>Take immediate<br/>action to avoid further<br/><u>exceedance</u>:</li> <li>Submit proposals for<br/>remedial actions to IEC<br/>and ER within 3<br/>working days of<br/>notification;</li> <li>Implement the<br/>agreed proposals;</li> <li>Submit further<br/>proposal if problem still<br/>not under<br/>control;</li> <li>Stop the relevant<br/>portion of works as<br/>instructed by the ER<br/>until the exceedance is<br/>abated.</li> </ol> |



### **Event and Action Plan for Water Quality**

| EVENT   |   | 122   |  | ACTION  |
|---|---|---|--|---|
| Action level<br>being<br>exceeded by<br>one sampling<br>day                                 | <ol> <li>Repeat in-situ<br/>measurement to<br/>confirm findings;</li> <li>Identify reasons for<br/>non-compliance and<br/>sources of impact;</li> <li>Inform IEC and<br/>Contractor;</li> <li>Check monitoring<br/>data, all plant,<br/>equipment and<br/>Contractor's working<br/>methods;</li> <li>Discuss mitigation<br/>measures with IEC<br/>and Contractor;</li> <li>Repeat measurement<br/>on next day of<br/>exceedance.</li> </ol>   | IEC<br>1. Discuss with ET and<br>Contractor on the<br>mitigation measures;<br>2. Review proposals on<br>mitigation measures<br>submitted by Contractor<br>and advise the ER<br>accordingly;<br>3. Assess the<br>effectiveness of the<br>implemented mitigation<br>measures                          | ER<br>1. Discuss with IEC on<br>the proposed<br>mitigation measures;<br>2. Make agreement on<br>the mitigation<br>measures to be<br>implemented;<br>3. Assess the<br>effectiveness of the<br>implemented<br>mitigation measures  | CONTRACTOR<br>1. Inform the ER and confirm<br>notification of the non-<br>compliance in writing;<br>2. Rectify unacceptable<br>practice;<br>3. Check all plant and<br>equipment;<br>4. Consider changes of<br>working methods;<br>5. Discuss with ET and IEC<br>and propose mitigation<br>measures to IEC and ER;<br>6. Implement the agreed<br>mitigation measures.  |
| Action Level<br>being<br>exceeded by<br>more than<br>two<br>consecutive<br>sampling<br>days | <ol> <li>Repeat in-situ<br/>measurement to<br/>confirm findings;</li> <li>Identify reasons for<br/>non-compliance and<br/>sources of impact;</li> <li>Inform IEC and<br/>Contractor;</li> <li>Check monitoring<br/>data, all plant,<br/>equipment and<br/>Contractor; sworking</li> <li>Discuss mitigation<br/>measures with IEC<br/>and Contractor;</li> <li>Ensure mitigation<br/>measures are<br/>implemented;</li> <li>Prepare to increase<br/>the monitoring<br/>frequency to daily;</li> <li>Repeat measurement<br/>on next day of</li> </ol>   | <ol> <li>Discuss with ET and<br/>Contractor on the<br/>mitigation measures;</li> <li>Review proposals on<br/>mitigation measures<br/>submitted by Contractor<br/>and advise the ER<br/>accordingly;</li> <li>Assess the<br/>effectiveness of the<br/>implemented mitigation<br/>measures</li> </ol> | <ol> <li>Discuss with IEC on<br/>the proposed<br/>mitigation measures;</li> <li>Make agreement on<br/>the mitigation<br/>measures to be<br/>implemented;</li> <li>Assess the<br/>effectiveness of the<br/>implemented<br/>mitigation measures</li> </ol>   | <ol> <li>Inform the ER and confirm<br/>notification of the non-<br/>compliance in writing;</li> <li>Rectify unacceptable<br/>practice;</li> <li>Check all plant and<br/>equipment;</li> <li>Consider changes of<br/>working methods;</li> <li>Discuss with ET and IEC<br/>and propose mitigation<br/>measures to IEC and ER<br/>within 2 working daws.</li> <li>Implement the agreed<br/>mitigation measures.</li> </ol>  |
| Limit Level<br>being<br>exceeded by<br>one sampling<br>day                                  | <ol> <li>exceedance.</li> <li>Repeat in-situ<br/>measurement to<br/>confirm findings;</li> <li>Identify reasons for<br/>non-compliance and<br/>sources of impact;</li> <li>Inform IEC,<br/>Contractor and EPD;</li> <li>Check monitoring<br/>data, all plant,<br/>equipment and<br/>Contractor's working<br/>methods;</li> <li>Discuss mitigation<br/>measures with IEC,<br/>ER and Contractor;</li> <li>Ensure mitigation<br/>measures are<br/>implemented;</li> <li>Increase the<br/>monitoring frequency<br/>to daily until no<br/>exceedance of Limit<br/>Level</li> </ol>                          | <ol> <li>Discuss with ET and<br/>Contractor on the<br/>mitigation measures;</li> <li>Review proposals on<br/>mitigation measures<br/>submitted by Contractor<br/>and advise the ER<br/>accordingly;</li> <li>Assess the effectiveness<br/>of the implemented<br/>mitigation measures</li> </ol>     | <ol> <li>Discuss with IEC, ET<br/>and Contractor on the<br/>proposed mitigation<br/>measures;</li> <li>Request Contractor to<br/>critically review the<br/>working methods;</li> <li>Make agreement on<br/>the mitigation<br/>measures to be<br/>implemented;</li> <li>Assess the<br/>affectiveness of the<br/>implemented<br/>mitigation measures</li> </ol>  | <ol> <li>Inform the ER and confirm<br/>notification of the non-<br/>compliance in writing;</li> <li>Rectify unacceptable<br/>practice;</li> <li>Check all plant and<br/>equipment;</li> <li>Consider changes of<br/>working methods;</li> <li>Discuss with ET, IEC and<br/>ER and propose mitigatio<br/>measures to IEC and ER<br/>within 3 working days;</li> <li>Implement the agreed<br/>mitigation measures.</li> </ol>   |
| Limit level<br>being<br>exceeded by<br>more than<br>one<br>consecutive<br>sampling<br>days  | <ol> <li>Level.</li> <li>Repeat in-situ<br/>measurement to<br/>confirm findings;</li> <li>Identify reasons for<br/>non-compliance and<br/>sources of impact;</li> <li>Inform IEC, Contractor<br/>and EPD;</li> <li>Check monitoring<br/>data, all plant,<br/>equipment and<br/>Contractor's working<br/>methods;</li> <li>Discuss mitigation<br/>measures with IEC,<br/>ER and Contractor;</li> <li>Ensure mitigation<br/>measures are<br/>implemented;</li> <li>Increase the<br/>monitoring frequency<br/>to daily until no<br/>exceedance of Limit<br/>Level for two<br/>consecutive days.</li> </ol> | <ol> <li>Discuss with ET and<br/>Contractor on the<br/>mitigation measures;</li> <li>Review proposals on<br/>mitigation measures<br/>submitted by Contractor<br/>and advise the ER<br/>accordingly;</li> <li>Assess the effectiveness<br/>of the implemented<br/>mitigation measures.</li> </ol>    | <ol> <li>Discuss with IEC, ET<br/>and Contractor on the<br/>proposed mitigation<br/>measures;</li> <li>Request Contractor to<br/>critically review the<br/>working methods;</li> <li>Make agreement on<br/>the mitigation<br/>measures to be<br/>implemented;</li> <li>Assess the<br/>effectiveness of the<br/>implemented<br/>mitigation measures;</li> <li>Consider and instruct,<br/>if necessary, the<br/>Contractor to slow<br/>down or to stop all or<br/>part of the construction<br/>activities until no<br/>exceedance of Limit<br/>Level.</li> </ol> | <ol> <li>Inform the ER and confirm<br/>notification of the non-<br/>compliance in writing;</li> <li>Rectify unacceptable<br/>practice;</li> <li>Check all plant and<br/>equipment;</li> <li>Consider changes of<br/>working methods;</li> <li>Discuss with ET, IEC and<br/>ER and propose mitigatio<br/>measures to IEC and ER<br/>within 3 working days;</li> <li>Implement the agreed<br/>mitigation measures;</li> <li>As directed by the ER, to<br/>slow down or to stop all of<br/>part of the construction<br/>activities.</li> </ol> |





Appendix F


# **Graphical Plots for Monitoring Result**




## <u>Air Quality – 1-hour TSP</u>























**AUES** 





## <u>Air Quality – 24-hour TSP</u>






















### <u>Noise</u>


























### Water Quality
















 $\diamond$ 

0<sup>-</sup>CY



ALIF



Date

20.0

0.0

₩ 2010



Appendix G

## Weather information

### Weather Condition Extracted from HKO

#### The weather of November 2020

With the northeast monsoon over southern China generally weaker than normal for most of the time in the month, November 2020 was much warmer than usual in Hong Kong. The monthly mean maximum temperature was 26.4 degrees, 2.3 degrees above the normal figure and the highest on record for November. The monthly mean temperature of 23.5 degrees and mean minimum temperature of 21.7 degrees were respectively 1.7 degrees and 1.9 degrees above their corresponding normal figures and both were the second highest on record for November. Moreover, the autumn mean temperature in Hong Kong for the period from September to November 2020 was 25.8 degrees, 0.8 degrees above the normal figure and one of the fourth warmest autumns on record. The month was also drier than usual with a total rainfall of 5.1 millimetres, about 14 percent of the normal figure of 37.6 millimetres. The accumulated rainfall this year up to November was 2393.5 millimetres, slightly more than the normal figure of 2371.7 millimetres for the same period.

### The weather of December 2020

The weather for December 2020 was cloudier than usual. The mean amount of cloud in the month was 62 percent, 10 percent above the normal of 52 percent. The mean temperature for December 2020 was 18.1 degrees, 0.2 degrees above the normal figure of 17.9 degrees. The month was also much drier than usual with a total rainfall of only 1.5 millimetres, about 6 percent of the normal figure of 26.8 millimetres. The annual total rainfall in 2020 was 2395.0 millimetres, near the annual normal of 2398.5 millimetres.

### The weather of January 2021

January 2021 was characterized by colder weather during the first half of the month and relatively milder weather in the latter part. Overall, the month was colder than usual with a mean temperature of 16.2 degrees, 0.3 degrees below the normal figure of 16.5 degrees (or 0.1 degrees below the 1981-2010 normal). With dry winter monsoon dominating over southern China for most of the time in the month, January 2021 was also much sunnier and drier than usual. The monthly total sunshine duration amounted to 217.3 hours, 49 percent above the normal of 145.8 hours (or 52 percent above the 1981-2010 normal). Only traces of rainfall was recorded in the month, making it one of the eight Januaries with traces of rainfall since records began in 1884.

*Remark: The meteorological data during the Reporting Period is presented in the relevant monthly EM&A report.* 



Appendix H

Waste Flow Table

### Name of Department: CEDD

### Monthly Summary Waste Flow Table for 2020 (year)

|           | Actua                    | l Quantities             | of Inert C&D             | Materials G              | enerated Mo              | onthly                   | Actual                   | Quantities o             | f C&D Wastes             | Generated | Monthly                  |
|-----------|--------------------------|--------------------------|--------------------------|--------------------------|--------------------------|--------------------------|--------------------------|--------------------------|--------------------------|-----------|--------------------------|
|           |                          | Hard Rock                |                          |                          |                          |                          |                          |                          |                          |           |                          |
|           | Total                    | and Large                | Reused in                | <b>Reused in</b>         | Disposed                 |                          |                          | Paper/                   |                          |           | Others, e.g.             |
| Month     | Quantity                 | Broken                   | the                      | other                    | as Public                | Imported                 |                          | cardboard                |                          | Chemical  | general                  |
|           | Generated                | Concrete                 | Contract                 | Projects                 | Fill                     | Fill                     | Metals                   | packaging                | Plastics                 | Waste     | refuse                   |
|           | (in '000m <sup>3</sup> ) | (in m³)   | (in '000m <sup>3</sup> ) |
| Jan       | 0.280                    | 0.000                    | 0.000                    | 0.000                    | 0.280                    | 0.000                    | 0.000                    | 0.000                    | 0.000                    | 0.000     | 0.015                    |
| Feb       | 0.069                    | 0.000                    | 0.000                    | 0.000                    | 0.069                    | 0.000                    | 0.000                    | 0.000                    | 0.000                    | 0.000     | 0.020                    |
| Mar       | 0.089                    | 0.000                    | 0.000                    | 0.000                    | 0.089                    | 0.000                    | 0.000                    | 0.000                    | 0.000                    | 0.000     | 0.025                    |
| Apr       | 0.298                    | 0.000                    | 0.000                    | 0.000                    | 0.298                    | 0.000                    | 0.000                    | 0.000                    | 0.000                    | 0.000     | 0.010                    |
| May       | 0.167                    | 0.000                    | 0.000                    | 0.000                    | 0.167                    | 0.000                    | 0.000                    | 0.000                    | 0.000                    | 0.000     | 0.015                    |
| Jun       | 0.004                    | 0.000                    | 0.000                    | 0.000                    | 0.004                    | 0.000                    | 0.000                    | 0.000                    | 0.000                    | 0.000     | 0.010                    |
| Sub-total | 0.907                    | 0.000                    | 0.000                    | 0.000                    | 0.907                    | 0.000                    | 0.000                    | 0.000                    | 0.000                    | 0.000     | 0.095                    |
| Jul       | 0.164                    | 0.000                    | 0.000                    | 0.000                    | 0.164                    | 0.000                    | 0.000                    | 0.000                    | 0.000                    | 0.000     | 0.010                    |
| Aug       | 0.103                    | 0.000                    | 0.000                    | 0.000                    | 0.103                    | 0.000                    | 0.000                    | 0.000                    | 0.000                    | 0.000     | 0.010                    |
| Sep       | 0.149                    | 0.000                    | 0.000                    | 0.000                    | 0.149                    | 0.000                    | 0.000                    | 0.000                    | 0.000                    | 0.000     | 0.010                    |
| Oct       | 0.000                    | 0.000                    | 0.000                    | 0.000                    | 0.000                    | 0.000                    | 0.000                    | 0.000                    | 0.000                    | 0.000     | 0.000                    |
| Nov       | 0.004                    | 0.000                    | 0.000                    | 0.000                    | 0.004                    | 0.000                    | 0.000                    | 0.000                    | 0.000                    | 0.000     | 0.000                    |
| Dec       | 0.000                    | 0.000                    | 0.000                    | 0.000                    | 0.000                    | 0.000                    | 0.000                    | 0.000                    | 0.000                    | 0.000     | 0.005                    |
| Total     | 1.327                    | 0.000                    | 0.000                    | 0.000                    | 1.327                    | 0.000                    | 0.000                    | 0.000                    | 0.000                    | 0.000     | 0.130                    |

**Note:** 1. Assume the density of soil fill is 2 ton/m<sup>3</sup>.

2. Assume the density of rock and broken concrete is  $2.5 \text{ ton/m}^3$ .

3. Assume each truck of C&D wastes is  $5m^3$ .

4. The inert C&D materials except slurry and bentonite are disposed at Tuen Mun 38.

5. The slurry and bentonite are disposed at Tseung Kwun O 137.

6. The non-inert C&D wastes are disposed at NENT.

7. Assume the density of metal is  $7,850 \text{ kg/m}^3$ .

8. Assume the density of plastic is  $941 \text{ kg/m}^3$ .

9. Assume the density of paper is  $800 \text{ kg/m}^3$ .

### Monthly Summary Waste Flow Table for 2020 (year)

|           | Actua                    | l Quantities             | of Inert C&D             | Materials G              | enerated Mo              | onthly                   | Actual                   | Quantities o             | f C&D Wastes             | Generated            | Monthly                  |
|-----------|--------------------------|--------------------------|--------------------------|--------------------------|--------------------------|--------------------------|--------------------------|--------------------------|--------------------------|----------------------|--------------------------|
|           |                          | Hard Rock                |                          |                          |                          |                          |                          |                          |                          |                      |                          |
|           | Total                    | and Large                | Reused in                | <b>Reused in</b>         | Disposed                 |                          |                          | Paper/                   |                          |                      | Others, e.g.             |
| Month     | Quantity                 | Broken                   | the                      | other                    | as Public                | Imported                 |                          | cardboard                |                          | Chemical             | general                  |
|           | Generated                | Concrete                 | Contract                 | Projects                 | Fill                     | Fill                     | Metals                   | packaging                | Plastics                 | Waste                | refuse                   |
|           | (in '000m <sup>3</sup> ) | (in m <sup>3</sup> ) | (in '000m <sup>3</sup> ) |
| Jan       | 0.006                    | 0.000                    | 0.000                    | 0.000                    | 0.006                    | 0.000                    | 0.000                    | 0.000                    | 0.000                    | 0.000                | 0.010                    |
| Feb       |                          |                          |                          |                          |                          |                          |                          |                          |                          |                      |                          |
| Mar       |                          |                          |                          |                          |                          |                          |                          |                          |                          |                      |                          |
| Apr       |                          |                          |                          |                          |                          |                          |                          |                          |                          |                      |                          |
| May       |                          |                          |                          |                          |                          |                          |                          |                          |                          |                      |                          |
| Jun       |                          |                          |                          |                          |                          |                          |                          |                          |                          |                      |                          |
| Sub-total | 0.006                    | 0.000                    | 0.000                    | 0.000                    | 0.006                    | 0.000                    | 0.000                    | 0.000                    | 0.000                    | 0.000                | 0.010                    |
| Jul       |                          |                          |                          |                          |                          |                          |                          |                          |                          |                      |                          |
| Aug       |                          |                          |                          |                          |                          |                          |                          |                          |                          |                      |                          |
| Sep       |                          |                          |                          |                          |                          |                          |                          |                          |                          |                      |                          |
| Oct       |                          |                          |                          |                          |                          |                          |                          |                          |                          |                      |                          |
| Nov       |                          |                          |                          |                          |                          |                          |                          |                          |                          |                      |                          |
| Dec       |                          |                          |                          |                          |                          |                          |                          |                          |                          |                      |                          |
| Total     | 0.006                    | 0.000                    | 0.000                    | 0.000                    | 0.006                    | 0.000                    | 0.000                    | 0.000                    | 0.000                    | 0.000                | 0.010                    |

**Note:** 1. Assume the density of soil fill is 2 ton/m<sup>3</sup>.

2. Assume the density of rock and broken concrete is  $2.5 \text{ ton/m}^3$ .

3. Assume each truck of C&D wastes is  $5m^3$ .

4. The inert C&D materials except slurry and bentonite are disposed at Tuen Mun 38.

5. The slurry and bentonite are disposed at Tseung Kwun O 137.

6. The non-inert C&D wastes are disposed at NENT.

7. Assume the density of metal is  $7,850 \text{ kg/m}^3$ .

8. Assume the density of plastic is  $941 \text{ kg/m}^3$ .

9. Assume the density of paper is  $800 \text{ kg/m}^3$ .

### Monthly Summary Waste Flow Table for <u>2020</u> (year)

Name of Person completing the record: K.M. Lui (EO)

Project : Liangtang / Heung Yuen Wai Boundary Control Point Site Formation and Infrastructure Works - Contract 6 Contract No.: CV/2013/08 Actual Quantities of C&D Wastes Generated Monthly Actual Quantities of Inert C&D Materials Generated Monthly Hard Rock Total Paper/ Reused in Others, e.g. and Large Reused in Disposed as Chemical Plastics Imported Fill other cardboard Quantity Metals general Public Fill Waste Broken the Contract Month Generated Projects packaging refuse Concrete (see Note 3)  $(in '000m^3)$  $(in '000m^3)$  $(in '000m^3)$  $(in '000m^3)$ (in '000 kg) (in '000kg) (in '000kg) (in '000kg)  $(in '000 m^3)$  $(in '000m^3)$  $(in '000m^3)$ 10.280 0 0 10.280 0 0 0.22 0.377 Jan 0 0 0 0 0 0 0 0 0 0 Feb 21.439 21.439 0 0.522 Mar 7.623 7.623 0 0 0 0 0 0 0 0.417 Ω 0.310 1.567 1.567 0 0 0 0 0 0 0 0.419 Apr May 3.590 0 0 0 3.590 0 0 0 0 0 0.477 1.390 0 1.390 0 0 0 0 0 0 0.218 Jun  $\mathbf{0}$ 45.889 45.889 0.000 0.220 2.430 0.000 0.000 0.000 0.000 0.310 0.000 Sub-total 1.336 0 0 0 0 0.325 0 Jul 0 1.336 0 0.360 2.876 0 2.876 0 0 0.217 0 0 0 Aug 0 0 1.045 1.045 0 0 Sep 0 0 0 0 0.282 0 0.240 0.321 0 0.321 Oct 0 0 0 0 0 0 0 0.187 0 0 0.379 0 0 0 0 Nov 0.379 0 0 0.085

1.322

53.168

0

0.000

0

0.000

Ω

0.917

0

0.220

0

0.000

0.077

3.596

Notes: (1) The waste flow table shall also include C&D materials that are specified in the Contract to be imported for use at the Site.

0.000

0

(2) Plastics refer to plastic bottles/containers, plastic sheets/ foam from packaging materials.

0.000

0

(3) Broken concrete for recycling into aggregates.

0.000

0

1.322

53.168

Dec

Total

### Monthly Summary Waste Flow Table for <u>2021</u> (year)

Name of Person completing the record: K.M. Lui (EO)

Project : Liangtang / Heung Yuen Wai Boundary Control Point Site Formation and Infrastructure Works - Contract 6

Contract No.: CV/2013/08

|           | <u> </u>                       | ě  | -                         |                                | enerated Month             |                          |              |                                  | of C&D Waste             | es Generated M    |                                   |
|-----------|--------------------------------|--|---------------------------|--------------------------------|----------------------------|--------------------------|--------------|----------------------------------|--------------------------|-------------------|-----------------------------------|
| Month     | Total<br>Quantity<br>Generated | Hard Rock<br>and Large<br>Broken<br>Concrete | Reused in<br>the Contract | Reused in<br>other<br>Projects | Disposed as<br>Public Fill | Imported Fill            | Metals       | Paper/<br>cardboard<br>packaging | Plastics<br>(see Note 3) | Chemical<br>Waste | Others, e.g.<br>general<br>refuse |
|           | (in '000m <sup>3</sup> )       | (in '000m <sup>3</sup> )                     | (in '000m <sup>3</sup> )  | (in '000m <sup>3</sup> )       | (in '000m <sup>3</sup> )   | (in '000m <sup>3</sup> ) | (in '000 kg) | (in '000kg)                      | (in '000kg)              | (in '000kg)       | (in '000 m <sup>3</sup> )         |
| Jan       | 0.023                          | 0  | 0                         | 0                              | 0.023                      | 0                        | 0            | 0                                | 0                        | 0                 | 0.059                             |
| Feb       |                                |  |                           |                                |                            |                          |              |                                  |                          |                   |                                   |
| Mar       |                                |  |                           |                                |                            |                          |              |                                  |                          |                   |                                   |
| Apr       |                                |  |                           |                                |                            |                          |              |                                  |                          |                   |                                   |
| May       |                                |  |                           |                                |                            |                          |              |                                  |                          |                   |                                   |
| Jun       |                                |  |                           |                                |                            |                          |              |                                  |                          |                   |                                   |
| Sub-total | 0.023                          | 0.000  | 0.000                     | 0.000                          | 0.023                      | 0.000                    | 0.000        | 0.000                            | 0.000                    | 0.000             | 0.059                             |
| Jul       |                                |  |                           |                                |                            |                          |              |                                  |                          |                   |                                   |
| Aug       |                                |  |                           |                                |                            |                          |              |                                  |                          |                   |                                   |
| Sep       |                                |  |                           |                                |                            |                          |              |                                  |                          |                   |                                   |
| Oct       |                                |  |                           |                                |                            |                          |              |                                  |                          |                   |                                   |
| Nov       |                                |  |                           |                                |                            |                          |              |                                  |                          |                   |                                   |
| Dec       |                                |  |                           |                                |                            |                          |              |                                  |                          |                   |                                   |
| Total     | 0.023                          | 0.000  | 0.000                     | 0.000                          | 0.023                      | 0.000                    | 0.000        | 0.000                            | 0.000                    | 0.000             | 0.059                             |

Notes:

(1) The waste flow table shall also include C&D materials that are specified in the Contract to be imported for use at the Site.

(2) Plastics refer to plastic bottles/containers, plastic sheets/ foam from packaging materials.

(3) Broken concrete for recycling into aggregates.



### Appendix I

Implementation Schedule for Environmental Mitigation Measures



| EIA Ref.                    | EM&A<br>Ref.              | Recommended Mitigation Measures   | Objectives of the<br>Recommended<br>Measure<br>& Main Concerns<br>to address  | Who to<br>implement<br>the<br>measure? | Location of the measure     | When to<br>implement the<br>measure? | What requirements<br>or standards for the<br>measure to<br>achieve?                  |
|-----------------------------|---------------------------|---|---|--|-----------------------------|--------------------------------------|--|
| <u>Air Quali</u><br>3.6.1.1 | <u>ty Impact (</u><br>2.1 | <ul> <li>Construction)</li> <li>General Dust Control Measures</li> <li>The following dust suppression measures should be implemented:</li> <li>Frequent water spraying for active construction areas (4 times per day for active areas in Po Kak Tsai and 8 times per day for all other active areas), including areas with heavy construction and slope cutting activities</li> <li>80% of stockpile areas should be covered by impervious sheets</li> <li>Speed of trucks within the site should be controlled to about 10 km/hr</li> <li>All haul roads within the site should be paved to avoid dust emission due to vehicular movement</li> </ul>  | To minimize<br>adverse dust<br>emission generated<br>from various<br>construction<br>activities of the<br>works sites | Contractor                             | Construction<br>Works Sites | During<br>Construction               | EIA Recommendation<br>and Air Pollution<br>Control (Construction<br>Dust) Regulation |
| 3.6.1.2                     | 2.1                       | <ul> <li>emission due to vehicular movement</li> <li>Best Practice for Dust Control</li> <li>The relevant best practices for dust control as stipulated in the Air Pollution Control (Construction Dust) Regulation should be adopted to further reduce the construction dust impacts of the Project. These best practices include:</li> <li>Good site management</li> <li>The Contractor should maintain high standard of housekeeping to prevent emission of fugitive dust.</li> <li>Loading, unloading, handling and storage of raw materials, wastes or by-products should be carried out in a manner so as to minimize the release of visible dust emission.</li> <li>Any piles of materials accumulated on or around the work areas should be cleaned up regularly.</li> <li>Cleaning, repair and maintenance of all plant facilities within the work areas should be carried out in a manner minimizing generation of fugitive dust emissions.</li> <li>The material should be handled properly to prevent fugitive dust emission before cleaning.</li> <li>Disturbed Parts of the Roads</li> <li>Each and every main temporary access should be paved with</li> </ul> | To minimize<br>adverse dust<br>emission generated<br>from various<br>construction<br>activities of the<br>works sites | Contractor                             | Construction<br>Works Sites | During<br>Construction               | EIA Recommendation<br>and Air Pollution<br>Control (Construction<br>Dust) Regulation |



| EIA Ref. | EM&A | Recommended Mitigation Measures   | Objectives of the<br>Recommended<br>Measure | Who to<br>implement | Location of the | When to implement the | What requirements<br>or standards for th |
|----------|------|---|---|---------------------|-----------------|-----------------------|--|
|          | Ref. |   | & Main Concerns<br>to address               | the<br>measure?     | measure         | measure?              | measure to achieve?                      |
|          |      | concrete, bituminous hardcore materials or metal plates and kept clear of dusty materials; or   |   |                     |                 |                       |  |
|          |      | <ul> <li>Unpaved parts of the road should be sprayed with water or a dust<br/>suppression chemical so as to keep the entire road surface wet.</li> </ul>  |   |                     |                 |                       |  |
|          |      | Exposed Earth   |   |                     |                 |                       |  |
|          |      | Exposed earth should be properly treated by compaction,<br>hydroseeding, vegetation planting or seating with latex, vinyl,<br>bitumen within six months after the last construction activity on the<br>site or part of the site where the exposed earth lies. |   |                     |                 |                       |  |
|          |      | Loading, Unloading or Transfer of Dusty Materials   |   |                     |                 |                       |  |
|          |      | <ul> <li>All dusty materials should be sprayed with water immediately prior<br/>to any loading or transfer operation so as to keep the dusty<br/>material wet.</li> </ul>   |   |                     |                 |                       |  |
|          |      | Debris Handling   |   |                     |                 |                       |  |
|          |      | <ul> <li>Any debris should be covered entirely by impervious sheeting or<br/>stored in a debris collection area sheltered on the top and the three<br/>sides.</li> </ul>  |   |                     |                 |                       |  |
|          |      | <ul> <li>Before debris is dumped into a chute, water should be sprayed so<br/>that it remains wet when it is dumped.</li> </ul>   |   |                     |                 |                       |  |
|          |      | Transport of Dusty Materials  |   |                     |                 |                       |  |
|          |      | <ul> <li>Vehicle used for transporting dusty materials/spoils should be<br/>covered with tarpaulin or similar material. The cover should extend<br/>over the edges of the sides and tailboards.</li> </ul>  |   |                     |                 |                       |  |
|          |      | Wheel washing   |   |                     |                 |                       |  |
|          |      | Vehicle wheel washing facilities should be provided at each<br>construction site exit. Immediately before leaving the construction<br>site, every vehicle should be washed to remove any dusty<br>materials from its body and wheels.                         |   |                     |                 |                       |  |
|          |      | Use of vehicles   |   |                     |                 |                       |  |
|          |      | Immediately before leaving the construction site, every vehicle<br>should be washed to remove any dusty materials from its body<br>and wheels.  |   |                     |                 |                       |  |
|          |      | Where a vehicle leaving the construction site is carrying a load of<br>dusty materials, the load should be covered entirely by clean<br>impervious sheeting to ensure that the dusty materials do not leak<br>from the vehicle.                               |   |                     |                 |                       |  |



| EIA Ref.  | EM&A<br>Ref. | Recommended Mitigation Measures Site hoarding Where a site boundary adjoins a road, street, service lane or other   | Objectives of the<br>Recommended<br>Measure<br>& Main Concerns<br>to address                                     | Who to<br>implement<br>the<br>measure? | Location of the measure    | When to<br>implement the<br>measure? | What requirements<br>or standards for the<br>measure to<br>achieve? |
|-----------|--------------|---|--|--|----------------------------|--------------------------------------|---|
|           |              | area accessible to the public, hoarding of not less than 2.4m high<br>from ground level should be provided along the entire length of<br>that portion of the site boundary except for a site entrance or exit.  |  |  |                            |                                      |   |
|           |              | <ul> <li>Blasting</li> <li>The areas within 30m from the blasting area should be wetted with water prior to blasting.</li> </ul>  |  |  |                            |                                      |   |
| Air Quali | ty Impact (  | Operation)  |  |  |                            |                                      |   |
| 3.5.2.2   | 2.2          | <ul> <li>The following odour containment and control measures will be provided for the proposed sewage treatment work at the BCP site:</li> <li>The treatment work will be totally enclosed. Negative pressure ventilation will be provided within the enclosure to avoid any fugitive odorous emission from the treatment work.</li> <li>Further odour containment will be achieved by covering or confining the sewage channels, sewage tanks, and equipment with potential odour emission.</li> <li>Proper mixing will be provided at the equalization and sludge holding tanks to prevent sewage septicity.</li> <li>Chemical or biological deodorisation facilities with a minimum odour removal efficiency of 90% will be provided to treat potential odorous emissions from the treatment plant including sewage channels / tanks, filter press and screening facilities so as to minimize any potential odour impact to the nearby ASRs.</li> </ul> | To minimize<br>potential odour<br>impact from<br>operation of the<br>proposed sewage<br>treatment work at<br>BCP | DSD                                    | BCP                        | Operation<br>Phase                   | EIA recommendation  |
| Noise Im  | pact (Cons   | truction)   |  |  |                            |                                      |   |
| 4.4.1.4   | 3.1          | Adoption of Quieter PME<br>Use of the recommended quieter PME such as those given in the<br>BS5228: Part 1:2009 and presented in <b>Table 4.14</b> , which can be found<br>in Hong Kong.  | To minimize the<br>construction air-<br>borne noise impact   | Contractors                            | Construction<br>Work Sites | During<br>Construction               | EIA recommendation,<br>EIAO and Noise<br>Control Ordinance<br>(NCO) |



| EIA Ref. | EM&A<br>Ref. | Recommended Mitigation Measures  | Objectives of the<br>Recommended<br>Measure<br>& Main Concerns<br>to address | Who to<br>implement<br>the<br>measure? | Location of the measure    | When to<br>implement the<br>measure? | What requirements<br>or standards for the<br>measure to<br>achieve? |
|----------|--------------|--|--|--|----------------------------|--------------------------------------|---|
| 4.4.1.4  | 3.1          | Use of Movable Noise Barrier<br>The use of movable barrier for certain PME can further alleviate the<br>construction noise impacts. In general, a 5 dB(A) reduction for movable<br>PME and 10 dB(A) for stationary PME can be achieved depending on<br>the actual design of the movable noise barrier. The Contractor shall be<br>responsible for design of the movable noise barrier with due<br>consideration given to the size of the PME and the requirement for<br>intercepting the line of sight between the NSRs and PME. Barrier<br>material with surface mass in excess of 7 kg/m <sup>2</sup> is recommended to<br>achieve the predicted screening effect. | To minimize the<br>construction air-<br>borne noise impact                   | Contractors                            | Construction<br>Work Sites | During<br>Construction               | EIA recommendation,<br>EIAO and NCO                                 |
| 4.4.1.4  | 3.1          | Use of Noise Enclosure/ Acoustic Shed<br>The use of noise enclosure or acoustic shed is to cover stationary PME<br>such as air compressor and concrete pump. With the adoption of the<br>noise enclosure, the PME could be completely screened, and noise<br>reduction of 15 dB(A) can be achieved according to the GW-TM.   | To minimize the<br>construction air-<br>borne noise impact                   | Contractors                            | Construction<br>Work Sites | During<br>Construction               | EIA recommendation,<br>EIAO and NCO                                 |
| 4.4.1.4  | 3.1          | <b>Use of Noise Insulating Fabric</b><br>Noise insulating fabric can be adopted for certain PME (e.g. drill rig, pilling auger etc). The insulating fabric should be lapped such that there are no openings or gaps on the joints. Technical data from manufacturers state that by using the Fabric, a noise reduction of over 10 dB(A) can be achieved on noise level.  | To minimize the<br>construction air-<br>borne noise impact                   | Contractors                            | Construction<br>Work Sites | During<br>Construction               | EIA recommendation,<br>EIAO and NCO                                 |



|  |              |  | Objectives of the   | Who to  |  |                          | What requirements                   |
|--|--------------|--|---|---|--|--------------------------|-------------------------------------|
| EIA Ref.   | EM&A<br>Ref. | Recommended Mitigation Measures  | Recommended<br>Measure  | implement<br>the  | Location of the measure  | When to<br>implement the | or standards for the<br>measure to  |
|  | nei.         |  | & Main Concerns<br>to address   | measure?  | measure  | measure?                 | achieve?                            |
| 4.4.1.4  | 3.1          | Good Site Practice   | To minimize the   | Contractors   | Construction   | During                   | EIA recommendation,                 |
|  |              | The good site practices listed below should be followed during each phase of construction:   | construction air-<br>borne noise impact   |   | Work Sites Construction  | Construction             | EIAO and NCO                        |
|  |              | • Only well-maintained plant should be operated on-site and plant should be serviced regularly during the construction programme;  |   |   |  |                          |                                     |
|  |              | <ul> <li>Silencers or mufflers on construction equipment should be utilized<br/>and should be properly maintained during the construction<br/>programme;</li> </ul>                |   |   |  |                          |                                     |
|  |              | • Mobile plant, if any, should be sited as far from NSRs as possible;  |   |   |  |                          |                                     |
|  |              | <ul> <li>Machines and plant (such as trucks) that may be in intermittent<br/>use should be shut down between work periods or should be<br/>throttled down to a minimum;</li> </ul> |   |   |  |                          |                                     |
|  |              | • Plant known to emit noise strongly in one direction should, wherever possible, be orientated so that the noise is directed away from the nearby NSRs; and                        |   |   |  |                          |                                     |
|  |              | • Material stockpiles and other structures should be effectively utilized, wherever practicable, in screening noise from on-site construction activities.                          |   |   |  |                          |                                     |
| Noise Im   | pact (Oper   | ation)   |   |   |  |                          |                                     |
|  |              | Road Traffic Noise   |   |   |  |                          |                                     |
| Table<br>4.42<br>and<br>Figure<br>4.20.1<br>to<br>4.20.4 | 3.2          | Erection of noise barrier/ enclosure along the viaduct section.  | To minimize the<br>road traffic noise<br>along the<br>connecting road of<br>BCP | Contractor  | Loi Tung and<br>Fanling<br>Highway<br>Interchange                      | Before<br>Operation      | EIAO and NCO                        |
|  |              | Fixed Plant Noise  |   |   |  |                          |                                     |
| Table<br>4.46  | 3.2          | Specification of the maximum allowable sound power levels of the proposed fixed plants during daytime and night-time.  | To minimize the<br>fixed plant noise<br>impact                                  | Managing<br>Authority of<br>the buildings /<br>Contractor | BCP,<br>Administration<br>Building and all<br>ventilation<br>buildings | Before<br>Operation      | EIA recommendation,<br>EIAO and NCO |



| EIA Ref. | EM&A<br>Ref. | Recommended Mitigation Measures   | Objectives of the<br>Recommended<br>Measure<br>& Main Concerns<br>to address  | Who to<br>implement<br>the<br>measure?                    | Location of the measure  | When to<br>implement the<br>measure? | What requirements<br>or standards for the<br>measure to<br>achieve?                                     |
|----------|--------------|---|---|---|--|--------------------------------------|---|
| 4.5.2.4  | 3.2          | <ul> <li>The following noise reduction measures shall be considered as far as practicable during operation:</li> <li>Choose quieter plant such as those which have been effectively silenced;</li> <li>Include noise levels specification when ordering new plant (including chillier and E/M equipment);</li> <li>Locate fixed plant/louver away from any NSRs as far as practicable;</li> <li>Locate fixed plant in walled plant rooms or in specially designed enclosures;</li> <li>Locate noisy machines in a basement or a completely separate building;</li> <li>Install direct noise mitigation measures including silencers, acoustic louvers and acoustic enclosure where necessary; and</li> <li>Develop and implement a regularly scheduled plant maintenance programme so that equipment is properly operated and serviced in order to maintain a controlled level of noise.</li> </ul>   | To minimize the<br>fixed plant noise<br>impact  | Managing<br>Authority of<br>the buildings /<br>Contractor | BCP,<br>Administration<br>Building and all<br>ventilation<br>buildings | Before<br>Operation                  | EIAO and NCO  |
| Water Qu | uality Impa  | ct (Construction)   |   |   |  |                                      |   |
| 5.6.1.1  | 4.1          | <ul> <li>Construction site runoff and drainage</li> <li>The site practices outlined in ProPECC Note PN 1/94 should be followed as far as practicable in order to minimise surface runoff and the chance of erosion. The following measures are recommended to protect water quality and when properly implemented should be sufficient to adequately control site discharges so as to avoid water quality impacts:</li> <li>At the start of site establishment, perimeter cut-off drains to direct off-site water around the site should be constructed with internal drainage works and erosion and sedimentation control facilities implemented. Channels (both temporary and permanent drainage pipes and culverts), earth bunds or sand bag barriers should be provided on site to direct stormwater to silt removal facilities. The design of the temporary on-site drainage system should be undertaken by the Contractor prior to the commencement of</li> </ul> | To control site<br>runoff and<br>drainage; prevent<br>high sediment<br>loading from<br>reaching the<br>nearby<br>watercourses | Contractor  | Construction<br>Works Sites  | Construction<br>Phase                | Practice Note for<br>Professional Persons<br>on Construction Site<br>Drainage (ProPECC<br>Note PN 1/94) |

The dikes or embankments for flood protection should be implemented around the boundaries of earthwork areas.

construction.



| EIA Ref. | EM&A<br>Ref. | Recommended Mitigation Measures  | Objectives of the<br>Recommended<br>Measure | Who to<br>implement<br>the | Location of the measure | When to implement the | What requirements<br>or standards for the<br>measure to |
|----------|--------------|--|---|----------------------------|-------------------------|-----------------------|---|
|          | nei.         |  | & Main Concerns<br>to address               | measure?                   | measure                 | measure?              | achieve?  |
|          |              | Temporary ditches should be provided to facilitate the runoff<br>discharge into stormwater drainage system through a sediment/silt<br>trap. The sediment/silt traps should be incorporated in the<br>permanent drainage channels to enhance deposition rates, if<br>practical.   |   |                            |                         |                       |   |
|          |              | Sand/silt removal facilities such as sand/silt traps and sediment<br>basins should be provided to remove sand/silt particles from runoff<br>to meet the requirements of the TM standards under the WPCO.<br>The design of efficient silt removal facilities should be based on the<br>guidelines in Appendix A1 of ProPECC Note PN 1/94. Sizes may<br>vary depending upon the flow rate. The detailed design of the<br>sand/silt traps should be undertaken by the Contractor prior to the<br>commencement of construction.  |   |                            |                         |                       |   |
|          |              | All drainage facilities and erosion and sediment control structures<br>should be regularly inspected and maintained to ensure proper and<br>efficient operation at all times and particularly during rainstorms.<br>Deposited silt and grit should be regularly removed, at the onset of<br>and after each rainstorm to ensure that these facilities are<br>functioning properly at all times.   |   |                            |                         |                       |   |
|          |              | Measures should be taken to minimize the ingress of site drainage<br>into excavations. If excavation of trenches in wet periods is<br>necessary, they should be dug and backfilled in short sections<br>wherever practicable. Water pumped out from foundation<br>excavations should be discharged into storm drains via silt removal<br>facilities.   |   |                            |                         |                       |   |
|          |              | If surface excavation works cannot be avoided during the wet season (April to September), temporarily exposed slope/soil surfaces should be covered by tarpaulin or other means, as far as practicable, and temporary access roads should be protected by crushed stone or gravel, as excavation proceeds. Interception channels should be provided (e.g. along the crest/edge of the excavation) to prevent storm runoff from washing across exposed soil surfaces. Arrangements should always be in place to ensure that adequate surface protection measures can be safely carried out well before the arrival of a rainstorm. Other measures that need to be implemented before, during and after rainstorms are summarized in ProPECC Note PN 1/94. |   |                            |                         |                       |   |



| EIA Ref. | EM&A<br>Ref. | Recommended Mitigation Measures               | Objectives of the<br>Recommended<br>Measure<br>& Main Concerns<br>to address | Who to<br>implement<br>the<br>measure? | Location of the measure | When to<br>implement the<br>measure? | What requirements<br>or standards for the<br>measure to<br>achieve? |
|----------|--------------|---|--|--|-------------------------|--------------------------------------|---|
|          |              | the erosive potential of surface water flows. |  |  |                         |                                      |   |

All vehicles and plant should be cleaned before leaving a construction site to ensure no earth, mud, debris and the like is deposited by them on roads. An adequately designed and sited wheel washing facility should be provided at construction site exit where practicable. Wash-water should have sand and silt settled out and removed regularly to ensure the continued efficiency of the process. The section of access road leading to, and exiting from, the wheel-wash bay to the public road should be paved with sufficient backfall toward the wheel-wash bay to prevent vehicle tracking of soil and silty water to public roads and drains.

- Open stockpiles of construction materials or construction wastes on-site should be covered with tarpaulin or similar fabric during rainstorms. Measures should be taken to prevent the washing away of construction materials, soil, silt or debris into any drainage system.
- Manholes (including newly constructed ones) should be adequately covered and temporarily sealed so as to prevent silt, construction materials or debris being washed into the drainage system and stormwater runoff being directed into foul sewers.
- Precautions should be taken at any time of the year when rainstorms are likely. Actions should be taken when a rainstorm is imminent or forecasted and actions to be taken during or after rainstorms are summarized in Appendix A2 of ProPECC Note PN 1/94. Particular attention should be paid to the control of silty surface runoff during storm events, especially for areas located near steep slopes.
- Bentonite slurries used in piling or slurry walling should be reconditioned and reused wherever practicable. Temporary enclosed storage locations should be provided on-site for any unused bentonite that needs to be transported away after all the related construction activities are completed. The requirements in ProPECC Note PN 1/94 should be adhered to in the handling and disposal of bentonite slurries.

| 5.6.1.1 | 4.1 | Good site practices for works within water gathering grounds             | To minimize water   | Contractor | Construction     | Construction | ProPECC Note PN |
|---------|-----|--|---------------------|------------|------------------|--------------|-----------------|
|         |     | The following conditions should be complied, if there is any works to be | quality impacts to  |            | Works Sites      | Phase        | 1/94            |
|         |     | carried out within the water gathering grounds:                          | the water gathering |            | within the water |              |                 |
|         |     |  | grounds             |            | gathering        |              |                 |

255228/ENL/ENL/61/C December 2010



| nvironmenta | al Monitc    | pring and Audit Manual   |  |  |                         |                                      |  |
|-------------|--------------|--|--|--|-------------------------|--------------------------------------|--|
| EIA Ref.    | EM&A<br>Ref. | Recommended Mitigation Measures  | Objectives of the<br>Recommended<br>Measure<br>& Main Concerns<br>to address | Who to<br>implement<br>the<br>measure? | Location of the measure | When to<br>implement the<br>measure? | What requirements<br>or standards for th<br>measure to<br>achieve? |
|             | •            | Adequate measures should be implemented to ensure no pollution or siltation occurs to the catchwaters and catchments.  |  |  | grounds                 |                                      |  |
|             | •            | No earth, building materials, oil or fuel, soil, toxic materials or any materials that may possibly cause contamination to water gathering grounds are allowed to be stockpiled on site.   |  |  |                         |                                      |  |
|             | •            | All surplus spoil should be removed from water gathering grounds as soon as possible.  |  |  |                         |                                      |  |
|             | •            | Temporary drains with silt traps should be constructed at the site boundary before the commencement of any earthworks.   |  |  |                         |                                      |  |
|             | •            | Regular cleaning of silt traps should be carried out to ensure proper operation at all time.   |  |  |                         |                                      |  |
|             | •            | All excavated or filled surfaces which have the risk of erosion should always be protected form erosion.   |  |  |                         |                                      |  |
|             | •            | Facilities for washing the wheels of vehicles before leaving the site should be provided.  |  |  |                         |                                      |  |
|             | •            | Any construction plant which causes pollution to catchwaters or<br>catchments due to the leakage of oil or fuel should be removed off<br>site immediately.   |  |  |                         |                                      |  |
|             | -            | No maintenance activities which may generate chemical wastes<br>should be undertaken in the water gathering grounds. Vehicle<br>maintenance should be confined to designated paved areas only<br>and any spillages should be cleared up immediately using<br>absorbents and waste oils should be collected in designated tanks<br>prior to disposal off site. All storm water run-off from these areas<br>should be discharged via oil/petrol separators and sand/silt removal<br>traps. |  |  |                         |                                      |  |
|             | •            | Any soil contaminated with fuel leaked from plant should be<br>removed off site and the voids arising from removal of<br>contaminated soil should be replaced by suitable material approved<br>by the Director of Water Supplies.  |  |  |                         |                                      |  |
|             | •            | Provision of temporary toilet facilities and use of chemicals or insecticide of any kind are subject to the approval of the Director of Water Supplies.  |  |  |                         |                                      |  |

Drainage plans should be submitted for approval by the Director of



| EIA Ref. | EM&A<br>Ref. | Recommended Mitigation Measures  | Objectives of the<br>Recommended<br>Measure<br>& Main Concerns<br>to address | Who to<br>implement<br>the<br>measure? | Location of the measure                            | When to<br>implement the<br>measure? | What requirements<br>or standards for the<br>measure to<br>achieve? |
|----------|--------------|--|--|--|--|--------------------------------------|---|
|          |              | Water Supplies.  |  |  |  |                                      |   |
|          |              | <ul> <li>An unimpeded access through the waterworks access road should<br/>always be maintained.</li> </ul>  |  |  |  |                                      |   |
|          |              | <ul> <li>Earthworks near catchwaters or streamcourses should only be<br/>carried out in dry season between October and March,</li> </ul>   |  |  |  |                                      |   |
|          |              | <ul> <li>Advance notice must be given before the commencement of works<br/>on site quoting WSD's approval letter reference.</li> </ul>   |  |  |  |                                      |   |
| 5.6.1.2  | 4.1          | Good site practices of general construction activities   | To minimize water  | Contractor                             | All construction                                   | Construction phase                   | EIA Recommendation  |
|          |              | Construction solid waste, debris and refuse generated on-site should<br>be collected, handled and disposed of properly to avoid entering any<br>nearby stormwater drain. Stockpiles of cement and other construction<br>materials should be kept covered when not being used.  | y<br>n   |  | works sites  |                                      |   |
|          |              | Oils and fuels should only be stored in designated areas which have<br>pollution prevention facilities. To prevent spillage of fuels and solvents<br>to any nearby stormwater drain, all fuel tanks and storage areas should<br>be provided with locks and be sited on sealed areas, within bunds of a<br>capacity equal to 110% of the storage capacity of the largest tank. The<br>bund should be drained of rainwater after a rain event.   |  |  |  |                                      |   |
| 5.6.1.3  | 4.1          | Sewage effluent from construction workforce  | To minimize water  | Contractor                             | All construction                                   | Construction                         | EIA Recommendation  |
|          |              | Temporary sanitary facilities, such as portable chemical toilets, should<br>be employed on-site where necessary to handle sewage from the<br>workforce. A licensed contractor should be employed to provide<br>appropriate and adequate portable toilets and be responsible for<br>appropriate disposal and maintenance.   | quality impacts  |  | works sites with<br>on-site sanitary<br>facilities | phase                                | and Water Pollution<br>Control Ordinance<br>(WPCO)                  |
| 5.6.1.4  | 4.1          | Hydrogeological Impact   | To minimize water  | Contractor                             | Construction                                       | Construction                         | EIA Recommendation  |
|          |              | Grout injection works would be conducted before blasting, for sealing a<br>limited area around the tunnel with a grout of a suitable strength for<br>controlling the potential groundwater inflows. The pre-injection grouting<br>method would be supplemented by post-injection grouting where<br>necessary to further enhance the groundwater inflow control. On-site<br>treatment for the groundwater ingress pumped out would be required<br>to remove any contamination by grouting materials before discharge<br>off-site. | quality impacts  |  | works sites of<br>the drill and<br>blast tunnel    | phase                                | and WPCO  |
| Water Qu | ality Impa   | ct (Operation)   |  |  |  |                                      |   |
|          |              | No mitigation measure is required.   |  |  |  |                                      |   |
|          |              |  |  |  |  |                                      |   |



| EIA Ref. | EM&A<br>Ref. | Recommended Mitigation Measures   | Objectives of the<br>Recommended<br>Measure<br>& Main Concerns<br>to address | Who to<br>implement<br>the<br>measure? | Location of the measure  | When to<br>implement the<br>measure? | What requirements<br>or standards for the<br>measure to<br>achieve?  |
|----------|--------------|---|--|--|--|--------------------------------------|--|
| Sewage   | and Sewera   | age Treatment Impact (Construction)   |  |  |  |                                      |  |
| 6.7      | 5            | The sewage generated by the on-site workforce should be collected in chemical toilets and disposed of off-site by a licensed waste collector.   | To minimize water<br>quality impacts   | Contractor                             | All construction<br>works sites with<br>on-site sanitary<br>facilities | Construction phase                   | EIA recommendation<br>and WPCO   |
| Sewage a | and Sewera   | age Treatment Impact (Operation)  |  |  |  |                                      |  |
| 6.6.3    | 5            | Sewage generated by the BCP and Chuk Yuen Village Resite will be<br>collected and treated by the proposed on-site sewage treatment facility<br>using Membrane Bioreactor treatment with a portion of the treated<br>wastewater reused for irrigation and flushing within the BCP.   | To minimize water<br>quality impacts   | DSD                                    | BCP  | Operation<br>phase                   | EIA recommendation<br>and WPCO   |
| 6.5.3    | 5            | Sewage generated from the Administration Building will be discharged to the existing local sewerage system.   | To minimize water<br>quality impacts   | DSD                                    | Administration<br>Building   | Operation<br>phase                   | EIA recommendation and WPCO  |
| Waste M  | anagement    | Implication (Construction)  |  |  |  |                                      |  |
| 7.6.1.1  | 6            | <b>Good Site Practices</b><br>Adverse impacts related to waste management such as potential hazard, air, odour, noise, wastewater discharge and public transport as mentioned in section 3.4.7.2 (ii)(c) of the Study Brief are not expected to arise, provided that good site practices are strictly followed. Recommendations for good site practices during the construction activities include: | To minimize<br>adverse<br>environmental<br>impact                            | Contractor                             | Construction<br>works sites<br>(general)                               | Construction<br>Phase                | EIA recommendation<br>Waste Disposal<br>Ordinance; Waste<br>Disposal (Chemical<br>Wastes) (General)<br>Regulation; and<br>ETWB TC(W) No. |
|          |              | <ul> <li>Nomination of an approved person, such as a site manager, to be<br/>responsible for good site practices, arrangements for collection and<br/>effective disposal to an appropriate facility, of all wastes generated<br/>at the site</li> </ul>   |  |  |  |                                      | 19/2005,<br>Environmental<br>Management on<br>Construction Site  |
|          |              | <ul> <li>Training of site personnel in proper waste management and<br/>chemical handling procedures</li> </ul>  |  |  |  |                                      |  |
|          |              | <ul> <li>Provision of sufficient waste disposal points and regular collection<br/>of waste</li> </ul>   |  |  |  |                                      |  |
|          |              | <ul> <li>Dust suppression measures as required under the Air Pollution<br/>Control (Construction Dust) Regulation should be followed as far as<br/>practicable. Appropriate measures to minimise windblown litter and<br/>dust/odour during transportation of waste by covering trucks or in<br/>enclosed containers</li> </ul>   |  |  |  |                                      |  |
|          |              | <ul> <li>General refuse shall be removed away immediately for disposal. As</li> </ul>   |  |  |  |                                      |  |



| EIA Ref. | EM&A<br>Ref. | Recommended Mitigation Measures   | Objectives of the<br>Recommended<br>Measure | Who to<br>implement<br>the | Location of the measure  | When to implement the | What requirements<br>or standards for the<br>measure to |
|----------|--------------|---|---|----------------------------|--------------------------|-----------------------|---|
|          | nei.         |   | & Main Concerns<br>to address               | measure?                   | measure                  | measure?              | achieve?  |
|          |              | such odour is not anticipated to be an issue to distant sensitive receivers   |   |                            |                          |                       |   |
|          |              | <ul> <li>Provision of wheel washing facilities before the trucks leaving the<br/>works area so as to minimise dust introduction from public road</li> </ul>   |   |                            |                          |                       |   |
|          |              | <ul> <li>Covers and water spraying system should be provided for the<br/>stockpiled C&amp;D material to prevent dust impact or being washed<br/>away</li> </ul>   |   |                            |                          |                       |   |
|          |              | <ul> <li>Designate different locations for storage of C&amp;D material to<br/>enhance reuse</li> </ul>  |   |                            |                          |                       |   |
|          |              | <ul> <li>Well planned programme for transportation of C&amp;D material to<br/>lessen the off-site traffic impact. Well planned delivery programme<br/>for offsite disposal and imported filling material such that adverse<br/>noise impact from transporting of C&amp;D material is not anticipated</li> </ul> |   |                            |                          |                       |   |
|          |              | <ul> <li>Site practices outlined in ProPECC PN 1/94 "Construction Site<br/>Drainage" should be adopted as far as practicable, such as<br/>cleaning and maintenance of drainage systems regularly</li> </ul>   |   |                            |                          |                       |   |
|          |              | <ul> <li>Provision of cover for the stockpile material, sand bag or earth<br/>bund as barrier to prevent material from washing away and<br/>entering the drains</li> </ul>  |   |                            |                          |                       |   |
| .6.1.2   | 6            | Waste Reduction Measures  | To reduce the                               | Contractor                 | Construction             | Construction          | EIA recommendation                                      |
|          |              | Good management and control can prevent the generation of a significant amount of waste. Waste reduction is best achieved at the planning and design stage, as well as by ensuring the implementation of good site practices. Recommendations to achieve waste reduction include:                               | quantity of wastes                          |                            | works sites<br>(General) | Phase                 | and Waste Disposal<br>Ordinance                         |
|          |              | <ul> <li>Segregation and storage of different types of waste in different<br/>containers, skips or stockpiles to enhance reuse or recycling of<br/>materials and their proper disposal</li> </ul>   |   |                            |                          |                       |   |
|          |              | <ul> <li>Encourage collection of aluminium cans by providing separate<br/>labelled bins to enable this waste to be segregated from other<br/>general refuse generated by the work force</li> </ul>  |   |                            |                          |                       |   |
|          |              | <ul> <li>Proper storage and site practices to minimise the potential for<br/>damage or contamination of construction materials</li> </ul>   |   |                            |                          |                       |   |
|          |              | Plan and stock construction materials carefully to minimise amount  |   |                            |                          |                       |   |



| EIA Ref. | EM&A<br>Ref. | Recommended Mitigation Measures   | Objectives of the<br>Recommended<br>Measure<br>& Main Concerns  | Who to<br>implement<br>the<br>measure? | Location of the measure                  | When to<br>implement the<br>measure? | What requirements<br>or standards for the<br>measure to<br>achieve?   |
|----------|--------------|---|---|--|--|--------------------------------------|---|
|          |              | of waste generated and avoid unnecessary generation of waste  | to address  |  |  |                                      |   |
|          |              | <ul> <li>In addition to the above measures, specific mitigation measures<br/>are recommended below for the identified waste arising to minimise<br/>environmental impacts during handling, transportation and disposal<br/>of these wastes.</li> </ul>  |   |  |  |                                      |   |
| 7.6.1.3  | 6            | <b>C&amp;D Materials</b><br>In order to minimise impacts resulting from collection and transportation of C&D material for off-site disposal, the excavated materials should be reused on-site as backfilling material as far as practicable. The surplus rock and other inert C&D material would be disposed of at the Government's Public Fill Reception Facilities (PFRFs) at Tuen Mun Area 38 for beneficial use by other projects in the HKSAR as the last resort. C&D waste generated from general site clearance and tree felling works would require disposal to the designated landfill site. Other mitigation requirements are listed below: | To minimize<br>impacts resulting<br>from C&D material   | Contractor                             | Construction<br>Works Sites<br>(General) | Construction<br>Phase                | EIA recommendation;<br>Waste Disposal<br>Ordinance; and<br>ETWB TCW No.<br>31/2004  |
|          |              | <ul> <li>A Waste Management Plan should be prepared and implemented<br/>in accordance with ETWB TC(W) No. 19/2005 Environmental<br/>Management on Construction Site; and</li> <li>In order to monitor the disposal of C&amp;D material and solid wastes<br/>at public filling facilities and landfills, and to control fly-tipping, a<br/>trip-ticket system (e.g. ETWB TCW No. 31/2004) should be<br/>included.</li> </ul>   |   |  |  |                                      |   |
| 7.6.1.4  | 6            | <b>General refuse</b><br>General refuse should be stored in enclosed bins or compaction units separated from other C&D material. A reputable waste collector is to be employed by the Contractor to remove general refuse from the site separately. Preferably an enclosed and covered area should be provided to reduce the occurrence of 'wind blown' litter.   | To minimize<br>impacts resulting<br>from collection and<br>transportation of<br>general refuse for<br>off-site disposal | Contractor                             | Construction<br>works sites<br>(General) | Construction<br>phase                | Waste Disposal<br>Ordinance and Public<br>Health and Municipal<br>Services Ordinance -<br>Public Cleansing and<br>Prevention of<br>Nuisances Regulation |
| 7.6.1.5  | 6            | <b>Chemical waste</b><br>If chemical wastes are produced at the construction site, the Contractor<br>will be required to register with the EPD as a chemical waste producer<br>and to follow the guidelines stated in the <i>Code of Practice on the</i><br><i>Packaging, Labelling and Storage of Chemical Wastes.</i> Good quality<br>containers compatible with the chemical wastes should be used, and<br>incompatible chemicals should be stored separately. Appropriate labels<br>should be securely attached on each chemical waste container<br>indicating the corresponding chemical characteristics of the chemical                         | To minimize<br>impacts resulting<br>from collection and<br>transportation of<br>chemical waste for<br>off-site disposal | Contractor                             | Construction<br>works sites<br>(General) | Construction<br>phase                | Waste Disposal<br>(Chemical Waste)<br>(General) Regulation<br>and Code of Practice<br>on the Packaging,<br>Labelling and Storage<br>of Chemical Wastes  |



### Appendix J

**Implementation Status of Mitigation Measures for Operation Phase** 



| EP/EIA<br>Ref.          | Recommended Mitigation Measures   | Objectives of the<br>Recommended<br>Measures & Main<br>Concern to Address                                  | Who to<br>implement<br>the<br>measures? | Location of the<br>measures               | When to implement the measures? | Implementation<br>Status   | Remarks  |
|-------------------------|---|--|---|---|---------------------------------|----------------------------|--|
| Air Qualit              | ty Impact (Operation)   |  |   |   |                                 |                            |  |
| EP<br>C3.11/<br>3.5.2.2 | <ul> <li>The sewage treatment plant installed for the Project shall be installed at the location shown in Figure 3 of the EP</li> <li>The plant shall be designed with the following odour containment and control measures : <ol> <li><u>Negative Pressure Ventilation</u></li> <li>The treatment plant shall be totally enclosed with negative pressure ventilation to avoid odorous emission from the treatment works. The tanks will be connected to deodorisation facilities designed for a minimum removal of 90% directly to eliminate odour problem.</li> </ol> </li> <li>Total Containment of Sewage <u>Channels</u> <ol> <li>air-tight cover shall be installed to sewage channels, sewage tanks, and equipment with potential odour emission and the trapped gases shall be collected by air handling</li> </ol> </li> </ul> | To minimize potential<br>odour impact from<br>operation of the<br>proposed sewage<br>treatment work at BCP | DSD                                     | Sewage<br>Treatment Plant<br>(STP) at BCP | Operation Phase                 | Implemented<br>Implemented | STP was implemented at<br>BCP and it was handover<br>to DSD on 29 July 2019<br>for operation.<br>The STP was enclosed<br>with negative pressure<br>ventilation and the tanks<br>are connected to<br>deodorisation facilities.<br>The underground sewage<br>tank, sewage channel and<br>potential odour emission<br>with air tight cover and<br>were connected to<br>deodorisation facilities |
|                         |   |  |   |   |                                 |                            | were connected to deodorisation facilities.  |



| EP/EIA<br>Ref.  | Recommended Mitigation Measures   | Objectives of the<br>Recommended<br>Measures & Main<br>Concern to Address    | Who to<br>implement<br>the<br>measures? | Location of the<br>measures                    | When to implement the measures? | Implementation<br>Status | Remarks   |
|---|---|--|---|--|---------------------------------|--------------------------|---|
|   | (b) Gravity sewer, equalization and<br>sludge holding tanks shall be<br>designed with suitable sewer distance<br>and retention time to prevent sewage<br>septicity.   |  |   |  |                                 |                          |   |
|   | <ul> <li>3. <u>Deodorisation</u></li> <li>(a) Deodorisation facilities at the sewage treatment plant shall be designed with a minimum odour removal efficiency of 90%.</li> </ul>   |  |   |  |                                 | Implemented              | The deodorisation<br>facilities was monitored<br>by control room to<br>ensure odour removal<br>efficiency of 90%. |
| Noise Impa  | act (Operation)   |  |   |  |                                 |                          |   |
| ]   | Road Traffic Noise  |  |   |  |                                 |                          |   |
| EP C3.5 /<br>Table<br>4.42 and<br>Figure<br>4.20.1 to<br>4.20.4 | <ul> <li>Erection of noise barrier/ enclosure along the viaduct section.</li> <li>To mitigate the traffic noise impact arising from the operation of the Project, the noise mitigation measures shall be implemented in accordance with Fig 4, 5, 6 and 7 attached to the EP, or otherwise approved by the Director subject to the submission of a Noise Mitigation Plan by the Permit Holder to cater for the final layout and design of the Project.</li> </ul> | To minimize the road<br>traffic noise along the<br>connecting road of<br>BCP | Contractor                              | Loi Tung and<br>Fanling Highway<br>Interchange | Before Operation                | Implemented              | Noise barriers were<br>installed in accordance<br>with the Noise<br>Mitigation Plan.                              |
|   | Fixed Plant Noise   |  | <u> </u>                                | <u> </u>                                       |                                 |                          |   |



| EP/EIA<br>Ref.<br>Table<br>4.46 | Recommended Mitigation Measures         Specification of the maximum allowable sound power levels of the proposed fixed plants during daytime and night-time.  | Objectives of the<br>Recommended<br>Measures & Main<br>Concern to Address<br>To minimize the fixed<br>plant noise impact | Who to<br>implement<br>the<br>measures?<br>Managing<br>Authority of<br>the buildings | Location of the<br>measures<br>BCP,<br>Administration<br>Building (Admin | When to implement<br>the measures?<br>Before Operation | Implementation         Status         BCP not yet         commenced         Implemented in   | Remarks |
|---------------------------------|--|--|--|--|--|--|---------|
|                                 |  |  | / Contractor   | bldg.) and all<br>ventilation<br>buildings                               |  | Admin bldg. and<br>all ventilation<br>buildings  |         |
| 4.6.2                           | Commissioning test should be conducted<br>for all major fixed noise sources to ensure<br>compliance of the operational for all<br>major fixed noise sources before<br>operation.   | To minimize the fixed<br>plant noise impact  | Managing<br>Authority of<br>the buildings<br>/ Contractor                            | BCP,<br>Administration<br>Building and all<br>ventilation<br>buildings   | Before Operation                                       | BCP not yet<br>commenced<br>Implemented in<br>Admin bldg. and<br>all ventilation<br>buildings  |         |
| 4.5.2.4                         | <ul> <li>The following noise reduction measures shall be considered as far as practicable during operation:</li> <li>Choose quieter plant such as those which have been effectively silenced;</li> <li>Include noise levels specification when ordering new plant (including chillier and E/M equipment);</li> </ul> | To minimize the fixed<br>plant noise impact  | Managing<br>Authority of<br>the buildings<br>/ Contractor                            | BCP,<br>Administration<br>Building and all<br>ventilation<br>buildings   | Before Operation                                       | BCP not yet<br>commenced<br>Implemented in<br>Admin bldg. and<br>all ventilation<br>buildings<br>BCP not yet<br>commenced<br>Implemented in<br>Admin bldg. and<br>all ventilation<br>buildings |         |
|                                 | • Locate fixed plant/louver away from any NSRs as far as practicable;  |  |  |  |  | BCP not yet<br>commenced<br>Implemented in<br>Admin bldg. and<br>all ventilation   |         |



| EP/EIA<br>Ref. | Recommended Mitigation Measures  | Objectives of the<br>Recommended<br>Measures & Main<br>Concern to Address | Who to<br>implement<br>the<br>measures? | Location of the<br>measures | When to implement the measures? | Implementation<br>Status   | Remarks |
|----------------|--|---|---|-----------------------------|---------------------------------|--|---------|
|                |  |   |   |                             |                                 | buildings  |         |
|                | • Locate fixed plant in walled plant rooms or in specially designed enclosures;  |   |   |                             |                                 | BCP not yet<br>commenced<br>Implemented in<br>Admin bldg. and<br>all ventilation                           |         |
|                | • Locate noisy machines in a basement<br>or a completely separate building;  |   |   |                             |                                 | buildings<br>BCP not yet<br>commenced<br>Implemented in<br>Admin bldg. and<br>all ventilation<br>buildings |         |
|                | • Install direct noise mitigation measures including silencers, acoustic louvers and acoustic enclosure where necessary; and;  |   |   |                             |                                 | BCP not yet<br>commenced<br>Implemented in<br>Admin bldg. and<br>all ventilation<br>buildings              |         |
|                | • Develop and implement a regularly<br>scheduled plant maintenance<br>programme so that equipment is<br>properly operated and serviced in<br>order to maintain a controlled level<br>of noise. |   |   |                             |                                 | BCP not yet<br>commenced<br>Implemented in<br>Admin bldg. and<br>all ventilation<br>buildings              |         |
| Sewage a       | order to maintain a controlled level   | 2   |   |                             |                                 | all ventilation  |         |



| EP/EIA<br>Ref. | Recommended Mitigation Measures  | Objectives of the<br>Recommended<br>Measures & Main<br>Concern to Address   | Who to<br>implement<br>the<br>measures? | Location of the<br>measures             | When to implement the measures? | Implementation<br>Status  | Remarks   |
|----------------|--|---|---|---|---------------------------------|---------------------------|---|
| 6.6.3          | Sewage generated by the BCP and Chuk<br>Yuen Village Resite will be collected and<br>treated by the proposed on-site sewage<br>treatment facility using Membrane<br>Bioreactor treatment with a portion of the<br>treated wastewater reused for irrigation<br>and flushing within the BCP.   | To minimize water<br>quality impacts  | DSD                                     | BCP                                     | Operation phase                 | Implemented               | STP was implemented at<br>BCP and it was handover<br>to DSD on 29 July 2019<br>for operation. |
| 6.5.3          | Sewage generated from the<br>Administration Building will be<br>discharged to the existing local sewerage<br>system.   | To minimize water<br>quality impacts  | DSD                                     | Administration<br>Building              | Operation phase                 | Implemented               |   |
| Waste Ma       | nagement (Operation Phase)   | I   |   |   |                                 | 1                         |   |
| 7.6.2.1        | General refuse<br>General refuse should be collected on<br>daily basis and delivered to the refuse<br>collection point accordingly. A reputable<br>waste collector should be employed to<br>remove general refuse regularly to avoid<br>odour nuisance or pest and vermin<br>problem. Recycling containers are<br>recommended to be provided to<br>encourage recycling of aluminium cans<br>and waste paper. | To minimize impacts<br>resulting from<br>collection and<br>transportation of<br>general refuse for<br>off-site disposal | Managing<br>Authority of<br>the BCP     | BCP and its<br>Associated<br>facilities | Operation phase                 | BCP not yet<br>commenced. | NA  |

#### Agreement No. CE 45/2008 (CE) Liantang/Heung Yuen Wai Boundary Control Point and Associated Works 30<sup>th</sup> Quarterly Environmental Monitoring and Audit Summary Report – (November 2020 to January 2021)



| EP/EIA<br>Ref. | Recommended Mitigation Measures   | Objectives of the<br>Recommended<br>Measures & Main<br>Concern to Address   | Who to<br>implement<br>the<br>measures? | Location of the measures                | When to implement the measures? | Implementation<br>Status  | Remarks |
|----------------|---|---|---|---|---------------------------------|---------------------------|---------|
| 7.6.2.2        | <ul> <li>Chemical waste</li> <li>Register with the EPD as a chemical waste producer should be made and guidelines stated in the <i>Code of Practice on the Packaging</i>, <i>Labelling and Storage of Chemical Wastes</i> should be followed.</li> <li>Good quality containers compatible with the chemical wastes should be used, and incompatible chemicals should be stored separately. Appropriate labels should be securely attached on each chemical waste container indicating the corresponding chemical characteristics of the chemical waste, such as explosive, flammable, oxidizing, irritant, toxic, harmful, corrosive, etc. Licensed collector should be deployed to transport and dispose of the chemical waste Treatment Centre, or licensed facilities, in accordance with the Waste Disposal (Chemical Waste) (General) Regulation.</li> </ul> | To minimize impacts<br>resulting from<br>collection and<br>transportation of<br>chemical waste for<br>off-site disposal | Managing<br>Authority of<br>the BCP     | BCP and its<br>associated<br>facilities | Operation phase                 | BCP not yet<br>commenced. | NA      |



| EP/EIA<br>Ref.   | Recommended Mitigation Measures  | Objectives of the<br>Recommended<br>Measures & Main<br>Concern to Address | Who to<br>implement<br>the<br>measures? | Location of the<br>measures                    | When to implement the measures?  | Implementation<br>Status  | Remarks  |
|------------------|--|---|---|--|--|---|--|
| <b>Ecologica</b> | <u>l Impact</u>  |   |   |  |  |   |  |
| 9.8              | <ul> <li>Mitigation to Anthropogenic</li> <li>Disturbance</li> <li>Buffer planting shall be provided<br/>for screening the proposed<br/>structures and associated facilities.</li> </ul>   | To screen the<br>Proposed structures<br>and associated<br>facilities.     | Contractors                             | Contractors                                    | In proximity to<br>proposed new<br>development structures<br>and associated<br>facilities. | Refer to OM4<br>below   | N/A  |
| 9.8              | <ul> <li>Mitigation to Habitat Fragmentation</li> <li>Landscape fragmentation should be kept to a minimum and key wildlife routes preserved as far as possible (i.e. OM1 of EM&amp;A Manual Chapter 10).</li> <li>Provision of landscape plantings (i.e. OM3-7 of EM&amp;A Manual Chapter 10)</li> </ul> | To minimize the<br>obstruction on<br>wildlife movement                    | Contractors                             | All viaduct<br>sections                        | Operation phase  | Refer to OM1<br>below.<br>Refer to OM3 to 7<br>below.                       | N/A  |
| EP C3.6          | All measures recommended in<br>the Vegetation Survey Report, updated<br>Woodland Compensation Plan and the<br>Habitat Creation and Management Plan<br>approved under Condition 2.8, 2.9 and<br>2.10 of this Permit respectively shall be<br>fully implemented and thereafter<br>maintained.              | N/A   | N/A                                     | N/A  | Operation phase  | Implemented.  |  |
| EP C3.7          | To reduce collisions from birds, the design of noise barriers shall avoid/minimize the use of transparent / reflective materials or adopt bird-friendly design on such surfaces.   | To avoid bird<br>mortality due to<br>collision with noise<br>barrier      | Contractor                              | Locations with<br>erection of noise<br>barrier | During detailed<br>design and<br>construction<br>phases                                    | Implemented in<br>Designed,<br>construction phase<br>and operation<br>phase | The steel works of noise<br>barrier was painted in<br>different tone of mat<br>finished green and avoid<br>use of transparent /<br>reflective materials. |



| EP/EIA<br>Ref. | Recommended Mitigation Measures   | Objectives of the<br>Recommended<br>Measures & Main<br>Concern to Address                         | Who to<br>implement<br>the<br>measures? | Location of the<br>measures                | When to implement the measures?                                 | Implementation<br>Status  | Remarks   |
|----------------|---|---|---|--|---|---|---|
| Landscap       | e, Visual and Glare Impact  |   |   | _  |   |   |   |
| 3.8            | (OM1) Detailed Design Considerations<br>Detailed design of development<br>components should aim to reduce<br>landscape footprint and visibility of<br>structures. The area allowed for any<br>development components should be<br>reduced to a practical minimum.   | To reduce architectural<br>footprint on the land<br>and minimize visibility<br>of structures.     | Detailed<br>designer/<br>Consultants    | Proposed new<br>development<br>structures. | During Detailed<br>Design &<br>Construction/<br>Operation Phase | Implemented in<br>Designed and<br>construction phase                                | The detail landscape<br>design of the project is<br>divided into 3 packages<br>as described in the<br>Landscape Plan. |
| 3.8            | <b>(OM2) Aesthetically Pleasing Design</b><br>The form, textures, finishes and colours<br>of the proposed development components<br>should be compatible with the existing<br>surroundings. Light earthy tone colours<br>such as shades of green, shades of grey,<br>shades of brown and off-white may be<br>utilised where technically feasible to<br>reduce the visibility of the development<br>components, including all roadwork,<br>buildings and noise barriers etc. To<br>further improve visual amenity, natural<br>building materials such as stone and<br>timber, should be preferably adopted for<br>architectural features, where technically<br>feasible. | To reduce visibility of<br>structures and increase<br>their compatibility<br>with the surrounding | Detailed<br>designer/<br>Consultants    | Proposed new<br>development<br>structures. | During Detailed<br>Design &<br>Construction/<br>Operation Phase | Implemented in<br>Designed and<br>construction.<br>Implement in<br>operation phase. |   |
| 3.8            | (OM3) Compensatory Planting<br>All compensatory planting of trees is to<br>be carried out in accordance with ETWB<br>TCW No. 03/2006.   | To compensate for loss<br>of trees and some<br>shrubs due to the<br>Project.                      | Contractors                             | Proposed new<br>development<br>structures. | During Construction/<br>Operation Phase                         | Implemented   |   |
| 3.8            | (OM4) Buffer Tree Planting  | To screen the proposed  | Contractors                             | In proximity to                            | During Construction/  | Implemented   |   |



| EP/EIA<br>Ref. | Recommended Mitigation Measures   | Objectives of the<br>Recommended<br>Measures & Main<br>Concern to Address           | Who to<br>implement<br>the<br>measures? | Location of the<br>measures  | When to implement the measures?         | Implementation<br>Status | Remarks |
|----------------|---|---|---|--|---|--------------------------|---------|
|                | Tree planting shall be provided to screen<br>the proposed structures and associated<br>facilities. In addition, the compensatory<br>shrub and ground cover planting detailed<br>in OM4 will provide screening and<br>improve compatibility with the<br>surrounding environment.                         | structures and<br>associated facilities<br>including roads.                         |   | proposed new<br>development<br>structures and<br>associated<br>facilities. | Operation Phase                         |                          |         |
| 3.8            | (OM5) Aesthetic Improvement<br>Planting - Viaduct Structure<br>Planters will be provided for trailer<br>planting to soften the hard, straight edges<br>of the viaduct. Where space allows for<br>planters, climbers are proposed to cover<br>vertical, hard surfaces of the piers.                      | To soften the hard<br>edges on the viaduct<br>and maximize<br>greening opportunity. | Contractors                             | Viaduct<br>Structure.  | During Construction/<br>Operation Phase | Implemented              |         |
| 3.8            | (OM6) Aesthetic Improvement<br>Planting – under Viaduct<br>Shade tolerant plant will be planted,<br>where light is insufficient, to improve<br>value of areas under viaducts.   | To soften the hard<br>edges on the viaduct<br>and maximize<br>greening opportunity. | Contractors                             | Viaduct<br>Structure.  | During Construction/<br>Operation Phase | Implemented              |         |
| 3.8            | <b>(OM7) Landscaped Slope</b><br>Where existing hillside slopes are anticipated to be modified (eg cut slope at the portals of the tunnel sections and embankments along the alignment) the final slope surface will be landscaped by hydroseeding, tree or shrub planting where slope gradient allows. | To prevent soil erosion<br>and reduce visible<br>impact of man-made<br>slopes.      | Contractors                             | Construction Site<br>Works.  | During Construction/<br>Operation Phase | Implemented              |         |
| 3.8            | (OM8) Green Roof<br>Green roofing should be established on  | To reduce exposure to untreated concrete  | Contractors                             | Proposed new buildings.  | During Construction/<br>Operation Phase | Implemented              |         |



| EP/EIA<br>Ref. | Recommended Mitigation Measures  | Objectives of the<br>Recommended<br>Measures & Main<br>Concern to Address  | Who to<br>implement<br>the<br>measures? | Location of the<br>measures                                      | When to implement<br>the measures?      | Implementation<br>Status | Remarks |
|----------------|--|--|---|--|---|--------------------------|---------|
|                | proposed buildings to reduce exposure to<br>untreated concrete surfaces and mitigate<br>visual impact to VSRs at high levels.  | surfaces, reduce visual<br>impact to VSRs at<br>high levels and<br>maximize greening<br>opportunity.   |   |  |   |                          |         |
| 3.8            | (OM9) Vertical Greening<br>Vertical planting should be established to<br>soften the hard, vertical surfaces of the<br>proposed development components.<br>These components will include walls of<br>administration and ventilation buildings,<br>retaining walls and road abutments. | To reduce visible<br>impact of proposed<br>new structures and<br>facilities and<br>maximize greening<br>opportunity.   | Contractors                             | Proposed new<br>development<br>structures.                       | During Construction/<br>Operation Phase | Implemented              |         |
| 3.8            | <b>(OM10) Roadside Amenity Planting</b><br>Roadside amenity planting should be<br>provided, to enhance the landscape and<br>visual quality of the existing and<br>proposed transport routes and car parks.   | To soften edges of the<br>proposed engineer<br>structures and<br>associated facilities<br>and enhance the<br>landscape and visual<br>quality of the existing<br>and proposed road. | Contractors                             | Proposed new<br>development<br>structures.                       | During Construction/<br>Operation Phase | Implemented              |         |
| 3.8            | <b>(OM11) Reinstatement</b><br>Certain areas unavoidably disturbed by<br>the Project will be reprovisioned.  | Particularly aimed at<br>temporarily disturbed<br>areas, to reduce long<br>term impact on<br>landscape.  | Contractors                             | Construction Site<br>Works.                                      | During Construction/<br>Operation Phase | Implemented              |         |
| 3.8            | <b>(OM12) Light Control</b><br>Street and night time lighting glare will<br>be controlled to minimize glare impact to<br>adjacent VSRs during the operation stage.   | To minimize glare<br>impact to adjacent<br>VSRs.   | Contractors                             | Lit areas around<br>proposed new<br>development<br>buildings and | During Operation<br>Phase               | Implemented              |         |



| EP/EIA | <b>Recommended Mitigation Measures</b>   | Objectives of the         | Who to      | Location of the  | When to implement    | Implementation | Remarks |
|--------|--|---------------------------|-------------|------------------|----------------------|----------------|---------|
| Ref.   |  | Recommended               | implement   | measures         | the measures?        | Status         |         |
|        |  | Measures & Main           | the         |                  |                      |                |         |
|        |  | <b>Concern to Address</b> | measures?   |                  |                      |                |         |
|        |  |                           |             | along roads.     |                      |                |         |
| 3.8    | (OM13) Reprovisioned LCSD Garden         | To compensate for loss    | Contractors | Contractors Near | During Construction/ | Implemented    |         |
|        | The Open Space of Wo Keng Shan public    | of Open Space due to      |             | existing Wo      | Operation Phase      |                |         |
|        | garden falls within the Project Site and | the Project.              |             | Keng Shan        |                      |                |         |
|        | will be reprovisioned to reprovide the   |                           |             | public garden,   |                      |                |         |
|        | amenities of the garden on a one to one  |                           |             | subject to       |                      |                |         |
|        | basis.                                   |                           |             | confirmation by  |                      |                |         |
|        |  |                           |             | CEDD and         |                      |                |         |
|        |  |                           |             | LCSD             |                      |                |         |