

CASTLE PEAK POWER COMPANY LIMITED

Enhanced Ash Utilisation and Water Management Facilities at Castle Peak Power Station

Monthly Audit Report for April 2020

May 2020

AECOM ASIA CO. LTD.

Disclaimer:

This report is prepared for **Castle Peak Power Company Limited** (**CAPCO**) and is given for its sole benefit in relation to and pursuant to **Enhanced Ash Utilisation and Water Management Facilities at Castle Peak Power Station** and may not be disclosed to, quoted to or relied upon by any person (other than **CAPCO**) without our prior written consent. No person other than **CAPCO** into whose possession a copy of this report comes may rely on this report without our express written consent and **CAPCO** may not rely on it for any purpose other than as described above.

Table of Contents

Page

1	INTRO	DUCTION	1
	1.1 1.2 1.3	Project Background Purpose of the Report Report Structure	1 1 1
2	PROJ	ECT INFORMATION	2
	2.1	Site Description	2
	2.2	Construction Programme and Activities	2
	2.3	Status of Environmental Licences, Notification and Permits	2
3	ENVIR	ONMENTAL SITE INSPECTION	3
	3.1	Environmental Site Inspection	3
4	IMPLE	MENTATION STATUS OF ENVIRONMENTAL MITIGATION MEASURES	3
5	CONC	LUSION	4

List of Tables

Table 2.1	Status of Environmental Licences, Notifications and Permits
Table 3.1	Observations and Recommendations of Site Audit

List of Appendices

- Appendix A Location Plan of Key Project Components (2017 Scheme)
- Appendix B Construction Programme
- Environmental Audit Records
- Appendix C Appendix D Summary of Implementation Status of Environmental Mitigation Measures

1 INTRODUCTION

1.1 Project Background

- 1.1.1 Pursuant to the Environmental Impact Assessment Ordinance (EIAO), the Director of Environmental Protection (DEP) granted an environmental permit (No. EP-441/2012) to the Castle Peak Power Company Limited (CAPCO) on 23 July 2012 to construct and operate the designated project for Enhanced Ash Utilisation and Water Management Facilities at Castle Peak Power Station (hereinafter referred to as "the Project"). An application for variation of environmental permit (VEP) was subsequently made and the revised EP (No: EP-441/2012/A) was issued by DEP on 29 June 2018.
- 1.1.2 CAPCO appointed AECOM Asia Company Limited (AECOM) as the Independent Checker (IC) to undertake environmental audit work for the Project.

1.2 Purpose of the Report

1.2.1 Under the EP Condition 2.3, the audit for the implementation of all mitigation measures recommended in the Project Profile (Register No. PP-468/2012) commenced in November 2019. This is the sixth Monthly Audit Report which summarises the audit findings for the Project during the reporting period from 1 to 30 April 2020.

1.3 Report Structure

- 1.3.1 This Monthly Audit Report is organised as follows:
 - Section 1: Introduction
 - Section 2: Project Information
 - Section 3: Environmental Site Inspection
 - Section 4: Implementation Status of Environmental Mitigation Measures
 - Section 5: Conclusions

2 **PROJECT INFORMATION**

2.1 Site Description

2.1.1 The Project site is located within the boundary of the existing Castle Peak Power Station (CPPS). The locations of the key project components are shown in **Appendix A**.

2.2 Construction Programme and Activities

- 2.2.1 The major construction activity undertaken in the reporting month is removal of construction waste due to demolition of the two existing silos and its associated works.
- 2.2.2 The major construction activities for the coming month includes:
 - Conduct the plate load test for the foundation of a Pulverized Fuel Ash (PFA) Silo;
 - Conduct the foundation works for construction of a PFA Silo; and
 - Erect hoarding for enhancement works to water management facilities.
- 2.2.3 The construction programme for the construction of PFA is presented in **Appendix B.**

2.3 Status of Environmental Licences, Notification and Permits

2.3.1 Relevant environmental licences, permits and/or notifications on environmental protection for this Project and valid in the reporting month are summarised in **Table 2.1**.

Table 2.1 Status of Environmental Licences, Notifications and Permits

Permit / Licence No. / Notification/ Reference	Valid F	Valid Period		Remarks
No.	From	То		
Environmental Permit			<u>.</u>	
EP-441/2012/A	29 June 2018		Valid	
Billing Account for Cons	struction Waste D	Disposal		
7033071	25 January 2019		Valid	
Notification Under Air Po	ollution Control (Construction D	ust) Regulation	
444243	15 April 2019		Valid	

3 ENVIRONMENTAL SITE INSPECTION

3.1 Environmental Site Inspection

- 3.1.1 Site inspections were carried out by the IC on a bi-weekly basis to monitor the implementation of mitigation measures for the Project.
- 3.1.2 In the reporting month, the site inspection was carried out on 6 and 24 April 2020, respectively. Both IC inspections were conducted jointly with the Contractor. No non-compliance was recorded during the site inspections. Findings and recommendations for the site inspection in this reporting month are summarised as follows and details of observations recorded during the site inspections are presented in **Appendix C**.
 - 6 April 2020:
 - No specific observation was identified in this inspection.
 - 24 April 2020:
 - No specific observation was identified in this inspection.
- 3.1.3 All follow-up actions requested by IC during the site inspections were taken as reported by the Contractor and confirmed by the IC in the subsequent site inspection conducted during the reporting month. There is no outstanding follow-up action at the time of this report.

4 IMPLEMENTATION STATUS OF ENVIRONMENTAL MITIGATION MEASURES


4.1.1 The Contractor has implemented all the relevant environmental mitigation measures as recommended in the Project Profile. The implementation status of the environmental mitigation measures during the reporting period is summarised in **Appendix D**.

5 CONCLUSION

- 5.1.1 Two environmental site inspections were carried out for the Project in the reporting month of April 2020. No non-compliance was recorded during the site inspections. Based on the observations during the site inspections, the Contractor has implemented all the relevant environmental mitigation measures as recommended in the Project Profile (Register No. PP-468/2012).
- 5.1.1 Referring to the information provided by the Contractor, no complaint, notification of summons and successful prosecution was received in the reporting month.

Appendix A

Location Plan of Key Project Components (2017 Scheme)



Source: Environmental Review Report of "Enhanced Ash Utilisation and Water Management Facilities at castle Peak Power Station", January 2018, Castle Peak Power Company Limited

Appendix B

Construction Programme

J9589_Construction of Ash Silo and the Associated E&M Plants & Equipment for Ash Handling (Master Programme Rev. 3 - September 2019)

Xeeling 義合工程有限公司 YEE HOP ENGINEERING CO., LTD.

Number Numbr Numbr Numbr <th>YEE</th> <th>E HOP ENGINEERING CO., LTD.</th> <th>, c</th> <th></th> <th>1</th> <th></th> <th></th> <th></th>	YEE	E HOP ENGINEERING CO., LTD.	, c		1			
Cartes: Period Cartes: Period Cartes: A	ID Task Name		Start	Finish				2019 2020
Cartes: Period Cartes: Period Cartes: A						Feb Ma	r Apr	May Jun Jul Aug Sep Oct Nov Dec Jan Feb Mar Apr May Jun Jul Aug Sep Oct Nov Dec
Sie Pracease Design Weits de Statute Registermits Te 14209 The 6020 206 Design Weits Schweite de Charles (and and and and and and and and and and	Contract F	Period	Thu 14/2/19	Fri 1/1/21			, M5	M4 M5 M0 M7 M6 M9 M10 M11 M12 M13 M14 M15 M10 M17 M18 M19 M20 M21 M22 M23
Design Solution and Statuston The 124.99 The 6820 The 6820 <t< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td>_</td><td></td></t<>							_	
Describing Works Schemissin To 126/09 Pi 105/09 Pi 105/							÷÷	
Design Shamason of Decading Annulation Arounder (19m) The 1979 Weil (1987) State BD Apergonic AC Sconst to Londing Works The 104/9 File (1989) State BD Apergonic AC Sconst to Londing Works The 104/9 File (1989) State BD Creame to Sconst to Londing Works The 104/9 File (1999) State BD Creame to Sconst to Londing Works The 104/9 State State BD Creame to Sconst to Londing Works The 104/9 Works State File Sconst The 104/9 Works State State State Sconst The 104/9 Works The 104/9 Works Decoding of Sconst Decade Deca							<u> </u>	
BD Approval & Concent for Decembra Wess The II (14/9) Fe [10/97) Fe								
Production & Speprisourne Works Schemission Ski 11/579 The 6500 Pro- BD Consent for Speprisourne Works Schemission Ski 11/579 The 6500 Pro- BD Consent for Speprisourne Works Schemission Fil 10/23 The 6500 Pro- BD Consent for Speprisourne Works Schemission Fil 10/23 The 6500 Pro- BD Consent for Speprisourne Construction Works Fil 10/23 The 6500 Pro- BD Consent for Speprisourne Construction Works Fil 10/23 The 6500 Pro- BD Consent for Speprisourne Construction Works Fil 10/23 The 6500 Pro- BD Consent for Speprisourne Construction Conducts Survey The 14/279 Weil 20000 Pro- BD Consent for Speprisourne Construction Conducts Survey The 14/279 Weil 20000 Pro- BD Consent for Speprisourne Construction Conducts Survey The 14/279 Weil 20000 Pro- BD Consent for Speprisourne Construction Constructi								
BDConner for Foundation Works Fit 10/197 Fit 8/692 Fit BDConner for Spectrature Works Fit 10/202 Fit 8/692 Fit Site Aring The 14/219 Mos 30/919 1035 Site Aring The 14/219 Mos 30/919 1035 Fit Aring The 14/219 Mos 30/919 1035 String Aring The 14/219 Mos 30/919 1035 String Aring The 14/219 Mos 30/919 1035 String Aring The 14/219 Mos 30/919 1035 Parts Molinzon The 14/219 Mos 30/919 1035 Parts Molinzon The 23/919 Mos 30/919 1035 Porticition of Chain Lak Text Cold Mas 316 The 23/919 Mos 30/919 1035 Remard of Data Elast Text Cold Mas 316 The 23/919 Mos 30/919 1035 Remard of Data Arks Stol Ark 2 The 23/919 Mos 42/910 1035 Demolition of Apre								
BD Consert for Superstandare Works Fin 10720 The 60201 Org Site Stag The 10219 Web Status Fin 10219 Site Status The 10219 Web Status Fin 10219 December Status Fin 10219 Fin 10219 Fin 10219 December Status <t< td=""><td>Toun</td><td></td><td></td><td></td><td>(C. C.)</td><td></td><td></td><td></td></t<>	Toun				(C. C.)			
Concention Works The 14/219 Mon 300716 388 Six Stay The 14/219 Work 202276 1004 Pre-Construction Conduction Survey The 14/219 Work 202276 1004 U.U. Sarvey The 14/219 Work 202276 1004 Pre-Construction Conduction Survey The 14/219 Work 202276 1004 Instruction Conduction Instrument The 22/219 Work 50/376 1004 Pace Modelination The 22/219 Work 50/376 1004 Removed of Date Hiles or 5 bits Ash 50k A 2 The 22/419 Mon 20/3716 Removed of Date Hiles or 5 bits Ash 50k The 22/419 Mon 20/3716 1004 Removed of Date Hiles or 5 bits Ash 50k The 22/419 Mon 20/3716 1004 Removed of Date Hiles or 5 bits Ash 50k The 22/419 Mon 20/3716 1004 Removed of Ash 50k Al The 22/419 Mon 20/3716 1004 Removed of Ash 50k Al The 22/419 Mon 20/3716 1004 </td <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>								
No. Supp. The 16219 Web 2020/9 Ores Pre-Controcton Condition Survey The 46219 Web 2020/9 Ores Image: Control of Control Survey The 46219 Web 2020/9 Ores Image: Control of Control Survey The 46219 Web 2020/9 Ores Image: Control of Control Survey The 46219 Web 2020/9 Ores Image: Control of Control Survey The 46219 Web 2020/9 Ores Image: Control of Control Survey The 46219 Web 2020/9 Ores Image: Control of Control Survey The 26219 Web 2020/9 Ores The 26219 </td <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>								
ProcessionsCondensSurvey The 142079 Wed 227218 D005 String Ox The 142079 Wed 227218 D005 Description of String EAS Arrows The 120709 Wed 220718 D005 Discretion of String EAS Arrows The 120709 Wed 20718 D005 Discretion of String EAS Arrows The 120709 Wed 20718 D005 Condition Servey of Istring CAS Arrows The 20709 Wed 100718 D05 Condition Servey of Istring CAS Arrows The 20709 Wed 100718 D05 Condition Servey of Istring CAS Arrows The 20709 Stri 10078 Not 10078 Description of Arbox Shing At A A The 20709 Stri 10078 Not 10078 Not 10078 Description of Arbox Shing At A A The 20709 Stri 10078 Not 10078 Not 10078 Description of Arbox Shing At A A The 20709 Stri 10079 Not 10078 N	General							
U. U. Survey The 14/2/9 Wei 20/2/9 00% Sening Code The 14/2/9 Wei 20/2/9 00% Parts Medization The 20/2/9 Wei 20/2/9 00% Decontention of Chain Lak Francet Water Barriss The 20/2/9 Wei 20/2/9 00% Decontention Stop of Participa of Neh Ads Stos The 20/2/9 Wei 20/2/9 00% 00% Renoval of Dast Effects of Neh Ads Stos A The 25/2/9 Sta 16/01 00% 00% Demolition of Aprentage Sta 20/21 The 25/2/9 Sta 16/01 00% 00% Demolition of Aprentage Sta 20/21 The 20/21/9 Ned Stop 20/21 Ned								
Installation of monitoring Instrument The 21/21/9 Work 65/10 100% Pant Mohilization The 22/21/9 Work 65/210 100% Beneticon of Lining L&M. Services The 76/10 Work 65/210 100% Descentation of Bating E&M. Services The 12/21/9 Work 65/210 100% Descentation of Bating E&M. Services The 12/21/9 Work 65/210 100% Operation of Chain Lak Free/Water Barries The 12/21/9 Work 65/210 100% Descentation of Stating ASS 10/A 1& A2 The 25/41/9 100% Descentation of ASS 10/A 1& A2 The 25/41/9 100% Descentation of ASS 10/A 1& A2 The 25/41/9 100% Descentation of ASS 10/A 1& A2 The 25/41/9 100% Descentation of Assentation and the ASS 10/A 1& A2 The 25/41/9 100% Descentation of Assentation and the ASS 10/A 1& A2 The 25/41/9 100% Descentation of Assentation and the ASS 10/A 1/A A2 The 25/41/9 100% Descentation of Assentation and the ASS 10/A 1/A A2 The 25/41/9 100% Descentation of Assentation and the ASS 10/A 1/A A2 The 25/41/9 100% Descentation of Assentation and the ASS 10/A 1/A A2 The 25/41/9 100% Descentation of Assentation and the ASS 10/A 1/A A2 The 25/21/9 100% <td>110 0</td> <td></td> <td></td> <td></td> <td></td> <td>×</td> <td></td> <td></td>	110 0					×		
Installation of monitoring Instrument The 21/21/9 Work 65/10 100% Pant Mohilization The 22/21/9 Work 65/210 100% Beneticon of Lining L&M. Services The 76/10 Work 65/210 100% Descentation of Bating E&M. Services The 12/21/9 Work 65/210 100% Descentation of Bating E&M. Services The 12/21/9 Work 65/210 100% Operation of Chain Lak Free/Water Barries The 12/21/9 Work 65/210 100% Descentation of Stating ASS 10/A 1& A2 The 25/41/9 100% Descentation of ASS 10/A 1& A2 The 25/41/9 100% Descentation of ASS 10/A 1& A2 The 25/41/9 100% Descentation of ASS 10/A 1& A2 The 25/41/9 100% Descentation of Assentation and the ASS 10/A 1& A2 The 25/41/9 100% Descentation of Assentation and the ASS 10/A 1& A2 The 25/41/9 100% Descentation of Assentation and the ASS 10/A 1/A A2 The 25/41/9 100% Descentation of Assentation and the ASS 10/A 1/A A2 The 25/41/9 100% Descentation of Assentation and the ASS 10/A 1/A A2 The 25/41/9 100% Descentation of Assentation and the ASS 10/A 1/A A2 The 25/41/9 100% Descentation of Assentation and the ASS 10/A 1/A A2 The 25/21/9 100% <td>000</td> <td></td> <td></td> <td></td> <td></td> <td>X</td> <td></td> <td></td>	000					X		
 Plan Mobilization The 28/210 Weid XMUP Barriers The VAGNUP Weid XMUP Barriers The VAGNUP Weid XMUP Barriers Decondition of Existing according the analysis and associated supporting frames down to existing ground level The VAGNUP Weid XMUP Barriers Condition State A State A A A The VAGNUP Weid XMUP Barriers Condition State A Associated associated asporting frames down to existing ground level The XXUP Weid XMUP Barriers Condition State A Associated asporting frames down to existing ground level The XXUP Weid XMUP Barriers Condition State A Associated in Adv State A A A The 254(4) The VAGNUP Weid XMUP Barriers Demolition of Appendages Sun 254(4) Sun 254(4)	ooun.							
Descenaction of Existing EAM Services Thu 14/870 Wei 10/1919 205 Denolition of existing accessorated supporting frames. down to existing ground level Thu 12/870 Wei 10/1919 205 Removal of Dust Filters of both Ash Sika A A.2 Thu 12/870 Wei 10/1919 205 Denolition of Existing Ash Sik Al & A.2 Thu 12/870 Wei 10/1919 205 Denolition of Approaches Thu 25/970 Wei 10/1919 205 Denolition of Approaches Sun 26/970 Sun 26/970 206 Denolition of Approaches Sun 26/9719 Sun 26/9719 206 Denolition of Stele Supporting France Wei 10/1719 606 Denolition of Stele Supporting France Sun 28/1709 Fri 13/1219 606 Denolition of Stele Supporting France Sun 28/1709 Fri 13/1219 606 Denolition of Stele Supporting France Sun 28/1700 Fri 13/1219 606 Denolition of Stele Supporting France Sun 28/1700 Fri 13/1719 606 D	moun							
Descenaction of Existing EAM Services Thu 14/870 Wei 10/1919 205 Denolition of existing accessorated supporting frames. down to existing ground level Thu 12/870 Wei 10/1919 205 Removal of Dust Filters of both Ash Sika A A.2 Thu 12/870 Wei 10/1919 205 Denolition of Existing Ash Sik Al & A.2 Thu 12/870 Wei 10/1919 205 Denolition of Approaches Thu 25/970 Wei 10/1919 205 Denolition of Approaches Sun 26/970 Sun 26/970 206 Denolition of Approaches Sun 26/9719 Sun 26/9719 206 Denolition of Stele Supporting France Wei 10/1719 606 Denolition of Stele Supporting France Sun 28/1709 Fri 13/1219 606 Denolition of Stele Supporting France Sun 28/1709 Fri 13/1219 606 Denolition of Stele Supporting France Sun 28/1700 Fri 13/1219 606 Denolition of Stele Supporting France Sun 28/1700 Fri 13/1719 606 D	1 Iunit					1		
 Demolition of existing associated supporting frames down to existing ground level The 124/19 Doendition of Lash Rish of both Ash Silos Condition Survey of Interior of Ash Silo A1 Thu 254/19 Menolition of Ash Silo A1 Thu 254/19 Sat LeV19 Mond ASS20 Sat Borling Sat LeV19 Mond ASS20 Sat Borling Sat LeV19 Mond ASS20 Mond								
2 Removal of Dast Filters of both Adv Silss Thu 28/07 906 2 Removal of Dast Filters of both Adv Silss A1 & A2 Thu 28/07 906 2 Demolition of Stating Adv Sils A1 & A2 Thu 28/07 906 2 Demolition of Adv Sils A1 & A2 Thu 28/07 906 2 Demolition of Adv Sils A1 & A2 Thu 28/07 906 2 Demolition of Adv Sils A1 & A2 Thu 28/07 907 2 Demolition of Apendages Sin 15/07 066 2 Demolition of Sils As Hopper Thu 12/17 Thu 12/17 766 2 Demolition of Sils As Sils A1 Nea 29/17 Thu 12/17 766 3 Demolition of Sils As Sils A2 Fri 13/17 Nea 45/20 766 4 Demolition of Sils As Sils A1 Fri 13/17 Nea 45/20 766 5 Demolition of Sils As Sils A2 Fri 13/17 Nea 45/20 766 6 Demolition of Sils As Sils A2 Fri 13/17 Nea 45/20 766 6 Demolition of Sils As Sils A2 Fri 13/120 771/100 766 7 Demolition of Sils As Sils A1							1	
 Condition Survey of Interior of Adv Silo Al & A2 Thu 13/491 Wind 224/49 Nonoblion of Silo Al & A2 Thu 23/491 Silo Al Silo Al Thu 23/491 Silo Al Thu 23/491 Silo Al Thu 23/491 Silo Al Thu 23/491 Silo Al Silo Al						9		
2 Denolition of Basing Adv Sho Al & A2 Thu 25/40/P Mon 4/500 228 0 Denolition of Adv Sho Al Thu 25/40/P Fig 12/202 Adv Sho Fig 12/202 Adv Sho 0 Denolition of Adv Sho Al Thu 25/40/P Fig 12/202 Adv Sho Fig 12/202 Adv Sho 0 Denolition of Adv Sho Al Mon 2/201 Stat 15/6/9 1008 0 Denolition of Sho Al & Poper Thu 1/201 Mon 2/201 Post 16/01/9 Fig 12/202 Mon 2/201 Fig 12/202 Mon 2/201 Post 16/01/9 Fig 12/201 Mon 2/202 Fig 12/201 Fig								
 Denolition of Ash Silo A1 Thu 25/149 Fit 21/220 Appendiated And Construction of Ash Silo A1 Denolition of Ash Silo A1 Denolition of Sel Supporting Frame Sel Sel Sel Sel Sel Sel Sel Sel Sel Sel			Thu 11/4/19	Wed 24/4/19	100%		1 Alert	
 Removal of ash accumulated in Ads Silo Demolition of Appendages Demolition of Sub Supporting Frame Demolition of Silo & Hopper Submission and BD A Chowledgement of BAI4A for Demolition Woeks Submission and BD A Chowledgement of BAI4A for Demolition Woeks Submission and BD A Chowledgement of BAI4A for Demolition Works Fi Si2020 Fi Si2020	2 Demoli	ion of Existing Ash Silo A1 & A2	Thu 25/4/19	Mon 4/5/20	22%		-	
 Demolition of Appendages Bernolition of Meal Sattification Mon 20019 Satt 16/19 Satt 16/10 Satt	3 Demo	olition of Ash Silo A1	Thu 25/4/19	Fri 21/2/20	49%		-	
9 Demolition of Appendages Sun 205/19 Sun 15/19 1006 6 Demolition of Metal Sacifolding The 12/11/9 7us 19/11/9 7 Demolition of Suc Supporting Frame The 12/11/9 7us 19/11/9 8 Demolition of Suc Supporting Frame Fri 13/12/19 066 9 Demolition of Ash Nio AD Fri 13/12/19 066 9 Demolition of Ash Nio AD Fri 13/12/19 066 9 Demolition of Ash Nio AD Fri 13/12/19 066 9 Demolition of Ash Nio AD Fri 13/12/19 066 9 Demolition of Ash Nio AD Fri 13/12/19 066 9 Demolition of Ash Nio AD Fri 13/12/19 066 9 Demolition of Ash Nio AD Fri 13/12/19 076 9 Demolition of Stock Supporting Frame Sat 25/1/20 Fri 14/2/20 9 Demolition of Stock Supporting Frame Sat 25/1/20 Fri 14/2/20 9 Milestone 1 (Do Ale Anis OA 1 San 51/120 Fri 14/2/20 066 9 Submission and BD Acknowledgement of BA14A for Demolition Works San 51/120 Fri 14/2/20 066 9 Milestone 1 (Dev Anis Sto 1 San 51/120 Fri 14/2/20 066 9	24 Re	moval of ash accumulated in Ash Silo	Thu 25/4/19	Sat 25/5/19	100%			
Berection of Metal Scaffolding Mon 29/09 Sun 159/09 60% Demolition of Silo & Hopper The 121/11/19 The 101/19 The 101/19 </td <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>								
2 Demolition of Silo & Hopper The 12/11/19 The 19/11/19 Own 3 Demolition of Salo & Hopper Wel 20/11/19 The 10/12/19 Office 4 Demolition of Salo Silo A2 Fri 13/12/19 Wel 25/12/19 Office 4 Removal of sh accumulated in Ash Silo Wel 29/10/19 100% 5 Demolition of Ash Silo A2 Fri 13/12/19 Wed 29/10/19 100% 6 Eraction of Mala Scaffolding Fri 20/12/19 Fri 20/12/19 Fri 20/12/19 Fri 20/12/19 6 Demolition of Salo Silo A Hopper Sat 25/120 Fri 30/12/19 Fri 41/20 Office 6 Demolition of Salo Silo A Sat 25/120 Fri 34/20 Office Fri 14/20 Office 6 Demolition of Salo Silo A Sat 25/120 Fri 34/20 Office Fri 15/20 Fri 34/20 Office 7 Demolition of Salo Silo A Sat 51/20 Fri 14/20 Office Fri 15/20 Fri 14/20 Office 7 Construction of New Ads Silo A1 Sat 14/20 Fri 14/20 Office Fri 15/20 That 14/20 Office Fri 15/20 That 14							1	
 Bernolition of Steel Supporting Prane Dernolition of Steel Supporting Prane Weid 2011/19 The 10/12/19 Org Dernolition of Ash Silo A2 Fri 13/12/19 Weid 9/10/19 Weid 9/10/19 Dorg Dernolition of Ash Silo A2 Fri 13/12/19 Med 9/10/19 Weid 9/10/19 Dorg Dernolition of Ash Silo A2 Fri 13/12/19 Med 9/10/19 Med 9/10/19 Dorg Dernolition of Ash Silo A2 Fri 13/12/19 Med 9/10/19 Dorg Dernolition of Silo & Hopper Sat 25/120 Fri 20/12/19 Sun 5/12/0 Fri 20/20 Fri 13/20 Fri 20/20 Sun 40/20 Sus 5/120 Fri 13/20 Fri 20/20 Fri 13/20 Fri 20/20 Fri 13/20 Fri 20/20 Fri 13/20 Fri 20/20 Fri 13/20 Fr								
Pernolition of Existing Footings Fri 13/12/19 Wed 25/12/19 0% Domolition of Ash Silo A2 Fri 13/12/19 Mon 45/20 0% Encolition of Appendages Pri 13/12/19 Thu 19/12/19 0% Demolition of Appendages Pri 13/12/19 Thu 19/12/19 0% Erection of Metal Scaffolding Fri 24/120 Fri 24/120 0% Demolition of Stel Supporting Frame Sat 25/120 Fri 24/220 0% Submission and BD Acknowledgement of BA14A for Demolition Works Sat 15/220 Fri 24/220 0% Milestone 1 (305 days from Contract Commencement) Sun 15/12/19 Sun 15/12/19 0% Construction of New Abis ISol A1 Sun 41/020 0% Excavate to Formation Level of Raft Footing Sat 44/20 Fri 13/220 0% Carst Blinding Layer Fri 15/20 Thu 14/5/20 0% Carst Blinding Layer Fri 13/20 Milestone 2 (501 days from Contract Commencement) Thu 68/20 0% Submission and BD Acknowledgement of BA14 for Foundation Works Fri 12/620 Thu 14/5/20 0% Carst Blinding Layer Fri 12/620 Thu 14/5/20 0% Submission a								
2 Demolition of Ash Silo A2 Fri 13/21/9 Mon 4/5/20 0% Removal of sah accumulated in Ash Silo Wed 9/10/19 Wed 9/10/19 Wed 9/10/19 Wed 9/10/19 2 Demolition of Ash Silo A2 Fri 13/21/9 Thi 19/12/19 0% 3 Erection of Metal Scaffolding Fri 20/12/19 Fri 21/12/19 0% 4 Demolition of Sile Klopper Sat 25/120 Fri 14/220 0% 5 Demolition of Skel Supporting Frame Sat 25/120 Fri 14/220 0% 6 Demolition of Skel Supporting Frame Sat 25/120 Fri 14/220 0% 7 Submission and BD Acknowledgement of BA14A for Demolition Works Sat 25/120 Fri 14/220 0% 6 Demolition of New Ash Silo A1 Sun 15/12/19 Sun 15/12/19 0% 0% 7 Excavate to Formation Level of Raft Footing Sat 18/4/20 Thi 17/20 0% 7 Carry out Plate Load Test Fri 15/5/20 Thu 11/5/20 0% 8 Submission and BD Acknowledgement of BA14 for Foundation Works Fri 15/5/20 Thu 11/5/20 0% 7 Garry out Plate Load Test Sin	DU							
1 Removal of ash accumulated in Ash Silo Wed 9/10/19 100% 2 Demolition of Appendages Fri 13/12/19 Thu 19/12/19 0% 2 Demolition of Medi Scaffolding Fri 20/12/19 0% 4 Demolition of Medi Scaffolding Fri 20/12/19 0% 5 Demolition of Stole Supporting Frame Sat 25/12/0 0% 6 Demolition of Stel Supporting Frame Sat 15/2/20 Fri 14/2/20 0% 7 Submission and BD Acknowledgement of BA14A for Demolition Works Sat 15/2/20 Fri 14/2/20 0% 7 Submission and BD Acknowledgement of BA14A for Demolition Works Sat 15/2/20 Pri 1/2/219 0% 7 Foundation Works Sat 19/2/20 Pri 1/2/219 0% 7 Foundation Works Mon 2/3/20 Sun 15/12/19 0% 7 Foundation Works Mon 2/3/20 Sun 14/2/20 0% 8 Linding Layer Fri 15/20 0% 1/2/20 0% 9 Evection of Portunet Commencement) Thu 16/8/20 0% 1/2/20 0% 9 Evection of Portunet								
2 Demolition of Appendages Fri 13/12/19 Thu 19/12/19 Offs 2 Demolition of Sited Supporting Frame Fri 27/12/19 Offs 3 Demolition of Sited Supporting Frame Sat 28/12/0 Fri 14/12/0 Offs 4 Demolition of Sited Supporting Frame Sat 25/12/0 Fri 14/12/0 Offs 5 Demolition of Sited Supporting Frame Sat 28/12/0 Fri 24/20 Offs 6 Demolition of Sited Supporting Frame Sat 25/12/0 Fri 14/20 Offs 7 Submission and BD Acknowledgement of BA14 for Demolition Works Sat 15/2/2 Fri 34/20 Offs 6 Octostruction of New Ash Silo A1 San 5/1/20 Fri 14/12/0 Offs Sat 4/4/20 Fri 11/12/1 Offs 7 Excavate to Formation Level of Raft Footing Sat 4/4/20 Fri 11/12/10 Offs Sat 4/4/20 Fri 11/12/10 Offs 6 Castr Binding Layer Fri 15/5/20 Thu 11/6/20 Offs Fri 14/12/0 Offs 7 Batomation Level of Raft Footing Fri 15/5/20 Thu 11/6/20 Offs Fri 11/12/10 Offs 6 Brinding L	20111				1000		1 1	900
3 Erection of Metal Scaffolding Fri 20/12/19 Fri 20/12/19 Offe 4 Demolition of Silo & Hopper Sat 28/12/18 Fri 22/1/20 Offe 5 Demolition of Stel Supporting Frame Sat 28/12/18 Fri 22/12/19 Offe 5 Demolition of Stel Supporting Frame Sat 15/12/19 Offe Offe 6 Demolition of Stel Stel Supporting Frame Sat 15/12/19 Offe 7 Submission and BD Acknowledgement of BA14A for Demolition Works Sat 15/12/19 Offe 7 Fri 14/20 Offe Sun 51/12/19 Offe 7 Submission and BD Acknowledgement of BA14A for Demolition Works Sat 15/12/19 Sun 15/12/19 Offe 7 Construction of New Ash Silo A1 Sun 51/12/19 Offe Offe Offe 7 Carry out Plate Load Test Sat 14/20 Thi 11/520 Offe Offe 8 Erection of Formwork and Rebar Fixing Fri 37/20 Thu 14/520 Offe Offe 6 Submission and BD Acknowledgement of BA14 for Foundation Works Fri 37/20 Thu 6/8/20 Offe Offe 7 Milestone 2 (501 days	100							
4 Demolition of Silo & Hopper Sat 28/12/19 Fri 24/1/20 0% 5 Demolition of Skel Supporting Frame Sat 25/1/20 Fri 14/2/20 0% 6 Demolition of Skel Supporting Frame Sat 12/2/20 Fri 14/2/20 0% 7 Submission and BD Acknowledgement of BA14A for Demolition Works Sat 15/12/19 Sun 15/12/19 Sun 15/12/19 0% 9 Construction of New Ash Silo A1 Sun 5/12/19 Sun 15/12/19 0% 9 Construction of New Ash Silo A1 Sun 5/12/19 Sun 11/4/20 0% 9 Construction of New Ash Silo A1 Sun 5/12/19 Sun 11/4/20 0% 9 Carstruction of New Ash Silo A1 Sun 5/12/19 Sun 11/4/20 0% 2 Carry out Plate Load Test Sat 18/4/20 Thu 1/5/20 0% 4 Execution of Formwork and Rebar Fixing Fri 15/5/20 Thu 11/6/20 0% 5 Submission and BD Acknowledgement of BA14 for Foundation Works Fri 3/1/20 Thu 6/8/20 0% 6 Submission and BD Acknowledgement of BA14 for Foundation Works Fri 3/1/20 Thu 6/8/20 0% 7 Submission a	2.0							
b Demolition of Steel Supporting Frame Sat 25/1/20 Fri 14/2/20 0% c Demolition of Existing Footings Sat 25/1/20 Fri 14/2/20 0% c Submission and BD Acknoveldgement of BA14A for Demolition Works Sat 25/1/20 Fri 14/2/20 0% e Construction of New Ash Silo A1 Sun 15/1/2/19 Sun 15/1/2/19 0% c Construction of New Ash Silo A1 Sun 25/1/20 Fri 11/1/21 0% c Construction of New Ash Silo A1 Sat 44/20 Fri 11/1/21 0% c Carry out Plate Load Test Sat 14/20 Fri 11/1/21 0% d Carst Dinding Layer Fri 8/5/20 Thu 11/6/20 0% c Carst Out Plate Load Test Sat 15/1/20 Fri 15/2/20 0% c Carst Dinding Layer Fri 15/5/20 Thu 11/6/20 0% c Constructing for Raft Footing Fri 15/2/20 Thu 11/6/20 0% c Constructing for Raft Footing Fri 17/2/20 Thu 6/8/20 0% d Constructing for Raft Footing Fri 15/2/20 Thu 11/6/20 0% Submission and BD Acknowledgement of BA14 for Foundation Works Fri 37/20 Thu 6/8/20 0% Erection of Metal Scaffolding Sun 30	1.11							
b Demolition of Existing Footings Sat 15/2/20 Fri 34/20 0% 7 Submission and BD Acknowledgement of BA14A for Demolition Works Sat 29/2/20 Fri 34/20 0% 7 Submission and BD Acknowledgement of BA14A for Demolition Works Sat 29/2/20 Fri 34/20 0% 9 Construction of New Ash Silo A1 Sun 51/1/20 Fri 11/1/21 0% 9 Foundation Works Mon 23/20 Sun 41/10/20 0% 16 Excavate to Formation Level of Raft Footing Sat 44/2/20 Fri 11/1/20 0% 17 Excavate to Formation Level of Raft Footing Sat 44/2/20 Thu 1/5/2/0 0% 16 Excavate to Formawork and Rebar Fixing Fri 15/5/20 Thu 14/5/20 0% 16 Erection of Formwork and Rebar Fixing Fri 15/5/20 Thu 11/5/20 0% 16 Erection of Sontwark and Rebar Fixing Fri 37/20 Thu 6/8/20 0% 17 Milestone 2 (50) days from Contract Commencement) Thu 6/8/20 0% 17 Barbication & Delivery of Silo & Hopper Sun 30/8/20 Sat 28/11/20 0% 17 On-site preparation works for subsequent installa	DU							
2 Submission and BD Acknowledgement of BA14A for Demolition Works Sat 29/2/20 Fri 3/4/20 0% 8 Milestone I (305 days from Contract Commencement) Sun 15/12/19 0% 9 Construction of New Ash Silo A1 Sun 5/1/20 Fri 1/1/21 0% 9 Construction of New Ash Silo A1 Sun 5/1/20 Fri 1/1/21 0% 9 Construction of New Ash Silo A1 Sun 5/1/20 Fri 1/1/21 0% 9 Construction of New Ash Silo A1 Sun 5/1/20 Fri 1/1/21 0% 9 Construction of New Ash Silo A1 Sun 5/1/20 Fri 1/1/21 0% 9 Construction of New Ash Silo A1 Sun 5/1/20 Fri 1/1/21 0% 6 Carry out Plate Load Test Sat 4/4/20 Fri 1/5/20 0% 2 Carry out Plate Load Test Sat 18/4/20 Thu 1/6/20 0% 5 Submission and BD Acknowledgement of BA14 for Foundation Works Fri 3/7/20 Thu 6/8/20 0% 5 Superstructure Works Sun 5/1/20 Fri 1/1/21 0% 9 Erection of Meal Scaffolding Sun 3/0/20 Sat 8/1/20 0%								
Buildistone 10305 days from Contract Commencement) Sun 15/12/19	100							
2 Construction of New Ash Silo A1 Sun 5/1/20 Fri 1/1/21 0% 3 Foundation Works Mon 2/3/20 Sun 4/10/20 0% 4 Excavate to Formation Level of Raft Footing Sat 4/4/20 Fri 17/4/20 0% 5 Carry out Plate Load Test Sat 18/4/20 Thu 17/5/20 0% 6 Carry out Plate Load Test Sat 18/4/20 Thu 14/5/20 0% 6 Cast Blinding Layer Fri 15/5/20 Thu 14/5/20 0% 6 Concreting for Raft Footing Fri 15/5/20 Thu 14/5/20 0% 6 Submission and BD Acknowledgement of BA14 for Foundation Works Fri 3/7/20 Thu 6/8/20 0% 7 Milestone 2 (501 days from Contract Commencement) Thu 6/8/20 0% 8 Superstructure Works Sun 30/8/20 Sat 38/1/20 0% 9 Erection of Ketal Scaffolding Sun 30/8/20 Sat 38/1/20 0% 9 Frection of Steel Supporting Frame & Staircases Fri 3/7/20 7 0% 2 Erection of Steel Supporting Frame & Staircases Fri 7/8/20 Sun 20/9/20 0%	Du					- 1		↓
Occurrent of the function of th							1 1	15/12
Image: Concentration Level of Raft Footing Nat 2010 Origon Print 2010 Origon Print 2010 Image: Carry out Plate Load Test Sat 18/4/20 Fri 17/4/20 Origon Print 2010 Origon Print 2010 Image: Carry out Plate Load Test Sat 18/4/20 Thu 1/5/20 Origon Print 2010 Origon Pr	Combuda							
2 Carry out Plate Load Test Sat 18/4/20 Thu 7/5/20 0% 3 Cast Blinding Layer Fri 8/5/20 Thu 11/5/20 0% 4 Erection of Formwork and Rebar Fixing Fri 15/5/20 Thu 11/6/20 0% 5 Concreting for Raft Footing Fri 15/5/20 Thu 11/6/20 0% 6 Submission and BD Acknowledgement of BA14 for Foundation Works Fri 3/7/20 Thu 6/8/20 0% 7 Milestone 2 (501 days from Contract Commencement) Thu 6/8/20 Thu 6/8/20 0% 8 Superstructure Works Sun 30/8/20 Sat 28/11/20 0% 9 Erection of Metal Scaffolding Sun 30/8/20 Sat 28/11/20 0% 10 On-site preparation works for subsequent installation of Silo & Hopper Fri 3/7/20 0% 12 Erection of Steel Supporting Frame & Staircases Fri 7/8/20 Sun 20/9/20 0%	Toun							
Cast Blinding Layer Fri 8/5/20 Thu 14/5/20 0% Erection of Formwork and Rebar Fixing Fri 15/5/20 Thu 14/5/20 0% Concreting for Raft Footing Fri 15/5/20 Thu 14/5/20 0% Submission and BD Acknowledgement of BA14 for Foundation Works Fri 3/7/20 Thu 6/8/20 0% Submission and BD Acknowledgement of BA14 for Foundation Works Fri 3/7/20 Thu 6/8/20 0% Superstructure Works Sun 5/1/20 Fri 1/1/21 0% Erection of Metal Scaffolding Sun 30/8/20 Sat 28/11/20 0% Fri 3/7/20 Fri 3/7/20 Fri 3/7/20 0% On-site preparation works for subsequent installation of Silo & Hopper Fri 3/7/20 Fri P Erection of Steel Supporting Frame & Staircases Fri 7/8/20 Sun 20/9/20	Lin							
4 Erection of Formwork and Rebar Fixing Fri 15/5/20 Thu 11/5/20 0% 5 Concreting for Raft Footing Fri 15/5/20 Thu 2/1/20 0% 5 Submission and BD Acknowledgement of BA14 for Foundation Works Fri 3/7/20 Thu 6/8/20 0% 6 Submission and BD Acknowledgement of BA14 for Foundation Works Fri 3/7/20 0% 7 Milestone 2 (501 days from Contract Commencement) Thu 6/8/20 0% 8 Superstructure Works Sun 5/1/20 Fri 11/21 0% 9 Erection of Metal Scaffolding Sun 30/8/20 Sat 28/11/20 0% 10 On-site preparation works for subsequent installation of Silo & Hopper Fri 3/7/20 Fri 3/7/20 12 Erection of Steel Supporting Frame & Staircases Fri 7/8/20 Sun 20/9/20 0%								
5 Concreting for Raft Footing Fri 12//5/20 Thu 27/20 0% 6 Submission and BD Acknowledgement of BA14 for Foundation Works Fri 37/20 Thu 6/8/20 0% 7 Milestone 2 (501 days from Contract Commencement) Thu 6/8/20 0% 8 Superstructure Works Sun 5/1/20 Fri 11/1/21 0% 9 Erection of Metal Scaffolding Sun 30/8/20 Sat 28/11/20 0% 10 On-site preparation works for subsequent installation of Silo & Hopper Fri 3/7/20 Fri 3/7/20 2 Erection of Steel Supporting Frame & Staircases Fri 7/8/20 Sun 20/9/20 0%	Cu							
Submission and BD Acknowledgement of BA14 for Foundation Works Fri 3/7/20 Thu 6/8/20 0% Milestone 2 (501 days from Contract Commencement) Thu 6/8/20 0% Superstructure Works Sun 5/1/20 Fri 1/1/21 0% Erection of Metal Scaffolding Sun 30/8/20 Sat 28/11/20 0% P Frei Jri/20 Fri 3/7/20 Fri 3/7/20 P Frei of Metal Scaffolding Sun 30/8/20 Sat 28/11/20 P Frei Jri/20 Fri 3/7/20 O% P Fri Jri/20 Sun 5/1/20 Fri 3/7/20 P Fri Jri/20 Sun 5/1/20 Sun 5/1/20 P Fri Jri/20 O% Fri 3/7/20 P Fri Jri/20 O% P Fri Jri/20 O% P Erection of Steel Supporting Frame & Staircases Fri 7/8/20 Sun 20/9/20 P Erection of Steel Supporting Frame & Staircases Fri 7/8/20 Sun 20/9/20 0%						1		
Determinant The Share The Share Office 0 Milestone 2 (501 days from Contract Commencement) The Share Office 8 Superstructure Works Sun 5/1/20 Fri 1/1/21 Office 9 Erection of Metal Scaffolding Sun 30/8/20 Sat 28/11/20 Office 0 Fabrication & Delivery of Silo & Hopper Sun 5/1/20 Fri 3/7/20 Office 1 On-site preparation works for subsequent installation of Silo & Hopper Fri 3/7/20 Office 2 Erection of Steel Supporting Frame & Staircases Fri 7/8/20 Sun 20/9/20 Office		ncreting for Raft Footing	Fri 12/6/20	Thu 2/7/20	0%			
7 Milestone 2 (501 days from Contract Commencement) Thu 6/8/20 0% 8 Superstructure Works Sun 5/1/20 Fri 1/1/21 0% 9 Erection of Metal Scaffolding Sun 30/8/20 Sat 28/11/20 0% 0 Fabrication & Delivery of Silo & Hopper Sun 5/1/20 Fri 3/7/20 0% 1 On-site preparation works for subsequent installation of Silo & Hopper Fri 3/7/20 Thu 6/8/20 2 Erection of Steel Supporting Frame & Staircases Fri 7/8/20 Sun 20/9/20 0%			Fri 3/7/20	Thu 6/8/20				
8 Superstructure Works Sun 5/1/20 Fri 1/1/21 0% 9 Erection of Metal Scaffolding Sun 30/8/20 Sat 28/11/20 0% 9 Fabrication & Delivery of Silo & Hopper Sun 5/1/20 Fri 3/7/20 0% 0 Fabrication & Delivery of Silo & Hopper Sun 5/1/20 Fri 3/7/20 0% 1 On-site preparation works for subsequent installation of Silo & Hopper Fri 3/7/20 0% 2 Erection of Steel Supporting Frame & Staircases Fri 7/8/20 Sun 20/9/20 0%	7 Mi		Thu 6/8/20	Thu 6/8/20	0%			6/8
P Erection of Metal Scaffolding Sun 30/8/20 Sat 28/11/20 0% P Fabrication & Delivery of Silo & Hopper Sun 5/1/20 Fri 3/7/20 0% P On-site preparation works for subsequent installation of Silo & Hopper Fri 3/7/20 0% P Erection of Steel Supporting Frame & Staircases Fri 7/8/20 Sun 20/9/20 0%	8 Super	rstructure Works				1		
0 Fabrication & Delivery of Silo & Hopper Sun 5/1/20 Fri 3/7/20 0% 1 On-site preparation works for subsequent installation of Silo & Hopper Fri 3/7/20 Thu 6/8/20 0% 2 Erection of Steel Supporting Frame & Staircases Fri 7/8/20 Sun 20/9/20 0%	9 Ere	ection of Metal Scaffolding						
1 On-site preparation works for subsequent installation of Silo & Hopper Fri 3/7/20 Thu 6/8/20 0% 2 Erection of Steel Supporting Frame & Staircases Fri 7/8/20 Sun 20/9/20 0%								
2 Erection of Steel Supporting Frame & Staircases Fri 7/8/20 Sun 20/9/20 0%	1 44					1		
	- On	one preparation works for subsequent mountation of one or propper	111 5/1120	1114 0/0/20	0.0	1		
	52 Ere	action of Steal Supporting Frame & Staircases	E.: 7/0/00	Sun 20/0/20	007			
Installation of Silo & Proper Prior 21/9/20 Wioil 20/10/20 0% Allow Others for Installation of E&M Mon 28/9/20 Wed 11/1/20 0% Construction of Silo Top Frame including Removable Grating Tue 27/10/20 Fri 13/11/20 0% Erection of Maintenance Platform at Silo Top Sat 14/11/20 Fri 27/11/20 0% Submission and BD Acknowledgement of BA13 Sat 28/11/20 Sun 27/12/20 0% Installation of Aluminium Cladding Sat 28/11/20 Sat 12/12/20 0% Install 2nrs of Height Warning Post Sat 28/11/20 Sat 12/12/20 0% Removal of Metal Scaffolding & Site Clearance Sun 13/12/20 Fri 11/1/21 0%						1		
Allow Outers for Installation of EacM Mion 28/9/20 Wed 11/11/20 0% Construction of Silo Top Frame including Removable Grating Tue 27/10/20 Fri 13/11/20 0% Erection of Maintenance Platform at Silo Top Sat 14/11/20 Fri 27/11/20 0% Submission and BD Acknowledgement of BA13 Sat 28/11/20 Sun 27/12/20 0% Installation of Aluminium Cladding Sat 28/11/20 Sat 28/11/20 0% Install 2nrs of Height Warning Post Sat 28/11/20 Sat 12/12/20 0% Removal of Metal Scaffolding & Site Clearance Sun 13/12/20 Fri 11/12/10 0%	1110							
Construction of Silo 10p Frame including Removable Grating Iue 2//10/20 Fri 13/11/20 0% Erection of Maintenance Platform at Silo Top Sat 14/11/20 Fri 27/11/20 0% Submission and BD Acknowledgement of BA13 Sat 28/11/20 Sun 27/12/20 0% Installation of Aluminium Cladding Sat 28/11/20 Fri 11/12/20 0% Install Arns of Height Warning Post Sat 28/11/20 Sat 21/21/20 0% Removal of Metal Scaffolding & Site Clearance Sun 13/12/20 Fri 11/12/10 0%								
• Erection of Maintenance Platform at Silo Top Sat 14/11/20 Fin 27/11/20 0% 7 Submission and BD Acknowledgement of BA13 Sat 28/11/20 Sat 28/11/20 0% 8 Installation of Aluminium Cladding Sat 28/11/20 Fri 11/12/20 0% 9 Install Arns of Height Warning Post Sat 28/11/20 Sat 28/11/20 Sat 28/11/20 9 Removal of Metal Scaffolding & Site Clearance Sun 13/12/20 Fri 11/1/21 0%						1		
V Submission and BD Acknowledgement of BA13 Sat 28/11/20 0% Installation of Aluminium Cladding Sat 28/11/20 Fri 11/12/20 0% Install 2nrs of Height Warning Post Sat 28/11/20 Sat 12/12/20 0% Renoval of Metal Scaffolding & Site Clearance Sun 13/12/20 Fri 11/1/21 0%	Div					ł		
8 Installation of Aluminium Cladding Sat 28/11/20 Fri 11/12/20 0% 9 Install 2nrs of Height Warning Post Sat 28/11/20 Sat 12/12/20 0% 1 Removal of Metal Scaffolding & Site Clearance Sun 13/12/20 Fri 11/12/10 0%					1.11.1		1	
9 Install 2nrs of Height Warning Post Sat 28/11/20 Sat 12/12/20 0% 1 Removal of Metal Scaffolding & Site Clearance Sun 13/12/20 Fri 1/1/21 0%								
Removal of Metal Scaffolding & Site Clearance Sun 13/12/20 Fri 1/1/21 0%			Sat 28/11/20	Sat 12/12/20	0%		1	
	60 Re	moval of Metal Scaffolding & Site Clearance	Sun 13/12/20	Fri 1/1/21	0%		1	

Appendix C

Environmental Audit Records

ΑΞϹΟΜ

Environmental Audit Checklist

Project Contra Contra Inspect Date: Time: PART Weath Tempe Humidi Wind: PART	act no: actor: ction A: er: er: erature: ity:	Enhanced Ash Utilisation and Water Management Facilities at the Castle Peak Power Station (CPPS)	Clier ER: IEC: Cont	ected by nt: ractor:		Chan Chan Chun Long		
	-	[Not Obs.	Yes	No	Follow	N/A	Photo/ Remarks
Sectio	n 1: Wat	er Quality		/				
1.01	ls wettir	g of materials and surfaces avoided excess use of water?						
1.02		nnels, earth bunds or sand bag barriers provided on-site to direct stormwater to desilting facilities?		\square				
1.03	maintair of and a	ting on-site silt removal facilities, channels and manholes, if any, ned and the deposited silt and grit removed regularly, at the onset fter each rainstorm and to ensure that these facilities are ing properly at all times?	₫					
1.04	adequat	er manholes, if any, including any newly constructed ones tely covered and temporarily sealed so as to prevent silt, ction materials or debris from getting into the drainage system?		₫				
1.05	covered	n stockpiles of materials on site avoided or where unavoidable with tarpaulin or similar fabric during rainstorm? Are measures prevent the washing away of construction materials, soil, silt or		₫				
1.06	temporatoilets?	ge arising from the construction workers on-site collected by rry sanitary facilities where necessary, e.g. portable chemical Are portable toilets used coupled with tankering away services d by a reputable collector?	\square					
1.07	Are all s dischar	ite drainages comply with the terms and conditions of a valid ge licence issued by EPD?	Ø					
1.08	discharg from wh	icle washing facilities drained into desilting facilities before ge? Is water recycled on-site wherever possible? Is the wash water eel wash basins either reused for site watering or pumped to the desilting facilities for treatment?	Ń					
1.09		ilting facilities checked and the deposited silt and grit removed y to ensure that they are working properly at all times?	\square					
1.10		uel tanks and chemical storage sited on sealed and bunded areas vided with locks?						
1.11		age areas surrounded by bunds with a capacity equal to 110% of age capacity of the largest tank to prevent accidental spillage, if ary?						
1.12		and grease removal facilities provided where appropriate, e.g. in ar plant workshop/maintenance area, if any?	б					
1.13	and disp	ical waste arising from the site properly stored, handled, treated bosed of in compliance with the requirements stipulated under the Disposal (Chemical Waste) (General) Regulation?	⊿					

AECOM

Environmental Audit Checklist

		Not Obs.	Yes	No	Follow up	N/A	Photo/ Remarks
Sectio	n 2: Air Quality						
2.01	Are all areas involving site clearance and excavation works sprayed with water before, during and after the operations to maintain the entire surface wet?						
2.02	Are materials dropped from restricting heights as far as practicable to minimize the fugitive dust arising from loading/unloading?		┢				
2.03	Is hoarding of not less than 2.4m high from ground level along the major work site boundary erected, for the new process water tank and the new PFA storage silo, where appropriate?		\square				
2.04	Are all vehicles washed to remove any dusty materials from the bodies and wheels immediately before leaving a work site?		₫				
2.05	Is the load of the vehicle leaving a work site is carrying a load of dusty materials covered entirely by clean impervious sheeting to ensure that the dusty materials will not be released from the vehicle?		Ь				
2.06	Is stockpile of dusty materials on-site covered entirely by impervious sheeting; and/or placed in an area sheltered on the top and 4 sides?		白				
2.07	Is stockpile of dusty materials on-site sprayed with water immediately prior to any loading, unloading or transfer operation to dampen the dusty materials?		₫				
2.08	Is the travelling speed of vehicles within the work sites controlled to within 10 km/h to reduce the traffic induced dusty dispersion and re-suspension?		\square				
2.09	Is unpaved haul road sprayed with water to maintain the entire road surface wet?		\square				
2.10	Is coal dust suppressed by water sprays using the spray guns and water browser as existing normal operations at the coal stockyard during the clearance of the coal pile?		₫				
Sectio	on 3: Noise						
3.01	Is unused equipment turned off?		\square				
3.02	Is PME kept to a minimum and the parallel use of noisy equipment / machinery avoided?		₫				
3.03	Are all plant and equipment maintained regularly?		\square				
3.04	Are material stockpiles and other on-site structures effectively used as noise barriers, where practicable?		\square				
3.05	Are purpose-built movable noise barrier, silencer and quiet plant used as necessary?		亡				
Section	on 4: Waste/Chemical Management		,				
4.01	Is reuse / recycling of all materials on-site investigated and exhausted prior to treatment / disposal off-site?						
4.02	Are all waste materials sorted on-site into inert and non-inert C&D materials, and where the materials recycled or reused, are they further segregated?		₫				
4.03	Is trip-ticket system implemented in accordance with the contract and the requirements of WBTC 31/2004 "Trip Ticket System for Disposal of Construction and Demolition Material"?		₫				
4.04	Is the Contractor registered as a Chemical Waste Producer if chemical wastes are generated on-site?	ď					
4.05	Are licensed chemical waste collectors employed to collect any chemical waste generated at site?	┢					
4.06	Are handling, storage, transportation and disposal of chemical wastes conducted in accordance with the <i>Code of Practice on the Packaging,</i> <i>Labelling and Storage of Chemical Wastes</i> and <i>A Guide to the Chemical</i> <i>Waste Control Scheme</i> both published by EPD?		Ø				
4.07	Are sufficient number of covered bins provided on-site for the containment of general refuse to prevent visual impacts and nuisances? Are these bins emptied daily and the collected waste disposed of to WENT Landfill?		Ø				
4.08	Is the site maintained clean and hygienic throughout the project works?		Ź				Page 2 of 3

AECON

Environmental Audit Checklist


		Not Obs.	Yes	No	Follow up	N/A	Photo/ Remarks
4.09	Are toolbox talks provided to workers about the concepts of site cleanliness and appropriate waste management procedures, including waste reduction, reuse and recycling?	⊿					
Sectio	on 5: Others						
5.01	Are relevant Environmental Permits posted at all vehicle site entrances/exits or at a convenient location for public's information at all times??						
5.02	Others:						

Remarks:

Wo specific observation

Was identified

in this inspection



Page 3 of 3



Environmental Audit Checklist

Contr Inspe Date: Time: PART Weath	ract no: ractor: ection	Enhanced Ash Utilisation and Water Management Facilities at the Castle Peak Power Station (CPPS)	Clier ER: IEC: Cont		Alex	Chan Chun Long		
Humic Wind:		High Moderate Low Strong Breeze Light Calm	ı					
PART	в:	SITE AUDIT						
Contin			Not Obs.	Yes	No	Follow up	N/A	Photo/ Remarks
1.01		ter Quality g of materials and surfaces avoided excess use of water?		\square				
1.02		nnels, earth bunds or sand bag barriers provided on-site to direct stormwater to desilting facilities?						
1.03	maintair of and a	ting on-site silt removal facilities, channels and manholes, if any, ned and the deposited silt and grit removed regularly, at the onset fter each rainstorm and to ensure that these facilities are ing properly at all times?	ď					
1.04	adequat	er manholes, if any, including any newly constructed ones tely covered and temporarily sealed so as to prevent silt, ction materials or debris from getting into the drainage system?						
1.05	covered	n stockpiles of materials on site avoided or where unavoidable with tarpaulin or similar fabric during rainstorm? Are measures prevent the washing away of construction materials, soil, silt or						
1.06	temporatoilets?	ge arising from the construction workers on-site collected by ry sanitary facilities where necessary, e.g. portable chemical Are portable toilets used coupled with tankering away services d by a reputable collector?	ď					
1.07		ite drainages comply with the terms and conditions of a valid ge licence issued by EPD?	\square					
1.08	discharo from wh	icle washing facilities drained into desilting facilities before ge? Is water recycled on-site wherever possible? Is the wash water eel wash basins either reused for site watering or pumped to the desilting facilities for treatment?	Ø					
1.09		ilting facilities checked and the deposited silt and grit removed to ensure that they are working properly at all times?						
1.10		uel tanks and chemical storage sited on sealed and bunded areas vided with locks?		Ź				
1.11		age areas surrounded by bunds with a capacity equal to 110% of age capacity of the largest tank to prevent accidental spillage, if ary?		₫				
1.12		nd grease removal facilities provided where appropriate, e.g. in ar plant workshop/maintenance area, if any?	\square					
1.13	and disp	ical waste arising from the site properly stored, handled, treated oosed of in compliance with the requirements stipulated under the Disposal (Chemical Waste) (General) Regulation?	Ц					

AECOM

Environmental Audit Checklist


		Not Obs.	Yes	No	Follow up	N/A	Photo/ Remarks
Sectio	n 2: Air Quality		/				
2.01	Are all areas involving site clearance and excavation works sprayed with water before, during and after the operations to maintain the entire surface wet?						
2.02	Are materials dropped from restricting heights as far as practicable to minimize the fugitive dust arising from loading/unloading?						
2.03	Is hoarding of not less than 2.4m high from ground level along the major work site boundary erected, for the new process water tank and the new PFA storage silo, where appropriate?		б				
2.04	Are all vehicles washed to remove any dusty materials from the bodies and wheels immediately before leaving a work site?		\square				
2.05	Is the load of the vehicle leaving a work site is carrying a load of dusty materials covered entirely by clean impervious sheeting to ensure that the dusty materials will not be released from the vehicle?		Ь				
2.06	Is stockpile of dusty materials on-site covered entirely by impervious sheeting; and/or placed in an area sheltered on the top and 4 sides?		⊿				
2.07	Is stockpile of dusty materials on-site sprayed with water immediately prior to any loading, unloading or transfer operation to dampen the dusty materials?		\square				
2.08	Is the travelling speed of vehicles within the work sites controlled to within 10 km/h to reduce the traffic induced dusty dispersion and re-suspension?		\square				
2.09	Is unpaved haul road sprayed with water to maintain the entire road surface wet?		\square				
2.10	Is coal dust suppressed by water sprays using the spray guns and water browser as existing normal operations at the coal stockyard during the clearance of the coal pile?		ď				
Sectio	n 3: Noise		/				
3.01	Is unused equipment turned off?		位				
3.02	Is PME kept to a minimum and the parallel use of noisy equipment / machinery avoided?		d,				
3.03	Are all plant and equipment maintained regularly?						
3.04	Are material stockpiles and other on-site structures effectively used as noise barriers, where practicable?						
3.05	Are purpose-built movable noise barrier, silencer and quiet plant used as necessary?						
Sectio	n 4: Waste/Chemical Management		,				
4.01	Is reuse / recycling of all materials on-site investigated and exhausted prior to treatment / disposal off-site?		\square				
4.02	Are all waste materials sorted on-site into inert and non-inert C&D materials, and where the materials recycled or reused, are they further segregated?		₫				
4.03	Is trip-ticket system implemented in accordance with the contract and the requirements of WBTC 31/2004 "Trip Ticket System for Disposal of Construction and Demolition Material"?						
4.04	Is the Contractor registered as a Chemical Waste Producer if chemical wastes are generated on-site?	Ø					
4.05	Are licensed chemical waste collectors employed to collect any chemical waste generated at site?						
4.06	Are handling, storage, transportation and disposal of chemical wastes conducted in accordance with the Code of Practice on the Packaging, Labelling and Storage of Chemical Wastes and A Guide to the Chemical Waste Control Scheme both published by EPD?		б				
4.07	Are sufficient number of covered bins provided on-site for the containment of general refuse to prevent visual impacts and nuisances? Are these bins emptied daily and the collected waste disposed of to WENT Landfill?						
4.08	Is the site maintained clean and hygienic throughout the project works?						Page 2 of 3

AECOM

Environmental Audit Checklist

		Not Obs.	Yes	No	Follow up	N/A	Photo/ Remarks
4.09	Are toolbox talks provided to workers about the concepts of site cleanliness and appropriate waste management procedures, including waste reduction, reuse and recycling?	d					
Sectio	on 5: Others						
5.01	Are relevant Environmental Permits posted at all vehicle site entrances/exits or at a convenient location for public's information at all times??						
5.02	Others:						

Remarks:



Appendix D

Summary of Implementation Status of Environmental Mitigation Measure

Appendix D Implementation Status of Recommended Mitigation Measures during Construction Stage

Environmental Aspect	Recommended Mitigation Measures	Implementation Status
Air Quality	Measures for Construction Activities involving Excavations, Loading and Unloading of Soils	
(Section 4.1 of Project Profile)	 All areas involving site clearance and excavations works will be sprayed with water before, during and after the operations to maintain the entire surface wet; 	Y
	 Restricting heights from which materials are to be dropped, as far as practicable to minimize the fugitive dust arising from unloading/ loading; 	Y
	• Erection of hoarding of not less than 2.4 m high from ground level along the major work site boundary (the new process water tank and the new PFA storage silo), where appropriate;	N/A
	 Immediately before leaving a work site, all vehicles shall be washed to remove any dusty materials from the bodies and wheels. However, wetting of materials and surfaces should avoid excessive use of water; 	Y
	 Where a vehicle leaving a work site is carrying a load of dusty materials, the load shall be covered entirely by clean impervious sheeting to ensure that the dusty materials will not be released from the vehicle; 	Y
	 Any stockpile of dusty materials on-site will be covered entirely by impervious sheeting; and/or placed in an area sheltered on the top and 4 sides. They should also be sprayed with water immediately prior to any loading, unloading or transfer operation to dampen the dusty materials; 	Y
	 To reduce the traffic induced dust dispersion and re-suspension, the travelling speed of vehicles within the work sites should be controlled to within 10 km/h; 	Y
	 Any unpaved haul road shall be sprayed with water so as to maintain the entire road surface wet. 	Y
	Measures for Partial Decommissioning of the West Coal Stockyard	
	 During the clearance of the coal pile, coal dust will be suppressed by water sprays using the spray guns and water browser as existing normal operations at the coal stockyard. 	N/A
Noise	Good Site Practice	
(Section 4.2 of Project Profile)	 Unused equipment should be turned off. PME will be kept to a minimum and the parallel use of noisy equipment/ machinery will be avoided; 	Y
	Regular maintenance of all plant and equipment;	Y
	• Material stockpiles and other on-site structures will be effectively used as noise barriers, where practicable;	N/A
	 Use of purpose-built movable noise barrier, silencer and quiet plant as necessary. 	N/A

Environmental Aspect	Recommended Mitigation Measures	Implementation Status
Water Quality	Measures for Construction Site Runoff and Discharge	
(Section 4.3 of Project Profile)	 Surface runoff from the affected works areas are to be directed towards desilting facilities before discharging into the stormwater drainage; 	N/A
	 Channels, earth bunds or sand bag barriers will be provided on-site to properly direct stormwater to the above- mentioned facilities; 	Y
	• Existing on-site silt removal facilities, channels and manholes, if any, will be maintained and the deposited silt and grit will be removed regularly, at the onset of and after each rainstorm and to ensure that these facilities are functioning properly at all times;	N/A
	• Other manholes, if any, including any newly constructed ones will be adequately covered and temporarily sealed so as to prevent silt, construction materials or debris from getting into the drainage system;	Y
	 Open stockpiles of materials on site will be avoided or where unavoidable covered with tarpaulin or similar fabric during rainstorms. Measures will be taken to prevent the washing away of construction materials, soil, silt or debris; 	N/A
	• Sewage arising from the construction workers on-site will be collected by temporary sanitary facilities where necessary e.g. portable chemical toilets. Portable toilets will be used coupled with tankering away services provided by a reputable collector;	N/A
	• All site discharges will comply with the terms and conditions of a valid discharge license issued by EPD;	N/A
	• Vehicle washing facilities will be drained into desilting facilities before discharge. Water will be recycled on-site wherever possible. It is suggested that the wash water from wheel wash basins are either reused for site watering or pumped to the on-site desilting facilities for treatment;	N/A
	• Desilting facilities will be checked and the deposited silt and grit will be removed regularly to ensure that they are working properly at all times.	N/A
	Protection against Accidental Spillage	
	 The works may occasionally involve the handling of fuel and generates a small amount of chemical wastes. It must be ensured that all fuel tanks and chemical storage are sited on sealed and bunded areas and provided with locks; 	N/A
	 If necessary, the storage areas will be surrounded by bunds with a capacity equal to 110% of the storage capacity of the largest tank to prevent accidentally spillage; 	N/A
	 Oil and grease removal facilities will be provided where appropriate, for example, in area near plant workshop/ maintenance areas, if any; 	Y
	• Chemical waste arising from the site will be properly stored, handled, treated and disposed of in compliance with the requirements stipulated under the Waste Disposal (Chemical Waste) (General) Regulation.	N/A

Environmental Aspect	Recommended Mitigation Measures	Implementation Status
Waste	Waste Management Plan (WMP)	
Management Implications (Section 4.4 of the Project Profile)	The main contractor of the Project shall prepare a <i>Waste Management Plan (WMP)</i> , which will become part of the <i>Environmental Management Plan (EMP)</i> , with reference to the requirements set out in the <i>ETWB TCW No. 19/2005</i> , <i>Waste Management on Construction Sites</i> and the Practice Note for Authorized Persons and Registered Structural Engineers, <i>e.g. Practice Note No. 243 – Construction and Demolition Waste</i> . The WMP shall include monthly Waste Flow Tables (WFT) which indicate the amounts of waste generated, recycled and disposed of (including final disposal site), and it should be updated regularly.	Y
	General waste management measures during Construction	
	• The reuse/recycling of all materials on-site shall be investigated and exhausted prior to treatment/ disposal off-site;	Y
	• All waste materials shall be sorted on-site into inert and non-inert C&D materials, and where the materials can be recycled or reused, they shall be further segregated. Inert material, or public fill shall be disposed of at Fill Bank at Tuen Mun Area 38 whilst non-inert materials or construction waste shall be disposed of at the WENT Landfill.	Y
	• The contractor shall be responsible for identifying what materials can be recycled/ reused, whether on-site or off-site. In the event of the latter, the contractor shall arrange for the collection of the recyclable materials.	Y
	• In order to monitor the disposal of public fill and construction waste at public filling facilities and landfills, and control fly- tipping, a trip-ticket system shall be implemented by the Contractor, in accordance with the contract and the requirements of WBTC 31/2004 " <i>Trip Ticket System for Disposal of Construction and Demolition Material</i> ";	Y
	• Under the <i>Waste Disposal (Chemical Waste) (General) Regulation</i> , the Contractor shall register as a Chemical Waste Producer if chemical wastes such as spent lubricants and paints are generated on-site. Only licensed chemical waste collectors shall be employed to collect any chemical waste generated at site. The handling, storage, transportation and disposal of chemical wastes shall be conducted in accordance with the <i>Code of Practice on the Packaging, Labelling and Storage of Chemical Wastes and A Guide to the Chemical Waste Control Scheme</i> both published by EPD;	N/A
	• A sufficient number of covered bins shall be provided on-site for the containment of general refuse to prevent visual impacts and nuisances. These bins shall be emptied daily and the collected waste disposed of to the WENT Landfill. Further to the issue of ETWB TCW No. 6/2002A, Enhanced Specification for Site Cleanliness and Tidiness, the contractor will be required to maintain a clean and hygienic site throughout the project works;	Y
	• Toolbox talks should be provided to workers about the concepts of site cleanliness and appropriate waste management procedures, including waste reduction, reuse and recycling.	N/A
Land Contamination (Section 4.5 of Project Profile)	Based on the recent SI result, signs of land contamination were not identified and no mitigation measures are considered necessary. However, the situation will be reconfirmed after the SI work at the coal stockyard proposed in the CAP is completed. The SI results will be documented in a Contamination Assessment Report (CAR). If contamination is identified, the necessary remediation method will be proposed and documented in the Remediation Action Plan (RAP) for EPD's approval. If remediation is necessary, the CAPCO will clean up the contaminated land according to the approved RAP, and a Remediation Report (RR) will be prepared to demonstrate that the concerned area(s) have been cleaned up to the	N/A

Environmental Aspect	Recommended Mitigation Measures	Implementation Status
	relevant RBRG's standards. The RR will be submitted to EPD for agreement prior to the commencement of any development or redevelopment works.	
Landscape & Visual (Section 4.7 of Project Profile)	No mitigation measures for landscape and visual impacts are considered necessary, as no adverse landscape and visual impacts are identified during the construction and operation of the Project.	N/A

Notes:

Y Compliance of Mitigation Measures N Non-compliance of Mitigation Measures D Deficiency of Mitigation Measures N/A Not Applicable in Reporting Period

Non-compliance of Mitigation Measures but rectified by the Contractor ٠

 \diamond Deficiency of Mitigation Measures but rectified by the Contractor