

Enhanced Ash Utilisation and Water Management Facilities at Castle Peak Power Station

Monthly Audit Report for March 2023

April 2023

AECOM ASIA CO. LTD.

Disclaimer:

This report is prepared for Castle Peak Power Company Limited (CAPCO) and is given for its sole benefit in relation to and pursuant to Enhanced Ash Utilisation and Water Management Facilities at Castle Peak Power Station and may not be disclosed to, quoted to or relied upon by any person (other than CAPCO) without our prior written consent. No person other than CAPCO into whose possession a copy of this report comes may rely on this report without our express written consent and CAPCO may not rely on it for any purpose other than as described above.

Table of Contents

			Page
1	INTR	ODUCTION	1
	1.1 1.2 1.3	Project Background Purpose of the Report Report Structure	1
2	PRO	JECT INFORMATION	2
	2.1 2.2 2.3	Site Description Construction Programme and Activities Status of Environmental Licences, Notification and Permits	2
3	ENVI	RONMENTAL SITE INSPECTION	4
	3.1	Environmental Site Inspection	4
4	IMPL	EMENTATION STATUS OF ENVIRONMENTAL MITIGATION MEASURES	4
5	CON	CLUSION	4

List of Tables

Table 2.1	Status of Environmental Licences, Notifications and Permits – for Ash Silo
	Construction Works
Table 2.2	Status of Environmental Licences, Notifications and Permits - for Water Management
	Facilities Enhancement Works

List of Appendices

Appendix A	Location Plan of Key Project Components (2017 Scheme)
Appendix B	Construction Programme
Appendix C	Environmental Audit Records
Appendix D	Summary of Implementation Status of Environmental Mitigation Measures

AECOM ii April 2023

1 INTRODUCTION

1.1 Project Background

- 1.1.1 Pursuant to the Environmental Impact Assessment Ordinance (EIAO), the Director of Environmental Protection (DEP) granted an environmental permit (No. EP-441/2012) to the Castle Peak Power Company Limited (CAPCO) on 23 July 2012 to construct and operate the designated project for Enhanced Ash Utilisation and Water Management Facilities at Castle Peak Power Station (hereinafter referred to as "the Project"). An application for variation of environmental permit (VEP) was subsequently made and the revised EP (No: EP-441/2012/A) was issued by DEP on 29 June 2018.
- 1.1.2 CAPCO appointed AECOM Asia Company Limited (AECOM) as the Independent Checker (IC) to undertake environmental audit work for the Project. Yee Hop Engineering Company Limited is the Contractor for construction of Ash Silo, while Guangxi Electric Power Design Institute Company Limited is the Contractor for the enhancement works of Water Management Facilities. The civil construction works of Ash Silo were completed by Yee Hop in December 2021. The construction of Ash Silo was handed over to Kum Shing E&M Limited for the E&M works in January 2022. The E&M works undertaken by Kum Shing E&M Limited were substantially completed in April 2022 and only some minor E&M works were remained that significant environmental impacts arising from these works would not be anticipated. Hence, the audit works for Ash Silo site has been terminated since May 2022.
- 1.1.3 In addition, the construction for the enhancement works of Water Management Facilities according to the Environmental Review Report for VEP has also been completed in March 2023. Therefore, this is the last Monthly Audit Report for the Project.

1.2 Purpose of the Report

1.2.1 Under the EP Condition 2.3, the audit for the implementation of all mitigation measures recommended in the Project Profile (Register No. PP-468/2012) commenced in November 2019. This is the Forty-first Monthly Audit Report which summarises the audit findings for the Project during the reporting period from 1 to 31 March 2023.

1.3 Report Structure

- 1.3.1 This Monthly Audit Report is organised as follows:
 - Section 1: Introduction
 - Section 2: Project Information
 - Section 3: Environmental Site Inspection
 - Section 4: Implementation Status of Environmental Mitigation Measures
 - Section 5: Conclusions

AECOM 1 April 2023

2 PROJECT INFORMATION

2.1 Site Description

2.1.1 The Project site is located within the boundary of the existing Castle Peak Power Station (CPPS). The locations of the key project components are shown in **Appendix A**.

2.2 Construction Programme and Activities

2.2.1 The major construction activities of the Project undertaken in the reporting month includes:

Water Management Facilities Enhancement Works

- (i) Plant Room
 - EVA road construction work.
- (ii) Process Water Tank
 - No construction activities in reporting month
- (iii) Water Management Facilities
 - No construction activities in reporting month
- (iv) West Coal Store
 - No construction activities in reporting month
- (v) Drainage Modification Works
 - No construction activities in reporting month
- 2.2.2 The construction of the Project has been completed in March 2023 and no further site inspection would be conducted.
- 2.2.3 The construction programmes for the above-mentioned construction / enhancement works is presented in **Appendix B**.

2.3 Status of Environmental Licences, Notification and Permits

2.3.1 Relevant environmental licences, permits and/or notifications on environmental protection for this Project and valid in the reporting month are summarised in **Tables 2.1** and **2.2**.

AECOM 2 April 2023

Table 2.1 Status of Environmental Licences, Notifications and Permits for Ash Silo Construction Works

Permit / Licence No. / Notification/ Reference	Valid F	Period	Status	Remarks						
No.	From	То								
Environmental Permit			<u>'</u>							
EP-441/2012/A	29 June 2018		Valid							
Billing Account for Cons	struction Waste D	Disposal								
7033071	25 January 2019		Valid							
Notification Under Air P	Notification Under Air Pollution Control (Construction Dust) Regulation									
444243	15 April 2019		Valid							

Table 2.2 Status of Environmental Licences, Notifications and Permits for Water Management Facilities Enhancement Works

Permit / Licence No. / Notification/ Reference	Valid F	Period	Status	Remarks
No.	From	То		
Environmental Permit		ı		
EP-441/2012/A	29 June 2018		Valid	
Billing Account for Cons	struction Waste D	 Disposal		
7037396	27 May 2020		Valid	
Notification Under Air Po	ollution Control (Construction Du	ıst) Regulation	
455899	7 May 2020		Valid	
Notification of Commen	coment of Ashes	tos Ahatement V	Vork	
AX200323	14 July 2020		closed	All asbestos removal works was finished in October 2020 and the Completion Report of Asbestos Abatement Work (AAW) was sent to EPD on 14 December 2020 for record.
Construction Noise Perr	nit			
GW-RW0337-20	30 July 2020	21 January 2021	Expired	
GW-RW0593-20	22 January 2021	21 July 2021	Expired	
GW-RW0247-21	22 July 2021	21 January 2022	Expired	
GW-RW0009-22	22 January 2022	21 July 2022	Expired	No further works in restricted hours is required for remaining tasks. No renewal of CNP is required.
Discharge Licence				
WT0036990-2020	12 November 2020	30 November 2025	Valid	

3 ENVIRONMENTAL SITE INSPECTION

3.1 Environmental Site Inspection

- 3.1.1 Site inspections were carried out by the IC on a bi-weekly basis to monitor the implementation of mitigation measures for the Project.
- 3.1.2 In the reporting month, the site inspections were carried out jointly with the CAPCO Project Team on 9 March 2023 and the Contractor on 30 March 2023. No non-compliance was recorded during the site inspections. Findings and recommendations for the site inspections are summarised below. Details of observations recorded during the site inspections are presented in **Appendix C**.

Water Management facilities Enhancement Works

- 9 March 2023
 - No specific observation was identified in this inspection.
- 30 March 2023
 - No specific observation was identified in this inspection.
- 3.1.3 All construction works of the Project have been completed in March 2023. No further site inspection is required.

4 IMPLEMENTATION STATUS OF ENVIRONMENTAL MITIGATION MEASURES

4.1.1 The Contractor has implemented all the relevant environmental mitigation measures as recommended in the Project Profile. The implementation status of the environmental mitigation measures during the reporting period is summarised in **Appendix D**.

5 CONCLUSION

- 5.1.1 Two environmental site inspections were carried out for the Project in the reporting month of March 2023. No non-compliance was recorded during the site inspections. Based on the observations during the site inspections, the Contractor has implemented all the relevant environmental mitigation measures as recommended in the Project Profile (Register No. PP-468/2012).
- 5.1.1 Referring to the information provided by the Contractor, no complaint, notification of summons and successful prosecution was received in the reporting month.
- 5.1.2 The construction of the Project has been completed in the reporting period. This is the last Monthly Audit Report for the Project.

AECOM 4 April 2023

Appendix A

Location Plan of Key Project Components (2017 Scheme)



Source: Environmental Review Report of "Enhanced Ash Utilisation and Water Management Facilities at castle Peak Power Station", January 2018, Castle Peak Power Company Limited

Appendix B

Construction Programme

Appendix B Tentative Schedule for the Water Management Facilities Enhancement Works

Milestone	Works Description	Dates	Duration
1	Commencement of Contract	12 March 2020	N/A
2a	Construction of Plant House of Process Water Recycling Facility	By 458 days from commencement of Contract (13 June 2021)	458 days (15 months approx.)
2b	T&C Works of Process Water Recycling Facility	By 641 days from commencement of Contract (13 December 2021)	641 days (21 months approx.)
3a	Construction of Process Water Tank	By 458 days from commencement of Contract (13 June 2021)	458 days (15 months approx.)
3b	T&C Works of Process Water Tank	By 641 days from commencement of Contract (13 December 2021)	641 days (21 months approx.)
4a	Construction of FS Water Tank and T&C Works of FS Water Tank	By 337 days from commencement of Contract (12 February 2021)	337 days (11 months approx.)
4b	Construction of Modified Fire Service System for CPA	By 641 days from commencement of Contract (13 December 2021)	641 days (21 months approx.)
5a	Construction of Storm/ Process Water Management Facilities	By 337 days from commencement of Contract (12 February 2021)	337 days (11 months approx.)
5b	T&C Works of Storm/ Process Water Management Facilities	By 397 days from commencement of Contract (13 April 2021)	397 days (13 months approx.)
6	Handing over of the West Coal Store to the Contractor for construction	By 307 days from commencement of Contract (13 January 2021)	307 days (10 months approx.)
7	Works related to Partial Decommissioning of West Coal Store	By 641 days from commencement of Contract (13 December 2021)	641 days (21 months approx.)
8	Drainage Modification Works including the necessary T&C Works	By 458 days from commencement of Contract (13 June 2021)	458 days (15 months approx.)
9	Completion of All Related Works	By 458 days from commencement of Contract (13 June 2021)	458 days (15 months approx.)
10	Completion of all Contract works	By 641 days from commencement of Contract (13 December 2021)	641 days (21 months approx.)

Appendix C Environmental Audit Records



Contr Inspe Date: Time:	A: ner: erature: dity:	Enhanced Ash Utilisation and Water Management Facilities at the Castle Peak Power Station (CPPS) Guangxi Electric Power Design Institute Co., Ltd 913 23 11:00 &m GENERAL INFORMATION Sunny Fine Cloudy Rainy CC High Moderate Low Strong Breeze Light Calm	Clie ER: IEC: Con		SP		YEMG	Ho LAP
PART	В:	SITE AUDIT	Not			- "		
Section	on 1: Wat	er Quality	Not Obs.	Yes	No	Follow up	N/A	Photo/ Remarks
1.01		g of materials and surfaces avoided excess use of water?						
1.02		nnels, earth bunds or sand bag barriers provided on-site to direct stormwater to desilting facilities?						
1.03	maintain of and a	ting on-site silt removal facilities, channels and manholes, if any, ed and the deposited silt and grit removed regularly, at the onset fter each rainstorm and to ensure that these facilities are ng properly at all times?						
1.04	adequat	r manholes, if any, including any newly constructed ones ely covered and temporarily sealed so as to prevent silt, tion materials or debris from getting into the drainage system?						
1.05	covered	n stockpiles of materials on site avoided or where unavoidable with tarpaulin or similar fabric during rainstorm? Are measures prevent the washing away of construction materials, soil, silt or						
1.06	tempora toilets? A	pe arising from the construction workers on-site collected by ry sanitary facilities where necessary, e.g. portable chemical Are portable toilets used coupled with tankering away services by a reputable collector?						
1.07	Are all si discharg	te drainages comply with the terms and conditions of a valid e licence issued by EPD?						
1.08	discharg from whe	cle washing facilities drained into desilting facilities before e? Is water recycled on-site wherever possible? Is the wash water eel wash basins either reused for site watering or pumped to the esilting facilities for treatment?						- 119 9 - 3 - 3 - 3 - 3 - 3 - 3 - 3 - 3 - 3
1.09		ting facilities checked and the deposited silt and grit removed to ensure that they are working properly at all times?						
1.10		el tanks and chemical storage sited on sealed and bunded areas ided with locks?						
1.11		age areas surrounded by bunds with a capacity equal to 110% of ge capacity of the largest tank to prevent accidental spillage, if ry?						
1.12	Are oil ar area nea	nd grease removal facilities provided where appropriate, e.g. in r plant workshop/maintenance area, if any?						
1.13	and disp	cal waste arising from the site properly stored, handled, treated osed of in compliance with the requirements stipulated under the isposal (Chemical Waste) (General) Regulation?						



		Not Obs.	Yes	No	Follow up	N/A	Photo/ Remarks
Section	n 2: Air Quality						
2.01	Are all areas involving site clearance and excavation works sprayed with water before, during and after the operations to maintain the entire surface wet?						
2.02	Are materials dropped from restricting heights as far as practicable to minimize the fugitive dust arising from loading/unloading?						
2.03	Is hoarding of not less than 2.4m high from ground level along the major work site boundary erected, for the new process water tank and the new PFA storage silo, where appropriate?						
2.04	Are all vehicles washed to remove any dusty materials from the bodies and wheels immediately before leaving a work site?						
2.05	Is the load of the vehicle leaving a work site is carrying a load of dusty materials covered entirely by clean impervious sheeting to ensure that the dusty materials will not be released from the vehicle?						
2.06	Is stockpile of dusty materials on-site covered entirely by impervious sheeting; and/or placed in an area sheltered on the top and 4 sides?		\square				
2.07	Is stockpile of dusty materials on-site sprayed with water immediately prior to any loading, unloading or transfer operation to dampen the dusty materials?						×
2.08	Is the travelling speed of vehicles within the work sites controlled to within 10 km/h to reduce the traffic induced dusty dispersion and re-suspension?						
2.09	Is unpaved haul road sprayed with water to maintain the entire road surface wet?						
2.10	Is coal dust suppressed by water sprays using the spray guns and water browser as existing normal operations at the coal stockyard during the clearance of the coal pile?						
Section	on 3: Noise		/				
3.01	Is unused equipment turned off?		1				
3.02	Is PME kept to a minimum and the parallel use of noisy equipment / machinery avoided?						
3.03	Are all plant and equipment maintained regularly?		\square				
3.04	Are material stockpiles and other on-site structures effectively used as noise barriers, where practicable?						
3.05	Are purpose-built movable noise barrier, silencer and quiet plant used as necessary?						
Secti	on 4: Waste/Chemical Management		/				
4.01	Is reuse / recycling of all materials on-site investigated and exhausted prior to treatment / disposal off-site?						
4.02	Are all waste materials sorted on-site into inert and non-inert C&D materials, and where the materials recycled or reused, are they further segregated?						
4.03	Is trip-ticket system implemented in accordance with the contract and the requirements of WBTC 31/2004 "Trip Ticket System for Disposal of Construction and Demolition Material"?						
4.04	Is the Contractor registered as a Chemical Waste Producer if chemical wastes are generated on-site?						
4.05	Are licensed chemical waste collectors employed to collect any chemical waste generated at site?						
4.06	Are handling, storage, transportation and disposal of chemical wastes conducted in accordance with the Code of Practice on the Packaging, Labelling and Storage of Chemical Wastes and A Guide to the Chemical Waste Control Scheme both published by EPD?						
4.07	Are sufficient number of covered bins provided on-site for the containment of general refuse to prevent visual impacts and nuisances? Are these bins emptied daily and the collected waste disposed of to WENT Landfill?						
4.08	Is the site maintained clean and hygienic throughout the project works?						Page 2 of 3

Manage of the second		Not Obs.	Yes	No	Follow up	N/A	Photo/ Remarks
4.09	Are toolbox talks provided to workers about the concepts of site cleanliness and appropriate waste management procedures, including waste reduction, reuse and recycling?						
Section	on 5: Others						
5.01	Are relevant Environmental Permits posted at all vehicle site entrances/exits or at a convenient location for public's information at all times??						
5.02	Others:					ď.	

Remarks:

No specific observation was identified in this inspection.

Client ER IEC Contractor

Par

(YEUNG HO LAP)

(NA SPUPING)



Contribute Inspection Date: Time: PART Weath	act no: actor: ction A: ner: erature:	Enhanced Ash Utilisation and Water Management Facilities at the Castle Peak Power Station (CPPS) Guangxi Electric Power Design Institute Co., Ltd 39/3/23 CIDENTIFY COMMATION Sunny Fine Cloudy Rain Aligh Moderate Light Calculated SITE AUDIT	Clier ER: IEC: Conf		SPI		3/1/2	
		1	Not Obs.	Yes	No	Follow up	N/A	Photo/ Remarks
Section	on 1: Wat	ter Quality				•		
1.01	ls wettir	ng of materials and surfaces avoided excess use of water?						
1.02	properly	nnels, earth bunds or sand bag barriers provided on-site to direct stormwater to desilting facilities?		Ø				
1.03	maintair of and a	ting on-site silt removal facilities, channels and manholes, if any, ned and the deposited silt and grit removed regularly, at the onset fter each rainstorm and to ensure that these facilities are ing properly at all times?						
1.04	adequat	er manholes, if any, including any newly constructed ones ely covered and temporarily sealed so as to prevent silt, ction materials or debris from getting into the drainage system?						
1.05	covered	n stockpiles of materials on site avoided or where unavoidable with tarpaulin or similar fabric during rainstorm? Are measures prevent the washing away of construction materials, soil, silt or		ď				
1.06	tempora toilets?	ge arising from the construction workers on-site collected by my sanitary facilities where necessary, e.g. portable chemical Are portable toilets used coupled with tankering away services if by a reputable collector?						
1.07		ite drainages comply with the terms and conditions of a valid ge licence issued by EPD?						
1.08	discharg from wh	cle washing facilities drained into desilting facilities before ge? Is water recycled on-site wherever possible? Is the wash water eel wash basins either reused for site watering or pumped to the desilting facilities for treatment?		d				
1.09		ilting facilities checked and the deposited silt and grit removed or to ensure that they are working properly at all times?						
1.10		uel tanks and chemical storage sited on sealed and bunded areas vided with locks?						
1.11		age areas surrounded by bunds with a capacity equal to 110% of age capacity of the largest tank to prevent accidental spillage, if any?						
1.12		nd grease removal facilities provided where appropriate, e.g. in ar plant workshop/maintenance area, if any?						
1.13	and disp	ical waste arising from the site properly stored, handled, treated bosed of in compliance with the requirements stipulated under the bisposal (Chemical Waste) (General) Regulation?		Ø				



Page 2 of 3

Environmental Audit Checklist Photo/ Follow N/A No Yes Obs. up Remarks Section 2: Air Quality Are all areas involving site clearance and excavation works sprayed with water before, during and after the operations to maintain the entire surface wet? Are materials dropped from restricting heights as far as practicable to 2.02 minimize the fugitive dust arising from loading/unloading? Is hoarding of not less than 2.4m high from ground level along the major work site boundary erected, for the new process water tank and the new 2.03 PFA storage silo, where appropriate? Are all vehicles washed to remove any dusty materials from the bodies 2.04 and wheels immediately before leaving a work site? Is the load of the vehicle leaving a work site is carrying a load of dusty materials covered entirely by clean impervious sheeting to ensure that the 2.05 dusty materials will not be released from the vehicle? Is stockpile of dusty materials on-site covered entirely by impervious 2.06 sheeting; and/or placed in an area sheltered on the top and 4 sides? Is stockpile of dusty materials on-site sprayed with water immediately prior to any loading, unloading or transfer operation to dampen the dusty 2.07 Is the travelling speed of vehicles within the work sites controlled to within 2.08 10 km/h to reduce the traffic induced dusty dispersion and re-suspension? Is unpaved haul road sprayed with water to maintain the entire road 2.09 surface wet? Is coal dust suppressed by water sprays using the spray guns and water browser as existing normal operations at the coal stockyard during the 2.10 clearance of the coal pile? Section 3: Noise Is unused equipment turned off? Is PME kept to a minimum and the parallel use of noisy equipment / 3.02 machinery avoided? 3.03 Are all plant and equipment maintained regularly? Are material stockpiles and other on-site structures effectively used as 3.04 noise barriers, where practicable? Are purpose-built movable noise barrier, silencer and quiet plant used as 3.05 necessary? Section 4: Waste/Chemical Management Is reuse / recycling of all materials on-site investigated and exhausted prior 4 01 to treatment / disposal off-site? Are all waste materials sorted on-site into inert and non-inert C&D materials, and where the materials recycled or reused, are they further 4.02 segregated? Is trip-ticket system implemented in accordance with the contract and the requirements of WBTC 31/2004 "Trip Ticket System for Disposal of 4.03 Construction and Demolition Material"? Is the Contractor registered as a Chemical Waste Producer if chemical 4.04 wastes are generated on-site? Are licensed chemical waste collectors employed to collect any chemical 4.05 waste generated at site? Are handling, storage, transportation and disposal of chemical wastes conducted in accordance with the Code of Practice on the Packaging, 4.06 Labelling and Storage of Chemical Wastes and A Guide to the Chemical Waste Control Scheme both published by EPD? Are sufficient number of covered bins provided on-site for the containment of general refuse to prevent visual impacts and nuisances? Are these bins emptied daily and the collected waste disposed of to WENT Landfill? Is the site maintained clean and hygienic throughout the project works? 4.08

							AECOM
Env	ironmental Audit Checklist						
		Not Obs.	Yes	No	Follow up	N/A	Photo/ Remarks
4.09	Are toolbox talks provided to workers about the concepts of site cleanliness and appropriate waste management procedures, including waste reduction, reuse and recycling?		d				
Secti	on 5: Others		,				
5.01	Are relevant Environmental Permits posted at all vehicle site entrances/exits or at a convenient location for public's information at all times??					84	
5.02	Others:						
Rem	arks:						
	No specific observation was identifie	d in	th1.	s Zr	rspectia	۹,	

Client ER IEC Contractor

() () (MASMURING (Fing van Pang)

Appendix D

Summary of Implementation Status of Environmental Mitigation Measure

Appendix D Implementation Status of Recommended Mitigation Measures during Construction Stage - Water Management Facilities Enhancement Works

Environmental Aspect	Recommended Mitigation Measures	Implementation Status		
Air Quality	Measures for Construction Activities involving Excavations, Loading and Unloading of Soils			
(Section 4.1 of Project Profile)	 All areas involving site clearance and excavations works will be sprayed with water before, during and after the operations to maintain the entire surface wet; 	Y		
	 Restricting heights from which materials are to be dropped, as far as practicable to minimise the fugitive dust arising from unloading/ loading; 	Y		
	• Erection of hoarding of not less than 2.4 m high from ground level along the major work site boundary (the new process water tank and the new PFA storage silo), where appropriate;	Y		
	Immediately before leaving a work site, all vehicles shall be washed to remove any dusty materials from the bodies and wheels. However, wetting of materials and surfaces should avoid excessive use of water;			
	Where a vehicle leaving a work site is carrying a load of dusty materials, the load shall be covered entirely by clean impervious sheeting to ensure that the dusty materials will not be released from the vehicle;	Y		
	 Any stockpile of dusty materials on-site will be covered entirely by impervious sheeting; and/or placed in an area sheltered on the top and 4 sides. They should also be sprayed with water immediately prior to any loading, unloading or transfer operation to dampen the dusty materials; 			
	• To reduce the traffic induced dust dispersion and re-suspension, the travelling speed of vehicles within the work sites should be controlled to within 10 km/h;	Y		
	Any unpaved haul road shall be sprayed with water so as to maintain the entire road surface wet.	Y		
	Measures for Partial Decommissioning of the West Coal Stockyard			
	During the clearance of the coal pile, coal dust will be suppressed by water sprays using the spray guns and water browser as existing normal operations at the coal stockyard.	N/A		
Noise	Good Site Practice			
(Section 4.2 of Project Profile)	 Unused equipment should be turned off. PME will be kept to a minimum and the parallel use of noisy equipment/ machinery will be avoided; 	Y		
	Regular maintenance of all plant and equipment;	Υ		
	Material stockpiles and other on-site structures will be effectively used as noise barriers, where practicable;	N/A		
	Use of purpose-built movable noise barrier, silencer and quiet plant as necessary.	N/A		

Environmental Aspect	Recommended Mitigation Measures	Implementation Status
Water Quality (Section 4.3 of Project Profile)	Measures for Construction Site Runoff and Discharge	
	 Surface runoff from the affected works areas are to be directed towards desilting facilities before discharging into the stormwater drainage; 	Y
	 Channels, earth bunds or sand bag barriers will be provided on-site to properly direct stormwater to the above- mentioned facilities; 	Y
	 Existing on-site silt removal facilities, channels and manholes, if any, will be maintained and the deposited silt and grit will be removed regularly, at the onset of and after each rainstorm and to ensure that these facilities are functioning properly at all times; 	Y
	• Other manholes, if any, including any newly constructed ones will be adequately covered and temporarily sealed so as to prevent silt, construction materials or debris from getting into the drainage system;	Y
	 Open stockpiles of materials on site will be avoided or where unavoidable covered with tarpaulin or similar fabric during rainstorms. Measures will be taken to prevent the washing away of construction materials, soil, silt or debris; 	N/A
	• Sewage arising from the construction workers on-site will be collected by temporary sanitary facilities where necessary e.g. portable chemical toilets. Portable toilets will be used coupled with tankering away services provided by a reputable collector;	N/A
	• All site discharges will comply with the terms and conditions of a valid discharge licence issued by EPD;	Y
	 Vehicle washing facilities will be drained into desilting facilities before discharge. Water will be recycled on-site wherever possible. It is suggested that the wash water from wheel wash basins are either reused for site watering or pumped to the on-site desilting facilities for treatment; 	Y
	• Desilting facilities will be checked and the deposited silt and grit will be removed regularly to ensure that they are working properly at all times.	Y
	Protection against Accidental Spillage	
	 The works may occasionally involve the handling of fuel and generates a small amount of chemical wastes. It must be ensured that all fuel tanks and chemical storage are sited on sealed and bunded areas and provided with locks; 	Y
	• If necessary, the storage areas will be surrounded by bunds with a capacity equal to 110% of the storage capacity of the largest tank to prevent accidentally spillage;	N/A
	 Oil and grease removal facilities will be provided where appropriate, for example, in area near plant workshop/ maintenance areas, if any; 	Y
	• Chemical waste arising from the site will be properly stored, handled, treated and disposed of in compliance with the requirements stipulated under the Waste Disposal (Chemical Waste) (General) Regulation.	Y

Environmental Aspect	Recommended Mitigation Measures	Implementation Status
Waste	Waste Management Plan (WMP)	
Management Implications (Section 4.4 of the Project Profile)	The main contractor of the Project shall prepare a <i>Waste Management Plan (WMP)</i> , which will become part of the <i>Environmental Management Plan (EMP)</i> , with reference to the requirements set out in the <i>ETWB TCW No. 19/2005</i> , <i>Waste Management on Construction Sites</i> and the Practice Note for Authorized Persons and Registered Structural Engineers, e.g. <i>Practice Note No. 243 – Construction and Demolition Waste</i> . The WMP shall include monthly Waste Flow Tables (WFT) which indicate the amounts of waste generated, recycled and disposed of (including final disposal site), and it should be updated regularly.	Y
	General waste management measures during Construction	
	• The reuse/recycling of all materials on-site shall be investigated and exhausted prior to treatment/ disposal off-site;	Y
	• All waste materials shall be sorted on-site into inert and non-inert C&D materials, and where the materials can be recycled or reused, they shall be further segregated. Inert material, or public fill shall be disposed of at Fill Bank at Tuen Mun Area 38 whilst non-inert materials or construction waste shall be disposed of at the WENT Landfill.	Y
	• The contractor shall be responsible for identifying what materials can be recycled/ reused, whether on-site or off-site. In the event of the latter, the contractor shall arrange for the collection of the recyclable materials.	Y
	• In order to monitor the disposal of public fill and construction waste at public filling facilities and landfills, and control fly-tipping, a trip-ticket system shall be implemented by the Contractor, in accordance with the contract and the requirements of WBTC 31/2004 "Trip Ticket System for Disposal of Construction and Demolition Material";	Y
	• Under the Waste Disposal (Chemical Waste) (General) Regulation, the Contractor shall register as a Chemical Waste Producer if chemical wastes such as spent lubricants and paints are generated on-site. Only licensed chemical waste collectors shall be employed to collect any chemical waste generated at site. The handling, storage, transportation and disposal of chemical wastes shall be conducted in accordance with the Code of Practice on the Packaging, Labelling and Storage of Chemical Wastes and A Guide to the Chemical Waste Control Scheme both published by EPD;	Y
	• A sufficient number of covered bins shall be provided on-site for the containment of general refuse to prevent visual impacts and nuisances. These bins shall be emptied daily and the collected waste disposed of to the WENT Landfill. Further to the issue of ETWB TCW No. 6/2002A, Enhanced Specification for Site Cleanliness and Tidiness, the contractor will be required to maintain a clean and hygienic site throughout the project works;	Y
	• Toolbox talks should be provided to workers about the concepts of site cleanliness and appropriate waste management procedures, including waste reduction, reuse and recycling.	N/A
Land Contamination (Section 4.5 of Project Profile)	Based on the recent SI result, signs of land contamination were not identified and no mitigation measures are considered necessary. However, the situation will be reconfirmed after the SI work at the coal stockyard proposed in the CAP is completed. The SI results will be documented in a Contamination Assessment Report (CAR). If contamination is identified, the necessary remediation method will be proposed and documented in the Remediation Action Plan (RAP) for EPD's approval. If remediation is necessary, the CAPCO will clean up the contaminated land according to the approved RAP, and a Remediation Report (RR) will be prepared to demonstrate that the concerned area(s) have been cleaned up to the	N/A

Environmental Aspect	Recommended Mitigation Measures	Implementation Status
	relevant RBRG's standards. The RR will be submitted to EPD for agreement prior to the commencement of any development or redevelopment works.	
Landscape & Visual (Section 4.7 of Project Profile)	No mitigation measures for landscape and visual impacts are considered necessary, as no adverse landscape and visual impacts are identified during the construction and operation of the Project.	N/A

Notes:

- Y Compliance of Mitigation Measures
 N Non-compliance of Mitigation Measures
 D Deficiency of Mitigation Measures
 N/A Not Applicable in Reporting Period

- Non-compliance of Mitigation Measures but rectified by the Contractor
- Deficiency of Mitigation Measures but rectified by the Contractor