



Reprovisioning of Diamond Hill Crematorium
重置鑽石山火葬場
Environmental Permit number EP-179/2004/C
環境許可証 EP-179/2004/C

Figure 6 : S1 to S6 - Subsurface Soil sampling locations for confirmatory contamination analysis
圖六 S1至S6 - 地下土採樣位置(以供進行污泥驗證分析)

Note :
Extracted from
Figure 6.2 of the
Approved EIA report
(AEIAR-076/2004)

Scale : NTS